

Available from
National Technical Information Service
Springfield, Virginia 22161

TITLE LIST
of
DOCUMENTS MADE PUBLICLY AVAILABLE

May 1 - 31, 1979

Division of Technical Information and Document Control
Office of Administration
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Arrangement of Docket 50 Items by Facility Name	xviii
Docketed Items	1
Low Level Radwaste Disposal Sites - Docket 27	1
Domestic Licensing of Source Material - Docket 40	1
Domestic Licensing of Production and Utilization Facilities - Docket 50	6
Domestic Licensing of Special Nuclear Material - Docket 70	272
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions - Docket 71	279
Nondocketed Items	289
Personal Author Index	321
Corporate Source Index - By Corporate Types	357
Citizen Group/Individual/Media	357
Engineering/Construction/Consultants/Services	357
Educational Institutions	357
Foreign Governments and Agencies	358
Legal/Law Firms/Insurance Companies	358
Local Government and Agencies	359
Medical Institutions and Laboratories	359
Manufacturers/Equipment and Supplies	360
Professional/Industrial Institutions, Societies	362
State Governments and Agencies	362
U.S. Federal Government and Agencies	362
Utilities, Holding Companies, Investor Associations	363
Research Institutions and Laboratories	373
U.S. Nuclear Regulatory Commission Organizational Source Index	375
Report Number Index	395
Appendix A - Definitions of Docket 50 Categories	397

PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information includes the information formerly issued through the Department of Energy's Technical Information Center under the title *Power Reactor Docket Information* (PRDI) and, in addition, information received or generated on other uses of radioactive materials. The last issue of PRDI, published in January 1979, was an annual cumulation of the information for 1978. The *Title List* series initiated by this document replaces PRDI, which will no longer be prepared. Plans for providing microfiche of the docketed material will be announced in a future issue of the *Title List* and in other mailings and announcements.

We are making the monthly issues produced in 1979 available free to all who subscribed to PRDI in Calendar Year 1978. We are doing this to encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material. Near the end of 1979, subscriptions will be solicited for Calendar Year 1980 at a fee yet to be established.


DOCKETED ITEMS

Beginning with Vol. 1, No. 4, the listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:




1. NRC/PDR Document category (see Appendix A).
2. NRC Accession Number
3. Description of information contained in the document
4. Personal author. An asterisk in this position indicates that there is no personal author.
5. Corporate, agency or nonindividual source
6. Date of document described
7. Pages in document
8. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The principal elements of the nondocketed items are:



1. NRC Accession Number
2. NRC Report Number
3. Title and description of information contained in the document
4. Personal author(s). An asterisk in this position indicates that there is no personal author
5. Corporate, agency or other nonindividual source
6. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
7. Date of document described
8. Pages in document
9. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or Available at GPO."

The Nondocketed Items list is arranged sequentially by Accession Number. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NTIS is:

National Technical Information Service
Springfield, Virginia 22161

2. The address for GPO is:

Superintendent of Documents
Government Printing Office
Washington, D.C. 20402

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
27-039	Sheffield, IL., Nuclear Engineering Co., Inc.	1	40-8698	Plateau Resources, Ltd.	5
27-047	Barnwell, SC., Chem-Nuclear Systems, Inc.	1	40-8714	Cleveland Cliffs Iron Co.	6
40-0299	Union Carbide Corp.	1	40-8721	Rocky Mountain Energy Co.	6
40-1162	Western Nuclear	2	40-8722	Brush-Wellman, Inc.	6
40-2061	Kerr-McGee Corp., West Chicago Facility	2	50-2	Univ. of Michigan Research Reactor	6
40-2259	Pathfinder Mines Corp.	2	50-3	Indian Point Station, Unit 1	6
40-2407	Fellows Medical Manufacturing Co., Inc.	2	50-5	Pennsylvania State Univ. Research Reactor	7
40-3392	Allied Chemical Corp.	3	50-6	Battelle Memorial Inst. Research Reactor	7
40-3453	Atlas Minerals	4	50-8	North Carolina State Univ. Research Reactor	7
40-4492	Federal American Partners	4	50-10	Dresden Nuclear Power Station, Unit 1	7
40-4602	Morton Ranch Uranium Mill	4	50-12	Lynchburg Pool Reactor	9
40-6659	Petrotomics Co.	4	50-13	Babcock & Wilcox Co. Critical Facility	9
40-7086	Army, Dept. of	4	50-14	Battelle Memorial Inst. Critical Facility	9
40-8027	Kerr-McGee Corp.	4	50-16	Enrico Fermi Atomic Power Plant, Unit 1	9
40-8035	Cotter Corp.	4	50-18	Vallecitos Boiling Water Reactor	9
40-8064	Exxon Minerals Co., USA	4	50-20	Massachusetts Institute of Technology Research Reactor	9
40-8102	Exxon Minerals Co., USA, Exxon Corp.	4	50-22	Westinghouse Test Reactor	9
40-8158	Army, Dept. of, Communications & Electronics Material	4	50-24	General Electric Co. Critical Experiment	9
40-8452	Bear Creek Mining Co.	4	50-27		
40-8502	Wyoming Mining Corp., Irigary Mine	5			
40-8584	Union 76 Exploration Co.	5			
40-8602	United Nuclear Corp.	5			
40-8663	Nuclear Dynamics	5			
40-8681	Energy Fuels Nuclear	5			
40-8693	Ogle Petroleum, Inc.	5			
40-8697	Rocky Mountain Energy Co.	5			

Docket	Name	Page	Docket	Name	Page
50-53	Aerojet General Nucleonics	11	50-142	UCLA Training Reactor	16
50-54	Pawling Research Reactor	11	50-146	Saxton Nuclear Experimental Facility	16
50-59	Texas A & M Univ. Research Reactor	11	50-147	Rockwell International Corp. Critical Facility	16
50-62	Univ. of Virginia Research Reactor	11	50-148	Univ. of Kansas Research Reactor	16
50-70	General Electric Test Reactor	12	50-150	Ohio State Univ. Research Reactor	16
50-72	Univ. of Utah Research Reactor	12	50-151	Univ. of Illinois Research Reactor	16
50-73	General Electric Nuclear Test Reactor	12	50-155	Big Rock Point Nuclear Power Plant	16
50-77	Catholic Univ. of America Research Reactor	12	50-156	Univ. of Wisconsin Research Reactor	17
50-83	Univ. of Florida Training Reactor	12	50-157	Cornell Univ. Research Reactor	18
50-84	Univ. of California Research Reactor	12	50-160	Georgia Institute of Technology Research Reactor	18
50-87	Westinghouse Critical Experiment	12	50-166	Univ. of Maryland Research Reactor	18
50-89	General Atomic Co.	12	50-170	National Naval Medical Center	18
50-94	Rockwell International Research Reactor	12	50-171	Peach Bottom Atomic Power Station, Unit 1	18
50-97	Cornell Univ. Zero Power Reactor	12	50-182	Purdue Univ. Research Reactor	18
50-99	Babcock & Wilcox Test Reactor	13	50-183	Vallecitos Experimental Supercritical Reactor	18
50-103	Aerojet General Nucleonics	13	50-184	National Bureau of Standards Reactor	18
50-106	Oregon State Univ.	13	50-186	Univ. of Missouri Research Reactor	18
50-111	North Carolina State Univ. Research Reactor	13	50-187	Space Radiation Research Reactor	18
50-112	Univ. of Oklahoma Research Reactor	13	50-188	Kansas State Univ. Research Reactor	18
50-113	Univ. of Arizona Research Reactor	13	50-191	Babcock & Wilcox Co. Critical Facility	19
50-116	Iowa State Univ. Research Reactor	13	50-192	Univ. of Texas Research Reactor	19
50-123	Univ. of Missouri Research Reactor	13	50-193	Rhode Island & Providence Plantations AEC	19
50-124	Virginia Polytech Inst. Training Reactor	14	50-199	Manhattan College Research Reactor	19
	Texas A & M Univ. Research Reactor	14	50-200	Babcock & Wilcox Test Reactor	19
	Texas A & M Univ. Research Reactor	14	50-201	West Valley Reprocessing Plant	19
	Omaha Veterans Administration Hospital Research Reactor	14	50-206	San Onofre Nuclear Station, Unit 1	19
	Humboldt Bay Power Plant, Unit 3	14	50-208	Columbia Univ. Research Reactor	21
	Worcester Polytech Inst. Research Reactor	16	50-213	Haddam Neck Plant	21
	Univ. of Washington Research Reactor	16	50-219	Oyster Creek Nuclear Power Plant	22
	Stanford Univ. Research Reactor	16	50-220	Nine Mile Point Nuclear Station, Unit 1	24

Docket	Name	Page	Docket	Name	Page
50-223	Univ. of Lowell Research Reactor	25	50-267	Fort St. Vrain Nuclear Generating Station	50
50-224	Univ. of California Research Reactor	25	50-269	Oconee Nuclear Station, Unit 1	52
50-225	RPI Critical Experiment	25	50-270	Oconee Nuclear Station, Unit 2	55
50-227	TRIGA Thermionic Prototype Reactor	26	50-271	Vermont Yankee Nuclear Power Station	57
50-228	Aerotest Radiography & Research Reactor	26	50-272	Salem Nuclear Generating Station, Unit 1	58
50-233	Mexico Research Reactor	26	50-273	Bernau Nuclear Station, Unit 1	61
50-234	Tungsten Nuclear Rocket Critical Facility	26	50-274	U.S. Geological Survey Research Reactor	61
50-235	Accelerator Pulsed Fast Assembly	26	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	61
50-237	Dresden Nuclear Power Station, Unit 2	26	50-276	Georgia Tech Research Reactor	64
50-240	High Temp. Gas Cooled Critical Experiment	28	50-277	Peach Bottom Atomic Power Station, Unit 2	64
50-241	Mississippi State Univ. Research Reactor	28	50-278	Peach Bottom Atomic Power Station, Unit 3	66
50-243	Oregon State Univ. Research Reactor	28	50-280	Surry Power Station, Unit 1	67
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	28	50-281	Surry Power Station, Unit 2	70
50-245	Millstone Nuclear Power Station, Unit 1	29	50-282	Prairie Island Nuclear Station, Unit 1	72
50-247	Indian Point Station, Unit 2	31	50-284	Idaho State Univ. Research Reactor	74
50-249	Dresden Nuclear Power Station, Unit 3	32	50-285	Fort Calhoun Station, Unit 1	74
50-250	Turkey Point Plant, Unit 3	34	50-286	Indian Point Station, Unit 3	76
50-251	Turkey Point Plant, Unit 4	36	50-287	Oconee Nuclear Station, Unit 3	77
50-252	Univ. of New Mexico Research Reactor	38	50-288	Reed College Research Reactor	80
50-254	Quad-Cities Station, Unit 1	38	50-289	Three Mile Island Nuclear Station, Unit 1	80
50-255	Palisades Nuclear Plant	39	50-293	Pilgrim Nuclear Power Station, Unit 1	81
50-259	Browns Ferry Nuclear Power Station, Unit 1	41	50-294	Michigan State Univ. Research Reactor	82
50-260	Browns Ferry Nuclear Power Station, Unit 2	42	50-295	Zion Nuclear Power Station, Unit 1	82
50-261	H.B. Robinson Plant, Unit 2	44	50-296	Browns Ferry Nuclear Power Station, Unit 3	84
50-262	Brigham Young Univ. Research Reactor	46	50-297	North Carolina State Univ. PULSTAR Reactor	85
50-263	Monticello Nuclear Generating Plant	46	50-298	Cooper Nuclear Station	86
50-264	Dow Chemical Co.	47	50-301	Point Beach Nuclear Plant, Unit 2	87
50-265	Quad-Cities Station, Unit 2	48	50-302	Crystal River Nuclear Plant, Unit 3	88
50-266	Point Beach Nuclear Plant, Unit 1	49			

	Name	Page	Docket	Name	Page
50-313	Crystal River Nuclear Plant, Unit 4	91	50-338	North Anna Power Station, Unit 1	154
50-314	Zion Nuclear Power Station, Unit 2	91	50-339	North Anna Power Station, Unit 2	158
50-315	Kewaunee Nuclear Power Plant	93	50-341	Enrico Fermi Atomic Power Plant, Unit 2	160
50-316	Praine Island Nuclear Station, Unit 2	94	50-344	Trojan Nuclear Plant, Unit 1	161
50-317	Maine Yankee Atomic Power Plant	95	50-346	Davis-Besse Nuclear Power Station, Unit 1	164
50-318	Salem Nuclear Generating Station, Unit 2	97	50-348	Joseph M. Farley Nuclear Plant, Unit 1	166
50-319	Rancho Seco Nuclear Generating Station	99	50-352	Limerick Generating Station, Unit 1	168
50-320	Arkansas Nuclear One, Unit 1	100	50-353	Limerick Generating Station, Unit 2	168
50-321	Donald C. Cook Nuclear Power Plant, Unit 1	103	50-354	Hope Creek Nuclear Station, Unit 1	169
50-322	Donald C. Cook Nuclear Power Plant, Unit 2	105	50-355	Hope Creek Nuclear Station, Unit 2	169
50-323	Calvert Cliffs Nuclear Power Plant, Unit 1	106	50-358	William H. Zimmer Nuclear Station, Unit 1	170
50-324	Calvert Cliffs Nuclear Power Plant, Unit 2	107	50-360	Battelle Memorial Inst. Critical Facility	173
50-325	Three Mile Island Nuclear Station, Unit 2	108	50-361	San Onofre Nuclear Station, Unit 2	173
50-326	Edwin L. Hatch Nuclear Plant, Unit 1	130	50-362	San Onofre Nuclear Station, Unit 3	174
50-327	Shoreham Nuclear Power Station	131	50-363	Forked River Nuclear Station, Unit 1	175
50-328	Diablo Canyon Nuclear Power Plant, Unit 2	133	50-364	Joseph M. Farley Nuclear Plant, Unit 2	176
50-329	Brunswick Steam Electric Plant, Unit 2	135	50-366	Edwin H. Hatch Nuclear Plant, Unit 2	176
50-330	Brunswick Steam Electric Plant, Unit 1	137	50-367	Bailly Generating Station	178
50-331	Univ. of California at Irvine Res. Reactor	139	50-368	Arkansas Nuclear One, Unit 2	178
50-332	Sequoyah Nuclear Plant, Unit 1	139	50-369	William B. MacGuire Nuclear Station, Unit 1	180
50-333	Sequoyah Nuclear Plant, Unit 2	141	50-370	William B. MacGuire Nuclear Station, Unit 2	182
		142	50-373	LaSalle County Station, Unit 1	182
			50-374	LaSalle County Station, Unit 2	184
			50-375	Nuclear Examination Reactor	185
			50-376	North Coast Nuclear Plant (Puerto Rico)	185
			50-382	Waterford Generating Station, Unit 3	185
			50-387	Susquehanna Steam Electric Station, Unit 1	186
			50-388	Susquehanna Steam Electric Station, Unit 2	187
			50-389	St. Lucie Plant, Unit 2	188

Docket	Name	Page	Docket	Name	Page
50-390	Watts Bar Nuclear Plant, Unit 1	189	50-440	Perry Nuclear Power Plant, Unit 1	210
50-391	Watts Bar Nuclear Plant, Unit 2	191	50-441	Perry Nuclear Power Plant, Unit 2	211
50-394	California State Polytech College Research Reactor	192	50-443	Seabrook Nuclear Station, Unit 1	211
50-395	Virgil C. Summer Nuclear Station, Unit 1	192	50-444	Seabrook Nuclear Station, Unit 2	212
50-396	Univ. of Virginia Cavalier Reactor	193	50-445	Comanche Peak Steam Electric Station, Unit 1	213
50-397	WPPSS Nuclear Project, Unit 2	193	50-446	Comanche Peak Steam Electric Station, Unit 2	216
50-400	Shearon Harris Nuclear Power Plant, Unit 1	194	STN-50-447	GESSAR-238	218
50-401	Shearon Harris Nuclear Power Plant, Unit 2	196	50-448	Douglas Point Nuclear Station, Unit 1	218
50-402	Shearon Harris Nuclear Power Plant, Unit 3	197	50-449	Douglas Point Nuclear Station, Unit 2	219
50-403	Shearon Harris Nuclear Power Plant, Unit 4	198	50-450	Summit Nuclear Power Station, Unit 1	219
50-404	North Anna Power Station, Unit 3	199	50-451	Summit Nuclear Power Station, Unit 2	219
50-405	North Anna Power Station, Unit 4	200	50-452	Greenwood Energy Center, Unit 2	219
50-406	Tuskegee Inst. Research Reactor	201	50-453	Greenwood Energy Center, Unit 3	219
50-407	Univ. of Utah Research Reactor	201	50-454	Byron Station, Unit 1	219
50-409	La Crosse Boiling Water Reactor	201	50-455	Byron Station, Unit 2	220
50-410	Nine Mile Point Nuclear Station, Unit 2	202	50-456	Braidwood Station, Unit 1	221
50-412	Beaver Valley Power Station, Unit 2	203	50-457	Braidwood Station, Unit 2	222
50-413	Catawba Nuclear Station, Unit 1	203	50-458	River Bend Station, Unit 1	223
50-414	Catawba Nuclear Station, Unit 2	204	50-459	River Bend Station, Unit 2	224
50-416	Grand Gulf Nuclear Station, Unit 1	204	50-460	WPPSS Nuclear Project, Unit 1	224
50-417	Grand Gulf Nuclear Station, Unit 2	205	50-461	Clinton Power Station, Unit 1	225
50-423	Millstone Nuclear Power Station, Unit 3	206	50-462	Clinton Power Station, Unit 2	226
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	206	50-463	Fulton Generating Station, Unit 1	226
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	207	50-464	Fulton Generating Station, Unit 2	226
50-426	Alvin W. Vogtle Nuclear Plant, Unit 3	208	50-466	Allens Creek Nuclear Station, Unit 1	227
50-427	Alvin W. Vogtle Nuclear Plant, Unit 4	208	50-467	Allens Creek Nuclear Station, Unit 2	229
50-430	ASCO, Unit 1	208	50-471	Pilgrim Nuclear Power Station, Unit 2	229
50-433	UC-Santa Barbara Research Reactor	208	50-472	Pilgrim Nuclear Power Station, Unit 3	230
STN-50-437	Floating Nuclear Plant	208	STN-50-477	Atlantic Generating Station, Unit 1	230
50-438	Bellefonte Nuclear Plant, Unit 1	209	STN-50-478	Atlantic Generating Station, Unit 2	230
50-439	Bellefonte Nuclear Plant, Unit 2	210	STN-50-482	Wolf Creek Generating Station	230
			STN-50-483	Calloway Plant, Unit 1	232
			STN-50-484	Tyrone Energy Park, Unit 1	232

Docket	Name	Page	Docket	Name	Page
STN-50-485	Sterling Power Project, Nuclear, Unit 1	233	STN-50-530	Palo Verde Nuclear Station, Unit 3	258
STN-50-486	Caloway Plant, Unit 2	234	STN-50-531	GESSAR-251	258
STN-50-488	Perkins Nuclear Station, Unit 1	234	STN-50-532	BOP SAR	259
STN-50-489	Perkins Nuclear Station, Unit 2	235	50-537	Clinch River Breeder Reactor	259
STN-50-490	Perkins Nuclear Station, Unit 3	236	50-538	Memphis State Univ. Research Reactor	259
STN-50-491	Cherokee Nuclear Station, Unit 1	236	STN-50-546	Marble Hill Nuclear Station, Unit 1	259
STN-50-492	Cherokee Nuclear Station, Unit 2	237	STN-50-547	Marble Hill Nuclear Station, Unit 2	260
STN-50-493	Cherokee Nuclear Station, Unit 3	238	50-548	Fort Calhoun Station, Unit 2	261
STN-50-495	SWESSAR-P1	239	50-549	Greene County Nuclear Power Plant	261
STN-50-498	South Texas Project, Unit 1	239	STN-50-550	GESSAR-238-BOP Interface	262
STN-50-499	South Texas Project, Unit 2	241	STN-50-553	Phipps Bend Nuclear Plant, Unit 1	262
50-500	Davis-Besse Nuclear Power Station, Unit 2	244	STN-50-554	Phipps Bend Nuclear Plant, Unit 2	263
50-501	Davis-Besse Nuclear Power Station, Unit 3	245	STN-50-556	Black Fox Station, Unit 1	263
STN-50-502	Haven Nuclear Plant, Unit 1	245	STN-50-557	Black Fox Station, Unit 2	264
STN-50-503	Haven Nuclear Plant, Unit 2	246	50-564	Nuclear Fuels Recovery and Recycle Center	266
STN-50-508	WPPSS Nuclear Project, Unit 3	246	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	266
STN-50-509	WPPSS Nuclear Project, Unit 5	247	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	266
50-510	Blue Hills Station, Unit 1	247	STN-50-568	NEP Nuclear, Unit 1	267
50-511	Blue Hills Station, Unit 2	248	STN-50-569	NEP Nuclear, Unit 2	267
50-513	WPPSS Nuclear Project, Unit 4	248	STN-50-574	Bagnac Nuclear Power Project	267
50-514	Pebble Springs Nuclear Plant, Unit 1	249	STN-50-580	Erie Nuclear Plant, Unit 1	267
50-515	Pebble Springs Nuclear Plant, Unit 2	249	STN-50-581	Erie Nuclear Plant, Unit 2	267
STN-50-516	Jamesport Nuclear Station, Unit 1	250	STN-50-584	GIBBSAR	268
STN-50-517	Jamesport Nuclear Station, Unit 2	250	STN-50-592	Palo Verde Nuclear Station, Unit 4	268
		251	STN-50-593	Palo Verde Nuclear Station, Unit 5	268
		251	50-596	New Haven, Unit 1	269
		252	50-597	New Haven, Unit 2	270
		253	50-598	Northwestern Univ.	271
		254	50-599	Carroll Facility I	271
		255	50-600	Carroll Facility II	271
		256	70-0008	Battelle Columbus Laboratories	272
		256	70-0025	Rockwell International Corp.	272
		256	70-0027	Babcock & Wilcox Co.	272
		256	70-0033	Texas Instruments, Inc.	272
		257	70-0102	Amherst College	272

Docket	Name	Page	Docket	Name	Page
70-0135	Babcock & Wilcox Co.	272	70-2838	Cincinnati Gas & Electric Co.	279
70-0143	Nuclear Fuel Services, Inc.	273	71-0001	ANEFco, Inc.	279
70-0150	Purdue University	273	71-0002	Chem-Nuclear Systems, Inc.	279
70-0364	Parks Township Site, Babcock & Wilcox Co.	273	71-0006	United Nuclear Corp.	279
70-0371	United Nuclear Corp.	274	71-0008	Commonwealth Edison Co.	279
70-0734	General Atomic Co.	274	71-0024	Hittman Nuclear & Development Corp.	279
70-0754	Vallecitos Nuclear Center, General Electric Co.	274	71-0031	Maryland Shipbuilding & Dry Dock Co.	279
70-0820	United Nuclear Corp.	274	71-0033	Industrial Testing Laboratory Services Co.	279
70-0824	Babcock & Wilcox Co.	275	71-0034	Babcock & Wilcox Co.	279
70-0984	Pacific Northwest Laboratory	275	71-0036	ITT Grinnell Corp.	279
70-1007	General Electric Co.	275	71-0038	Crane Co.	279
70-1086	Westinghouse Electric Corp.	275	71-0039	Walworth Co.	279
70-1100	Combustion Engineering, Inc.	275	71-0047	Capital International Airways, Inc.	280
70-1113	General Electric Co.	275	71-0048	Intermountain Pipe and Welding	280
70-1143	Westinghouse Electric Corp.	275	71-0050	Midland-Ross Corp.	280
70-1151	Westinghouse Electric Corp.	276	71-0055	H.R. Inspection Service	280
70-1173	Mercyhurst College	276	71-0056	Philadelphia Electric Co.	280
70-1193	Cinnarron Facility, Kerr-McGee Corp.	276	71-0057	Exxon Co. U.S.A., Exxon Corp.	280
70-1201	UF ₆ Conversion Facility, Babcock & Wilcox Co.	276	71-0063	Ozark Airlines, Inc.	280
70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	277	71-0065	H.P. & Associates, Inc.	280
70-1308	Morris Operations, General Electric Co.	277	71-0066	Certified Testing Laboratories, Inc.	280
70-1309	Morris Operations, Sources & Standards, General	277	71-0068	Yankee Atomic Electric	280
70-1318	NL Nuclear/NL Industries, Inc.	277	71-0070	General Motors Corp.	280
70-1319	U.S. Nuclear, Inc.	277	71-0072	Babcock & Wilcox Co.	280
70-1355	Army, Dept. of	278	71-0074	Nuclear Welding, Inc.	280
70-1379	Parkwell Laboratories, Inc.	278	71-0077	Midstate Testing Laboratory	280
70-1821	Plutonium Production Facility, Allied General Nuclear Service Corp.	278	71-0087	Navy, Dept. of	280
70-2428	St. Francis General Hospital, Pittsburgh, PA	278	71-0088	Babcock & Wilcox Co.	280
70-2623	McGuire Spent Fuel Pool, Duke Power Co.	278	71-0089	Navy, Dept. of	280
70-2753	Holyoke Hospital, Holyoke, MA	279	71-0090	Combustion Engineering Co., Inc.	280
70-2760	United Nuclear Corp.	279	71-0099	Foster Wheeler Energy Corp.	281
			71-0103	Twin City Testing & Engineering Laboratory	281
			71-0104	Chicago Bridge & Iron Co.	281
			71-0109	Union Carbide Corp.	281

Docket	Name	Page	Docket	Name	Page
71-0110	Buckeye Steel Castings	281	71-0209	Jacksonville Shipyards, Inc.	282
71-0111	Material Testing Laboratory of Virginia, Inc.	281	71-0213	Intermountain Testing Co.	283
71-0116	Navy, Dept. of	281	71-0214	Gas Rentals, Inc.	283
71-0119	Ingersoll-Rand Co.	281	71-0215	Space Science Services	283
71-0120	Daniel International Corp.	281	71-0216	Nuclear Energy Services, Inc.	283
71-0121	Neutron Products, Inc.	281	71-0217	Pullman Kellogg, Inc.	283
71-0126	Stanwick Corp.	281	71-0220	General Dynamics Corp.	283
71-0127	National Annealing Box Co.	281	71-0222	St. Louis Testing Laboratories, Inc.	283
71-0128	Amoco Oil Co.	281	71-0223	B.F. Shaw, Inc.	283
71-0130	Chicago Bridge & Iron Co.	281	71-0225	Navy, Dept. of	283
71-0131	Welding Institute of Alaska	281	71-0226	New York, State Univ. of	283
71-0137	Metals Testing Co., Inc.	281	71-0234	X-Ray, Inc.	283
71-0141	Rockwell International	281	71-0235	Army, Dept. of	283
71-0143	Ranchers Exploration and Development Co.	281	71-0238	Agriculture, Dept. of	283
71-0151	Hess Oil Virgin Islands Corp.	282	71-0239	Navy, Dept. of	283
71-0154	General Dynamics	282	71-0241	United Nuclear Corp.	283
71-0156	Industrial Fabricating Co.	282	71-0251	Westinghouse Electric Corp.	283
71-0158	X-Ray Industries, Inc.	282	71-0255	Walworth Co.	283
71-0161	Curtiss-Wright Corp.	282	71-0257	Industrial Laboratories, Inc.	283
71-0162	Ebasco Services, Inc.	282	71-0260	Astrotech, Inc.	283
71-0166	New York Testing Laboratories, Inc.	282	71-0261	Navy, Dept. of	283
71-0167	Finlay Testing Laboratories	282	71-0266	Duke Power Co.	284
71-0168	Quality Assurance Laboratories	282	71-0268	Navy, Dept. of	284
71-0169	Florida Power & Light Co.	282	71-0273	Navy, Dept. of	284
71-0174	Southern California Edison Co.	282	71-0277	Allied Chemical Corp.	284
71-0175	QC Services, Inc.	282	71-0280	ABCO Perforators, Inc.	284
71-0178	Energy Products Group	282	71-0282	WKM Wellhead Systems, Inc.	284
71-0180	Hartford Steam Boiler Co.	282	71-0286	BPB Instruments, Inc.	284
71-0181	Consolidated X-Ray Service Co.	282	71-0287	Carson Non-Destructive Testing	284
71-0188	Maynard Steel Casting Co.	282	71-0288	North Dakota State Water Commission	284
71-0189	Todd Shipyards Corp.	282	71-0290	United Testing Services, Inc.	284
71-0202	Pacific Gas & Electric Co.	282	71-0296	Iowa Electric Light & Phone Co.	284
71-0205	Quality Testing, Inc.	282	71-0297	E. Lewis Cook & Associates	284
71-0207	Connecticut Yankee Atomic Power Co.	282	71-0299	Quality Control Services, Inc.	284
			71-0300	Independent Testing Laboratories	284

Docket	Name	Page	Docket	Name	Page
71-0304	Teledyne Brown Engineering Co.	284	71-6697	Model: 8500 PKG, General Electric Co.	286
71-0305	American X-Ray & Inspection, Inc.	284	71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	286
71-0307	Texas Pipe Bending Co. of Puerto Rico	284	71-6744	Model: Poly Tiger, Nuclear Engineering Co.	287
71-0309	Worthington Pump Corp. (U.S.A.)	284	71-6771	Model: SN-1, Nuclear Engineering Co.	287
71-0311	Logwell, Inc.	285	71-9009	Model: FL-10-1, General Electric Co.	287
71-0312	Metalfoms, Inc.	285	71-9010	Model: NLI-1/2, NL Industries, Inc.	287
71-0317	Hudson Products Corp.	285	71-9023	Model: NLI-10/24, NL Industries, Inc.	287
71-0322	Control Components International	285	71-9033	Model: 660 & 660E, Technical Operations, Inc.	287
71-4986	Model: RA-2, Exxon Nuclear Co., Inc.	285	71-9044	Model: GE-1600, General Electric Co.	287
71-5026	Model: BC-48-220, Atcor, Inc.	285	71-9070	Model: N-55, Energy, Dept. of	287
71-5450	Model: RCC-1, -2, -3, Westinghouse Electric Corp.	285	71-9079	Model: HN-100 Series 2, Hittman Nuclear & Development Corp.	287
71-5790	Model: A1-M3, Energy, Dept of	285	71-9080	Model: HN-600, Hittman Nuclear & Development Corp.	287
71-5791	Model: A1-M6, Energy, Dept. of	285	71-9086	Model: HN-100, Series 1, Hittman Nuclear & Development Corp.	287
71-5795	Model: None, Energy, Dept. of	285	71-9089	Model: NH-100 S, Hittman Nuclear & Development Corp.	287
71-5805	Model: Atcor VNDB Cask, Atcor, Inc.	285	71-9090	Model: 480M, Allied Chemical Corp.	287
71-5908	Model: DOT-GM Type B, Babcock & Wilcox Co.	285	71-9091	Model: 30A, General Electric Co.	287
71-5926	Model: 100, General Electric Co.	285	71-9092	Model: HN-300, Hittman Nuclear & Development Corp.	288
71-5957	Model: BMI-1, Energy, Dept. of	285	71-9093	Model: HN-400 Hittman Nuclear & Development Corp.	288
71-6058	Model: B3-1, Nuclear Engineering Co.	285	71-9116	Model: CN6-80B, Nuclear Packaging, Inc.	288
71-6144	Model: 6144, Nuclear Engineering Co.	286	71-9120	Model: TN-12, Transnuclear Corp.	288
71-6244	Model: 6244, Chem-Nuclear Systems, Inc.	286	71-9132	Model: T-3, Nuclear Packaging, Inc.	288
71-6272	Model: Poly Panther, Nuclear Engineering Co.	286	71-9506	Model: MS27684-2, Energy, Dept. of	288
71-6273	Model: 48X, F, A, Y, Allied-General Nuclear Services	286	71-9785	Model: SZW/SZWA, Energy, Dept. of	288
71-6346	Model: FSV-1, General Atomic Co.	286	71-9852	Model: DT-14, Energy, Dept. of	288
71-6386	Model: 235R001, Energy, Dept. of	286			
71-6387	Model: 60, Battelle Memorial Institute	286			
71-6400	Model: Super Tiger, Westinghouse Electric Corp.	286			
71-6553	Model: Paducah Tiger, Energy, Dept. of	286			
71-6679	Model: 1/2 Super Tiger, Nuclear Engineering Co.	286			

ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Accelerator Pulsed Fast Assembly	50-235	26	Battelle Memorial Inst. Critical Facility	50-360	173
Aerojet General Nucleonics	50-32	11	Battelle Memorial Inst. Research Reactor	50-6	7
Aerojet General Nucleonics	50-53	11	Beaver Valley Power Station, Unit 1	50-334	149
Aerojet General Nucleonics	50-103	13	Beaver Valley Power Station, Unit 2	50-412	203
Aerotest Radiography & Research Reactor	50-228	26	Bellefonte Nuclear Plant, Unit 1	50-438	209
Allens Creek Nuclear Station, Unit 1	50-466	227	Bellefonte Nuclear Plant, Unit 2	50-439	210
Allens Creek Nuclear Station, Unit 2	50-467	229	Bernau Nuclear Station, Unit 1	50-273	61
Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	206	Big Rock Point Nuclear Power Plant	50-155	16
Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	207	Black Fox Station, Unit 1	STN-50-556	263
Alvin W. Vogtle Nuclear Plant, Unit 3	50-426	208	Black Fox Station, Unit 2	STN-50-557	264
Alvin W. Vogtle Nuclear Plant, Unit 4	50-427	208	Blue Hills Station, Unit 1	50-510	247
Arkansas Nuclear One, Unit 1	50-313	100	Blue Hills Station, Unit 2	50-511	248
Arkansas Nuclear One, Unit 2	50-368	178	BOP SAR, C.F. Braun	STN-50-532	259
Army Materials Research Reactor	50-47	11	Braidwood Station, Unit 1	50-456	221
ASCO, Unit 1	50-430	208	Braidwood Station, Unit 2	50-457	222
Atlantic Generating Station, Unit 1	STN-50-477	230	Brigham Young Univ. Research Reactor	50-262	46
Atlantic Generating Station, Unit 2	STN-50-478	230	Browns Ferry Nuclear Power Station, Unit 1	50-259	41
Babcock & Wilcox Co. Critical Facility	50-13	9	Browns Ferry Nuclear Power Station, Unit 2	50-260	42
Babcock & Wilcox Co. Critical Facility	50-191	19	Browns Ferry Nuclear Power Station, Unit 3	50-296	84
Babcock & Wilcox Test Reactor	50-99	13	Brunswick Steam Electric Plant, Unit 2	50-324	135
Babcock & Wilcox Test Reactor	50-200	19	Brunswick Steam Electric Plant, Unit 1	50-325	137
Bagnac Nuclear Power Project	STN-50-574	267	Byron Station, Unit 1	50-454	219
Bally Generating Station	50-367	178	Byron Station, Unit 2	50-455	220
essing Plant	50-332	148	California State Polytech College Research Reactor	50-394	192
	50-524	256	Calloway Plant, Unit 1	STN-50-483	232
	50-525	256			
	50-14	9			

Name	Docket	Page	Name	Docket	Page
Calloway Plant, Unit 2	STN-50-486	234	Douglas Point Nuclear Station, Unit 2	50-449	219
Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	106	Dow Chemical Co.	50-264	47
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	107	Dresden Nuclear Power Station, Unit 1	50-10	7
Carroll Facility I	50-599	271	Dresden Nuclear Power Station, Unit 2	50-237	26
Carroll Facility II	50-600	271	Dresden Nuclear Power Station, Unit 3	50-249	32
Catawba Nuclear Station, Unit 1	50-413	203	Duane Arnold Energy Center	50-331	146
Catawba Nuclear Station, Unit 2	50-414	204	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	130
Catholic Univ. of America Research Reactor	50-77	12	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	176
Cherokee Nuclear Station, Unit 1	STN-50-491	236	Enrico Fermi Atomic Power Plant, Unit 1	50-16	9
Cherokee Nuclear Station, Unit 2	STN-50-492	237	Enrico Fermi Atomic Power Plant, Unit 2	50-341	160
Cherokee Nuclear Station, Unit 3	STN-50-493	238	Erie Nuclear Plant, Unit 1	STN-50-580	267
Clinch River Breeder Reactor	50-537	259	Erie Nuclear Plant, Unit 2	STN-50-581	267
Clinton Power Station, Unit 1	50-461	225	Floating Nuclear Plant	STN-50-437	208
Clinton Power Station, Unit 2	50-462	226	Forked River Nuclear Station, Unit 1	50-363	175
Columbia Univ. Research Reactor	50-208	21	Fort Calhoun Station, Unit 1	50-285	74
Comanche Peak Steam Electric Station, Unit 1	50-445	213	Fort Calhoun Station, Unit 2	50-548	261
Comanche Peak Steam Electric Station, Unit 2	50-446	216	Fort St. Vrain Nuclear Generating Station	50-267	50
Cooper Nuclear Station	50-298	86	Fulton Generating Station, Unit 1	50-463	226
Cornell Univ. Research Reactor	50-157	18	Fulton Generating Station, Unit 2	50-464	226
Cornell Univ. Zero Power Reactor	50-97	12	General Atomic Co.	50-89	12
Crystal River Nuclear Plant, Unit 3	50-302	88	General Electric Co. Critical Experiment	50-24	9
Crystal River Nuclear Plant, Unit 4	50-303	91	General Electric Test Reactor	50-70	12
Davis-Besse Nuclear Power Station, Unit 1	50-346	164	General Electric Nuclear Test Reactor	50-7	--
Davis-Besse Nuclear Power Station, Unit 2	50-500	244	Georgia Institute of Technology Research Reactor		
Davis-Besse Nuclear Power Station, Unit 3	50-501	245	Georgia Institute of Technology Research Reactor		
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	61	GESSAR-238	STN	
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	133	GESSAR-238-BOP Interface	STN	
Donald C. Cook Nuclear Power Plant, Unit 1	50-315	103	GESSAR-251		
Donald C. Cook Nuclear Power Plant, Unit 2	50-316	105	GIBBSAR	STN	
Douglas Point Nuclear Station, Unit 1	50-448	218	Grand Gulf Nuclear Station, Unit 1		
			Grand Gulf Nuclear Station, Unit 2		
			Greene County Nuclear Power Plant		

Name	Docket	Page	Name	Docket	Page
Greenwood Energy Center, Unit 2	50-452	219	Marble Hill Nuclear Station, Unit 2	STN-50-547	260
Greenwood Energy Center, Unit 3	50-453	219	Massachusetts Institute of Technology Research Reactor	50-20	9
Hill Robinson Plant, Unit 2	50-261	44	Memphis State Univ. Research Reactor	50-538	259
Hudson Neck Plant	50-213	21	Mexico Research Reactor	50-233	26
Hartsville Nuclear Plant, Unit 1	STN-50-518	251	Michigan State Univ. Research Reactor	50-294	82
Hartsville Nuclear Plant, Unit 2	STN-50-519	251	Midland Plant, Unit 1	50-329	142
Hartsville Nuclear Plant, Unit 3	STN-50-520	252	Midland Plant, Unit 2	50-330	144
Hartsville Nuclear Plant, Unit 4	STN-50-521	253	Millstone Nuclear Power Station, Unit 1	50-245	29
Haven Nuclear Plant, Unit 1	STN-50-502	245	Millstone Nuclear Power Station, Unit 2	50-336	153
Haven Nuclear Plant, Unit 2	STN-50-503	246	Millstone Nuclear Power Station, Unit 3	50-423	206
High Temp. Gas Cooled Critical Experiment	50-240	28	Mississippi State Univ. Research Reactor	50-241	28
Hope Creek Nuclear Station, Unit 1	50-354	169	Monticello Nuclear Generating Plant	50-263	46
Hope Creek Nuclear Station, Unit 2	50-355	169	National Bureau of Standards Reactor	50-184	18
Humboldt Bay Power Plant, Unit 3	50-133	14	National Naval Medical Center	50-170	18
Idaho State Univ. Research Reactor	50-284	74	NEP Nuclear, Unit 1	STN-50-568	267
Indian Point Station, Unit 1	50-3	6	NEP Nuclear, Unit 2	STN-50-569	267
Indian Point Station, Unit 2	50-247	31	New Haven, Unit 1	50-596	269
Indian Point Station, Unit 3	50-286	76	New Haven, Unit 2	50-597	270
Iowa State Univ. Research Reactor	50-116	13	Nine Mile Point Nuclear Station, Unit 1	50-220	24
James A. Fitzpatrick Nuclear Power Plant	50-333	148	Nine Mile Point Nuclear Station, Unit 2	50-410	202
Jamesport Nuclear Station, Unit 1	STN-50-516	250	North Anna Power Station, Unit 1	50-338	154
Jamesport Nuclear Station, Unit 2	STN-50-517	250	North Anna Power Station, Unit 2	50-339	158
Joseph M. Farley Nuclear Plant, Unit 1	50-348	166	North Anna Power Station, Unit 3	50-404	199
Joseph M. Farley Nuclear Plant, Unit 2	50-364	176	North Anna Power Station, Unit 4	50-405	200
			North Carolina State Univ. PULSTAR Reactor	50-297	85
			North Carolina State Univ. Research Reactor	50-8	7
			North Carolina State Univ. Research Reactor	50-111	13
			San Juan Nuclear Plant (Puerto Rico)	50-376	185
			University of Tennessee Research Reactor	50-598	271
			University of Tennessee Research Reactor	50-375	185
			University of Tennessee Research Reactor	50-564	266

Name	Docket	Page	Name	Docket	Page
Oconee Nuclear Station, Unit 1	50-269	52	Point Beach Nuclear Plant, Unit 2	50-301	87
Oconee Nuclear Station, Unit 2	50-270	55	Prairie Island Nuclear Station, Unit 1	50-282	72
Oconee Nuclear Station, Unit 3	50-287	77	Prairie Island Nuclear Station, Unit 2	50-306	94
Ohio State Univ. Research Reactor	50-150	16	Purdue Univ. Research Reactor	50-182	18
Omaha Veterans Administration Hospital Research Reactor	50-131	14	Quad-Cities Station, Unit 1	50-254	38
Oregon State Univ.	50-106	13	Quad-Cities Station, Unit 2	50-265	48
Oregon State Univ. Research Reactor	50-243	28	Rancho Seco Nuclear Generating Station	50-312	99
Oyster Creek Nuclear Power Plant	50-219	22	Reed College Research Reactor	50-288	80
Pallsades Nuclear Plant	50-255	39	Rhode Island & Providence Plantations AEC	50-193	19
Palo Verde Nuclear Station, Unit 1	STN-50-528	256	River Bend Station, Unit 1	50-458	223
Palo Verde Nuclear Station, Unit 2	STN-50-529	257	River Bend Station, Unit 2	50-459	224
Palo Verde Nuclear Station, Unit 3	STN-50-530	258	Rockwell International Corp. Critical Facility	50-147	16
Palo Verde Nuclear Station, Unit 4	STN-50-592	268	Rockwell International Research Reactor	50-94	12
Palo Verde Nuclear Station, Unit 5	STN-50-593	268	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	28
Pawling Research Reactor	50-54	11	RPI Critical Experiment	50-225	25
Peach Bottom Atomic Power Station, Unit 1	50-171	18	Salem Nuclear Generating Station, Unit 1	50-272	58
Peach Bottom Atomic Power Station, Unit 2	50-277	64	Salem Nuclear Generating Station, Unit 2	50-311	97
Peach Bottom Atomic Power Station, Unit 3	50-278	66	San Onofre Nuclear Station, Unit 1	50-206	19
Pebble Springs Nuclear Plant, Unit 1	50-514	249	San Onofre Nuclear Station, Unit 2	50-361	173
Pebble Springs Nuclear Plant, Unit 2	50-515	249	San Onofre Nuclear Station, Unit 3	50-362	174
Pennsylvania State Univ. Research Reactor	50-5	7	Saxton Nuclear Experimental Facility	50-146	16
Perkins Nuclear Station, Unit 1	STN-50-488	234	Seabrook Nuclear Station, Unit 1	50-443	211
Perkins Nuclear Station, Unit 2	STN-50-489	235	Seabrook Nuclear Station, Unit 2	50-444	212
Perkins Nuclear Station, Unit 3	STN-50-490	236	Sequoyah Nuclear Plant, Unit 1	50-327	139
Perry Nuclear Power Plant, Unit 1	50-440	210	Sequoyah Nuclear Plant, Unit 2	50-328	141
Perry Nuclear Power Plant, Unit 2	50-441	211	Shearon Harris Nuclear Power Plant, Unit 1	50-400	194
Phipps Bend Nuclear Plant, Unit 1	50-553	262	Shearon Harris Nuclear Power Plant, Unit 2	50-401	196
Phipps Bend Nuclear Plant, Unit 2	50-554	263	Shearon Harris Nuclear Power Plant, Unit 3	50-402	197
Pilgrim Nuclear Power Station, Unit 1	50-293	81	Shearon Harris Nuclear Power Plant, Unit 4	50-403	198
Pilgrim Nuclear Power Station, Unit 2	50-471	229	Shoreham Nuclear Power Station	50-322	131
Pilgrim Nuclear Power Station, Unit 3	50-472	230			
Plum Brook Research Reactor Facility	50-30	11			
Point Beach Nuclear Plant, Unit 1	50-266	49			

Name	Docket	Page	Name	Docket	Page
Summit Nuclear Power Project, Unit 1	STN-50-522	254	UCLA Training Reactor	50-142	16
Summit Nuclear Power Project, Unit 2	STN-50-523	255	UC-Santa Barbara Research Reactor	50-433	208
South Texas Project, Unit 1	STN-50-498	239	Univ. of Arizona Research Reactor	50-113	13
South Texas Project, Unit 2	STN-50-499	241	Univ. of California Research Reactor	50-84	12
Space Radiation Research Reactor	50-187	18	Univ. of California Research Reactor	50-224	25
Stanford Univ. Research Reactor	50-141	16	Univ. of Florida Training Reactor	50-83	12
Swelling Power Project, Nuclear, Unit 1	STN-50-485	233	Univ. of Illinois Research Reactor	50-151	16
St. Lucie Plant, Unit 1	50-335	151	Univ. of Kansas Research Reactor	50-148	16
St. Lucie Plant, Unit 2	50-389	188	Univ. of Lowell Research Reactor	50-223	25
Summit Nuclear Power Station, Unit 1	50-450	219	Univ. of Maryland Research Reactor	50-166	18
Summit Nuclear Power Station, Unit 2	50-451	219	Univ. of Michigan Research Reactor	50-2	6
Surry Power Station, Unit 1	50-280	67	Univ. of Missouri Research Reactor	50-123	13
Surry Power Station, Unit 2	50-281	70	Univ. of Missouri Research Reactor	50-186	18
Susquehanna Steam Electric Station, Unit 1	50-387	186	Univ. of New Mexico Research Reactor	50-252	38
Susquehanna Steam Electric Station, Unit 2	50-388	187	Univ. of Oklahoma Research Reactor	50-112	13
SWFSSAR-PI	STN-50-495	239	Univ. of Texas Research Reactor	50-192	19
Texas A & M Univ. Research Reactor	50-59	11	Univ. of Utah Research Reactor	50-72	12
Texas A & M Univ. Research Reactor	50-128	14	Univ. of Utah Research Reactor	50-407	201
Texas A & M Univ. Research Reactor	50-129	14	Univ. of Virginia Cavaller Reactor	50-396	193
Three Mile Island Nuclear Station, Unit 1	50-289	80	Univ. of Virginia Research Reactor	50-62	11
Three Mile Island Nuclear Station, Unit 2	50-320	108	Univ. of Washington Research Reactor	50-139	16
			Univ. of Wisconsin Research Reactor	50-156	17
			U.S. Geological Survey Research Reactor	50-274	61
			Vallecitos Boiling Water Reactor	50-18	9
			Vallecitos Experimental Superheat Reactor	50-183	18
			Vermont Yankee Nuclear Power Station	50-271	57
			Virgil C. Summer Nuclear Station, Unit 1	50-395	192
			Virginia Polytech Inst. Training Reactor	50-124	14
			Washington State Univ. Research Reactor	50-27	10
			Waterford Generating Station, Unit 3	50-382	185
			Watts Bar Nuclear Plant, Unit 1	50-390	189

Name	Docket	Page	Name	Docket	Page
Watts Bar Nuclear Plant, Unit 2	50-391	191	WPPSS Nuclear Project, Unit 1	50-460	224
Westinghouse Critical Experiment	50-87	12	WPPSS Nuclear Project, Unit 2	50-397	193
Westinghouse Test Reactor	50-22	9	WPPSS Nuclear Project, Unit 3	STN-50-508	246
West Valley Reprocessing Plant	50-201	19	WPPSS Nuclear Project, Unit 4	50-513	248
William B. MacGuire Nuclear Station, Unit 1	50-369	180	WPPSS Nuclear Project, Unit 5	STN-50-509	247
William B. MacGuire Nuclear Station, Unit 2	50-370	182	Yankee-Rowe Nuclear Power Station	50-29	10
William H. Zimmer Nuclear Station, Unit 1	50-358	170	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	266
Wolf Creek Generating Station	STN-50-482	230	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	266
Worcester Polytech Inst. Research Reactor	50-134	16	Zion Nuclear Power Station, Unit 1	50-295	82
			Zion Nuclear Power Station, Unit 2	50-304	91

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL : NUCLEAR ENGINEERING CO

7905100225 Motion by licensee for emergency action to rescind NMSS 790320 order to show cause Seeks to refer matter to ASLB Affidavit of TB Baer encl CONNER, T B , RADER, R Conner, Moore & Corber 79/03/22 19pp

7905310010 Response to 790320 order to show cause Order should be found void; denies any violation of license Certificate of Bvc encl CONNER, T B Conner, Moore & Corber 79/03/23 9pp

7905250372 Response to ASLB 790313 directive Concurs w/NRC 790320 motion that license applications may only be withdrawn per NRC terms & conditions Request to file instant. affidavit of SN Sekuler & Certificate of Bvc encl SCOTT, W J , SEKULER, B N Illinois, State of 79/03/24 13pp

7905100248 NRC response to licensee's motion for emergency action Urges denial of request to rescind 790320 order to show cause why licensee should not resume obligations under DL Supporting documentation & Certificate of Bvc encl. REIS, E J Branch 3 79/04/02 26pp.

7905030168 Forwards Bureau County Circuit Court, IL, order granting preliminary injunctive relief re operation of facility REIS, E J Branch 3 79/04/03 1p

--7905030171 Order granting preliminary injunctive relief & ordering licensee to take certain actions re facility * Illinois, State of 79/03/27 7pp

7905100237 Post-hearing brief submitted by licensee re issues arising during 790327 oral argument before ASLB. Responds to positions of NRC & State of IL Certificate of Bvc encl. CONNER, T B Conner, Moore & Corber. 79/04/03 30pp

7905240138 Proposed corrections to transcript of 790327 oral argument in Peoria, IL Certificate of Bvc encl CONNER, T B Conner, Moore & Corber 79/04/03 4pp

7905140153 FOIA request for all records, studies, correspondence & repts re decommissioning of reactor & shipment of decommissioned matl to Sheffield low level nuclear waste site HANSELL, D, Illinois, State of 79/04/06 2pp.

7905130521 Reply to applicant's motion for emergency action & to applicant's answer to show cause. Supporting documentation & Certificate of Bvc encl HANSELL, D Illinois, State of 79/04/06 94pp

7905110172 Responds to 790313 ltr re Nuclear Engineering Co illegal abandonment of Sheffield, IL low level nuclear waste burial ground. Forwards 790320 order to show cause why company should not resume responsibilities & obligations DIRCKS, W J Office of Nuclear Material Safety & Safeguards 79/04/09 2pp

--7905110181 Expresses concern w/illegal abandonment by Nuclear Engineering Co of its Sheffield, IL nuclear waste site Requests NRC intervene to secure site until matter of responsibility is adjudicated. DEMUZIO, V Illinois, State of. 79/03/13. 1p.

7905240299 Lists conditions by which proceeding may be dismissed relevant to site decommissioning & protection of public health & safety REIS, E J. Branch 3. 79/04/10. 3pp.

7905310392 Response by intervenor Bureau County, IL to ASLB 790327 hearing. State of IL licensees are jointly responsible for maint of waste disposal site Certificate of Bvc encl MADSON, B Illinois, State of 79/04/10. 7pp.

7905070364 Forwards 790330 ltr discussing insp of License 13-10042-01 on 790309, 16, 21-23 & 29 Ltr referenced in reply to applicant's motion for emergency action & applicant's order to show cause HANSELL, D, Illinois, State of. 79/04/11. 1p.

7905020157 Responds to 790227 ltr re plans to prepare EIS for low level radioactive waste burial ground EIS has been delayed because applicant has withdrawn its application & has not complied w/requests for addl info CORNELL, E K Office of the Executive Director for Operations 79/04/12 2pp

7905100372 Forwards signed affidavit by MJ Bell of Low Level Waste Branch to be included in NRC response to licensee's motion for emergency action, to replace earlier unsigned version REIS, E J Branch 3 79/04/12 6pp

7905310273 Discusses conditions precedent to Nuclear Engineering Co withdrawal of application & termination of activities Licensee should fulfill obligations Supporting documentation & Certificate of Bvc encl SEKULER, B N Illinois, State of 79/04/12 63pp

7905241004 Cites objections to draft interim branch position re low level waste burial ground site closure & stabilization Most of position is reasonable REYNOLDS, L E Chem-Nuclear Systems, Inc 79/04/13 2pp

7905240579 Grants NRC & intervenors' motion to dismiss license amend for site expansion Denies licensee's motion for withdrawal of application for license renewal & motion to dismiss proceedings LITTLE, L W , REMICK, F J , OODHOPE, A C Atomic Safety and Licensing Board Panel 79/05/03 6pp

7905140155 Partial response to FOIA request for records re decommissioning of reactor & shipping of decommissioned matl Ltrs forwarded from IL Dept of Public Health dtd 730201, 730124, 700116, 700102, 720324 & 720223 encl FELTON, J M Division of Rules and Records 79/05/07 8pp

DOCKET 27-047 BARNHILL, SC :CHEM-NUCLEAR SYSTEMS

7905220454 Requests that Condition 10 contained in Amend 12 to License 46-13536-01 be retained in future license amends re U-235 waste burial CORSETT, J S Chem-Nuclear Systems, Inc 78/01/10 1p

7905250232 Discusses request for amend to License 45-13536-10 which would permit local power range monitors containing plutonium Prior to amend issuance, written permission from SC for plutonium burial must be obtained DRAGONETTE, K S. Low Level Waste Branch (Pre 790501) 79/04/04 1p

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0299 UNION CARBIDE CORP

7905010501 Requests amend to License 6UA-64B to permit receiving & processing of carbonate solution. Shipments are to begin 790515. REKEHEVER, P C. Union Carbide Corp 79/03/29 1p

7905020280 Comments on DES corrects factual errors in rept. Planned monitoring program should be adequate DEXTER, W D Wyoming, State of 79/03/30 1p

7905030132 Forwards 790221 "Environ Assessment of Below Grade U Tailing Disposal in A-9 Open Pit, East Gas Hills U Mine & Mill, WV, for Union Carbide Corp " MURDOCK, L T Dames & Moore 79/04/10. 1p

--7905030136 "Environ Assessment of Below Grade U Tailing Disposal in A-9 Open Pit, East Gas Hills U Mine & Mill, WV, for Union Carbide Corp. " MURDOCK, L T Dames & Moore 79/02/21 117pp

7905130613 Summary of 790301 meeting w/Union Carbide Corp in Silver Spring, MD re comments on DES. LINEHAM, J J Assistant Director for Waste Management (Pre 790301) 79/04/16. 2pp.

DOCKETED ITEMS

7905290033 Provides supplemental info requested in 790416 telcon re East Coast Hills heap leach
REDEMEYER, P C Union Carbide Corp 79/04/17 4pp

7905100113 Forwards supplementary info re source matl license: drawings of proposed heap leach & description of reclamation plant & costs Oversized drawings encl
REDEMEYER, P C Union Carbide Corp 79/04/19 7pp.

DOCKET 40-1162 WESTERN NUCLEAR, INC

7905170292 Forwards info requested by 790314 telcon re sediment samples from Green Mountain IX Marsh
BESKID, N Western Nuclear, Inc (subs of Phelps Dodge Corp.)
79/03/29 5pp

7905300147 Requests determination of need for toe drain prior to approval of tailings mgmt sys
BOGDEN, G Western Nuclear, Inc (subs of Phelps Dodge Corp.)
79/04/06 2pp

7905240442 Forwards addl copies of map showing location of wells & well water monitoring results for 1977-78.
BOGDEN, G Western Nuclear, Inc (subs of Phelps Dodge Corp.)
79/04/16 1p

--7905240457 Forwards map & chart showing location of wells & well water monitoring results for 1977-78
BOGDEN, G Western Nuclear, Inc (subs of Phelps Dodge Corp.)
79/04/09 6pp

DOCKET 40-2061 WEST CHICAGO FACILITY, KERR-MCQUEE CORP

7905100064 Confirms 780410 discussion re encl comments on decommissioning plan Plan submitted is not acceptable, due to lack of detail for preparation of EIA Outlines major deficiencies W/suggested format for plan
CROW, H T Fuel Process & Fab Branch 79/04/12 14PP

--7905100071 Forwards Region III comments on Kerr-McQuee decommissioning plan Thickness of "clay substructure" should be stated, environ criteria for radioactivity should be specified & "air scrubber sys" should be elaborated
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch, 79/03/08 3pp

--7905100078 Forwards comments on Kerr-McQuee decommissioning plan W/o encl
CATALANO, G R West Chicago, IL 79/03/14 1p

--7905100089 Summary of activities of IL State Geological Survey & data collected in attempts to locate suitable site for disposal of thorium-bearing solid wastes from Kerr-McQuee facility.
CARTWRIGHT, K Illinois, State of 79/01/11 3pp

--7905100094 Forwards "Liners for Sanitary Landfills & Chemical & Hazardous Waste Disposal Sites," EPA-600/9-78-005, May 1978, in response to 790214 meeting re decommissioning at Kerr-McQuee facility W/o encl
ORIGALAUSKI, C T Environmental Protection Agency 79/02/16 1p

7905240114 Requests amend to 790305 request re thorium residuals in West Chicago Decommissioning plan for West Chicago facility should be resolved within six months of date of ltr.
SPELMAN, H J West Chicago, IL 79/04/18 2pp.

DOCKET 40-2259 PATHFINDER MINES CORP

7905220039 Amends License SUA-672 to change name of licensee, modify yellowcake drying & packaging dust collection sys, & barreling area
SCARANO, R A Radioisotopes Licensing Branch (Pre 790501)
79/03/22 3pp

7905250011 Recommends approval of Pathfinder Mine Corp's request for Amend 4 to License SUA-672 authorizing mods to dust collection sys serving yellowcake dryer & packaging area.
SCARANO, R A, ROSSBACH, L H Radioisotopes Licensing Branch (Pre 790501) 79/03/22 4pp

7905240849 Forwards NRC positions & second round request for addl info re geology & geotechnical engineering of tailings retention project
SCARANO, R A Radioisotopes Licensing Branch (Pre 790501),
79/03/30 6pp

7905250176 Review of 790316 responses to requests for info have been completed & determined to be inadequate Forwards request for addl info re probable max 6-h rainfall value & area draining into pond associated w/proposed Tailings Dam Addition 4
SCARANO, R A Fuel Process & Fab Branch 79/04/09 3pp

7905290488 Forwards request for addl info to complete radiological assessment for amend request Requests response by 790504
SCARANO, R A Division of Fuel Cycle & Material Safety 79/04/10 4pp

7905100025 Responds to 790330 ltr Provides clarification & addl info re tailings mod plans, including area archeological inventory.
NUGENT, E L Pathfinder Mines Corp 79/04/20 27pp

DOCKET 40-2407 FELLOWS MEDICAL MFG CO, INC

7905230115 Response to FOIA request for info re Thorotrast, its licensing, manufacturers & licensees Forwards records contained in Docket 40-2407
FELTON, J M Division of Rules and Records 79/03/07 1p

--7905230132 Notifies Source Matl License STB-67B for Fellows Medical Co Inc is terminated Forwards 691110 ltr, radiation survey & evaluation rept on isotope preparation
HARMON, D F Atomic Energy Commission (Pre 1975) 69/12/09 3pp

--7905230197 Notifies of issuance of License C-5155 for Testagar & Co authorizing use of thorium oxalate in mfg of Thorotrast & Umbrator
DELANEY, J C Atomic Energy Commission (Pre 1975) 66/06/10 1p

--7905230201 Notifies of issuance of License R-152 for Testagar & Co authorizing use of thorium oxalate in mfg of Thorotrast & Umbrator
DELANEY, J C Atomic Energy Commission (Pre 1975) 69/03/03 1p

--7905230204 Notifies of issuance of License R-152 for Testagar & Co, Inc authorizing thorium oxalate for use in mfg of Thorotrast & Umbrator
JOHNSON, L Atomic Energy Commission (Pre 1975) 65/12/07 1p

--7905230214 Requests termination of License STB-67B Bldg at 1334 W Lafayette Boulevard, Detroit, MI should be released from license for destruction
CARRIGAN, R H Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 69/12/03 1p

--7905230219 Requests rept indicating that radioactivity limits of 4806 ltr have been met Application for license amend to be filed re proposed activities at new locations Encl radioactive limits set
HARMON, D F Atomic Energy Commission (Pre 1975) 68/08/14 2pp

--7905230255 Requests addl info on procedures for evaluating personnel exposure to airborne radioactivity, in response to 440911 application for renewal of License STB-67B
LAVFIELD, R L Atomic Energy Commission (Pre 1975), 64/10/22 2pp

--7905230284 Requests renewal of License STB-67B
CARRIGAN, R H Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 64/06/11 1p

--7905230313 Requests max quantity of source matl be change from 100 to 300 lb to maintain production levels
CARRIGAN, R H Fellows Medical Mfg Co, Inc, Fellows-Testagar Div, 63/02/07 1p

--7905230320 Advises that licensee dissolved 680831 Merger approved w/Fellows Medical Mfg Co, Inc New name as of 630101 is Fellows-Testagar Co Officers remain same, except for secretary & treasurer positions Mfg to be done in Detroit
CARRIGAN, R H Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 62/12/31 1p

--7905230342 Repeats 610521 request for info re license renewal, to determine if source matl use meets 610213 criteria
NUSSBAUMER, D A Atomic Energy Commission (Pre 1975) 61/05/23 1p.

--7905230345 Clarifies that request is for renewal of license, as opposed to application for new license
CARRIGAN, R H Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 61/05/05 1p

DOCKETED ITEMS

3

- 7905230348 Requests info necessary for application for renewal of License R-152 Application must include max quantity of matl to be possessed, safeguard procedure, list of survey instruments & methods of radioactive waste disposal
NUSSBAUMER, D A Atomic Energy Commission (Pre 1975) 61/05/02 1p
- 7905230351 Requests renewal of License R-152
CARRIGAN, R H. Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 61/03/28 1p
- 7905230352 Requests renewal of License R-152
CARRIGAN, R H. Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 60/06/02 1p
- 7905230357 Requests renewal of License R-152
CARRIGAN, R H. Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 59/02/18 1p
- 7905230370 Responds to 580314 request for info re License R-152 Thorium oxalate to be used for medical profession Personnel handling matl wear gowns, protective masks & work in isolated rooms Matl measured solely by badges
CARRIGAN, R H. Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 58/04/10 2pp
- 7905230374 Responds to licensee 580320 ltr Requests submittal of info requested in NRC 580314 ltr before renewal of source matl license can be considered
DELANEY, J C Atomic Energy Commission (Pre 1975) 58/04/01 1p
- 7905230390 Application for renewal of License R-152 authorizing use of thorium oxalate in x-ray media
CARRIGAN, R H. Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 56/11/26 3pp
- 7905230139 Forwards renewed Source Matl License STB-678
HARMON, D F Atomic Energy Commission (Pre 1975) 69/03/05 1p
- 7905230145 Source Matl License STB-678 for Fellows Medical Mfg Co, Inc authorizing use of thorium as described in 680216 application
HARMON, D F Radioisotopes Licensing Branch (Pre 1975) 68/03/04 1p
- 7905230150 Forwards renewed Source Matl License STB-678
NUSSBAUMER, D A Atomic Energy Commission (Pre 1975) 68/04/12 1p
- 7905230160 Source Matl License STB-678 for Fellows-Testagar Co authorizing use of thorium as described in 610607 & 610818 applications
* Radioisotopes Licensing Branch (Pre 1975) 69/04/12 2pp
- 7905230164 Forwards Source Matl License STB-678
NUSSBAUMER, D A Atomic Energy Commission (Pre 1975) 63/01/23 1p
- 7905230177 Source Matl License STB-678 for Fellows-Testagar Co authorizing use of U & thorium as described in 610607, 610727, & 610818 applications
NUSSBAUMER, D A Radioisotopes Licensing Branch (Pre 1975) 69/01/23 1p
- 7905230183 Forwards Source Matl License STB-404
NUSSBAUMER, D A Atomic Energy Commission (Pre 1975) 61/08/25 1p
- 7905230193 License STB-404 for Testagar & Co, Inc authorizing use of thorium as described in 610607, 610727, & 610818 application.
NUSSBAUMER, D A Radioisotopes Licensing Branch (Pre 1975) 61/08/25 1p
- 7905230226 Notifies of equipment for mfg of Thorotrast to be dismantled, moved, or disposed within next two months
CARRIGAN, R H. Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 68/08/07 1p
- 7905230233 Application for renewal of License STB-678 authorizing use of oxalate in mfg of sterile x-ray contrast medium
CARRIGAN, R H. Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 68/02/14 2pp
- 7905230250 Approves extension of time for submission of info requested in 641022 ltr
LAYFIELD, R L. Atomic Energy Commission (Pre 1975) 64/11/12 1p
- 7905230261 Ack receipt of AEC 640818 ltr Evaluation of personnel radiation exposure accomplished by readings of personnel badges & urine analyses Lab wiped down periodically Survey encl
CARRIGAN, R H. Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 64/09/11 2pp
- 7905230270 Requests addl info on procedures for evaluating personnel exposure to airborne radioactivity & airborne activity in exhaust fan effluent, in response to 640715 application for renewal of License STB-678
LAYFIELD, R L. Atomic Energy Commission (Pre 1975) 64/08/18 2pp
- 7905230276 Application for renewal of License STB-678 authorizing use of thorium oxalate in mfg of sterile x-ray contrast
CARRIGAN, R H. Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 64/07/15 2pp
- 7905230291 Requests replies to AEC 630312 questions Amend to License STB-678 to be filed on Form AEC-2.
NUSSBAUMER, D A Atomic Energy Commission (Pre 1975) 63/07/29 1p
- 7905230299 Inquires whether current source matl license needs to be amended to incorporate handling of Th-320 for ANL.
CARRIGAN, R H. Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 63/07/08 1p
- 7905230306 Discusses AEC 630312 ltr requesting addl info re application for amend of License STB-678 Detroit Health Dept called to assist in evaluation.
CARRIGAN, R H. Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 63/04/16 1p
- 7905230312 Requests addl info re amend of License STB-678 authorizing use of addl 200 lb of thorium Requires description of procedures for evaluating personnel exposure to airborne activity & decontamination control within lab
NUSSBAUMER, D A. Fellows Medical Mfg. Co, Inc, Fellows-Testagar Div 63/03/12 1p
- 7905230328 Submits info as amend to Parts 1,2 & 3 of 610607 application for License R-152 Max quantity of source matl to be possessed is 100 lb Dust inhalation masks contain CR 72292 Comfo Respirator dust filter
CARRIGAN, R H. Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 61/08/18 2pp
- 7905230332 Informs licensee not yet received Requests issuance of license or reasons for not receiving license.
CARRIGAN, R H. Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 61/07/27 1p.
- 7905230338 Applies for renewal of License R-152
CARRIGAN, R H. Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 61/06/07 2pp
- 7905230380 Ack receipt of AEC 580314 ltr re renewal of License R-152 Insp indicates controls & safety precautions in order Inquires whether written rept of insp desired
CARRIGAN, R H. Fellows Medical Mfg. Co., Inc., Fellows-Testagar Div 58/03/20 1p.
- 7905230386 Requests addl info on activities, safeguard procedures, survey instrument description & method of waste disposal, in response to 580304 application for renewal of License R-152
DELANEY, J C Atomic Energy Commission (Pre 1975) 58/03/14 1p.
- 7905230388 Requests renewal of License R-152.
CARRIGAN, R H. Fellows Medical Mfg Co, Inc, Fellows-Testagar Div 58/03/04 1p

DOCKET 40-3392 ALLIED CHEMICAL CORP

- 7905220109 Forwards info requested by NRC 790115 ltr & 790226 memo re compliance of Metropolis, IL Works w/requirements of 40CFR190 Stock emission & lung fluid solubility data encl.
NEWMAN, R. I. Allied Chemical Corp, 79/03/22, 28pp
- 7905290655 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-3392/79-01
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/26 1p

DOCKETED ITEMS

--7903290665 Responds to NRC 790323 ltr re violations noted in IE Insp Rept 40-3392/79-01 Corrective actions preparation of DA manual, new air sampling lines installed & new constant air monitor installed
THOMAS, J H Allied Chemical Corp, Nuclear Services Div
79/04/10 3pp

DOCKET 40-3453 ATLAS MINERALS

7903240200 Summary of 790402 meeting w/Atlas Minerals Corp re reclamation surety arrangements Itemized cost breakdown will be conducted to finalize surety posting process Followup meeting scheduled for 790427 to finalize surety arrangement
DANIELS, R W Utah, State of 79/04/02 1p

DOCKET 40-4492 FEDERAL AMERICAN PARTNERS

7903230681 Forwards IE Insp Rept 40-4492/79-01 on 790301 No noncompliance noted
BROWN, G D Region 4, Dallas, Office of the Director 79/03/15 6pp

--7903230693 IE Insp Rept 40-4492/79-01 on 790301 No noncompliance noted Major areas inspected tailings area & retention dam
WILBORN, L L, BROWN, G D Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/03/14 6pp

7903020222 Hydrologic engineering info requested on 790226 has been sent by consultants, but will be resubmitted second time
JACKSON, F D, WRIGHT, K H Federal American Partners 79/04/04 5pp

7903070032 Forwards rept on radiological tissue analysis of WY animals & rept of five environ monitoring stations
JACKSON, F D Federal American Partners 79/04/04 2pp

--7903070037 "Radiological Tissue Analysis of Selected Plants & Animals Collected from WY U Districts."
KENNINGTON, G S, DOERGE, J E Wyoming, Univ of 78/10/31 48pp

7903240444 Forwards info re radiation monitoring program for total particulates, Rn-222, Th-230, Ra-226, Pb-210 & natural U
JACKSON, F D Federal American Partners 79/04/30 19pp

7903240732 "Supplemental Geotechnical Investigation & Stability Analysis for Proposed Tailing Dam 2 " Oversized drawings encl
* Federal American Partners 79/04/30 47pp

DOCKET 40-4602 MORTON RANCH URANIUM HILL

7903100407 Comments on DES for facility No significant environ impacts in areas of agency's concern
HEINEMANN, J H Federal Energy Regulatory Commission 79/03/16 1p

DOCKET 40-6639 PETROTONICS CO., GETTY OIL

7903150616 Summary of 790228 meeting w/Petrotonics in Silver Spring, MD re upgrading of environ & effluent monitoring program.
LINEHAN, J J Assistant Director for Waste Management (Pra 790301) 79/04/15 2pp.

7903100284 Forwards requested info to update environ monitoring program One oversized drawing encl
PFAFF, S J Petrotonics, Inc 79/04/20 11pp

7903240548 Notices of withdrawal of request for const mod of tailings dam Will continue to follow original design approved on 780602.
WHITMAN, J H Petrotonics, Inc 79/04/24. 1p

DOCKET 40-7086 ARMY, DEPT. OF

7903310001 IE Insp Findings & Licensee Ack dtd 790226-0301 of License SUB-734. Insp findings: no items of noncompliance found
* Region 4, Dallas, Office of the Director. 79/03/01. 1p

DOCKET 40-8027 KERR-MCGEE CORP

7903090003 Notices of Amend 3 to License SUB-1010 to include decommissioning plans & financial surety arrangements Requests correction of former amend numbers W/review of decommissioning plan
CROW, W T Fuel Process & Fab Branch 79/03/26 2pp

7903090008 Review of License SUB-1010 amend application for future decommissioning plan
CROW, W T Fuel Process & Fab Branch 79/03/26 3pp

7903090425 Forwards application for Amend 2 to License SUB-1010, dtd 780303, detailing plans for newly treated raffinate storage pond 3 Minor amend fee & oversized drawings encl
SHELLEY, W J US Nuclear, Inc 79/04/04 15pp

7903290479 Notices of amend to License SUB-1010, authorizing test distribution of barium treated neutralized solvent extraction raffinate over Kerr-McGee owned land
CROW, W T Fuel Process & Fab Branch 79/04/13 2pp

DOCKET 40-8035 COTTER CORP

7903250067 Confirms 790316 request for radiological survey of Bldg 21 of former Cotter Corp property in Hazelwood, MO Property previously released for unrestricted use Requests addl samples from Bldg 1
CROW, W T Fuel Process & Fab. Branch 79/04/16 1p

DOCKET 40-8064 EXXON MINERALS CO USA, EXXON CORP

7903250056 Forwards requested info on Monitor Wells O-9 at new solvents mining R&D site, & plot plan of R&D site showing relative location of leach field & monitor wells
FREEMAN, H D Exxon Minerals Co, USA 79/04/04 3pp

7903250538 Rept for first quarter 1979, including plot plan of R&D site well field, summaries of monitor well valves & sample well analyses
FREEMAN, H D Exxon Minerals Co, USA 79/04/19 15pp

DOCKET 40-8102 EXXON MINERALS CO USA, EXXON CORP

7903300691 Safety evaluation supporting amend to License SUA-1137 to permit solution process mining of U
COOPERSTEIN, R Fuel Process & Fab. Branch 79/01/25 27pp

7903150070 Confirms 790323 telcon re sandblasting of equipment which caused unrestricted release of airborne soluble U Radioactivity removed from room by wiping Forwards urine analyses from exposed employees W/o encl.
ORTLOFF, G D Exxon Minerals Co, USA 79/03/24 3pp

DOCKET 40-8158 ARMY, DEPT OF, COMMUNICATIONS & ELECTRONICS MATERIAL

7903100374 IE Insp Findings & Licensee Ack, dtd 790306, of License 29-01022-08, 29-01022-11, 29-01022-12, SUB-1150, SHB-1327 & SHB-1327 Insp findings no noncompliance noted
FRIEDMAN, L F Region 1, Philadelphia, Office of the Director 79/03/06. 1p.

DOCKET 40-8452 BEAR CREEK MINING CO

7903250304 Notices of individual's overexposure to airborne natural U on 790225. Caused by employee carelessness which created large cloud of dust using vane feeder repair in yellowcake dryer enclosure. Supervision of area increased
BAKER, J R Bear Creek Mining Co (subs of Kennecott Corp) 79/03/09 2pp

7903100223 Forwards engineering & reclamation drawings which provide details of revised operational & reclamation features of all tailings disposal sys for License SUA-1310
ANDREWS, R D Rocky Mountain Energy Co. 79/04/06 1p

DOCKETED ITEMS

5

7905100233 Forwards oversized drawing showing tailing reservoir after reclamation, per 790406 request Drainage from tailing cover reversed to flow south to diversion cut Downstream dam reduced in slope from 3:1 to 5:1 Oversized drawings encl
ANDREWS, R D Rocky Mountain Energy Co 79/04/06 3pp

7905240283 Forwards requested flow sheet for mill process Changes relate to process efficiency improvements or necessary additions to handle tolled ore Oversized drawing encl
ANDREWS, R D Rocky Mountain Energy Co 79/04/17 1p

DOCKET 40-8502 IRIQARY MINE, WYOMING MININO CORP

7905150806 Recommends Amend 1 to License SUA-1341 be approved to authorize in situ U solution extraction & recovery of natural U using calcium-magnesium-carbonate/bicarbonate & oxidant sys within licensed solution extraction area
COOPERSTEIN, R , BCARANO, R A Radioisotopes Licensing Branch (Pre 790501) 79/04/10 3pp

7905240267 Forwards 790405 ltr to DOE requesting mod of WY State Mine Permit 478
BCHENDEL, K R Wyoming Mineral Corp 79/04/26 3pp

DOCKET 40-8984 UNION 76 MINERALS EXPLORATION CO

7905150624 Summary of 790306 meeting w/Minerals Exploration Co in Silver Spring, MD re minor amends to License SUA-1350 & preoperational monitoring program
LINEHAN, J J Assistant Director for Waste Management (Pre 790501) 79/04/16 2pp

7905110019 Informs that manpower expenditure required for review of Amend 1 to License SUA-1350 calls for smaller amend fee than fee which was sent Refund will be made
MILLER, W O License Fee Management Branch 79/04/24 1p

DOCKET 40-8602 UNITED NUCLEAR CORP

7905140541 Responds to NRC 790409 request Submits summary of United Nuclear Corp/Teton Exploration Drilling Co/TVA rept re planned U milling facility at Morton Ranch property
WOLFF, C E United Nuclear Corp 79/04/12 2pp

7905030363 Responds to 790416 request Forwards revisions & additions to application for U mill license W/four oversized drawings
WOLFF, C E United Nuclear Corp 79/04/20 75pp

7905290063 Forwards revised application, in response to 790423 request Some mods were made to U milling application in lieu of inclusion in source mat'l license
WOLFF, C E United Nuclear Corp 79/04/23 7pp

DOCKET 40-8663 NUCLEAR DYNAMICS, INC

7905220029 Amends License SUA-1331 to authorize use of alternate ammonium carbonate/bicarbonate lixiviant sys in R&D U solution extraction program
CROW, W T Fuel Process. & Fab Branch 79/03/30 1p

7905240835 Evaluates licensee request to authorize in situ U solution extraction field tests w/ammonium carbonate/bicarbonate & oxidant sys.
COOPERSTEIN, R , CROW, W T Radioisotopes Licensing Branch (Pre 790501) 79/03/30 2pp.

DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC.

7905240301 Requests clarification of EIB re air pollution, W/790125 & 781207 internal correspondence
HANSEN, R C Utah, State of 79/01/31. 4pp.

7905300163 Comments on preliminary case rept for Energy Fuels White Mesa U Mill, DOI memo re professional considerations surrounding nonaqueous burial of archeological site encl
REAVES, R Interior, Dept of 79/04/06. 2pp

7905250201 Forwards "Research Design for White Mesa Archeological Project"
CABJENS, L. Utah, State of 79/04/09. 22pp.

7905250168 Comments on DES classification of containers as Type A in done by shipper, not DOT.
RIEDEL, W. R. Coast Guard, Transportation, Dept of 79/04/12 1p.

7905300132 Forwards supplemental archeological rept re stockpile area to east of tailings area
BAKER, C E Energy Fuels Nuclear, Inc 79/04/16 16pp

7905240344 Forwards rept re findings of recent archeological survey of eastern half of northeast quarter of Section 33 No further archeological work required
BAKER, C E Energy Fuels Nuclear, Inc 79/04/25 6pp

7905310088 Summary of 790409-11 trip to ORNL to revise DES reflecting finalized NRC comments
TRAGER, E A Radioisotopes Licensing Branch (Pre 790501) 79/04/26 1p

7905240258 Forwards requested eligibility determination for earth dam in San Juan County, UT to be included in Nat'l Register of Historic Places Info should be integrated into NEPA analysis
MURTAQH, W J Interior, Dept of 79/05/01 14pp

--7905240392 Requests determination of area eligibility as archaeological district for Nat'l Register Forwards State of UT 790104 ltr documenting eligibility
BCARANO, R A Fuel Process & Fab Branch 79/04/20 3pp

7905240425 Approves proposed memo of agreement w/White Mesa, San Juan County, UT, except items re obligations of developer
KEENE, J P Utah, State of 79/05/03 1p

DOCKET 40-8493 OGLE PETROLEUM, INC

7905100172 Forwards quarterly rept for License SUA-1336
CATCHPOLE, O J Ogle Petroleum, Inc 79/04/10 53pp

DOCKET 40-8698 PLATEAU RESOURCES, LTD

7905090441 Informs of completion of EIB review No comments at this time
BARROWS, H L Agriculture, Dept of 79/03/12 1p

7905010377 Offers no specific comments on DES (NUREG-0504)
MCHILLAN, O D Agriculture, Dept of 79/03/30 1p

7905250042 Suggests granting source mat'l license; project will help solve problems of economically depressed area
COOKE, P S Utah, State of 79/03/30 1p

7905010618 Comments on DES boundaries of Glen Canyon Nat'l Recreational Area are incorrectly shown
BENNEDEN, M B Woodward-Clyde Consultants 79/04/04 11pp

7905150303 Forwards UT state agency comments on DES
BRIGGS, K Utah, State of 79/04/04 11pp

7905300130 Forwards "Analysis of Shoshone Canyon U Project"
LOCHSTET, W A Affiliation Unknown 79/04/08 11pp

7905300134 Comments on DES recommends NRC contact Regional Director of Fish & Wildlife Bvc, Denver, CO for guidance re endangered American peregrine falcon
MEIEROTTO, L E Interior, Dept of 79/04/09 10pp

7905240658 Forwards documents containing comments & questions re DES (NUREG-0504), W/o encl
ROTHFLEISCH, J. Division of Fuel Cycle & Material Safety 79/04/10 2pp

7905150061 Requests approval of application for source mat'l license for Shoshone Canyon U Project. Project would be beneficial to economically depressed area
HARRIOTT, D House of Rep. 79/04/11. 2pp

7905250542 Supports conclusions of DES (NUREG-0504)
GARN, J Senate 79/04/12 1p

7905250022 Forwards DOI 790419 comments on DES. Requests appropriate reply
ROTHFLEISCH, J E Uranium Recovery Licensing Branch 79/04/13. 1p.

7905150594 Forwards 790110 ltr describing county economic conditions & significance of mine-mill complex & townsite. Eager to see project underway.
MIDDLETON, O Garfield County, UT. 79/04/19. 4pp.

DOCKETED ITEMS

7905100060 Forwards response to comments on DES Suggests revised language for FES
SEWELL, R B Plateau Resources, Ltd 79/04/24 55pp

DOCKET 40-8714 CLEVELAND CLIFFS IRON CO

7905250012 Summary of 790410 meeting w/Cleveland-Cliffs Iron Co in Silver Spring, MD re source natl license for Collins Draw, WV site, applicant's draft radiation manual, mine permit application & guidelines for U extraction R&D
COOPERSTEIN, R Radioisotopes Licensing Branch (Pre 790501) 79/04/13 2pp

DOCKET 40-8721 ROCKY MOUNTAIN ENERGY CO

7905150634 Summary of 790320 meeting w/Rocky Mountain Energy Co in Silver Spring, MD re commercial scale U solution extraction proposal & environ rept
COOPERSTEIN, R Fuel Process & Fab. Branch 79/03/28 2pp

DOCKET 40-8722 BRUSH-WELLMAN, INC

7905300505 Responds to 790412 telcon Violation of health stds has never been documented at plant
ANDERSON, L F Utah, State of 79/04/13 1p

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV OF MICHIGAN RESEARCH REACTOR

J Insurance & indemnity information

7905160341 Forwards Amend 10 to Indemnity Agreement E-24, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

P Operating license stage documents & correspondence

7905090298 Requests exemption of small quantities of SNM from proposed upgrade rules for research reactors
BURN, R R Michigan, Univ of 79/05/04 1p

7905090367 Requests exemption for small quantities of SNM from proposed upgrade rule for research reactors
BURN, R R Michigan, Univ of 79/05/04 1p

7905230402 Forwards QA program & procedures for handling BHI-1 shipping package 5927
KERR, W Michigan, Univ of 79/05/14 1p

--7905230406 QA program for Ford Nuclear Reactor
* Michigan, Univ of 78/05/14 18pp

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

O Adjudicatory correspondence

7905170162 Forwards compilation of Board notifications re licensee regulatory performance evaluation for distribution to all appropriate licensing boards
PATON, W D Branch 4 79/02/28 22pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 74, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHINI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, B M Mutual Atomic Energy Liability Underwriters, 79/05/01 1p

7905140407 Forwards Amend 21 to Indemnity Agreement B-19 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp

P Operating license stage documents & correspondence

7905070549 Ack receipt of NRC 790412 ltr Willing to cooperate in planned analysis scheduled for week of 790506
CAHILL, W J Consolidated Edison Co of New York 79/04/30 1p

B Inspection reports, IE Bulletins & correspondence

7905030272 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/26 1p

7905250248 Responds to IE Bulletin 79-03 re longitudinal weld defects in certain pipe spools mfg by Youngstown Welding & Engineering Co Piping not used in Unit 2 Info on Unit 1 will be provided when returned to svc
CAHILL, W J Consolidated Edison Co of New York 79/04/13 2pp

7905020350 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905030373 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905040183 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905010079 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/17 1p

--7905010083 IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Extract of GE Bvc Ltr 175(CPDD)19 3 encl
* Office of Inspection & Enforcement 79/04/17 10pp

7905010636 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/18 1p

7905290177 Ack receipt of 790321 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-003/78-13 & 50-247/78-38
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/04 2pp

--7905290185 Responds to NRC 790228 ltr re violation noted in IE Insp Repts 50-003/78-13 & 50-247/78-38 Corrective actions developing techniques to avoid variables leading to badge anomalies
CAHILL, W J Consolidated Edison Co. of New York 79/03/21 3pp

--7905290186 Forwards IE Insp Repts 50-003/78-13 & 50-247/78-38 on 781227-29 & 790117-18 & notice of violation
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/02/28 2pp

--7905290193 Notice of violation from insp on 781227-29 & 790117-18
* Region 1, Philadelphia, Office of the Director 79/02/28 1p

--7905290196 IE Insp Rept 50-003/78-13 & 50-247/79-38 on 781227-29 & 790117-18 Noncompliance noted failure to maintain personnel exposure limits in accordance w/10CFR20.101
NEELY, D R, SERABIAN, J A Region 1, Philadelphia, Office of the Director, CROCKER, H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/02/27 12pp

R Periodic operating reports & related correspondence

7905220376 Forwards effluent monitoring & impingement data specified in Section 401 Certification for Apr 1979
MONTI, W A Consolidated Edison Co of New York 79/03/10 17pp

7905230392 Forwards daily record of fish collections for Apr 1979 w/daily species breakdown & total weight for Units 2 & 3
ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/14 5pp

DOCKETED ITEMS

7

7905230365 Forwards monthly operating rept for Apr 1979
CAHILL, W J Consolidated Edison Co of New York 79/05/15 1p

--7905230367 Monthly operating rept for Apr 1979
KANULA, L Consolidated Edison Co of New York 79/05/04 7pp

S Reportable occurrences, LERs & related correspondence

7905220283 LER 79-001 has been voided
* Consolidated Edison Co of New York 79/04/01 1p

7905220286 LER 79-003 has been voided
* Consolidated Edison Co of New York 79/04/01 1p

7905220288 LER 79-004 has been voided
* Consolidated Edison Co of New York 79/04/01 1p

7905220291 LER 79-005 has been voided
* Consolidated Edison Co of New York 79/04/01 1p

7905220294 LER 79-006 has been voided
* Consolidated Edison Co of New York 79/04/01 1p

7905220299 LER 79-007 has been voided
* Consolidated Edison Co of New York 79/04/01 1p

7905220302 LER 79-008 has been voided
* Consolidated Edison Co. of New York 79/04/01 1p

7905220305 LER 79-009 has been voided
* Consolidated Edison Co of New York 79/04/01 1p

7905220312 LER 79-010 has been voided
* Consolidated Edison Co of New York 79/04/01 1p

7905220313 LER 79-011 has been voided
* Consolidated Edison Co. of New York 79/04/01 1p

7905190015 Forwards LER 79-012/04X-1
CAHILL, W J Consolidated Edison Co of New York 79/05/10 1p

--7905190018 LER 79-012/04X-1 on 790213 activity of precipitation sample
exceeded 10 times control station level Caused by tritium
releases from source external to facility Manufacturer in
area has modified installation to prevent recurrence
MASCIGULLI, S Consolidated Edison Co of New York 79/05/10 3pp

7905190021 Forwards LER 79-015/04T-0
CAHILL, W J Consolidated Edison Co of New York 79/05/10 1p

--7905190025 LER 79-015/04T-0 on 790405 activity of precipitation sample
exceeded 10 times control station level Caused by tritium
releases from source external to facility Manufacturer in
area has modified installation to prevent recurrence
MASCIGULLI, S Consolidated Edison Co of New York 79/05/10 2pp

DOCKET 50-5 PENNSYLVANIA STATE UNIV. RESEARCH REACTOR

J Insurance & indemnity information

7905160328 Forwards Amend 14 to Indemnity Agreement E-10, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-6 BATTELLE MEMORIAL INST RESEARCH REACTOR

J Insurance & indemnity information

7905300063 Forwards Amend 14 to Indemnity Agreement B-6, reflecting
change in 10CFR140 reflecting increase in primary layer of
liability from \$140 million to \$160 million, effective
790501, Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905240391 Forwards executed Amend 14 to Indemnity Agreement B-6,
effective 790514,
BTALL, D. H. Battelle Memorial Institute, Columbus Laboratories
79/05/14, 2pp.

DOCKET 50-B NORTH CAROLINA STATE UNIV. RESEARCH REACTOR

J Insurance & indemnity information

7905300069 Forwards Amend 15 to Indemnity Agreement E-7, reflecting
change in 10CFR140, increasing primary layer of liability
from \$140 million to \$160 million, effective 790501,
Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group. 79/05/01 5pp.

7905310452 Forwards Amend 15 to Indemnity Agreement E-7, Requests change
in addressee for correspondence
BOHANNON, J R North Carolina State Univ 79/05/25 2pp

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

D NRC Draft/Final Environmental Statements, suppl & correspondence

7905020234 Requests preparation of EIS for proposed chemical
decontamination experiment Forwards pertinent questions re
radioactive corrosive products, waste burials &
radionuclide-chelating agents
DREY, K Affiliation Unknown 79/03/30 6pp

F Security, medical, emergency & fire protection plans

7905240421 Summarizes 790320-22 fire protection review trip Areas
inspected physical separation of redundant safe shutdown
equipment, fire hazards & facility protection features
Forwards unanswered questions & positions
DERDERIAN, L Plant Systems Branch 79/04/17 11pp

7905250097 Notification of 790508 meeting w/util in Bethesda, MD to
discuss fire protection program
O'CONNOR, P W Operating Reactors Branch 2 79/04/25 1p.

7905030366 Forwards modified physical security plan, Revision 3 Plan
withheld (ref 10CFR2 790)
LEE, B Commonwealth Edison Co 79/04/26 1p

G Adjudicatory correspondence

7905020523 Forwards petition requesting EIS be prepared on proposed
decontamination experiments designed to flush radioactive
corrosion from reactor piping, W/FR notice
DENTON, H R Office of Nuclear Reactor Regulation. 79/04/09 2pp

--7905020533 Plea for preparation of EIS on proposed decontamination
experiments designed to dissolve & flush out radioactive
corrosion products from reactor piping
DREY, K. Affiliation Unknown 79/03/19, 5pp.

H General correspondence

7905150675 Forwards K Drey 790319 ltr requesting that EIS be required
before authorization is granted to flush piping at facility.
O'BRIEN, O M House of Rep 79/04/04 5pp

J Insurance & indemnity information

7905100163 Endorsement 99 to MAELU Policy MF-22
GERAS, T. Nuclear Energy Liability Insurance Association 79/03/27
1p

7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHINI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters. 79/05/01,
1p

7905140404 Forwards Amend 21 to Indemnity Agreement B-10 per 10CFR140
changes, re increase in liability insurance from \$140 million
to \$160 million, effective 790501 Supporting documentation
encl.
BALTZMAN, J Antitrust & Indemnity Group. 79/05/01, 6pp.

DOCKETED ITEMS

P Operating license stage documents & correspondence

7905030067 Forwards notes on 790302, 13 & 33 conference telcons between NRC, consultants & utility re bulletin "Potential Explosive Gas Mixtures Accumulations Associated w/BHR Offgas Sys Operations"
 3PPOLO, T A Operating Reactors Branch 3 79/04/16 4pp

7905080337 Forwards topics deleted from systematic evaluation program review of facilities Requests review & identification of errors within 30 days from receipt of ltr
 ZIEHANN, D L Operating Reactors Branch 2 79/04/16 7pp

7904270366 Summary of 790403 meeting of 22 utility operating 37 nuclear plants, re planned use of RETRAN NSS simulation program Requests meeting w/NRC to assure NRC familiarity w/program
 REED, C Commonwealth Edison Co 79/04/18 2pp

7905250324 Notifies that date for completion of solid waste handling sys has been delayed until 790430, due to lack of manpower for electrical work
 JANECEK, R F Commonwealth Edison Co 79/04/20 1p

7905040482 Notifies of intention to develop safety analysis using existing computer codes Requests add'l info
 BOLBRIG, C W Commonwealth Edison Co 79/04/26 1p

7905090370 Reviews systematic evaluation program for shared engineered safety features, onsite emergency power & svc sys for multiple unit stations
 JANECEK, R F Commonwealth Edison Co 79/05/02 2pp

7905140273 Summarizes status of completion of HPCL sys Bldg structure complete & most equipment is on site All concrete poured for north electric duct run, except for Manhole 4
 JANECEK, R F Commonwealth Edison Co 79/05/04 2pp

7905250391 Forwards current licensing open items status list
 REED, C Commonwealth Edison Co 79/05/18 11pp

Q Inspection reports, IE Bulletins & correspondence

7905020421 Forwards response to IE Bulletins 78-12 & 78-12A, "Atypical Weld Matl in Reactor Pressure Vessel Welds"
 REED, C Commonwealth Edison Co 79/03/22 10pp

7905010236 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
 KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23 1p

7905030370 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
 KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26 1p

7905010135 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air"
 KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/28 1p

7905010384 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
 KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/30 1p

7905030013 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
 KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/11 1p

7905240448 Forwards IE Insp Repts 50-010/79-07, 50-237/79-09 & 50-249/79-07 on 790306-07, 0312 & 0323, No noncompliance noted.
 DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/04/11 2pp.

--7905240454 IE Insp Repts 50-010/79-07, 50-237/79-09 & 50-249/79-07 on 790306-07, 0312 & 0323 No noncompliance noted Major areas inspected, internal audits, offsite support agency coordination, emergency facilities, training & drills
 GRANT, W B ; EBB10, T H Region 3, Chicago, Office of the Director. 79/04/05 3pp

7905250280 Responds to IE Bulletin 79-03 re welding defects in certain longitudinally welded pipe spools Plants inspected, no pipe found.
 REED, C. Commonwealth Edison Co. 79/04/12. 2pp.

7905010369 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
 KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/11 1p

7905040334 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
 KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/11 1p

7905040529 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
 KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/11 1p

7905030206 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
 KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/17 1p

7905040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."
 KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/21 1p

--7905040158 IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl" Supporting documentation encl
 * Region 3, Chicago, Office of the Director 79/04/21 12pp

--7905040170 ACRS recommendations re 790328 incident at TMI Suggests hi priority be placed on development of safety research on behavior of LWRs during anomalous transients
 * ACRS - Advisory Committee on Reactor Safeguards 79/04/17 2pp

--7905040201 Forwards ACRS recommendations re TMI incident, presented 790417
 FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards 79/04/18 1p

--7905040221 In response to NRC 790418 ltr, states 790417 ACRS recommendations apply to all PHRs, but were not intended to require immediate changes Plant mods should be made after study of effects on overall safety, TMI excluded
 CARBON, H X ACRS - Advisory Committee on Reactor Safeguards 79/04/20 2pp

7905240633 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping Reanalysis indicates method of intramodal combination has little effect on pipe stresses & equipment support loads
 REED, C Commonwealth Edison Co 79/04/24 4pp

7905250206 Ack receipt of 790416 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/79-04, 50-237/79-04 & 50-249/79-04
 HIND, J A Region 3, Chicago, Safeguards Branch. 79/04/24 1p

--7905250215 Responds to NRC 790328 ltr re violations noted in IE Insp Repts 50-010/79-04, 50-237/79-04 & 50-249/79-04 Corrective actions withheld (ref 10CFR2 790)
 REED, C Commonwealth Edison Co. 79/04/16 1p

7905150148 Forwards responses to IE Bulletin 79-06A, Revision I, re BHR events identified during TMI-2 Util has formed task force to review BHR events & recommend corrective action, as required
 REED, C Commonwealth Edison Co 79/04/27 22pp

7905300242 Responds to IE Bulletin 79-04 No 3, 4 or 6-inch Valves swing check valves are in use at Dresden or Quad-Cities Review of Zion has identified use of valves in some piping sys but review is incomplete, Will rept later
 REED, C Commonwealth Edison Co 79/05/01 2pp

7905140488 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase"
 KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/02 1p

--7905140492 IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase"
 B Region 3, Chicago, Office of the Director. 79/05/02 6pp

DOCKETED ITEMS

9

Periodic operating reports & related correspondence

7903160354 Forwards monthly operating rept for Apr 1979
STEPHENSON, B B Commonwealth Edison Co 79/05/08 1p

7903160359 Monthly operating rept for Apr 1979
CIESZKIEWICZ, S Commonwealth Edison Co 79/05/03 20pp

DOCKET 50-12 LYNCHBURG POOL REACTOR

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,
173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,
197,198,200,201,204,206,207,208,210,212,214,215, & others
QUATTROCHHI, J American Nuclear Insurers 79/05/01 1p

DOCKET 50-13 BABCOCK & WILCOX CO CRITICAL FACILITY

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,
173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,
197,198,200,201,204,206,207,208,210,212,214,215, & others
QUATTROCHHI, J American Nuclear Insurers 79/05/01 1p

7905300714 Forwards Amend 19 to Indemnity Agreement B-8, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905290427 Forwards executed Amend 1 to Indemnity Agreement Q-2 & Amend
19 to Indemnity Agreement B-8
OLSEN, A F Babcock & Wilcox Co 79/05/21 3pp

G Inspection reports, IE Bulletins & correspondence

7905070139 Forwards IE Bulletins 79-05, 79-05A & 79-06 re nuclear
incident at TMI
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/13 1p

DOCKET 50-14 BATTTELLE MEMORIAL INST CRITICAL FACILITY

J Insurance & indemnity information

7905300065 Forwards Amend 14 to Indemnity Agreement B-6, reflecting
change in 10CFR140 reflecting increase in primary layer of
liability from \$140 million to \$160 million, effective
790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905240391 Forwards executed Amend 14 to Indemnity Agreement B-6,
effective 790514
STALL, D H Battelle Memorial Institute, Columbus Laboratories
79/05/14 2pp

DOCKET 50-16 ENRICO FERMI ATOMIC POWER PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

7905100162 Responds to 790403 telcon & 790405 mailgram re fire
protection at facility Forwards most recent insp. conducted
on 781214 W/a encl.
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/13
2pp

J Insurance & indemnity information

7905160353 Forwards Amend 22 to Indemnity Agreement B-20, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905310451 Forwards Amend 22 to Indemnity Agreement B-20, per NRC
request
HARGUARDT, P A Detroit Edison Co 79/05/23 2pp

DOCKET 50-18 VALLECITOS BOILING WATER REACTOR

J Insurance & indemnity information

7905300190 Forwards Amend 20 to Indemnity Agreement B-11, reflecting
change in 10CFR140, increasing primary layer of liability
from \$140 million to \$160 million, effective 790501
Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905150308 Amend 20 to Indemnity Agreement B-11
SALTZMAN, J Antitrust & Indemnity Group 79/05/08 1p

P Operating license stage documents & correspondence

7905090364 Forwards questions of clarification re geologic
investigations around test reactor
DEVINE, J F Interior, Dept of, Geological Survey 79/05/04 5pp

DOCKET 50-20 MASSACHUSETTS INST OF TECH RES REACTOR

J Insurance & indemnity information

7905160322 Forwards Amend 10 to Indemnity Agreement E-39, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

P Operating license stage documents & correspondence

7905090331 Raises questions as to whether increase in matl science
activities are legal Requests advice re required changes to
license or Tech Specs before proceeding w/research
activities
FECYCH, W Massachusetts Institute of Technology 79/05/04 2pp

B Reportable occurrences, LERs & related correspondence

7905040480 RD 79-2 on 790410 during completion of startup checklist
for less than 100 kW operation, core tank level scram
discovered inoperable Caused by shorting between probe
conductor lead & casing
CLARK, L Massachusetts Institute of Technology 79/04/19 3pp

DOCKET 50-22 WESTINGHOUSE TEST REACTOR

J Insurance & indemnity information

7905070497 Confirms in
policies NF-1,25,43,
173,174,178,179,180
197,198,200,201,204
QUATTROCHHI, J Am

DOCKETED ITEMS

DOCKET 30-27 WASHINGTON STATE UNIV RESEARCH REACTOR

J Insurance & indemnity information

7905160300 Forwards Amend 12 to Indemnity Agreement E-3B, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905240472 Forwards accepted Amend 12 to Indemnity Agreement E-3B
GABER, E Washington State Univ 79/05/11 2pp

P Operating license stage documents & correspondence

7905310232 Forwards application for renewal of License R-76, revised proposed Tech Specs, EIA, emergency plan & Univ financial rpt for FY ended 780630
WILSON, W E, NYMAN, C J, SANDE, R D Washington State Univ 79/05/15 1p

--7905310236 Application for renewal of License R-76
* Washington State Univ 79/05/15 6pp

--7905310239 Proposed Tech Specs for WA State Univ modified TRIQA reactor w/original Tech Specs & bases
* Washington State Univ 79/05/15 72pp

--7905310242 EIA for continued operation of WA State Univ modified TRIQA reactor
* Washington State Univ 79/05/15 18pp

--7905310245 WA State Univ Nuclear Radiation Ctr emergency plan
* Washington State Univ 79/05/15 12pp

DOCKET 30-29 YANKEE-ROWE NUCLEAR POWER STATION

I Financial information

7905310390 Advises of plan to file annual cash flow statements guaranteeing payment of retrospective premiums on 790701 VT Yankee & CT Yankee will also file statements by 790401
BOUCY, A R Yankee Atomic Electric Co 79/05/23 1p

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHI, J American Nuclear Insurers 79/05/01 1p

7905070382 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D H Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905160285 Forwards Amend 12 to Indemnity Agreement B-17, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905160309 Forwards executed Amend 12 to Indemnity Agreement B-17 increasing liability insurance
BOUCY, A R Yankee Atomic Electric Co 79/05/09 3pp

7905110317 Submits response to NRC 790504 questions re auxiliary feedwater system

7905010327 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/30 1p

7905080075 Responds to IE Bulletin 79-03 re longitudinal weld defects
No action required; seam weld insp requirement in ASME Section III Only plants designed under these rules are affected
MODDY, D E Yankee Atomic Electric Co 79/04/04 1p

7905020116 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/11 1p

P Operating license stage documents & correspondence

7905290006 Finds YQAP-1-A "Operational QA Program," acceptable, based on review of Revision 6, including Amend 1
HAAS, W P Division of Project Management 79/04/10 2pp

7905090022 Forwards topics deleted from systematic evaluation program review of facilities Requests review & identification of errors within 30 days from receipt of ltr
ZIEHANN, D L Operating Reactors Branch 2 79/04/16 7pp

7905020363 Forwards draft evaluation of systematic evaluation program Topic IV-1-A, "Operation W/less than All Loops in Svc"
Requests review & response within 30 days
ZIEHANN, D L Operating Reactors Branch 2 79/04/18 0pp

7905030333 Discusses loss of feedwater transient analysis reported on 790417 Analysis error was found in inverted GEMINI code & incorrect assumption in analysis of reactor coolant pump operation following trip
GROCE, R H Yankee Atomic Electric Co 79/04/23 3pp

7905250040 Summary of 790321 meeting w/util & Weston Geophysical re ongoing review of systematic evaluation program topics: hydrology, seismic design & pipe breaks inside containment
BURGER, A Operating Reactors Branch 2 79/04/24 6pp

7905290058 Responds to 790413 request re QA program Suggests revision number of YQAP-1-A not be designated.
HEIDER, L H Yankee Atomic Electric Co 79/04/24 1p

7905070548 Forwards Revision 6 & Amend 1 to Revision 6 of operational QA program, as requested in 790410 ltr
GROCE, R H Yankee Atomic Electric Co 79/04/30 4pp

--7905070553 Informs that revisions to QA program are acceptable
HAAS, W P Quality Assurance Branch, 79/04/10 1pp

7905020311 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905040113 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905040301 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/14, 1p

7905030112 Forwards IE Bulletin 79-09, "Failures of OE Type AK 2 Circuit Breaker in Safety-Related Sys" Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/17 1p

7905020341 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/18 1p

7905250452 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Unit was designed using nondynamic methods of analysis
GROCE, R H Yankee Atomic Electric Co 79/04/24, 1p

DOCKETED ITEMS

11

7905250359 Responds to IE Bulletins 79-06, 79-06A & 79-06A, Revision 1, re
THI errors Outlines changes in operating procedures,
preventative measures taken Supporting personnel briefing &
documentation encl
MOODY, D E Yankee Atomic Electric Co 79/04/26 9pp

R Periodic operating reports & related correspondence

7905150334 Forwards monthly operating rept for Apr 1979
MOODY, D E Yankee Atomic Electric Co 79/05/12 1p

--7905150337 Monthly operating rept for Apr 1979
SUDGREN, R M Yankee Atomic Electric Co 79/05/12 5pp

S Reportable occurrences, LERs & related correspondence

7905150422 Forwards LER 78-012/03L-1
AUTIO, H A Yankee Atomic Electric Co 79/05/11 1p

--7905150428 LER 78-012/03L-1 on 780419 level of primary seal tank found
to be decreasing at faster rate than normal Caused by crack
in carbon ring of mechanical seal Seal replaced
MAY, E L Yankee Atomic Electric Co 79/05/11 1p

7905150433 Forwards LER 79-014/03L-0
AUTIO, H A Yankee Atomic Electric Co 79/05/11 1p

--7905150437 LER 79-014/03L-0 on 790412 CA-V-688 valve failed containment
leakage rate Caused by crud on valve seating surface Valve
isolated, cleaned, retested & returned to svc
MAY, E L Yankee Atomic Electric Co 79/05/11 1p

7905190126 Forwards LER 79-010/04X-0
AUTIO, H A Yankee Atomic Electric Co 79/05/14 1p

--7905190128 LER 79-010/04X-0 on 790213 while performing insp on air
sample pump station A-3, air sample pump found inoperative
Caused by bearing failure on motor shaft Bearing replaced
MAY, E L Yankee Atomic Electric Co 79/05/14 1p

DOCKET 50-30 PLUM BROOK RESEARCH REACTOR FACILITY

J Insurance & indemnity information

7905160280 Forwards Amend 14 to Indemnity Agreement D-3, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905190171 Amend 14 to Indemnity Agreement D-3 between NARA & AEC
BALTZMAN, J Antitrust & Indemnity Group 79/05/07 1p

DOCKET 50-32 AEROJET GENERAL NUCLEONICS

J Insurance & indemnity information

7905300059 Forwards Amend 17 to Indemnity Agreement B-2, reflecting
change in 10CFR140, increasing primary layer of liability
from \$140 million to \$160 million, effective 790501
Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905240357 Forwards executed Amend 17 to Indemnity Agreement B-2
NEWACHECK, R L Aerotest Operations 79/05/15 2pp

DOCKET 50-37 TRIQA-MARK I PROTOTYPE REACTOR

J Insurance & indemnity information

7905300202 Forwards Amendment 31 to Indemnity Agreement B-9, reflecting
change in 10CFR140, increasing primary layer of liability
from \$140 million to \$160 million, effective 790501
Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-47 ARMY MATERIALS RESEARCH REACTOR

J Insurance & indemnity information

7905160278 Forwards Amend 11 to Indemnity Agreement D-7, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905160431 Forwards Amend 11 to Indemnity Agreement D-7
O'KEEFE, A J Army, Dept of, Matls & Mechanics Research Center
79/05/09 2pp

DOCKET 50-53 AEROJET GENERAL NUCLEONICS

J Insurance & indemnity information

7905300059 Forwards Amend 17 to Indemnity Agreement B-2, reflecting
change in 10CFR140, increasing primary layer of liability
from \$140 million to \$160 million, effective 790501
Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905240357 Forwards executed Amend 17 to Indemnity Agreement B-2
NEWACHECK, R L Aerotest Operations 79/05/15 2pp

DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR

J Insurance & indemnity information

7905160348 Forwards Amend 11 to Indemnity Agreement B-14, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

P Operating license stage documents & correspondence

7905010531 Provides responses to proposed Tech Spec items re potential
reactivity, organization chart & definition of "unplanned
transients"
GEORGE, K D Union Carbide Corp 79/04/10 9pp

7905010495 Act 790412 telcon re Tech Spec mods Details requested
changes re liquid effluent releases
GEORGE, K D Union Carbide Corp 79/04/16 2pp

DOCKET 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR

J Insurance & indemnity information

7905160332 Forwards Amend 12 to Indemnity Agreement E-34, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

P Operating license stage documents & correspondence

7905190019 Requests change to Tech Specs re present period reversal &
scram
ORLOSKY, P M New York, State Univ of, Buffalo 79/01/09 2pp

DOCKET 50-59 TEXAS A&M UNIV RESEARCH REACTOR

J Insurance & indemnity information

7905160343 Forwards Amend 14 to Indemnity Agreement E-12, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-62 UNIV OF VIRGINIA RESEARCH REACTOR

J Insurance & indemnity information

7905230456 Forwards Amend 12 to Indemnity Agreement E-28, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905240462 Forwards accepted Amend 12 to Indemnity Agreement E-28,
effective 790516
JENNINGS, D W Virginia, Univ of 79/05/17 2pp

G. Inspection reports, IE Bulletins & correspondence

7905070148 Forwards IE Bulletins 79-03, 79-05A & 79-06 re nuclear
incident at THI
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/13 1p

DOCKETED ITEMS

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

E NRC Safety Evaluation Report (SER), supp's & correspondence

7903160428 Requests review of geologic rept & probability analysis be expedited so SER can be issued
DARMITZEL, R W General Electric Co, Nuclear Energy Products Div
79/05/09 1p

J Insurance & indemnity information

7903070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 74, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 189, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCCHI, J American Nuclear Insurers 79/05/01 1p

7903070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7903300190 Forwards Amend 20 to Indemnity Agreement B-11, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 790501
Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7903150308 Amend 20 to Indemnity Agreement B-11
SALTZMAN, J Antitrust & Indemnity Group 79/05/08 1p

DOCKET 50-72 UNIV OF UTAH RESEARCH REACTOR

J Insurance & indemnity information

7903300034 Forwards Amend 10 to Indemnity Agreement E-31, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 790501
Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp

7903140281 Amend 10 to Indemnity Agreement E-31
SALTZMAN, J Antitrust & Indemnity Group 79/05/07 1p

Q Inspection reports, IE Bulletins & correspondence

7905010655 Act receipt of 790302 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-072/79-01
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch, 79/03/29 1p

--7905010661 Responds to NRC 790208 ltr re violations noted in IE Insp Rept 50-072/79-01 Corrective actions reactor log corrected to include radiation survey around reactor seals
TURLEY, R E Utah, Univ of 79/03/02 2pp

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

J Insurance & indemnity information

7903300190 Forwards Amend 20 to Indemnity Agreement B-11, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 790501
Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group, 79/05/01 5pp

P. Operating license stage documents & correspondence

7905190154 Notifies that GE will have resources necessary to decommission reactor
BEATON, R H General Electric Co 79/05/14, 1p

DOCKET 50-77 CATHOLIC UNIV OF AMERICA RESEARCH REACTOR

J Insurance & indemnity information

7903160122 Forwards Amend 9 to Indemnity Agreement E-2, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501, Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01, 5pp.

7903180479 Forwards Amend 9 to Indemnity Agreement E-2.
LOWE, V P Catholic Univ 79/05/10, 2pp.

P Operating license stage documents & correspondence

7905090279 Forwards correction to page 16-4 in Amend 7 for License R-31
REID, R W Operating Reactors Branch 4 79/04/09 3pp

R Periodic operating reports & related correspondence

7903010539 Announces plan to restart AON-201 reactor on 790309 NRC representative invited to attend Forwards "Annual Operating Rept 1978"
JORDAN, E D Catholic Univ 79/04/20 11pp

--7905010547 "Annual Operating Rept 1978"
EBERT, D D, KEENE, W E, JORDAN, E D Catholic Univ 79/04/06 11pp

DOCKET 50-83 UNIV OF FLORIDA TRAINING REACTOR

J Insurance & indemnity information

7903160167 Forwards Amend 9 to Indemnity Agreement E-18, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl.
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

Q Inspection reports, IE Bulletins & correspondence

7905070142 Forwards IE Bulletins 79-05, 79-05A & 79-06 re nuclear incident at TMI
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/13 1p

DOCKET 50-84 UNIV OF CALIFORNIA RESEARCH REACTOR

J Insurance & indemnity information

7903300032 Forwards Amend 13 to Indemnity Agreement E-15, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 790501
Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-87 WESTINGHOUSE CRITICAL EXPERIMENT

J Insurance & indemnity information

7905160249 Forwards Amend B to Indemnity Agreement B-56, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-89 GENERAL ATOMIC CO

J Insurance & indemnity information

7903300202 Forwards Amendment 31 to Indemnity Agreement B-9, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 790501
Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-94 ROCKWELL INTERNATIONAL RESEARCH REACTOR

J Insurance & indemnity information

7905160320 Forwards Amend 15 to Indemnity Agreement B-13, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501, Supporting documentation encl.
SALTZMAN, J Antitrust & Indemnity Group, 79/05/01 5pp

DOCKET 50-97 CORNELL UNIV ZERO POWER REACTOR

J Insurance & indemnity information

7903300038 Forwards Amend 11 to Indemnity Agreement E-4, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 790501, Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01, 5pp

DOCKETED ITEMS

13

DOCKET 50-99 BABCOCK & WILCOX TEST REACTOR

J Insurance & indemnity information

7905300714 Forwards Amend 19 to Indemnity Agreement B-8, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905290427 Forwards executed Amend 1 to Indemnity Agreement G-2 & Amend 19 to Indemnity Agreement B-8
OLSEN, A F Babcock & Wilcox Co 79/05/21 3pp

P Operating license stage documents & correspondence

7905140411 Submits annual operations rept for 1975
OLSEN, A F Babcock & Wilcox Co 76/02/24 9pp

7905140414 Submits annual operations rept for 1976
OLSEN, A F Babcock & Wilcox Co 77/02/23 8pp

7905140408 Submits annual operations rept for 1977
OLSEN, A F Babcock & Wilcox Co 78/02/27 9pp

7905110307 Forwards additions to License R-47, renewal application & proposed Tech Specs for power limits
OLSEN, A F Babcock & Wilcox Co 79/05/01 2pp

G Inspection reports, IE Bulletins & correspondence

7905070159 Forwards IE Bulletins 79-05, 79-05A & 79-06 re nuclear incident at TMI
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/13 1p

R Periodic operating reports & related correspondence

7905140383 Forwards "Annual Rept 1978"
OLSEN, A F Babcock & Wilcox Co 79/02/28 1p

--7905140384 "Annual Rept 1978"
* Babcock & Wilcox Co 79/02/01 5pp

DOCKET 50-103 AERJET GENERAL NUCLEONICS

J Insurance & indemnity information

7905300099 Forwards Amend 17 to Indemnity Agreement B-2, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905240357 Forwards executed Amend 17 to Indemnity Agreement B-2.
NEHACHEK, R L Aerotest Operations 79/05/19 2pp

DOCKET 50-106 OREGON STATE UNIV

J Insurance & indemnity information

7905160326 Forwards Amend 12 to Indemnity Agreement E-11, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-111 NORTH CAROLINA STATE UNIV RESEARCH REACTOR

J Insurance & indemnity information

7905300069 Forwards Amend 15 to Indemnity Agreement E-7, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905310452 Forwards Amend 15 to Indemnity Agreement E-7, Requests change in addressee for correspondence.
BOHANNON, J R North Carolina State Univ 79/05/25 2pp

G Inspection reports, IE Bulletins & correspondence

7905070146 Forwards IE Bulletins 79-05, 79-05A & 79-06 re nuclear incident at TMI
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/13 1p

DOCKET 50-112 UNIV OF OKLAHOMA RESEARCH REACTOR

J Insurance & indemnity information

7905160236 Forwards Amend 9 to Indemnity Agreement E-26, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

G Inspection reports, IE Bulletins & correspondence

7905150378 Forwards IE Insp Rept 50-112/79-01 on 790412-13 No noncompliance noted
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/03/30 2pp

--7905150584 IE Insp Rept 50-112/79-01 on 790412-13 No noncompliance noted Major areas inspected security organization, physical barriers, access control detection aids & testing of security equipments Details withheld (ref 10CFR2 790)
CALDWELL, R A Region 4, Dallas, Office of the Director, Madsen, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/27 1p

DOCKET 50-113 UNIV OF ARIZONA RESEARCH REACTOR

J Insurance & indemnity information

7905160203 Forwards Amend 9 to Indemnity Agreement E-14, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905240607 Forwards executed Amend 9 to Indemnity Agreement E-14
CARR, S E Arizona, Univ of 79/05/10 2pp

DOCKET 50-116 IOWA STATE UNIV RESEARCH REACTOR

J Insurance & indemnity information

7905160106 Forwards Amend 9 to Indemnity Agreement E-5, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905160296 Forwards signed Amend 9 to Indemnity Agreement E-5, increasing liability insurance from \$140 to \$160 million
BUDECK, R R Iowa State Univ 79/05/09 2pp

G Inspection reports, IE Bulletins & correspondence

7905160488 Ack receipt of 790404 ltr informing NRC of steps taken to correct violations noted in IE insp on 790222-23
HIND, J A Region 3, Chicago, Safeguards Branch, 79/04/18 1p.

--7905160489 Responds to NRC 790313 ltr re violations noted in IE insp on 790222-23 Corrective actions withheld (ref 10CFR2 790).
BURNET, G Iowa State Univ 79/04/04 2pp.

DOCKET 50-123 UNIV OF MISSOURI RESEARCH REACTOR

J Insurance & indemnity information

7905160336 Forwards Amend 10 to Indemnity Agreement E-23, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group, 79/05/01 5pp

7905310401 Forwards executed Amends 10 & 11 to Indemnity Agreements E-23 & E-25, respectively.
BLANBETT, V, Missouri, Univ of, 79/05/25 3pp

DOCKETED ITEMS

R Periodic operating reports & related correspondence

7903220089 Forwards progress rept for Apr 1978-Mar 1979 for Rolla nuclear reactor facility
EDWARDS, D R Missouri, Univ of 79/04/30 1p

--7905220090 Progress rept for Apr 1978-Mar 1979 for Folla nuclear reactor facility
ELLIS, A E Missouri, Univ of 79/04/30 100pp

DOCKET 50-124 VIRGINIA POLYTECH INST TRAINING REACTORJ Insurance & indemnity information

7905160308 Forwards Amend 12 to Indemnity Agreement E-33, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905150363 Amend 12 to Indemnity Agreement E-33, increasing liability coverage from \$140 million to \$160 million
SALTZMAN, J Antitrust & Indemnity Group 79/05/10 1p

Q Inspection reports, IE Bulletins & correspondence

7905010193 Forwards IE Insp Rept 50-124/79-01 on 790129-31 No noncompliance noted
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/16 2pp

--7905010207 IE Insp Rept 50-124/79-01 on 790129-31 No noncompliance noted Major areas inspected radiation protection re procedures, posting, labeling, dosimetry, training, surveys & instrument calibr
EWALD, S C, QIBSON, A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/09 7pp

7905240474 Forwards IE Insp Rept 50-124/79-04 on 790320-0321 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/04 2pp

--7905240480 IE Insp Rept 50-124/79-04 on 790320-0321 No noncompliance noted Major areas inspected refueling operations & associated radiological controls
JULIAN, C A Region 2, Atlanta, Office of the Director
MARTIN, R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/02 3pp

7905070138 Forwards IE Bulletins 79-05, 79-05A & 79-06, re nuclear incident at TMI
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/13 1p

DOCKET 50-128 TEXAS A&M UNIV RESEARCH REACTORP Operating license stage documents & correspondence

7905150772 Requests addl info to complete review of proposed amend, including effects of blast, part beam strength & transportation of explosive matl
REID, R W Operating Reactors Branch 4 79/03/30 2pp

7905230836 Notices of pending license expiration Forwards license renewal review items Application for renewal must be filed at least 30 days prior to expiration
REID, R W Operating Reactors Branch 4 79/04/28 10pp

Q Inspection reports, IE Bulletins & correspondence

7905070136 Forwards IE Bulletins 79-05, 79-05A & 79-06, re nuclear incident at TMI
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/13 1p

DOCKET 50-131 OMAHA VET ADMIN HOSP RESEARCH REACTORF Security, medical, emergency & fire protection plans

7905140192 Forwards physical security plan Plan withheld (ref 10CFR2 790)
BLOTCKY, A J Vet Admin Hosp NE/OM 79/05/10 1p

J Insurance & indemnity information

7905160100 Forwards Amend 8 to Indemnity Agreement D-0, per (10CFR) changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 3pp

7905160297 Amend 8 to Indemnity Agreement D-8, increasing liability coverage from \$140 million to \$160 million
SALTZMAN, J Antitrust & Indemnity Group 79/05/04 1p

P Operating license stage documents & correspondence

7905140198 Forwards application for renewal of License R-57
BLOTCKY, A J Vet Admin Hosp NE/OM 79/05/10 1p

--7905140201 Applies for renewal of License R-57 Forwards application supporting documentation
MULLON, T P Vet Admin Hosp NE/OM, 79/05/10 1p

--7905140204 Application for renewal of License R-57
* Vet Admin Hosp NE/OM 79/05/10 70pp

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3Q Adjudicatory correspondence

7905030048 Forwards Lewis Committee rept (NUREG/CR-0400), NRC public statement on reactor safety study (WASH-1400), its review by Lewis Committee & survey of NRC uses of WASH-1400
MULKEY, M E Branch 2 79/03/30 2pp

7905070227 Notification of resignation of DE Pesonen as counsel for intervenors intervenors will continue to be represented by LJ Brown & Sierra Club Legal Defense Fund.
PESONEN, D E Garry, Dreyfus, McTernan, Brotsky, Herndon & Pesonen Inc 79/04/04 1p.

I Financial information

7905300168 Forwards "Annual Financial Rept 1978 "
CRANE, P A Pacific Gas & Electric Co 79/05/23 1p

--7905300174 "Annual Financial Rept 1978 "
* Pacific Gas & Electric Co 78/12/31 40pp

7905300310 Forwards "Estimated Internal Fund Generation for CY 78 & "Annual Financial Rept 1978 "
CRANE, P A Pacific Gas & Electric Co, 79/05/24 3pp

--7905300329 "Annual Financial Rept 1978 "
* Pacific Gas & Electric Co, 79/02/23 36pp

J Insurance & indemnity information

7905160298 Forwards Amend 21 to Indemnity Agreement B-21, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group, 79/05/01 5pp

7905140406 Forwards Amends executed Amends 21 & 4 to Indemnity Agreements B-21 & B-73, respectively
CRANE, P A Pacific Gas & Electric Co, 79/05/08 3pp

DOCKETED ITEMS

75

P Operating license stage documents & correspondence

7905290011 Responds to 790313 ltr Lists references to specific docketed info describing operational QA program
CRANE, P A Pacific Gas & Electric Co 79/04/20 1p

7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970
PORTER, F L EDS Nuclear, Inc 79/05/21 9pp

--7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program OE has no record of reanalysis for Cooper piping sys
STEPHENS, P W General Electric Co, Nuclear Energy Products Div 79/01/24 18pp

G Inspection reports, IE Bulletins & correspondence

7905010287 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
ENGELKEN, R H Region 4, Dallas, Office of the Director 79/03/23 1p

7905040081 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/03/26 1p

7905010216 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air"
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/03/28 1p

7905010423 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/03/30 1p

7905010023 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 1p

7905040508 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 1p

G Inspection reports, IE Bulletins & correspondence

7905070099 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 1p

7905030288 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/17 1p

7905150809 Responds to IE Bulletin 79-01, "Environ Qualification of Class IE Equipment" Will provide schedule for submission of info after seismic issues have been resolved
CRANE, P A Pacific Gas & Electric Co. 79/04/20 1p

7905080368 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/21 1p

R Periodic operating reports & related correspondence

7905090318 Forwards "Quarterly Status Rept of Investigations & Mods," Jan-Mar 1979, Rept 21
CRANE, P A Pacific Gas & Electric Co. 79/05/03 1p

7905190130 Forwards monthly operating rept for Apr 1979
WEEKS, E D Pacific Gas & Electric Co. 79/05/11 1p

--7905190132 Monthly operating rept for Apr 1979.
* Pacific Gas & Electric Co. 79/05/02 4pp

B Reportable occurrences, LERs & related correspondence

7905150060 Forwards PNO-79-67L
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/06 1p

7905140303 Forwards LER 78-004/03L-1
CRANE, P A Pacific Gas & Electric Co 79/04/09 1p

--7905140304 LER 78-004/03L-1 on 781213 redundant gas treatment sys dc fan operated below required design flow & pressure dropped across gas scrubber column Caused by apparent packing blockage in scrubber column Packing replaced
GETTY, B C Pacific Gas & Electric Co 79/04/09 1p

7905150167 Forwards PNO-79-67R
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/11 1p

7905040123 Forwards PNO-79-67B
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/12 1p

7905150141 Forwards PNO-79-67T
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/13 1p

7905030045 Forwards PNO-79-67U
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 1p

7905020527 Forwards PNO-79-67AA
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/20 1p

7905010425 Forwards PNO-79-67AB
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/21 1p

7905010444 Forwards PNO-79-67AC & AD
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/23 1p

7904300484 Forwards PNO-79-67AE
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/24 1p

7905020227 Forwards PNO-79-67AF
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/25 1p

--7905020230 PNO-79-67AF, summary of info re nuclear incident as of 790425, Describes plant status & environ status. Highest thermocouple reading, 312 F.
* Office of Inspection & Enforcement. 79/04/25 5pp.

7905020256 Forwards PNO-79-67AO
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/26 1p

--7905020260 PNO-79-67AO: summary of info re nuclear incident as of 790426 Describes plant status & environ status Highest incore temp reading is 311 F
PAULUS, R C, THOMPSON, D, Office of Inspection & Enforcement. 79/04/26 2pp.

7905090005 Forwards PNO-79-67AH.
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/27 1p

7905040339 Forwards PNO-79-67AI, AJ & AK per NRC 790401 ltr transmitting IE Bulletin 79-05.
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/30 1p

--7905040360 PNO-79-67AI: summary of info re nuclear incident as of 790428 Describes plant & environ status
* Office of Inspection & Enforcement. 79/04/28 2pp

--7905040365 PNO-79-67AK: summary of info re nuclear incident as of 790429 Describes plant & environ status
* Office of Inspection & Enforcement. 79/04/30 2pp.

DOCKETED ITEMS

7905070007 Forwards PNO-79-67AL per NRC 790401 ltr transmitting IE Bulletin 79-03
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/05/01 1p

7905170072 Forwards PNO-79-67AM
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/05/07 1p

DOCKET 50-134 WORCESTER POLYTECH INST RESEARCH REACTOR

J Insurance & indemnity information

7905160205 Forwards Amend 9 to Indemnity Agreement E-36, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905110298 Forwards Amend 9 to Indemnity Agreement E-36
LLOYD, D E Worcester Polytechnic Inst 79/05/08 2pp

DOCKET 50-139 UNIV OF WASHINGTON RESEARCH REACTOR

J Insurance & indemnity information

7905160192 Forwards Amend 9 to Indemnity Agreement E-29, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-141 STANFORD UNIV RESEARCH REACTOR

J Insurance & indemnity information

7905150306 Forwards Amend 9 to Indemnity Agreement E-19, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905240387 Forwards executed Amend 9 to Indemnity Agreement E-19, effective 790514
BETH, R H Stanford Univ 79/05/14 2pp

DOCKET 50-142 UCLA TRAINING REACTOR

J Insurance & indemnity information

7905160235 Forwards Amend 8 to Indemnity Agreement E-16, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

G Inspection reports, IE Bulletins & correspondence

7905020513 Forwards IE Insp Rept 50-142/79-01 on 790212-15, 28 & 0301 No noncompliance noted
BOOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/03/02 2pp

--7905020520 IE Insp Rept 50-142/79-01 on 790212-15, 28 & 0301 No noncompliance noted Major areas inspected environ protection, emergency planning, radiation control & independent insp effort
THOMAS, R D Region 5, San Francisco, Office of the Director
BOOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/03/02 7pp

DOCKET 50-146 SAXTON NUCLEAR EXPERIMENTAL FACILITY

J Insurance & indemnity information

DOCKET 50-148 UNIV OF KANSAS RESEARCH REACTOR

J Insurance & indemnity information

7905160160 Forwards Amend 9 to Indemnity Agreement E-21, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905160117 Forwards Amend 9 to Indemnity Agreement E-8, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-151 UNIV OF ILLINOIS RESEARCH REACTOR

J Insurance & indemnity information

7905150370 Forwards Amend 12 to Indemnity Agreement E-20, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

C Utility Environmental Report (ER); amends & correspondence

7905010498 Forwards addl info re systematic evaluation program Topic VII-I-A, requested by B MacDonald on 790306 Discusses isolation of reactor protection sys inputs from failures in plant computer
CASHILL, B Consumers Power Co 79/04/18 12pp

F Security, medical, emergency & fire protection plans

7905140211 Provides schedule for submittal of addl fire protection info, per NRC 790404 request
HOFFMAN, D P Consumers Power Co 79/05/09 2pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 29, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHINI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905160291 Forwards Amend 16 to Indemnity Agreement B-22, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905190484 Forwards executed Amend 16 to Indemnity Agreement B-22
BORIS, W R Consumers Power Co 79/05/10 2pp

7905250303 Forwards replacement copy of Amend 1 to Indemnity Agreement B-22, Ack 790510 telcon confirming original copy, dtd 620905, was transmitted to NRC
BORIS, W R Consumers Power Co 79/05/21 3pp

P Operating license stage documents & correspondence

7905150648 Forwards Amend 27 to License DPR-06 & notice of issuance & availability Security plan evaluation withheld (ref 10CFR2 790)
ZIEHANN, D L Operating Reactors Branch 2 79/04/10 3pp

--7905150707 Amend 27 to License DPR-06, revising security plan
ZIEHANN, D L Operating Reactors Branch 2 79/04/10 2pp

--7905150715 Notice of issuance & availability of Amend 27 to License DPR-06
ZIEHANN, D L Operating Reactors Branch 2 79/04/10 2pp

7905240271 Forwards topics deleted from systematic evaluation program review, due to parallel review as generic issue or inapplicability. Requests review & comments within 30 days
ZIEHANN, D L Operating Reactors Branch 2 79/04/16 7pp

DOCKETED ITEMS

17

7903100239 Notification of 790427 meeting w/util to discuss status of investigation into small primary sys coolant leak
NOWICKI, S J Operating Reactors Branch 2 79/04/24 1p

7903040099 Responds to NRC 790115 request for info Consultant will be utilized to develop seismic design basis which will entail providing dynamic models of structures listed in encl & response spectra at specified locations
BIXEL, D A Consumers Power Co 79/04/25 3pp

7903150489 Forwards revised page 3-4, inadvertently omitted from 790323 Tech Specs for license Amend 24
ZIEHMAN, D L Operating Reactors Branch 2 79/04/25 3pp

7903250095 Comments on draft evaluation "Station Battery Test Requirements," systematic evaluation program Topic VIII-3.A
BIXEL, D A Consumers Power Co 79/05/22 2pp

7903310449 Responds to IE Bulletin 78-12, "Atypical Weld Matl in Reactor Pressure Vessels " Final rept will be submitted by 790731
BIXEL, D A Consumers Power Co 79/05/29 1p

Q Inspection reports, IE Bulletins & correspondence

7905010333 Forwards IE Insp Rept 50-155/79-03 on 790226-0302 No noncompliance noted
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/03/19 2pp

--7905010336 IE Insp Rept 50-155/79-03 on 790226-0302 No noncompliance noted Major areas inspected design changes, mod program procedures & refueling surveillance
RIDGWAY, K R Region 3, Chicago, Office of the Director 79/03/15 8pp

7905030041 Forwards IE Insp Rept 50-155/79-02 on 790214-16 No noncompliance noted
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch, 79/03/19 2pp

--7905030046 IE Insp Rept 50-155/79-02 on 790214-16 No noncompliance noted Major areas inspected refueling radiation protection activities, including procedures, advanced planning, training, exposure, matl control & posting
SCHUMACHER, M C Region 3, Chicago, Office of the Director
FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/03/13 7pp

7905010247 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping "
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23 1p

7905040026 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks "
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26 1p

7905010162 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air "
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/28 1p

7905010390 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin "
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/30 1p

7905290554 Forwards IE Insp Rept 50-155/79-04 on 790213-14, 0313 & 26-27.
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch, 79/04/09 2pp

7905290569 IE Insp Rept 50-155/79-04 on 790213-14, 0313 & 26-27 No noncompliance noted Major areas inspected inservice insp GA/QC program, implementing procedures, work activities, nondestructive examination data & repts & core spray
WARD, K D, RIDGWAY, K R, DANIELSON, D H Region 3, Chicago, Office of the Director, 79/04/05 10pp

7905030025 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
KEPPLER, J O Region 3, Chicago, Office of the Director, 79/04/11 1p

7905010579 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified during TMI Incident "
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040328 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040550 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905070162 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905030220 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/17 1p

7905080486 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl "
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/21 1p

7905150355 Responds to 790329 request to allow util to combine reviews of IE Bulletin 79-02 & systematic evaluation program Topic III-5 A Since bulletin involves safety issue, NRC refuses to extend time for review
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/26 1p

7905310078 Informs that response to IE Bulletin 79-08, "Events Relevant to BWR Identified During TMI Incident," will be delayed one week due to plant outage considerations
HOFFMAN, D P Consumers Power Co 79/04/27 1p

7905240893 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase "
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/02 1p

7905290278 Provides addl response to IE Bulletin 79-07 Forwards verification benchmarks used for dynamic piping analyses
BIXEL, D A Consumers Power Co 79/05/04 7pp

7905210163 Responds to IE Bulletin 79-08 re events relevant to BWRs identified during TMI-2 incident No Tech Spec will be required to implement actions discussed in 790504 ltr
HOFFMAN, D P Consumers Power Co 79/05/16 1p

7905090319 "Quarterly Status Rept of Investigations & Mods," Jan-Mar 1979, Rept 21
* Pacific Gas & Electric Co 79/04/20, 1p

B Reportable occurrences, LERs & related correspondence

7905080480 Forwards LERs 79-019/03L-0 & 79-018/01T-0
BIXEL, D A Consumers Power Co 79/05/02 1p

--7905080484 LER 79-019/03L-0 on 790418 following scram & during routine primary sys leak rate testing, unidentified leakage observed at 1.85 gpm Apparent cause was cooling water temp transients
* Consumers Power Co 79/05/02 1p

--7905080488 LER 79-018/01T-0 on 790402 minor water leakage observed at interface between reactor vessel & F-2 rod drive housing Leak stopped when primary sys pressure was reduced to atmospheric conditions
* Consumers Power Co, 79/05/02 3pp.

7905150457 Forwards LER 79-017/03L-0
BIXEL, D A Consumers Power Co 79/05/10 1p

--7905150459 LER 79-017/03L-0 on 790410 eight mechanical snubbers on reactor depressurization sys piping appeared inadequately installed during NRC insp Units deemed inoperable w/o proof until mods completed 790426
* Consumers Power Co 79/05/10 1p

DOCKETED ITEMS

DOCKET 50-156 UNIV OF WISCONSIN RESEARCH REACTOR

J Insurance & indemnity information

7905160306 Forwards Amend 12 to Indemnity Agreement E-37, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905130435 Forwards executed Amend 12 to Indemnity Agreement E-37 WINTER, R W Wisconsin Univ of, Madison 79/05/10 2pp

G Inspection reports, IE Bulletins & correspondence

7905130159 Forwards IE Insp Rept 50-156/79-01 on 790315-16 No noncompliance noted
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/03/26 2pp

--7905150163 IE Insp Rept 50-156/79-01 on 790315-16 No noncompliance noted Major areas inspected operational experience, maint, surveillance, operator requalification, audits & procedures
LITTLE, H S Region 3, Chicago, Reactor Operations Nuclear Support Branch, MASSE, R E DANIELS, F T Region 3, Chicago, Office of the Director 79/03/23 3pp

DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR

J Insurance & indemnity information

7905300038 Forwards Amend 11 to Indemnity Agreement E-4, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-160 GEORGIA INST OF TECH RESEARCH REACTOR

J Insurance & indemnity information

7905300045 Forwards Amend 12 to Indemnity Agreement E-30, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

G Inspection reports, IE Bulletins & correspondence

7905070137 Forwards IE Bulletins 79-05, 79-05A & 79-06, re nuclear incident at TMI
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/13 1p

DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR

J Insurance & indemnity information

7905130376 Forwards Amend 9 to Indemnity Agreement E-22, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group, 79/05/01 5pp

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

J Insurance & indemnity information

7905130373 Forwards Amend 9 to Indemnity Agreement D-2, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905310356 Returns unsigned Amend 9 to Indemnity Agreement B-2, federal agencies are exempt per 10CFR140 10
MCINDOE, D W Defense, Dept of, Defense Nuclear Agency, 79/05/23 2pp

DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1

J Insurance & indemnity information

7905140415 Forwards Amend 20 to Indemnity Agreement B-28 per 10CFR140 changes re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp

DOCKET 50-182 PURDUE UNIV RESEARCH REACTOR

J Insurance & indemnity information

7905160258 Forwards Amend 9 to Indemnity Agreement E-6, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905300422 Forwards executed Amend 9 to Indemnity Agreement E-6 SMITH, R E Purdue Univ 79/05/22 2pp

G Inspection reports, IE Bulletins & correspondence

7905110041 Forwards IE Insp Repts 50-182/79-01 & 70-0150/79-02 on 790213-15 Notice of violation withheld (ref 10CFR2 790)
* Region 3, Chicago, Safeguards Branch 79/03/26 2pp

--7905110047 IE Insp Repts 50-182/79-01 & 70-0150/79-02 on 790213-15 Noncompliance noted keys, locks & hardware deficiencies for fast breeder blanket facility Details withheld (ref 10CFR2 790)
CHRISTOFFER, G M, MAEDA, T J Region 3, Chicago, Office of the Director
HIND, J A Region 3, Chicago, Safeguards Branch 79/03/21 1p

DOCKET 50-183 VALLECITOS EXPERIMENTAL SUPERHEAT REACTOR

A Application/construction stage documents & correspondence

7905090275 Summarizes 790403-04 meeting w/NRC in San Jose, CA re piping improvement program Progress Rept & Forwards requested action items re piping analysis
GRIDLEY, R L General Electric Co, Nuclear Energy Products Div 79/04/23 125pp

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

J Insurance & indemnity information

7905160281 Forwards Amend 11 to Indemnity Agreement D-9, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905240354 Forwards executed Amend 11 to Indemnity Agreement D-9 AMBLER, E Commerce, Dept of, National Bureau of Standards 79/05/15 2pp

DOCKET 50-186 UNIV OF MISSOURI RESEARCH REACTOR

J Insurance & indemnity information

7905160339 Forwards Amend 11 to Indemnity Agreement E-45, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905310401 Forwards executed Amends 10 & 11 to Indemnity Agreements E-23 & E-25, respectively
BLANBETT, V Missouri, Univ of 79/05/25 3pp

DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR

J Insurance & indemnity information

7905160345 Forwards Amend 13 to Indemnity Agreement B-26, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group, 79/05/01 5pp

DOCKET 50-188 KANSAS STATE UNIV RESEARCH REACTOR

J Insurance & indemnity information

7905160282 Forwards Amend 11 to Indemnity Agreement E-1, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905230384 Forwards Amend 11 to Indemnity Agreement E-1 HOFFMAN, W C Kansas State Univ 79/05/17 2pp

DOCKETED ITEMS

19

Q Inspection reports, IE Bulletins & correspondence

7903150596 Forwards IE Insp Rept, 90-188/79-01 on 790312-15 No noncompliance noted
HADBEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/03/28 2pp

--7903150604 IE Insp Rept 90-188/79-01 on 790312-15 No noncompliance noted Major areas inspected licensee's internal review, operating procedures, radiation protection, environ protection & emergency planning
JOHNSON, E H, COMSTABLE, G L Region 4, Dallas, Office of the Director HADBEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/03/27 9pp

DOCKET 90-191 BABCOCK & WILCOX COMPANY CRITICAL FACILITY

J Insurance & indemnity information

7903300714 Forwards Amend 19 to Indemnity Agreement B-B, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7903290427 Forwards executed Amend 1 to Indemnity Agreement C-2 & Amend 19 to Indemnity Agreement B-B
OLSEN, A F Babcock & Wilcox Co 79/05/21 3pp

DOCKET 90-192 UNIV OF TEXAS RESEARCH REACTOR

J Insurance & indemnity information

7903160355 Forwards Amend 11 to Indemnity Agreement E-25, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 90-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC

J Insurance & indemnity information

7903160260 Forwards Amend 9 to Indemnity Agreement E-43, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7903190049 Amend 9 to Indemnity Agreement E-43
SALTZMAN, J Antitrust & Indemnity Group 79/05/14 1p

DOCKET 90-199 MANHATTAN COLLEGE RESEARCH REACTOR

J Insurance & indemnity information

7903150377 Forwards Amend 10 to Indemnity Agreement E-41, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp.

DOCKET 90-200 B&W TEST REACTOR

J Insurance & indemnity information

7903300714 Forwards Amend 19 to Indemnity Agreement B-B, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7903290427 Forwards executed Amend 1 to Indemnity Agreement C-2 & Amend 19 to Indemnity Agreement B-B.
OLSEN, A F, Babcock & Wilcox Co 79/05/21 3pp

DOCKET 90-201 WEST VALLEY REPROCESSING PLANT

Q Adjudicatory correspondence

7903150732 Requests JM Hendrie to appear at 790404 hearing re safety aspects of high level radwaste tanks at facility Test results showed leak in pan under tank containing 600,000 gallons high level liquid radwaste
HOYT, W. B. New York, State of 79/03/21, 1p

J Insurance & indemnity information

7903160311 Forwards Amend 10 to Indemnity Agreement B-29, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

P Operating license stage documents & correspondence

7905020214 Notifies that high level waste stored at West Valley, NY will not be moved from site BD-2 to BD-1, as previously stated Action unwarranted & counterproductive to ongoing NRC studies
CLARK, J R Nuclear Fuel Services, Inc (subs of Getty Oil Co) 79/03/27 1p

7905030035 Forwards "Evaluation of Safety Associated w/Defect in Pan BD-2 at West Valley, NY " Defect cause unknown No attempt should be made to repair pan w/o further detailed analysis
HAUGHNEY, C J Fuel Reprocess & Recycle Branch 79/03/29 6pp

7903230813 Responds to 790322 ltr re radiation levels in Cattaraugus Creek & silt above Springville Power Dam Forwards data re silt samples for 1967-69, 1971, 1977 & 1978
CASHMAN, T J New York, State of 79/04/19 4pp

7903290282 Forwards NY Dept of Environ Conservation 790419 ltr to JA Lango of Springville, NY re detection of radioactivity in silt samples at Springville Dam W/data on silt samples for 1967-69, 1971 & 1977-78
CLARK, A T Fuel Reprocess & Recycle Branch 79/05/01 5pp

Q Inspection reports, IE Bulletins & correspondence

7905010082 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air."
GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/28, 1p

R Periodic operating reports & related correspondence

7905240619 Forwards discharge monitoring rept for Mar 1979 Radioactivity results re outfalls 001 & 003 will be reported as data becomes available
OLDHAM, W A Nuclear Fuel Services, Inc (subs of Getty Oil Co) 79/04/10 5pp

DOCKET 90-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

7905230914 Updates status of commitments re operating functions & plant mode of fire protection program Discusses safe shutdown casualty procedure, spurious valve actuation & hydrogen seal oil area fire.
BUSKIN, K P Southern California Edison Co 79/05/15 3pp

I Financial information

7905150400 Forwards "Annual Financial Rpt 1978" for S Edison Co & San Diego Gas & Electric Co
DRAKE, J H Southern California Edison Co 79/05/15

DOCKETED ITEMS

7905070382 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905160314 Forwards Amend 12 to Indemnity Agreement B-31, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790301 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905190150 Forwards executed Amend 12 to Indemnity Agreement B-31
WILLIAMS, F P San Diego Gas & Electric Co 79/05/14 1p

P Operating license stage documents & correspondence

7905020449 Forwards Amend 40 to License DPR-13, safety evaluation, notice of issuance & availability Security plan evaluation withheld (ref 10CFR2 790)
ZIEHANN, D L Operating Reactors Branch 2 79/04/10 3pp

--7905020450 Amend 40 to License DPR-13, requiring maint & implementation of physical security plan
ZIEHANN, D L Operating Reactors Branch 2 79/04/10 2pp

--7905020457 Notice of issuance & availability of Amend 40 to License DPR-13
ZIEHANN, D L Operating Reactors Branch 2 79/04/10 2pp

7905240302 Requests licenses provide design mods which will assure safe shutdown can be achieved & maintained using onsite power source
LAINAS, G Plant Systems Branch 79/04/13 2pp

7905090020 Forwards topics deleted from systematic evaluation program review of facilities Requests review & identification of errors within 30 days from receipt of ltr
ZIEHANN, D L Operating Reactors Branch 2 79/04/16 7pp

7905020218 Forwards draft evaluation of systematic evaluation program Topic VI-10 B Requests review & response within three days
ZIEHANN, D L Operating Reactors Branch 2 79/04/18 6pp

7905160319 Evaluates possible vibration problems re operation of chemical val & control sys test pump No problems anticipated
BASKIN, K P Southern California Edison Co 79/04/20 3pp

7905090347 Forwards Amend 7B to License DPR-13 Affidavit & Certificate of Svc encl
DRAKE, J H Southern California Edison Co 79/05/04 7pp

--7905090361 Amend 7B to License DPR-13, consisting of proposed Tech Spec Change 79, increasing annual discharge limit of sulphuric acid to allow Units 2 & 3 to discharge startup flushing wastewater directly into Unit 1
Southern California Edison Co 79/05/04 48pp

7905150374 Forwards results of util examination of NRC 790315 revised systematic evaluation program topic assessments
HAYNES, J O Southern California Edison Co 79/05/04 2pp

7905290069 Notifies of inability to meet reply deadline for IE Bulletin 78-12A Awaiting info from Westinghouse
HEAD, J T Southern California Edison Co 79/03/23 1p

7905010220 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Bys w/Bvc Air Bys Used as Source of Breathing Air"
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/03/28 1p

7905010431 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/03/30 1p

7905010020 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident"
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 1p

7905010025 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident" Licensee action required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 1p

7905040311 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident"
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 1p

7905040619 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 1p

7905070104 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 1p

7905030299 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys" Licensee action required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/17 1p

7905290500 Responds to IE Bulletin 79-06A, Item 5, re initiation of auxiliary feedwater sys. Bys initiated by operator action Requests exemption from requirements of item; immediate initiation is not essential
HEAD, J T Southern California Edison Co 79/04/19 2pp

7905080371 Forwards IE Bulletin 79-09B, "Nuclear Incident at TMI-Suppl"
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/21 1p

7905240073 Responds to IE Bulletin 79-07 re seismic stress analysis Computer codes containing algebraic summation errors have not been used in design &/or analysis at facility Computer code confirmation will be forwarded by 790330
HEAD, J Southern California Edison Co 79/04/24 2pp

R Periodic operating reports & related correspondence

7905150409 Forwards monthly operating rept for Apr 1979
CURRAN, J M Southern California Edison Co 79/05/04 1p.

DOCKETED ITEMS

21

7905040128 Forwards PND-79-67B
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/12 1p

7905150145 Forwards PND-79-67T
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/13 1p

7905030024 Forwards PND-79-67U
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/14 1p

7905020532 Forwards PND-79-67AA
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/20 1p

7905010434 Forwards PND-79-67AB
ENGELKEN, R H Region 5, San Francisco, Office of the Director.
79/04/21 1p

7905010449 Forwards PND-79-67AC & AD
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/23, 1p

7905010462 Forwards PND-79-67AE
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/24 1p

7905090041 Forwards PND-79-67AF
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/25 1p.

7905090057 Forwards PND-79-67AG
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/26 1p.

7905040586 Forwards LER 79-003/03L-0.
HEAD, J T Southern California Edison Co 79/04/27 2pp

--7905040592 LER 79-003/03L-0 on 790402 sea temp data from three sensors
not obtained for three periods Caused by double film image
on cartridge, jammed film cartridge & unit torn from
anchorage All units repaired or replaced
OTTOSON, H L Southern California Edison Co 79/05/01 1p

7905090119 Forwards PND-79-67AH.
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/27, 1p

7905070031 Forwards PND-79-67AI, AJ & AK, per NRC 790401 ltr transmitting
IE Bulletin 79-05
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/30 1p

7905070012 Forwards PND-79-67AL, per NRC 790401 ltr transmitting IE
Bulletin 79-05
ENGELKEN, R H Region 5, San Francisco, Office of the Director.
79/05/01 1p

7905080418 Forwards LER 79-003/03L-0
MOORE, J B Southern California Edison Co 79/05/03 2pp.

--7905080425 LER 79-003/03L-0 on 790404, during normal operation, isolation
valve on cooling water from containment air handling units
failed to latch in open position Caused by dislodged wire
clip & metal pin Solenoid replaced & pin secured
CURRAN, J M Southern California Edison Co 79/05/03, 1p.

7905110134 Forwards LER 79-002/03L-0.
HEAD, J T Southern California Edison Co. 79/05/04, 2pp.

--7905110139 LER 79-002/03L-0 on 790404, feedwater flow indication B rose
to 10% above actual flow, Caused by flow straightening tube
bundle dislodgement Straighteners B & C replaced &
attachment strengthened
CURRAN, J M. Southern California Edison Co 79/05/04 1p

7905030044 Forwards PND-79-67AM
ENGELKEN, R H Region 5, San Francisco, Office of the Director,
79/05/07 1p.

7905150503 Forwards LER 79-006/03L-0.
HEAD, J T. Southern California Edison Co. 79/05/11 2pp.

--7905150512 LER 79-006/03L-0 on 790413, two quarterly & two yearly
environ direct radiation TLDs were lost, Caused by vandalism.
TLDs now in locked PVC tube & permanently fastened at sample
locations
CURRAN, J M Southern California Edison Co. 79/05/11, 1P

7905300265 Forwards interim rept of Marine Review Committee re ECCB
MONO, B California, State of 79/05/13 1p

--7905300270 "Interim Rept of Marine Review Committee to CA Coastal
Commission, Part I General Summary of Findings, Predictions &
Recommendations Concerning Cooling Bys "
CONNELL, J H, MECHALAS, B J, MINHURSKY, J A California, State of
79/05/12 22pp

--7905300277 "Interim Rept of Marine Review Committee to CA Coastal
Commission, Part II App of Technical Evidence in Support of
General Summary "
CONNELL, J H, MECHALAS, B J, MINHURSKY, J A California, State of
79/05/12 197pp

7905310439 Forwards LER 79-007/03L-0.
HEAD, J T. Southern California Edison Co 79/05/22 1p

--7905310444 LER 79-007/03L-0 on 790423 during full power operation, steam
flow indicator for steam generator A failed, indicating
zero flow Caused by failed power supply in steam flow
indication circuitry Failed power supply replaced
CURRAN, J M Southern California Edison Co 79/05/22 1p

DOCKET 50-208 COLUMBIA UNIV RESEARCH REACTOR

J Insurance & indemnity information

7905160238 Forwards Amend 2 to Indemnity Agreement E-60, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-213 HADDAM NECK PLANT

F Security, medical, emergency & fire protection plans

7905270073 Forwards response to NRC verbal questions re fire
protection Engineering & design of most mods in progress
COUNSEL, M G Northeast Utilities 79/05/18 16pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 178, 179, 180, 182, 185, 186, 187, 189, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01
1p

7905160289 Forwards Amend 12 to Indemnity Agreement B-32, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01

P Operating license stage documents & correspondence

7905090016 Forwards topics deleted from systematic
review of facilities, Requests review & identifica
errors within 30 days from receipt of ltr
ZIEHANN, D L, Operating Reactors Branch 2, 79

7905240303 Informs that latest revision to operatic
described in Revision 3A to QA rept NU-QA-1, forw
on 790426
COUNSEL, M G Connecticut Yankee Atomic Power Co

G. Inspection reports, IE Bulletins & correspondence

7905090142 Forwards IE Insp Rept 50-213/79-05 on 79
noncompliance noted.
BRUNNER, E J Region 1, Philadelphia, Reactor
Support Branch 79/03/14, 2pp.

--7905090146 IE Insp Rept 50-213/79-05 on 790221-2
noted, Major areas inspected licensee strike co
plans & refueling/maint activities.
LAZARUS, W J Region 1, Philadelphia, Office
KEIMIO, R R Region 1, Philadelphia, Reactor
Support Branch, 79/03/13, 4pp.

DOCKETED ITEMS

7905010103 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/03/23 1p

7905030276 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/03/26 1p

7905010040 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/ Svc Air Sys Used as Source of Breathing Air"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/03/28 1p

7905010290 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/03/30 1p

7905020036 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/11 1p

7905020354 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040010 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040188 Forwards IE Bulletin 79-06, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905250446 Responds to IE Bulletin 79-03 re longitudinal weld defects in ASME SA-312 stainless steel pipe. Pipe not in use or planned for use in unit
COUNCIL, W O Northeast Utilities 79/04/16 1p

7905030059 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/17 1p

7905010641 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/18 1p

7905240392 Responds to IE Bulletin 79-06A & 79-06A, Revision 1, re TMI errors. Discusses changes in operating procedures, preventative measures & instructions to personnel
COUNCIL, W O Connecticut Yankee Atomic Power Co 79/04/24 79pp

7905310473 Responds to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp." No Velan valves in use on Seismic Category I piping sys
COUNCIL, W O Connecticut Yankee Atomic Power Co 79/04/26 1p

7905070542 Forwards "Inservice Insp & Testing Program," revised Jan 1978
COUNCIL, W O Connecticut Yankee Atomic Power Co 79/04/27 2pp

--7905070544 "Inservice Insp & Testing Program," revised Jan 1978
* Connecticut Yankee Atomic Power Co. 79/04/30 69pp.

7905300323 Forwards 790131-0223 steam generator tube insp rept
COUNCIL, W O Connecticut Yankee Atomic Power Co 79/05/23 1p

--7905300327 "Eddy Current Examination, Tube Sheet Cleaning & Explosive Plugging," insp rept for 790131-0223
* Connecticut Yankee Atomic Power Co 79/02/23 33pp

R Periodic operating reports & related correspondence

7905210211 Forwards monthly operating rept for Apr 1979
GRAVES, R H Connecticut Yankee Atomic Power Co 79/05/11 1p

--7905210214 Monthly operating rept for Apr 1979
* Connecticut Yankee Atomic Power Co 79/05/11 9pp

B Reportable occurrences, LERs & related correspondence

7905040061 Forwards LER 79-006/99X-0
GRAVES, R H Connecticut Yankee Atomic Power Co 79/04/26 1p

--7905040070 LER 79-006/99X-0 on 790118 auxiliary feed pump dia nil discharge at rated flow Cause Undetermined. New rotor & cooler supply water resulted in acceptable test
FLEMING, B T Connecticut Yankee Atomic Power Co 79/04/24 2p

7905310446 Notifies of 790517 RD during which 230 gallons of sodium hydrochloride were released at river's edge in 6-h period
GRAVES, R H Connecticut Yankee Atomic Power Co 79/05/23 2pp

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

O Adjudicatory correspondence

7905080039 Notifies of OE proposal for reanalysis of equipment effects resulting from a combination of seismic & LOCA loads for Mark II & III plants. Adequacy of proposed methodology being reviewed w/supporting documentation
WOODHEAD, C P Branch 3 79/04/04 1p

--7905080041 Board notification status of actions re program of reanalysis for Mark II & III sys. Evaluation will be included in individual safety evaluation
MATTSON, R J Division of Systems Safety 78/04/03 1p

--7905080044 Concludes nothing new was achieved in OE 790301 briefing on safety issues. However, structured pattern bringing separate issues together in equipment design program was innovative
MATTSON, R J Division of Systems Safety 78/03/16 4pp

--7905080048 Forwards handouts & list of attendees for meeting to identify deficiencies in acceptance criteria & combination methods proposed by OE for use in reanalysis of Mark II & III plant equipment
MATTSON, R J Division of Systems Safety 78/03/06 21pp

--7905080051 "Methodology for Combining Dynamic Responses"
CUDLIN, R, MOSEFORD, S, MATTU, R Office of Nuclear Reactor Regulation NUREG-0484 78/09/30 26pp Available at NTIS

7905090419 Forwards HR Denton 780929 memo discussing results of recently conducted fire protection research test by UL for NRC fire protection research program
WOODHEAD, C P Branch 3 79/04/05 1p

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHI, J American Nuclear Insurers, 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 27, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05 1p.

7905160292 Forwards Amend 12 to Indemnity Agreement B-37, per IOCFR-1; changes re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905290331 Forwards executed Amend 12 to Indemnity Agreement B-37
FINFROCK, I R Jersey Central Power & Light Co 79/05/21 3pp

7905290394 Forwards executed Amend 10 to Indemnity Agreement B-37
FINFROCK, I R Jersey Central Power & Light Co 79/05/21 3pp

P Operating license stage documents & correspondence

7905140570 "Analysis of Populations of Boring & Fouling Organisms in Vicinity of Oyster Creek Nuclear Generating Station," annual progress rept, Sept 1977-Aug 1978
HOAGLAND, K E, CROCKET, L Lehigh Univ, FIN B-5744 NUREG/CR-0631 79/03/31 115pp. Available at NTIS \$7.25.

7905090024 Forwards topics deleted from systematic evaluation program review facilities. Requests review & identification of errors & comments within 30 days from receipt of ltr
ZIEMANN, D L Operating Reactors Branch 2 79/04/16 7pp

DOCKETED ITEMS

23

7905070633 Informa of near completion of evaluation to determine impact of operation w/four recirculation pumps on currently docketed LOCA analysis & corresponding limits in Amend 33 Plant operation restricted until analyses completed
FINFROCK, I R Jersey Central Power & Light Co 79/04/30 3pp

/7905210173 Forwards Mar 1979 Mark I containment program activity review
BORDON, L J General Electric Co 79/05/10 6pp

7905220360 Submit info requested in 790501 telcon re proposed mode of operation pending completion of analyses to support four pump operation Discusses backflow through idle loop & heat generation rate curves during interim period
BORDON, G R GPU Service Corp 79/05/15 3pp

7905240347 Informa of no further comment or corrections to NRC revised safety assessment of systematic evaluation program Topic V-10 A
FINFROCK, I R Jersey Central Power & Light Co 79/05/15 1p

/7905210174 Forwards "Evaluation of Oyster Creek Reactor Core Liquid Level Following Inadvertent Reactor High Pressure Scram on 790502" Supplements 790512 submittal of transient analysis Addl info on reactor offgas activity encl
FINFROCK, I R Jersey Central Power & Light Co 79/05/17 2pp

--7905210174 "Evaluation of Oyster Creek Reactor Core Liquid Level Following Inadvertent Reactor High Pressure Scram on 790502" prepared by Exxon Nuclear Co, Inc
* Jersey Central Power & Light Co XN-NF-79-47 79/05/15 35pp

/7905210270 Forwards response to NRC info request re effect of four pump operation upon transient & accident analysis other than LOCA
BORDON, G R GPU Service Corp 79/05/17 4pp

/7905220000 Forwards schedule for implementation & resolution of MARK I containment long-term program All forum mods will be completed prior to Jan 1981
FINFROCK, I R Jersey Central Power & Light Co 79/05/17 2pp

/7905190066 Draft 1st ltr re status & rate of improvement of radiation protection program
QUIER, B H Region 1, Philadelphia, Office of the Director 79/05/10 3pp

/7905210267 Forwards "Bounding loss of Coolant Inventory Transient for Oyster Creek Plant" & info clarifying several aspects of original 790502 & 790517 submittals
FINFROCK, I R Jersey Central Power & Light Co 79/05/17 24pp

/7905210267 Forwards Tech Spec Change Request 72, modifying Section 2.1 D & adding Section 2.1 F
FINFROCK, I R Jersey Central Power & Light Co 79/05/17 1p

--7905210267 Tech Spec Change Request 72, modifying Section 2.1 D to extend applicability of safety limit & adding Section 2.1 F to prevent isolation of at least two recirculation pump loops, Certificate of BVC encl
* Jersey Central Power & Light Co 79/05/19 8pp

/7905240513 Forwards payment for Tech Spec Change Request 72
TIPTON, T L Jersey Central Power & Light Co 79/05/19 1p

7905250302 Responds to NRC 790317 questions re loss-of-inventory transient analysis Pump coastdown curves encl
* Jersey Central Power & Light Co 79/05/23 4pp

7905290170 Forwards Tech Spec Change Request 72, Addendum 1, adding limiting safety sys setting Water quality rept & Certificate of BVC encl
FINFROCK, I R Jersey Central Power & Light Co 79/05/23 27pp

--7905290170 Tech Spec Change Request 72, Addendum 1, adding new safety sys setting
* Jersey Central Power & Light Co 79/05/23 6pp

7905290194 Forwards Tech Spec Change Request 72, Addendum 1, re incorporation of new safety sys setting to Section 2.3 of App A
FINFROCK, I R Jersey Central Power & Light Co 79/05/23 1p

7905290172 Forwards Tech Spec Change Request 73 re incorporation of MAPLHOR curves w/Certificate of BVC & appropriate Class III fee
FINFROCK, I R Jersey Central Power & Light Co 79/05/24 3pp

Q Inspection reports, IE Bulletins & correspondence

7905110216 Forwards IE Insp Rept 50-219/79-04 on 790221-23 No noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/20 2pp

--7905110217 IE Insp Rept 50-219/79-04 on 790221-23 No noncompliance noted Major areas inspected previous insp findings, in-office review of periodic repts & LERs & containment spray exchanger review
BRIGGS, L E Region 1, Philadelphia, Office of the Director
MCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/19 8pp

7905010110 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
QUIER, B H Region 1, Philadelphia, Office of the Director 79/05/23 1p

7905010046 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/BVC Air Sys Used as Source of Breathing Air"
QUIER, B H Region 1, Philadelphia, Office of the Director 79/05/28 1p

7905010298 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
QUIER, B H Region 1, Philadelphia, Office of the Director 79/05/30 1p

7905100321 Forwards summary of 790228, 790301 & 790322 re reaction to IE Bulletin 78-03, "Potential Explosive Gas Mixtures Accumulations Associated w/BWR Offgas Sys Operations"
ZIEHANN, D L Operating Reactors Branch 2 79/05/30 4pp

7905020045 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
QUIER, B H Region 1, Philadelphia, Office of the Director 79/04/11 1p

7905250349 Responds to IE Bulletin 79-03, "Longitudinal Weld Defects in ASME SA-312 Type 304 Stainless Steel Pipe Spools Mfg by Youngstown Welding & Engineering Co" No plans to use pipes in safety-related sys
ROSB, D A Jersey Central Power & Light Co 79/04/11 1p

7905020337 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
QUIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905040025 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
QUIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905040204 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
QUIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

DOCKETED ITEMS

- 7905220381 Forwards LER 79-014/011-0
FINFROCK, I R Jersey Central Power & Light Co 79/05/16 1p
- 7905220388 LER 79-014/011-0 on 790302 while performing test of
isocandenser auto-actuation system for high pressure trips
occurred. Caused by lack of procedural direction. Procedures
reviewed & changed
ROSS, D A Jersey Central Power & Light Co 79/05/16 2pp
- 7905290014 Forwards LER 79-012/03L-0
FINFROCK, I R Jersey Central Power & Light Co 79/05/17 1p
- 7905290017 LER 79-012/03L-0 on 790419 oxygen level in suppression
chamber atmosphere was greater than 5% Caused by sensitivity of
oxygen analyzer & position of sample flow control valve
Oxygen analyzer recalibrated, now below 5%
ROSS, D A Jersey Central Power & Light Co 79/05/17 1pp
- 7905290023 Forwards LER 79-011/03L-0
FINFROCK, I R Jersey Central Power & Light Co 79/05/17 1p
- 7905290025 LER 79-011/03L-0 on 790419 core spray pump H/HA 11 1/2
failed to start upon initiation signal. Caused by fuse
failure. Fuse replaced & pump test successfully completed
ROSS, D A Jersey Central Power & Light Co 79/05/17 1pp
- 7905290164 Forwards LER 79-010/03L-0
FINFROCK, I R Jersey Central Power & Light Co 79/05/17 1p
- 7905290175 LER 79-010/03L-0 on 790417 leak of vent pipe in
noticed near inside penetration within pipe tunnel. Cause is
component failure. Drywell equipment drain tank line
routed to prevent further leakage
ROSS, D A Jersey Central Power & Light Co 79/05/17 1pp
- T Hearing transcripts on non-antitrust matters
- 7905290003 Transcript of 790303 briefing in Washington, D.C. by
HENDRIE, J M, GILINSKY, V, KENNEDY, R T Commission 79/05/17 1p
- 7905240609 Responds to 790409 ltr re constituent inquiry about
radioactive water stored under facility. Water passed through
condenser, was decontaminated & returned to condensate
storage tank
GOSSICK, L V Office of Congressional Affairs 79/05/17 1pp
- 7905240626 Requests info re disposal of 200,000 gallons of radioactive
water stored under facility near Forted River, NJ four to
five years ago
KOSTHAYER, P H House of Rep 79/04/09 1p
- DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1
F Security, medical, emergency & fire protection plans
- 7905030346 Forwards request for exemption Enc1 withheld
(ref 10CFR2 790)
THOMAS, E B LeBoeuf, Lamb, Leiby & MacRae 79/05/04 1p
- J Insurance & Indemnity Information
- 7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 181, 161, 164, 170,
173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 191, 194, 197,
198, 199, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATROCHI, J American Nuclear Insurance 79/05/01 1p
- 7905070582 Confirms increase in liability limit to \$24,000,000 for
policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 84, 85,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p
- 7905160286 Forwards Amend 13 to Indemnity Agreement B-24, per 10CFR21.1
changes, re increase from \$140 million to \$160 million
effective 790501 Supporting documentation enc1
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 3pp
- 7905180291 Forwards executed Amend 13 to Indemnity Agreement B-24
RUSHMORE Niagara Mohawk Power Corp. 79/05/10 3pp
- 7905220381 Forwards LER 79-014/011-0
FINFROCK, I R Jersey Central Power & Light Co 79/04/30 1p
- 7905220388 LER 79-014/011-0 on 790427 LOCA analysis does not consider
recirculation pump using four recirculation loops
analysis of recirculation pump analysis underway
ROSS, D A Jersey Central Power & Light Co 79/04/30 2pp
- 7905240609 Forwards LER 79-012/03L-0
FINFROCK, I R Jersey Central Power & Light Co 79/05/01 1p
- 7905290014 LER 79-012/03L-0 on 790432 rod worth minimizer not
functioning & was bypassed during third critical low power
test. Cause by failure to complete second part of
required testing & initialization sequence. Test stopped
ROSS, D A Jersey Central Power & Light Co 79/05/01 3pp
- 7905290023 Forwards LER 79-011/03L-0
FINFROCK, I R Jersey Central Power & Light Co 79/05/03 1p
- 7905290025 LER 79-011/03L-0 on 790302 during performance of actuation
sequence test, false inadvertent reactor high pressure
alarm occurred. Caused by possible operator error in closing
discharge valves. Reactor coolant analyses performed
QUINTENZ, T E Jersey Central Power & Light Co 79/05/02 3pp
- 7905290164 Forwards LER 79-010/03L-0
FINFROCK, I R Jersey Central Power & Light Co 79/05/04 1p
- 7905290175 LER 79-010/03L-0 on 790302 during recovery period
following reactor scram, pump was operated in violation of
Tech Specs. Caused by unusual s/c condition. Corrective action
still undetermined
ECCLEHAUSER, J E Jersey Central Power & Light Co 79/05/02 2pp
- 7905240609 Forwards LER 79-007/03L-0
FINFROCK, I R Jersey Central Power & Light Co 79/05/08 1p
- 7905240626 LER 79-007/03L-0 on 790408 torus to drywell vacuum breaker
valve alarm would not activate when valve opened more than
0.10 inch. Caused by loose jam-nut on valve arm. Jam-nut
tightened & valve retested
ROSS, D A Jersey Central Power & Light Co 79/05/08 3pp
- 7905290164 Forwards LER 79-008/03L-0
FINFROCK, I R Jersey Central Power & Light Co 79/05/08 1p
- 7905290175 LER 79-008/03L-0 on 790417 w/d reactor pump out of svc. C
reactor pump tripped. Caused by brush holder loosening from
mounting & burning tripping 30SR relay on overcurrent
Brushes & holders replaced
ROSS, D A Jersey Central Power & Light Co 79/05/08 3pp
- 7905160369 Forwards LER 79-013/011-0
ROSS, D A Jersey Central Power & Light Co 79/05/10 1p
- 7905160374 LER 79-013/011-0 on 790427 operation of reactor using four
recirculation pumps is not specifically analyzed in current
LOCA analysis. Plant derated to conform to more restrictive
MARLBOROUGH limits of Amend 20
ROSS, D A Jersey Central Power & Light Co 79/05/10 4pp
- 7905180291 Forwards "Rept on 790302 Transient" as required
by 10CFR20.36(c)(1)
FINFROCK, I R Jersey Central Power & Light Co 79/05/12 2pp
- 7905180277 "Rept on 790302 Transient"
FINFROCK, I R Jersey Central Power & Light Co 79/05/12 93pp
- 7905210210 Forwards LER 79-009/03L-0
FINFROCK, I R Jersey Central Power & Light Co 79/05/16 1p
- 7905210217 LER 79-009/03L-0 on 790416 air operated reactor bldg to
suppression chamber vacuum breaker valve V-26-1B failed to
operate. Caused by faulty solenoid actuator. Actuators
replaced
ROSS, D A Jersey Central Power & Light Co 79/05/16 3pp
- 7905210274 Forwards LER 79-015/011-0
FINFROCK, I R Jersey Central Power & Light Co 79/05/16 1p
- 7905210281 LER 79-015/011-0 on 790302 reactor recirculation pumps C & A
were started when temp of recirculation loop coolant was
over 30 F cooler than reactor coolant temp. Caused by lack of
communication between vessel annulus & core region
ROSS, D A Jersey Central Power & Light Co 79/05/16 3pp

DOCKETED ITEMS

25

P Operating license stage documents & correspondence

7905020239 Notification of 790402 meeting w/OE to discuss methodology for predicting safety relief Valve loads for Mark I containments using T-quencher
BU, T H Containment Systems Branch 79/03/26 2pp

7905020267 Detailed weld procedures to demonstrate N58 safe-end & elbow replacement
PERKINS, T J Niagara Mohawk Power Corp 79/04/24 41pp

7905080414 Forwards responses to Hydrology-Meteorology Branch questions Q372 2 & Q372 3, per 790108 ltr Design interfaces between radwaste reduction & solidification sys are not complete Accident analysis to be recalculated
RHODE, G K Niagara Mohawk Power Corp 79/05/01 22pp

7905230299 Forwards table re torus mods for Spring 1979 refueling outage Analysis is continuing, to determine if further mods are required Final analysis for major structural components is expected by end of 1979
SCHNEIDER, R R Niagara Mohawk Power Corp 79/05/16 3pp

7905230478 Responds to NRC 790319 ltr info re radiation levels in contained in annual environ operating rept
SCHNEIDER, R R Niagara Mohawk Power Corp 79/05/16 1p

7905310218 Forwards application for amend to License DPR-63 & \$4,000 fee
THOMAS, E B LeBoeuf, Lamb, Leiby & MacRae 79/05/29 2pp

--7905310221 Application for amend to License DPR-63 re Tech Specs changes to safety limits
DISE, D P Niagara Mohawk Power Corp 79/05/29 10pp

Q Inspection reports, IE Bulletins & correspondence

7905090134 Forwards IE Insp Rept 50-220/79-04 on 790206-09 & 21-23 No noncompliance noted
SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/03/19 2pp

--7905090140 IE Insp Rept 50-220/79-04 on 790206-09 & 21-23 No noncompliance noted Major areas inspected radioactive waste sys & radiation protection during refueling
THOMAS, E B Region 1, Philadelphia, Office of the Director
CROCKER, H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/03/14 8pp

7905010126 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/23 1p

7905010059 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/28 1p

7905010307 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/30 1p

7905020049 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/11 1p

7905100421 Responds to IE Bulletin 79-03 re longitudinal weld defects No piping was supplied by Youngstown Welding & Engineering Co.
SCHNEIDER, R R Niagara Mohawk Power Corp 79/04/11 1p

7905020332 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905040071 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905040237 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident" Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905030078 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/17 1p

7905020288 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/18 1p

R Periodic operating reports & related correspondence

7905150508 Forwards monthly operating rept for Apr 1979
SCHNEIDER, R R Niagara Mohawk Power Corp 79/05/10 1p

--7905150511 Monthly operating rept for Apr 1979
PERKINS, T J Niagara Mohawk Power Corp 79/05/08 6pp

S Reportable occurrences, LERs & related correspondence

7905070401 Forwards LER 79-005/03L-0
SCHNEIDER, R R Niagara Mohawk Power Corp 79/04/30 1p

--7905070411 LER 79-005/03L-0 on 790401 during periodic Type C leakage test, valves IV-6B-06, IV-201-09, IV-201-10 & IV-58 1-02 were found to be in excess of Tech Specs Cause unknown Repairs will be made during outage
JUTRAS, R Niagara Mohawk Power Corp 79/05/01 1p

7905160392 Forwards LER 79-006/03L-0
SCHNEIDER, R R Niagara Mohawk Power Corp 79/05/10 1p

--7905160394 LER 79-006/03L-0 on 790428 overfrequency relay on motor generator set 172 could not be calibr Caused by bad potentiometer adjustment Repairs being made
DUDA, E Niagara Mohawk Power Corp 79/05/10 1p

7905300486 Forwards LER-010/03L-0
LEMPER, T E Niagara Mohawk Power Corp 79/05/23 1p

--7905300496 LER 79-010/03L-0 on 790424 during refueling outage, containment vacuum relief valve 6B IV-10 flange failed leak rate test O-rings replaced on flange
DUDA, E. Niagara Mohawk Power Corp 79/05/23 1p

DOCKET 50-223 UNIV OF LOWELL RESEARCH REACTOR

J Insurance & indemnity information

7905160268 Forwards Amend B to Indemnity Agreement E-54, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-224 UNIV OF CALIFORNIA RESEARCH REACTOR

J Insurance & indemnity information

7905300052 Forwards Amend 13 to Indemnity Agreement E-15, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

P Operating license stage documents & correspondence

7905210178 Forwards Tech Spec Change & Requests info re BNM possession limits, amount exempt & nonexempt
KAPLAN, S N California, Univ. of, Berkeley 79/05/14 1p

--7905210181 Tech Specs Change 6 for Yriga Mark III
* California, Univ. of, Berkeley 79/05/14, 38pp

DOCKET 50-225 RPI CRITICAL EXPERIMENT

J Insurance & indemnity information

7905160266 Forwards Amend 9 to Indemnity Agreement E-42, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group, 79/05/01, 5pp

DOCKETED ITEMS

P Operating license stage documents & correspondence

7903220391 Requests renewal of License CX-22 for 25 years Formal
Application to be submitted by 790901
JUDG, G Rensselaer Polytechnic Inst 79/05/14 1p

Q Inspection reports, IE Bulletins & correspondence

7903240277 Forwards IE Insp Rept 50-225/79-02 on 790220-23 No
noncompliance noted
MARTIN, W G Region I, Philadelphia, Safeguards Branch 79/03/21
2pp

--7903240287 IE Insp Rept 50-225/79-02 on 790220-23 No noncompliance
noted Major areas inspected physical security plan, including
protection of SNM access control, alarm sys & communications
surveillance Details withheld (ref 10CFR2 7901)
LADUR, R H, DEVLIN, J W Region I, Philadelphia, Safeguards
Branch 79/03/20 1p

DOCKET 50-227 TRIA THERMIONIC PROTOTYPE REACTORJ Insurance & indemnity information

7903300202 Forwards Amendment 31 to Indemnity Agreement B-9, reflecting
change in 10CFR140, increasing primary layer of liability
from \$140 million to \$160 million, effective 790301
Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-228 AEROTEST RADIOGRAPHY & RESEARCH REACTORJ Insurance & indemnity information

7903300059 Forwards Amend 17 to Indemnity Agreement B-2, reflecting
change in 10CFR140, increasing primary layer of liability
from \$140 million to \$160 million, effective 790301
Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7903240337 Forwards accepted Amend 17 to Indemnity Agreement B-2
NEWACHEK, R L Aerotest Operations 79/03/15 2pp

DOCKET 50-233 MEXICO RESEARCH REACTORJ Insurance & indemnity information

7903300202 Forwards Amendment 31 to Indemnity Agreement B-9, reflecting
change in 10CFR140, increasing primary layer of liability
from \$140 million to \$160 million, effective 790301
Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-234 TUNGSTEN NUCLEAR ROCKET CRITICAL FACILITYJ Insurance & indemnity information

7903300202 Forwards Amendment 31 to Indemnity Agreement B-9, reflecting
change in 10CFR140, increasing primary layer of liability
from \$140 million to \$160 million, effective 790301
Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-235 ACCELERATOR PULSED FAST ASSEMBLYJ Insurance & indemnity information

7903300202 Forwards Amendment 31 to Indemnity Agreement B-9, reflecting
change in 10CFR140, increasing primary layer of liability
from \$140 million to \$160 million, effective 790301
Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2F Security, medical, emergency & fire protection plans

7903030366 Forwards modified physical security plan, Revision 5 Plan
withheld (ref 10CFR2 7901)
LEE, B Commonwealth Edison Co 79/04/26 1p

7903040603 Forwards pages of "Implementation of Nuclear Mutual Limited
Loss Prevention Program," in response to NRC 780629
request re fire protection administrative controls
JANECEK, R F Commonwealth Edison Co 79/04/30 6pp

O Adjudicatory correspondence

7903250258 Notifies properly worded contention re sabotage would be
accepted Contention 6, as admitted into Duke Power Co
proceeding, encompasses aspects of revised Contention 11
presented by State of IL
GODDARD, R J Branch 2 79/04/06 2pp

J Insurance & indemnity information

7903100163 Endorsement 99 to MAELU Policy MF-22
GERAB, T Nuclear Energy Liability Insurance Association 79/03/27
1p

7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHINI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 59, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01
1p

7905140404 Forwards Amend 21 to Indemnity Agreement B-10 per 10CFR14
changes re increase in liability insurance from \$140 million
to \$160 million, effective 790301 Supporting documentation
encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 4pp

P Operating license stage documents & correspondence

7903020235 Notification of 790402 meeting w/GE to discuss methodology
for predicting safety relief valve loads for Mark I
containments using T-quencher
SU, T M Containment Systems Branch 79/03/26 2pp

7903230866 Forwards application for license mod re spent fuel pool N
encl
GODDARD, R J Branch 2 79/03/26 1pp

7903080370 Requests supplemental info re 790311 application for spent
fuel pool mods be sent to ABLD & intervenor BN Bakula
ZIEHANN, D L Operating Reactors Branch 2 79/04/12 3pp

7903030067 Forwards notes on 790302, 13 & 33 conference telcons
between NRC, consultants & util re bulletin "Potential
Explosive Gas Mixtures Accumulations Associated w/BWR Offgas
Sys Operations"
IPPOLITO, T A Operating Reactors Branch 3 79/04/16 4pp

7903080339 Forwards topics deleted from systematic evaluation program
review of facilities Requests review & identification of
errors within 30 days from receipt of ltr
ZIEHANN, D L Operating Reactors Branch 2 79/04/16 1pp

7903080141 Responds to 790305 ltr criticizing application for approval
of proposed license amend that would allow shipment of spent
fuel between stations Provides info on upcoming hearing
IPPOLITO, T A Operating Reactors Branch 3 79/04/18 1p

--7903080151 Opposes application for approval of proposed license amend
that would allow shipment of spent fuel between stations
HOHENBOKEN, P. Affiliation Unknown. 79/03/15 2pp

7903040482 Notifies of intention to develop safety analysis using
existing computer codes Requests addl info
SOLBRIG, C W Commonwealth Edison Co 79/04/26 1p

7903090370 Reviews systematic evaluation program for shared engineering
safety features, onsite emergency power & avc sys for
multiple unit stations
JANECEK, R F Commonwealth Edison Co 79/05/02 2pp

7903190016 Forwards current schedule for implementation of Mark I
containment long-term mods Discusses constraints inhibiting
shorter time frame completion, including sys load
requirements & current fuel cycles
REED, G Commonwealth Edison Co 79/05/11 3pp

7903190097 Requests correction of error discovered in 780423 ltr re
capacity of Nuclear Assurance Corp NAC-1 truck cask used in
spent fuel transfer. Cask has capacity of two BWR assemblies
JANECEK, R F Commonwealth Edison Co. 79/05/11 1p

DOCKETED ITEMS

27

7905250391 Forwards current licensing open items status list
REED, C Commonwealth Edison Co 79/05/18 11pp

7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1979
Review & reanalysis included all work through Dec 1970
PORTER, F L EDS Nuclear, Inc 79/05/21 9pp

--7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program
OE has no record of reanalysis for Cooper piping sys
STEPHENSON, P W General Electric Co, Nuclear Energy Products Div
79/01/24 18pp

7905310364 Withdraws 781212 request for exemption from 10CFR50 to flood reactor vessel during integrated primary containment leak rate test
JANECEK, R F Commonwealth Edison Co 79/05/24 2pp

Q Inspection reports, IE Bulletins & correspondence

7905020421 Forwards response to IE Bulletin 78-12 & 78-12A, "Atypical Weld Matl in Reactor Pressure Vessel Welds"
REED, C Commonwealth Edison Co 79/03/22 10pp

7905010236 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23 1p

7905030370 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26 1p

7905010155 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/28 1p

7905010384 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/30 1p

7905030013 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/11 1p

7905240448 Forwards IE Insp Repts 50-010/79-07, 50-237/79-09 & 50-249/79-07 on 790306-07, 0312 & 0323 No noncompliance noted.
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/11 2pp

--7905240454 IL Insp Repts 50-010/79-07, 50-237/79-09 & 50-249/79-07 on 790306-07, 0312 & 0323 No noncompliance noted Major areas inspected, internal audits, offsite support agency coordination, emergency facilities, training & drills
GRANT, W. B., EBBIG, T. H Region 3, Chicago, Office of the Director 79/04/05 5pp

7905250280 Responds to IE Bulletin 79-03 re welding defects in certain longitudinally welded pipe spools. Plants inspected, no pipe found
REED, C Commonwealth Edison Co 79/04/12 2pp

7905010369 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040334 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040529 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905030206 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required.
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/17 1p

7905040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl 1"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/21 1p

--7905040158 IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl 1" Supporting documentation encl
Region 3, Chicago, Office of the Director 79/04/21 12pp

--7905040170 ACRS recommendations re 790328 incident at TMI Suggests high priority be placed on development of safety research on behavior of LWRs during anomalous transients
ACRS - Advisory Committee on Reactor Safeguards 79/04/17 2pp

--7905040201 Forwards ACRS recommendations re TMI incident, presented on 790417
FRALBY, R F ACRS - Advisory Committee on Reactor Safeguards 79/04/18 1p

--7905040221 In response to NRC 790418 ltr, states 790417 ACRS recommendations apply to all PWRs, but were not intended to require immediate changes Plant mods should be made after study of effects on overall safety. TMI excluded
CARBON, M X ACRS - Advisory Committee on Reactor Safeguards 79/04/20 2pp

7905240633 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping Reanalysis indicates method of intranodal combination has little effect on pipe stresses & equipment support loads
REED, C Commonwealth Edison Co 79/04/24 4pp

7905250206 Act receipt of 790416 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/79-04, 50-237/79-04 & 50-249/79-04
HIND, J A Region 3, Chicago, Safeguards Branch 79/04/26 1p

--7905250215 Responds to NRC 790328 ltr re violations noted in IE Insp Repts 50-010/79-04, 50-237/79-04 & 50-249/79-04 Corrective actions withheld (ref 10CFR2 790)
REED, C Commonwealth Edison Co 79/04/16 1p

7905150148 Forwards responses to IE Bulletin 79-06A, Revision 1 re BWR events identified during TMI-2 Util has formed task force to review BWR events & recommend corrective action as required
REED, C Commonwealth Edison Co 79/04/27 22pp

7905300242 Responds to IE Bulletin 79-04 No 3/4 or 6-inch Valves swing check valves are in use at Dresden or Quad-Cities Review of Zion has identified use of valves in some piping sys but review is incomplete Will rept later
REED, C Commonwealth Edison Co 79/05/01 2pp

7905140488 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/02 1p

R Periodic operating reports & related correspondence

7905160354 Forwards monthly operating rept for Apr 1979
STEPHENSON, B B Commonwealth Edison Co 79/05/08 1p

--7905160359 Monthly operating rept for Apr 1979
CIESZKIEWICZ, B Commonwealth Edison Co 79/05/03 20pp

S Reportable occurrences, LERs & related correspondence

7905040432 Forwards LER 79-022/03L-0
STEPHENSON, B B Commonwealth Edison Co 79/04/30 1p

--7905040561 LER 79-022/03L-0 on 790331 during refueling, diesel generator failed to start due to governor linkage sticking in closed position Solenoid removed; no fault found Linkage exercised & diesel started
CHAN, J. Commonwealth Edison Co 79/04/30 2pp

7905080533 Forwards LER 79-023/03L-0
STEPHENSON, B B Commonwealth Edison Co 79/04/30 1p

--7905080540 LER 79-023/03L-0 on 790406 during radioactive insp, lack of fusion noted in weld 4-4 on 4-inch reactor head vent line
2-0215-4 Weld cut out & rewelded per ASME boiler & pressure vessel code ASME hydrostatic test completed
COEN, R Commonwealth Edison Co 79/04/26 1p

DOCKETED ITEMS

7903220257 Forwards LER 79-001/03K-1
STEPHENSON, B B Commonwealth Edison Co 79/05/03 1p

--7905220264 LER 79-001/03K-1 on 790103 during steady state operation, torus level exceeded specs Caused by operator oversight
Excess torus water pumped to hotwell & operator admonished
Surveillance being revised
WRIGHT, M Commonwealth Edison Co 79/05/03 1p

7905160384 Forwards LER 79-020/03L-0
STEPHENSON, B B Commonwealth Edison Co 79/05/04 1p

7905160385 LER 79-020/03L-0 on 790413 measured leakage for personnel air lock was 54.63 std cubic ft/h Leakage identified through outer lower handwell shaft packing was replaced & air lock retested
PARCELL, M Commonwealth Edison Co 79/05/04 1p

7905170226 Forwards LER 79-021/03L-0
STEPHENSON, B B Commonwealth Edison Co 79/05/10 1p

--7905170229 LER 79-021/03L-0 on 790415 2A LPCI pump was manually stopped but would not restart properly Caused by trip on overcurrent relay Motor bridged & meggered satisfactorily Pump returned to svc
COEN, R Commonwealth Edison Co 79/05/14 1p

7905300367 Forwards LER 79-024/03L-0
STEPHENSON, B B Commonwealth Edison Co 79/05/22 1p

--7905300373 LER 79-024/03L-0 on 790424 while in shutdown for refueling, U2 diesel generator failed to start Caused by air lines to upper air motor being reversed Airstart motor was replaced & air lines properly routed
CHAN, J Commonwealth Edison Co 79/05/24 1p

7905300443 Forwards LER 79-026/03L-0
STEPHENSON, B B Commonwealth Edison Co 79/05/24 1p

--7905300447 LER 79-026/03L-0 on 790428 breaker trip logic testing disclosed motor generator set 2B output breaker would not trip Cause determined to be small piece of bakelite jamming tripping mechanism Breaker cleaned
DUNBAR, J Commonwealth Edison Co 79/05/24 1p

7905300485 Forwards LER 79-025/03L-0
STEPHENSON, B B Commonwealth Edison Co 79/05/24 1p

--7905300499 LER 79-025/03L-0 on 790425 during monthly surveillance, switches 500-7, PB 504C & PS 504D tripped at 410 psi Caused by instrument drift during prolonged shutdown period
Switches reset
DUNBAR, J Commonwealth Edison Co 79/05/24 1p

7905300475 Forwards LER 79-033/03L-0
STEPHENSON, B B Commonwealth Edison Co 79/05/25 1p

--7905300480 LER 79-033/03L-0 on 790428 during primary containment isolation valve surveillance, 2C TIP machine failed to retract Caused by ball valve limit switch which did not deenergize machine control circuitry
PARCELL, M Commonwealth Edison Co 79/05/25 2pp

DOCKET 50-240 HIGH TEMP GAS COOLED CRITICAL EXPERIMENT

DOCKET 50-243 OREGON STATE UNIV RESEARCH REACTOR

P Operating license stage documents & correspondence

7905070584 Forwards proposed changes to Tech Specs for TRIQA reactor & justification for mods Desires to upgrade console electronics & change reactivity pulsing limit during summer Changes would require about two weeks
WANG, C H, SMITH, C V Oregon State Univ 79/04/16 14pp

DOCKET 50-244 ROBERT EMMET OINNA NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

7905070486 Responds to request for addl info re 790214 fire protection
SER Discusses piping & duct penetrations, const joint, detector testing & electrical cable insulation
WHITE, L D Rochester Gas & Electric Corp 79/04/30 3pp

7905310395 Advises of steps undertaken re Items 3.2.9 & 3.1.11 of fire protection SER, concerning adequacy of fire brigade size & battery room ventilation
WHITE, L D Rochester Gas & Electric Corp 79/05/25 1p

I Financial information

7905030357 Forwards "Annual Financial Rept 1978"
THOMAS, E B LeBoeuf, Lamb, Leiby & MacRae 79/05/02 1p

--7905030359 "Annual Financial Rept 1978"
* Rochester Gas & Electric Corp 79/03/15 32pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905160186 Forwards Amend B to Indemnity Agreement B-3B, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl.
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905230417 Forwards Amend B to Indemnity Agreement B-3B
KUSBIER, R Rochester Gas & Electric Corp. 79/05/17 3pp

P Operating license stage documents & correspondence

7905030126 Reviews 781012 ltr re sys mod to add new battery chargers
Requests addl info
ZIEHANN, D L Operating Reactors Branch 2. 79/04/06 3pp

7905090026 Forwards topics deleted from systematic evaluation program review of facilities, Requests review & identification of errors within 30 days from receipt of ltr.
ZIEHANN, D L Operating Reactors Branch 2 79/04/16 7pp

7905020351 Forwards draft evaluation of systematic evaluation program; Topic III-A-B re turbine missiles, Requests review within 30 days
ZIEHANN, D L. Operating Reactors Branch 2. 79/04/18 8pp

7905090205 Forwards Amend 26 to License DPR-18, safety evaluation & notice of issuance & availability
ZIEHANN, D L Operating Reactors Branch 2. 79/04/18 2pp.

--7905090207 Amend 26 to License DPR-18, revising Tech Specs to require reactor coolant sys overpressure protection mod.
ZIEHANN, D L Operating Reactors Branch 2. 79/04/18 14pp.

--7905090208 Safety evaluation supporting Amend 26 to License DPR-18
* Office of Nuclear Reactor Regulation. 79/04/18 13pp

DOCKETED ITEMS

29

--7905090263 Notice of issuance & availability of Amend 26 to License DPR-18
ZIEHANN, P L Operating Reactors Branch 2 79/04/18 2pp

7905070580 Responds to 790125 ltr re analysis of boron dilution mechanisms Summarizes results of residual heat removal sys No single failure could result in boron dilution
WHITE, L D Rochester Gas & Electric Corp 79/04/30 5pp

7905100149 Provides addl seismic info requested by NRC seismic review team Forwards info on plant structural design except for details of containment & internal structures Dynamic model of auxiliary bldg & SS oversized drawings encl
WHITE, L D Rochester Gas & Electric Corp 79/03/07 11pp

7905150393 Submits revised Attachment A, B & C to 780728 submittal amending Tech Specs for charcoal filter testing & iodine removal equipment operability
WILKENS, P C Rochester Gas & Electric Corp 79/03/08 24pp

7905220377 Comments on NRC 790416 ltr deleting topics for further review from systematic evaluation program Lists other topics to be deleted which are not applicable or have been resolved
WHITE, L D Rochester Gas & Electric Corp 79/05/16 3pp

7905220031 Responds to request for addl info re pressure shielding steel diaphragm Submits info summarizing calculated pressure transients which result from breaks in 20-inch feedwater line or 12-inch steam line.
WHITE, L D Rochester Gas & Electric Corp 79/05/17 32pp

7905300474 Forwards supplemental info to 790507 ltr re systematic evaluation program seismic review Oversized drawings available in Central Files
WHITE, L D Rochester Gas & Electric Corp 79/05/22 60pp

G Inspection reports, IE Bulletins & correspondence

7905010148 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/23 1p

7905240294 Forwards IE Insp Rept 50-244/79-05 on 790305-0308 No noncompliance noted
SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/03/23 2pp

--7905240306 IE Insp Rept 50-244/79-05 on 790305-08 No noncompliance noted Major areas inspected radiation protection program during routine refueling operations, procedures, planning & preparation, training exposure control & posting
YUHAS, G P, CROCKER, H W Region 1, Philadelphia, Office of the Director 79/03/22 7pp

7905010073 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air"
ORIER, B. H. Region 1, Philadelphia, Office of the Director 79/03/28 1p

7905010322 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
ORIER, B. H. Region 1, Philadelphia, Office of the Director 79/03/30 1p.

7905250181 Responds to IE Bulletin 79-03, "Longitudinal Weld Defects in ASME SA-312 Type 304 Stainless Steel Pipe Spools Mfg by Youngstown Welding & Engineering Co." Class II stainless steel piping sys designed to ASME-B36.19 & B36.10.
WHITE, L D, Rochester Gas & Electric Corp 79/04/06 1p

7905290169 Forwards IE Insp Rept 50-244/79-04 on 790226-0302 No noncompliance noted.
BRUNNER, E J Region 1, Philadelphia, Office of the Director 79/04/10, 2pp

--7905290173 IE Insp Rept 50-244/79-04 on 790226-0302 No noncompliance noted Major areas inspected facility logs & records, plant status, refueling procedures, maint activities & plant tour.
BECKMAN, D. A, KALMAN, G Region 1, Philadelphia, Office of the Director KEIMIG, R R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/10 18pp

7905020106 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" Licensee action required.
ORIER, B. H. Region 1, Philadelphia, Office of the Director 79/04/11 1p

7905020315 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905040109 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905030108 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/17 1p

7905020335 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/18 1p

7905010497 Comments on IE Bulletin 79-06A re Westinghouse PWR facilities implementation of bistable trip would create situation where safety injection actuation could be susceptible to single bus perturbations
DEBOER, T K New York, State of 79/04/25 2pp

R Periodic operating reports & related correspondence

7905220223 Forwards monthly operating rept for Apr 1979
SNOW, B A Rochester Gas & Electric Corp 79/03/10 1p

--7905220227 Monthly operating rept for Apr 1979
DEPEW, L Rochester Gas & Electric Corp 79/05/08 3pp

B Reportable occurrences, LCRs & related correspondence

7905040101 Forwards LER 79-007/03L-0
WHITE, L D Rochester Gas & Electric Corp 79/04/30 1p

--7905040147 LER 79-007/03L-0 on 790402 surveillance requirement for nuclear intermediate range channel test within seven days was not performed for two training criticalities Caused by unclear training procedures
PECK, C Rochester Gas & Electric Corp 79/04/30 1p

7905040180 Forwards LERs 79-009/01T-0 & 79-010/01T-0
WHITE, L D Rochester Gas & Electric Corp 79/04/30 1p

--7905040187 LER 79-009/01T-0 on 790416 routine sample of boron boric acid tank showed 11.8% Reactor power reduction started. Caused by possible backflow of makeup water Check valve replaced
PECK, C H Rochester Gas & Electric Corp 79/04/30 2pp

--7905040191 LER 79-010/01T-0 on 790420 routine sample of boric acid storage tanks showed less than 12% Reactor power reduction started Caused by possible backflow of makeup water Check valve replaced
PECK, C H Rochester Gas & Electric Corp 79/04/30 2pp

7905110101 Forwards LER 79-008/03L-0.
WHITE, L D Rochester Gas & Electric Corp 79/05/07 1p

--7905110104 LER 79-008/03L-0 on 790406 boric acid flow control valve leak noted on valve outlet one inch nipple Caused by internal weld flow through defects & deep external pitting. Nipple replaced w/40 nipple
SPECTOR, S Rochester Gas & Electric Corp 79/05/07 1p

7905310431 Forwards LER 79-011/01T-0
WHITE, L D Rochester Gas & Electric Corp 79/05/25 1p.

--7905310435 LER 79-011/01T-0 on 790511 notified by manufacturer of pressurizer power operated relief valve that template used to fabricate valve internals not within specs Caused by error in tracer lathe template.
SPECTOR, S. Rochester Gas & Electric Corp. 79/05/25 2pp

DOCKETED ITEMS

DOCKET 50-245 HILLSTONE NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

7905290073 Forwards response to NRC verbal questions re fire protection Engineering & design of most mode in progress
COUNCIL W O Northeast Utilities 79/05/18 16pp

H General correspondence

7905090160 Responds to 790124 ltr expressing concern for faulty const problem associated w/compacted spent fuel racks Venting of boron plates to spent fuel pool water will not alter previous conclusion that use of racks is not dangerous
ZIEHANN, D L Operating Reactors Branch 2 79/04/03 3pp

J Insurance & indemnity information

7905140422 Forwards Amend 14 to Indemnity Agreement B-39 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/03/01 6pp

7905190075 Forwards executed Amend 14 to Indemnity Agreement B-39
O'CONNOR, L A Northeast Utilities 79/03/15 4pp

P Operating license stage documents & correspondence

7905080381 Forwards FR notice of proposed issuance of amend to provisional OL
ZIEHANN, D L Operating Reactors Branch 2 79/04/06 2pp

--7905080382 Notice of proposed issuance of amend to provisional License DPR-21 to revise Tech Specs re use of 148 BxER fuel assemblies for Reload 6
ZIEHANN, D L Operating Reactors Branch 2 79/04/06 5pp

7905080343 Forwards topics deleted from systematic evaluation program review of facilities Requests review & identification of errors within 30 days from receipt of ltr
ZIEHANN, D L Operating Reactors Branch 2 79/04/16 7pp

7905300729 Ack receipt of 790126 plans for insp of feedwater & control rod drive return line nozzles in reactor pressure vessel
Forwards safety evaluation
ZIEHANN, D L Operating Reactors Branch 2 79/04/21 2pp

--7905300731 Safety evaluation of proposed nozzle insp program
* Operating Reactors Branch 2 79/04/21 4pp

7905010485 In 780307 ltr to NRC & 780201 ltr to DC Sultz, util states it would be preferable to trip control valves in feedwater trains, as opposed to tripping feedwater pumps Impossible to complete installation in Spring 1979
COUNCIL W O Northeast Nuclear Energy Co (Northeast Utilities) 79/04/23 1p

7905010496 Forwards data & analysis of suppression pool temp transients
COUNCIL W O Northeast Nuclear Energy Co (Northeast Utilities) 79/04/24 10pp

7905290007 Forwards Amends 60 & 51 to Licenses DPR-21 & DPR-65, respectively, EIA & notice of issuance & negative declaration.
ZIEHANN, D L Operating Reactors Branch 2 79/04/24 3pp

--7905290012 Amends 60 & 51 to Licenses DPR-21 & DPR-65, respectively, revising ETB to provide more flexibility in sampling schedules & collection for aquatic monitoring & reflecting improved & modified program objectives
ZIEHANN, D L Operating Reactors Branch 2 79/04/24 13pp

--7905290016 EIA supporting Amends 60 & 51 to Licenses DPR-21 & DPR-65, respectively
* Office of Nuclear Reactor Regulation 79/04/24 11pp.

--7905290019 Notice of issuance of Amends 60 & 51 to Licenses DPR-21 & DPR-65, respectively, & negative declaration.
ZIEHANN, D L Operating Reactors Branch 2 79/04/24 2pp

7905070621 Forwards justification of unlimited purging of primary containment in order to provide flexibility to operators in control of containment oxygen level & drywell pressure
COUNCIL W O Northeast Utilities 79/04/27 3pp.

7905080562 Informs that NRC draft evaluation of systematic evaluation program needs addl clarification & should be revised accordingly
COUNCIL W O Northeast Utilities 79/04/27 2pp.

7905080454 Forwards NEDE-20592-4P, Revision 1, "Segmented Test Pig Bundle, Hillstone 1, Suppl 4" dtd Apr 1979 Rept withheld (ref 10CFR2 790)
COUNCIL W O Northeast Utilities 79/05/02 2pp

7905300645 Informs of forthcoming detailed reply to 790507 ltr re: nuclear power plants Plants will not start up until all post-TMI items & requirements are implemented & confirmed
HENDRIE, J H Commission 79/05/11 1p

--7905300647 Requests assurance that action required by IE info re: bulletins have been implemented before CT plants return to operation Also requests info on other anticipated NRC actions or anticipated problems
ORASO, E Connecticut, State of 79/05/07 2pp

7905300005 Responds to V Stello 790309 ltr Forwards bar-chart showing time periods for implementation of long-term program mode Essential completion of program planned for end of 1980
COUNCIL W O Northeast Utilities 79/05/18 3pp

Q Inspection reports, IE Bulletins & correspondence

7905240692 Forwards IE Insp Repts 50-245/78-42 & 50-336/78-39 re 781208-790105 No noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/21 2pp

--7905240704 IE Insp Repts 50-245/78-42 & 50-336/78-39 on 781208-790105 No noncompliance noted Major areas inspected Unit 1 reactor, turbine & radwaste bldgs, Unit 2 auxiliary & turbine bldgs, condensate polishing facility & radiation protection
SHEDLOSKEY, J T Region 1, Philadelphia, Office of the Director
MCCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/20 13pp

7905010121 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/23 1p.

7905010053 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/28 1p

7905010304 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/30, 2pp

7905290140 Forwards IE Insp Rept 50-245/79-05 on 790227-0302 No noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/03 2pp

--7905290149 IE Insp Rept 50-245/79-05 on 790227-0302 No noncompliance noted Major areas inspected, facility procedures, revisions per Tech Spec amend & action on previous insp findings
CONTE, R J, COHILL, C J, Region 1, Philadelphia, Office of the Director
KISTER, H B Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/31 11pp

7905020066 Forwards IE Bulletin 79-06, "Review of Operational Errors: Sys Misalignments Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/11, 1p

7905030013 Forwards IE Bulletin 79-06A, "Review of Operational Errors: Sys Misalignments Identified During TMI Incident"
KEPLER, J Q Region 3, Chicago, Office of the Director 79/04/11, 1p

7905020300 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905040059 Forwards IE Bulletin 79-06B, "Review of Operational Errors: Sys Misalignments Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14, 1p

7905040224 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
Licensee action required,
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14, 1p.

DOCKETED ITEMS

31

7905030077 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required
ORIER,B H Region 1, Philadelphia, Office of the Director
79/04/17 1p

7905020284 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
ORIER,B H Region 1, Philadelphia, Office of the Director
79/04/18 1p

R Periodic operating reports & related correspondence

7905220395 Forwards monthly operating rept for Apr 1979
OPEKA,J F Northeast Utilities 79/05/13 1p

--7905220404 Monthly operating rept for Apr 1979
YOUNG,R Northeast Utilities 79/05/03 6pp

S Reportable occurrences, LERs & related correspondence

7905300533 Forwards LER 79-012/03L-0
OPEKA,J F Northeast Utilities 79/05/21 1p

--7905300544 LER 79-012/03L-0 on 790423 while performing routine reactor bldg exhaust duct & refuel floor high radiation monitor functional surveillance, Channel 1 was out of calibr Caused by instrument drift
* Northeast Utilities 79/05/21 2pp

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,23,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215, & others.
QUATTROCHILI,J American Nuclear Insurers 79/05/01 1p

/7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96
ROBERTS,D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905140407 Forwards Amend 21 to Indemnity Agreement D-19 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
BALTZMAN,J Antitrust & Indemnity Group 79/05/01 6pp

P Operating license stage documents & correspondence

7905240229 Forwards proposed design criteria to be used in reracking spent fuel pool Requests comments by 790416 NRC comments relayed via telcon on 790410 Licensee should propose change to Tech Specs to provide U-235 loading limit.
OLSHAN,L Operating Reactors Branch 1 79/04/19 1p

7905070549 Ack receipt of NRC 790412 ltr Willing to cooperate in planned analysis scheduled for Week of 790506
CAHILL,W J Consolidated Edison Co of New York 79/04/30 1p

7905090287 Advises of suspension of NY Dept of EPA permit to construct cooling tower as air containment source, pending EPA review
Pertinent ltrs encl
CAHILL,W J Consolidated Edison Co of New York 79/05/04 4pp.

7905170244 Forwards "Evaluation of Effectiveness of Continuously Operating Fine Mesh Traveling Screen for Reducing Ichthyoplankton Entrainment " Affidavit & Certificate of Bvc encl.
CAHILL,W J Consolidated Edison Co. of New York 79/05/14 5pp

--7905170249 "Evaluation of Effectiveness of Continuously Operating Fine Mesh Traveling Screen for Reducing Ichthyoplankton Entrainment "
* Consolidated Edison Co of New York 79/04/30, 30pp

7905300354 Forwards application for amend to License DPR-26 Class III amend fee & Certificate of Bvc encl
CAHILL,W J Consolidated Edison Co of New York 79/05/29, 2pp

--7905300358 Application for amend of License DPR-26 to permit engineered safeguards actuation signal on low pressure regardless of pressurizer level Tech Spec page revisions & util safety evaluation encl
CAHILL,W J Consolidated Edison Co of New York 79/05/29 11pp

G Inspection reports, IE Bulletins & correspondence

7905070189 Forwards IE Insp Rept 50-247/79-03 on 790213-16 No noncompliance noted
BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/16 2pp

--7905070210 IE Insp Rept 50-247/79-03 on 790213-16 No noncompliance noted Major areas inspected document control, records & recent changes in QA program
KISTER,H B Region 1, Philadelphia, Reactor Operations Nuclear Support Branch
NAPUDA,G J, KEMOE,D Region 1, Philadelphia, Office of the Director 79/03/14 17pp

7905110362 Forwards IE Insp Rept 50-247/79-01 on 790107-0203 No noncompliance noted
BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/20 2pp

--7905110371 IE Insp Rept 50-247/79-01 on 790107-0203 No noncompliance noted Major areas inspected physical protection in area of access control, barriers, search, escort, communications & compensatory measures
REBELOWSKI,T Region 1, Philadelphia, Office of the Director
KEIMIO,R R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/19 10pp

7905030272 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks "
ORIER,B H Region 1, Philadelphia, Office of the Director
79/03/26 1p

7905250248 Responds to IE Bulletin 79-03 re longitudinal weld defects in certain pipe spools mfg by Youngstown Welding & Engineering Co Piping not used in Unit 2 Info on Unit 1 will be provided when returned to svc
CAHILL,W J Consolidated Edison Co of New York 79/04/13 2pp

7905020350 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required
ORIER,B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905030373 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
ORIER,B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040183 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
ORIER,B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905010079 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required
ORIER,B H Region 1, Philadelphia, Office of the Director
79/04/17 1p

--7905010083 IE Bulletin 79-09, "Fail Breaker in Safety-Related Sys " I 1751CPR-1-1

7905010497 Comments on IE Bulletin 79-06A re Westinghouse facilities implementation of bistable trip would create situation where safety injection actuation could be susceptible to single bus perturbations
DEBDER,T K New York, State of 79/04/25 2pp

7905290177 Ack receipt of 790321 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-003/78-13 & 50-247/78-38
SMITH,G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/04, 2pp

DOCKETED ITEMS

--7903290185 Responds to NRC 790228 ltr re violation noted in IE Insp Repts 50-003/78-13 & 50-247/78-38 Corrective actions developing techniques to avoid variables leading to badge anomalies
CAHILL, W J Consolidated Edison Co of New York 79/03/21 3pp

--7903290188 Forwards IE Insp Repts 50-003/78-13 & 50-247/78-38 on 781227-29 & 790117-18 & notice of violation
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/02/28 2pp

--7903290193 Notice of violation from insp on 781227-29 & 790117-18
Region 1, Philadelphia, Office of the Director 79/02/28 1p

--7903290196 IE Insp Rept 50-003/78-13 & 50-247/79-38 on 781227-29 & 790117-18 Noncompliance noted failure to maintain personnel exposure limits in accordance w/10CFR20.101
NEELY, D R, SERABIAN, J A Region 1, Philadelphia, Office of the Director
CROCKER, H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/02/27 12pp

7905310396 Forwards supplemental response to IE Bulletin 79-07 re seismic analysis as requested in 790517 meeting
CAHILL, W J Consolidated Edison Co of New York 79/05/22 5pp

R Periodic operating reports & related correspondence

7905220376 Forwards effluent monitoring & impingement data specified in Section 401 Certification for Apr 1979
MONTE, W A Consolidated Edison Co of New York 79/05/10 17pp

7905230392 Forwards daily record of fish collections for Apr 1979
Wdally species breakdown & total weight for Units 2 & 3
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/14 5pp

7905230365 Forwards monthly operating rept for Apr 1979
CAHILL, W J Consolidated Edison Co of New York 79/05/15 1p

--7905230367 Monthly operating rept for Apr 1979
KAHULA, L Consolidated Edison Co of New York 79/05/04 7pp

S Reportable occurrences, LERs & related correspondence

7905040004 Forwards LERs 79-013/03L-0 & 79-014/03L-0
CAHILL, W J Consolidated Edison Co of New York 79/04/27 1p

--7905040006 LER 79-013/03L-0 on 790329 pinhole leak at socket weld connection on seal injection header (line 402) downstream of seal injection filters Split collar placed around leak
Permanent repairs will be made during future outage
MAKEPEACE, J M Consolidated Edison Co of New York 79/04/27 1p

--7905040279 LER 79-014/03L-0 on 790331 electric heat trace 51B found to have inoperable primary circuit Caused by defective Chromalox strip heater elements PT-512 Elements replaced & circuit returned to svc
MAKEPEACE, J M Consolidated Edison Co of New York 79/04/27 1p

7905190013 Forwards LER 79-012/04X-1
CAHILL, W J Consolidated Edison Co of New York 79/05/10 1p

--7905190018 LER 79-012/04X-1 on 790213 activity of precipitation sample exceeded 10 times control station level Caused by tritium releases from source external to facility Manufacturer in area has modified installation to prevent recurrence
MASCILLI, S Consolidated Edison Co of New York 79/05/10 3pp

7905190021 Forwards LER 79-015/04E-0
CAHILL, W J Consolidated Edison Co of New York 79/05/10 1p

--7905190023 LER 79-015/04E-0 on 790405 activity of precipitation sample exceeded 10 times control station level Caused by tritium releases from source external to facility Manufacturer in area has modified installation to prevent recurrence
MASCILLI, S Consolidated Edison Co of New York 79/05/10 2pp

DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

Security, medical, emergency & fire protection plans

7905030366 Forwards modified physical security plan; Revision 3 Plan withheld (ref 10CFR2.790)
LEE, B Commonwealth Edison Co 79/04/26 1p.

7905040603 Forwards pages of "Implementation of Nuclear Mutual Liability Loss Prevention Program," in response to NRC 780629 request re fire protection administrative controls
JANECEK, R F Commonwealth Edison Co 79/04/30 6pp

O Adjudicatory correspondence

7905250298 Notifies properly worded contention re sabotage would be accepted Contention 6 as admitted into Duke Power Co proceeding, encompasses aspects of revised Contention 11 presented by State of IL
GODDARD, R J Branch 2 79/04/06 2pp

J Insurance & indemnity information

7905100163 Endorsement 99 to MAELU Policy MF-22
GERAS, T Nuclear Energy Liability Insurance Association 79/04/22 1p

7905070497 Confirms increased liability limit to \$124,000,000 for policies MF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 81, 82, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905140404 Forwards Amend 21 to Indemnity Agreement II-10 per NRC 79-014 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 4pp

P Operating license stage documents & correspondence

7905230866 Forwards application for license mod re spent fuel pool & encl
GODDARD, R J Branch 2 79/03/26 1pp

7905080570 Requests supplemental info re 780511 application for spent fuel pool mods be sent to ABLB & intervenor BN Bakuler
ZIEMANN, D L Operating Reactors Branch 2 79/04/12 1pp

7905030067 Forwards notes on 790302, 15 & 33 conference telcons between NRC, consultants & util re bulletin "Potential Explosive Gas Mixtures Accumulations Associated w/BWR Offgas Sys Operations"
IPPOLITO, T A Operating Reactors Branch 3 79/04/16 4pp

7905080141 Responds to 790305 ltr criticizing application for approval of proposed license amend that would allow shipment of spent fuel between stations Provides info on upcoming hearing
IPPOLITO, T A Operating Reactors Branch 3 79/04/10 1p

--7905080151 Opposes application for approval of proposed license amend that would allow shipment of spent fuel between stations
HOENBOKEN, P Affiliation Unknown, 79/03/15, 2pp

7905040482 Notifies of intention to develop safety analysis using existing computer codes Requests addl info
SOLBRIO, C W Commonwealth Edison Co 79/04/26 1p

7905140276 Submits info re slipped refueling outage schedule R&S will now begin in Mar 1979. All commitments & schedules for work should ref new outage date.
JANECEK, R F Commonwealth Edison Co. 79/05/04 1p

7905190016 Forwards current schedule for implementation of Mark II containment long-term mods Discusses constraints inhibiting shorter time frame completion, including sys load requirements & current fuel cycles
REED, C Commonwealth Edison Co 79/05/11 3pp

7905190097 Requests correction of error discovered in 780423 ltr re capacity of Nuclear Assurance Corp NAC-1 truck cask used in spent fuel transfer Cask has capacity of two BWR assemblies
JANECEK, R F Commonwealth Edison Co 79/05/11 1p

7905250391 Forwards current licensing open items status list
REED, C Commonwealth Edison Co 79/05/18 11pp.

DOCKETED ITEMS

33

7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970 PORTER, F L EDS Nuclear, Inc 79/03/21 9pp

--7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program GE has no record of reanalysis for Cooper piping sys STEPHENS, P W General Electric Co, Nuclear Energy Products Div 79/01/24 18pp

7905310364 Withdraws 781212 request for exemption from 10CFR50 to flood reactor vessel during integrated primary containment leak rate test JANECEK, R F Commonwealth Edison Co 79/05/24 2pp

Q Inspection reports, IE Bulletins & correspondence

7905020421 Forwards response to IE Bulletins 78-12 & 78-12A, "Atypical Weld Matl in Reactor Pressure Vessel Welds " REED, C Commonwealth Edison Co 79/03/22 10pp

7905010236 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping " KEPPLER, J Q Region 3, Chicago, Office of the Director 79/03/23 1p

7905030370 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks " KEPPLER, J Q Region 3, Chicago, Office of the Director 79/03/26 1p

7905010195 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air " KEPPLER, J Q, Region 3, Chicago, Office of the Director 79/03/28 1p

7905010384 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin " KEPPLER, J Q Region 3, Chicago, Office of the Director 79/03/30 1p

7905030013 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/11 1p

7905240448 Forwards IE Insp Repts 50-010/79-07, 50-237/79-09 & 50-249/79-07 on 790306-07, 0312 & 0323 No noncompliance noted DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/11 2pp

--7905240454 IE Insp Repts 50-010/79-07, 50-237/79-09 & 50-249/79-07 on 790306-07, 0312 & 0323 No noncompliance noted Major areas inspected internal audits, offsite support agency coordination, emergency facilities, training & drills ORANT, W B, EBBIO, T, H Region 3, Chicago, Office of the Director 79/04/05 5pp

7905250280 Responds to IE Bulletin 79-03 re welding defects in certain longitudinally welded pipe spools Plants inspected, no pipe found REED, C Commonwealth Edison Co 79/04/12 2pp

7905010569 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " KEPPLER, J Q, Region 3, Chicago, Office of the Director 79/04/14 1p

7905040334 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/14 1p

7905040529 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident " KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/14 1p

7905030206 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/17 1p

7905040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl. " KEPPLER, J, Q, Region 3, Chicago, Office of the Director 79/04/21 1p

--7905040158 IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl " Supporting documentation encl * Region 3, Chicago, Office of the Director 79/04/21 12pp

--7905040170 ACRS recommendations re 790328 incident at TMI suggests high priority be placed on development of safety research on behavior of LWRs during anomalous transients * ACRS - Advisory Committee on Reactor Safeguards 79/04/17 2pp

--7905040201 Forwards ACRS recommendations re TMI incident, presented on 790417 FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards 79/04/18 1p

--7905040221 In response to NRC 790418 ltr, states 790417 ACRS recommendations apply to all PWRs, but were not intended to require immediate changes Plant mods should be made after study of effects on overall safety, TMI excluded CARBON, M X ACRS - Advisory Committee on Reactor Safeguards 79/04/20 2pp

7905240633 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping Reanalysis indicates method of intramodal combination has little effect on pipe stresses & equipment support loads REED, C Commonwealth Edison Co 79/04/24 4pp

7905250206 Ack receipt of 790416 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/79-04, 50-237/79-04 & 50-249/79-04 HIND, J A Region 3, Chicago, Safeguards Branch 79/04/26 1p

--7905250215 Responds to NRC 790328 ltr re violations noted in IE Insp Repts 50-010/79-04, 50-237/79-04 & 50-249/79-04 Corrective actions withheld (ref 10CFR2.790) REED, C Commonwealth Edison Co 79/04/16 1p

7905150148 Forwards responses to IE Bulletin 79-06A, Revision 1, re BWR events identified during TMI-2 Util has formed task force to review BWR events & recommend corrective action, as required REED, C Commonwealth Edison Co 79/04/27 22pp

7905300242 Responds to IE Bulletin 79-04 No 3, 4 or 6-inch Velan swing check valves are in use at Dresden or Quad-Cities Review of Zion has identified use of valves in some piping sys but review is incomplete Will rept later REED, C Commonwealth Edison Co 79/05/01 2pp

7905140488 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase " KEPPLER, J Q Region 3, Chicago, Office of the Director 79/05/02 1p

R Periodic operating reports & related correspondence

7905160354 Forwards monthly operating rept for Apr 1979 STEPHENSON, B B Commonwealth Edison Co 79/05/08 1p

--7905160359 Monthly operating rept for Apr 1979 GIESZKIEWICZ, B Commonwealth Edison Co. 79/05/03 20pp

S. Reportable occurrences, LERs & related correspondence

7905080548 Forwards LER 79-005/03L-0 STEPHENSON, B B Commonwealth Edison Co 79/05/02 1p.

--7905080556 LER 79-005/03L-0 on 790418, during routine surveillance, h1 isolation condensate flow switch differential pressure 1349 tripped Caused by instrument drift LINDBERG, C Commonwealth Edison Co 79/05/02 1p

7905140318 Forwards LER 79-006/01T-0, STEPHENSON, B B Commonwealth Edison Co 79/05/04, 1p

--7905140324 LER 79-006/01T-0 on 790424 250 volt battery was not operable. Caused by operator error Battery was recharged after refueling outage discharge test. HOLLAND, P Commonwealth Edison Co 79/05/04 2pp

7905300579 Forwards LER 79-009/01T-0 STEPHENSON, B B, Commonwealth Edison Co 79/05/24 kepler, J

DOCKETED ITEMS

7905290553 LER 79-009/017-0 on 790511 review of records indicate valve 1452-9A & 1452-9B inside containment have limit switches not qualified for use in LOCA environ Switches not qualified because indication equipment is nonsafety-related
BAUSER J Commonwealth Edison Co 79/05/24 2pp

7905290597 Forwards LER 79-009/03L-0
STEFANSON B B Commonwealth Edison Co 79/05/24 1p

79052905705 LER 79-009/03L-0 on 790503 pinhole leak found on cleanup equalizing line caused by erosion due to flow characteristics & possible cavitation Leak was repaired
LANCEN T Commonwealth Edison Co 79/05/24 1p

DOCKET 20-250 TURKEY POINT PLANT, UNIT 3

F Security, medical emergency & fire protection plans

7905290143 Forwards schedule for plant modifications re fire protection & addl info re safety evaluation per 790321 request
WRIGHT R E Florida Power & Light Co 79/05/21 15pp

G Adjudicatory correspondence

7905300035 Licensee response to MP Oncavage 790209 request for hearing. Argues that request is untimely & fails to demonstrate standing. Supporting documentation, Affidavits & Certificate of Svc encl
BAUSER M A Lowenstein, Neuman, Reis, Aselrad & Toll COLL, N A Affiliation Unknown 79/05/09 22pp

7905300040 Conveys desire to undertake maint program to repair facilities. Describes type of repairs that should be undertaken
WRIGHT R E Florida Power & Light Co 79/05/20 2pp

7905300175 Forwards revision to 790209 petition to intervene
ONCAVAGE, M P Affiliation Unknown 79/03/19 1p

7905300182 Revision to 790209 petition to intervene re proposed OL amend to permit steam generator repairs. Affidavit, motion for production of documents & Certificate of Svc encl
ONCAVAGE, M P Affiliation Unknown 79/03/18 19pp

7905300753 Ack receipt of 790319 ltr to Board, encl revised petition to intervene. R Daily affidavit, motion for production of documents & entry upon land for insp & other purposes. Requests signed & notarized affidavit from R Daily
COLL, N A Steel, Hector & Davis 79/03/23 2pp

7905300793 Answer by util in opposition to 790319 motion by MP Oncavage for production of documents. Certificate of Svc encl
BAUSER, M A Lowenstein, Neuman, Reis, Aselrad & Toll COLL, N A Steel, Hector & Davis 79/03/30 3pp

7905300799 Response by util seeking denial on basis of untimeliness of MP Oncavage's petition to intervene. Petitioner does not demonstrate standing nor offer admissible contentions
BAUSER, M A Lowenstein, Neuman, Reis, Aselrad & Toll COLL, N A Steel, Hector & Davis 79/03/30 14pp

7905240479 Prehearing conference to rule on petition of MP Oncavage will be held on 790502 in Miami, FL
BOWERS E S Atomic Safety and Licensing Board Panel 79/04/05 2pp

7905290026 Replies to licensee 790330 response & NRC 790404 request. Petitioner's lack of special training or expertise. Petitioner does not assert expertise, but rather interests as be protected Certificate of Svc encl
ONCAVAGE, M P Affiliation Unknown 79/04/24 4pp

7905290489 Forwards FL Power & Light Co & NRC opportunity to submit responses to newly submitted contentions of petitioner
MP Oncavage, BOWERS E S Atomic Safety and Licensing Board Panel 79/04/24 2pp

H General correspondence

7905220100 Forwards H Purcell telegram requesting granting of MP Oncavage petition for hearing & intervention. Requests recommendation on appropriate action
LEHMAN, W House of Rep 79/04/12 1p

7905240864 Requests comments on correspondence from (uncl) & 14. MP Oncavage petition to intervene in hearing on proposed repairs
LEHMAN, W House of Rep 79/04/20 3pp

7905240718 Forwards constituent's request that NRC grant MP petition for hearing & intervention re facility repairs
STONE, R Senate 79/04/26 2pp

7905300762 Requests response to various telegrams supporting petition from MP Oncavage to intervene in steam generator repair proceeding. Telegrams encl
STONE, R Senate 79/05/01 12pp

7905290483 Responds to 790412 ltr requesting consideration of motion in support of MP Oncavage petition to intervene. Prehearing conference will be held on 790502 in Miami, FL
GOSSECK, L V Office of the Executive Director for Hearings 79/05/02 1p

7905290486 Forwards constituent's telex requesting support of MP Oncavage petition for hearing & intervention re steam generators repair
LEHMAN, W House of Rep 79/04/12 1p

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies MF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 171, 173, 174, 178, 179, 180, 182, 183, 186, 187, 188, 189, 192, 193, 194, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHINI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$160 million for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905140449 Forwards Amend 10 to Indemnity Agreement B & C changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 1pp

7905100316 Forwards Endorsement 48 to NELIA Policy MF-1117
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc 79/05/03 2pp

7905100307 Forwards Endorsement 47 to NELIA Policy MF-1115
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc 79/05/04 2pp

7905250411 Forwards executed Amend 10 to Indemnity Agreement B & C increasing coverage to \$160 million
WRIGHT, R E Florida Power & Light Co 79/05/21 3pp

7905300301 Forwards Endorsement 40 to MAELU Policy MF-55
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc 79/05/24 2pp

7905300311 Forwards Endorsement 41 to MAELU Policy MF-55
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc 79/05/24 2pp

DOCKETED ITEMS

35

M Antitrust correspondence

/7905150234 Motion by FL Cities seeking antitrust hearing. Renew's request to argue position re review & consolidation of antitrust issue Certificate of Bvc encl
JABLON, R A Spiegel & McDiarmid 79/03/28 2pp

/7905150727 Forwards motion for consolidated hearings on behalf of FL Cities
JABLON, R A Spiegel & McDiarmid 79/04/02 1p

--7905150733 Motion for consolidated hearings by FL Cities Certificate of Bvc encl
JABLON, R A Spiegel & McDiarmid 79/04/02 4pp

/7905104622 Responds to 790328 & 790402 motions filed by FL Cities to initiate antitrust hearing, in response to NRC 780727 order Certificate of Bvc encl
DEWLY, C; CHANANIA, I D; EVANS, D J Anti-Trust Division 79/04/17 9pp

P Operating license stage documents & correspondence

/7905080043 Forwards Amends 45 & 31 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability
GILWING, R A Operating Reactors Branch 2 79/03/21 3pp

--7905080044 Amends 45 & 31 to Licenses DPR-31 & 41, respectively, adding license conditions re completion of facility mods & implementation of administrative controls for fire protection
GILWING, R A Operating Reactors Branch 2 79/03/21 2pp

--7905080071 Safety evaluation supporting Amends 45 & 31 to Licenses DPR-31 & 41, respectively
" Operating Reactors Branch 2 79/03/21 47pp

- 7905080080 Notice of issuance & availability of Amends 45 & 31 to licenses DPR-31 & DPR-41, respectively
GILWING, R A Operating Reactors Branch 2 79/03/21 2pp

/7905070104 Forwards Amend 46 to License DPR-31, safety evaluation & notice of issuance & availability
GILWING, R A Operating Reactors Branch 1 79/03/30 2pp

/7905070114 Amend 46 to License DPR-31, permitting continued operation of Unit 3 for six equivalent months of operation
GILWING, R A Operating Reactors Branch 1 79/03/30 2pp

--7905070119 Safety evaluation supporting Amend 46 to License DPR-31
" Operating Reactors Branch 1 79/03/30 3pp

/7905070124 Notice of issuance & availability of Amend 46 to License DPR-31
GILWING, R A Operating Reactors Branch 1 79/03/30 2pp

/7905110058 Summary of 790413 meeting w/util & Westinghouse re seismic analysis of reaction coolant piping
THAMMILL, C M Operating Reactors Branch 1 79/04/18 3pp

/7905080412 Forwards request to amend App A of Licenses DPR-31 & DPR-41 re pressurizer level Affidavit & safety evaluation encl
UNRIQ, R E Florida Power & Light Co 79/05/02 7pp

/7905140217 Forwards replacement first page for safety evaluation, forwarded 790502, w/Tech Spec change proposal re safety injection trip logic
UNRIQ, R E Florida Power & Light Co 79/05/04 2pp

/7905140220 Forwards initial response re emergency power sys periodic tests requested in NRC 790309 ltr
UNRIQ, R E Florida Power & Light Co 79/05/07 2pp

--7905140225 Instructions for insp & tests of lockout relays
TAYLOR, R L Florida Power & Light Co 79/05/15 6pp

/7905240547 Forwards request for amend to App A of Licenses DPR-31 & DPR-41 Amend changes Tech Spec limits re ECCB cooling performance, in light of Westinghouse reevaluation
UNRIQ, R E Florida Power & Light Co 79/05/18 34pp

/7905250426 Submits analysis supporting amend to App A of Licenses DPR-31 & DPR-41 DNBR safety limit of 1.24 is consistent w/COBRA IIIC computer code Forwards "DNBR Safety Limit for COBRA IIIC Analysis"
UNRIQ, R E Florida Power & Light Co 79/05/21 8pp

--7905250430 "DNBR Safety Limit for COBRA IIIC Analysis"
IRANI, A; WILSON, W; WYRICK, R Florida Power & Light Co 79/03/31 16pp

7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970
PORTER, F L EDS Nuclear, Inc 79/05/21 9pp

--7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program GE has no record of reanalysis for Cooper piping sys
STEPHENS, P W General Electric Co Nuclear Energy Products Div 79/01/24 18pp

Q Inspection reports, IE Bulletins & correspondence

7905010193 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905030310 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/26 2pp

7905010104 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/28 2pp

7905010358 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/30 2pp

7905020127 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/11 1p

7905040212 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp

7905040308 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905040404 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905030164 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp

DOCKETED ITEMS

H Periodic operating reports & related correspondence

770300015 Forwards analysts of annual aerial photograph of cooling canal sys boundary
WRIGHT, R E Florida Power & Light Co 79/03/11 2pp

S Reportable occurrences, LERs & related correspondence

7903030457 Forwards LER 79-001/03L-3
SCHMIDT, A D Florida Power & Light Co 79/04/20 1p

--7903030471 LER 79-007/03L-0 on 790321 surveillance test of RHR sys not performed. Caused by misinterpretation of scheduling info relayed from QC to operations personnel. Amend proposed to change test interval
SCHOPPMAN, M A Florida Power & Light Co 79/04/20 1p

7903040067 Forwards LER 79-009/03L-0
SCHMIDT, A D Florida Power & Light Co 79/04/27 1p

--7903090712 LER 79-009/03L-0 on 790328 during refueling shutdown, leak observed from temporary level-indication line near base of refueling water storage tank. About 25 gallons of water leaked out. Cause undetermined. Investigation in progress.
SCHOPPMAN, M A Florida Power & Light Co 79/04/27 1p

7903070074 Forwards LER 79-008/03L-0
SCHMIDT, A D Florida Power & Light Co 79/04/27 1p

--7903090081 LER 79-008/03L-0 on 790328 chemical & vol control sys holdup tank overfilled, creating siphon through vent line & header, resulting in low internal tank pressure & tank damage. Caused by erroneous level indication
SCHOPPMAN, M A Florida Power & Light Co 79/04/27 2pp

7903220103 Forwards LER 79-011/03L-0
SCHMIDT, A D Florida Power & Light Co 79/05/09 1p

--7903220113 LER 79-011/03L-0 on 790410 during preparation for routine startup following refueling shutdown, condensate storage tank had to be drained. Caused by chloride contamination. Tank of other unit aligned. Change in Tech Spec wording proposed.
SCHOPPMAN, M A Florida Power & Light Co 79/05/09 1p

7903220122 Forwards LER 79-012/03L-0
SCHMIDT, A D Florida Power & Light Co 79/03/14 1p

--7903220128 LER 79-012/03L-0 on 790414 during startup, steam supply stop valves MDV-3-1404 & MDV-3-1405 leading to turbine drives of auxiliary feedwater pumps failed to open fully. Caused by damaged threads on valve operator stem nut. Nut replaced.
JAMES, D K Florida Power & Light Co 79/05/14 2pp

7903230388 Forwards LER 79-013/03L-0
SCHMIDT, A D Florida Power & Light Co 79/05/16 1p

--7903230392 LER 79-013/03L-0 on 790416 left turbine stop valve failed to fully close when turbine was tripped to balance exciter. Cause unknown. Valve tested & operated satisfactorily. Valve performance will be monitored regularly.
JAMES, D K Florida Power & Light Co 79/05/16 1p

T Hearing transcripts on non-antitrust matters

7903140567 Transcript of 790502 proceeding in Miami, FL. Pp 1-122
BOWERS, E S, HALL, D B, PAULIS, D H Atomic Safety and Licensing Board Panel 79/05/02 123pp

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

F Security, medical, emergency & fire protection plans

7903290143 Forwards schedule for plant mods re fire protection & add info re safety evaluation, per 790321 request
WRIGHT, R E Florida Power & Light Co 79/05/21 19pp

G Adjudicatory correspondence

7903300035 Licensee response to MP Oncavage 790209 request for hearing. Argues that request is untimely & fails to demonstrate standing. Supporting documentation, affidavits & Certificate of Svc encl.
BAUSER, M A Lowenstein, Newman, Reis, Axelrad & Toll COLL, N A Affiliation Unknown 79/03/09 22pp

7903150175 Forwards revision to 790209 petition to intervene
ONCAVAGE, M P Affiliation Unknown 79/03/19 1p

--7903150182 Revision to 790209 petition to intervene re proposed amend to permit steam generator repairs. Affidavit, motion for production of documents & Certificate of Svc encl.
ONCAVAGE, M P Affiliation Unknown 79/03/18 19pp

7903150753 Ack receipt of 790319 ltr to Board, encl revised petition to intervene. R Daily affidavit, motion for production of documents & entry upon land for insp & other purposes. Requests signed & notarized affidavit from R Daily.
COLL, N A Steel, Hector & Davis 79/03/23 2pp

7903150793 Answer by util in opposition to 790319 motion by MP Oncavage for production of documents. Certificate of Svc encl.
BAUSER, M A Lowenstein, Newman, Reis, Axelrad & Toll COLL, N A Steel, Hector & Davis 79/03/30 3pp

--7903150799 Response by util seeking denial on basis of untimeliness of MP Oncavage's petition to intervene. Petitioner does not demonstrate standing nor offer admissible contentions.
BAUSER, M A Lowenstein, Newman, Reis, Axelrad & Toll COLL, N A Steel, Hector & Davis 79/03/30 14pp

7903240479 Prehearing conference to rule on petition of MP Oncavage will be held on 790502 in Miami, FL.
BOWERS, E S Atomic Safety and Licensing Board Panel 79/04/05 2pp

7903250481 Requests granting MP Oncavage petition for hearings & intervention re facility repairs.
DAVIS, L, MENDOZA, M O, SMITH, W R Affiliation Unknown 79/04/11pp

7903300722 Response to MP Oncavage 790319 revised petition to intervene in proceeding. Certificate of Svc encl.
GOLDBERG, S C Branch 2 79/04/06 8pp

7903240973 Requests NA Coll be included on svc list.
COLL, N A Steel, Hector & Davis 79/04/09 1p

7903250060 Forwards various mailgrams requesting granting of petition for hearing & intervention re facility repairs.
FISHBACH, N Affiliation Unknown 79/04/12 9pp

7903250063 Requests granting of MP Oncavage petition for hearing & intervention in util proceedings.
COUSINS, R, BILLIO, J, BASTO, S Affiliation Unknown 79/04/19 12pp

7903290026 Replies to licensee 790330 response & NRC 790406 response. Petitioner's lack of special training or expertise. Petitioner does not assert expertise, but rather interests in being protected. Certificate of Svc encl.
ONCAVAGE, M P Affiliation Unknown 79/04/24 9pp

7903290489 Grants FL Power & Light Co & NRC opportunity to submit responses to newly submitted contentions of petitioner.
MP Oncavage
BOWERS, E S Atomic Safety and Licensing Board Panel 79/05/07 2pp

H General correspondence

7903290486 Forwards constituent's letter requesting support of MP Oncavage petition for hearing & intervention re steam generators repair.
LEHMAN, W House of Rep 79/04/12 1p

7903220100 Forwards M Purcell telegram requesting granting of MP Oncavage petition for hearing & intervention. Requests recommendation on appropriate action.
LEHMAN, W House of Rep 79/04/12 1p

7903240864 Requests comments on correspondence from constituents re MP Oncavage petition to intervene in hearing on proposed repairs.
LEHMAN, W House of Rep 79/04/20 3pp

7903240718 Forwards constituent's request that NRC grant MP Oncavage petition for hearing & intervention re facility repairs.
STONE, R Senate 79/04/26 2pp.

DOCKETED ITEMS

37

7705300762 Requests response to various telegrams supporting petition from MP Onccavage to intervene in steam generator repair proceeding Telegrams encl
STONE, R Senate 77/03/01 12pp

7705270483 Responds to 770412 ltr requesting consideration of telegram in support of MP Onccavage petition to intervene Prehearing conference will be held on 770502 in Miami, FL
GOSBICK, L V Office of the Executive Director for Operations 77/03/02 1p

J Insurance & indemnity information

7705070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 74, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUAYTROCCHI, J American Nuclear Insurers 77/03/01 1p

7705070582 Confirms increase in liability limit to \$36,000,000 for policies NF-2, 26, 29, 38, 39, 44, 46, 47, 49, 90, 91, 92, 93, 94, 95, 96, 97, 98, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 84, 87, 88, 90, 91, 92, 93, 94, 95 & 96
KNEHTIG, D M Mutual Atomic Energy Liability Underwriters 77/03/01 1p

7705140447 Forwards Amend 10 to Indemnity Agreement B-46 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 770501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 77/03/01 6pp

7705100316 Forwards Endorsement 48 to NELIA Policy NF-185
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc Div 77/03/03 2pp

7705100307 Forwards Endorsement 47 to NELIA Policy NF-185
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc Div 77/03/04 2pp

7705150411 Forwards executed Amend 10 to Indemnity Agreement B-46, increasing coverage to \$160 million
UHRIG, R E Florida Power & Light Co 77/03/21 3pp

77051300301 Forwards Endorsement 40 to MAELU Policy NF-55
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc Div 77/03/24 2pp

77051300311 Forwards Endorsement 41 to MAELU Policy NF-55
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc Div 77/03/24 2pp

M Antitrust correspondence

7705150234 Motion by FL Cities seeking antitrust hearing Renews request to argue position re review & consolidation of antitrust issue Certificate of Svc encl
JANLON, R A Spiegel & McDiarmid 77/03/28 2pp

7705150727 Forwards motion for consolidated hearings on behalf of FL Cities
JANLON, R A Spiegel & McDiarmid 77/04/02 1p

7705150733 Motion for consolidated hearings by FL Cities Certificate of Svc encl
JANLON, R A Spiegel & McDiarmid 77/04/02 4pp

7705230422 Responds to 770328 & 770402 motions filed by FL Cities to initiate antitrust hearing in response to NRC 780727 order Certificate of Svc encl
DEWEY, L., CHANANIA, F. D., EVANS, D J Anti-Trust Division 77/04/17 5pp

P Operating license stage documents & correspondence

7705080063 Forwards Amends 45 & 31 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability
SCHWENCER, A Operating Reactors Branch 2 77/03/21 3pp

7705080067 Amends 45 & 31 to Licenses DPR-31 & 41, respectively, adding license conditions re completion of facility mods & implementation of administrative controls for fire protection.
SCHWENCER, A Operating Reactors Branch 2 77/03/21 2pp

7705080073 Safety evaluation supporting Amends 45 & 31 to Licenses DPR-31 & 41, respectively
Operating Reactors Branch 2 77/03/21 47pp.

7705080080 Notice of issuance & availability of Amends 45 & 31 to Licenses DPR-31 & DPR-41, respectively
SCHWENCER, A Operating Reactors Branch 2 77/03/21 2pp

7705110058 Summary of 770413 meeting w/Util & Westinghouse re seismic analysis of reaction coolant piping
TRAMMELL, C M Operating Reactors Branch 1 77/04/18 2pp

7705080412 Forwards request to amend App A of Licenses DPR-31 & DPR-41 re pressurizer level Affidavit & safety evaluation encl
UHRIG, R E Florida Power & Light Co 77/03/02 7pp

7705140217 Forwards replacement first page for safety evaluation forwarded 770302, w/Tech Spec change proposal re safety injection trip logic
UHRIG, R E Florida Power & Light Co 77/03/04 2pp

7705140220 Forwards initial response re emergency power sys periodic tests requested in NRC 770309 ltr
UHRIG, R E Florida Power & Light Co 77/03/07 2pp

7705140225 Instructions for insp & tests of lockout relays
TAYLOR, R L Florida Power & Light Co 77/03/15 5pp

7705240547 Forwards request for amend to App A of Licenses DPR-31 & DPR-41 Amend changes Tech Spec limits re ECCS cooling performance, in light of Westinghouse reevaluation
UHRIG, R E Florida Power & Light Co 77/03/18 34pp

7705250426 Submits analysis supporting amend to App A of Licenses DPR-31 & DPR-41 DNBR safety limit of 1.24 is consistent w/COBRA IIIC computer code Forwards "DNBR Safety Limit for COBRA IIIC Analysis"
UHRIG, R E Florida Power & Light Co 77/03/21 8pp

7705250430 "DNBR Safety Limit for COBRA IIIC Analysis"
IRANI, A., WILSON, W., WYRICK, R Florida Power & Light Co 77/03/31 16pp

7705300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970
PORTER, F L EDS Nuclear, Inc 77/03/21 9pp

7705300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program GE has no record of reanalysis for Cooper piping sys
STEPHENS, P W General Electric Co Nuclear Energy Products Div 77/01/24 18pp

Q Inspection reports, IE Bulletins & correspondence

7705010195 Forwards IE Info Notice 77-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director 77/03/23 2pp

7705030310 Forwards IE Info Notice 77-07, "Rupture of Radwaste"
O'REILLY, J P Region 2, Atlanta, Office of the Director 77/03/26 2pp

7705010104 F Contaminat
Air "
O'REILLY, J P
77/03/26 2

77/03/30 2pp

7705020127 Forwards IE Bulletin 77-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 77/04/11 1p

7705040212 Forwards IE Bulletin 77-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 77/04/14 2pp.

7705040308 Forwards IE Bulletin 77-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 77/04/14 1p

DOCKETED ITEMS

7903040404 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 1p

7903030161 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/17 2pp

7903030247 Ack receipt of IE Insp Repts 50-250/79-08 & 50-251/79-08 on 790227-0301 No proprietary info
WRIQ, R E Florida Power & Light Co 79/04/17 1p

--7903030251 Forwards IE Insp Repts 50-250/79-08 & 50-251/79-08 on 790227-0301 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 2pp

--7903030259 IE Insp Rept 50-250/79-08 & 50-251/79-08 on 790227-0301 No noncompliance noted Major areas inspected refueling maint, open items, noncompliance followup, RDE & IE bulletin & circular followup
VERDERY, E M, CANTRELL, F B Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/22 4pp

7903040434 Forwards response to IE Bulletin 79-07 None of methods specified are used by A/E in seismic analysis of safety-related piping Item 2 not applicable to A/E & NSSS Vendor advises that computer code listings are proprietary
WRIQ, R F Florida Power & Light Co 79/04/25 2pp

7903040486 Forwards "Steam Generator Insp Program" Insp showed no new phenomena Verified general pattern of denting is within predictable limits Requests permission to return facility to power operation
WRIQ, R E Florida Power & Light Co 79/05/18 2pp

--7903040492 "Steam Generator Insp Program"
Florida Power & Light Co 79/05/18 25pp

R Periodic operating reports & related correspondence

7903030015 Forwards analysis of annual aerial photograph of cooling canal sys boundary
WRIQ, R E Florida Power & Light Co 79/05/11 2pp

S Reportable occurrences, LERs & related correspondence

7903080354 Forwards LER 79-005/03L-0
SCHMIDT, A D Florida Power & Light Co 79/04/20 1p

--7903080359 LER 79-005/03L-0 on 790322, process radiation monitors R-11 & R-12 were out of svc Caused by failure of air sampling blower which supplies monitors Blower replaced & monitors returned to svc
SCHOPPMAN, M A Florida Power & Light Co 79/04/20 1p

7903080367 Forwards LER 79-006/03L-0
SCHMIDT, A D Florida Power & Light Co. 79/04/20 1p.

--7903080371 LER 79-006/03L-0 on 790322 packing leak-off observed on three valves Cause undetermined for two valves, Leaking packing on third due to broken bellows seal Unit in resling shut down repairs will be made before return to power
SCHOPPMAN, M A Florida Power & Light Co 79/04/20 2pp

P. Operating license stage documents & correspondence

7903040166 Informs that operational portions of operator requalification must be delayed Accepts written & operational portions of requalification program if completed by 790513
COLLINS, P F Operator Licensing Branch. 79/04/13 1p

DOCKET 50-254 GUAD-CITIES STATION, UNIT 1

F Security, medical, emergency & fire protection plans

7903040415 Forwards sections of fire protection BER which require further NRC review valve supervision, air breathing equipment & interior hose stations
HALL, R E Brookhaven National Laboratory 79/04/12 3pp

7903030366 Forwards modified physical security plan, Revision 3 Plan withheld (ref 10CFR2 790)
LEE, B Commonwealth Edison Co 79/04/26 1p

O. Adjudicatory correspondence

7903030258 Notifies properly worded contention re sabotage would be accepted, Contention 6, as admitted into Duke Power Co proceeding, encompasses aspects of revised Contention 11 presented by State of IL
GOODARD, R J Branch 2 79/04/06 2pp

J Insurance & indemnity information

7903040163 Endorsement 99 to MARLU Policy MF-22
GERAS, T. Nuclear Energy Liability Insurance Association 79/03/1p

7903070497 Confirms increased liability limit to \$124,000,000 for policies MF-1, 25, 43, 74, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHINI, J American Nuclear Insurers 79/03/01 1p

7903070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 81, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M. Mutual Atomic Energy Liability Underwriters 79/01/1p

7903140456 Forwards Amend 11 to Indemnity Agreement B-47 per 10CFR1 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501, Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/03/01 6pp

7903210262 Forwards Endorsements 38 & 39 to NELIA Policy MF-187 & Endorsements 47 & 48 to NELIA Policy MF-201
OSTER, J. Commonwealth Edison Co 79/03/16 4pp.

P Operating license stage documents & correspondence

7903030067 Forwards notes on 790302:15 & 22 conference telcons between NRC, consultants & util re bulletin "Potential Explosive Gas Mixtures Accumulations Associated w/ BWR Offgas Sys Operations"
IPPOLITO, T A Operating Reactors Branch 3 79/04/16 4pp

7903080141 Responds to 790305 ltr criticizing application for approval of proposed license amend that would allow shipment of spent fuel between stations Provides info on upcoming hearing
IPPOLITO, T A Operating Reactors Branch 3 79/04/18 1p

--7903080151 Opposes application for approval of proposed license amend that would allow shipment of spent fuel between stations
HOENBOKEN, P. Affiliation Unknown 79/03/15 2pp

7903010526 Forwards response to NRC 781205 request for addl info re instrument setpoint changes.
JANECEK, R F Commonwealth Edison Co 79/04/25 3pp

7903040482 Notifies of intention to develop safety analysis using existing computer codes, Requests addl info
BOLBRIO, C H Commonwealth Edison Co. 79/04/26. 1p

DOCKETED ITEMS

39

7905190016 Forwards current schedule for implementation of Mark I containment long-term mods. Discusses constraints inhibiting shorter time frame completion, including sys load requirements & current fuel cycles
REED, C Commonwealth Edison Co 79/05/11 3pp

7905190077 Requests correction of error discovered in 780423 ltr re capacity of Nuclear Assurance Corp NAC-1 truck cask used in spent fuel transfer Cask has capacity of two BWR assemblies
JANECEK, R F Commonwealth Edison Co 79/05/11 1p

7905250391 Forwards current licensing open items status list
REED, C Commonwealth Edison Co 79/05/18 11pp

7905250333 Forwards "Quad-Cities Nuclear Power Station Unit 1, Cycle 5 Startup Test Results"
JANECEK, R F Commonwealth Edison Co 79/05/21 1p

--7905250536 "Quad-Cities Nuclear Power Station Unit 1, Reload 4, Cycle 5 Startup Test Results"
* Commonwealth Edison Co. 79/05/21, 15pp

0 Inspection reports, IE Bulletins & correspondence

7905020421 Forwards response to IE Bulletins 78-12 & 78-12A, "Atypical Weld Fail in Reactor Pressure Vessel Welds"
REED, C Commonwealth Edison Co 79/03/22 10pp

7905010236 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23 1p

7905030370 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26 1p

7905010133 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/BVC Air Sys Used as Source of Breathing Air"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/28 1p

7905010181 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/30 1p

7905250200 Responds to IE Bulletin 79-03 re welding defects in certain longitudinally welded pipe spools. Plants inspected, no pipe found
REED, C Commonwealth Edison Co 79/04/12 2pp

7905010567 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040334 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040529 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905030206 Forwards IE bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required.
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/17 1p

7905040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/21

--7905040201 Forwards ACRS recommendations re TMI incident, presented on 790417
FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards 79/04/18 1p

--7905040221 In response to NRC 790418 ltr, states all ACRS 790417 recommendations apply to all PWRs, but were not intended to require immediate changes. Plant mods should be made after study of effects on overall safety. TMI excluded
CARBON, H X ACRS - Advisory Committee on Reactor Safeguards 79/04/20 2pp

7905240633 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping. Reanalysis indicates method of intramodal combination has little effect on pipe stresses & equipment support loads
REED, C Commonwealth Edison Co 79/04/24 4pp

7905150148 Forwards responses to IE Bulletin 79-06A, Revision 1 re BWR events identified during TMI-2. Util has formed task force to review BWR events & recommend corrective action, as required
REED, C Commonwealth Edison Co 79/04/27 22pp

7905300242 Responds to IE Bulletin 79-04 No 3.4 or 6-inch Valves swing check valves are in use at Dresden or Quad-Cities. Review of Zion has identified use of valves in some piping, but review is incomplete. Will rept later
REED, C Commonwealth Edison Co 79/05/01 2pp

7905140488 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Circulation Motor Generator Set Resulted in Reactor Power Increase"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/02 1p

R Periodic operating reports & related correspondence

7905170250 Forwards monthly operating rept for Apr 1979
KALIVIANAKIS, N Commonwealth Edison Co 79/05/17 1p

--7905170260 Monthly operating rept for Apr 1979
HANNUK, D Commonwealth Edison Co 79/05/17 28pp

S Reportable occurrences, LERs & related correspondence

7905100296 Forwards LER 79-017/03L-0
KALIVIANAKIS, N Commonwealth Edison Co 79/04/26 1p

--7905100297 LER 79-017/03L-0 on 790416 leak between RHR water & svc water side of heat exchanger. Caused by crack in pipe to flange weld of bellows assembly. Pipe repaired
VAHRENWALD, J Commonwealth Edison Co 79/04/26 1p

7905090389 Informs that release rate of radiiodine & radioactive particulate matl w/half-lives greater than eight days was 2.22 times higher than Tech Spec design objective for first quarter 1979. Caused by steam leaks & "spiking"
KALIVIANAKIS, N Commonwealth Edison Co 79/04/30 2pp

7905240597 Forwards LER 79-018/01T-0
KALIVIANAKIS, N Commonwealth Edison Co 79/05/11 1p

--79

DOCKETED ITEMS

790310131 Orders special prehearing conference on 790510 in St Joseph, MI to consider petitions to intervene, to identify key issues & to establish schedule for further actions in proceeding
 BECKENFELDER, C Atomic Safety and Licensing Board Panel 79/04/05 2pp

790310046 Forwards steam generator repair rept which accompanied 790307 license amend request w/o encl
 BARTH, C A Branch 3 79/04/16 1p

7903100140 Forwards steam generator repair rept which constitutes basic documentation by util accompanying 790103 request for license amend Rept to be used as aid in preparation of petition to intervene
 BARTH, C A Branch 3 79/04/16 1p

790310571 Responds to NRC, Consumers Power Co & ASLB re intervention in hearings on steam generator replacement Supporting documentation & Certificate of Svc encl
 SINCLAIR, M Great Lakes Energy Alliance 79/04/20 19pp

J Insurance & indemnity information

7903070497 Confirms increased liability limit to \$124,000,000 for policies NF-1 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
 QUATTROCHI, J American Nuclear Insurers 79/05/01 1p

7903160172 Forwards Amend B to Indemnity Agreement B-40, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
 SALTMAN, J Antitrust & Indemnity Group 79/05/01 5pp

790310125 Forwards Endorsements 61 & 62 to NELIA Policy NF-179
 GUTER, B C Consumers Power Co 79/05/15 3pp

P Operating license stage documents & correspondence

7903070029 Forwards topics deleted from systematic evaluation program review of facilities Requests review & identification of errors within 30 days from receipt of ltr
 ZIEHMAN, D L Operating Reactors Branch 2 79/04/16 7pp

7903230602 Forwards steam generator repair rept Requests addl info to complete evaluation of alternatives in steam generator replacement program
 ZIEHMAN, D L Operating Reactors Branch 2 79/04/17 4pp

7903080138 Forwards request for addl info re steam generator replacement program
 ZIEHMAN, D L Operating Reactors Branch 2 79/04/19 3pp

7903250343 Forwards draft evaluation of systematic evaluation program Topic V-10 A, "RRR Sys Heat Exchanger" Requests review & responses within 30 days
 ZIEHMAN, D L Operating Reactors Branch 2 79/04/21 6pp

7903290162 Notification of 790427 meeting w/Bechtel, Consumers Power & Northern States Power Co in Bethesda, MD to discuss status of review of nonconservative value used for elbow stiffness in certain piping stress calculations
 JORDAN, E L Division of Reactor Operations Inspections 79/04/24 1p

7903250210 Summary of 790425 meeting w/C-E re natural circulation capability for C-E plants
 THADANI, A C Reactor Systems Branch 79/05/02 43pp

7903110085 Forwards rapid response to NRC followup questions re TMI Responses may not be totally complete
 DEWITT, R B, HOFFMAN, D P Consumers Power Co 79/05/08 44pp.

7903240731 Notifies that request for addl info re degraded grid voltage should be submitted to licensee
 LAINAS, G C Plant Systems Branch 79/05/08 3pp

7903230087 Forwards summary of 790501 meeting w/C-E re natural circulation conditions in C-E operating reactors
 THADANI, A C Reactor Systems Branch 79/05/09 1p

7903150309 Forwards addl info requested on 790508 re pressurizer code safety valves & main feedwater sys
 DEWITT, R B, HOFFMAN, D P Consumers Power Co 79/05/10 3pp

7903210150 Submits bimonthly status rept for Mar-Apr 1979 Bechtel Power Corp has been designated as A/E for cooling equipment mod program
 HOFFMAN, D P Consumers Power Co 79/05/15 1p

7903220020 Forwards responses to questions re TMI incident deliv A Schwencer at 790512 meeting Oversized drawing encl
 HOFFMAN, D P Consumers Power Co 79/05/15 20pp

7903230052 Responds to concerns raised at 790507 meeting Util & ASLB make mods necessary to bring piping sys to FSAR stress limits by end of next refueling outage
 HOFFMAN, D P Consumers Power Co 79/05/16 2pp

7903230095 Forwards "Atrial Power Distributions from Fourier Fitted Incore Detector Powers" to clarify Tech Spec change
 HOFFMAN, D P Consumers Power Co 79/05/17 1p

--7903230104 "Atrial Power Distributions from Fourier Fitting of Incore Detector Powers," presented at ANS winter meeting in San Francisco, CA on 751116-21
 TERNEY, W B, MARKS, O H, WILLIAMSON, E A Consumers Power Co 75/11/21 7pp

7903300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970
 PORTER, F L EDS Nuclear, Inc 79/05/21 9pp

--7903300263 Forwards EDS Nuclear, Inc list of DWRs & piping sys which could have been impacted by deficient computer program GE has no record of reanalysis for Cooper piping sys
 STEPHENS, P W General Electric Co, Nuclear Energy Products 79/01/24 18pp

7903310449 Responds to IE Bulletin 78-12, "Atypical Weld Metallurgy in Reactor Pressure Vessels" Final rept will be submitted by 790731
 BIXEL, D A Consumers Power Co 79/05/29 1p

Q Inspection reports, IE Bulletins & correspondence

7903080084 Forwards IE Insp Rept 50-255/79-04 on 790220-23 & no violation
 HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/03/08 2pp

--7903080086 Notice of violation from Insp on 790220-23
 * Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/03/08 1p

--7903080093 IE Insp Rept 50-255/79-04 on 790220-23 Noncompliance failure to implement procedures re mods made to filter drain plugs on emergency diesel during maint
 JORGENSEN, B L, HARNICK, R F Region 3, Chicago, Office of the Director 79/03/06 5pp

7903010247 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
 KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/08 1p.

7903040026 Forwards IE Info Notice 79-07, "Rupture of Radwaste Transfer Line"
 KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/08 1p.

7903010162 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air"
 KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/08 1p.

7903010390 Forwards IE Info Notice 79-09, "Spill of Radioactive Contaminated Resin"
 KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/08 1p

7903090167 Act receipt of 790330 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-255/79-04
 HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/04/06 1p

--7903090172 Responds to NRC ltr re violations noted in IE Insp Rept 50-255/79-04 Corrective actions diesel generators inspected & valve drain tap removed.
 HOFFMAN, D P Consumers Power Co 79/03/30 2pp

7903030023 Forwards IE Bulletin 79-06, "Review of Operational Error Sys Misalignments Identified During TMI Incident" Licensee action required
 KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/08 1p

7905010579 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified during TMI Incident " Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040324 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040548 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident " Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905070162 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905030220 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/17 1p

7905080486 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl 1 " Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/21 1p

7905150355 Responds to 790329 request to allow util to combine reviews of IE Bulletin 79-02 & systematic evaluation program Topic III-5 A Since bulletin involves safety issue, NRC refuses to extend time for review
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/26 1p

7905240309 Responds to IE Bulletin 79-06B re TMI errors Conditions & events which led to TMI incident were reviewed w/employees
HOFFMAN, D P Consumers Power Co 79/04/27 10pp

7905250364 Responds to IE Bulletin 79-01, per 790501 discussion w/HJ Wong Identifies & compares computer program used in seismic analysis of safety-related piping
HOFFMAN, D P Consumers Power Co 79/05/03 3pp

R Periodic operating reports & related correspondence

7905150414 Forwards monthly operating rept for Apr 1979
ADAMS, W E Consumers Power Co 79/05/07 1p

--7905150416 Monthly operating rept for Apr 1979
BODTKE, P J Consumers Power Co 79/05/07 4pp

B Reportable occurrences, LERs & related correspondence

7905040386 Forwards LER 79-016/03L-0
HOFFMAN, D P Consumers Power Co 79/04/30 1p

--7905040407 LER 79-016/03L-0 on 790406 diesel generator output breaker has potential to lockout open. Caused by failure of contact on shutdown sequencer to operate. Sequencer repaired
* Consumers Power Co 79/04/30 1p

7905080537 Forwards LER 79-017/03L-0
HOFFMAN, D P Consumers Power Co. 79/05/04 1p

--7905080539 LER 79-017/03L-0 on 790404 while taking battery voltage readings, two cells in station battery 2 burst due to explosion of hydrogen inside cells. Battery taken out of svc. Two replacement cells ordered
* Consumers Power Co 79/04/04 1p

7905100249 Forwards LER 79-009/01X-1
HOFFMAN, D P Consumers Power Co 79/05/07 1p

--7905100252 LER 79-009/01X-1 on 790220 design review indicated butterfly valves may not close under accident conditions. Caused by vague purchase specs which did not include requirements for closing against pressure.
* Consumers Power Co 79/05/07 1p.

7905100255 Forwards LER 79-018/03L-0
HOFFMAN, D P Consumers Power Co. 79/05/07 1p

--7905100259 LER 79-018/03L-0 on 790409 reactor made critical w/o conducting flow test of lines. Caused by misinterpretation of Tech Specs. Personnel instructed to exercise care when revising operability requirements
* Consumers Power Co 79/05/07 1p

7905150619 Forwards LER 79-019/03L-0
HOFFMAN, D P Consumers Power Co 79/05/10 1p

--7905150625 LER 79-019/03L-0 on 790331 sump drained to auxiliary bldg floor drains through test connection located between containment bldg isolation valves. Caused by communication failure. Corrective action still being evaluated
* Consumers Power Co 79/05/10 1p

7905220329 Forwards LER 79-020/01T-0
HOFFMAN, D P Consumers Power Co 79/05/15 1p

--7905220335 LER 79-020/01T-0 on 790501 restraints for piping between power conversion sys safety injection tanks B & D not adequate. Caused by program error used by consultant to determine hanger placement
* Consumers Power Co 79/05/15 1p

7905220340 Forwards LER 79-013/01X-1
HOFFMAN, D P Consumers Power Co 79/05/15 1p

--7905220343 LER 79-013/01X-1 on 790327 level in T-82C safety injection tank decreased while draining D tank to permit increase in boron concentration. Caused by seal leakage CV 3004 drain valve will be repaired during next refueling outage
* Consumers Power Co 79/05/15 1p

T Hearing transcripts on non-antitrust matters

7905240330 Transcript of 790509 meeting in St Joseph, MI. Pp 1-171
BECHHOEFER, C ; ANDERSON, O C ; LIVINGSTON, S Atomic Safety and Licensing Board Panel 79/05/09 172pp

DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

J Insurance & indemnity information

7905140462 Forwards Amend 12 to Indemnity Agreement B-52 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp

7905080390 Forwards Endorsement 47 to ANI Policy NF-19B
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc Div 79/05/03 2pp

7905080394 Forwards Endorsement 48 to ANI Policy NF-19B
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc Div 79/05/03 2pp

K Utility Final Safety Analysis Report (FSAR) & amends

7905110024 Forwards Amend 6B to FSAR
GILLELAND, J E Tennessee Valley Authority 79/05/08 2pp

--7905110031 Amend 6B to FSAR w/oversized drawings
* Tennessee Valley Authority 79/05/08 100pp

P. Operating license stage documents & correspondence

7905080033 Act receipt of Class II fee & application for amend to Licenses DPR-33, DPR-52 & DPR-6B. Requests payment of addl fee.
MILLER, W O License Fee Management Branch 79/04/04 1p

7905110177 Submits schedule for torus mods. in response to NRC 790312 ltr to HQ Parris
GILLELAND, J E Tennessee Valley Authority 79/05/04 3pp

7905140371 Forwards "Summary Rept. Refueling Test Program, Cycle 3 "
GILLELAND, J E Tennessee Valley Authority 79/05/07 1p

--7905140378 "Summary Rept. Refueling Test Program, Cycle 3, "
* Tennessee Valley Authority 79/05/07 6pp

DOCKETED ITEMS

7905240846 Notification of 790523 meeting w/util in Chattanooga, TN to discuss NRC presentation on results of facility vital area confirmatory analysis. Discussion will cover 10CFR2 790 info & will be closed to public
CLARK, R A Reactor Safeguards Licensing Branch 79/05/08 1p

7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969. Review & reanalysis included all work through Dec 1970
PORTER, F L EDS Nuclear, Inc 79/05/21 9pp

--7905300263 Forwards EDS Nuclear, Inc list of BHRs & piping sys which could have been impacted by deficient computer program. GE has no record of reanalysis for Cooper piping sys
STEPHENS, P W General Electric Co, Nuclear Energy Products Div 79/01/24 16pp

Q Inspection reports, IE Bulletins & correspondence

7905150103 Forwards IE Insp Repts 50-259/79-04, 50-260/79-04 & 50-296/79-04 on 790102-0202 No noncompliance noted
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/22 2pp

--7905150107 IE Insp Repts 50-259/79-04, 50-260/79-04 & 50-296/79-04 on 790102-0202 No noncompliance noted. Major areas inspected plant operations, refueling & restart of Unit 1, plant tour & liquid radwaste processing
SULLIVAN, R F Region 2, Atlanta, Office of the Director
DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/19 7pp

7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905150138 Forwards IE Insp Repts 50-259/79-05, 50-260/79-05 & 50-296/79-05 on 790226-0302 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 2pp

--7905150147 IE Insp Repts 50-259/79-05, 50-260/79-05 & 50-296/79-05 on 790226-0302 No noncompliance noted. Major areas inspected reportable secondary containment leak rate testing, IE circulars & bulletins
PRICE, D B Region 2, Atlanta, Office of the Director
DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/22 6pp

7905010113 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Avc Air Sys Used as Source of Breathing Air"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/28 2pp

7905010363 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/30 2pp

7905080176 Responds to IE Bulletin 79-03 No evidence that any stainless steel pipe mfg by Youngstown Welding & Engineering Co was used in any ASME Class I, II or III safety-related sys
OILLELAND, J E Tennessee Valley Authority 79/04/12 1p

7905030368 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 3pp

7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 3pp

7905150700 Forwards IE Bulletin 79-08, "Events Relevant to BHRs Identified During TMI Incident" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp

7905030172 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp

7905020479 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp

7905250344 Forwards response to Item 7 b of IE Insp Repts 50-259/79-05 50-260/79-05 & 50-296/79-05 re deterioration of Buna-N components in ASCO solenoids, as followup to IE Bulletin 78-14
OILLELAND, J E Tennessee Valley Authority 79/04/20 3pp

7905300745 Forwards response to IE Bulletin 79-08 Plant superintendent will present review of TMI incident to all managers & supervisors w/operational responsibilities. Containment isolation design & procedures have been reviewed
OILLELAND, J E Tennessee Valley Authority 79/04/25 14pp

7905240947 Ack receipt of 790423 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/79-07, 50-260/79-07 & 50-296/79-07
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/30 2pp

--7905240972 Responds to NRC 790330 ltr re violations noted in IE Insp Repts 50-259/79-07, 50-260/79-07 & 50-296/79-07. Corrective actions entire radwaste bldg properly posted as radioactive area
OILLELAND, F E Tennessee Valley Authority 79/04/23 4pp

--7905240992 Forwards IE Insp Repts 50-259/79-07, 50-260/79-07 & 50-296/79-07 on 790226-0302 & notice of violation
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/30 2pp

--7905241003 Notice of violation from insp on 790226-0302
* Region 2, Atlanta, Office of the Director 79/03/30 2pp

--7905241005 IE Insp Repts 50-259/79-07, 50-260/79-07 & 50-296/79-07 on 790226-0302 Noncompliance noted. Failure to post radiation area, label containers of radioactive matl & barricade high radiation area
JACKSON, L L Region 2, Atlanta, Office of the Director
O'BSON, A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 2pp

--7905241005 IE Insp Repts 50-259/79-07, 50-260/79-07 & 50-296/79-07 on 790226-0302 Noncompliance noted. Failure to post radiation area, label containers of radioactive matl & barricade high radiation area
JACKSON, L L Region 2, Atlanta, Office of the Director 79/03/29 2pp

7905240632 Forwards responses to IE Bulletin 79-04 re incorrect swing check valve weights. Corrected valve weights do not create any overstressing in pipes, hangers or supports. Addl info will be provided by 790511
OILLELAND, J E Tennessee Valley Authority 79/05/01 6pp

R Periodic operating reports & related correspondence

7905030343 Forwards "Environ Radioactivity Levels, Annual Rpt 1978"
OILLELAND, J E Tennessee Valley Authority 79/04/27 1p

--7905030349 "Environ Radioactivity Levels, Annual Rpt 1978"
* Tennessee Valley Authority MRH-79-3-BF2 79/04/27 50pp

7905010475 Forwards "Fish Impingement Rpt" for first quarter 1979
OILLELAND, J E Tennessee Valley Authority 79/05/01 2pp

--7905010476 "Fish Impingement Rpt" for first quarter 1979
* Tennessee Valley Authority 79/05/01 14pp

7905150346 Forwards monthly operating rpt for Apr 1979
DEWEASE, J O Tennessee Valley Authority 79/05/09 1p

--7905150352 Monthly operating rpt for Apr 1979
DEWEASE, J O Tennessee Valley Authority 79/04/30 36pp

S Reportable occurrences, LERs & related correspondence

7905090314 Forwards LER 79-007/03L-0
FOX, H S Tennessee Valley Authority 79/05/02 1p

--7905090316 LER 79-007/03L-0 on 790404 one zone of initiation logic for spreader room sprinkler sys found inoperable. Caused by failure of contact on auxiliary relay to make up Relay replaced.
* Tennessee Valley Authority 79/05/02 2pp

DOCKETED ITEMS

43

DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2

J Insurance & indemnity information

/905140462 forwards Amend 12 to Indemnity Agreement B 92 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
BALITMAN, J Antitrust & Indemnity Group 79/05/01 6pp

/905080390 forwards Indorsement 47 to ANI Policy No 190
FIEDLER, J Marsh & McLennan, M & M Nuclear Consultants, Inc Div
79/05/01 2pp

/905000794 forwards Indorsement 48 to ANI Policy No 190
FIEDLER, J Marsh & McLennan, M & M Nuclear Consultants, Inc Div
79/05/01 2pp

K Utility final Safety Analysis Report (FSAR) & amends

/905110024 forwards Amend 60 to FSAR
OILILAND, J E Tennessee Valley Authority 79/05/01 2pp

- /905110031 Amend 60 to FSAR H/oversized drawings
" Tennessee Valley Authority 79/05/01 100pp

P Operating license stage documents & correspondence

/905000073 Ack receipt of Class II fee & application for amend to
licenses DPR-1, DPR 52 & DPR 60 Requests payment of addl
fee
MILLER, W O License Fee Management Branch 79/04/04 1p

/905170104 Notices of refund of fees, submitted 78/05, for authority to
transfer fuel between facility & Crystal River Unit 3 Refund
will be sent when processed
MILLER, W O License Fee Management Branch 79/05/03 1p

/905110177 Submits schedule for torus mode, in response to NRC 790312
1st to HD Parris
OILILAND, J E Tennessee Valley Authority 79/05/04 3pp

/905240046 Notification of 790721 meeting w/uttl in Chattanooga, TN to
discuss NRC presentation on results of facility vital area
confirmatory analysis Discussion will cover 10CFR2790 info
& will be listed to public
CLARK, R A Reactor Safeguards Licensing Branch 79/05/00 1p

/905102611 forwards addl info re 790204 request for Tech Spec amend to
allow one relief valve out of svc w/out decrease in power
OILILAND, J E Tennessee Valley Authority 79/05/15 1pp

- /905102669 "Supplemental Helrad Licensing Submittal for Reload 2"
IRVIN, A M, BRUDOK, R O General Electric Co, Nuclear Energy
Products Div MD 2416A 79/04/30 24pp

/905220370 Responds to 790423 ltr forwards addl info re proposed Tech
Spec changes for startup test program, code loading
verification & limiting cases after dc power failure
OILILAND, J E Tennessee Valley Authority 79/05/16 7pp

7905100208 forwards summary of EDN Nuclear, Inc resolution/documentation
of elbow flexibility error which existed in versions of
PIBOL piping analysis computer program from Jan-Oct 1969.
Review & reanalysis included all work through Dec 1970
PORTER, C L EDN Nuclear, Inc 79/05/21 9pp

--7905300263 forwards EDN Nuclear, Inc list of BWRs & piping sys which
could have been impacted by deficient computer program
OE has no record of reanalysis for Cooper piping sys
STEPHENS, P W General Electric Co, Nuclear Energy Products Div
79/01/24 10pp

Q Inspection reports, IE Bulletins & correspondence

7905150103 forwards IL Insp Repts 50-259/79-04, 50-260/79-04 &
50-296/79-04 on 790102-0302 No noncompliance noted
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/03/22 2pp

--7905150107 IE Insp Repts 50-259/79-04, 50-260/79-04 & 50-296/79-04 on
790102-0302 No noncompliance noted Major areas inspected
plant operations, refueling & restart of Unit 1, plant tour &
liquid radwaste processing
BULLIVAN, R F Region 2, Atlanta, Office of the Director
DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear
Support Branch 79/03/19 7pp

7905010211 forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director,
79/03/23 2pp

7905150138 forwards IE Insp Repts 50-259/79-05, 50-260/79-05 &
50-296/79-05 on 790226-0302, No noncompliance noted.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 79/03/23 2pp

--7905150147 IE Insp Repts 50-259/79-05, 50-260/79-05 & 50-296/79-05 on
790226-0302 No noncompliance noted Major areas inspected
reportable secondary containment leak rate testing, IE
circulars & bulletins
PRICE, D B Region 2, Atlanta, Office of the Director
DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear
Support Branch 79/03/22 6pp

7905010113 forwards IE Info Notice 79-08, "Interconnection of
Contaminated Bys w/Bvc Air Bys Used as Source of Breathing
Air"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/28 2pp

7905010363 forwards IE Info Notice 79-09, "Spill of Radioactively
Contaminated Resin"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/01/30 2pp

/905080176 Responds to IE Bulletin 79-03 No evidence that any stainless
steel pipe mfg by Youngstown Welding & Engineering Co was
used in any ABHF Class I, II or III safety-related sys
OILILAND, J E Tennessee Valley Authority 79/04/12 1p

/905030368 forwards IE Bulletin 79-07, "Seismic Stress Analysis of
Safety-Related Piping" Licenses action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 3pp

/905040233 forwards IE Bulletin 79-06B, "Review of Operational Errors &
Bys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director,
79/04/14 3pp

/905150700 forwards IE Bulletin 79-08, "Events Relevant to BWRs
Identified During TMI Incident," Licenses action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 2pp

7905030172 forwards IE Bulletin 79-09, "Failures of OE Type AK-2
Circuit Breaker in Safety-Related Bys," Licenses action
required.
O'REILLY, J P Region 2, Atlanta, Office of the Director,
79/04/17 2pp

/905020479 forwards IE Bulletin 79-06A, Revision 1, "Review of
Operational Errors & Bys Misalignments Identified During TMI
Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/10 2pp

7905250344 forwards response to Item 7.b of IE Insp Repts 50-259/79-05,
50-260/79-05 & 50-296/79-05 re deterioration of Buna-N
components in ABCU solenoids, as followup to IE Bulletin
78-14
OILILAND, J E Tennessee Valley Authority 79/04/20 3pp.

7905300745 forwards response to IE Bulletin 79-08 Plant superintendent
will present review of TMI incident to all managers &
supervisors w/operational responsibilities Containment
isolation design & procedures have been reviewed.
OILILAND, J E Tennessee Valley Authority, 79/04/25 14pp.

7905240947 Ack receipt of 790423 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-259/79-07,
50-260/79-07 & 50-296/79-07
BUTLERLAND, J T Region 2, Atlanta, Fuel Facility & Materials
Safety Branch 79/04/30 2pp.

--7905240972 Responds to NRC 790330 ltr re violations noted in IE Insp
Repts 50-259/79-07, 50-260/79-07 & 50-296/79-07 Corrective
actions, entire radwaste bldg properly posted as radioactive
area
OILILAND, F E Tennessee Valley Authority, 79/04/23 4pp.

--7905240992 forwards IE Insp Repts 50-259/79-07, 50-260/79-07 &
50-296/79-07 on 790226-0302 & notice of violation
BUTLERLAND, J T Region 2, Atlanta, Fuel Facility & Materials
Safety Branch, 79/03/30 2pp

--7905241003 Notice of violation from insp on 790226-0302,
" Region 2, Atlanta, Office of the Director, 79/03/30 2pp

DOCKETED ITEMS

--7905241005 IE Insp Repts 50-259/79-07, 50-260/79-07 & 50-296/79-07 on 790226-0302 Noncompliance noted failure to post radiation area, label containers of radioactive matl & barricade high radiation area
JACKSON, L L Region 2, Atlanta, Office of the Director
OIBSON, A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch, 79/03/27 2pp

7905240652 Forwards responses to IE Bulletin 79-04 re incorrect swing check valve weights Corrected valve weights do not create any overstressing in pipes, hangers or supports Addl info will be provided by 790511
GILLELAND, J E Tennessee Valley Authority 79/05/01 4pp

R Periodic operating reports & related correspondence

7905030343 Forwards "Environ Radioactivity Levels, Annual Rept 1978"
GILLELAND, J E Tennessee Valley Authority 79/04/27 1p

--7905030349 "Environ Radioactivity Levels, Annual Rept 1978"
* Tennessee Valley Authority MRH-79-3-BF2 79/04/27 30pp

7905010475 Forwards "Fish Impingement Rept" for first quarter 1979
GILLELAND, J E Tennessee Valley Authority 79/03/01 2pp

--7905010476 "Fish Impingement Rept" for first quarter 1979
* Tennessee Valley Authority 79/03/01 14pp

790510346 Forwards monthly operating rpt for Apr 1979
DEWEASE, J G Tennessee Valley Authority 79/05/09 1p

--790510392 Monthly operating rpt for Apr 1979
DEWEASE, J G Tennessee Valley Authority 79/04/30 36pp

S Reportable occurrences, LERs & related correspondence

7905110313 Forwards LER 79-004/03L-0
FOX, H S Tennessee Valley Authority 79/05/07 1p

7905110318 LER 79-004/03L-0 on 790414 reactor bldg, turbine bldg & refueling zone vent exhaust monitor RM-90-230 failed surveillance test SI 4 B B-4 J, Section 4a Caused by failure of input card for radiation monitor
* Tennessee Valley Authority 79/05/07 2pp

7905230078 Forwards LER 79-005/03L-0
FOX, H S Tennessee Valley Authority 79/05/17 1p

--7905230335 LER 79-005/03L-0 on 790419 broken terminal discovered on shutdown board D battery Cause unknown Affected cells replaced & personnel instructed in proper tightening methods
* Tennessee Valley Authority 79/05/17 2pp

7905310362 Forwards LER 79-008/01T-0
FOX, H S Tennessee Valley Authority 79/05/18 1p

7905100328 Notification of change in 780901 submittal Fire protection penetrations filled w/9 inches of foam instead of 12 inches
UTLEY, E E Carolina Power & Light Co 79/03/09 1p

7905250121 Forwards application for amend to License DPR-23, revising Tech Specs re fire protection sys
UTLEY, E E Carolina Power & Light Co 79/03/17 1p

--7905250124 Application for amend to License DPR-23, revising Tech Specs re fire protection sys
* Carolina Power & Light Co 79/03/17 12pp

Q Adjudicatory correspondence

7905140194 Forwards TF Carter 790122 memo describing recent draft document re sabotage of spent nuclear fuel Info is being assessed ASLAs will be notified upon completion
LEWIS, B H Branch 2 79/03/30 3pp

7905240603 Forwards EQ Case 780403 memo to S Levine re studies to determine capability of existing personnel neutron dosimetry sys to monitor reactor neutron environ
LEWIS, B H Branch 2 79/04/02 7pp

7905240771 Advises that Suppl 2 of SER was issued 790330 Recommends conference call to discuss ASLAs plans for future action
LEWIS, B H Branch 2 79/04/04 1p

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies MF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHI, J American Nuclear Insurers 79/03/01 1p

7905070382 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/03/01 1p

7905160183 Forwards Amend B to Indemnity Agreement B-43, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/03/01 3pp

7905140337 Forwards Endorsement 46 to MAELU Policy MF-49
GRAHAM, W E Carolina Power & Light Co 79/03/01 2pp

7905170233 Forwards Amend 9 to Indemnity Agreements B-42 & B-41 reflecting increase in primary liability insurance provided by ANI/MAELU
BARHAM, C D Douglass & Barham 79/03/11 3pp

P Operating license stage documents & correspondence

7905040307 Forwards Suppl 2 to 740520 safety evaluation of proposed power increase
SCHWENGER, A Operating Reactors Branch 1 79/03/30 2pp

--7905040309 Suppl 2 to 740520 safety evaluation of proposed amend to License DPR-23, allowing power increase from 2,200 MWt to 2,300 MWt
* Operating Reactors Branch 1 79/03/30 30pp

7905070121 Forwards Amend 36 to License DPR-23, safety evaluation & notice of issuance & availability
SCHWENGER, A Operating Reactors Branch 1 79/04/11 2pp

--7905070123 Amend 36 to License DPR-23 authorizing removal of all part-length control rods from reactor
SCHWENGER, A Operating Reactors Branch 1 79/04/11 11pp

--7905070127 Safety evaluation supporting Amend 36 to License DPR-23
* Office of Nuclear Reactor Regulation 79/04/11 3pp

--7905070130 Notice of issuance & availability of Amend 36 to License DPR-23
SCHWENGER, A Operating Reactors Branch 1 79/04/11 2pp

to

7905150290 Notifies that 790306 application for amend to License DPR-23 has been received w/\$6,400 for two Class 2 & one Class 3 amends Review determined first & second changes each require Class 3 amend fee
MILLER, W O License Fee Management Branch 79/04/20 1p

7905030331 Notifies that util will perform extended burnup test for four assemblies during Cycle 7 Forwards program description
UTLEY, E E Carolina Power & Light Co 79/04/23 3pp

7905020333 Forwards \$2,800 addl license fee requested in NRC 790420 ltr
UTLEY, E E Carolina Power & Light Co. 79/04/27 1p

7905080437 Requests extension until 790731 to submit evaluation justifying unlimited purging of containment bldg during normal operation
UTLEY, E E Carolina Power & Light Co 79/05/01 1p

7905080453 Forwards oversized maps & photo attachments to util 781129 rept on main dam core trench features w/o drawings
FLOYD, B D Carolina Power & Light Co 79/05/08 3pp

7905220346 Requests change in Tech Specs to reflect deletion of pressurizer pressure signal w/supporting documentation & Class III amend fee
UTLEY, E E Carolina Power & Light Co 79/05/18 9pp

7905290374 Forwards seismic reanalysis of RCB in response to 790517 & 790518 telcons Loads & moments meet FSAR criteria
UTLEY, E E Carolina Power & Light Co 79/05/21 4pp

3 Inspection reports, IE Bulletins & correspondence

7905230583 Forwards IE Insp Rept 50-261/79-04 on 790213-16 No noncompliance noted
LEHIB, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/19 2pp

--7905230592 IE Insp Rept 50-261/79-04 on 790213-16 No noncompliance noted Major areas inspected licensee event followup & plant operations
MCHEENRY, T J Region 2, Atlanta, Office of the Director
DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/19 4pp

7905010168 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905030294 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/26 2pp

7905010093 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/28 2pp.

7905010346 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/30 2pp

7905020125 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" Licensee action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/11 1p

7905230613 Responds to IE Bulletin 79-03. No pipe spools from Youngstown Welding & Engineering Co are used or planned to be used
UTLEY, E E Carolina Power & Light Co 79/04/13 1p

7905040163 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp

7905040281 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/14 1p

7905040329 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905030141 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp

7905020426 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp

7905230598 Ack receipt of 790414 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/79-03
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/19 1p

--7905230604 Responds to NRC 790323 ltr re violation noted in IE Insp Rept 50-261/79-03 Corrective actions only health physics technicians w/proper qualifications will be utilized for back shift coverage
BANKS, H R Carolina Power & Light Co 79/04/14 2pp

--7905230610 Forwards IE Insp Rept 50-261/79-05 on 790226-0302 & notice of violation
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/23 2pp

--7905230614 Notice of violation from insp on 790226-0302
* Region 2, Atlanta, Office of the Director. 79/03/23 1p

--7905230623 IE Insp Rept 50-261/79-05 on 790226-0302 Noncompliance noted technicians used in responsible positions w/o sufficient health physics experience
JENKINS, O R Region 2, Atlanta, Office of the Director
GIBSON, A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/23 7pp

7905010317 Forwards restated paragraph from 770330 ltr, submitted as revision to QA program, in response to IE Insp Repts 50-324/79-02 & 50-325/79-02 Paragraph discusses radiation survey/measuring instruments
UTLEY, E E Carolina Power & Light Co 79/04/23 2pp

7905040084 Requests that present inservice testing program for pumps & valves, conditionally accepted by NRC on 771014, be allowed to continue through 810307
UTLEY, E E Carolina Power & Light Co 79/04/25 1p

7905010552 Forwards util 790424 response to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Requests review & reply
UTLEY, E E Carolina Power & Light Co 79/04/27 1p

--7905010557 Responds to IE Bulletin 79-07 requesting info on seismic stress analysis of safety-related piping Westinghouse reanalysis revealed max stress was well below allowable limit.
UTLEY, E E Carolina Power & Light Co 79/04/24 2pp

7905300296 Responds to IE Bulletin 79-04. Requests extension of response date to 790531
UTLEY, E E Carolina Power & Light Co 79/05/01 1p

7905270388 Preliminary response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Review of records revealed QC documentation not available to sufficiently support proper bolt installation
UTLEY, E E Carolina Power & Light Co 79/05/22 3pp

R Periodic operating reports & related correspondence

7905150418 Forwards monthly operating rept for Apr 1979
FURR, B J Carolina Power & Light Co 79/05/10 1p

--7905150426 Monthly operating rept for Apr 1979
HATFORD, K L Carolina Power & Light Co. 79/05/02 4pp.

B Reportable occurrences, LERs & related correspondence

7905040531 Forwards LER 79-006/03L-0
FURR, B J Carolina Power & Light Co 79/05/01 1p

--7905040535 LER 79-006/03L-0 on 790402 boric acid transfer pump B tripped due to high temp. Caused by broken shaft. Pump replaced & tested satisfactorily
STARKEY, R B Carolina Power & Light Co 79/05/01 2pp

DOCKETED ITEMS

7905130450 Forwards LER-79-007/03L-0
FURR, B J Carolina Power & Light Co 79/05/10 1p

--7905130451 LER 79-007/03L-0 on 790411 leak found in steam generator B
Insp revealed six tubes w/small leaks Cause undetermined
Leaks will be repaired by explosive plugging
STARKEY, R B Carolina Power & Light Co 79/05/10 2pp

7905130461 Forwards LER 79-011/01T-0
FURR, B J Carolina Power & Light Co 79/05/10 1p

--7905130463 LER 79-011/01T-0 on 790426 small pin hole leaks found on
four canopy seal welds Caused by weld degradation NSSS
supplier examining this type failure
STARKEY, R B Carolina Power & Light Co 79/05/10 2pp

7905190010 Discusses 790413 operation of overpressure protection sys
while proceeding to cold shutdown Requests license amend re
overpressure protection Forwards 790413 RD & 771222 request
for license amend
BANKS, H R Carolina Power & Light Co 79/05/14 1p

--7905190012 RD on 790413 while proceeding to cold shutdown, overpressure
protection sys actuated Caused by operator error Event
details are being studied
* Carolina Power & Light Co 79/05/14 3pp

--7905190013 Request for license amend to revise Tech Specs re
overpressure protection W/ revised pages to implement
changes
UTLEY, E E Carolina Power & Light Co 77/12/22 11pp

7905190027 Forwards LER 79-008/03L-0
FURR, B J Carolina Power & Light Co 79/05/15 1p

--7905190030 LER 79-008/03L-0 on 790414 safety injection pump A failed to
start Cause unknown Pump, its breaker & timing relay were
checked electrically, no problems observed Pump started
locally & returned to svc
STARKEY, R B Carolina Power & Light Co 79/05/15 2pp

7905190086 Forwards LER 79-009/03L-0
BANKS, H R Carolina Power & Light Co 79/05/15 1p

--7905190088 LER 79-009/03L-0 on 790414 diesels failed to assume
electrical loadings in required 50-s Caused by timing
relays being set too long, due to instrument drift Timing
relays reset Permanent change being considered
STARKEY, R B Carolina Power & Light Co 79/05/15 2pp

7905220106 Forwards LER 79-010/03L-0
BANKS, H R Carolina Power & Light Co 79/05/16 1p

--7905220110 LER 79-010/03L-0 on 790415 engine driven fire pump rendered
inoperable due to fuel leak Caused by failure of solenoid
operated fuel shutoff valve to close fully, due to pieces of
slag between valve seating surfaces Slag removed
STARKEY, R B Carolina Power & Light Co, 79/05/16 2pp

7905290219 Forwards LER 79-012/01T-0
BANKS, H R Carolina Power & Light Co. 79/05/22 1p

--7905290230 LER 79-012/01T-0 on 790508 during normal operation, six of
ten supports of cold leg safety injection line failed,
allowing section of pipe to rust on floor, Caused by
waterhammer New supports to be installed.
STARKEY, R B Carolina Power & Light Co 79/05/22 3pp

DOCKET 50-262 BRIGHAM YOUNG UNIV RESEARCH REACTOR

J Insurance & indemnity information

7905130378 Forwards Amend 9 to Indemnity Agreement E-50, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

G. Adjudicatory correspondence

7905220024 Denies 781208 request to prohibit further installation of
spent fuel storage racks, pending hearing to determine if
license amend should be issued
DENTON, H R Office of Nuclear Reactor Regulation 79/04/24 1p

--7905220030 Director's decision per 10CFR2 206 request Proposed spent
fuel storage rack mods do not require license amend Request
by MN Pollution Control Agency to prohibit installation
racks is denied
BOYD, R S Office of Nuclear Reactor Regulation 79/04/24 17pp

--7905220033 Notice of issuance of Director's decision, per 10CFR2 206,
denying MN Pollution Control Agency's request for
suspension of fuel rack installation
BOYD, R S Office of Nuclear Reactor Regulation 79/04/24 2pp

I Financial information

7905130225 Forwards "Financial & Statistical Info" as suppl to "Annual
Financial Rept 1978"
BRUSVEN, A D Northern States Power Co 79/05/10 1p

--7905130231 "Financial & Statistical Info," submitted as suppl to
"Annual Financial Rept 1978"
* Northern States Power Co 79/03/31 21pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHINI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905160170 Forwards Amend 9 to Indemnity Agreement B-42, per 10CFR140
changes, re liability insurance increase from \$140 million to
\$160 million, effective 790501 Supporting documentation encl.
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905230394 Forwards Amend 9 to Indemnity Agreement B-42 & Amend 7 to
Indemnity Agreement B-60
JOHNSON, R G Northern States Power Co 79/05/18 5pp

7905290093 Forwards Endorsements 31 & 32, 43 & 44 to NELIA Policies
MF-174 & MF-31, respectively
JOHNSON, R G Northern States Power Co 79/05/23 5pp

P Operating license stage documents & correspondence

7905130575 Submits status repts on snubber springs, retainer clip
replacement & fire deluge extension, in response to TL
Harpster's request
WACHTER, L J Northern States Power Co 79/04/10 2pp

7905040415 Responds to TA Ippolito 790319 ltr requesting info re
radiation levels attributable to plant operation Forwards
plant environ radiation survey prepared by Environ Analysts.
MAYER, L O Northern States Power Co 79/04/20, 2pp.

7905090367 Comments on QE study of dc power source failure on ECCB
performance for operating BWR/3 & 4, dtd 781101. Rept is
applicable to facility
MAYER, L O Northern States Power Co 79/04/24 1p

7905290162 Notification of 790427 meeting w/Bechtel, Consumers Power
& Northern States Power Co in Bethesda, MD to discuss status
of review of nonconservative value used for elbow stiffness
in certain piping stress calculations.
JORDAN, E L. Division of Reactor Operations Inspections 79/04/24 1p

7905040604 Potential diesel generator turbocharger problem w/repeated
hot starts is being avoided Necessary mod will be available
in six months.
ELIASON, L R Northern States Power Co. 79/04/27 1p.

7905080413 Informs of review of OE's failure mode & effects analysis
proposal to modify reactor protection sys power supply Util
plans to modify supply protective circuitry per conceptual
design approved in NRC 790223 ltr, Submits Tech Spec changes
MAYER, L O. Northern States Power Co. 79/04/27, 1p

7905040011 Forwards request for license amend & \$4,000 fee
MAYER, L O Northern States Power Co. 79/03/01. 2pp.

DOCKETED ITEMS

47

--7903040022 Requests amend to DPR-22 to delete App B, Section 2.4, interim radioactive effluent Tech Specs & to revise App A Tech Specs
WACHTER, L J Northern States Power Co 79/03/01 71pp

7903040930 Forwards \$4,000 fee for 790301 license amend request re radioactive effluent Tech Spec changes
* Northern States Power Co 79/03/01 1p

7903070366 Forwards documents supporting proposed Tech Specs changes, submitted 790301, reflecting requirements re Offsite Dose Calculation Manual & process control program
HAYER, L O Northern States Power Co 79/03/02 1p

--7903070372 "Process Control Program for Waste Solidification"
* Northern States Power Co 79/03/01 22pp

--7903070380 "Offsite Dose Calculation Manual"
* Northern States Power Co 79/04/30 125pp

7903080411 Confirms 790302 telcon & 790314 meeting to discuss spent fuel storage racks. Suggests discussion be limited to six technical questions. Discussions will be open to public, but should not be considered as hearing
BTENBUVAAG, J Minnesota, State of 79/03/02 3pp

7903080402 Confirms 790302 telcon re possible meeting during week of 790314 w/Util, NRC & MN Pollution Control Agency to discuss spent fuel storage racks at facility
BTENBUVAAG, T Minnesota, State of 79/03/02 3pp

7903190032 Responds to V Stello 790312 ltr Submits schedule for implementation of Mark I containment long-term program
HAYER, L O Northern States Power Co 79/03/13 2pp

7903230315 Submits supplemental info to 78113 & 22 ltrs re RHR suction piping restraint mode Bachtel Corp used envelope response spectrum method, meeting FSAR requirements for RHR suction line
WACHTER, L J Northern States Power Co 79/03/17 1p

7903240360 Presents summary of results of suppression pool temp transient study, in response to NRC 771212 ltr
HAYER, L O Northern States Power Co 79/03/18 4pp

7903250424 Forwards tabulation of reactor operator & senior reactor operator retraining results for 1976-79, in response to IE Bulletin 79-10
WACHTER, L J Northern States Power Co 79/03/21 4pp

7903300200 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PIGOL piping analysis computer program from Jan-Oct 1969. Review & reanalysis included all work through Dec 1970.
PORTER, F L EDS Nuclear, Inc 79/03/21 9pp

--7903300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program. QF has no record of reanalysis for Cooper piping sys
BYEPHENS, P W General Electric Co, Nuclear Energy Products Div 79/01/24 10pp

A Inspection reports, IE Bulletins & correspondence

7903010262 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/03/23 1p

7903040040 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/03/26 1p

7903010174 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/8vc Air Sys Used as Source of Breathing Air"
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/03/28 1p

7903010410 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/03/30 1p

7903290336 Forwards IE Insp Rept 50-263/79-02 on 790319-0323 No noncompliance noted
HEISHMAN, R F Region 3, Chicago, Office of the Director, 79/04/10 2pp

--7903290346 IE Insp Rept 50-263/79-02 on 790319-0323 No noncompliance noted. Major areas inspected design change & mod program, plant operations, cleanliness, followup on license amend conditions, bulletins, circulars & LERs
HARPER, T L, KENNING, J E, WARNICK, R F Region 3 Chicago Office of the Director 79/04/09 7pp

7903290321 Inform of investigation resulting from IE Bulletin 79-03 No ASME SA-312, Type 304 or other welded pipe mfg by Youngstown Welding & Engineering Co is in use or planned for use
WACHTER, L J Northern States Power Co 79/04/12 1p

7903010399 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified during TMI Incident"
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/14 1p

7903040405 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/14 1p

7903040451 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/14 1p

7903040576 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/14 1p

7903030237 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/17 1p

7903080505 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/21 1p

7903040517 Responds to IE Bulletin 79-01 re stem-mounted limit switch Types similar to those described are used on safety-related valves inside containment. Qualification data for safety-related electrical equipment encl
WACHTER, L J Northern States Power Co 79/04/30 5pp

7903240681 Responds to IE Insp Rept 50-263/79-02 re info on high density fuel storage sys. Util will not use eight resized fuel storage tubes prior to safety evaluation
HAYER, L O Northern States Power Co 79/03/21 1p

R Periodic operating reports & related correspondence

7903090388 Forwards monthly operating rept for Apr 1979
HAYER, L O Northern States Power Co 79/03/07 1p

--7903090392 Monthly operating rept for Apr 1979
* Northern States Power Co 79/03/02 4pp

B Reportable occurrences, LERs & related correspondence

7903080424 Forwards LER 79-009/03L-0
HAYER, L O Northern States Power Co 79/03/04 1p

--7903080438 LER 79-009/03L-0 on 790404 steam leak found in 90 degree elbow in 1-inch core isolation cooling steam supply drain Pot condenser line. Caused by erosion due to high velocity steam from leaking valve. Hole patched. Repairs planned
HAMMER, S J Northern States Power Co 79/03/04 1p

7903160379 Forwards LER 79-010/01T-0
HAYER, L O Northern States Power Co 79/03/10 1p

--7903160381 LER 79-010/01T-0 on 790426 informed by General Motors of potential diesel generator turbocharger problem. Caused by inadequate design of lube oil sys. Had being developed
PEDERSON, D E Northern States Power Co 79/03/10 1p

DOCKETED ITEMS

DOCKET 50-264 DOW CHEMICAL CO

J Insurance & indemnity information

7905160357 Forwards Amend 10 to Indemnity Agreement B-34, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905150359 Forwards executed Amend 10 to Indemnity Agreement B-34
COALWELL, T N Dow Chemical Co 79/05/09 2pp

DOCKET 50-265 GUAD-CITIES STATION, UNIT 2

F Security, medical, emergency & fire protection plans

7905160415 Forwards sections of fire protection SER which require further NRC review valve supervision, air breathing equipment & interior hose stations
HALL, R E Brookhaven National Laboratory 79/04/12 3pp

7905030366 Forwards modified physical security plan, Revision 5 Plan withheld (ref 10CFR2 790)
LEE, B Commonwealth Edison Co 79/04/26 1p

G Adjudicatory correspondence

7905250258 Notifies properly worded contention addressing contention of sabotage would be accepted into proceeding Contention 6, as admitted into Duke Power Co proceeding, encompasses aspects of revised Contention 11 presented by State of IL
GODDARD, R J Branch 2 79/04/06 2pp

J Insurance & indemnity information

7905100163 Endorsement 99 to MAELU Policy MF-22
GERAS, T Nuclear Energy Liability Insurance Association 79/03/27 1p

7905070497 Confirms increased liability limit to \$124,000,000 for policies MF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905140456 Forwards Amend 11 to Indemnity Agreement B-47 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp

P Operating license stage documents & correspondence

7905030067 Forwards notes on 790302, 15 & 22 conference telcons between NRC, consultants & util re bulletin "Potential Explosive Gas Mixtures Accumulations Associated w/BWR Offgas Sys Operations."
IPFOLITO, T A Operating Reactors Branch 3 79/04/16 4pp

7905080141 Responds to 790305 ltr criticizing application for approval of proposed license amend that would allow shipment of spent fuel between stations Provides info on upcoming hearing
IPFOLITO, T A Operating Reactors Branch 3 79/04/18 1p

--7905080131 Opposes application for approval of proposed license amend that would allow shipment of spent fuel between stations
HOHENBOKEN, P Affiliation Unknown 79/03/15 2pp

7905010526 Forwards response to NRC 781205 request for addl info re instrument setpoint changes
JANECEK, R F Commonwealth Edison Co 79/04/25 3pp

7905040482 Notifies of intention to develop safety analysis using existing computer codes Requests addl info
SOLBRIG, C W Commonwealth Edison Co 79/04/26 1p

7905190016 Forwards current schedule for implementation of Mark I containment long-term mode. Discusses constraints inhibiting shorter time frame completion, including sys load requirements & current fuel cycles
REED, C Commonwealth Edison Co 79/05/11 3pp

7905190097 Requests correction to error discovered in 780421 ltr re capacity of Nuclear Assurance Corp NAC-1 truck cask used in spent fuel transfer Subj truck cask has capacity of two BWR assemblies
JANECEK, R F Commonwealth Edison Co 79/05/11 1p

P Operating license stage documents & correspondence

7905250391 Forwards current licensing open items status list
REED, C Commonwealth Edison Co 79/05/18 11pp

Q. Inspection reports, IE Bulletins & correspondence

7905020421 Forwards response to IE Bulletin 79-12 & #1 ltr, "At-Risk Weld Matl in Reactor Pressure Vessel Welds"
REED, C Commonwealth Edison Co 79/03/22 10pp

7905010236 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/21 1p

7905030370 Forwards IE Info Notice 79-07, "Rupture of Radiant Heating Contaminated Sys w/BWR Air Sys Used as Source of Breathing Air"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/21 1p

7905010155 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/BWR Air Sys Used as Source of Breathing Air"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/21 1p

7905010384 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/21 1p

7905030013 Forwards IE Bulletin 79-06, "Review of Operational Events & Sys Misalignments Identified During TMI Incident"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/21 1p

7905250280 Responds to IE Bulletin 79-03 re welding defects in 4800 lb longitudinally welded pipe spools Plants inspected; no pipe found
REED, C Commonwealth Edison Co 79/04/12 2pp

7905010569 Forwards IE Bulletin 79-06A, "Review of Operational Events & Sys Misalignments Identified During TMI Incident"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/21 1p

7905040334 Forwards IE Bulletin 79-06B, "Review of Operational Events & Sys Misalignments Identified During TMI Incident"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/21 1p

7905040529 Forwards IE Bulletin 79-08, "Events Relevant to Building Water Power Reactors Identified During TMI Incident"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/21 1p

7905030206 Forwards IE Bulletin 79-09, "Failures of OL Type Air Circuit Breaker in Safety-Related Sys" License action required
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/21 1p

7905040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/21 1p

--790504015B IE Bulletin 79-05B, "Nuclear Incident at TMI Suppl" Supporting documentation encl
* Region 3, Chicago, Office of the Director 79/04/21 12pp

--7905040170 ACRS recommendations re 790328 incident at TMI Suppl re priority be placed on development of safety research on behavior of LWRs during anomalous transients
* ACRS - Advisory Committee on Reactor Safeguards 79/04/15 2pp.

DOCKETED ITEMS

49

--7905040201 Forwards ACRS recommendations re TMI incident, presented on 790417
 FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards
 79/04/18 1p

--7905040221 In response to NRC 790418 ltr, states all ACRS 790417 recommendations apply to all PHRs, but were not intended to require immediate changes. Plant mods should be made after study of effects on overall safety. TMI excluded
 CARBON, M X ACRS - Advisory Committee on Reactor Safeguards
 79/04/20 2pp

7905240633 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping Reanalysis indicates method of intramodal combination has little effect on pipe stresses & equipment support loads
 REED, C Commonwealth Edison Co 79/04/24 4pp

7905130148 Forwards responses to IE Bulletin 79-06A, Revision 1, re BWR events identified during TMI-2. Util has formed task force to review BWR events & recommend corrective actions as required
 REED, C Commonwealth Edison Co 79/04/27 22pp

7905300242 Responds to IE Bulletin 79-04 No 3, 4 or 6-inch Velan swing check valves are in use at Dresden or Quad-Cities. Review of Zion has identified use of valves in some piping systems but review is incomplete. Will report later
 REED, C Commonwealth Edison Co 79/05/01 2pp

7905140488 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase"
 KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/02 1p

R Periodic operating reports & related correspondence

7905170250 Forwards monthly operating report for Apr 1979
 KALIVIANAKIS, N Commonwealth Edison Co 79/05/17 1p

--7905170260 Monthly operating report for Apr 1979
 HANNUM, D Commonwealth Edison Co 79/05/17 28pp

S Reportable occurrences, LERs & related correspondence

7905090389 Informs that release rate of radioiodine & radioactive particulate matter w/half-lives greater than eight days was 2.22 times higher than Tech Spec design objective for first quarter 1979. Caused by steam leaks & "spiking"
 KALIVIANAKIS, N Commonwealth Edison Co 79/04/30 2pp

7905240678 Forwards LER 79-004/03L-0
 KALIVIANAKIS, N Commonwealth Edison Co 79/04/30 1p

--7905240687 LER 79-004/03L-0 on 790211 while in cold shutdown, suction isolation valve MD 2-1001-50 failed to close from control room. Caused by stuck auxiliary contact on valve motor control circuit breaker. Contact cleaned & proved operable
 VAHRENWALD, J Commonwealth Edison Co 79/04/30 2pp

7905240702 Forwards LER 79-007/03L-0
 KALIVIANAKIS, N Commonwealth Edison Co 79/05/02 1p

--7905240707 LER 79-007/03L-0 on 790409 small leak discovered at weld edge in transition weld. Cause unknown. Leaks filled w/weld metal & penetrant tested to verify removal of indications
 TIEY, G Commonwealth Edison Co 79/05/02 3pp

7905240691 Forwards LER 79-008/03L-0
 KALIVIANAKIS, N Commonwealth Edison Co 79/05/04 1p

--7905240699 LER 79-008/03L-0 on 790409 suppression chamber level determined to be below Tech Spec min. Caused by instrument setpoint drift. Level indicator recalibrated & water added to suppression pool
 SWALES, J Commonwealth Edison Co 79/05/04 3pp

DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

7905300466 Submits proposed mods to fire protection plan as set forth in SER. Recommends fire hydrant inspection & supervision of valves controlling fire water supply
 HALL, R E Brookhaven National Laboratory 79/04/27 3pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
 QUATTROCHINI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
 ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905140431 Forwards Amend 11 to Indemnity Agreement B-41 per 10CFR140 changes re increase in liability insurance from \$140 million to \$160 million effective 790501. Supporting documentation enclosed
 SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp

7905230463 Forwards executed Amend 11 to Indemnity Agreement B-41 per NRC 790501 request
 DUNDAS, W J Wisconsin Electric Power Co 79/05/17 3pp

P Operating license stage documents & correspondence

7905140513 Forwards Amends 35 & 41 to Licenses DPR-24 & DPR-27, respectively, safety evaluation, EIA & notice of issuance & availability
 SCHWENCER, A Operating Reactors Branch 1 79/04/04 2pp

--7905140520 Amends 35 & 41 to Licenses DPR-24 & DPR-27, respectively authorizing installation & use of modified spent fuel storage racks in spent fuel pool, which increases capacity for storage from 331 assemblies to 1,502 assemblies
 ZIEHANN, D L Assistant Director for Systems & Projects 79/04/04 24pp

--7905140526 Safety evaluation supporting Amends 35 & 41 to Licenses DPR-24 & DPR-27, respectively
 * Office of Nuclear Reactor Regulation 79/04/04 16pp

--7905140529 EIA of Amends 35 & 41 to Licenses DPR-24 & DPR-27, respectively
 * Office of Nuclear Reactor Regulation 79/04/04 33pp

--7905140533 Notice of issuance & availability of Amends 35 & 41 to Licenses DPR-24 & DPR-27, respectively
 SCHWENCER, A Operating Reactors Branch 1 79/04/04 3pp

7905090065 Forwards Amend 36 to License DPR-24, safety evaluation & notice of issuance & availability
 SCHWENCER, A Operating Reactors Branch 1 79/04/06 2pp

--7905090068 Amend 36 to License DPR-24, extending reactor coolant system pressure-temp. heatup & cooldown curves from 7 to 11 effective full power years
 SCHWENCER, A Operating Reactors Branch 1 79/04/06 5pp

--7905090071 Safety evaluation supporting Amend 36 to License DPR-24
 * Office of Nuclear Reactor Regulation 79/04/06 3pp

--7905090076 Notice of issuance & availability of Amend 36 to License DPR-24
 SCHWENCER, A Operating Reactors Branch 1 79/04/06

7905100439 Forwards Amends 37 & 42 to Licenses DPR-24 & DPR-27, respectively & notice of issuance & availability. Security plan evaluation withheld (ref 10CFR2.7903).
 SCHWENCER, A Operating Reactors Branch 1 79/04/13

--7905100442 Amends 37 & 42 to Licenses DPR-24 & DPR-27, respectively implementing provisions of NRC-approved physical security plan
 SCHWENCER, A Operating Reactors Branch 1 79/04/13

--7905100446 Notice of issuance & availability of Amends 37 to Licenses DPR-24 & DPR-27, respectively
 SCHWENCER, A Operating Reactors Branch 1 79/04/13

7905130071 Forwards info in response to 790321 request re plant shutdowns.
 DENTON, H R Office of Nuclear Reactor Regulation 79/04

DOCKETED ITEMS

7905020271 Request amends to Licenses DPR-24 & DPR-27, changing Tech Specs re initiation instrument setting limits for engineered safety features Forwards Class III amend fee BURSTEIN, S Wisconsin Electric Power Co 79/04/27 7pp

7905240831 Responds to IE Bulletin 79-06A, Item 3 re TMI errors Pressurizer low level setpoint bistable returned to untripped position until logic change requested in 790427 license amend is implemented BURSTEIN, S Wisconsin Electric Power Co 79/04/30 2pp

7905150202 Forwards addl info re reactor vessel weld & surveillance weld metals BURSTEIN, S Wisconsin Electric Power Co 79/05/04 5pp

7905150448 Forwards addl info re Tech Spec Change Request 62, permitting safety injection actuation circuitry mod to two out of three pressurizer low pressure logic Requests approval by 790511, to permit mods on 790512-13 & 790519-20 BURSTEIN, S Wisconsin Electric Power Co 79/05/07 3pp

7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970 PORTER, F L EDS Nuclear, Inc 79/05/21 9pp

--7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program OE has no record of reanalysis for Cooper piping sys STEPHENS, P W General Electric Co, Nuclear Energy Products Div 79/01/24 18pp

7905310359 Submits formal responses to 790510 questionnaire re pressurizer heater, loss of feedwater event & steam generator BURSTEIN, S Wisconsin Electric Power Co 79/05/22 8pp

0 Inspection reports, IE Bulletins & correspondence

7905010142 Forwards IE Insp Repts 50-246/79-04 & 50-301/79-03 on 790220-23 & notice of violation DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/03/22 2pp

--7905010151 Notice of violation from insp on 790220-23 * Region 3, Chicago, Office of the Director 79/03/19 1p

--7905010160 IE Insp Repts 50-246/79-04 & 50-301/79-03 on 790220-23 Noncompliance noted failure to provide 7-day holdup of radioactive gas before release GREGER, L R, KIATT, J W Region 3, Chicago, Office of the Director FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/03/19 10pp

7905010270 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" KEPLER, J O Region 3, Chicago, Office of the Director 79/03/23 1p

7905040060 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks" KEPLER, J O Region 3, Chicago, Office of the Director 79/03/26 1p

7905010181 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air" KEPLER, J O Region 3, Chicago, Office of the Director 79/03/28 1p

7905010417 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin" KEPLER, J O Region 3, Chicago, Office of the Director 79/03/30 1p

7905030062 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" Licensee action required KEPLER, J O Region 3, Chicago, Office of the Director 79/04/11 1p

7905010413 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" Licensee action required KEPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040431 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" KEPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040438 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required KEPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040598 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident" KEPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905030253 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required KEPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905290075 Responds to IE Bulletin 79-06A Expresses concern re emergency operating procedures for reactor coolant pump & requirement for immediate tripping of low level bistables BURSTEIN, S Wisconsin Electric Power Co 79/04/19 3pp

7905080515 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl" KEPLER, J O Region 3, Chicago, Office of the Director 79/04/12 1p

7905240519 Responds to IE Bulletin 79-07 re computer program used in seismic stress analysis of safety-related piping sys No computer codes used which utilized algebraic summation techniques BURSTEIN, S Wisconsin Electric Power Co 79/04/25 2pp

7905240303 Responds to IE Bulletin 79-03 re possibility of longitudinal weld defects in ASME SA-312 Type 304 stainless steel pipe spools Review of pipe documentation records indicates no use of such tubing BURSTEIN, S Wisconsin Electric Power Co 79/04/26 2pp

7905300316 Responds to IE Bulletin 79-06A & 79-06A, Revision 1 Has established task force to facilitate review & understanding of TMI incident & impact on facility BURSTEIN, S Wisconsin Electric Power Co 79/04/27 13pp

7905290284 Responds to IE Bulletin 79-09 re OE Type AK-2 circuit breakers Item not in use at plant BURSTEIN, S Wisconsin Electric Power Co 79/05/07 1p

R Periodic operating reports & related correspondence

7905140362 Forwards monthly operating rept for Apr 1979 BURSTEIN, S Wisconsin Electric Power Co 79/05/08 1p

--7905140365 Monthly operating rept for Apr 1979 * Wisconsin Electric Power Co 79/05/04 10pp

S Reportable occurrences, LERs & related correspondence

7905020310 Forwards LER 79-006/03L-0 BURSTEIN, S Wisconsin Electric Power Co 79/04/18 1p

--7905020318 LER 79-006/03L-0 on 790404 during biweekly test, recording heat tracing circuit of boric acid sys Circuit 47 found inoperable Caused by shorted heat tracing cable in circuit Cable replaced & circuit returned to operation BURSTEIN, S Wisconsin Electric Power Co 79/04/18 2pp

7905240611 Forwards LER 79-007/01T-0 BURSTEIN, S Wisconsin Electric Power Co 79/05/07 1p

--7905240627 LER 79-007/01T-0 on 790424: vendor issued bulletin re potential problem w/turbosupercharger bearing lubrication Administrative controls instituted, Mods to be made as soon as possible BURSTEIN, S Wisconsin Electric Power Co 79/05/07 3pp

DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 183, 185, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others QUATROCCHI, J American Nuclear Insurers 79/05/01 1p

DOCKETED ITEMS

51

- 7909070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,27,38,39,44,46,47,49,50,51,52,53,54,55,56, 57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87, 88,90,91,92,93,94,95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p
- 7905160176 Forwards Amend B to Indemnity Agreement B-50, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp
- 7905220354 Amend B to Indemnity Agreement B-50, changing amount of financial protection
SALTZMAN, J Antitrust & Indemnity Group 79/05/15 2pp
- P Operating license stage documents & correspondence
- 7905010179 Notification of 790502 meeting w/util in Bethesda, MD to discuss status of inservice insp program, primary sys valves, steam generators & agenda items
KUZMYCZ, G Advanced Reactors Branch 79/04/17 3pp
- 7905310160 Forwards Amend 20 to License DPR-34, safety evaluation & notice of issuance & availability
SPEIB, T P Advanced Reactors Branch 79/04/20 2pp
- 7905310171 Amend 20 to License DPR-34 to revise Tech Specs to install eight test fuel elements into reactor core at first refueling & to install graphite surveillance specimens into five bottom transition reflector elements
SPEIB, T P Advanced Reactors Branch 79/04/20 9pp
- 7905310180 Safety evaluation supporting Amend 20 to License DPR-34 * Office of Nuclear Reactor Regulation 79/04/20 22pp
- 7905310186 Notice of issuance & availability of Amend 20 to License DPR-34
SPEIB, T P Advanced Reactors Branch 79/04/20 1p
- 7905030321 Informs that util will not alter existing Tech Specs to accommodate STS format format of present Tech Specs is adequate & meets intent of proposed STS
FULLER, J K Public Service Co of Colorado 79/04/23 1p
- 7905300210 Describes proposed mods resulting from various analyses of 761123 power failure of steam/water two loop dump sys
SPEIB, T P Advanced Reactors Branch 79/05/04 3pp
- 7905250204 Responds to 790130 request for temporary alteration to scheduled refueling program in order to correlate planned refueling outage Mod acceptable
COLLINS, P F Operator Licensing Branch 79/05/07 2pp
- 7905160315 Submits outline describing special tests to be performed during startup & rise to power, per 790508 request
WAREMBOURG, D Public Service Co of Colorado 79/05/11 22pp
- 7905230025 Forwards list of outstanding ltrs & requests for Tech Spec changes Oversized encl available in Central Files only
WAREMBOURG, D Public Service Co of Colorado 79/05/14 4pp
- Q Inspection reports, IE Bulletins & correspondence
- 7905150086 Forwards IE Circular 79-04, "Loose Locking Nut on Limitorque Valve Operators"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/16 1p
- 7905010434 Forwards IE Bulletin 78-128, "Atypical Weld Matl in Reactor Pressure Vessel Welds" Licensee action required
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/19 1p
- 7905020446 Forwards IE Circular 79-05, "Moisture Leakage in Stranded Wire Conductors"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/20 1p
- 7905020279 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/23 1p
- 7905020411 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/26 1p
- 7905020431 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/28 1p
- 7905230464 Responds to IE Bulletin 78-128 Bulletin was sent to util by mistake & no response is required
WAREMBOURG, D Public Service Co of Colorado 79/03/28 1p
- 7905010354 Ack receipt of 790315 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-267/79-03
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/03/29 1p
- 7905010361 Responds to NRC 790221 ltr re violations noted in IE Insp Rept 50-267/79-03 Corrective actions Tech Specs requirements reviewed & emphasized w/personnel involved
MILLEN, C K Public Service Co of Colorado 79/03/15 2pp
- 7905100261 Forwards IE Insp Rept 50-267/79-05 on 790227-0302 No noncompliance noted
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/03/29 2pp
- 7905100266 IE Insp Rept 50-267/79-05 on 790227-0302 No noncompliance noted Major areas inspected radiation protection program & analytical measurement results
MURRAY, B, BROWN, G D Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/03/28 9pp
- 7905140143 Forwards IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Valan Engineering Corp" Licensee action required
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/30 1p
- 7905190051 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/30 1p
- 7905230637 Responds to IE Bulletin 79-03 Util has no intention of using stainless steel pipe mfg by Youngstown Welding & Engineering Co
FULLER, J K Public Service Co of Colorado 79/04/06 1p
- 7905040498 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TH1 Incident"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 1p
- 7905040627 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TH1 Incident"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 1p
- 7905070077 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 1p
- 7905090106 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at TH1"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/16 1p
- 7905030282 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/17 1p
- 7905080355 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1-Suppl."
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/21 1p
- 7905300222 Requests 30-day extension to respond to IE Bulletin 79-07
SMART, F E Public Service Co of Colorado 79/04/24 1p
- 7905150795 Ack receipt of 790406 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-267/79-04
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/26 1p

DOCKETED ITEMS

--7905100800 Responds to NRC 790315 ltr re violations noted in IE Insp Rept 50-267/79-04 Corrective actions supervisors informed that surveillance tests & other controlled work procedures must be reviewed before being signed off
MILLEN, C K Public Service Co of Colorado 79/04/06 1p

R Periodic operating reports & related correspondence

7905010907 Forwards monthly operating rept for Mar 1979
WAREMBOURG, D Public Service Co of Colorado 79/04/25 1p

--7905010514 Monthly operating rept for Mar 1979
GAHM, J W Public Service Co of Colorado 79/04/01 10pp

7905080435 Forwards monthly operating rept for Apr 1979
WAREMBOURG, D Public Service Co of Colorado 79/05/02 1p

--7905080457 Monthly operating rept for Apr 1979
GAHM, J W Public Service Co of Colorado 79/05/01 5pp

S Reportable occurrences, LERs & related correspondence

7905140288 Forwards LER 78-002/01Y-0
SWART, F E Public Service Co of Colorado 78/02/01 1p

--7905140294 LER 78-002/01Y-0 on 790118 data indicates temp of control rod drives in power operated relief valve top head penetrations greater than expected by analytical model
Surveillance frequency increased
HILLYARD, H W Public Service Co of Colorado 78/02/01 5pp

7905140319 Forwards LER 78-001/03L-0
SWART, F E Public Service Co of Colorado 78/02/14 1p

--7905140323 LER 78-001/03L-0 on 780115 at 90% thermal level, average core outlet temp exceeded 1,200 F, resulting in operation in degraded mode Caused by moisture ingress into primary coolant sys from steam generator tube leak Oxidants removed
HILLYARD, H W Public Service Co of Colorado 78/02/14 5pp

7905150110 Forwards PNO-79-67R & 79-77(NRR)
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/11 1p

--7905150111 PNO-79-77(NRR)
* Office of Nuclear Reactor Regulation 79/04/10 4pp

7905040115 Forwards PNO-79-67S
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/12 1p

7905150223 Forwards PNO-79-67T correction
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/13 1p

--7905150245 PNO-79-67T correction
* Office of Inspection & Enforcement 79/04/13 4pp

7905010535 Forwards PNO-79-67U, V & W
MADSEN, G L Region 4, Dallas, Office of the Director 79/04/16 1p

7905010548 Forwards PNO-79-67X & Y
MADSEN, G L Region 4, Dallas, Office of the Director 79/04/18 1p

7905010406 Forwards PNO-79-67AA, AB, AC & AD
MADSEN, G L Region 4, Dallas, Office of the Director 79/04/24 1p

7905040374 Forwards LER 79-010/03L-0
WAREMBOURG, D Public Service Co of Colorado 79/04/27 1p

--7905040376 LER 79-010/03L-0 on 790330 during routine surveillance of circular speed bistable trips, two high speed trip setpoints found higher than max acceptable speeds Caused by bistable instrument drift. Bistable adjusted.
GAHM, J W Public Service Co of Colorado 79/04/27 5pp

7905150102 Forwards PNO-79-67AF, AG, AH, AI & AJ re nuclear incident at TH1
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/04/30 1p

7905080544 Forwards LER 79-011/03L-0
WAREMBOURG, D Public Service Co of Colorado 79/05/01 1p

--7905080549 LER 79-011/03L-0 on 790402 during post-mod testing, discovered water pressure differential indicating switches inoperable Caused by failure of range adjustment mechanism due to normal wear New movement & terminal ends installed
GAHM, J W Public Service Co of Colorado 79/05/01 5pp

7905240428 Forwards PNO-79-67AK & AL
MADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/02 1p

7905160367 Forwards LER 79-012/03L-0
WAREMBOURG, D Public Service Co of Colorado 79/05/07 1p

--7905160371 LER 79-012/03L-0 on 790410 while flushing basin, effluent exceeded for xant Caused by large amount of sediment
GAHM, J W Public Service Co of Colorado 79/05/07 3pp

7905160372 Forwards LER 78-027/03X-4
WAREMBOURG, D Public Service Co of Colorado 79/05/07 1p

--7905160377 LER 78-027/03X-4 on 790319 five of nine helium circuit seal malfunction differential pressure switches tripped Caused by dirt accumulation in ITT Barton Model 289 pressure differential switches
GAHM, J W Public Service Co of Colorado 79/05/07 6pp

7905230393 Forwards LER 79-014/03L-0
WAREMBOURG, D Public Service Co of Colorado 79/05/16 1p

--7905230403 LER 79-014/03L-0 on 790419 w/reactor bldg sump properties, sampler inoperable, daily direct samples of sump effluent were not taken, nor was sampler operability verified daily Caused by improper personnel procedures
GAHM, J W Public Service Co of Colorado 79/05/16 4pp

DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

7905290090 Discusses 790213 submission of security plan for storage of spent fuel & 790216 telcon re requirement for security plan mods Initial plan is subj to withholding from public record of transmittal is required
ROUSE, L C Fuel Reprocess & Recycle Branch 79/03/27 1p

7905140283 Forwards emergency procedure EP/D/A/1800/4, "Loss of Residual Coolant," containing instructions for operator action for small breaks
PARKER, W O Duke Power Co 79/05/09 29pp

H General correspondence

7905230131 Urges careful review of staff rept before ordering shutdown of facility, since action could cause extensive power curtailments & higher fuel costs for 12 million customers in Carolina piedmont
HELMG, J Senate 79/04/26 1p

7905020254 Expresses gratitude for decision to close facility
THOMPSON, M W Affiliation Unknown 79/04/28 1p

J Insurance & indemnity information

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/11 1p

7905140438 Forwards Amend 13 to Indemnity Agreement B-44 per 10CFR110 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp

7905160361 Submits executed copy of Amend 13 to Indemnity Agreement B-44, reflecting changes in 10CFR140
PARKER, W O Duke Power Co 79/05/08 3pp

7905310348 Forwards replacement copy of Amend 8 to Indemnity Agreement B-44 in response to 790516 request W/copy of util 740412 transmittal ltr.
PARKER, W O Duke Power Co 79/05/22 3pp

DOCKETED ITEMS

53

P Operating license stage documents & correspondence

7905110129 Agrees to close block valve RC-66 until approval of wall thickness analysis for electromagnetic relief valve RC-66 is received. However, valve will be opened for reactor transients
THIES, A C Duke Power Co 73/10/05 2pp

7905110129 On 731217 pressurizer electromagnetic relief block valve RC-4 was opened while unit was in transient mode B&W & util have evaluated continued plant operation w/pressurizer spray valve inoperable & found it acceptable
THIES, A C Duke Power Co 73/12/19 1p

7905250014 Forwards Amends 69, 69 & 66 to Licenses DPR-3B, DPR-47 & DPR-55, respectively, EIA & notice of issuance & availability
REID, R W Operating Reactors Branch 4 79/03/02 3pp

--7905250018 Amends 69, 69 & 66 to Licenses DPR-3B, DPR-47 & DPR-55, respectively, which revises ETS by deleting aquatic surveillance program & special study programs
REID, R W Operating Reactors Branch 4 79/03/02 11pp

--7905250021 EIA supporting Amends 69, 69 & 66 to Licenses DPR-3B, DPR-47 & DPR-55, respectively
* Operating Reactors Branch 4 79/03/02 4pp

7905190155 Responds to R Mattson & D Ross concerning value of running natural circulation test on B&W reactor
TEDESCO, RL Assistant Director for Plant Systems 79/04/05 4pp

7905080130 Responds to 790329 submittal re radiological effluent Tech Spec, which omitted solid radwaste process control program. Requests omitted portion
REID, R W Operating Reactors Branch 4 79/04/18 2pp

7905010321 Forwards documentation, design info & projected implementation schedules re emergency feedwater sys, as committed in NRC 790425 meeting
PARKER, W O Duke Power Co 79/04/25 4pp

7905010390 Forwards addl info re Oic of Nuclear Reactor Regulation status rept. Requests addl dialogue w/NRC re control sys
LEE, W S Duke Power Co 79/04/25 1p

7905030371 Informs that util has conducted review of plant design & operation, including goal of improving reliability of normal feedwater sys & added assurance of emergency feedwater supply to steam generators. Design adequate
OWEN, W H Duke Power Co 79/04/25 2pp

7905040047 Corrects error in 790419 ltr to NRC Reported period of facility mode should be Jan-Dec 1979
PARKER, W O Duke Power Co 79/04/25 1p.

7905110068 Informs that small break analyses review is complete. Analyses are unacceptable & incomplete
ROBZTOCZY, Z R Analysis Branch 79/04/25 1p

--7905110074 Comments on draft rept received 790420 too lengthy, does not concentrate on important issues & has dozens of incorrect & misleading statements. Rept should be reorganized
ROBZTOCZY, Z R Analysis Branch 79/04/25 3pp

7905240982 Responds to 790320 ltr requesting advice on allowable time interval for submittal of repts to NRC
REID, R W Operating Reactors Branch 4 79/04/26 2pp

7905020283 Informs of util position on issuance of formal order re continued plant operation. Written issuance is undesirable as policy & legally unnecessary
LEE, W S Duke Power Co 79/04/29 1p

7905040352 Forwards response to 780329 request for addl info re proposed changes to hydraulic shock suppressor Tech Spec
PARKER, W O Duke Power Co 79/04/30 2pp

7905080433 Forwards proposed revision to Tech Specs covering reactor bldg hydrogen purge sys, penetration room ventilation sys, reactor bldg purge filters & spent fuel pool ventilation sys
PARKER, W O Duke Power Co 79/05/01 11pp

7905080566 Forwards proposed revision to Tech Specs, deleting Tech Spec 4 id which is no longer required
PARKER, W O Duke Power Co 79/05/01 4pp

7905080388 Responds to questions raised at 790501 meeting. Forwards addl info re proposed installation of high capacity storage racks. Info supplements 790202 & 790420 submittals.
PARKER, W O Duke Power Co 79/05/02 3pp

7905240466 Documents completion of 761001 proposal to delete Tech Specs re tendon, anchorage & liner plate surveillance programs. License fee not required
PARKER, W O Duke Power Co 79/05/02 1p

7905190104 Notifies of refund of fees, remitted 780705, for authority to transfer fuel between facility & Crystal River Unit 3. Refund will be sent when processed
MILLER, W O License Fee Management Branch 79/05/03 1p

7905140189 In response to NRC 790418 request, forwards proposed Tech Spec re plant solid radwaste process control program
PARKER, W O Duke Power Co 79/05/07 5pp

7905240231 Forwards status on improvements to emergency feedwater sys, per WO Parker 790425 ltr & WS Lee 790426 ltr
PARKER, W O Duke Power Co 79/05/07 100pp

7905190317 Clarifies 790507 conversation re ALARA program associated w/reracking of spent fuel pool
PARKER, W O Duke Power Co 79/05/08 2pp

7905140365 Lists drawings used for installation of automatic starting of interconnected emergency feedwater sys, which were sent to NRC on 790503
PARKER, W O Duke Power Co 79/05/09 1p

7905140268 Forwards "Emergency Feedwater Sys, Sys Concept & Analysis" Pump installation to be complete by 790825. Oversized drawing in Central Files
PARKER, W O Duke Power Co 79/05/10 9pp

7905160389 Forwards "B&W 177 Fuel Assembly Owners Group Asymmetric LOCA Loads Evaluation Program, Phase 2," dtd 790410. Supersedes program provided on 790111
PARKER, W O Duke Power Co 79/05/10 1p

--7905160390 "B&W 177 Fuel Assembly Owners Group Asymmetric LOCA Loads Evaluations Program, Phase 2"
* Duke Power Co 79/04/10 9pp

7905220270 Submits request for relief from requirement of ASME Boiler & Pressure Vessel Code, Section II, re impracticality of doing hydrostatic test on emergency feedwater header due to excessive leakage through boundary isolation valves
PARKER, W O Duke Power Co 79/05/11 7pp

7905220235 Forwards "Steam Generator Operating History"
PARKER, W O Duke Power Co 79/05/14 1p

--7905220239 "Steam Generator Operating History"
* Duke Power Co 79/05/14 30pp

7905230543 Forwards revised sys concept & analysis re addition of two motor-driven emergency feedwater pumps. Supersedes 790510 submittal w/oversized drawing
PARKER, W O Duke Power Co 79/05/17 10pp

7905240475 Responds to IE Bulletin 79-038 re TMI incident. Forwards proposed amend to Tech Specs, changing setpoints of pressurizer electromagnetic relief valve & reactor coolant sys high pressure trip
PARKER, W O Duke Power Co 79/05/21 11pp.

7905240478 Forwards design description for safety grade anticipatory reactor trip on turbine trip or loss of main feedwater. Mode will be installed for each refueling outage following NRC approval
PARKER, W O Duke Power Co 79/05/21 3pp.

7905300208 Forwards summary of EDB Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISDL piping analysis computer program from Jan-Oct 1969. Review & reanalysis included all work through Dec 1970
PORTER, F L EDB Nuclear, Inc 79/05/21 9pp

--7905300263 Forwards EDB Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program. GE has no record of reanalysis for Cooper piping sys
STEPHENS, P W General Electric Co, Nuclear Energy Products Div. 79/01/24 18pp

7905310211 Forwards proposed Tech Specs revision re limiting conditions for operation & surveillance requirements
PARKER, W O Duke Power Co. 79/05/23 8pp

DOCKETED ITEMS

G Inspection reports, IE Bulletins & correspondence

- 7905230492 Forwards IE Insp Repts 50-269/79-04, 50-270/79-04, & 50-287/79-04 on 790205-07 No noncompliance noted. LEHIS, R. L. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/12. 2pp
- 7905230503 IE Insp Repts 50-269/79-04, 50-270/79-04, 50-287/79-04 on 790205-07 No noncompliance noted. Major areas inspected: fire protection/prevention program, QA surveillance, fire insurance repts & administrative control procedures. BRADFORD, W. H.; TAYLOR, P. A.; KELLODD, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/05. 4pp
- 7905230503 IE Insp Repts 50-269/79-04, 50-270/79-04, 50-287/79-04 on 790205-07. No noncompliance noted. Major areas inspected: fire protection/prevention program, QA surveillance, fire insurance repts & administrative control procedures. BRADFORD, W. H. Region 2, Atlanta, Office of the Director 79/03/05. App
- 7905010177 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping". O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/23. 2pp
- 7905030307 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks". O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/26. 2pp
- 7905230272 Discusses B&W rept, "Records Investigation Rept Related to Off-Chemistry Welds in Hot Surveillance Specimens & Response to IE Bulletins 78-12 & 78-12A-Suppl." rept accurately represents data for reactor pressure vessels. PARKER, W. D. Duke Power Co. 79/03/27. 1p
- 7905010098 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Bys w/Bvc Air Bys Used as Source of Breathing Air". O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/28. 2pp
- 7905010350 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin". O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/30. 2pp.
- 7905230279 Responds to IE Bulletin 79-02 re longitudinal weld defects. No ASME SA-312, Type 304 piping or any other welding w/o filler metal piping mfg by Youngstown Welding is in use or planned for use. PARKER, W. D. Duke Power Co. 79/04/04. 1p
- 7905100298 Forwards responses to IE Bulletins 79-05 & 79-05A, "Nuclear Incident at TMI". PARKER, W. D. Duke Power Co. 79/04/10. 21pp
- 7905100299 Forwards Abnormal Occurrence Rept AD-287/75-07. PARKER, W. D. Duke Power Co. 75/06/27. 1p.
- 7905100301 AD-287/75-07 on 750613: excessive reactor coolant sys cooldown rate occurred. Caused by operator error & failure of power-actuated pressurizer relief valve 3RC-66 to close. * Duke Power Co. 75/06/27. 1p.
- 7905100303 Forwards addl info re AD-287/75-07 Corrective actions. shutdown procedures revised; relief valves will be examined & quench tank rupture disc replaced. PARKER, W. D. Duke Power Co. 75/08/08. 3pp.
- 7905020048 Ack receipt of 790326 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-03, 50-270/79-03 & 50-287/79-03. KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 79/04/12. 1p
- 7905020064 Responds to NRC 790306 ltr re violations noted in IE Insp Repts 50-269/79-03, 50-270/79-03 & 50-287/79-03 Corrective actions withheld (ref IOCFR2 7901). PARKER, W. D. Duke Power Co. 79/03/26. 1p.
- 7905020078 Forwards IE Insp Repts 50-269/79-03, 50-270/79-03 & 50-287/79-03 on 790205-06. Notice of violation withheld (ref IOCFR2 7901). KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 79/03/06. 2pp
- 7905020087 IE Insp Repts 50-269/79-03, 50-270/79-03 & 50-287/79-03 on 790205-06. Noncompliance noted: areas of testing/maint & detection aids. Details withheld (ref IOCFR2 7901). TOBIN, W. J. Region 2, Atlanta, Office of the Director. GILLESPIE, F. F. Region 2, Atlanta, Safeguards Branch. 79/03/06. 1p
- 7905100046 Responds to IE Bulletin 79-05A, Items 7, 8, 10 & 11 re TMI Incident. All manual valves which could defeat or compromise flow are locked open. PARKER, W. D. Duke Power Co. 79/04/13. 8pp
- 7905040176 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident". O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p
- 7905040263 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping". Licensee action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp
- 7905040381 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident". O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p
- 7905030160 Forwards IE Bulletin 79-09, "Failures of QC Type AK-2 Circuit Breaker in Safety-Related Bys". Licensee action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/17. 2pp
- 7905020429 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident". O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/18. 2pp
- 7905240452 Responds to IE Bulletin 79-05, Item 3, re TMI incident. Reactor protective sys high RCB pressure setpoint lowered to not greater than 2,300 psig. Pressurizer power operated relief valve raised nominally to 2,450 psig. PARKER, W. D. Duke Power Co. 79/04/21. 1p
- 7905240505 Forwards response to IE Bulletin 79-07 re computer program used for piping analysis. Algebraic summation methods were not used in piping analysis. PARKER, W. D. Duke Power Co. 79/04/24. 2pp
- 7905110264 Forwards 790505 response to IE Bulletin 79-05B, Items 1, 2, 4 & 6 re TMI incident. PARKER, W. D. Duke Power Co. 79/03/05. 1p.
- 7905110268 Responds to IE Bulletin 79-05B, Items 1, 2, 4 & 6. Emergency procedures for loss of reactor coolant flow, steam supply sys rupture, uncontrollable flooding of turbine bldg & loss of normal HPI makeup or letdown have been revised. PARKER, W. D. Duke Power Co. 79/05/05. 6pp.
- 7905300541 Forwards inservice insp program. PARKER, W. D. Duke Power Co. 79/05/15. 1p.
- 7905300550 Inservice insp program. * Duke Power Co. 79/05/15. 70pp
- 7905220351 Forwards description of post-TMI operator training. per 790515 discussions & IE Bulletin 79-05, 79-05A & B. Operating shifts have adequate knowledge to operate reactors in all modes. PARKER, W. D. Duke Power Co. 79/05/16. 4pp.
- R. Periodic operating reports & related correspondence
- 7905220358 Forwards monthly operating rept for Apr 1979. PARKER, W. D. Duke Power Co. 79/05/15. 1p.
- 7905220365 Monthly operating rept for Apr 1979. REAVIS, J. A. Duke Power Co. 79/05/15. 16pp
- 7905110017 RO 269/7827 on 781214 on 781213, reactor coolant temp became erratic. Feedwater problem resulted from operation of one or more feedwater valves. Power cords have been fitted. * Duke Power Co. 79/01/13. 2pp.
- 7905140373 Describes RO-269/79-10, which was to have been submitted 790413, re removal from svc of high pressure svc water pump. Caused by leakage from motor cooler. Cooler repaired & returned to svc. PARKER, W. D. Duke Power Co. 79/04/13. 1p
- 7905020327 Forwards LER 79-010/03L-0. PARKER, W. D. Duke Power Co. 79/04/27. 1p.

DOCKETED ITEMS

65

--7903040340 LER 79-010/03L-0 on 790315 & 28 redundant high pressure svc water pump A inoperable while pump B was out of svc to repair leakage from pump motor cooler Leak source repaired & replacement coolers ordered
THIBB, B Duke Power Co 79/04/27 3pp

7903201031 Forwards LER 79-012/03L-0
PARKER, W O Duke Power Co 79/05/18 1p

--7903201031 LER 79-012/03L-0 on 790419 during performance test, RB spray pump ID declared inoperable Caused by water leakage through pipe threads on short vent line on pump casing Vent line replaced & other RB spray pumps inspected
THIBB, B Duke Power Co 79/05/18 3pp

7903270101 Forwards LER 79-013/01T-0
PARKER, W O Duke Power Co 79/05/21 1p

--7903270101 LER 79-013/01T-0 on 790307 quadrant power tilt exceeded steady state limit w/o nuclear overpower trip setpoint being reduced Caused by difference in core inlet temp which occurred as result of conditions required for feedwater test
THIBB, B Duke Power Co 79/05/21 3pp

7903280423 Forwards LER 79-014/01T-0
PARKER, W O Duke Power Co 79/05/21 1p

--7903280423 LER 79-014/01T-0 on 790307 nuclear instrumentation power indications less than thermal power levels Caused by changes in core characteristics which accompany changes in power levels
THIBB, B Duke Power Co 79/05/21 3pp

DOCKET 50-240 (CONCEAL NUCLEAR STATION, UNIT 2

Security, medical, emergency & fire protection plans

7903290070 Discusses 790217 submission of security plan for storage of spent fuel & 790218 telcon re requirement for security plan made Initial plan is subj to withholding from public record of transmittal is required
HARRIS, C Fuel Reprocess & Recycle Branch 79/03/29 1p

7903402011 Forwards emergency procedure EP/D/A/1800/4, "Loss of Reactor Coolant," containing instructions for operator action for small breaks
PARKER, W O Duke Power Co 79/05/09 29pp

(General correspondence

7903403131 Urges careful review of staff rept before ordering shutdown of facility, since action could cause extensive power curtailments & higher fuel costs for 1.2 million customers in Carolina piedmont
KELLEY, J Senate. 79/04/26 1p

7903404254 Expresses gratitude for decision to close facility.
KIMMEL, M W Affiliation Unknown 79/04/28 1p

J Insurance & indemnity information

7903050502 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 30, 37, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

790340433B Forwards Amend 13 to Indemnity Agreement B-44 per 10CFR140 changes re increase in liability insurance from \$140 million to \$160 million, effective 790301. Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group. 79/05/01 6pp

790340761 Submits executed copy of Amend 13 to Indemnity Agreement B-44, reflecting changes in 10CFR140.
PARKER, W O Duke Power Co 79/05/08 3pp

7903310340 Forwards replacement copy of Amend B to Indemnity Agreement B-44 in response to 790316 request w/copy of util. Amend 12 transmittal ltr
PARKER, W O Duke Power Co 79/05/22 3pp

P Operating license stage documents & correspondence

7903110125 Agrees to close block valve RC-25 until approval of wa thickness analyses for electromagnetic relief valve RC-25 is received However, valve will be opened for reactor transients
THIBB, A C Duke Power Co 73/10/05 2pp

7903250014 Forwards Amends 69, 69 & 66 to Licenses DPR-55 & DPR-55, respectively. EIA & notice of issuance & availability
REID, R W Operating Reactors Branch 4 79/05/01 1p

--7903250018 Amends 69, 69 & 66 to Licenses DPR-33 & DPR-33, respectively, which revises EIS by deleting aquatic surveillance program & special study programs
REID, R W Operating Reactors Branch 4 79/05/01 11pp

--7903250021 EIA supporting Amends 69, 69 & 66 to Licenses DPR-33 & DPR-33, respectively
* Operating Reactors Branch 4 79/03/02 4pp

7903190135 Responds to R Mattson & D Ross concerning value of running natural circulation test on B&W reactor
TEDESCO, RL Assistant Director for Plant Systems 79/04/25 4p

7903080130 Responds to 790329 submittal re radiological effluent Term Spec, which omitted solid radwaste process control program Requests omitted portion
REID, R W Operating Reactors Branch 4 79/04/18 2pp

7903010321 Forwards documentation, design info & projected implementation schedules re emergency feedwater sys as committed in NRC 790425 meeting
PARKER, W O Duke Power Co 79/04/25 4pp

7903010350 Forwards addl info re Ofc of Nuclear Reactor Regulation status rept Requests addl dialogue w/NRC re control sys
LEE, W B Duke Power Co 79/04/25 1p

7903030371 Informs that util has conducted review of plant design & operation, including goal of improving reliability of normal feedwater sys & added assurance of emergency feedwater supply to steam generators Design adequate
OHEN, W H Duke Power Co 79/04/25 2pp

7903040047 Corrects error in 790419 ltr to NRC Reported period of facility modt should be Jan-Dec 1979
PARKER, W O Duke Power Co 79/04/25 1p

7903240782 Responds to 790320 ltr requesting advice on allowable time interval for submittal of repts to NRC
REID, R W Operating Reactors Branch 4 79/04/26 2pp

7903020283 Informs of util position on issuance of formal order re continued plant operation Written issuance is undesirable as policy & legally unnecessary
LEE, W B Duke Power Co 79/04/29 1p

7903040332 Forwards response to 780329 request for addl info re proposed changes to hydraulic shock suppressor Tech Spec
PARKER, W O Duke Power Co 79/04/30 2pp

7903080433 Forwards proposed revision to Tech Specs covering reactor bldg hydrogen purge sys, penetration room ventilation sys, reactor bldg purge filters & spent fuel pool ventilation sys
PARKER, W O Duke Power Co 79/05/01 11pp

7903080566 Forwards proposed revision to Tech Specs, deleting Term Spec 4.13 which is no longer required
PARKER, W O Duke Power Co 79/05/01 4pp

7903080388 Responds to questions raised at 790301 meeting Forwards addl info re proposed installation of high capacity storage racks Info supplements 790202 & 790420 submittals
PARKER, W O Duke Power Co 79/05/02 3pp

7903240466 Documents completion of 761001 proposal to delete Tech Specs re tandem anchorage & liner plate surveillance programs License fee not required.
PARKER, W O Duke Power Co 79/05/02 1p

DOCKETED ITEMS

7905140189 In response to NRC 790418 request, forwards proposed Tech Spec re plant solid radwaste process control program
PARKER, W O Duke Power Co 79/05/07 5pp

7905240231 Forwards status on improvements to emergency feedwater sys. per WD Parker 790423 ltr & WS Loe 790426 ltr
PARKER, W O Duke Power Co 79/05/07 100pp

7905150317 Clarifies 790507 conversation re ALARA program associated w/reracking of spent fuel pool
PARKER, W O Duke Power Co 79/05/08 2pp

7905140365 Lists drawings used for installation of automatic starting of interconnected emergency feedwater sys. which were sent to NRC on 790503
PARKER, W O Duke Power Co 79/05/09 1p

7905140268 Forwards "Emergency Feedwater Sys. Sys Concept & Analysis" Pump installation to be complete by 790829 Oversized drawing in Central Files
PARKER, W O Duke Power Co 79/05/10 9pp

7905140389 Forwards "B&W 177 Fuel Assembly Owners Group Asymmetric LOCA Loads Evaluation Program, Phase 2," dtd 790410 Supersedes program provided on 790111
PARKER, W O Duke Power Co 79/05/10 1p

--7905160390 "B&W 177 Fuel Assembly Owners Group Asymmetric LOCA Loads Evaluations Program, Phase 2"
* Duke Power Co 79/04/10 9pp

7905220270 Submits request for relief from requirement of ASME Boiler & Pressure Vessel Code, Section II, re impracticality of doing hydrostatic test on emergency feedwater header due to excessive leakage through boundary isolation valves
PARKER, W O Duke Power Co 79/05/11 7pp

7905220235 Forwards "Steam Generator Operating History"
PARKER, W O Duke Power Co 79/05/14 1p

--7905220239 "Steam Generator Operating History"
* Duke Power Co 79/05/14 30pp

7905230343 Forwards revised sys concept & analysis re addition of two motor-driven emergency feedwater pumps Supersedes 790310 submittal w/oversized drawing
PARKER, W O Duke Power Co, 79/05/17 10pp

7905240475 Responds to IE Bulletin 79-05B re TMI Incident Forwards proposed amend to Tech Specs, changing setpoints of pressurizer electromagnetic relief valve & reactor coolant sys high pressure trip
PARKER, W O Duke Power Co 79/05/21 11pp

7905240478 Forwards design description for safety grade anticipatory reactor trip on turbine trip or loss of main feedwater. Mods will be installed for each refueling outage following NRC approval
PARKER, W O Duke Power Co 79/05/21 5pp

7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of P180L piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970
PORTER, F L EDS Nuclear, Inc 79/05/21 9pp

--7905300263 Forwards EDS Nuclear, Inc list of BHRs & piping sys which could have been impacted by deficient computer program GE has no record of reanalysis for Cooper Piping sys
STEPHENS, P W General Electric Co, Nuclear Energy Products Div 79/01/24 18pp

7905310211 Forwards proposed Tech Specs revision re limiting conditions for operation & surveillance requirements
PARKER, W O Duke Power Co 79/05/25 8pp

s, IE Bulletins & correspondence

7905010177 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905030307 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tank"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/26 2pp

7905230272 Discusses B&W rept, "Records Investigation Rept Related to Off-Chemistry Welds in Matl Surveillance Specimens & Response to IE Bulletin 78-12 & 78-12A-Suppl," rept accurately represents data for reactor pressure vessels
PARKER, W O Duke Power Co 79/03/27 1p

7905010098 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/28 2pp

7905010350 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/30 2pp

7905230279 Responds to IE Bulletin 79-02 re longitudinal weld defects. No ASME SA-312, Type 304 piping or any other welding w/o filler metal piping mfg by Youngstown Welding is in use or planned for use.
PARKER, W O Duke Power Co 79/04/04 1p

7905100298 Forwards responses to IE Bulletins 79-05 & 79-05A, "Nuclear Incident at TMI"
PARKER, W O Duke Power Co 79/04/10 21pp

7905020048 Ack receipt of 790326 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-03, 50-270/79-03 & 50-287/79-03
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/04/12 1p

--7905020064 Responds to NRC 790306 ltr re violations noted in IE Insp Repts 50-269/79-03, 50-270/79-03 & 50-287/79-03 Corrective actions withheld (ref 10CFR2.790)
PARKER, W O Duke Power Co 79/03/26 1p

--7905020078 Forwards IE Insp Repts 50-269/79-03, 50-270/79-03 & 50-287/79-03 on 790205-06 Notice of violation withheld (ref 10CFR2.790)
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/04/05 2pp

--7905020087 IE Insp Repts 50-269/79-03, 50-270/79-03 & 50-287/79-03 on 790205-06 Noncompliance noted areas of testing/maint & deflection aids Details withheld (ref 10CFR2.790)
TOBIN, W J Region 2, Atlanta, Office of the Director GILLESPIE, F P Region 2, Atlanta, Safeguards Branch 79/03/1p

7905100046 Responds to IE Bulletin 79-05A, Items 7, 8, 10 & 11 re TMI Incident All manual valves which could defeat or compromise flow are locked open
PARKER, W O Duke Power Co 79/04/13 8pp

7905040176 Forwards IE Bulletin 79-06B, "Review of Operational Errors Sys Misalignments Identified During TMI Incident."
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905040263 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp

7905040381 Forwards IE Bulletin 79-08, "Events Relevant to Holding Water Power Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905030160 Forwards IE Bulletin 79-09, "Failures of GE Type AM-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp

7905020429 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp

DOCKETED ITEMS

57

7903240492 Responds to IC Bulletin 79-05, Item 3, re TH1 incident Reactor protective sys High RCS pressure setpoint lowered to not greater than 2,300 psig Pressurizer power operated relief valve raised nominally to 2,450 psig
PARKER, H O Duke Power Co 79/04/21 1p

7903240505 Forwards response to IE Bulletin 79-07 re computer program used for piping analysis Algebraic summation methods were not used in piping analysis
PARKER, H O Duke Power Co 79/04/24 2pp

790310264 Forwards 790505 response to IE Bulletin 79-05B, Items 1, 2, 4 & 6 re TH1 incident
PARKER, H O Duke Power Co 79/05/05 1p

--7905110268 Responds to IE Bulletin 79-05B, Items 1, 2, 4 & 6 Emergency procedures for loss of reactor coolant flow, steam supply sys rupture, uncontrollable flooding of turbine bldg & loss of normal MWI makeup or letdown have been revised
PARKER, H O Duke Power Co 79/05/05 6pp

7905100541 Forwards inservice insp program
PARKER, H O Duke Power Co. 79/05/15 1p

--7905100550 Inservice insp program
" Duke Power Co 79/05/15 75pp

7905229731 Forwards description of post-TH1 operator training, per 790515 discussions & IC Bulletin 79-05, 79-05A & B Operating shifts have adequate knowledge to operate reactors in all modes
PARKER, H O Duke Power Co 79/05/16 4pp

R Periodic operating reports & related correspondence

7905220358 Forwards monthly operating rept for Apr 1979
PARKER, H O Duke Power Co 79/05/15 1p

--7905220369 Monthly operating rept for Apr 1979
REAVILL, J A Duke Power Co 79/05/15 16pp

B Reportable occurrences, LERs & related correspondence

7905020121 Forwards LER 79-010/03L-0
PARKER, H O Duke Power Co 79/04/27 1p

--7905020140 LER 79-010/03L-0 on 790315 & 25 redundant high pressure svc water pump A inoperable while pump B was out of svc to repair leakage from pump motor cooler Leak source repaired & replacement coolers ordered
LEWIS, B R Duke Power Co 79/04/27 3pp

7905150574 Forwards LER 79-002/03L-0
PARKER, H O Duke Power Co 79/05/11 1p

--7905150543 LER 79-002/03L-0 on 790412 during monthly performance test, pressurizer sample valve ZRC-6 failed to close on actuation & closed on either torque limit

J Insurance & indemnity information

7905310261 Forwards GA Carlson ltr re Price-Anderson Act retrospective insurance premiums
BRUE, M L Green Mountain Power Corp 78/08/15 3pp

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 159, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 85, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D H Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905160215 Forwards Amend 9 to Indemnity Agreement B-47, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905150361 Forwards Amend 9 to Indemnity Agreement B-47 re increase in liability insurance effective 790501
CAREY, W H Vermont Yankee Nuclear Power Corp 79/05/11 3pp

P Operating license stage documents & correspondence

7905080239 Responds to 790429 ltr requesting 6-month delay in implementing 10CFR50.35 requirements Review continuing
GRIMES, B K Assistant Director for Engineers & Projects
79/04/11 2pp

7905080423 Supplements 790404 ltr re environ qualification of Class 1E equipment Limit switches will be replaced w/switches qualified for LOCA environ Conclusion in 790404 ltr remains valid
MOODY, D E Vermont Yankee Nuclear Power Corp 79/04/24 1p

7905290058 Responds to 790413 request re QA program Suggests revision number of YQAP-1-A not be designated
HEIDER, L H Yankee Atomic Electric Co 79/04/24 1p

7905070548 Forwards Revision 6 & Amend 1 to Revision 6 of operational QA program, as requested in 790410 ltr
OROCE, R H Yankee Atomic Electric Co 79/04/30 4pp

--7905070533 Informs that revisions to QA program are acceptable
HAASS, W P Quality Assurance Branch 79/04/10 17pp

7905100319 Responds to NRC 790312 ltr requesting schedule for completion of Mark 1 containment program structural mod
Major mod planned for completion before Dec 1980
OROCE, R H Vermont Yankee Nuclear Power Corp 79/05/04 3pp

7905160253 Forwards addl info re Tech Spec changes to average power ratio monitor gain adjustment
MANNIV, D E Vermont Yankee Nuclear Power Corp 79/05/09 2pp

DOCKETED ITEMS

Q Inspection reports, IE Bulletins & correspondence

7905110388 Forwards IE Insp Rept 50-271/79-04 on 790213-16 & 21-22
No noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 79/03/20 2pp

--7905110394 IE Insp Rept 50-271/79-04 on 790213-16 & 21-22 No
noncompliance noted Major areas inspected plant operations,
organization & administration, onsite review committee, LERs
& licensee action on previous findings
STETKA, T F, FOLEY, T Region 1, Philadelphia, Office of the
Director MCCABE, E C Region 1, Philadelphia, Reactor
Operations Nuclear Support Branch 79/03/19 14pp

7905010150 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/03/23 1p

7905010075 Forwards IE Info Notice 79-08, "Interconnection of
Contaminated Sys w/ Svc Air Sys Used as Source of Breathing
Air"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/03/28 1p

7905010326 Forwards IE Info Notice 79-09, "Spill of Radioactively
Contaminated Resin"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/03/30 1p

7905070693 Responds to IE Bulletin 79-03 re welding defects No further
action required since seam weld insp requirement is ASME
III Only plants fabricated under these rules are affected
MOODY, D E Vermont Yankee Nuclear Power Corp 79/03/30 1p

7905020113 Forwards IE Bulletin 79-06, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/11 1p

7905020308 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of
Safety-Related Piping" Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040111 Forwards IE Bulletin 79-06B, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040297 Forwards IE Bulletin 79-08, "Events Relevant to Boiling
Water Power Reactors Identified During TMI Incident"
Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905030111 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2
Circuit Breaker in Safety-Related Sys" Licensee action
required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/17 1p

7905020339 Forwards IE Bulletin 79-06A, Revision 1, "Review of
Operational Errors & Sys Misalignments Identified During TMI
Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/18 1p

7905010500 Submits second request for six month delay, until 800130, for
implementation of pump & valve testing portion of updated
inservice insp program
VANDENBURGH, D E Vermont Yankee Nuclear Power Corp 79/04/25 2pp

7905010506 Forwards Class III license amend fee for inservice insp
changes to Tech Specs Believes fee schedule is illegal
Submits fee under protest w/o waiving right to contest fee
validity
GRACE, R H Vermont Yankee Nuclear Power Corp 79/04/25 3pp

7905070455 Forwards proposed "Inservice Insp Program," w/ 18 sys flow
drawings
GRACE, R H Vermont Yankee Nuclear Power Corp 79/04/30 2pp

--7905070462 "Inservice Insp Program," exam schedule & sys flow drawings
FLONKAY, W, QUIROIR, D C, MOODY, T E Vermont Yankee Nuclear Power
Corp 79/04/30 38pp

7905290088 Submits addl info to 790427 response to IE Bulletin 79-07 re
seismic stress analyses of safety-related piping
GRACE, R H Vermont Yankee Nuclear Power Corp 79/05/04 2pp

R Periodic operating reports & related correspondence

7905010480 Forwards "Ecological Studies of CT River, Vernon, VT," Rept
VIII, 1978
VANDENBURGH, D Vermont Yankee Nuclear Power Corp 79/04/23 1p

--7905010482 "Ecological Studies of CT River, Vernon, VT," Rept VIII, 1978
* Vermont Yankee Nuclear Power Corp 79/04/25 188pp

7905070588 Forwards "Hydrothermal & Biological Studies, CT River, Vermon
VT, Phase V," Oct 1977-May 1978
MARK, D J Vermont Yankee Nuclear Power Corp. 79/05/01 1p

7905070592 "Hydrothermal & Biological Studies, CT River, Vernon, VT, Phase
V," Oct 1977-May 1978
* Vermont Yankee Nuclear Power Corp 79/03/31 100pp

7905150341 Forwards monthly operating rept for Apr 1979
MOODY, D E Vermont Yankee Nuclear Power Corp 79/05/12 1p

--7905150343 Monthly operating rept for Apr 1979
SJOEGREN, R M Vermont Yankee Nuclear Power Corp 79/05/12 4pp

S Reportable occurrences, LERs & related correspondence

7905080552 Forwards LER 79-011/03L-0
CONWAY, W F Vermont Yankee Nuclear Power Corp 79/05/03 1p

--7905080553 LER 79-011/03L-0 on 790403 spring plate of actuator was
binding on guide staffs Caused by rough surface on guide
shafts Surface smoothed & verified operable
CONWAY, W F Vermont Yankee Nuclear Power Corp 79/05/03 2pp

7905290037 Forwards LER 79-001/03L-1
CONWAY, W F Vermont Yankee Nuclear Power Corp 79/05/23 1p

--7905290040 LER 79-001/03L-1 on 790110 through wall leak near reactor
water cleanup sys suction piping noted. Caused by cracks in
weld neck due to intergranular stress corrosion Repairs
made & sys returned to svc
CONWAY, W F Vermont Yankee Nuclear Power Corp 79/05/23 2pp

DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

E NRC Safety Evaluation Report (SER), suppl & correspondence

7905250137 Forwards SER & EIA, w/o encl
SMITH, B H Branch 2 79/03/29 1p

Q Adjudicatory correspondence

7905170300 Forwards resolution of storage of spent fuel in Lower
Alloways Creek Township, NJ
MCDONOUGH, J A Pennsville, NJ 79/03/06 1p

--7905170302 Resolution opposing increase in spent fuel storage capacity
at plant in Lower Alloways Creek Township, NJ
SPARKS, D W, MCDONOUGH, J A Pennsville, NJ 79/03/01 2pp

7905230653 Answer of Intervenor Township of Lower Alloways Creek, NJ
seeking denial of licensee motion for summary disposition
Statement of matl facts, affidavit & Certificate of Svc encl
VALORE, C Lower Alloways Creek, NJ 79/03/12 9pp

7905230471 Forwards Amend 42 to F8AR, per 790315 prehearing conference
request
FRILING, R Public Service Electric & Gas Co of New Jersey
79/03/26 1p

7905230649 Discusses actions taken at 790315 prehearing conference
Possible settlement & consolidation of contentions,
identification of witnesses & denial of motion to
consolidate conferences discussed. Hearing schedule set.
MILHOLLIN, G L Atomic Safety and Licensing Board Panel 79/03/29
3pp

7905150180 Response in support of licensee's motion for summary
disposition Forwards response to licensee's statement of
facts Forwards licensee's memo in support of its motion
for summary disposition
SMITH, B H, MOORE, J E Branch 2 79/03/30 1p.

--7905150187 Responds to licensee's statement of matl facts, no genuine
issue to be heard
SMITH, B H, MOORE, J E Branch 2 79/03/30 14pp.

DOCKETED ITEMS

59

- 7905150192 Responds to licensee's memo in support of its 790227 motion for summary disposition Affidavits of JR Weeks, JM Donohew, TJ Carter, AL Tomlinson & GO Zech encl
BHITH, B H , MOORE, T F Branch 2 79/03/30 44pp
- 7905150196 "Corrosion of Metals in Spent Fuel Storage Pools"
WEEKS, J R Brookhaven National Laboratory EY-76-C-02-0016
BNL-NUREG-23021 77/07/31 20pp
- 7905150201 "Corrosion Considerations in Use of Boron in Spent Fuel Storage Pool Racks"
WEEKS, J R Brookhaven National Laboratory FIN A-3106
BNL-NUREG-23582 78/12/31 26pp
- 7905290102 Informs that listed documents have been requested from persons making limited appearances at special prehearing conference Requests that Legal Div make appropriate response
MILHOLLIN, G L Atomic Safety and Licensing Board Panel 79/03/30 1p
- 7905030020 NRC response to 790329 order following prehearing conference Intends to introduce into evidence SER & EIA re mod of spent fuel pool Supporting documentation & Certificate of Bvc encl
BHITH, B H Branch 2 79/04/02 27pp
- 7905220030 Forwards Figure 7-2, fuel handling area Drawing is to be attached to FBAR section filed on 790402 as part of NRC response to 790329 order following prehearing conference
MOORE, J C Branch 2 79/04/03 2pp
- 7905110407 Submits testimony re Contention 1 Licensee gave inadequate consideration to alternatives to expansion of onsite spent fuel storage Certificate of Bvc & professional qualifications encl
LUCHAK, Q Affiliation Unknown 79/04/10 12pp
- 7905250235 Testimony of Q Luchak Licensee has given inadequate consideration to alternatives to onsite expansion of fuel storage capacity Certificate of Bvc & professional qualifications encl
LUCHAK, Q Lower Alloways Creek, NJ 79/04/10 12pp
- 7905240709 Forwards proposed direct testimony of RM Crockett, witness for Colemans join objection of Township of Lower Alloways Creek, NJ to prehearing conference directive re cross-examination Certificate of Bvc encl
VANNIEB, D C New Jersey, State of. 79/04/11 13pp
- 7905230525 Forwards application by Township of Lower Alloways Creek, NJ for stay of 790329 prehearing conference order re cross-examination
VALORE, C Valore, C 79/04/12 1p
- 7905230532 Application by Township of Lower Alloways Creek, NJ for stay of 790329 prehearing conference order re cross-examination Supporting documentation & Certificate of Bvc encl
VALORE, C Valore, C. 79/04/12 11pp
- 7905150001 Forwards form of order, per 790413 conference call
VALORE, C Valore, C 79/04/16 3pp
- 7905150681 Requests NRC provide statement responding to questions posed at 790315-16 special prehearing conference Topics include error in computer codes, effect of low level radiation & K-eff calculation.
MILHOLLIN, G L Atomic Safety and Licensing Board Panel 79/04/17 2pp
- 7905150068 Objects to testimony of intervenor Township of Lower Alloways Creek, NJ & to proposed testimony offered by intervenors Colemans re Contentions 2 & 6 Certificate of Bvc encl
BHITH, B H Branch 2. 79/04/23. 7pp
- 7905150672 Pretrial order of 790329 is amended to provide that on 790425, parties seeking to conduct cross-examination shall file outline of areas of cross-examination to be pursued, w/estimate of required time
MILHOLLIN, G L Atomic Safety and Licensing Board Panel 79/04/24 2pp
- 7905240094 Forwards nonproprietary version of Exxon's XN-NB-TP-009, "Fuel Storage Racks Corrosion Program," to minimize need for "in camera" session W/o encl
WETTERHAHN, M J Conner, Moore & Corber 79/04/24 1p
- 7905240954 Outline of cross-examination of witnesses to be conducted at ABLB 790502 hearing. Reserves right to cross-examine on TMI issues raised in ABLB 790418 order Certificate of Bvc encl
DEONAN, J J , HLUCHAK, R M New Jersey, State of 79/04/25 4pp
- 7905250024 Outline of proposed cross-examination of evidence submitted by NRC
VALORE, C Lower Alloways Creek, NJ 79/04/25 7pp
- 7905250028 Outline of proposed cross-examination of evidence submitted by util Certificate of Bvc encl
VALORE, C Lower Alloways Creek, NJ 79/04/25 4pp
- 7905230540 Retains Contention 1 & dismisses Contention 3 of intervenor Township of Lower Alloways Creek, NJ Retains Contentions 2 & 6 but dismisses Contention 9 & 13 of intervenor Coleman W/dissenting opinion of L Kornblith
MILHOLLIN, G L , KORNBLITH, L Atomic Safety and Licensing Board Panel 79/04/30 36pp
- H General correspondence
- 7905070450 Ack receipt of 790216 resolution opposing storage of high level radioactive wastes in township Objections should be made at ASLB hearing Expansion of storage pools is unlikely No independent facilities are planned
DENTON, H R Office of Nuclear Reactor Regulation 79/03/29 5pp
- 7905140291 Responds to 790312 ltr re resolution adopted on 790216 by Township of Lower Alloways Creek, NJ Resolution opposes storage of high level wastes Forwards NRC response
OOSICK, L V Office of the Executive Director for Operations 79/04/11 1p
- 7905070551 Notifies of change of address for DG Brinderbaugh & RB Hubbard to 1723 Hamilton Ave, Suite K, San Jose, CA 95125
COOPER, K F MHB Technical Associates 79/04/25 1p
- I Financial information
- 7905070647 Forwards "Annual Financial Rept, 1978" for Public Service Electric & Gas Co, Atlantic City Electric Co, Delaware Power & Light Co & Philadelphia Electric Co
FRYLING, R Public Service Electric & Gas Co of New Jersey 79/04/30 162pp
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHILI, J American Nuclear Insurers 79/05/01 1p
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p
- 7905150367 Forwards Amend 6 to Indemnity Agreement B-74, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp
- 7905290089 Forwards Endorsements 33, 34 & 35 to ANI Policy NF-230
CORREA, C Marsh & McLendon, M & M Nuclear Consultants, Inc Div 79/05/22 4pp
- P Operating license stage documents & correspondence
- 7905020490 Discusses 790315 telcon w/R Sero of Westinghouse re incorrect weights for Velan Model C658 6-inch check valves used in safety injection sys
SCHWENGER, A Operating Reactors Branch 1 79/04/02 1p
- 7905170263 Submits request for amend of Tech Specs re removal of coincident pressurizer pressure/level logic for safeguards actuation W/Class III amend fee
LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey 79/05/07 1p
- 7905150280 Submits up-to-date summary of all proposed ETS changes, suggested replacement pages & supporting justifications, to assist preparation of amend to ETS, App B
LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey 79/05/09 73pp
- 7905220349 Responds to Westinghouse 790328 notification of potential single dropped rod events which could lead to DNB ratios lower than reported Units are four loop plants & do not have potential problem
MITTL, R L Public Service Electric & Gas Co of New Jersey 79/05/15 2pp

DOCKETED ITEMS

Q Inspection reports, IE Bulletins & correspondence

790501013B Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/23 1p

7905010067 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air" GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/28 1p

7905010320 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin" GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/30 1p

7905290065 Responds to IE Bulletin 79-03 No safety-related pipe assemblies from Youngstown Welding & Engineering Co are used SCHNEIDER, F W Public Service Electric & Gas Co of New Jersey 79/04/04 2pp

7905020095 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" Licensee action required GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/11 1p

7905070133 Act receipt of 790323 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-272/79-08 BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/11 1p

--7905070140 Responds to NRC 790305 ltr re violation noted in IE Insp Rept 50-272/79-08 Corrective actions operators restructured, reactor engineering manual revised & surveillance procedures revised SCHNEIDER, F W Public Service Electric & Gas Co of New Jersey 79/03/23 3pp

--7905070145 Forwards IE Insp Rept 50-272/79-08 on 790213-16 & notice of violation BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/03 2pp

--7905070149 Notice of violation from insp on 790213-16 " Region 1, Philadelphia, Office of the Director 79/03/05 1p

--7905070158 IE Insp Rept 50-272/79-08 on 790213-16 Noncompliance noted surveillance procedures for determination of axial flux not performed as required CONTE, R J, BLUMBERG, N Region 1, Philadelphia, Office of the Director KISTER, H B Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/02 12pp

7905040095 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905040273 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident" GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905140103 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905030098 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/17 1p

7905020317 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/18 1p

7905250072 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Provides results of Westinghouse analysis of reactor coolant loop & large bore Class I piping. SCHNEIDER, F W Public Service Electric & Gas Co of New Jersey. 79/03/03. 27pp

R Periodic operating reports & related correspondence

7905080462 Forwards Mar 1979 operating rept for industrial waste treatment plant MIDURA, H J Public Service Electric & Gas Co of New Jersey 79/04/05 2pp

7905080466 Forwards Mar 1979 wastewater treatment rept for sewage treatment plant MIDURA, H J Public Service Electric & Gas Co of New Jersey 79/04/12 2pp

7905080489 Forwards rept of subsurface water diversion & chloride analysis of well water for quarter ending 790331 MIDURA, H J Public Service Electric & Gas Co of New Jersey 79/04/16 3pp

7905030360 Forwards "Impingement Monitoring Program Rept 24," for Mar 1979 LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey 79/04/20 73pp

7905080421 Forwards Natl Pollution Discharge Elimination Sys discharge monitoring rept for Mar 1979 MIDURA, H J Public Service Electric & Gas Co of New Jersey 79/04/20 13pp

7905300417 Forwards "Operating Rept for Apr 1979 for Industrial Waste Treatment Plant" MIDURA, H J Public Service Electric & Gas Co of New Jersey 79/05/08 1p

--7905300421 "Operating Rept for Apr 1979 for Industrial Waste Treatment Plant" MIDURA, H J Public Service Electric & Gas Co of New Jersey 79/04/30 1p

7905150295 Forwards monthly operating rept for Apr 1979 MIDURA, H J Public Service Electric & Gas Co of New Jersey 79/05/09 1p

--7905150299 Monthly operating rept for Apr 1979 MILLER, L K Public Service Electric & Gas Co of New Jersey 79/05/09 13pp

7905300431 Forwards Apr 1979 wastewater treatment rept for sewage treatment plant MIDURA, H J Public Service Electric & Gas Co of New Jersey 79/05/10 2pp

7905300363 Forwards discharge monitoring repts for Apr 1979 MIDURA, H J Public Service Electric & Gas Co of New Jersey 79/05/22 13pp

B Reportable occurrences, LERs & related correspondence

7905290070 Confirms 790405 telcon re RO 79-35/01P w/high pressure fire pump out of svc for planned maint, fire suppression water header pressure dropped below 135 psig & fire pump 2 did not start at once MIDURA, H J Public Service Electric & Gas Co of New Jersey 79/04/05 1p

7905290495 RO-79-36/01T re apparent design deficiency associated w/seismic qualifications for 4 kV vital bus switchgear differential relay protection Currently evaluating solution involving design change MIDURA, H J Public Service Electric & Gas Co of New Jersey 79/04/11 1p

7905010525 Forwards LER 79-036/01T-0 LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey 79/04/24 1p

--7905010555 LER 79-036/01T-0 on 790410 util notified of design deficiency re differential relays not meeting seismic design qualifications. Problem exists in both units Relays will be disconnected until design change implemented KAPPLE, A W Public Service Electric & Gas Co of New Jersey 79/04/24 3pp

7905250441 Confirms RO 79-41/01P on 790425 re missing zotec tube plugs Subsequent investigations have not located missing plug Assumes plug was lost in steam generator 12 hot leg reactor coolant piping. MIDURA, H J Public Service Electric & Gas Co. of New Jersey 79/04/26 1p

DOCKETED ITEMS

61

7905040538 Forwards LER 79-031/03L-0
LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey
79/04/27 1p

--7905040541 LER 79-031/03L-0 on 790329 100 elevation containment
personnel air lock failed to pass leak rate test Caused by
split inner door seal snagged by some object passing through
door Seal replaced
KAPPLE, A W Public Service Electric & Gas Co of New Jersey
79/04/27 2pp

7905040370 Forwards LER 79-032/03L-0
LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey
79/04/30 1p

--7905040371 LER 79-032/03L-0 on 790330 during normal operation, auxiliary
typewriter started printing meaningless messages Caused by
failed solid state component circuit board in typewriter
logic control cabinet Component board replaced
KAPPLE, A W Public Service Electric & Gas Co of New Jersey
79/04/30, 3pp.

7905080485 Forwards LER 79-034/03L-0
LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey
79/05/01 1p

--7905080525 LER 79-034/03L-0 on 790331 Loop 12 steamline pressure 100
psig less than loop 11 Caused by failed comparator module
Comparator calibr & channel setpoints verified
KAPPLE, A W Public Service Electric & Gas Co of New Jersey
79/05/01 3pp

7905140227 Forwards LER 79-011/01X-2
LIBRIZZI, R P Public Service Electric & Gas Co of New Jersey
79/05/02 1p

- 7905140230 LER 79-011/01X-2 on 790116 RMS channel which had alarmed &
cleared had been reset at control console but not at RMS
panel Caused by procedure inadequacy Procedure changed
initiated to clarify functions
KAPPLE, A W Public Service Electric & Gas Co of New Jersey
79/05/29 3pp

7905150444 Forwards LER 79-041/01T-0,
LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey
79/05/09 1p

--7905150446 LER 79-041/01T-0 on 790425 loss of eddy current template
plug assembly inside reactor coolant sys Caused by error of
contractor maint supervisor Supervisor will be properly
instructed
KAPPLE, A W Public Service Electric & Gas Co of New Jersey
79/05/09 3pp

7905150462 forwards LER 79-037/03L-0
LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey
79/05/11 1p

--7905150464 LER 79-037/03L on 790416 source range nuclear
instrumentation channel N-32 indication became erratic
Caused by disconnected shield on source range high voltage
drawer connector Drawer connection reworked
KAPPLE, A W Public Service Electric & Gas Co. of New Jersey
79/05/11 3pp

7905220127 Forwards LER 79-038/03L-0
LIBRIZZI, F P Public Service Electric & Gas Co of New Jersey
79/05/15 1p

--7905220132 LER 79-038/03L-0 on 790417 ground fault on station power
Transformer 21 resulted in loss of Transformers 1, 11 & 21
Caused by failed cable in pothead supplying transformer
Failed cable & pothead replaced
KAPPLE, A W Public Service Electric & Gas Co of New Jersey
79/05/15 3pp

7905220308 Forwards LER 79-039/03L-0
LIBRIZZI, R P Public Service Electric & Gas Co of New Jersey
79/05/15 1p

--7905220314 LER 79-039/03L-0 on 790416 unit inadvertently entered Mode
when work was begun to remove reactor head. Caused by maint
supervisor not verifying that RCS had been brought up to
refueling status
KAPPLE, A W Public Service Electric & Gas Co. of New Jersey
79/05/15 3pp

7905290408 RD 79-43/01P on 790522 procedure to demonstrate operability
of steam driven auxiliary feedwater pump 13 permitted
closure of discharge control valves Procedure changed to
ensure operability.
MIDURA, H. J. Public Service Electric & Gas Co of New Jersey
79/05/22 1p.

T Hearing transcripts on non-antitrust matters

7905140568 Transcript of 790502 hearing in Salem, NJ Pp 317-503
MILHOLLIN, G L, KORNBLITH, L, LAMB, J C Atomic Safety and Licensing
Board Panel 79/05/02 191pp

7905140561 Transcript of 790503 hearing in Salem, NJ Pp 507-700
MILHOLLIN, G L, KORNBLITH, L, LAMB, J C Atomic Safety and Licensing
Board Panel 79/05/03 190pp

7905140558 Transcript of 790504 hearing in Salem, NJ Pp 701-918
MILHOLLIN, G L, KORNBLITH, L, LAMB, J C Atomic Safety and Licensing
Board Panel 79/05/04 208pp

DOCKET 50-273 BERNAU NUCLEAR STATION, UNIT 1

G Adjudicatory correspondence

7905160227 Reviews impact of TMI on upcoming hearings, lists hearings
scheduled for Apr & May
CUNNINGHAM, G H Branch 2 79/04/03 2pp

DOCKET 50-274 U S GEOLOGICAL SURVEY RESEARCH REACTOR

J Insurance & indemnity information

7905160244 Forwards Amend 9 to Indemnity Agreement D-10, per 10CFR140
changes, re increase from \$140 million to \$160 million
effective 790301 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/03/01 5pp

7905150481 Forwards Amend 9 to Indemnity Agreement D-10
HARRANZINO, A P Interior, Dept of, Geological Survey 79/05/09
2pp

DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

7905070674 Forwards replacement pages for Amends 1 & 4 to CPPR-39 &
CPPR-69
STOLZ, J F Light Water Reactors Branch 1 79/03/29 10pp

7905020490 Discusses 790315 telcon w/R Sero of Westinghouse re
incorrect weights for Velan Model C658 6-inch check valves
used in safety injection sys
SCHWENCER, A Operating Reactors Branch 1 79/04/02 1p

7905230578 Extends const completion dates to 790630 for Unit 1 & 800229
for Unit 2
STOLZ, J F Light Water Reactors Branch 1 79/04/13 6pp

--7905230582 FR notice ordering extension of const completion dates to
790630 for Unit 1 & 800229 for Unit 2
BOYD, R S Division of Project Management 79/04/13 2pp

DOCKETED ITEMS

G Adjudicatory correspondence

7903030166 Request by intervenors Scenic Shoreline Preservation Conference, San Luis Obispo Mothers for Peace, Ecology Action Club, SA Silver & JJ Foster for late filing of proposed findings of fact & conclusions of law w/ Certificate of Svc encl
FLEISCHAKER, D S Fleischaker, D S 79/03/25 4pp

--7905030174 Proposed findings of fact & conclusions of law by intervenors Scenic Shoreline Preservation Conference, San Luis Obispo Mothers for Peace, Ecology Action Club, SA Silver & JJ Foster
FLEISCHAKER, D S Fleischaker, D S PHILLIPS, J R., KRISTOVICH, S Center for Law in the Public Interest 79/03/25 69pp

7903250052 Informs of inability to submit proposed findings of fact on adequacy of plant security system denied access to evidence & access to hearing on security plan Certificate of Svc encl
BALDWIN, W A San Luis Obispo Mothers for Peace 79/03/29 3pp

7903230789 Group of 13 ltrs protesting opening of facility
MARQULETS, K R, NYLER, B Affiliation Unknown 79/03/30 19pp

7903010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients
SCINTO, J F Hearings Division 79/04/02 31pp

--7905010156 Board notification staff assessment re nonsafety-grade equipment to mitigate transients
VASSALLO, D B Assistant Director for Light Water Reactors 79/03/29 2pp

--7905010190 Board notification recent issue on nonsafety-grade equipment to mitigate transients More info is required
TEDESCO, R L Assistant Director for Reactor Safety 79/03/16 3pp

7903240236 Requests info on facility & earthquake, Unhappy w/nuclear power
QARCIA, G Affiliation Unknown 79/04/04 1p

--7903240279 Requests that facility not be allowed to operate.
MANZER, M, MANZER, R Affiliation Unknown 79/03/30 1p

7903300044 Motion of extension of time until 790410 to file proposed findings of fact & conclusions of law Certificate of Svc encl
KETCHEN, E G Branch 3 79/04/04 4pp

7903290114 Grants NRC 790404 motion for extension until 790410 in which to file findings of fact
SCHWERS, E B Atomic Safety and Licensing Board Panel 79/04/05 1p

7903310104 Errata sheet to joint intervenors' proposed findings of fact & conclusions of law Certificate of Svc encl
FLEISCHAKER, D S Fleischaker, D S PHILLIPS, J R., KRISTOVICH, S Center for Law in the Public Interest 79/04/05 7pp.

7903250330 Responds to 790326 ltr re status of facility licensing Evidentiary record in proceeding closed 790312; last pleading scheduled to be filed by 790416 Precise date for initial decision cannot be made
YORE, J R Atomic Safety and Licensing Board Panel 79/04/06 1p

790300370 Forwards corrected pages to NRC 790410 proposed findings, changing words "Initial Decision" to "Conclusions of Law"
TOURTELLOTT, J Branch 4 79/04/12 3pp

7903190726 Responds to 790216 & 790321 ltrs requesting denial of DL ASLB will consider issue Views to be included in docket file of proceeding
ENGELHARDT, T F Deputy Executive Legal Director 79/04/17 1p

7903130598 Forwards resolution adopted on 790416 Resolution requests deferment of action on license application, pending determination that safety sys are adequate to assure public safety
MENZEL, H C Santa Barbara County, CA 79/04/18 1p

--7903150603 Resolution of Board of Supervisors of Santa Barbara Co., CA urging NRC to defer final action on license application until facility safety systems are adequate to ensure public safety
YAGER, D M Santa Barbara County, CA 79/04/16 1p.

7903150118 Responds to encl ltr opposing operation of facility because of proximity to active earthquake fault & concern for disposal of high level radioactive wastes Matters being considered by ASLB
BOYD, R S Division of Project Management 79/04/30 3pp

7903240364 Requests denial w/o prejudice of joint intervenors' notice to withhold issuance of DL Certificate of Svc encl
TOURTELLOTT, J Branch 4 79/05/02 8pp

7903300007 Response in opposition to joint intervenors' request to withhold issuance of DL Motion is untimely, in wrong form & poorly taken
MORRISSEY, J C Pacific Gas & Electric Co GEHR, A C Enell & Wilmer NORTON, B Bruce Norton 79/05/09 6pp

7903300716 Ack receipt of 790423 & 790426 ltrs re opposition to operation of facility due to proximity to Hosgri Fault. Facility designed to withstand seismic event of 7.5 ASLB is preparing decision re licensing based on 790215 hearing.
DENTON, H R - Office of Nuclear Reactor Regulation 79/03/14. 2pp

--7903300719 Expresses opposition to operation of facility due to proximity to Hosgri Fault
WATERHOUSE, H Affiliation Unknown 79/04/26 1p

--7903300720 Expresses opposition to operation of facility due to proximity to Hosgri Fault
WATERHOUSE, E Affiliation Unknown 79/04/25 1p

H General correspondence

7903230452 Requests immediate halt to const of facility.
ANDREWS, M House of Rep 79/04/02 1p

7903070351 Notifies of change of address for DO Brindenbaugh & RU Hubbard to 1723 Hamilton Ave, Suite K, San Jose, CA 95125
COOPER, K F MHB Technical Associates 79/04/23 1p

7903240713 Requests suspension of DL until necessary safety mods are implemented
BROWN, E G California, State of 79/05/04. 2pp

7903240265 Responds to 790320 ltr re constituent concerns re granting of license to facility seismic event of 7.5 magnitude can be withstood & quality of const is controlled by licensee GA program.
GOSSICK, L V. Office of the Executive Director for Operations. 79/05/08. 3pp

I Financial information

of 7903300168 Forwards "Annual Financial Rept 1978."
CRANE, P A Pacific Gas & Electric Co 79/05/23 1p.

--7903300174 "Annual Financial Rept 1978"
* Pacific Gas & Electric Co 78/12/31. 40pp.

7903300310 Forwards "Estimated Internal Fund Generation for CY79" & "Annual Financial Rept 1978"
CRANE, P A Pacific Gas & Electric Co 79/05/24 3pp

--7903300329 "Annual Financial Rept 1978"
* Pacific Gas & Electric Co. 79/02/23 36pp.

DOCKETED ITEMS

63

J Insurance & indemnity information

7905140512 Forwards Amend 4 to Indemnity Agreement B-75 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
GALTZMAN, J Antitrust & Indemnity Group 79/03/01 6pp

7905140406 Forwards Amends executed Amends 21 & 4 to Indemnity Agreements B-21 & B-75, respectively
CRANE, P A Pacific Gas & Electric Co 79/03/08 3pp

Q Advisory Committee on Reactor Safeguards reports & correspondence

7905100325 Responds to request for written rept after cancellation of ACRS 790331 meeting re possibility of problem w/instrument guide tubes Staff rept encl
CROCKER, L P Division of Project Management 79/03/30 5pp

P. Operating license stage documents & correspondence

7905020244 Responds to NRC 790314 request for addl info re containment purge valves Forwards results of CBDREVI program to calculate containment purge valve closing data coincident w/LOGA
CRANE, P A Pacific Gas & Electric Co 79/04/13 45pp

7905020302 Forwards \$1,400 fee to extend CP, in response to NRC 790410 ltr Requests acknowledgment
CRANE, P A Pacific Gas & Electric Co 79/04/27 2pp

Q Inspection reports, IE Bulletins & correspondence

7905240747 Forwards IC Insp Rept 50-275/79-03 on 790220-23 No noncompliance noted
ROOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/03/19 2pp

---7905240740 IE Insp Rept 50-275/79-03 on 790220-23 No noncompliance noted Major areas inspected: emergency planning facilities & equipment; training; radiation protection staffing; radioactive waste sys & Offsite Dose Calculation Manual
NORTH, H G ; ROOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch. 79/03/19 5pp

7905230617 Forwards IC Insp Repts 50-275/79-05 & 50-323/79-03 on 790306-09 & 15, No noncompliance noted.
CARLINO, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/03/21 2pp

--7905230640 IC Insp Repts 50-275/79-05 & 50-323/79-03 on 790306-09 & 15 No noncompliance noted Major areas inspected preoperational testing, evaluation & verification of test results, IE bulletins & circulars followup
MORRILL, P O Region 5, San Francisco, Office of the Director
STERNBERG, D M Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/03/20 4pp

7905010287 Forwards IF Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
ENGELKEN, R H Region 4, Dallas, Office of the Director 79/03/23 1p

7905040081 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/03/26 1p

7905290147 Forwards IC Insp Rept 50-275/79-08 on 790225-0316 No noncompliance noted.
CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 79/04/13 2pp

--7905290152 IE Insp Rept 50-275/79-08 on 790225-0316 No noncompliance noted Major areas inspected: preoperational testing, plant tour, sys verification testing & fuel storage
YOUNG, T. Region 5, San Francisco, Office of the Director
STERNBERG, D M Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/04/13 4pp.

7905010023 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 1p

7905040509 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 1p.

7905070099 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 1p

7905030291 Forwards IE Bulletin 79-09, "Failures of GE Type AX-2 Circuit Breaker in Safety-Related Sys" Licensee action required
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/17 1p

7905080366 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/21 1p

S Reportable occurrences, LERs & related correspondence

7905110203 Board notification Seabrook refueling water storage tank design deficiency
SCINTO, J Hearings Division 79/03/29 30pp

7905150060 Forwards PNO-79-67L
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/06 1p

7905150167 Forwards PNO-79-67R
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/11 1p

7905040123 Forwards PNO-79-67B
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/12 1p

7905150141 Forwards PNO-79-67T
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/13 1p

7905030045 Forwards PNO-79-67U
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 1p

7905020527 Forwards PNO-79-67AA
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/20 1p

7905010425 Forwards PNO-79-67AB
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/21 1p

7905010444 Forwards PNO-79-67AC & AD
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/23 1p

7905020227 Forwards PNO-79-67AF
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/23 1p

7905020256 Forwards PNO-79-67AO
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/26 1p

7905090005 Forwards PNO-79-67AH
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/26 1p

--7905040360 PNO-79-67AI summary of intro to nuclear power
790428 Describes plant & environ status
* Office of Inspection & Enforcement 79/04/28 2pp

7905070007 Forwards PNO-79-67AL, per NRC 790401 ltr transmitting IE Bulletin 79-05
ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/01 1p

7905090380 Submits followup rept to 790404 notification of RO During progress of routine weld repairs on pipe rupture restraints, cracking discovered in immediate vicinity of repairs Full rept will be submitted
CRANE, P A Pacific Gas & Electric Co. 79/05/03 3pp

DOCKETED ITEMS

7905170072 Forwards PNO-79-474M
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/05/07 1p

7905240631 Ack receipt of 790503 ltr providing preliminary rept re
cracking found in pipe rupture restraints
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/05/16 1p

--7905240701 Discusses situation reported to IE on 790404 re cracking
in pipe rupture restraints Details program of investigation
Suppl on crack severity will be forwarded
CRANE, P A Pacific Gas & Electric Co 79/05/03 3pp

T Hearing transcripts on non-antitrust matters

7905030244 Corrections to transcripts from Dec 1978 & Jan 1979
hearings Certificate of Svc encl
MORRISSEY, J C, FURBUSH, M H, CRANE, P A Pacific Gas & Electric Co
79/04/04 23pp

7905240273 Requests info re E Maschke 790315 ltr of concerns about
granting of license to Util
LAGOMARINO, R House of Rep 79/03/20 1p

DOCKET 50-276 GEORGIA TECH RESEARCH REACTOR

J Insurance & indemnity information

7905300049 Forwards Amend 12 to Indemnity Agreement E-30, reflecting
change in 10CFR140, increasing primary layer of liability
from \$140 million to \$160 million, effective 790501
Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 3pp

O Inspection reports, IE Bulletins & correspondence

7905070137 Forwards IE Bulletins 79-05, 79-05A & 79-06, re nuclear
incident at TMI
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/13 1p

DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

O Adjudicatory correspondence

7905230312 Util response to briefs opposing de minimus approach of
Partins proceeding Licensees in Peach Bottom & Hope Creek
proceedings conted approach is valid, no need to consider
health effects further W/Certificate of Svc
CONNER, T B Conner, Moore & Corber 79/04/04 30pp

7905110418 Response to ALAB-509 re radon emissions & de minimus theory
from Partins record Certificate of Svc encl
SCINTO, J F Hearings Division BORDENICK, B H Branch 4
LEWIS, S H Branch 2 79/04/11 45pp

7905140319 Response to 790404 brief of Philadelphia Electric Co, Public
Svc Electric & Gas, & Atlantic City (NJ) Electric Co re de
minimus theory Certificate of Svc encl
KEPFORD, C P Citizens for Safe Environment 79/04/11 8pp

7905140332 Notifies of consolidation of five intervenor groups re radon
emissions issue Parties have until 790525 in which to file
for summary disposition
DUFLOR, M E Atomic Safety and Licensing Appeal Panel 79/04/25
13pp

7905240383 Memo & order ALAB-346 Denies applicants' petition for
reconsideration of ALAB-340, which consolidates applicants re
radon issue
DUFLOR, M E Atomic Safety and Licensing Appeal Panel 79/05/08
3pp.

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHINI, J American Nuclear Insurers. 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01,
1p.

7905140415 Forwards Amend 20 to Indemnity Agreement E-30, reflecting
changes re increase in liability insurance from \$140 million to
to \$160 million, effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 3pp

7905220347 Forwards Endorsement 04 to ANI Policy E-30, reflecting
BRADLEY, E J Philadelphia Electric Co 79/05/01 1p

P Operating license stage documents & correspondence

7905240184 Informs that Amend 38 to PHAR license E-30, reflecting
in response to NRC 790321 request
DALTROFF, B L Philadelphia Electric Co 79/05/01 1p

7905030348 Forwards application for amend of license E-30, reflecting
fee
BRADLEY, E J Philadelphia Electric Co 79/05/01 1p

--7905030352 Application for amend of license E-30, reflecting
surveillance frequency to reflect change from 12 to 8 months Certificate of Svc encl
BAUER, E O, BRADLEY, E J Philadelphia Electric Co 79/05/01 6pp

7905110073 Forwards application for amend of license E-30, reflecting
BRADLEY, E J Philadelphia Electric Co 79/05/01 1p

--7905110076 Application for amend of license E-30, reflecting
Tech Specs re reactor vessel wall surveillance Certificate of Svc encl
Philadelphia Electric Co 79/05/01 1p

7905290345 Forwards schedule for implementation of long-term program acceptable
necessary for long-term program acceptable to be completed during Spring 1980 refueling & Spring 1981 for Unit 3
BOYER, V B Philadelphia Electric Co 79/05/01 1p

7905300208 Forwards summary of LDB Nuclear, Inc. review of elbow flexibility error which stated that
PIBOL piping analysis computer program Review & reanalysis included all work
PORTER, F L EDS Nuclear, Inc 79/05/24 1p

--7905300263 Forwards LDB Nuclear, Inc. list of defects which could have been impacted by deficient
QC has no record of reanalysis for defects STEPHENS, P W General Electric Co 79/01/24 10pp

O Inspection reports, IE Bulletins & correspondence

7905010131 Forwards IE Info Notice 79-04, "Safety-Related Piping"
ORIER, B H Region 1, Philadelphia, 79/03/23 1p

7905010065 Forwards IE Info Notice 79-04, "Contaminated Bys w/Bvc Air Bys Used as the Air"
ORIER, B H Region 1, Philadelphia, 79/03/28 1p

7905010315 Forwards IE Info Notice 79-04, "Contaminated Resin"
ORIER, B H Region 1, Philadelphia, 79/03/30 1p

7905290129 Forwards IE Insp Repts 50-277/79-03 & 50-277/79-04
790228-0301 No noncompliance noted
CARLSON, R T Region 1, Philadelphia, 79/04/01 1p

--7905290132 IE Insp Repts 50-277/79-03 & 50-277/79-04
noncompliance noted Major areas inspected equipment, GA, fire protection & status of IE bulletins.
FINKEL, A E, KOLTAY, P B Region 1, Philadelphia, 79/05/01 1p

7905250152 Responds to IE Bulletin 79-04, "ASME SA-312 Type 304 stainless steel pipe
in ASME SA-312 Type 304 stainless steel pipe certifications for seam weld piping found to locate remaining pipe.
DALTROFF, B L Philadelphia Electric Co 79/05/01 1p

DOCKETED ITEMS

65

7905020082 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/11 1p

7905230694 Ack receipt of 790116 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/79-02 & 50-270/79-02
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch
79/04/12 1p

--7905230710 Responds to NRC 790220 ltr re violations noted in IE Insp Repts 50-277/79-02 & 50-270/79-02 Corrective actions detailed station procedures prepared & approved & surveillance test procedures revised
BALTRONIS, B L Philadelphia Electric Co 79/01/16 3pp

--7905230724 Forwards IE Insp Repts 50-277/79-02 & 50-270/79-02 on 790102-05 & 00 10 & notice of violation
SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch
79/02/20 1pp

--7905230732 Notice of violation from Insp on 790102-05 & 00 10
" Region 1, Philadelphia, Office of the Director 79/02/14 3pp.

--7905230750 IE Insp Repts 50-277/79-02 & 50-270/79-02 on 790102-5 & 00 10 Noncompliance noted failure to maintain effluent releases within Tech Upr: limits & failure to have procedures for tank loading & closure
NEELY, D R; NIMITZ, R I Region 1, Philadelphia, Office of the Director
CRUCKER, H H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch
79/02/14 2dpp

7905240116 Forwards IE Insp Repts 50-277/79-03 & 50-270/79-04 on 790129-0202 No noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Office of the Director
79/04/13 2pp

--7905240120 IE Insp Repts 50-277/79-05 & 50-270/79-07 on 790129-0202 No noncompliance noted Major areas inspected plant operations, facility tour, IE circular followup & IER review in off & on site
GREENMAN, L O Region 1, Philadelphia, Office of the Director
MCCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch
79/04/11 4pp

7905020323 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
ORICH, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040007 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORICH, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040234 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
Licensee action required
ORICH, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905030008 Forwards IE Bulletin 79-09, "Failures of GL Type AK 2 Circuit Breaker in Safety-Related Sys" Licensee action required
ORICH, B H Region 1, Philadelphia, Office of the Director
79/04/17 1p.

7905020309 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORICH, B H Region 1, Philadelphia, Office of the Director
79/04/10 1p

7905150307 Forwards IE Insp Repts 50-277/79-11 & 50-270/79-12 on 790409-13 & notice of violation
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch
79/04/20 2pp

--7905150314 Notice of violation from Insp on 790409-13
" Region 1, Philadelphia, Office of the Director 79/04/19 2pp

--7905150323 IE Insp Repts 50-277/79-11 & 50-270/79-12 on 790409-13 Noncompliance noted improper valve positioning & positive control, improper approval & review
GREENMAN, E J; GRAHAM, P D Region 1, Philadelphia, Office of the Director
MCCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch
79/04/19 2dpp

R Periodic operating reports & related correspondence

7905140344 Forwards "Annual Plant Mod Rept 1978"
ALDEN, W M Philadelphia Electric Co 79/04/27 1p

--7905140346 "Annual Plant Mod Rept 1978"
ULRICH, W T Philadelphia Electric Co 78/12/31 12pp

7905170236 Forwards monthly operating rept for Apr 1979
COONEY, M J Philadelphia Electric Co 79/05/11 1p

--7905170241 Monthly operating rept for Apr 1979
ALDEN, W M Philadelphia Electric Co 79/05/10 9pp

G Reportable occurrences, LERs & related correspondence

7905220280 Forwards LER 79-007/01T-0
COONEY, M J Philadelphia Electric Co 79/02/15 1p

--7905220284 LER 79-007/01T-0 on 790131 standby gas treatment sys sprinkler valve was not reopened following temp sensor test
Caused by operator error Operator was retrained in proper procedures
COONEY, M J Philadelphia Electric Co 79/02/15 1p

7905040378 LER 79-013/03L-0 on 790323 C trip logic HPCI area temp switches (TB-4941C, -42C, -43C, -44C) indicated less than ambient during routine surveillance Caused by dirty contacts on power supply for temp switch card units
COONEY, M J Philadelphia Electric Co 79/04/23 1p

7905040077 Forwards LER 79-016/01T-0
COONEY, M J Philadelphia Electric Co 79/04/26 3pp

--7905040072 LER 79-016/01T-0 on 790411 engineering review discovered valving associated w/seismically qualified emergency svc water sys was normally open Caused by faulty plant design
Open valves locked closed
COONEY, M J Philadelphia Electric Co 79/04/26 1p

7905020347 Forwards LER 79-017/04T-0
COONLY, M J Philadelphia Electric Co 79/04/27 2pp

--7905020356 LER 79-017/04T-0 on 790418 effluent pH of 5.3 identified, exceeding Tech Spec range Cause could not be determined
Aeration tank neutralized to bring effluent pH within limits Mod of treatment plant under investigation
COONEY, M J Philadelphia Electric Co 79/04/27 1p

7905040381 Forwards LER 79-010/01T-1 Discusses results of continuing investigation re design errors in recirculation sys valves
COONEY, M J Philadelphia Electric Co 79/04/30 3pp

--7905080464 LER 79-010/01T-1 on 790226 power & control cable associated w/recirculation pump discharge valves & bypass valves were found routed in nonsafeguard cable trays Caused by improperly designated cables during design phase
COONEY, M J Philadelphia Electric Co 79/03/12 1p

7905150443 LER 79-015/03L-0 on 790410 limit switch on M failed Cause not found due to high temp & radiation 1 in MBIV room Appropriate logic channel was placed in condition
COONEY, M J Philadelphia Electric Co 79/05/07 1p

7905230861 RD 2-79-21/1P on 790504 HPCI control cable 1 w/ADS cables for short distance in cable spreading rd Caused by failure of supplier to provide proper sys interface documents to A/E during design phase
ULRICH, W T Philadelphia Electric Co 79/05/07 2p

7905160383 LER 79-018/03L-0 on 790428 channel D refuel reactor bldg area ventilation exhaust radiation monit failed downscale while at power Caused by defective converter in common radiation monitor power supply
COONEY, M J Philadelphia Electric Co 79/05/11 1p

7905290214 Forwards LER 79-021/01T-0
COONEY, M J Philadelphia Electric Co 79/05/18 3

--7905290216 LER 79-021/01T-0 on 790504 HPCI cables im Caused by errors in designs Rerouting of cables w affected during outages
COONEY, M J Philadelphia Electric Co 79/05/18

DOCKETED ITEMS

DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

Q Adjudicatory correspondence

7905220070 Dismisses exceptions to LBP-74-42 Approves stipulation among certain parties & participants & accompanying Tech Specs as fulfilling NRC responsibilities re thermal discharges
 DUFLD, M E Atomic Safety and Licensing Appeal Panel 79/03/23 11pp

7905230512 Util response to briefs opposing de minimus approach of Perkins proceeding Licensees in Peach Bottom & Hope Creek proceedings contend approach is valid; no need to consider health effects further W/Certificate of Svc
 CONNER, T B Conner, Moore & Corber 79/04/04 30pp

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins Record Certificate of Svc encl
 SCINTO, J F Hearings Division BORDENICK, B M Branch 4
 LEWIS, S H Branch 2 79/04/11 45pp

7905140319 Response to 790404 brief of Philadelphia Electric Co, Public Svc Electric & Gas, & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Svc encl
 KEPPORD, C P Citizens for Safe Environment 79/04/11 8pp

7905240385 Memo & order ALAB-346 Denies applicants' petition for reconsideration of ALAB-340, which consolidates applicants re radon issue
 DUFLD, M E Atomic Safety and Licensing Appeal Panel 79/05/08 3pp

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790523 in which to file for summary disposition
 DUFLD, M E Atomic Safety and Licensing Appeal Panel 79/04/25 13pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies MF-1, 25, 43, 76, 83, 100, 111, 140, 145, 151, 161, 164, 170, 173, 174, 179, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
 GUAYTROCHHI, J American Nuclear Insurers 79/05/01 1p

7905070382 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
 ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905140415 Forwards Amend 20 to Indemnity Agreement B-2B per 10CFR140 changes re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
 BALTZHAN, J. Antitrust & Indemnity Group 79/05/01 6pp

7905220347 Forwards Endorsement B4 to ANI Policy NF-140
 BRADLEY, E J Philadelphia Electric Co 79/05/14 2pp

P Operating license stage documents & correspondence

7905240184 Informs that Amend 35 to FSAR contains existing QA program; in response to NRC 790321 request
 DALTROFF, B L Philadelphia Electric Co 79/04/10 1p

7905030348 Forwards application for amend of licenses & \$1,600 filing fee
 BRADLEY, E J Philadelphia Electric Co 79/04/30 1p

--7905030352 Application for amend of Licenses DPR-44 & DPR-56 to change surveillance frequency to reflect change in refueling cycle from 12 to 8 months Certificate of Svc encl
 BAUER, E O., BRADLEY, E J Philadelphia Electric Co 79/04/30 6pp

7905110073 Forwards application for amend of Licenses DPR-44 & DPR-56
 BRADLEY, E. J. Philadelphia Electric Co 79/05/08 1p

--7905110076 Application for amend of Licenses DPR-44 & DPR-56, changing Tech Specs re reactor vessel matl surveillance program Certificate of Svc encl
 * Philadelphia Electric Co 79/05/04, 19pp

7905290345 Forwards schedule for implementation of major plant acc, necessary for long-term program acceptance criteria Mode to be completed during Spring 1980 refueling outage for Unit 2 & Spring 1981 for Unit 3
 BOYER, V S Philadelphia Electric Co 79/05/21 3pp

7905300208 Forwards summary of EDS Nuclear, Inc resolution/documents, of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970
 PORTER, F L EDS Nuclear, Inc 79/05/21 9pp

--7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program GE has no record of reanalysis for Cooper piping sys
 STEPHENS, P W General Electric Co, Nuclear Energy Products Div 79/01/24 18pp

d Inspection reports, IE Bulletins & correspondence

7905010131 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
 ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/23 1p

7905010065 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air"
 ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/28 1p

7905010315 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
 ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/30 1p

7905290129 Forwards IE Insp Repts 50-277/79-03 & 50-278/79-08 on 790228-0301 No noncompliance noted
 CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/03 2pp

--7905290132 IE Insp Repts 50-277/79-03 & 50-278/79-08 on 790228-0301 & noncompliance noted Major areas inspected electrical equipment, QA, fire protection & status of IE circulars & bulletins
 FINKEL, A E, KOLTAJ, P S Region 1, Philadelphia, Office of the Director
 EBNETER, S D Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/29 6pp

7905250152 Responds to IE Bulletin 79-03 re longitudinal weld defects in ABME BA-312 Type 304 stainless steel pipe spools Two certifications for seam weld piping found Requests add time to locate remaining pipe
 DALTROFF, S L Philadelphia Electric Co 79/04/09 2pp

7905020082 Forwards IE Bulletin 79-04, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
 ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/11 1p

7905230694 Ack receipt of 790316 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/79-02 & 50-278/79-02
 SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/04/12, 1p

--7905230710 Responds to NRC 790228 ltr re violations noted in IE Insp Repts 50-277/79-02 & 50-278/79-02 Corrective actions detailed station procedures prepared & approved & surveillance test procedures revised
 DALTROFF, S L Philadelphia Electric Co 79/03/16 3pp

--7905230724 Forwards IE Insp Repts 50-277/79-02 & 50-278/79-02 on 790102-05 & 08-10 & notice of violation
 SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/02/28 3pp

--7905230732 Notice of violation from insp on 790102-05 & 08-10
 * Region 1, Philadelphia, Office of the Director 79/02/14 3pp

--7905230750 IE Insp Repts 50-277/79-02 & 50-278/79-02 on 790102-05 & 08-10 Noncompliance noted failure to maintain effluent releases within Tech Spec limits & failure to have procedures for cask loading & closure
 NEELY, D R, NIMITZ, R L Region 1, Philadelphia, Office of the Director
 CROCKER, H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch, 79/02/14 22pp

DOCKETED ITEMS

67

7905290116 Forwards IC Insp Repts 50-277/79-03 & 50-278/79-04 on 790129-0202 No noncompliance noted
BRUNNEN, E J Region 1, Philadelphia, Office of the Director
79/04/13 2pp

--7905290120 IC Insp Repts 50-277/79-03 & 50-278/79-04 on 790129-0202 No noncompliance noted Major areas inspected plant operations, facility tour, IC circular followup & ICR review in nfc & on site
GREENMAN, E O Region 1, Philadelphia, Office of the Director
MCCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch
79/04/11 4pp

7905040323 Forwards II Bulletin 79 07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required
GRIFIN, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040087 Forwards IC Bulletin 79 06D, "Review of Operational Errors & Hys Misalignments Identified During TMI Incident "
GRIFIN, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p.

7905040259 Forwards II Bulletin 79 08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident "
Licensee action required
GRIFIN, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040080 Forwards II Bulletin 79 09, "Failures of GI Type AK-2 Circuit Breaker in Safety Related Hys " Licensee action required.
GRIFIN, B H Region 1, Philadelphia, Office of the Director.
79/04/17 1p

7905020709 Forwards II Bulletin 79 06A, Revision 1, "Review of Operational Errors & Hys Misalignments Identified During TMI Incident."
GRIFIN, B H Region 1, Philadelphia, Office of the Director
79/04/10 1p

7905150707 Forwards II Insp Repts 50 277/79 11 & 50 278/79 12 on 790409 13 & notice of violation
BRUNNEN, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch
79/04/20 2pp

7905150714 Notice of violation from Insp on 790409 11
* Region 1, Philadelphia, Office of the Director 79/04/19 2pp

7905150521 IC Insp Repts 50 277/79 11 & 50 278/79 12 on 790409 13 Noncompliance noted improper valve positioning & positive control, improper approval & review
GREENMAN, E O Region 1, Philadelphia, Office of the Director
MCCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch
79/04/19 2pp

R Periodic operating reports & related correspondence

7905140344 Forwards "Annual Plant Mod Rept 1978 "
ALDEN, W H Philadelphia Electric Co 79/04/27 1p

--7905140346 "Annual Plant Mod Rept 1978 "
URICH, W T Philadelphia Electric Co 7/12/78 12pp

7905170236 Forwards monthly operating rept for Apr 1979
COONEY, M J Philadelphia Electric Co 79/05/11 1p

--7905170241 Monthly operating rept for Apr 1979
ALDEN, W H Philadelphia Electric Co 79/05/10 9pp

B Reportable occurrences, IIRs & related correspondence

7905040077 Forwards IIR 79-016/OIT-0
COONEY, M J Philadelphia Electric Co 79/04/26 7pp

--7905040072 LER 79-016/OIT-0 on 790411 engineering review discovered valving associated w/seismically qualified emergency svc water sys was normally open Caused by faulty plant design
Open valves locked closed
COONEY, M J Philadelphia Electric Co 79/04/26 1p

7905040581 Forwards LER 79-010/OIT-1 Discusses results of continuing investigation re design errors in recirculation sys valves
COONEY, M J Philadelphia Electric Co 79/04/30 5pp

7905230861 RD 2-79-21/1P on 790504 HPCI control cable improperly routed w/ADS cables for short distance in cable spreading room
Caused by failure of supplier to provide proper sys interface documents to A/E during design phase
URICH, W T Philadelphia Electric Co 79/05/07 2pp

7905290214 Forwards LER 79-021/OIT-0.
COONEY, M J Philadelphia Electric Co 79/05/18 3pp

--7905290216 LER 79-021/OIT-0 on 790504 HPCI cables improperly routed Caused by errors in designs Rerouting of cables will be effected during outages
COONEY, M J Philadelphia Electric Co 79/05/18 1p

DOCKET 50-280 SURRY POWER STATION, UNIT 1

A Application/construction stage documents & correspondence

7905290296 Requests NRC reconsider its 3-month moratorium on issuance of new OL because of large addl costs of replacement power
RADONE, S Virginia Electric & Power Co 79/05/22 2pp

O Adjudicatory correspondence

7905230646 Orders extension, until 790524, for NRC review of 790404 denial of enforcement action
CHILK, B J Office of the Secretary of the Commission 79/04/13 1p

7905100262 Forwards petition of Potomac Alliance, et al for emergency & remedial action
DUQUHERTY, J B Potomac Alliance 79/04/18 2pp

--7905100328 Petition for emergency & remedial action re NRC violations of NEPA in issuing Amends 46 & 47 to OL
DUQUHERTY, J B Potomac Alliance 79/04/18 65pp

7905240455 Ack receipt of 790405 ltr requesting NRC to revoke OLs Ltr is currently under consideration Forwards FR notice re Allen 790405 ltr
DENTON, H R Office of Nuclear Reactor Regulation 79/05/04 1p

--7905240461 FR notice re J Allen 790405 request for revocation of OLs
DENTON, H R Office of Nuclear Reactor Regulation 79/05/04 2pp

7905310033 Forwards J Allen 790405 ltr requesting NRC revoke facility OLs & FR notice of revocation request W/790330 ltr to ASLAB re Westinghouse EOCB deficiency
DENTON, H R Office of Nuclear Reactor Regulation 79/05/04 3pp

J Insurance & indemnity information

7905110107 Amend to Endorsement 51 to NELIA Policy NF-186 Constitutes Endorsement 54
* Nuclear Energy Liability Insurance Association 79/04/27 1p

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHI, J American Nuclear Insurers 79/05/01 1p

DOCKETED ITEMS

P Operating license stage documents & correspondence

7905080347 Assigns responsibility for prompt meeting notification re 790313 show cause orders
STELLO,V Division of Operating Reactors 79/03/29 3pp

7905020490 Discusses 790315 telcon w/R Sero of Westinghouse re incorrect weights for Valan Model C65B 4-inch check valves used in safety injection sys
SCHWENGER,A Operating Reactors Branch 1 79/04/02 1p

7905240189 Forwards 790220 ltr requesting NRC to conduct hearing & prepare EIS on proposed replacement of steam generators Related Fr notice encl
DENTON,H R Office of Nuclear Reactor Regulation 79/04/04 2pp

--7905240199 Requests reconsideration of issuance of license Amends 46 & 47 for replacement of steam generators Also requests public hearing & EIS
BERICK,D , ALVAREZ,D Environmental Policy Institute 79/02/20 2pp

--7905240204 Notification of "Director's Decision under 10CFR2 206," denying request for public hearing & EIS preparation re steam generator repair program
DENTON,H R Office of Nuclear Reactor Regulation 79/04/04 8pp

7905300010 Summary of 790404 meeting w/S&W & util in Boston,MA re sequential operations of safety sys required to reach shutdown in all conditions & pipe sys stress reanalysis
NEIGHBORS,D Operating Reactors Branch 1 79/04/06 5pp

7905100158 Responds to 790330 ltr re analysis of piping sys per 790313 show cause order Use of soil structure interaction techniques in calculation of amplified response spectra is acceptable if appropriate documentation is included
STELLO,V Division of Operating Reactors 79/04/13 2pp

7905100073 Requests review,mod & testing plans re action taken to correct design deficiency identified in electrical load study Suggests application for appropriate license amend be made as soon as possible
VOLLMER,R H Assistant Director for Systems & Projects 79/04/16 2pp

7905150789 Summary of 790419 meeting w/S&W & util in Boston,MA re review of pipe stress analyses
NEIGHBORS,J D Operating Reactors Branch 1 79/04/24 3pp

7905310472 Summary of 790419 meeting w/S&W & util in Boston,MA re review of pipe stress analyses
NEIGHBORS,J D Operating Reactors Branch 1 79/04/24 5pp

7905040468 Forwards VEP-FRD-32, "Burry Unit 2,Cycle 4 Core Performance Rept"
THOMAS,W N Virginia Electric & Power Co 79/04/27 1p

--7905040472 "Burry Unit 2,Cycle 4 Core Performance Rept"
ROSS,T K , LEBERSTEIN,J H Virginia Electric & Power Co VEP-FRD-32 79/04/30 47pp

7905040615 Forwards status rept on 790427 "Plan for Verification of Dynamic Analysis Codes."
JACOBBS,B B Stone & Webster Engineering Corp 79/04/27 2pp

7905070473 Notifies that two completed pipe stress problems were sent to contractor subsequent to 790419 meeting Specific info encl
SPENCER,W C Virginia Electric & Power Co 79/04/27 2pp.

7905040036 Believes recordkeeping requirements should be modified to agree w/ASME Section XI Code requirements Change to Tech Specs 6 & 7 designated as suppl to encl Change 66
STALLINGS,C M Virginia Electric & Power Co 79/05/01 4pp

7905040380 Notifies that steam generator replacement program initial progress rept for 790203-0331 is being prepared Reporting period should cover two months rather than 60 days
STALLINGS,C M Virginia Electric & Power Co 79/05/02 1p

7905070610 Responds to 790413 ltr Forwards summary of soil structure interaction analyses,summary of subgrade matl properties & damping values which were calculated by Shake Program Summary of sample pipe stress analyses
SPENCER,W C Virginia Electric & Power Co 79/05/02. 51pp

7905070637 Requests NRC recommend to Commissioners that Unit 1 be returned to svc immediately Util will supply any supportive technical presentations deemed necessary
STALLINGS,C M Virginia Electric & Power Co. 79/05/02 2pp

7905070460 Responds to NRC 790222 ltr requesting addl info re environ qualification testing performed on continental instrument cable presently in use
O'REILLY,J P Virginia Electric & Power Co 79/05/03 19pp

7905080938 Forwards addl info re organizational chart to support proposed Tech Specs Change 71
STALLINGS,C M Virginia Electric & Power Co 79/05/04 2pp

7905300751 Responds to 790320 telegram re shutdown of units NRC revis: of pipe stress levels will be limited to safety considerations
DENTON,H R Office of Nuclear Reactor Regulation 79/05/04 2pp

--7905300756 Comments on areas of concern re shutdown units Urges pres: analysis of effects of shutdown
SHANNON,P C Virginia, State of 79/03/20 3pp

7905140239 Forwards proprietary documents requested during 790301-C4 special insp
ERLEWINE,J A Stone & Webster Engineering Corp 79/05/08 1p

--7905140243 Requests withholding Technical Guideline EMT0-22-0 & Technical Rept EMT0-612 (ref 10CFR2 790) Affidavit encl
KENNEDY,W J Stone & Webster Engineering Corp 79/05/04 10pp

7905140382 Confirms 790504 telcon w/WT Russell re computer deci associated w/SHOCK 0 program
KENNEDY,W J Stone & Webster Engineering Corp 79/05/09 1p

7905140335 Notifies that review of computer deck is completed SHOCK 0 program still unrecovered Piping sys conservatively designed & will perform intended function
KENNEDY,W J Stone & Webster Engineering Corp 79/05/11 1p

7905210111 Forwards SHOCK 1 computer program listing Supersedes submittal of 790406 Program listing withheld (ref 10CFR2 790)
KENNEDY,W J Stone & Webster Engineering Corp 79/05/14 1p

7905290335 Summarizes procedures & calculational techniques used in reanalysis of piping sys designed w/SHOCK II computer program Reanalysis will satisfy 790313 order to show cause
KENNEDY,W J Stone & Webster Engineering Corp 79/05/18 6pp

7905250108 Submits corrections to 780920 proposed Tech Spec Change 33 re listing of hydraulic shock suppressors
STALLINGS,C M Virginia Electric & Power Co 79/05/22 1p

7905250092 Submits response to 790518 request for info concerning review of methodology in use of soil structure interaction
SPENCER,W C Virginia Electric & Power Co 79/05/24 33pp

7905250132 Submits addl info in response to 790402 request re safety sys analyzed by SHOCK II code,pipe stresses & verification of dynamic analysis codes Info relates to 790313 order to show cause
SPENCER,W C Virginia Electric & Power Co 79/05/24 9pp

7905290001 Resubmits 761230 Tech Spec change request as Change 24 No unreviewed safety question involved
STALLINGS,C M Virginia Electric & Power Co 79/05/24 16pp

G Inspection reports, IE Bulletins & correspondence

7905020040 Forwards IE Insp Repts 50-280/79-10 & 50-281/79-12 on 790214-16 No noncompliance noted
LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/12 2pp.

--7905020049 IE Insp Repts 50-280/79-10 & 50-281/79-12 on 790214-16 No noncompliance noted.Major areas inspected protection of components in containment,tag out practices,long-term layup & temporary ventilation
ELROD,S A Region 2, Atlanta, Office of the Director
CANTRELL,F B Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/09 4pp

7905020012 Forwards IE Insp Repts 50-280/79-02 & 50-281/79-02 on 790102-0202 No noncompliance noted
LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/13 2pp

--7905020019 IE Insp Repts 50-280/79-02 & 50-281/79-02 on 790102-0202 w noncompliance noted.Major areas inspected plant physical barriers & preparations for steam generator replacement
BURKE,D J Region 2, Atlanta, Office of the Director
CANTRELL,F B Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/12 9pp.

DOCKETED ITEMS

69

7905010224 Forwards IF Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/03/21 2pp

7905010319 Forwards IF Info Notice 79-07, "Rupture of Radwaste Tanks"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/03/26 2pp

7905010123 Forwards IF Info Notice 79-08, "Interconnection of Contaminated Hys w/Hvc Air Hys Used as Source of Breathing Air"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/01/20 2pp

7905010169 Forwards IF Info Notice 79-09, "Upill of Radioactively Contaminated Resin"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/01/30 2pp

7905020025 Forwards IF Insp Repts 70 200/79 11 & 50 201/79 16 on 790121 21 No noncompliance noted
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/04/11 2pp

- 7905020011 IF Insp Rept 70 200/79 11 & 70 201/79 16 on 790121 21 No noncompliance noted Major area inspected independent Insp effort re 10CIRAJ B5 Interim measures Details withheld (ref 10CIR2 790)
HEMMISLEY, R J Region 2, Atlanta, Office of the Director
TOBIN, W J Region 2, Atlanta, Safeguards Branch 79/04/11 1p

7905080514 Forwards IF Bulletin 79-06, "Review of Operational Errors & Hys Misalignments Identified During TMI Incident" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/11 1p

7905040254 Forwards IF Bulletin 79-06b, "Review of Operational Errors & Hys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 2pp

7905040271 Forwards IF Bulletin 79-07, "Reisner Stress Analysis of Safety Related Piping" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 1p

7905040448 Forwards IF Bulletin 79-08, "Events Relevant to Boiling Water Reactor Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 1p

7905080164 Responds to IF Bulletin 79-07, "Longitudinal Weld Defects in AWH OA 112 Type 104 (Stainless Steel) Pipe (Opus 189 by Youngstown Welding & Engineering Co. North Anna) uses no OA 312 piping Entry 1 & 2 records are still under review
BTALLINOS, C M Virginia Electric & Power Co 79/04/16 2pp

7905010191 Forwards IF Bulletin 79-09, "Failures of Q1 Type AK J Circuit Breaker in Safety Related Hys" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/17 2pp

7905020496 Forwards IF Bulletin 79-06A, Revision 1, "Review of Operational Errors & Hys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/10 2pp

7905100520 Informs that response to IF Bulletin 79-07 re seismic analysis of safety related piping will be provided in conjunction w/order to show cause dtd 790311
BPENCER, W C Virginia Electric & Power Co 79/04/21 1p

7905240181 Responds to IF Bulletin 79-06A, "Review of Operational Errors & Hys Misalignments Identified During TMI Incident" Review committee was established & detailed review of TMI incident has been completed
BTALLINOS, C M Virginia Electric & Power Co 79/04/26 4pp

7905300706 Forwards response to IF Bulletin 79-04 Velen swing check valves of three & six inches installed in chemical vol & control & safety injection sys
BTALLINOS, C M Virginia Electric & Power Co 79/05/03 4pp

7905320275 Responds to IF Bulletin 79-06A, Revision 1 Provides requested info on design changes re containment sump pump trip valve actuation & safety injection logic
BTALLINOS, C M Virginia Electric & Power Co 79/05/17 2pp

7905220142 Forwards requested relief from inservice insp requirements for Class 1, 2 & 3 components & requested relief from inservice testing requirements for pumps 4/29 over sized drawings
BTALLINOS, C M Virginia Electric & Power Co 79/05/17 109pp

7905290032 Responds to IF Bulletin 79-09 Q1 Type AK-2 circuit breakers not in use or planned for use
BTALLINOS, C M Virginia Electric & Power Co 79/05/23 1p

7905300010 Responds to IF Bulletin 79-10 Forwards requalification training program statistics
BTALLINOS, C M Virginia Electric & Power Co 79/05/24 3pp

7905300112 Responds to IF Insp Rept 50-201/79 10 Steam generator cutting method & description of decontamination procedure revised
BTALLINOS, C M Virginia Electric & Power Co 79/05/25 1p

R Periodic operating reports & related correspondence

7905110017 Forwards "Steam Generator Repair Program Progress Rept 1" for 790201 790311
BTALLINOS, C M Virginia Electric & Power Co 79/05/00 1p

7905110011 "Steam Generator Repair Program Progress Rept 1" for 790201 0111
* Virginia Electric & Power Co 79/01/11 3pp

7905130510 Forwards monthly operating rept for Apr 1979
BTALLINOS, C M Virginia Electric & Power Co 79/05/10 1p

7905150515 Monthly operating rept for Apr 1979
BTWART, D Virginia Electric & Power Co 79/05/01 30pp

B Reportable occurrences, LIRs & related correspondence

7905202012 Forwards LIR 79-009/01T 0
BTALLINOS, C M Virginia Electric & Power Co 79/04/26 1p

- 7905202019 LIR 79-009/01T 0 on 790412, 01T informed that potential problem exists in inside recirculation spray pump monitors caused by possible overheating of lower bearing due to clearance tolerances allowed on end shields & shaft
BTWART, H L Virginia Electric & Power Co 79/04/26 2pp

7905010492 Forwards LIR 79-011/01H 0
BTALLINOS, C M Virginia Electric & Power Co 79/04/17 1p

- 7905010490 LIR 79-011/01H 0 on 790720 while in cold shutdown, gaseous monitors process vent particulate & ventilation vent particulate were w/o power caused by loose lug connection on power supply cable lug connection repaired
BTWART, H L Virginia Electric & Power Co 79/04/27 2pp

7905040196 Forwards LIR 79-012/01H 0
BTALLINOS, C M Virginia Electric & Power Co 79/05/02 1p

- 7905040414 LIR 79-012/01H 0 on 790402 during function test, 21 of 74 snubbers did not meet acceptance criteria stipulated in governing procedure caused by failure to readjust snubbers to optimum design condition failed snubbers reset
BTWART, H L Virginia Electric & Power Co 79/05/02 3pp

7905070655 Forwards "Analysis & Hys Mod for 480 Volt Emergency Hys" in response to NRC 790416 LIR
BTALLINOS, C M Virginia Electric & Power Co 79/05/01

--7905070657 "Analysis & Hys Mod for 480 Volt Emergency"
* Virginia Electric & Power Co 79/05/03 24p

7905110157 Forwards LIR 79-013/03H 0
BTALLINOS, C M Virginia Electric & Power Co

- 7905110164 LIR 79-013/03H 0 on 790410 100 g recovery test tank 1-BR-TK-2B prior to o results caused by improper valve lineup recirculation in preparation for samp
BTWART, H L Virginia Electric & Power Co

7905190119 Forwards LIR 79-017/01T 0
BTALLINOS, C M Virginia Electric

DOCKETED ITEMS

--7903190123 LER 79-017/01T-O on 790502 problem could develop in thrust bearing of turbocharger for emergency diesel generators under repeat start operating modes Engineering design problem occurs only under restrictive conditions
STEWART, W L Virginia Electric & Power Co 79/05/15 3pp

7905250141 Forwards LERs 79-014/03L-O, 79-015/03L-O & 79-016/03L-O
STALLINGS, C M Virginia Electric & Power Co 79/05/22 1p

--7905250150 LER 79-014/03L-O on 790422 liquid waste disposal radiation monitor failed to give high alarm & trip release valve
Caused by instrument drift in high alarm setpoint All liquid waste releases were secured & alarm board checked
STEWART, W L Virginia Electric & Power Co 79/05/22 2pp

--7905250154 LER 79-015/03L-O on 790422 liquid waste disposal radiation monitor failed to give high alarm & trip release valve
Caused by procedural inadequacy Procedures modified
STEWART, W L Virginia Electric & Power Co 79/05/22 2pp

--7905250157 LER 79-016/03L-O on 790423 cracks noted in concrete support for 1-RH-E-1A & 1-RH-E-1B Caused by thermal expansion of heat exchanger Cracks repaired Heat exchanger supports will be modified to allow for thermal expansion
STEWART, W L Virginia Electric & Power Co 79/05/22 2pp

7905290005 Forwards LER 79-018/01T-O
STALLINGS, C M Virginia Electric & Power Co. 79/05/23 1p

--7905290010 LER 79-018/01T-O on 790509 solenoid valve Model 8320A102 mfg by Automatic Switch Co found environmentally unqualified & reportable per IE Bulletin 79-01 & Tech Specs Valve could fail to control admission & venting of air during LDCA
STEWART, W L Virginia Electric & Power Co 79/05/23 2pp

DOCKET 80-281 SURRY POWER STATION, UNIT 2

Q Adjudicatory correspondence

7905230646 Orders extension, until 790524, for NRC review of 790404 denial of enforcement action
CHILK, S J Office of the Secretary of the Commission 79/04/13 1p

7905100262 Forwards petition of Potomac Alliance et al for emergency & remedial action
DOUGHERTY, J B Potomac Alliance 79/04/18 2pp

--7905100328 Petition for emergency & remedial action re NRC violations of NEPA in issuing Amendments 46 & 47 to DL
DOUGHERTY, J B Potomac Alliance 79/04/18 65pp.

7905240435 Ack receipt of 790405 ltr requesting NRC to revoke DLs Ltr is currently under consideration Forwards FR notice re Allen
790405 ltr
DENTON, H R Office of Nuclear Reactor Regulation 79/05/04 1p

--7905240461 FR notice re J Allen 790405 request for revocation of DLs
DENTON, H R Office of Nuclear Reactor Regulation. 79/05/04 2pp

7905310033 Forwards J Allen 790405 ltr requesting NRC revoke facility DLs & FR notice of revocation request W/790330 ltr to ASLAR re Westinghouse ECCS deficiency
DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/04 3pp

J. Insurance & indemnity information

7905110107 Amend to Endorsement S1 to NELIA Policy NF-186 Constitutes Endorsement S4
* Nuclear Energy Liability Insurance Association 79/04/27. 1p.

7905110107 Amend to Endorsement S1 to NELIA Policy NF-186 Constitutes Endorsement S4.
* Nuclear Energy Liability Insurance Association 79/04/27. 1p

7905070497 Confirms increased liability limit to \$24,000,000 for policies NF-1, 29, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 189, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHNE, J. American Nuclear Insurers 79/05/01. 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D M Mutual Atomic Energy Liability Underwriters. 79/05/01 1p.

7905110090 Endorsements 16, 30, 36 & 47 to NELIA Policy NF-186
BARDES, C R Nuclear Energy Liability Insurance Association
79/05/01 1p

7905140444 Forwards Amend 10 to Indemnity Agreement B-43 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp

7905240485 Forwards executed Amend 10 to Indemnity Agreement B-43, effective 790518
STALLINGS, C M Virginia Electric & Power Co 79/05/21 3pp

P. Operating license stage documents & correspondence

7905080347 Assigns responsibility for prompt meeting notification re 790313 show cause orders
STELLO, V Division of Operating Reactors 79/03/29 3pp

7905020490 Discusses 790315 telcon w/R Sero of Westinghouse re incorrect weights for Valan Model C638 6-inch check valves used in safety injection sys
SCHWENGER, A Operating Reactors Branch 1 79/04/02 1p

7905240189 Forwards 790220 ltr requesting NRC to conduct hearing & prepare EIS on proposed replacement of steam generators
Related FR notice encl
DENTON, H R Office of Nuclear Reactor Regulation 79/04/04 2pp

--7905240199 Requests reconsideration of issuance of license Amendments 46 & 47 for replacement of steam generators Also requests public hearing & EIS
BERTICK, D, ALVAREZ, B Environmental Policy Institute 79/02/20 2pp

--7905240204 Notification of "Director's Decision under 10CFR2.206," denying request for public hearing & EIS preparation re steam generator repair program
DENTON, H R Office of Nuclear Reactor Regulation 79/04/04 8pp

7905300010 Summary of 790404 meeting w/S&W & util in Boston, MA re sequential operations of safety sys required to reach shutdown in all conditions & pipe sys stress reanalysis.
NEIGHBOR, D Operating Reactors Branch 1 79/04/06 5pp

7905100198 Responds to 790330 ltr re analysis of piping sys per 790313 show cause order Use of soil structure interaction techniques in calculation of amplified response spectra is acceptable if appropriate documentation is included
STELLO, V Division of Operating Reactors 79/04/13 2pp

7905100073 Requests review, mod & testing plans re action taken to correct design deficiency identified in electrical load study Suggests application for appropriate license amend be made as soon as possible
VOLLMER, R H Assistant Director for Systems & Projects 79/04/14 2pp

7905040468 Forwards VEP-FRD-32, "Surry Unit 2, Cycle 4 Core Performance Rept"
THOMAS, W N Virginia Electric & Power Co 79/04/27 1p

--7905040472 "Surry Unit 2, Cycle 4 Core Performance Rept"
ROSS, T K, LEBERSTEIN, J H Virginia Electric & Power Co
VEP-FRD-32 79/04/30 47pp.

7905040615 Forwards status rept on 790427 "Plan for Verification of Dynamic Analysis Codes"
JACOBS, B B. Stone & Webster Engineering Corp. 79/04/27 2pp

7905070473 Notifies that two completed pipe stress problems were sent to contractor subsequent to 790419 meeting. Specific info encl.
SPENCER, W C. Virginia Electric & Power Co 79/04/27 2pp

7905040036 Believes recordkeeping requirements should be modified to agree w/ASME Section XI Code requirements. Change to Tech Specs 6.5.8.7 designated as suppl to encl Change 66
STALLINGS, C M Virginia Electric & Power Co 79/05/01 4pp

7905040380 Notifies that steam generator replacement program initial progress rept for 790203-0331 is being prepared. Reporting period should cover two months rather than 60 days
STALLINGS, C M. Virginia Electric & Power Co 79/05/02 1p

7905070610 Responds to 790413 ltr Forwards summary of soil structure interaction analyses, summary of subgrade matl properties & damping values which were calculated by Shake Program
Summary of sample pipe stress analyses
SPENCER, W C Virginia Electric & Power Co 79/05/02 5pp

7905070637 Requests NRC recommend to Commissioners that Unit 1 be returned to svc immediately Util will supply any supportive technical presentations deemed necessary
STALLINGS, C M Virginia Electric & Power Co 79/05/02 2pp

7905290405 Notification of 790303 meeting w/util in Bethesda, MD to discuss startup
NEIGHBOR, D Operating Reactors Branch 1 79/05/02 1p

7905070460 Responds to NRC 790222 ltr requesting addl info re environ qualification testing performed on continental instrument cable presently in use
O'REILLY, J P Virginia Electric & Power Co 79/05/03 19pp

7905080538 Forwards addl info re organizational chart to support proposed Tech Specs Change 71
STALLINGS, C M Virginia Electric & Power Co 79/05/04 2pp

7905300751 Responds to 790320 telegram re shutdown of units NRC review of pipe stress levels will be limited to safety considerations
DENTON, H R Office of Nuclear Reactor Regulation 79/05/04 2pp

--7905300756 Comments on areas of concern re shutdown units Urges prompt analysis of effects of shutdown
SHANNON, P C Virginia, State of 79/03/20 3pp

7905140239 Forwards proprietary documents requested during 790501-04 special insp
ERLEWINE, J A Stone & Webster Engineering Corp 79/05/08 1p

--7905140245 Requests withholding Technical Guideline EMT-22-O & Technical Rept EMT-612 (ref 10CFR2 790) Affidavit encl
KENNEDY, W J Stone & Webster Engineering Corp 79/05/04 10pp

7905140382 Confirms 790504 telcon w/HT Russell re computer deck associated w/BHOCK O program
KENNEDY, W J Stone & Webster Engineering Corp 79/05/09 1p

7905160335 Notifies that review of computer deck is completed BHOCK O program still unrecovered Piping sys conservatively designed & will perform intended function
KENNEDY, W J Stone & Webster Engineering Corp 79/05/11 1p.

7905210111 Forwards BHOCK I computer program listing Supersedes submittal of 790406 Program listing withheld (ref 10CFR2 790)
KENNEDY, W J Stone & Webster Engineering Corp 79/05/14 1p

7905290335 Summarizes procedures & calculational techniques used in analysis of piping sys designed w/BHOCK II computer program Reanalysis will satisfy 790313 order to show cause
KENNEDY, W J Stone & Webster Engineering Corp 79/05/18 6pp

7905250108 Submits corrections to 780920 proposed Tech Spec Change 70 re listing of hydraulic shock suppressors
STALLINGS, C M Virginia Electric & Power Co 79/05/22 1p.

7905250092 Submits response to 790518 request for info concerning review of methodology in use of oil structure interaction
SPENCER, W C Virginia Electric & Power Co 79/05/24 33pp

7905250132 Submits addl info in response to 790402 request re safety sys analyzed by BHOCK II code, pipe stresses & verification of dynamic analysis codes Info relates to 790313 order to show cause.
SPENCER, W C Virginia Electric & Power Co. 79/05/24 9pp

7905290001 Resubmits 761230 Tech Spec change request as Change 24 No unreviewed safety question involved.
STALLINGS, C M Virginia Electric & Power Co 79/05/24 16pp

G Inspection reports, IE Bulletins & correspondence

7905020040 Forwards IE Insp Repts 50-280/79-10 & 50-281/79-12 on 790214-16 No noncompliance noted.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/12 2pp.

--7905020049 IE Insp Repts 50-280/79-10 & 50-281/79-12 on 790214-16 No noncompliance noted Major areas inspected protection of components in containment, tag out practices, long-term layup & temporary ventilation
ELROD, S A Region 2, Atlanta, Office of the Director
CANTRELL, F S Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/09 4pp

7905020012 Forwards IE Insp Repts 50-280/79-02 & 50-281/79-02 on 790102-0202 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/13 2pp

--7905020019 IE Insp Repts 50-280/79-02 & 50-281/79-02 on 790102-0202 No noncompliance noted Major areas inspected plant physical barriers & preparations for steam generator replacement
BURKE, D J Region 2, Atlanta, Office of the Director
CANTRELL, F S Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/12 7pp

7905070115 Forwards IE Insp Rept 50-281/79-11 on 790213-16 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/17 2pp

--7905070115 IE Insp Rept 50-281/79-11 on 790213-16 No noncompliance noted Major area inspected steam generator replacement
WILCOX, J B, HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/14 3pp

7905010224 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905030319 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/26 2pp

7905010123 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/28 2pp

7905010369 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/30 2pp

7905020025 Forwards IE Insp Repts 50-280/79-13 & 50-281/79-16 on 790321-23 No noncompliance noted
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/04/11 2pp

--7905020033 IE Insp Rept 50-280/79-13 & 50-281/79-16 on 790321-23 No noncompliance noted Major area inspected independent insp effort re 10CFR23 55 interim measures Details withheld (ref 10CFR2 790)
HENNESSY, R J Region 2, Atlanta, Office of the Director
TOBIN, W J Region 2, Atlanta, Safeguards Branch, 79/04/11 1p

7905080534 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/11 1p

7905040234 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/04/14 2pp

7905040271 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/04/14 1p.

7905040448 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905080164 Responds to IE Bulletin 79-03, "Longitudinal Weld Defects in ASME SA-312 Type 304 Stainless Steel Pipe Spools Mfg by Youngstown Welding & Engineering Co." North Anna 1 uses no SA-312 piping, Burry 1 & 2 records are still under review.
STALLINGS, C M Virginia Electric & Power Co 79/04/16 2pp.

DOCKETED ITEMS

7905010484 Forwards IE Bulletin 79-07 "Failures of GE Type AK-2
Type 1A Breaker in Safety-Related Bys * Licensee action
required
MILLER, J P Region 2 Atlanta, Office of the Director
79/04/17 2pp

7905010487 Forwards IE Bulletin 79-06A Revision 1, "Review of
Operational Errors & Bys Misalignments Identified During TMI
Incident"
MILLER, J P Region 2 Atlanta, Office of the Director
79/04/17 2pp

7905070655 Forwards that response to IE Bulletin 79-07 re seismic
analysis of safety-related piping will be provided in
response to NRC 790313
STALLINGS, C M Virginia Electric & Power Co 79/04/23 1p

7905230341 Forwards to IE Bulletin 79-06A "Review of Operational
Errors & Bys Misalignments Identified During TMI Incident"
Review committee was established & detailed review of TMI
incident has been completed
STALLINGS, C M Virginia Electric & Power Co 79/04/26 9pp

7905230355 Ack receipt of 790412 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-281/79-09
MAYHEW, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 79/05/01 1p

7905290372 Responds to NRC 790320 ltr re violations noted in IE Insp
Rept 50-281/79-09 Corrective actions installation of fire
protection header is in progress
STALLINGS, C M Virginia Electric & Power Co 79/04/12 3pp

7905290383 Forwards IE Insp Rept 50-281/79-09 on 790213-16 & notice of
violation
MAYHEW, C E Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 79/03/20 3pp

7905290392 Notice of violation from Insp on 790213-16
Region 2, Atlanta, Office of the Director 79/03/19 1p

7905290378 IE Insp Rept 50-281/79-09 on 790213-16 Noncompliance noted
lack of fire protection sys & equipment for const area
containment & lack of organized const site fire brigade for
steam generator repair program
MILLER, W H Region 2, Atlanta, Office of the Director
BRYANT, J C Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 79/03/19 3pp

7905290706 Forwards response to IE Bulletin 79-04 Valve swing check
valves of three & six inches installed in chemical vol &
control & safety injection sys
STALLINGS, C M Virginia Electric & Power Co 79/05/03 4pp

7905210275 Responds to IE Bulletin 79-06A, Revision 1 Provides requested
info on design changes re containment sump pump trip valve
activation & safety injection logic
STALLINGS, C M Virginia Electric & Power Co 79/05/17 2pp

B Reportable occurrences, LERs & related correspondence

7905010484 Forwards LER 79-011/12T-D
STALLINGS, C M Virginia Electric & Power Co 79/04/27 1p

7905010487 LER 79-011/12T-D on 790414 Individual received excessive
dose while inspecting area beneath vessel Caused by elevated
radiation levels due to incorrect instrumentation refueling
status Individual disciplined
STEWART, W L Virginia Electric & Power Co 79/04/27 2pp

7905070655 Forwards "Analysis & Bys Mod for 480 Volt Emergency Power
Sys." in response to NRC 790416 ltr
STALLINGS, C M Virginia Electric & Power Co 79/05/03 1p

7905070657 "Analysis & Bys Mod for 480 Volt Emergency Power Sys."
Virginia Electric & Power Co 79/05/03 24pp

7905230341 Forwards LER 79-012/08T-0
STALLINGS, C M Virginia Electric & Power Co 79/05/21 1p

7905230344 LER 79-012/08T-0 on 790507 caustic residue discovered on
62 new fuel assemblies Caused by industrial sabotage
Fuel removed & assemblies rinsed Investigation continuing
STEWART, W L Virginia Electric & Power Co 79/05/21 2pp

7905290005 Forwards LER 79-018/01T-0
STALLINGS, C M Virginia Electric & Power Co 79/05/21 1p

7905290010 LER 79-018/01T-0 on 790509 solenoid valve Model 1912A123
by Automatic Switch Co found environmentally unqualified &
reportable per IE Bulletin 79-01 & Tech Specs Valve could
fail to control admission & venting of air during LOCA
STEWART, W L Virginia Electric & Power Co 79/05/23 2pp

DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

7905070459 Forwards info requested in NRC 790206 ltr re fire protection
program Revision to 78051B fire protection outline encl
MAYER, L D Northern States Power Co 79/05/02 18pp

7905300406 Forwards supplemental info on status of security plan
implementation info withheld (ref 10CFR2 790)
MAYER, L D Northern States Power Co 79/05/25 1p

I Financial information

7905150225 Forwards "Financial & Statistical Info" as suppl to "Annual
Financial Rept 1978"
BRUSVEN, A D Northern States Power Co 79/05/10 1p

7905150231 "Financial & Statistical Info," submitted as suppl to
"Annual Financial Rept 1978"
Northern States Power Co 79/05/31 21pp.

DOCKETED ITEMS

73

7905010474 Forwards application for amend to Licenses DPR-42 & DPR-60, changing Tech Specs re pressurizer initiating signals for safety injection signals Amend fee & proposed Tech Spec changes encl
MAYER, L O Northern States Power Co 79/04/26 10pp

7905020462 Forwards ambient sound level survey in response to recent J Lehr request for addl info re ETS
WARD, E C Northern States Power Co 79/04/27 2pp

7905010479 Forwards amend fee of \$4,400 for Licenses DPR-42 & DPR-60
* Northern States Power Co 79/05/01 1p

7905140214 Submits Environ Event Rept 79-03 for 790424-0302 discharge canal gate structure under water, rendering control & monitoring of blowdown flow inoperable
WARD, E C Northern States Power Co 79/05/08 1p

P Operating license stage documents & correspondence

7905020490 Discusses 790315 telcon w/R Bern of Westinghouse re incorrect weights for Volan Model C69B 6-inch check valves used in safety injection sys
SCHWENGER, A Operating Reactors Branch 1 79/04/02 1p

7905020236 Forwards PWRPTS computer code input & affidavit requesting exemption from public disclosure Computer code input withheld (ref 10CFR2 790)
MAYER, L O Northern States Power Co 79/04/18 35pp

7905240300 Forwards Amends 35 & 29 to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability
SCHWENGER, A Operating Reactors Branch 1 79/04/20 3pp

--7905240322 Amends 35 & 29 to Licenses DPR-42 & DPR-60, respectively, changing common station Tech Specs re refueling & incorporating changes to App A Tech Specs to support operation in Cycle 5 w/reload Fuel by Exxon Nuclear Co
SCHWENGER, A Operating Reactors Branch 1 79/04/20 19pp

--7905240329 Safety evaluation supporting Amends 35 & 29 to Licenses DPR-42 & DPR-60, respectively
* Office of Nuclear Reactor Regulation 79/04/20 19pp

--7905240333 Notice of issuance & availability of Amends 35 & 29 to Licenses DPR-42 & DPR-60, respectively.
SCHWENGER, A Operating Reactors Branch 1 79/04/20 3pp

Q Inspection reports, IE Bulletins & correspondence

7905010262 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J O. Region 3, Chicago, Office of the Director 79/03/23 1p

7905040040 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J O. Region 3, Chicago, Office of the Director 79/03/26 1p

7905090126 Forwards IE Insp Repts 50-282/79-06 & 50-306/79-06 on 790227-28 & 0301-02
DAVIS, A B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/03/26 2pp

--7905090131 IE Insp Repts 50-282/79-06 & 50-306/79-06 on 790227-28 & 0301-02. No noncompliance noted Major areas inspected emergency plan, emergency facilities, equipment & supplies, radioactive effluent sys & emergency training
DEBTHANN, M J, EBBIO, T H Region 3, Chicago, Office of the Director 79/03/20 6pp

7905010174 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air"
KEPPLER, J O. Region 3, Chicago, Office of the Director 79/03/28 1p

7905010410 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
KEPPLER, J O. Region 3, Chicago, Office of the Director 79/03/30 1p

7905070344 Responds to IE Bulletin 79-03 All longitudinal welds of ABYM-A31 stainless steel piping 100% radiographed & free of defects. Addl testing unnecessary
WACHTER, L J Northern States Power Co 79/04/10 1p

7905030040 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/11 1p

7905010600 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified during TMI Incident" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040409 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040451 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040376 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905030237 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/17 1p

7905080505 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Buppi"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/21 1p

7905140100 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/79-03 & 50-306/79-03
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/25 1p

--7905140104 Responds to NRC 790323 ltr re violations noted in IE Insp Repts 50-282/79-03 & 50-306/79-03 Corrective actions torque values were reduced & new bolts were retorqued to specified value
WACHTER, L J Northern States Power Co 79/04/10 2pp

7905290290 Responds to IE Bulletin 79-09 GE Type AK-2 breakers not in use at unit
WACHTER, L J Northern States Power Co 79/05/04 1p

R Periodic operating reports & related correspondence

7905010909 Forwards monthly operating rept for Feb 1979
MAYER, L O Northern States Power Co 79/04/25 1p

--7905010311 Monthly operating rept for Feb 1979
HUNSTAD, A A Northern States Power Co 79/03/01 2pp

790
M

7905030364 Forwards LER 79-009/01T-0
MAYER, L O Northern States Power Co 79/04/26 1p

--7905030367 LER 79-009/01T-0 on 790412 notified by vendor that small break in pressurizer indicator Lp may hang up while Pp decreases, delaying safety injection Westinghouse recommends manually initiating safety injection implements
HUNSTAD, A A Northern States Power Co 79/04/26 1p

7905040521 RO 79-14 on 790427 fuel loading pattern of Cycle 5 core is in error. Core has not achieved criticality; unit still in refueling shutdown Core loading pattern will be corrected.
TIERNEY, F P Northern States Power Co 79/04/27 1p

7905080543 Forwards LER 79-012/01T-0
MAYER, L O Northern States Power Co 79/05/02 1p

DOCKETED ITEMS

--7905080569 LER 79-012/01T-0 on 790418 insp of Region 4 assemblies removed during refueling revealed rod bowing greater than previously discharged assemblies. All Region 4 fuel has been discharged from core vendor investigating
HUNSTAD, A A Northern States Power Co 79/05/02 1p

7905110127 Forwards LER 79-008/03L-0
HAYER, L O Northern States Power Co 79/05/05 1pp

--7905110131 LER 79-008/03L-0 on 790408 safety injection pump 11 failed to start automatically, started in manual Cause unknown Event could not be repeated Feasibility of monitor light to detect failures being studied
HUNSTAD, A A Northern States Power Co 79/05/08 1p

7905160352 Forwards LER 79-010/03L-0
HAYER, L O Northern States Power Co 79/05/10 1p

--7905160358 LER 79-010/03L-0 on 790410 high head safety injection valve to reactor vessel, MV-32067, failed to open on demand Subsequent opening attempts were successful Cause of failure not found
HUNSTAD, A A Northern States Power Co 79/05/10 2pp

7905150466 Forwards LER 79-014/01T-0
HAYER, L O Northern States Power Co 79/05/11 1p

--7905150468 LER 79-014/01T-0 on 790427 informed by Exxon of error in core loading pattern, specifically gadolinia-bearing assemblies not properly located Assemblies repositioned on 790430
HUNSTAD, A A Northern States Power Co 79/05/11 1p

DOCKET 50-284 IDAHO STATE UNIV RESEARCH REACTOR

J Insurance & indemnity information

7905160334 Forwards Amend 11 to Indemnity Agreement E-49, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 3pp

7905240604 Forwards executed Amend 11 to Indemnity Agreement E-49
EASTMAN, P H Idaho State Univ 79/05/15 2pp

DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

F Security, medical, emergency & fire protection plans

7905090046 Forwards revision to physical security plan Revision withheld (ref 10CFR2 790)
SHORT, T E Omaha Public Power District 79/05/03 1p

Financial information

905300347 Forwards "Annual Financial Rept 1978"
PETERSEN, H E Omaha Public Power District 79/05/22 1p

--7905300353 "Annual Financial Rept 1978"
" Omaha Public Power District 79/02/23 31PP

I Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 189, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHINI, J American Nuclear Insurers 79/05/01 1p

7905160164 Forwards Amend 6 to Indemnity Agreement B-67, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 3pp

7905160382 Forwards Endorsements 35, 36, 37, 38 & 39 to MAELU Policy NF-63 & Endorsements 39, 40, 41, 42, 43 & 44 to NELIA Policy NF-207,
PETERSEN, H E Omaha Public Power District 79/05/09 12pp,

7905160406 Forwards executed Amend 6 to Indemnity Agreement B-67
PETERSEN, H E Omaha Public Power District 79/05/09 3pp

P Operating license stage documents & correspondence

7905100251 "Omaha Dose Measurements at Zion & Fort Calhoun Stations"
BYER, N C, BUNTING, R L, NIESCHMIDT, E B, EO & O, Inc FIN A-6075
NUREG/CR-0753 79/04/30 137pp Available at NTIS, \$7 25

7905090317 Forwards responses to Questions 1 & 2 re auxiliary feeders, sys Response to Question 3 will be submitted by 790503
MORRIS, K J Omaha Public Power District 79/05/01 2pp

7905080446 Forwards response to 790502 request for addl info re steam generator water mass, signals which originate ECCB & setpoint values
MORRIS, K J Omaha Public Power District 79/05/02 6pp

7905100312 Responds to 790501 questions re licensee experience w/ pressurizer power operating relief Valves lifting due to instrumentation & control failures & transient events
MORRIS, K J Omaha Public Power District 79/05/03 2pp

7905090358 Forwards application for amend to License DPR-40 Certificate of Svc & amend fee encl
MACRAE, C F LeBoeuf, Lamb, Leiby & MacRae 79/05/08 3pp

--7905090363 Application for amend to License DPR-40, deleting condition which require collection & reporting of nonradiological water quality data or info
SHORT, T E Omaha Public Power District 79/05/04 4pp

7905240562 Submits info re main feedwater sys & pressurizer code refs, valves, in response to NRC 790507 telecopy
MORRIS, K J Omaha Public Power District 79/05/10 4pp

7905150316 Forwards application for amend to OL Certificate of Svc encl
" LeBoeuf, Lamb, Leiby & MacRae 79/05/14 3pp

--7905150319 Application for amend to License DPR-40, changing Tech E, to prevent low temp reactor coolant sys overpressurization
SHORT, T E Omaha Public Power District 79/05/11 3pp

7905310243 Forwards application for amend to License DPR-40 Certificate of Svc encl
MACRAE, C F LeBoeuf, Lamb, Leiby & MacRae 79/05/30 3pp

--7905310248 Application for amend to License DPR-40 to change Tech E, re fire protection sys
SHORT, T E Omaha Public Power District 79/05/25 6pp

G Inspection reports, IE Bulletins & correspondence

7905150085 Forwards IE Circular 79-04, "Loose Locking Nut on Limiting Valve Operators"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/15 1p

7905010453 Forwards IE Bulletin 78-12B, "Atypical Weld Matl in Reactor Pressure Vessel Welds"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/19 1p

7905020440 Forwards IE Circular 79-05, "Moisture Leakage in Stranded Wire Conductors"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/20 1p

7905020248 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/23 1p

7905290222 Responds to IE Bulletin 78-12 & 78-12A re atypical weld matl in reactor pressure vessel Util currently performing records search & will submit generic rept
SHORT, T E Omaha Public Power District 79/03/23 1p

7905020413 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tank"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/25 1p.

7905150306 Forwards IE Insp Rept 50-285/79-04 on 790319-22 No noncompliance noted
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/03/27 2pp.

--7905150310 IE Insp Rept 50-285/79-04 on 790319-22, No noncompliance noted Major areas inspected records program, plant operation & plant conditions, as observed during plant tours
MADSEN, O L, KELLEY, D L Region 4, Dallas, Reactor Operations Nuclear Support Branch, 79/03/27 3pp

7905020434 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/28 1p.

DOCKETED ITEMS

75

7905140146 Forwards IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp " Licensee action required
BEYFRIT,K V Region 4, Dallas, Office of the Director 79/03/30 1p

7905150049 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin "
BEYFRIT,K V Region 4, Dallas, Office of the Director 79/03/30 1p

7905150211 Notifies that C-E informed Util that generic response to IE Bulletin 78-12B, re matl in reactor vessel welds, cannot be provided before 790813 Util will submit plant-specific response by 790914
SHORT,T E Omaha Public Power District 79/04/03 1p

7905230618 Responds to IE Bulletin 79-03 Util has in intention of using ASME SA-312 Type 304 or other welded pipe mfg by Youngstown Welding & Engineering Co
SHORT,T E Omaha Public Power District 79/04/10 1p

7905240486 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " Licensee action required
BEYFRIT,K V Region 4, Dallas, Office of the Director 79/04/14 1p

7905240623 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
BEYFRIT,K V Region 4, Dallas, Office of the Director 79/04/14 1p

7905270073 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required
BEYFRIT,K V Region 4, Dallas, Office of the Director 79/04/14 1p

7905270104 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at TMI "
BEYFRIT,K V Region 4, Dallas, Office of the Director 79/04/16 1p.

7905270200 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required
BEYFRIT,K V, Region 4, Dallas, Office of the Director 79/04/17 1p.

7905280334 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl.,"
BEYFRIT,K V Region 4, Dallas, Office of the Director 79/04/21 1p.

7905100128 Forwards responses to IE Bulletin 79-06B "Review of Operational Errors & Sys Misalignments Identified During TMI " Operators reminded to check confirmatory indication when responding to accident conditions
SHORT,T E Omaha Public Power District 79/04/23 34pp

7905240672 Responds to IE Bulletin 79-07 re seismic stress analysis of safety-related piping Util does not use methods described in bulletin
SHORT,T E, Omaha Public Power District 79/04/23 9pp

7905290499 Responds to IE Bulletin 79-04 No Velan swing check valves are installed or scheduled to be installed in Seismic I piping.
SHORT,T E Omaha Public Power District 79/04/23 1p

7905230257 Forwards IE Insp Rept 50-285/79-05 on 790326-30 Notice of violation withheld (ref 10CFR2 790)
MADSEN,Q L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/24, 2pp

--7905230268 IE Insp Rept 50-285/79-05 on 790326-30 Noncompliance noted physical barriers do not meet requirements Details withheld (ref 10CFR2 790)
CALDWELL,R A., EVANS,C A, Region 4, Dallas, Office of the Director, MADSEN,Q L Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/04/17 1p

790523045B Notifies that certain safety-related electrical equipment failed to meet environ qualification criteria,per IE Bulletin 79-01 Valves will be replaced
SHORT,T.E Omaha Public Power District 79/05/15 2pp

R. Periodic operating reports & related correspondence

7905140238 Forwards monthly operating rept for Apr 1979.
SHORT,T E, Omaha Public Power District 79/05/09 1p

--7905140240 Monthly operating rept for Apr 1979
HICKLE,B J Omaha Public Power District 79/05/09 7pp

B Reportable occurrences, LERs & related correspondence

7905140487 Forwards LER 78-001/03L-0
JONES,W C Omaha Public Power District 78/02/01 1p

7905140494 LER 78-001/03L-0 on 780116 during monthly calibr of recirculation actuation signal pressure switches found switch A/LC-383 drifted from setpoint tolerance
Static-O-Ring Model 12NN-KK0A, XIV readjusted & checked
PETERSON,Q, CONNOLLEY,J L Omaha Public Power District 78/01/20 2pp

7905150122 Forwards PNO-79-67R & 79-77(NRR)
MADSEN,Q L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/11 1p

7905040112 Forwards PNO-79-67S
MADSEN,Q L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/12 1p

7905150261 Forwards PNO-79-67T correction
MADSEN,G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/13 1p

7905010533 Forwards PNO-79-67U,V & W
MADSEN,G L Region 4, Dallas, Office of the Director 79/04/16 1p

7905010546 Forwards PNO-79-67X & Y
MADSEN,G L Region 4, Dallas, Office of the Director 79/04/18 1p

7905010559 Forwards PNO-79-67Z
MADSEN,Q L Region 4, Dallas, Office of the Director 79/04/19 1p

7905010401 Forwards PNO-79-67AA,AB,AC & AD
MADSEN,Q L Region 4, Dallas, Office of the Director 79/04/24 1p

7905070541 Forwards LER 79-009/03L-0
ANDREWS,R L Omaha Public Power District 79/04/30 1p

--7905070545 LER 79-009/03L-0 on 790406 ac matrix failed test Caused by failure of mercury wetted relay to break contact Relay exercised & found normal Matrix will continue to be tested
CORE,M, PETERSON,Q Omaha Public Power District 79/04/19 4pp

7905150100 Forwards PNO-79-67AF,AG,AH,AI & AJ, re incident at TMI
MADSEN,Q L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/30 1p

7905240440 Forwards PNO-79-67AK & AL
MADSEN,Q L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/02 1p

7905210256 Forwards LER 79-011/03L-0
ANDREWS,R L Omaha Public Power District 79/05/07 1p

--7905210259 LER 79-011/03L-0 on 790424 channel A dc sequencer SI-1 deenergized matrix lights Caused by GE CR120A 125 volt dc relay faulting internally Relay replaced & sequencer tested satisfactorily
CONNOLLEY,J L, PETERSON,Q R Omaha Public Power District 79/04/26 4pp

7905210268 Forwards LER 79-010/03L-0
ANDREWS,R L Omaha Public Power District 79/05/16 1p

--7905210271 LER 79-010/03L-0 on 790420 containment spray pump SI-3B failed to start by control switch Caused by racking of circuit breaker beyond connected position,resulting in binding of breaker Breaker racked out & back in
CONNOLLEY,J L Omaha Public Power District 79/05/16 3pp

7905220300 Forwards LER 79-012/03L-0
ANDREWS,R L Omaha Public Power District 79/05/16 1p

--7905220306 LER 79-012/03L-0 on 790507 during surveillance test, matrix test failed for BC matrix Caused by failure of mercury wetted relay in matrix circuit,CP Clare Model HQZX 1011, to break contact Relay removed & contacts cleaned
CORE,M, PETERSON,Q Omaha Public Power District 79/05/16 4pp

DOCKETED ITEMS

7905300948 Forwards LER 79-015/01T-0
ANDREWS, R L Omaha Public Power District 79/05/25 1p

--7905300557 LER 79-015/01T-0 on 790511 seismic support appeared inadequate for component cooling water piping-to-containment cooling & filtering unit VA-3A Analyses indicated that clamping piping-to-cooling unit will provide needed support
MUELLER, R Omaha Public Power District 79/05/22 4pp

DOCKET 50-286 INDIAN POINT STATION, UNIT 3

F Security, medical, emergency & fire protection plans

7905220380 Forwards, under protest, filing fee for NRC review of revised emergency plan
EARLY, P J Power Authority State of New York 79/05/14 1p

G Adjudicatory correspondence

7905250039 Offers to provide Board "Comparison of Simulation Models Used in Assessing Effects of Power Plant-Induced Mortality of Fish Population," by GL Swartzman, RB Deniso & C Conan of Univ of WA
LEWIS, S H Branch 2 79/03/30 1p

7905080198 Forwards "Comparison of Simulation Models Used in Assessing Effects of Power Plant-Induced Mortality on Fish Populations" per telcon request W/o encl
MOORE, J E Branch 2 79/04/16 1p

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHINI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905140407 Forwards Amend 21 to Indemnity Agreement B-19 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp

P Operating license stage documents & correspondence

7905070311 Forwards Amend 25 to License DPR-64 & notice of issuance & availability
SCHWENCER, A Operating Reactors Branch 1 79/03/29 4pp

--7905070315 Amend 25 to License DPR-64, revising Tech Specs to allow continuous chlorination of plant discharge from new sewage treatment facility
SCHWENCER, A Operating Reactors Branch 1 79/03/29 6pp

7905040513 Forwards "Steam Generator Operating History Questionnaire," Revision 1
EARLY, P J Power Authority State of New York 79/04/30 1p

--7905040518 "Steam Generator Operating History Questionnaire," Revision 1
* Power Authority State of New York 79/04/30 13pp

7905070549 Ack receipt of NRC 790412 ltr Willing to cooperate in planned analysis scheduled for week of 790506
CAHILL, W J Consolidated Edison Co of New York 79/04/30 1p

7905100136 Forwards application to amend License DPR-64, proposed Tech Spec changes & \$4,000 fee W/o check
EARLY, P J Power Authority State of New York 79/05/02 3pp

--7905100161 Application for amend to License DPR-64, adding definition to Section 1 App A & new specs for limiting conditions for operation & surveillance requirements to radiological effluent Tech Specs.
* Power Authority State of New York 79/04/30 73pp

7905170244 Forwards "Evaluation of Effectiveness of Continuously Operating Fine Mesh Traveling Screen for Reducing Ichthyoplankton Entrainment" Affidavit & Certificate of Svc encl
CAHILL, W J Consolidated Edison Co of New York 79/05/14 5pp

--7905170249 "Evaluation of Effectiveness of Continuously Operating Fine Mesh Traveling Screen for Reducing Ichthyoplankton Entrainment"
* Consolidated Edison Co of New York 79/04/30 30pp

7905230581 Forwards responses to 790510 request for info re heaters, relief valves, loss of feedwater events, steam operator & small break analysis
BAYNE, J P Power Authority State of New York 79/05/18 5pp

--7905230556 Forwards request for info re ability of currently operating PHRs to safely withstand TH1-2 type events
SCHWENCER, A Operating Reactors Branch 1 79/05/10 4pp

Q Inspection reports, IE Bulletins & correspondence

7905080099 Forwards IE Insp Rept 50-286/79-02 on 790121-0217 No noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/16 2pp

--7905080110 IE Insp Rept 50-286/79-02 on 790121-0217 No noncompliance noted. Major areas inspected log & record reviews, followup on previous insp items & observation of control room personnel during simulated emergency drill
REBELOWSKI, T, JOHNSON, D Region 1, Philadelphia, Office of the Director
KEIMIG, R R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/15 9pp

7905010129 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/23 1p

7905030279 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/26 1p

7905010038 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/28 1p

7905030181 Requests extension of time to respond to IE Bulletins 78-12, 12A, & 12B, due to delay in issuance
BAYNE, J P Power Authority State of New York 79/03/28 1p

7905010313 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
GRIER, B H Region 1, Philadelphia, Office of the Director, 79/03/30 2pp

7905020075 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TH1 Incident" Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/11 1p

7905070161 Ack receipt of 790323 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-286/79-04
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/11 1p

--7905070168 Responds to NRC 790301 ltr re violations noted in IE Insp Rept 50-286/79-04 Corrective actions superseded procedures removed from file, procedures & test schedule revised
BAYNE, J P Power Authority State of New York 79/03/23 2pp

--7905070172 Forwards IE Insp Rept 50-286/79-04 on 790206-09 & notice of violation
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/01 2pp

--7905070177 Notice of violation from insp on 790206-09
* Region 1, Philadelphia, Office of the Director 79/03/01 2pp

DOCKETED ITEMS

77

--7903070102 IE Insp Rept 50-286/79-04 on 790206-09. Noncompliance noted failure to use latest revision of procedure & failure to adhere to procedures
MAUNACK, M H, BLUMBERG, N J Region 1, Philadelphia, Office of the Director
KINTER, H B Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 7/7/02/28 13pp

05250241 Responds to IE Bulletin 79-03 re longitudinal weld defects in certain pipe spools mfg by Youngstown Welding & Engineering Co Piping used in const, but not w/o filler metal Piping under 4-inches will be investigated by 790525
BAYNE, J P Power Authority State of New York 7/9/04/13 2pp

105020245 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required.
GRIER, B H Region 1, Philadelphia, Office of the Director 7/9/04/14 1p

105040019 Forwards IL Bulletin 79-06B, "Review of Operational Errors & Bus Misalignments Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director 7/9/04/14 1p

7905040245 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director 7/9/04/14 1p

7905010004 Forwards IL Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys" Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director 7/9/04/17 1p

7905020240 Forwards IL Bulletin 79-06A, Revision 1, "Review of Operational Errors & Bus Misalignments Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director 7/9/04/10 1p

7905010447 Comments on IE Bulletin 79-06A re Westinghouse PWR facilities implementation of bistable trip would create situation where safety injection actuation could be susceptible to single bus perturbations
DEBOLD, T K New York, State of 7/9/04/25 2pp

7905310194 Forwards addl response to IE Bulletin 79-07 re seismic pipe stress reanalysis, as requested by NRC on 790317 Matl supplements info in 790424 ltr
SCHWILDER, J R Power Authority State of New York 7/9/05/22 36pp

7905310443 Forwards addl info to IE Bulletin 79-07 re piping seismic stress analytic method, in response to 790523 request Matl supplements 790424 & 790522 ltrs
EARLE, P J Power Authority State of New York 7/9/05/24 2pp

R Periodic operating reports & related correspondence

7905220176 Forwards effluent monitoring & impingement data specified in Section 401 Certification for Apr 1979
MONTI, W A Consolidated Edison Co of New York 7/9/05/10 17pp

7905150302 Forwards monthly operating rept for Apr 1979
BAYNE, J P Power Authority State of New York 7/9/05/11 1p

--7905150304 Monthly operating rept for Apr 1979.
CONNELL, C Power Authority State of New York 7/9/05/01 6pp

7905210392 Forwards daily record of fish collections for Apr 1979 w/daily species breakdown & total weight for Units 2 & 3
GRIER, B H Region 1, Philadelphia, Office of the Director 7/9/05/14 3pp

B Reportable occurrences, LERs & related correspondence

7905250172 Describes LER-003-01T-0 on 790328 Westinghouse review revealed potential for safety analysis methodology to lead to calculated DND ratios less conservative than previously reported Constitutes 24-hr required notification
BAYNE, J P Power Authority State of New York 7/9/03/29 2pp

7905220319 LER 79-011 has been voided
* Power Authority State of New York 7/9/04/01 1p

7905220322 LER 79-010 has been voided
* Power Authority State of New York 7/9/04/01 1p

7905220327 LER 79-007 has been voided.
* Power Authority State of New York 7/9/04/01 1p

7905220331 LER 79-008 has been voided
* Power Authority State of New York 7/9/04/01 1p

7905220334 LER 79-009 has been voided
* Power Authority State of New York 7/9/04/01 1p

7905220338 LER 79-006 has been voided
* Power Authority State of New York 7/9/04/01 1p

7905010516 Forwards LER 79-004/03L-0
BAYNE, J P Power Authority State of New York 7/9/04/26 1p

--7905010522 LER 79-004/03L-0 on 790327 condensate storage tank level fell below Tech Spec limit during hot shutdown Caused by use of steam generator blowdown sys which was being held at max. Onsite demineralization plant to be added
GUMBLE, F W Power Authority State of New York 7/9/04/26 2PP

7905090301 Forwards LER 79-005/03L-0
BAYNE, J P Power Authority State of New York 7/9/05/04 1p

--7905090305 LER 79-005/03L-0 on 790405 svc water pump 34 removed due to low discharge pressure; main pump shaft broke, disabling one of three essential head pumps Caused by bearing failures making shaft break repairs are pending
GUMBLE, F W Power Authority State of New York 7/9/05/04 1p

7905190015 Forwards LER 79-012/04X-1
CAHILL, W J Consolidated Edison Co of New York 7/9/05/10 1p

--7905190018 LER 79-012/04X-1 on 790213 activity of precipitation sample exceeded 10 times control station level Caused by tritium releases from source external to facility Manufacturer in area has modified installation to prevent recurrence
MASCULLI, S Consolidated Edison Co of New York 7/9/05/10 3pp

7905190021 Forwards LER 79-015/04T-0
CAHILL, W J Consolidated Edison Co of New York 7/9/05/10 1p

--7905190025 LER 79-015/04T-0 on 790405 activity of precipitation sample exceeded 10 times control station level Caused by tritium releases from source external to facility Manufacturer in area has modified installation to prevent recurrence
MASCULLI, S Consolidated Edison Co of New York 7/9/05/10 2pp

DOCKET 50-287 CONEEN NUCLEAR STATION, UNIT 3

F Security, medical, emergency & fire protection plans

7905290090 Discusses 790213 submission of security plan for storage of spent fuel & 790216 telcon re requirement for security plan mods Initial plan is subj to withholding from public record of transmittal is required
ROUSE, L C Fuel Reprocess & Recycle Branch 7/9/03/29 1p

7905140283 Forwards emergency procedure EP/0/A/1800/4, "Loss of Reactor Coolant," containing instructions for operator action for small breaks
PARKER, W O Duke Power Co 7/9/05/09 29pp

H General correspondence

7905250131 Urges careful review of staff rept before ordering shutdown of facility, since action could cause extensive power curtailments & higher fuel costs for 1 2 million customers in Carolina piedmont
HELMS, J Senate 7/9/04/26 1p

7905020254 Expresses gratitude for decision to close facility
THOMPSON, M W Affiliation Unknown 7/9/04/28 1p

J Insurance & indemnity information

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 7/9/05/01 1p

7905140438 Forwards Amend 13 to Indemnity Agreement B-44 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 7/9/05/01 6pp

DOCKETED ITEMS

7905160361 Submits executed copy of Amend 13 to Indemnity Agreement B-44, reflecting changes in 10CFR140
PARKER, W O Duke Power Co 79/05/08 3pp

7905310348 Forwards replacement copy of Amend 8 to Indemnity Agreement B-44 in response to 790516 request W/copy of util 740412 transmittal ltr
PARKER, W O Duke Power Co 79/05/22 3pp

P Operating license stage documents & correspondence

7905150104 Notices of refund of fees, remitted 780705, for authority to transfer fuel between facility & Crystal River Unit 3 Refund will be sent when processed
HILLER, W O License Fee Management Branch 79/05/03 1p

7905250014 Forwards Amends 69, 69 & 66 to Licenses DPR-38, DPR-47 & DPR-55, respectively, EIA & notice of issuance & availability
REID, R W Operating Reactors Branch 4 79/03/02 3pp

--7905250018 Amends 69, 69 & 66 to Licenses DPR-38, DPR-47 & DPR-55, respectively, which revises ETS by deleting aquatic surveillance program & special study programs
REID, R W Operating Reactors Branch 4 79/03/02 11pp

7905190155 Responds to R Mattson & D Ross concerning value of running natural circulation test on B&W reactor
TEDESCO, RL Assistant Director for Plant Systems 79/04/03 4pp

7905080130 Responds to 790329 submittal re radiological effluent Tech Spec, which omitted solid radwaste process control program Requests omitted portion
REID, R W Operating Reactors Branch 4 79/04/18 2pp

7905010521 Forwards documentation, design info & projected implementation schedules re emergency feedwater sys, as committed in NRC 790425 meeting
PARKER, W O Duke Power Co 79/04/25 4pp

7905010530 Forwards addl info re Ofc of Nuclear Reactor Regulation status rept Requests addl dialogue w/NRC re control sys
LEE, W B Duke Power Co 79/04/25 1p

7905030371 Informs that util has conducted review of plant design & operation, including goal of improving reliability of normal feedwater sys & added assurance of emergency feedwater supply to steam generators Design adequate
GHEN, W H Duke Power Co 79/04/25 2pp

7905040047 Corrects error in 790419 ltr to NRC Reported period of facility mods should be Jan-Dec 1979
PARKER, W O Duke Power Co 79/04/25 1p

7905110068 Informs that small break analyses review is complete Analyses are unacceptable & incomplete
ROBZTOCZY, Z R Analysis Branch 79/04/25 1p

--7905110074 Comments on draft rept received 790420 too lengthy, does not concentrate on important issues & has dozens of incorrect & misleading statements Rept should be reorganized
ROBZTOCZY, Z R Analysis Branch 79/04/25 5pp

7905240982 Responds to 790320 ltr requesting advice on allowable time interval for submittal of repts to NRC
REID, R W Operating Reactors Branch 4 79/04/26 2pp

7905020283 Informs of util position on issuance of formal order re continued plant operation Written issuance is undesirable as policy & legally unnecessary
LEE, W B Duke Power Co 79/04/29 1p

7905040352 Forwards response to 780329 request for addl info re proposed changes to hydraulic shock suppressor Tech Spec
PARKER, W O Duke Power Co 79/04/30 2pp

7905080433 Forwards proposed revision to Tech Specs covering reactor bldg hydrogen purge sys, penetration room ventilation sys, reactor bldg purge filters & spent fuel pool ventilation sys
PARKER, W O Duke Power Co 79/05/01 11pp

7905080566 Forwards proposed revision to Tech Specs, deleting Tech Spec 4 13 which is no longer required
PARKER, W O Duke Power Co 79/05/01 4pp

7905240466 Documents completion of 761001 proposal to delete Tech Specs re tendon, anchorage & liner plate surveillance programs. License fee not required
PARKER, W O Duke Power Co 79/05/02 1p

7905140189 In response to NRC 790418 request, forwards proposed Tech Spec re plant solid radwaste process control program
PARKER, W O Duke Power Co 79/05/07 5pp

7905240231 Forwards status on improvements to emergency feedwater sys per WD Parker 790423 ltr & WS Lee 790426 ltr
PARKER, W O Duke Power Co 79/05/07 100pp

7905140365 Lists drawings used for installation of automatic starting of interconnected emergency feedwater sys, which were sent to NRC on 790503
PARKER, W O Duke Power Co 79/05/09 1p

7905140268 Forwards "Emergency Feedwater Sys, Sys Concept & Analysis" Pump installation to be complete by 790825 Oversized drawing in Central Files
PARKER, W O Duke Power Co 79/05/10 9pp

7905160389 Forwards "B&W 177 Fuel Assembly Owners Group Asymmetric Lx Loads Evaluation Program, Phase 2," dtd 790410 Supersedes program provided on 790111
PARKER, W O Duke Power Co 79/05/10 1p

--7905160390 "B&W 177 Fuel Assembly Owners Group Asymmetric LOCA Lx Evaluations Program, Phase 2"
* Duke Power Co 79/04/10 9pp

7905230487 Notifies that analyses were performed w/actual Cycle 4 burnup to ascertain changes required for operation at full rated power during Cycle 5 Results indicate no need for changes in core loading or Tech Spec
PARKER, W O Duke Power Co 79/05/17 1p

7905230543 Forwards revised sys concept & analysis re addition of 12 motor-driven emergency feedwater pumps Supersedes 790510 submittal W/oversized drawing
PARKER, W O Duke Power Co 79/05/17 10pp

7905240593 Submits results of addl analyses re 790330 proposed Tech Specs changes for operation at full rated power during Cycle 5
PARKER, W O Duke Power Co 79/05/17 1p

7905240475 Responds to IE Bulletin 79-05B re TMI incident Forwards proposed amend to Tech Specs, changing setpoints of pressurizer electromagnetic relief valve & reactor coolant sys high pressure trip
PARKER, W O Duke Power Co 79/05/21 11pp

7905240478 Forwards design description for safety grade anticipatory reactor trip on turbine trip or loss of main feedwater Mode will be installed for each refueling outage following NRC approval
PARKER, W O Duke Power Co 79/05/21 5pp

7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970
PORTER, F L EDS Nuclear, Inc 79/05/21 9pp

--7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program OE has no record of reanalysis for Cooper piping sys
STEPHENS, P W General Electric Co, Nuclear Energy Products Div 79/01/24 18pp

7905310211 Forwards proposed Tech Specs revision re limiting conditi for operation & surveillance requirements
PARKER, W O Duke Power Co 79/05/23 8pp

Q Inspection reports, IE Bulletins & correspondence

7905230482 Forwards IE Insp Repts 50-269/79-04, 50-270/79-04, & 50-289/79-04 on 790205-07 No noncompliance noted
LEWIS, R L Region 2, Atlanta, Reactor Operations Nuclear Supp. Branch 79/03/12 2pp

--7905230503 IE Insp Repts 50-269/79-04, 50-270/79-04, 50-287/79-04 & 50-289/79-04 on 790205-07 No noncompliance noted fire protection/prevention program, QA surveillance, fire insurance repts & administrative control procedures
BRADFORD, W H, TAYLOR, P A, KELLOGG, P J, Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/05 4pp

7905010177 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P, Region 2, Atlanta, Office of the Director 79/03/23 2pp

DOCKETED ITEMS

79

- 7905010307 Forwards II Info Notice 79-07, "Rupture of Radwaste Tanks"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/03/26 2pp
- 7905230272 Discusses B&W rept, "Records Investigation Rept Related to Off Chemistry Welds in Heat Surveillance Specimens & Response to II Bulletins 79-12 & 79-12A Suppl." rept accurately represents data for reactor pressure vessels
PARKER, W O Duke Power Co 79/01/27 1p
- 7905010090 forwards II Info Notice 79-08, "Interconnection of Contaminated Hys w/Over Air Hys Used as Source of Breathing Air"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/01/20 2pp
- 7907010170 Forwards II Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/07/30 2pp
- 7905230279 Responds to II Bulletin 79-02 re longitudinal weld defects. No AGRH UA J12, type B4 piping or any other welding w/o filler metal piping mfg by Youngstown Welding is in use or planned for use
PARKER, W O Duke Power Co 79/04/04 1p
- 7905100240 forwards responses to II Bulletins 79-05 & 79-05A, "Nuclear Incident at TMI"
PARKER, W O Duke Power Co 79/04/10 2pp
- 7905100299 Forwards Abnormal Occurrence Rept AD 207775 07
PARKER, W O Duke Power Co 79/06/27 1p
- 7905100101 AD 207775 07 on 790611 excessive reactor coolant sys cooldown rate occurred caused by operator error & failure of power-actuated pressurizer relief valve HRC 66 to close
* Duke Power Co 79/06/27 1p
- 7905100101 forwards addl info re AD 207775 07 Corrective Actions shutdown procedures revised, relief valves will be examined & quench tank rupture disc replaced
PARKER, W O Duke Power Co 79/08/08 1pp
- 7905020040 Airt receipt of 790126 ltr informing NRC of steps taken to correct violations noted in II Insp Repts 70 269779 01, 70 270779 01 & 70 287779 01
KIRKHA, W H Region 2, Atlanta, Safeguards Branch 79/04/10 1p
- 7905020064 Responds to NRC 790106 ltr re violations noted in II Insp Repts 70 269779 01, 70 270779 01 & 70 287779 01 Corrective actions withheld (ref 10C102 790)
PARKER, W O Duke Power Co 79/01/26 1p
- 7905020070 forwards II Insp Repts 70 269779 01, 70 270779 03 & 70 287779 01 on 790205 06 Notice of violation withheld (ref 10C102 790)
KIRKHA, W H Region 2, Atlanta, Safeguards Branch 79/01/06 2pp
- 7905020087 II Insp Repts 70 269779 01, 70 270779 01 & 70 287779 01 on 790205 06 Noncompliance noted areas of testing/maint & detection aids Details withheld (ref 10C102 790)
TOBIN, W J Region 2, Atlanta, Office of the Director
O'REILLY, J P Region 2, Atlanta, Safeguards Branch 79/07/06 1p
- 7905100046 Responds to II Bulletin 79-05A, items 7, 8, 10 & 11 re TMI Incident All manual valves which could defeat or compromise flow are locked open
PARKER, W O Duke Power Co 79/04/13 8pp
- 7905040176 Forwards II Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 1p
- 7905040267 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" license action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 2pp
- 7905040381 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 1p
- 7905030160 Forwards II Bulletin 79-09, "Failures of QC Type AK-2 Circuit Breaker in Safety Related Sys" license action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/17 2pp
- 7905020429 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/18 2pp
- 7905240452 Responds to IE Bulletin 79-05, Item 3, re TMI incident Reactor protective sys high RCS pressure setpoint lowered to not greater than 2,300 psig Pressurizer power operated relief valve raised nominally to 2,450 psig
PARKER, W O Duke Power Co 79/04/21 1p
- 7905240303 Forwards response to IE Bulletin 79-07 re computer program used for piping analysis Algebraic summation methods were not used in piping analysis
PARKER, W O Duke Power Co 79/04/24 2pp
- 7905110264 Forwards 790505 response to IE Bulletin 79-05B, Items 1, 2, 4 & 6, re TMI incident
PARKER, W O Duke Power Co 79/05/05 1p
- 7905110268 Responds to IE Bulletin 79-05B, Items 1, 2, 4 & 6 Emergency procedures for loss of reactor coolant flow, steam supply sys rupture, uncontrollable flooding of turbine bldg & loss of normal HPI makeup or letdown have been revised
PARKER, W O Duke Power Co 79/05/05 6pp
- 7905300541 Forwards inservice insp program
PARKER, W O Duke Power Co 79/05/15 1p
- 7905300550 Inservice insp program
* Duke Power Co 79/05/15 75pp
- 7905220351 Forwards description of post-TMI operator training, per 790515 discussions & IE Bulletin 79-05, 79-05A & B Operating shifts have adequate knowledge to operate reactors in all modes
PARKER, W O Duke Power Co 79/05/16 4pp
- R Periodic operating reports & related correspondence
- 7905220358 Forwards monthly operating rept for Apr 1979
PARKER, W O Duke Power Co 79/05/15 1p
- 7905220365 Monthly operating rept for Apr 1979
REAVIS, J A Duke Power Co 79/05/15 16pp
- S Reportable occurrences, LERs & related correspondence
- 7905110020 RD 287/78-1B on 781129 while engineered safeguards analog channel A was tripped in order to allow repairs, channel B tripped Event not considered to be recurring problem Sys returned to normal operating condition w/o problem
* Duke Power Co 79/01/15 2pp
- 7905140306 RD-287/79-4, which was to have been submitted by 790327, will be submitted by 790403, as investigation is still in progress
PARKER, W O Duke Power Co 79/03/27 1p

DOCKETED ITEMS

--7905250427 LER 79-014/OIT-0 on 790507 nuclear instrumentation power indication less than thermal power levels caused by changes in core characteristics which accompany changes in power levels
LEWIS, S R Duke Power Co 79/05/21 3pp

7905310404 Forwards LER 79-010/O3L-0
PARKER, W O Duke Power Co 79/05/23 1p

--7905310410 LER 79-010/O3L-0 on 790423 reactor bldg gaseous radiation monitors made inoperable when containment isolation valve on monitor inlet line failed caused by ruptured operator diaphragm
LEWIS, S R Duke Power Co 79/05/23 3pp

DOCKET 50-288 REED COLLEGE RESEARCH REACTOR

J Insurance & Indemnity Information

7905160265 Forwards Amend 9 to Indemnity Agreement E-52, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905140341 Forwards Amend 9 to Indemnity Agreement E-52
MCFARLANE, E O Reed College 79/05/07 2pp

DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

7905290556 Forwards Suppl 2 to fire protection SER, in response to 790313 ltr
REID, R W Operating Reactors Branch 4 79/04/14 2pp

--7905290559 Suppl 2 to fire protection SER accepting proposed change in completion date for proposed mods to fire barrier penetration & electrical cable penetration seals to 790427
* Office of Nuclear Reactor Regulation 79/04/14 4pp

7905240558 Requests approval of plan to eliminate four fire detectors in nuclear instrumentation & reactor protection sys cabinets
HERBEIN, J O Metropolitan Edison Co 79/05/18 1p

G Adjudicatory correspondence

7905290285 Forwards class action complaint re TMI accident filed against utility & vendors in C Robert Larson, et al, vs Metropolitan Edison Co, et al
CARRIER, W C American Nuclear Insurers 79/05/22 9pp

J Insurance & Indemnity Information

7905140486 Forwards Amend 8 to Indemnity Agreement B-64 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501
encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp

7905220362 Returns unsigned Amend 8 to Indemnity Agreement B-64 Nuclear Liability Insurance Pools will not provide addl coverage
GERETY, W F GPU Service Corp 79/05/16 3pp

P Operating license stage documents & correspondence

7905100420 Forwards "Initial Startup Rept"
ARNOLD, R C Metropolitan Edison Co 74/11/27 1p.

--7905100425 "Initial Startup Rept"
* Metropolitan Edison Co 74/11/26 220pp

7905110178 Applies for license authorizing util to receive, possess & handle radioactive matl at temporary field locations outside site boundaries
ARNOLD, R C Metropolitan Edison Co 77/04/18 55pp

7905110173 Forwards addl info on procedures requested in NRC 771219 ltr re application for byproduct matl license
HERBEIN, J O Metropolitan Edison Co 78/01/30 143pp

7905250021 EIA supporting Amends 69, 69 & 66 to Licenses DPR-38, DPR-47 & DPR-55, respectively
* Operating Reactors Branch 4 79/03/02 4pp

7905160141 Forwards personnel exposure & monitoring rept for 1978
HERBEIN, J O Metropolitan Edison Co 79/04/02 2pp

7905020294 Confirms 790328 oral commitment to provide advance notice prior to taking unit out of present cold shutdown condition
HERBEIN, J O Metropolitan Edison Co 79/04/16 1p

7905150486 Notifies that Class III fee required for 780870 applicallis re ring girder surveillance test has not been received Fee should be forwarded within 15 days of receipt of ltr
MILLER, W O License Fee Management Branch 79/04/26 1p

7905070587 Requests 90-day extension to 790415 deadline for submission of draft radiological effluent Tech Specs & Offsite Dose Calculation Manual
HERBEIN, J O Metropolitan Edison Co 79/04/28 1p

7905090320 Notifies that submission of final rept re impingement/entrainment monitoring program at TMI will be delayed to 790715
HELBISH, J F, TROFFER, G J Metropolitan Edison Co 79/05/01 1p

7905190115 Responds to NRC 790205 ltr re potential consequences of postulated fuel handling accident inside containment
Consequences of potential accident are within guidelines of 10CFR100 No further action required
HERBEIN, J O Metropolitan Edison Co 79/05/08 2pp

7905220371 Forwards amend fee for Tech Spec Change Request 77
HERBEIN, J O Metropolitan Edison Co 79/05/15 1p

Q Inspection reports, IE Bulletins & correspondence

7905230385 IE Bulletin 78-07, "Protection Afforded by Air-Line Respirators & Supplied-Air Hoods"
* Region 1, Philadelphia, Office of the Director 79/04/12 3p

7905020135 Forwards IE Insp Rept 50-289/79-05 on 790215, 21, 22 & 23 H noncompliance noted
CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/20 2pp

--7905020140 IE Insp Rept 50-289/79-05 on 790215, 21, 22 & 23 H noncompliance noted Major areas inspected inservice insp program
WALTON, G A, TRIPP, L Region 1, Philadelphia, Office of the Director 79/03/16 7pp

7905240430 Forwards IE Insp Rept 50-289/79-06 on 790221-23 & 26-28 H noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/21 2pp

--7905240437 IE Insp Rept 50-289/79-06 on 790221-23 & 26-28 H noncompliance noted Major areas inspected refueling activities, preparation for refueling, outage related maint, pipe supports & restraints, shift logs & records
HAVERKAMP, D, HIGGINS, J C, KEMIG, R R Region 1, Philadelphia, Office of the Director 79/03/20 17pp.

7905010118 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/23 1p

7905010047 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/28 1p.

7905010300 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."
GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/30 2pp

7905020053 Forwards IE Bulletin 79-06, "Review of Operational Errors Sys Misalignments Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/11 1p.

7905190215 Discusses schedule for completing actions required by IE Bulletin 79-03 Search of procurement documents to determine use of specified welded pipe will be complete by 790831
HERBEIN, J O Metropolitan Edison Co. 79/04/13 1p.

7909020377 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required
ORIER, B H Region I, Philadelphia, Office of the Director
79/04/14 1p

7909040040 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Gys Misalignments Identified During TMI Incident "
ORIER, B H Region I, Philadelphia, Office of the Director
79/04/14 1p

7909040210 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
ORIER, B H Region I, Philadelphia, Office of the Director
79/04/14 1p

7909030072 Forwards II Bulletin 79-09, "Failures of OI Type AK 2 Circuit Breaker in Safety Related Gys " Licensee action required
ORIER, B H Region I, Philadelphia, Office of the Director
79/04/17 1p

7909020275 Forwards II Bulletin 79-06A, Revision 1, "Review of Operational Errors & Gys Misalignments Identified During TMI Incident "
ORIER, B H Region I, Philadelphia, Office of the Director
79/04/18 1p.

R Periodic operating reports & related correspondence

7909030338 Forwards monthly operating rept for Mar 1979 W/H encl
HERBEIN, J Q Metropolitan Edison Co 79/04/27 1p

7909030375 Forwards monthly operating rept for Apr 1979
HERBEIN, J Q Metropolitan Edison Co 79/05/15 1p

--7909030376 Monthly operating rept for Apr 1979
MITCHELL, D Q Metropolitan Edison Co 79/05/01 3pp

B Reportable occurrences, lifts & related correspondence

7909090227 "LER Output on Events at TMI-1 & TMI-2 from 1969 to Present "
" Health, Education & Welfare, Dept of 79/04/18 8pp

7909090445 Forwards IIR 79-009/03H-0
HERBEIN, J Q Metropolitan Edison Co 79/04/26 1p

--7909090451 IIR 79-009/03H-0 on 790110 during refueling frequency local leak rate test, excessive leakage noted across valve AH VIII
Caused by loose valve seat retaining screws in valve stems
tightened & valve tested satisfactorily
STANLEY, W B Metropolitan Edison Co 79/04/26 1p

7909090542 Forwards IIR 79-007/01T-0
HERBEIN, J Q Metropolitan Edison Co 79/04/26 1p

--7909090547 IIR 79-007/01T-0 on 790223 dome of borated water storage tank found partially collapsed Caused by failure of vacuum breaker DH-V27 to relieve differential pressure when required. Breaker bench tested & reinstalled
STANLEY, W B Metropolitan Edison Co 79/04/26 2pp

7909090590 Forwards IIR 79-011/07I-0
HERBEIN, J Q Metropolitan Edison Co. 79/05/01 1p

--7909090604 LIR 79-011/03I-0 on 790405 leaks noted in spent fuel pool cooling sys piping Caused by intergranular stress corrosion cracking Areas of leakage isolated, stress analysis will be performed.
MITCHELL, D Q Metropolitan Edison Co. 79/05/16 2pp

7909140282 Forwards IIR 79-009/03L-0.
HERBEIN, J Q Metropolitan Edison Co 79/05/02 1p

--7909140296 LER 79-009/03L-0 on 790410 during surveillance testing on turbine-driven emergency feedpump, steam regulating valve found closed Caused by maint procedure not specifying opening of valve
STANLEY, W B Metropolitan Edison Co 79/05/02 2pp

7909220318 Forwards IIR 79-010/03L-0
HERBEIN, J Q Metropolitan Edison Co. 79/05/02 1p

--7909220325 LER 79-010/03L-0 on 790411 while in hot shutdown, reassignment of personnel to Unit 2 prevented surveillance re chemistry & radiological analysis at proper frequency
Missed surveillances subsequently performed
MITCHELL, D Q Metropolitan Edison Co 79/05/02 2pp

DOCKET 90-273 PIORIN NUCLEAR POWER STATION, UNIT 1
F Security, medical, emergency & fire protection plans

7909010342 Forwards Revision 4 of modified physical security plan Plan withheld (ref 10CFR2 790)
ANDOGNINI, Q C Boston Edison Co 79/04/23 1p

O Adjudicatory correspondence

7909160227 Reviews impact of TMI on upcoming hearings scheduled for Apr & May
CUNNINGHAM, Q H Branch 2 79/04/01 2pp

7909020311 Forwards complaints re new class action against Boston Edison Co. et al. commenced by Plymouth County Nuclear Info Committee, Inc. et al summons, order & class action complaint encl
MAZZONE, J American Nuclear Insurers 79/04/26 29pp

7909090901 Notifies that claim has been filed against util by Plymouth County Nuclear Info Committee Forwards CA 79-13916, motion for appointment of special process server & summons & order of notice
ANDOGNINI, Q C Boston Edison Co 79/05/01 10pp

J Insurance & indemnity information

7909070497 Confirms increased liability limit to \$124,000,000 for policies MI 1, 2, 3, 4, 76, 81, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 176, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATRECHEN, J American Nuclear Insurers 79/05/01 1p

7909070782 Confirms increase in liability limit to \$16,000,000 for policies MI 1, 2, 3, 4, 76, 81, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 176, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
RUBIN, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7909160180 Forwards Amend B to Indemnity Agreement B 4H per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790901 Supporting documentation encl
BAITMAN, J Antitrust & Indemnity Group 79/05/01 2pp

7909290208 Forwards executed Amend B to Indemnity Agreement B 4H
FELDMAN, P A Boston Edison Co 79/05/22 1pp

P Operating license stage documents & correspondence

7909170210 Submits schedule for implementation & resolution of Mark 1 containment long term program mode, in response to NRC request
ANDOGNINI, Q C Boston Edison Co 79/05/09 2pp

7909190797 Forwards responses to question re comparison of projected population densities in PHAN & 1970 update to 1974 site selection study
BUTLER, R M Boston Edison Co 79/05/10, 14pp

7909300208 Forwards summary of EDN Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PIGB piping analysis computer program from Jan Oct 1969
Review & reanalysis included all work through Dec 1970
PORTER, F L EDN Nuclear, Inc 79/05/21 9pp

--7909300263 Forwards EDN Nuclear, Inc list of BWRs & piping sys could have been impacted by deficient computer program
GE has no record of reanalysis for Cooper piping sys
STEPHEN, P H General Electric Co, Nuclear Energy Prod
79/01/24 10pp

Q Inspection reports, II Bulletins & correspondence

7909010100 Forwards IE Info Notice 79-06, "Stress Analysis Safety-Related Piping "
ORIER, B H Region I, Philadelphia, Office of the Director
79/03/23 1p

7909070266 Forwards II, Info Notice 79-07, "Rupture of Radwair"
ORIER, B H Region I, Philadelphia, Office of the Director
79/03/26 1p

7909010034 Forwards IE Info Notice 79-08, "Interconnection Contaminated Gys w/Bvc Air Gys Used as Source of Breathing Air "
ORIER, B H Region I, Philadelphia, Office of the Director
79/03/20 1p

DOCKETED ITEMS

7905010282 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/03/30 1p

7905020026 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/11 1p

7905020357 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905030326 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040167 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905030052 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/17 1p

7905010432 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/18 1p

7905310352 Provides supplemental info to initial response to IE Bulletin 79-07 & to LER 79-014 Reanalysis of all lines indicates all stresses remain below code allowables All snubber locations were verified by insitu insp
ANDOGNINI, G C Boston Edison Co 79/05/23 3pp

R Periodic operating reports & related correspondence

7905160420 Forwards monthly operating rept for Apr 1979
MCQUIRE, P J Boston Edison Co 79/03/08 1p

--7905160423 Monthly operating rept for Apr 1979
MATHIS, C J Boston Edison Co 79/03/08, 6pp

B Reportable occurrences, LERs & related correspondence

7905010536 Forwards LER 79-012/01X-0
MCQUIRE, P J Boston Edison Co. 79/04/24 1p

--7905010540 LER 79-012/01X-0 on 790424 util informed that DAPS computer program used by OE for seismic analysis is not consistent w/ current requirements. Caused by state-of-the-art applied during design of Pilgrim Affected piping reanalyzed
MATHIS, C J Boston Edison Co 79/04/24, 1p

7905020261 Forwards LER 79-013/03L-0
MCQUIRE, P J Boston Edison Co 79/04/26, 1p

--7905020267 LER 79-013/03L-0 on 790331, during OPER-09 surveillance testing, drywell to suppression chamber pressure was less than 1.30 psid on pressure instruments PI-5067 A & B, while greater than 1.30 elsewhere Caused by setpoint drift
MATHIS, C J Boston Edison Co 79/04/26 1p

7905140244 Forwards LER 79-012/01Y-1
MCQUIRE, P J Boston Edison Co 79/05/08 1p

--7905140247 LER 79-012/01Y-1 on 790424, seismic analysis computer program for main steam & recirculation piping gave unsatisfactory results Caused by outdated state-of-the-art. Different program gave satisfactory results
MATHIS, C J Boston Edison Co 79/05/08 2pp

7905170233 Requests extension until 790708 for weld & hydrostatic testing program
ANDOGNINI, G C Boston Edison Co. 79/05/08 1p.

7905150553 Forwards LER 79-014/01X-0,
MCQUIRE, P J Boston Edison Co 79/05/09 1p

--7905150558 LER 79-014/01X-0 on 790509 four recirculation sys hydra, snubbers failed to satisfy Tech Spec requirements for operability under design basis earthquake loading Caused by design error Snubbers will be modified
FULTON, J M Boston Edison Co 79/05/09 1p

7905150554 Forwards LER 79-013/03L-0
MCQUIRE, P J Boston Edison Co 79/05/11 1p

--7905150559 LER 79-013/03L-0 on 790415 reactor core isolation cooling, barometric condenser condensate pump tripped Caused by tarnished relay contacts in pump starting logic Contacts cleaned & pump loads successfully tested
FULTON, J M Boston Edison Co 79/05/10 1p

7905290095 Forwards LER 79-017/03L-0
MCQUIRE, P J Boston Edison Co 79/05/22 1p

--7905290100 LER 79-017/03L-0 on 790429 control rod 26-27 unresponsive insert signal Cause undetermined Corrective actions relay contacts & relay socket contacts on relay 3A-KL32 spray cleaned
MATHIS, C J Boston Edison Co 79/05/22 1p

7905300472 Forwards LER 79-016/03L-0
MCQUIRE, P J Boston Edison Co 79/05/23 1p

--7905300482 LER 79-016/03L-0 on 790511 inoperable snubber inside drywell Caused by snubber 0063 (Bergen-Patterson Model HS A10-6) being disconnected New snubber installed on 790512
FULTON, J M Boston Edison Co 79/05/22 2pp

7905300535 Forwards LER 79-018/01X-0
MCQUIRE, P J Boston Edison Co 79/05/23 1p

--7905300543 LER 79-018/01X-0 on 790519 recirculation pump P-201A st. w/ reactor coolant temp greater than 212 F, primary containment integrity not maintained & delta temp between loops greater than 50 F Caused by operator error
MATHIS, C J Boston Edison Co 79/05/23 1p

DOCKET 50-294 MICHIGAN STATE UNIV RESEARCH REACTOR

J Insurance & indemnity information

7905160240 Forwards Amend 9 to Indemnity Agreement E-51, per 10CFR143 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

G. Inspection reports, IE Bulletins & correspondence

7905040161 Ack receipt of 790404 & 0407 ltrs informing NRC of steps taken to correct noncompliance noted in NRC 790221 ltr
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/04/20 1p

--7905040165 Responds to NRC 790221 ltr re noncompliance noted in 790131-0202 Corrective actions 1979 requalification exam will be given to operators during Apr
TERRY, B H, GARRICK, J T Michigan State 79/04/07 1p

--7905040168 Responds to NRC 790221 ltr re 790131-0202 insp Details annual audit
TERRY, B H, GARRICK, J T Michigan State 79/04/04 1p

DOCKET 50-293 ZION NUCLEAR POWER STATION, UNIT 1

E NRC Safety Evaluation Report (SER), suppl & correspondence

7905240995 Forwards SER & EIA re plant spent fuel pool mods w/c encl
GODDARD, R J Branch 2 79/04/03, 1p

F Security, medical, emergency & fire protection plans

7905030366 Forwards modified physical security plan, Revision 5 Plan, withheld (ref 10CFR2 790),
LEE, B, Commonwealth Edison Co 79/04/26 1p

7905290079 Forwards Chemtron drawings FL27652-7, sheets 1 through 5, w/design details for fire suppression sys to be installed for auxiliary feedwater sys & component cooling pumps, Overse drawings encl.
NAUGHTON, W F Commonwealth Edison Co 79/05/23 2pp.

DOCKETED ITEMS

83

G Adjudicatory correspondence

7905230768 Affidavit of M Haskinoff re spent fuel issue Professional qualifications & Certificate of Evc encl
HASKINOFF, M R Illinois, State of 79/02/23 12pp

7905300711 Responds to State of IL's 790221 motion for continuance & request to allow future supplementation of Intervenor's Affidavits Certificate of Evc encl
GONNARD, R J Branch 2 79/07/13 4pp

7907070174 Forwards GHI & FIA re spent fuel pool mods W/O encl
GONNARD, R J Branch 2 79/04/07 1p

7905250190 Provides list of witnesses for util in Zion spent fuel case
STELTON, P. Isham, Lincoln & Neale 79/04/01 2pp

7905300028 Request by util on its own behalf & on behalf of State of IL & NRC for AMO to begin hearings on 790714 Certificate of Evc encl
HILANBKI, A P Isham, Lincoln & Neale 79/04/06 3pp

7905100121 Interrogatories submitted to state of IL per AMO 790119 order Certificate of Evc encl
GONNARD, R J Branch 2 79/04/09 4pp

7905150256 Motion to file supplementary affidavits to response to util & NRC motions for summary disposition Affidavits of DO Bridenbaugh & QC Minor & Certificate of Evc encl
SEKULER, D N Illinois, State of 79/04/10 2pp

7905150240 Forwards unexecuted affidavit of M Haskinoff Certificate of Evc encl
SEKULER, D N Illinois, State of 79/04/11 4pp

7905150691 Forwards Chapter 1 of NANO77 1/31, "Spent Fuel Heatup Following Loss of Water During Storage," which contains info relevant to util's application to increase spent fuel storage pool capacity Requests to be placed on evc list
WEBB, R L Affiliation Unknown 79/04/17 40pp

7905250367 Moves for summary disposition of State of IL's Contention 2(a)-(d) for lack of genuine issue of fact Affidavits, notices of appearance & withdrawal & Certificate of Evc encl
GONNARD, R J Branch 2 79/04/27 20pp

7905150241 Denies summary disposition of Intervenor's Contentions 2(f), 2(g), 2(h) & 2(i) Grants summary disposition of Intervenor's Contention 2(h)
LUTON, E Atomic Safety and Licensing Board Panel 79/03/01 3pp

H General correspondence

7905070014 Responds to 790202 its requesting info re leakage of water through liner of spent fuel pool at facility NRC is monitoring util's efforts to control seepage
BTELL, D V Division of Operating Reactors 79/04/19 7pp

J Insurance & Indemnity Information

7905100163 Endorsement 44 to MAMU Policy NF 22
OENAS, T Nuclear Energy Liability Insurance Association 79/01/27 1p

7907070497 Confirms increased liability limit to \$124,000,000 for policies NF 1, 25, 43, 76, 03, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATYRROCH, J American Nuclear Insurers 79/03/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF 22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/03/01 1p

7905140470 Forwards Amend 9 to Indemnity Agreement B-59 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/03/01 6pp

7905160399 Confirms 790301 & OI agreement w/NRC that Westinghouse need not sign Amend 7 to Indemnity Agreement B-56
CAMP, Q T Johnson & Higgins Insurance 79/03/09 1p

7905210262 Forwards Endorsements 58 & 59 to NELIA Policy NF-187 & Endorsements 47 & 48 to NELIA Policy NF-201
OSTER, J Commonwealth Edison Co 79/05/16 4pp

P Operating license stage documents & correspondence

7905250103 Amends 47 & 44 to Licenses DPR-39 & DPR-48, respectively, revising Tech Specs re rod drop time
SCHWENGER, A Operating Reactors Branch 1 79/04/09 6pp

--7905250107 Safety evaluation supporting Amends 47 & 44 to Licenses DPR-39 & DPR-48, respectively
* Office of Nuclear Reactor Regulation 79/04/09 3pp

--7905250190 Notice of issuance & availability of Amends 47 & 44 to Licenses DPR-39 & DPR-48, respectively
SCHWENGER, A Operating Reactors Branch 1 79/04/09 2pp

7905040482 Notices of intention to develop safety analysis using existing computer codes Requests addl info
GOLDRIC, C W Commonwealth Edison Co 79/04/26 1p

7905040502 Requests amend to Tech Specs to require actuation of safety injection based on two out of three channels of low pressurizer pressure & to delete pressurizer level from safeguards logic Class 1 & II Amend fees encl
RIED, C Commonwealth Edison Co 79/04/30 9pp

7905100251 "Gamma Dose Measurements at Zion & Fort Calhoun Stations," BYER, N C, BUNTING, R L, NIECHMIDT, E B EO & O, Inc FIN A-6075
NUREG/CR-0735 79/04/30 137pp Available at NTIS #7 25

7905070794 Forwards response to request for addl info re review of proposed license amend to increase allowable LOCA peaking factor limit to 1.93 based on ECCS reanalysis
NAUGHTON, W F Commonwealth Edison Co 79/05/03 4pp

7905250425 Forwards Amends 49 & 46 to licenses DPR-39 & DPR-48, respectively, safety evaluation & notice of issuance & availability
SCHWENGER, A Operating Reactors Branch 1 79/05/03 2pp

--7905250432 Amends 49 & 46 to Licenses DPR-39 & DPR-48, respectively
SCHWENGER, A Operating Reactors Branch 1 79/05/03 16pp

- 7905250435 Safety evaluation supporting Amends 49 & 46 to Licenses DPR-39 & DPR-48, respectively
* Operating Reactors Branch 1 79/04/03 3pp.

--7905250440 Notice of issuance & availability of Amends 49 & 46 to Licenses DPR-39 & DPR-48, respectively
SCHWENGER, A Operating Reactors Branch 1 79/05/03 2pp

7905170237 Forwards revised Tech Specs re heating & cooldown curves & added provision for overpressure protection.
RIED, C Commonwealth Edison Co 79/05/11 2pp

--7905170255 Revised Tech Specs re heating & cooldown curves & added provision for overpressure protection
* Commonwealth Edison Co, 79/05/11 4pp

7905250391 Forwards current licensing open items status list
RIED, C Commonwealth Edison Co 79/05/18 11pp

G Inspection reports, IE Bulletins & correspondence

7905020421 Forwards response to IE Bulletins 78-12 & 78-12A, "Atypical Weld Heat in Reactor Pressure Vessel Welds."
RIED, C Commonwealth Edison Co 79/03/22 10pp

7905010236 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23 1p.

7905030370 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks,"
KEPPLER, J O Region 3, Chicago, Office of the Director, 79/03/26 1p

7905010155 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Bys w/Bvc Air Bys Used as Source of Breathing Air"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/28 1p

7905140084 Forwards IE Insp Repts 80-295/79-05 & 80-304/79-06 on 790321-23 No noncompliance noted.
HEIBMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch, 79/03/28 2pp

--7905140087 IE Insp Repts 80-295/79-05 & 80-304/79-06 on 790321-23 No noncompliance noted Major areas inspected: preparations made for refueling & maint during refueling outage
DANIELS, F T, LITTLE, W B, BOYD, D C Region 3, Chicago, Office of the Director 79/03/28 3pp

DOCKETED ITEMS

- 7905010114 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
KEFFLER, J G Region 3, Chicago, Office of the Director 79/03/30 1p
- 7905030007 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" Licensee action required
KEFFLER, J G Region 3, Chicago, Office of the Director 79/04/11 1p
- 7905030260 Responds to IE Bulletin 79-03 re welding defects in certain longitudinally welded pipe spools Plants inspected no pipe found
REED, C Commonwealth Edison Co 79/04/12 2pp
- 7905010572 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified during TMI Incident" Licensee action required
KEFFLER, J G Region 3, Chicago, Office of the Director 79/04/14 1p
- 7905040334 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEFFLER, J G Region 3, Chicago, Office of the Director 79/04/14 1p
- 7905040527 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
KEFFLER, J G Region 3, Chicago, Office of the Director 79/04/14 1p
- 7905030206 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
KEFFLER, J G Region 3, Chicago, Office of the Director 79/04/17 1p
- 7905040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"
KEFFLER, J G Region 3, Chicago, Office of the Director 79/04/21 1p
- 7905040158 IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl" Supporting documentation encl
* Region 3, Chicago, Office of the Director 79/04/21 12pp
- 7905040170 ACRS recommendations re 790328 Incident at TMI Suggests high priority be placed on development of safety research on behavior of LWRs during anomalous transients
* ACRS - Advisory Committee on Reactor Safeguards 79/04/17 2pp
- 7905040201 Forwards ACRS recommendations re TMI incident, presented on 790417
FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards 79/04/18 1p
- 7905040221 In response to NRC 790418 ltr, states all 790417 ACRS recommendations apply to all PWRs, but were not intended to require immediate changes Plant mods should be made after study of effects on overall safety. TMI excluded
CARBON, M X ACRS - Advisory Committee on Reactor Safeguards 79/04/20 2pp
- 7905090323 "Annual Operating Rept 1978"
* Commonwealth Edison Co 79/04/26 24pp
- S Reportable occurrences, LERs & related correspondence
- 7905020272 Forwards LER 79-024/03L-0
WANDKE, N E Commonwealth Edison Co 79/04/25 1p
- 7905020282 LER 79-024/03L-0 on 790326 during normal operation discovered channel IL-53B was 4X higher than other IG stage steam generator channels Fischer-Porter transmitter zero-shifted for unknown reasons Zero reset
HANSEN, P Commonwealth Edison Co 79/04/25 1p
- 7905240543 Forwards LER 79-029/03L-0
WANDKE, N E Commonwealth Edison Co 79/05/08 1p
- 7905240546 LER 79-029/03L-0 on 790408 during normal operation discovered low reading on pressurizer level channel 11 433 Caused by transmitter drift (Barton DP XMTR Model 3041) Adjustment made
ROGERB, C L Commonwealth Edison Co 79/05/08 1p
- 7905240538 Forwards LER 79-031/03L-0
WANDKE, N E Commonwealth Edison Co 79/05/09 1p
- 7905240541 LER 79-031/03L-0 on 790416 instrument failure alarm for containment purge exhaust iodine monitor repeatedly alarmed Event repeated after alarm repaired Caused by poor solder possibly causing short circuit
MEYER, B A Commonwealth Edison Co 79/05/09 1p
- DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1
J Insurance & indemnity information
- 7905140462 Forwards Amend 12 to Indemnity Agreement B-52 per 1-14-81 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 4pp
- 7905080390 Forwards Endorsement 47 to ANI Policy NF-198
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc. 79/05/03 2pp
- 7905080394 Forwards Endorsement 40 to ANI Policy NF-190
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc. 79/05/03 2pp
- K Utility Final Safety Analysis Report (FSAR) & amendments
- 7905110024 Forwards Amend 68 to FSAR,
GILLELAND, J E Tennessee Valley Authority 79/05/08 2pp
- 7905110031 Amend 68 to FSAR, w/oversized drawings,
* Tennessee Valley Authority. 79/05/08 100pp
- P. Operating license stage documents & correspondence
- 7905080033 Ack receipt of Class II fee & application for award to Licensee DPR-33, DPR-62 & DPR-6B Requests payment of addl fee
MILLER, W O License Fee Management Branch 79/04/04 1p
- 7905290352 Proposes meeting w/Bandia address final test plan, based on review of 790216 second draft of Bandia connector test plan List of items needing resolution encl.
STELLO, V Division of Operating Reactors 79/04/19 4pp
- 7905110177 Submits schedule for torus mods, in response to NRC 790312 ltr to HQ Harris
GILLELAND, J E Tennessee Valley Authority. 79/05/04 3pp
- 7905110211 Confirms plans for feedwater nozzle insp during Feb 1979 refueling outage, as well as feedwater sparger final fis mod, clad removal & ultrasonic test
GILLELAND, J E Tennessee Valley Authority. 79/05/07 1p
- 7905300208 Forwards summary of EDS Nuclear, Inc resolution/feasibility of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970
PORTER, F L EDS Nuclear, Inc. 79/05/21 9pp

DOCKETED ITEMS

85

--7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program
GE has no record of reanalysis for Copper piping sys
STEPHENS, P W General Electric Co ,Nuclear Energy Products Div
79/01/24 18pp

G Inspection reports, IE Bulletins & correspondence

7905150103 Forwards IE Insp Repts 50-259/79-04, 50-260/79-04 & 50-296/79-04 on 790102-0202 No noncompliance noted
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/03/22 2pp

--7905150107 IE Insp Repts 50-259/79-04, 50-260/79-04 & 50-296/79-04 on 790102-0202 No noncompliance noted Major areas inspected
plant operations, refueling & restart of Unit 1, plant tour & liquid radwaste processing
SULLIVAN, R F Region 2, Atlanta, Office of the Director
DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch
79/03/19 7pp

7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/03/23 2pp

7905150138 Forwards IE Insp Repts 50-259/79-05, 50-260/79-05 & 50-296/79-05 on 790226-0302 No noncompliance noted
LEHIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch
79/03/23 2pp

--7905150147 IE Insp Repts 50-259/79-05, 50-260/79-05 & 50-296/79-05 on 790226-0302 No noncompliance noted Major areas inspected
reportable secondary containment leak rate testing, IE circulars & bulletins
PRICE, D S Region 2, Atlanta, Office of the Director
DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch
79/03/22 8pp

7905010113 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/03/28 2pp

7905010363 Forwards IE Info Notice 79-07, "Spill of Radioactively Contaminated Resin"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/03/30 2pp

7905080176 Responds to IE Bulletin 79-03 No evidence that any stainless steel pipe mfg by Youngstown Welding & Engineering Co was used in any ASME Class I, II or III safety-related sys
GILLELAND, J E Tennessee Valley Authority 79/04/12 1p

7905030368 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 3pp

7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 3pp

7905150700 Forwards IE Bulletin 79-08, "Events Relevant to BWRs Identified During TMI Incident" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 2pp

7905030172 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/17 2pp

7905020479 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/18 2pp

7905250344 Forwards response to Item 7 b of IE Insp Repts 50-259/79-05, 50-260/79-05 & 50-296/79-05 re deterioration of Buna-N components in ASCO solenoids, as followup to IE Bulletin 78-14
GILLELAND, J E Tennessee Valley Authority 79/04/20 3pp

7905300745 Forwards response to IE Bulletin 79-08 Plant superintendent will present review of TMI incident to all managers & supervisors w/operational responsibilities Containment isolation design & procedures have been reviewed.
GILLELAND, J E Tennessee Valley Authority 79/04/25 14pp

7905240947 Ack receipt of 790423 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/79-07, 50-260/79-07 & 50-296/79-07
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/30 2pp

--7905240972 Responds to NRC 790330 ltr re violations noted in IE Insp Repts 50-259/79-07, 50-260/79-07 & 50-296/79-07 Corrective actions entire radwaste bldg properly posted as radioactive area
GILLELAND, J E Tennessee Valley Authority 79/04/23 4pp

--7905240992 Forwards IE Insp Repts 50-259/79-07, 50-260/79-07 & 50-296/79-07 on 790226-0302 & notice of violation
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/30 2pp

--7905241003 Notice of violation from insp on 790226-0302
* Region 2, Atlanta, Office of the Director 79/03/30 2pp

--7905241005 IE Insp Repts 50-259/79-07, 50-260/79-07 & 50-296/79-07 on 790226-0302 Noncompliance noted, failure to post radiation area, label containers of radioactive matl & barricade high radiation area
JACKSON, L L Region 2, Atlanta, Office of the Director
GIBSON, A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 2pp

7905240652 Forwards responses to IE Bulletin 79-04 re incorrect swing check valve weights Corrected valve weights do not create any overstressing in pipes, hangers or supports Addl info will be provided by 790511
GILLELAND, J E Tennessee Valley Authority 79/05/01 6pp

7905150322 Forwards addl inservice insp program revisions based on further review & comparison of facility design w/respect to ASME boiler & pressure vessel code requirements
GILLELAND, J E Tennessee Valley Authority 79/05/08 21pp

R Periodic operating reports & related correspondence

7905030343 Forwards "Environ Radioactivity Levels, Annual Rept 1978"
GILLELAND, J E Tennessee Valley Authority 79/04/27 1p

--7905030349 "Environ Radioactivity Levels, Annual Rept 1978"
* Tennessee Valley Authority MRH-79-3-BF2 79/04/27 50pp

7905010475 Forwards "Fish Impingement Rept" for first quarter 1979
GILLELAND, J E Tennessee Valley Authority 79/05/01 2pp

--7905010476 "Fish Impingement Rept" for first quarter 1979
* Tennessee Valley Authority 79/05/01 14pp

7905150346 Forwards monthly operating rept for Apr 1979
DEWEASE, J O Tennessee Valley Authority 79/05/09 1p

--7905150352 Monthly operating rept for Apr 1979
DEWEASE, J O Tennessee Valley Authority 79/04/30 36pp

A Reportable occurrences, LERs & related correspondence

7905110196 Forwards LER 79-004/03L-0
FOX, H S Tennessee Valley Authority 79/05/07 1p

--7905110201 LER 79-004/03L-0 on 790411 during normal operation, heat detector alarmed & would not clear Alarm would have masked signals from other detector, required to be operational Caused by personnel damaging detector
* Tennessee Valley Authority 79/05/07 2pp

790531
FOX

* Tennessee Valley Authority 79/05/10 4pp

DOCKET 50-297 NORTH CAROLINA STATE UNIV, PULSTAR REACTOR

G. Inspection reports, IE Bulletins & correspondence

7905070146 Forwards IE Bulletins 79-05, 79-05A & 79-06, re nuclear incident at TMI.
O'REILLY, J P Region 2, Atlanta, Office of the Director.
79/04/13 1p

DOCKETED ITEMS

DOCKET 30-298 COOPER NUCLEAR STATION

A Application/construction stage documents & correspondence

7905140228 Forwards schedule for implementation & resolution of Mark I containment long-term program, in response to 790312 ltr
PILANT, J M Nebraska Public Power District 79/05/07 5pp

F Security, medical, emergency & fire protection plans

7905230355 Forwards modified physical security plan Plan withheld (ref 10CFR2 790)
PILANT, J M Nebraska Public Power District 79/05/16 1p

I Financial information

7903080487 Forwards "Annual Financial Rept 1978 "
PILANT, J M Nebraska Public Power District 79/05/04 1p

--7905080495 "Annual Financial Rept 1978 "
* Nebraska Public Power District 79/05/04 39pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905150365 Forwards Amend 9 to Indemnity Agreement B-57, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905150384 Forwards executed Amend 9 to Indemnity Agreement B-57
PILANT, J M Nebraska Public Power District 79/05/08 3pp

7905160127 Forwards Endorsements 45 & 46 to NELIA Policy NF-200
PILANT, J M Nebraska Public Power District 79/05/11 3pp

P Operating license stage documents & correspondence

7905110001 Forwards Amend 55 to License DPR-46, safety evaluation & notice of issuance & availability
IPPOLITO, T A Operating Reactors Branch 3 79/04/27 2pp.

--7905110002 Amend 55 to License DPR-46, revising App A & B of Tech Specs re primary containment & reactor vessel isolation instrumentation
IPPOLITO, T A Operating Reactors Branch 3 79/04/27 25pp

--7905110003 Safety evaluation supporting Amend 55 to License DPR-46
* Office of Nuclear Reactor Regulation 79/04/27, 13pp

--7905110005 Notice of issuance & availability of Amend 55 to License DPR-46
IPPOLITO, T A Operating Reactors Branch 3 79/04/27, 2pp.

7905020269 Forwards fee payment for Amends 39 & 40 to PSAR Disagrees w/imposition of Class III fees
PILANT, J M Nebraska Public Power District, 79/05/02 1p.

7905080478 Requests that GE rept NEDO-25070, "Analytical Model for Estimating Drag Forces on Rigid Submerged Structures Caused by Condensation Oscillations & Chugging" be included in docket
PILANT, J M Nebraska Public Power District, 79/05/04, 1p

7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970.
PORTER, F L EDS Nuclear, Inc 79/05/21, 9pp.

--7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program. GE has no record of reanalysis for Cooper piping sys.
STEPHENS, P W General Electric Co., Nuclear Energy Products Div 79/01/24 18pp

G Inspection reports, IE Bulletins & correspondence

7905150083 Forwards IE Circular 79-04, "Loose Locking Nut on Limiting Valve Operators "
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/16 1p

7905010431 Forwards IE Bulletin 78-12B, "Atypical Weld Matl in Reactor Pressure Vessel Welds "
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/19 1p.

7905020444 Forwards IE Circular 79-05, "Moisture Leakage in Strandif Wire Conductors "
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/25 1p

7905020273 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping "
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/21 1p

7905020415 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tank "
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/23 1p

7905020428 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air "
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/26 1p

7905020122 Ack receipt of 790301 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-298/79-02
HADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Supp'l Branch 79/03/29 1p

--7905020129 Responds to NRC 790213 ltr re violations noted in IE Insp Rept 50-298/79-02 Corrective actions alcohol removed from reactor room floor & importance of procedures stressed to employees
PILANT, J M Nebraska Public Power District 79/03/01 3pp

7905140148 Forwards IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Valan Engineering Corp " Licensee action required
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/31 1p

7905150046 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin "
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/31 1p

7905040537 Forwards IE Bulletin 79-06B, "Review of Operational Error! Sys Misalignments Identified During TMI Incident "
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/11 1p

7905040621 Forwards IE Bulletin 79-08, "Events Relevant to Rolling Water Power Reactors Identified During TMI Incident "
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/11 1p

7905070072 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/11 1p

7905090103 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at TMI "
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/16 1p.

7905030277 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/17 1p.

7905080352 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl. "
SEYFRIT, K V Region 4, Dallas, Office of the Director, 79/04/21 1p

R Periodic operating reports & related correspondence

7905150522 Forwards monthly operating rept for Apr 1979
LEBBOR, L C Nebraska Public Power District 79/05/08, 1p

DOCKETED ITEMS

87

--7905150526 Monthly operating rept for Apr 1979
BORER, P S Nebraska Public Power District 79/05/08 4pp

8 Reportable occurrences, LERs & related correspondence

7905150120 Forwards PNO-79-67R & 79-77(NRR)
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/11 1p

7905040110 Forwards PNO-79-67B
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/12 1p

7905150258 Forwards PNO-79-67T correction
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/13 1p

7905010530 Forwards PNO-79-67U, V & W
MADSEN, O L Region 4, Dallas, Office of the Director 79/04/16
1p

7905010544 Forwards PNO-79-67X & Y
MADSEN, O L Region 4, Dallas, Office of the Director 79/04/18
1p.

7905010558 Forwards PNO-79-67Z
MADSEN, O L Region 4, Dallas, Office of the Director 79/04/19
1p

7905140335 Forwards LER 79-007/03L-0
LESEBOR, L C Nebraska Public Power District 79/04/20 2pp

--7905140336 LER 79-007/03L-0 on 790321 during core spray sys
surveillance testing, CB-MO-11A valve failed to reopen by
remote switch. Caused by axial movement of worm set clutch
collar on limiterque SMB-2 operator
FLANNIOAN, R D Nebraska Public Power District 79/04/20 1p

7905010375 Forwards PNO-79-67AA, AB, AC & AD
MADSEN, O L Region 4, Dallas, Office of the Director 79/04/24
1p

7905150077 Forwards PNO-79-67AF, AG, AH, AI & AJ, re nuclear incident at
TMI
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/30 1p.

7905240445 Forwards PNO-79-67AK & AL
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/05/02 1p

DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

7905300466 Submits proposed mods to fire protection plan as set forth
in BER Recommends fire hydrant insp & supervision of valves
controlling fire water sys
HALL, R E. Brookhaven National Laboratory 79/04/27 3pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHINI, J American Nuclear Insurers. 79/05/01. 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01
1p

7905140431 Forwards Amend 11 to Indemnity Agreement B-41 per 10CFR140
changes re increase in liability insurance from \$140 million
to \$160 million effective 790501 Supporting documentation
encl
BALTZMAN, J Antitrust & Indemnity Group. 79/05/01 6pp

7905230463 Forwards executed Amend 11 to Indemnity Agreement B-41, per
NRC 790501 request
DUNDAS, W J. Wisconsin Electric Power Co 79/05/17. 3pp

P Operating license stage documents & correspondence

7905140513 Forwards Amends 35 & 41 to Licenses DPR-24 & DPR-27,
respectively, safety evaluation, EIA & notice of issuance &
availability
SCHWENCER, A Operating Reactors Branch 1 79/04/04 2pp

--7905140520 Amends 35 & 41 to Licenses DPR-24 & DPR-27, respectively
authorizing installation & use of modified spent fuel
storage racks in spent fuel pool, which increases capacity
for storage from 351 assemblies to 1,502 assemblies
ZIEHMAN, D L Assistant Director for Systems & Projects
79/04/04 24pp

--7905140526 Safety evaluation supporting Amends 35 & 41 to Licenses
DPR-24 & DPR-27, respectively
* Office of Nuclear Reactor Regulation 79/04/04 16pp

--7905140529 EIA of Amends 35 & 41 to Licenses DPR-24 & DPR-27,
respectively
* Office of Nuclear Reactor Regulation 79/04/04 33pp

--7905140533 Notice of issuance & availability of Amends 35 & 41 to
Licenses DPR-24 & DPR-27, respectively
SCHWENCER, A Operating Reactors Branch 1 79/04/04 3pp

7905100439 Forwards Amends 37 & 42 to Licenses DPR-24 & DPR-27,
respectively & notice of issuance & availability Security
plan evaluation withheld (ref 10CFR2 790)
SCHWENCER, A Operating Reactors Branch 1 79/04/13 3pp

--7905100442 Amends 37 & 42 to Licenses DPR-24 & DPR-27, respectively,
implementing provisions of NRC-approved physical security
plan
SCHWENCER, A Operating Reactors Branch 1 79/04/13 4pp

--7905100446 Notice of issuance & availability of Amends 37 & 42 to
Licenses DPR-24 & DPR-27, respectively
SCHWENCER, A Operating Reactors Branch 1 79/04/13 3pp

7905150071 Forwards info in response to 790321 request re details of
plant shutdowns
DENTON, H R Office of Nuclear Reactor Regulation 79/04/18 4pp

7905020271 Request amends to Licenses DPR-24 & DPR-27, changing Tech
Specs re initiation instrument setting limits for
engineered safety features Forwards Class III amend fee.
BURSTEIN, S Wisconsin Electric Power Co 79/04/27 7pp

7905240831 Responds to IE Bulletin 79-06A, Item 3 re TMI errors
Pressurizer low level setpoint bistable returned to
untripped position until logic change requested in 790427
license amend is implemented
BURSTEIN, S Wisconsin Electric Power Co 79/04/30 2pp

7905150202 Forwards addl info re reactor vessel weld & surveill.
weld metals
BURSTEIN, S Wisconsin Electric Power Co 79/05/04 5pp

7905150448 Forwards addl info re Tech Spec Change Request &
safety injection actuation circuitry mod to two out of the
pressurizer low pressure logic Requests approval by 79051
to permit mods on 790512-13 & 790519-20
BURSTEIN, S Wisconsin Electric Power Co 79/05/07 3pp

7905240397 Forwards drawings for piping & instrumentation #
Section 3 of inservice test plan Encl 28 oversized drawing
available in Central Files only
BURSTEIN, S Wisconsin Electric Power Co 79/05/17 7pp

7905300208 Forwards summary of EDS Nuclear, Inc resolution/d
of elbow flexibility error which existed in versions of
PISOL piping analysis computer program from Jan-Oct 1969
Review & reanalysis included all work through Dec 1970
ORTER, F L EDS Nuclear, Inc 79/05/21 9pp

--7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping
could have been impacted by deficient computer program
OE has no record of reanalysis for Cooper piping sys
STEPHENS, P W General Electric Co, Nuclear Energy Prod
79/01/24 18pp

7905310359 Submits formal responses to 790510 questionnaire
pressurizer heater, loss of feedwater event & steam
generator
BURSTEIN, S Wisconsin Electric Power Co 79/05/22 8pp

DOCKETED ITEMS

7905300493 Forwards startup physics testing rept re rod worth measurements which employ "rod swap" methodology Rept demonstrates adequacy of nuclear design rod worth predictions
FAY, C W Wisconsin Electric Power Co 79/05/24 9pp

7905010142 Forwards IE Insp Repts 90-266/79-04 & 50-301/79-03 on 790220-23 & notice of violation
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/03/22 2pp

--7905010151 Notice of violation from insp on 790220-23
* Region 3, Chicago, Office of the Director 79/03/19 1p

--7905010160 IE Insp Repts 50-266/79-04 & 50-301/79-03 on 790220-23 Noncompliance noted failure to provide 7-day holdup of radioactive gas before release
GREGOR, L R, HIATT, J W Region 3, Chicago, Office of the Director FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/03/19 10pp

7905010270 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/23 1p

7905040060 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/26 1p

7905010181 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air"
KEPPLER, J G Region 3, Chicago, Office of the Director, 79/03/28 1p

7905010417 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/30 1p

7905030062 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TH1 Incident" Licensee action required
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/11 1p

7905010613 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified during TH1 Incident" Licensee action required
KEPPLER, J G Region 3, Chicago, Office of the Director, 79/04/14 1p

7905040431 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TH1 Incident"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14 1p

7905040438 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14 1p

7905040598 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TH1 Incident"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14 1p

7905030253 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/17 1p

7905290075 Responds to IE Bulletin 79-06A Expresses concern re emergency operating procedures for reactor coolant pump & requirement for immediate tripping of low level bistables
BURSTEIN, S Wisconsin Electric Power Co 79/04/19 3pp

7905080515 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1-Suppl."
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/21 1p.

7905240519 Responds to IE Bulletin 79-07 re computer programs used in seismic stress analysis of safety-related piping sys No computer codes used which utilized algebraic summation techniques
BURSTEIN, S Wisconsin Electric Power Co 79/04/23 2pp

7905240303 Responds to IE Bulletin 79-03 re possibility of longitudinal weld defects in ASME SA-312 Type 304 stainless steel pipe spools Review of pipe documentation records indicates no use of such tubing
BURSTEIN, S Wisconsin Electric Power Co 79/04/26 4pp

7905300316 Responds to IE Bulletin 79-06A & 79-06A, Revision 1 H., established task force to facilitate review & understanding of TH1 incident & impact on facility
BURSTEIN, S Wisconsin Electric Power Co 79/04/27 13pp

7905290284 Responds to IE Bulletin 79-09 re OE Type AK-2 circuit breakers Item not in use at plant
BURSTEIN, S Wisconsin Electric Power Co 79/05/07 1p

R Periodic operating reports & related correspondence

7905160362 Forwards monthly operating rept for Apr 1979
BURSTEIN, S Wisconsin Electric Power Co 79/05/08 1p

--7905160365 Monthly operating rept for Apr 1979
* Wisconsin Electric Power Co 79/05/04 10pp

S Reportable occurrences, LERs & related correspondence

7905020289 Forwards LER 79-003/01T-0
BURSTEIN, S Wisconsin Electric Power Co 79/04/17 1p

--7905020304 LER 79-003/01T-0 on 790410, during refueling leakage test, two valves were found w/excessive leakage Caused by foreign matter accumulations in internals Valves cleaned, reassembled & successfully retested
BURSTEIN, S Wisconsin Electric Power Co 79/04/17 2pp

7905100256 Forwards LER 79-004/01T-0
BURSTEIN, S Wisconsin Electric Power Co 79/04/28 1p

--7905100263 LER 79-004/01T-0 on 790412 overcurrent protection filter dashpots for 2803 safeguards bus supply breaker exhibited erratic long time delay trip time Caused by hairline cracks in dashpot caps Cracked caps will be replaced
BURSTEIN, S Wisconsin Electric Power Co 79/04/26 3pp

7905100314 Forwards LER 79-005/01T-0
BURSTEIN, S Wisconsin Electric Power Co 79/04/27 1p

--7905100315 LER 79-005/01T-0 on 790417 hydraulic snubber 3/14/78-11 located on main steam line at top of B steam generator inoperable Caused by piston rod O ring leakage Snubber repaired
BURSTEIN, S Wisconsin Electric Power Co 79/04/27 2pp

7905240611 Forwards LER 79-007/01T-0
BURSTEIN, S Wisconsin Electric Power Co 79/05/07 1p

--7905240627 LER 79-007/01T-0 on 790424 vendor issued bulletin re potential problem w/turbogenerator bearing lubrication Administrative controls instituted Mods to be made as soon as possible
BURSTEIN, S Wisconsin Electric Power Co 79/05/07 3pp

7905150378 Submits addl info on LER 79-004/01T-0 re testing of 480V basis circuit breakers. Margin of about 27-s exists between worst svc condition expected & overload delay setting verified by multi-amp calibr test.
BURSTEIN, S Wisconsin Electric Power Co 79/05/10 3pp.

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHI, J American Nuclear Insurers, 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 84, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters, 79/05/01 1p.

DOCKETED ITEMS

89

7905160252 Forwards Amend 6 to Indemnity Agreement B-54, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905080474 Forwards Endorsement 36 to NELIA Policy NF-195
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc Div 79/05/03 2pp

7905080476 Forwards Endorsement 37 to NELIA Policy NF-195
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc Div 79/05/03 2pp

7905310379 Ack receipt of NRC ltr indicating info submitted by util met requirements of 10CFR140 21 Assumes no addl info needed prior to June 1980
MCKEE, C W Florida Power Corp 79/05/25 1p

P Operating license stage documents & correspondence

7905090200 Forwards request for addl info in order to complete review of proposed change to spray additive sys
REID, R W Operating Reactors Branch 4 79/04/09 3pp

7905020271 Agrees to meet w/NRC to resolve & implement safety concerns identified in 790425 Ofc of Nuclear Reactor Regulation "Status Rept to Commission" re B&W-designed reactors Intends to resolve items before 790601 startup
GRIFFIN, B L Florida Power Corp 79/04/27 3pp

7905020274 Discusses interim action, in response to 790425 Ofc of Nuclear Reactor Regulation "Status Rept to Commission" re B&W-designed reactor safety items will be resolved prior to 790601 startup
GRIFFIN, B L Florida Power Corp 79/05/01 5pp

7905150206 Responds to NRC 790329 ltr re addition of reactor coolant pump power monitors.
MOORE, G C Florida Power Corp 79/05/07 5pp

7905210272 Forwards actions & design mods, in response to safety concerns of 790425 status rept to NRC Actions include implementation of hard-wired control-grade reactor trip on loss of main feedwater or turbine trip W/affidavit
STEWART, W P Florida Power Corp 79/05/16 28pp

7905310290 Forwards Tech Specs Change Requests 40, 41, 43, 44, 45 & 48 for amend to Apps A & B of License DPR-72, consisting of changes to administrative controls, emergency feedwater sys & electrical power sys Certificate of Svc encl
STEWART, W P Florida Power Corp 79/05/23 25pp

7905300158 Forwards page change for Tech Spec change Request 46 Also forwards "Borated Water & Sodium Hydroxide Storage Tanks Drawdown Transient Analysis."
STEWART, W P Florida Power Corp 79/05/25 5pp

--7905300164 "Borated Water & Sodium Hydroxide Storage Tanks Drawdown Transient Analysis"
* Florida Power Corp 79/05/30 53pp

7905300185 Forwards revised pages to 781129 Tech Spec Change Request 27 & "Test Rept for Seismic Qualification Testing of Potential Transformer Model JYM4 & Current Transformer Model JCM4 " Certificate of Svc encl
STEWART, W P Florida Power Corp 79/05/25 10pp.

--7905300189 "Test Rept for Seismic Qualification Testing of Potential Transformer Model JYM4 & Current Transformer Model JCM4 "
* Florida Power Corp 79/05/10 19pp

7905300546 Forwards revised pages to BAW-1521, Feb 1979 Cycle 2 reload rept & to Tech Spec Change Request 39, dtd 790315 Certificate of Svc encl
STEWART, W P Florida Power Corp 79/05/25 18pp

Q Inspection reports, IE Bulletins & correspondence

7905010192 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping "
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905020404 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks "
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/26 1p

7905010102 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air "
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/28 2pp

7905010353 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin "
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/30 1p

7905080095 Forwards response to Items 1,2,3,4 & 5 in IE Bulletin 79-05A re TMI incident Review demonstrates that similar events would not result in similar consequences at Crystal River
STEWART, W P Florida Power Corp 79/04/09 77pp

7905310017 Forwards IE Insp Rept 50-302/79-14 on 790323 No noncompliance noted Discusses mgt meeting
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/10 2pp

--7905310024 IE Insp Rept 50-302/79-14 on 790323 No noncompliance noted Major areas inspected enforcement history, licensee reported events, safety performance, radiation protection, environ controls, security & QA
DANCE, H C Region 2, Atlanta, Office of the Director 79/04/09 3pp

7905010403 Ack receipt of 790403 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/79-06
MURPHY, C E Region 2, Atlanta, Office of the Director 79/04/12 1p

--7905010408 Responds to NRC 790313 ltr re violations noted in IE Insp Rept 50-302/79-06 Corrective actions welding rod holding oven temp gauges calibr at regular intervals & calibr stickers displayed
STEWART, W P Florida Power Corp 79/04/03 2pp

--7905010418 Forwards IE Insp Rept 50-302/79-06 on 790206-08 & notice of violation
MURPHY, C E Region 2, Atlanta, Office of the Director 79/03/13 2pp

--7905010421 Notice of violation from insp on 790206-08
* Region 2, Atlanta, Office of the Director 79/03/08 1p

--7905010471 IE Insp Rept 50-302/79-06 on 790206-08 Noncompliance noted failure to follow calibr control procedure & inadequate welding rod control procedures
ECNONKOS, N , CONLON, T E Region 2, Atlanta, Office of the Director 79/03/08 7pp

7905040209 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp

7905040306 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905040395 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905100238 Responds to IE Bulletin 79-03 No welded pipe from Youngstown Welding & Engineering Co is being used
STEWART, W P Florida Power Corp 79/04/16 1p

7905030162 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp

7905020463 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp

7905230628 Ack receipt of 790409 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/79-05
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/04/18 1p

DOCKETED ITEMS

- 7903230632 Forwards IE Insp Rept 50-302/79-03 on 790204-08 Notice of violation withheld (ref 10CFR2 790)
MENNA, H B Region 2, Atlanta, Safeguards Branch 79/03/16 2pp
- 7903230641 IE Insp Rept 50-302/79-03 on 790204-08 Noncompliance noted deficiency in records & repts re program for safeguarding nuclear matl Details withheld (ref 10CFR2 790)
DAVIS, C L, GILLESPIE, F P Region 2, Atlanta, Office of the Director 79/03/15 1p
- 7903240802 Responds to IE Bulletin 79-07, PIPDYN II program used on all project mods. Response based on reviews of analytical methods used to predict stresses in safety-related piping sys. conducted by B&W & Gilbert Associates
STEWART, W P. Florida Power Corp 79/04/24 4pp
- 7903250381 Act receipt of 790416 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/79-03
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/01 1p.
- 7903250390 Responds to NRC 790323 ltr re violations noted in IE Insp Rept 50-302/79-03 Corrective actions backlog data being reviewed & forwarded in retrograde manner & surveillance procedures being revised
STEWART, W P Florida Power Corp 79/04/16 2pp
- 7903250396 Forwards IE Insp Rept 50-302/79-03 on 790115-19 & notice of violation
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 2pp
- 7903250402 Notice of violation from insp on 790115-19
* Region 2, Atlanta, Office of the Director 79/03/23 1p
- 7903250410 IE Insp Rept 50-302/79-03 on 790115-19 Noncompliance noted: failure to review & approve radiation chemistry data sheet & failure to document supervisory review of surveillance test results.
SHAFFER, W D, QUICK, D, WHITT, K W Region 2, Atlanta, Office of the Director 79/02/27 7pp
- 7903290493 Responds to IE Bulletin 79-04 Results of reanalysis indicate piping stresses to be very close to original values & well within seismic stress allowable
STEWART, W P Florida Power Corp 79/03/01 2pp
- 7903290513 Forwards response to IE Bulletin 79-05 B&W has provided guidelines to assist in writing procedures for establishing & maintaining natural circulation Procedures will describe actions to take in event feedwater flow is lost
STEWART, W P Florida Power Corp. 79/03/04 3pp
- R Periodic operating reports & related correspondence
- 7903030331 Forwards revised pages (Suppl 2) to "Annual Environ Operating Rept," Vol 1
STEWART, W P. Florida Power Corp 79/04/27. 7pp.
- 7903210153 Forwards monthly operating rept for Apr 1979
STEWART, W P Florida Power Corp. 79/03/15 1p.
- 7903040094 LER 79-033/03L-0 on 790404 discovered A decay heat slug discharge throttle valve DHV-110 would not control flow in automatic Cause unknown ECCS pump operability demonstration performed w/satisfactory results
COOPER, J Florida Power Corp 79/04/23 2pp
- 7903040630 Forwards LER 79-040/03L-0
STEWART, W P Florida Power Corp 79/05/01 1p
- 7903040632 LER 79-040/03L-0 on 790405 containment purge supply valve AHV-1C would not fully open Caused by cracked right angle drive gear case Motor & drive assembly renewed
COOPER, J Florida Power Corp 79/04/27 2pp
- 7903070337 Forwards supplemental info re LER 79-016/04X-1 on 790309 environ sample analyzed w/inadequate procedures Caused by inadequate sample time No corrective action proposed
STEWART, W P Florida Power Corp 79/05/01 3pp
- 7903070397 Forwards LER 79-035/03L-0
STEWART, W P Florida Power Corp 79/05/01. 1p
- 7903070602 LER 79-035/03L-0 on 790404 radioactivity monitor RMA-61 to be incorrectly positioned while changing particulate filters Detector repositioned & returned to svc Personnel instructed on proper method of installation
COOPER, J Florida Power Corp 79/04/23 2pp
- 7903070611 Forwards LER 79-036/03L-0
STEWART, W P Florida Power Corp 79/05/01 1p
- 7903070626 LER 79-036/03L-0 on 790404 failure of meteorological monitoring tower temp monitoring device discovered during reactor bldg purge Caused by loose terminal box at 173 feet elevation Terminal tightened & returned to svc on 790407
COOPER, J Florida Power Corp 79/04/24 2pp
- 7903070624 Forwards supplemental info re LER 79-039/04L-0 on 790115 operational & preoperational studies of discharge salt marshes differed more than two std deviations Caused by natural or seasonal variations & unit thermal output
STEWART, W P Florida Power Corp 79/05/01 4pp
- 7903070645 Forwards LER 79-037/03L-0
STEWART, W P Florida Power Corp 79/05/01 1p
- 7903070648 LER 79-037/03L-0 on 790407 RCS sample valve CAV-2 would close Cause unknown CAV-2 cycled & returned to svc on 790425
COOPER, J Florida Power Corp 79/04/26 2pp
- 7903070652 Forwards LER 79-038/03L-0.
STEWART, W P Florida Power Corp 79/05/01 1p
- 7903070654 LER 79-038/03L-0 on 790409 pressurizer water space slug line isolation valve CAV-3 would not close Cause unknown CAV-3 tested & returned to svc on 790413
COOPER, J Florida Power Corp 79/05/01 2pp
- 7903080429 Forwards supplemental info re LER 79-016/04X-1 in Jan 1979 environ samples were not analyzed using procedures required in ETS Caused by inadequate sample time
STEWART, W P Florida Power Corp. 79/05/01 1p.
- 7903090278 Forwards LER 79-041/03L-0
STEWART, W P Florida Power Corp 79/05/04 1p
- 7903090281 LER 79-041/03L-0 on 790409 methyl iodine removal efficiency was less than 99% Caused by flue gases & other site airborne pollutants deteriorating charcoal & its impregnant Charcoal will be renewed following plant refueling
COOPER, J Florida Power Corp 79/05/01 2pp
- 7903110241 Forwards LER 79-042/03L-0.
STEWART, W. P. Florida Power Corp. 79/05/07. 1p
- 7903110244 LER 79-042/03L-0 on 790411 storage tank IA level decreased to 308,500 gallons. Caused by improper lineup Tank filled to Tech Spec limit.
COOPER, J Florida Power Corp 79/05/02 2pp.
- 7903190023 Forwards LER 79-043/03L-0.
STEWART, W P Florida Power Corp. 79/05/14. 1p.
- 7903190028 LER 79-043/03L-0 on 790420 channel functional & ctrl. operability of fire protection instrumentation SP-190 not performed in required time. Caused by personnel error in scheduling surveillance procedure
COOPER, J Florida Power Corp. 79/05/08 2pp

DOCKETED ITEMS

91

7905230369 Forwards LER 79-044/03L-0
STEWART, W P Florida Power Corp 79/05/18 1p

--7905230373 LER 79-044/03L-0 on 790423 while attempting to add boric acid to RCS, chemical addition pump 1B would not operate Cause under investigation Corrective actions will be based on evaluation results
COOPER, J Florida Power Corp 79/05/10 2pp

7905230375 Forwards LER 79-016/04X-2
STEWART, W P Florida Power Corp 79/05/18 1p

--7905230380 LER 79-016/04X-2 on 790511 environ samples not analyzed using procedures providing lowest level detectors equal to or less than Tech Specs requirements Caused by inadequate sample time
* Florida Power Corp 79/05/15 2pp

7905230383 Forwards LER 79-046/03L-0
STEWART, W P Florida Power Corp 79/05/22 1p

--7905230385 LER 79-046/03L-0 on 790425 during plant cooldown for refueling outage, decay heat removal valve 4 failed to open upon remote activation Caused by washer binding at stem nut interface & inadequate lubrication & torque limiter setting
COOPER, J Florida Power Corp 79/05/18 2pp

7905300497 Forwards LER 79-045/03L-0,
STEWART, W P Florida Power Corp 79/05/22 1p

--7905300503 LER 79-045/03L-0 on 790424 core flood valve CFV-5 annunciator did not actuate properly Cause unknown Corrective action to be taken prior to ascension into Mode 3
COOPER, J Florida Power Corp 79/05/14 2pp

7905300484 Forwards LER 79-048/03L-0
STEWART, W P Florida Power Corp 79/05/25 1p

--7905300491 LER 79-048/03L-0 on 790501 reactor coolant snubber RCM-90 found inoperable Caused by inadvertent damage to snubber by unknown persons Snubber replaced & spare tested satisfactorily
COOPER, J Florida Power Corp 79/05/23 2pp

7905310371 Forwards LER 79-047/03L-0
STEWART, W P Florida Power Corp 79/05/25 1p

--7905310403 LER 79-047/03L-0 on 790428, boron concentration in boric acid tank exceeded level of Tech Spec Caused by inadequate design, Request for engineering info was initiated to provide corrective measure
COOPER, J Florida Power Corp 79/05/25 2pp

DOCKET 30-303 CRYSTAL RIVER NUCLEAR PLANT, UNIT 4

P. Operating license stage documents & correspondence

7905310298 Forwards Tech Specs Change Requests 40, 41, 43, 44, 45 & 48 for amend to Apps A & B of License DPR-72, consisting of changes to administrative controls, emergency feedwater sys & electrical power sys, Certificate of Svc encl
STEWART, W P Florida Power Corp 79/05/23 25pp

DOCKET 30-304 ZION NUCLEAR POWER STATION, UNIT 2

E NRC Safety Evaluation Report (SER), supps & correspondence

7905240995 Forwards SER & EIA re plant spent fuel pool mods W/o encl
GODDARD, R J Branch 2 79/04/03 1p

F Security, medical, emergency & fire protection plans

7905030366 Forwards modified physical security plan, Revision 5 Plan withheld (ref 10CFR2 790)
LEE, B Commonwealth Edison Co 79/04/24 1p

7905290077 Forwards Chemtron drawings FL27652-7, sheets 1 through 5, w/design details for fire suppression sys to be installed for auxiliary feedwater sys & component cooling pumps Oversize drawings encl
NAUGHTON, W F Commonwealth Edison Co 79/05/23 2pp

G. Adjudicatory correspondence

7905230768 Affidavit of M Resnikoff re spent fuel issue, Professional qualifications & Certificate of Svc encl
RESNIKOFF, M R Illinois, State of 79/02/23 12pp

7905300711 Responds to State of IL's 790221 motion for continuance & request to allow future supplementation of intervenor's affidavits Certificate of Svc encl
GODDARD, R J Branch 2 79/03/13 4pp

7905070154 Forwards SER & EIA re spent fuel pool mods W/o encl
GODDARD, R J Branch 2 79/04/03 1p

7905250158 Provides list of witnesses for util in Zion spent fuel case
STEPHENS, P Isham, Lincoln & Beale 79/04/03 2pp

7905300022 Request by util on its own behalf & on behalf of State of IL & NRC, for ASLB to begin hearings on 790514 Certificate of Svc encl
BIELAWSKI, A P Isham, Lincoln & Beale 79/04/06 3pp

7905100121 Interrogatories submitted to state of IL per ASLB 790119 order Certificate of Svc encl
GODDARD, R J Branch 2 79/04/09 4pp

7905150256 Motion to file supplementary affidavits to response to util & NRC motions for summary disposition Affidavits of DO Bridenbaugh & GC Minor & Certificate of Svc encl
SEKULER, S N Illinois, State of 79/04/10 23pp

7905150248 Forwards unexecuted affidavit of M Resnikoff Certificate of Svc encl
SEKULER, S N Illinois, State of 79/04/13 4pp

7905150691 Forwards Chapter 1 of SAND77-1371, "Spent Fuel Heatup Following Loss of Water During Storage," which contains info relevant to util's application to increase spent fuel storage pool capacity Requests to be placed on svc list
WEBB, R E Affiliation Unknown 79/04/13 40pp

7905230367 Moves for summary disposition of State of IL's Contention 2(a)-(d) for lack of genuine issue of matl fact Affidavits, notices of appearance & withdrawal & Certificate of Svc encl
GOLDBERG, S C Branch 2 79/04/27 20pp

7905150243 Denies summary disposition of intervenors' Contentions 2(f) (2), 2(g), 2(h) & 2(i) Grants summary disposition of intervenors' Contention 2(n)
LUTON, E Atomic Safety and Licensing Board Panel 79/08/01 3pp

H General correspondence

7905070014 Responds to 790202 ltr requesting info re leakage of water through liner of spent fuel pool at facility NRC is monitoring util's efforts to control seepage
STELLO, V Division of Operating Reactors 79/04/19 79pp

J Insurance & indemnity information

7905100163 Endorsement 99 to MAELU Policy MF-22
GERAS, T Nuclear Energy Liability Insurance Association 79/03/27 1p

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & oth
QUATTROCHILI, J American Nuclear Insurers 79/03/01

7905070582 Confirms increase in liability limit tr policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51 -- 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M 1p

DOCKETED ITEMS

--7905230632 Forwards IE Insp Rept 50-302/79-03 on 790204-08 Notice of violation withheld (ref 10CFR2 7901 KENNA, W B Region 2, Atlanta, Safeguards Branch 79/03/16 2pp

--7905230641 IE Insp Rept 50-302/79-03 on 790204-08 Noncompliance noted deficiency in records & repts re program for safeguarding nuclear matl Details withheld (ref 10CFR2 7901 DAVIS, C L, GILLESPIE, F P Region 2, Atlanta, Office of the Director 79/03/15 1p

7905240802 Responds to IE Bulletin 79-07 PIPBYN II program used on all project mode Response based on reviews of analytical methods used to predict stresses in safety-related piping sys. conducted by B&W & Gilbert Associates STEWART, W P Florida Power Corp 79/04/24 4pp

7905250381 Ack receipt of 790416 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/79-03 LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/01 1p

--7905250390 Responds to NRC 790323 ltr re violations noted in IE Insp Rept 50-302/79-03 Corrective actions backlog data being reviewed & forwarded in retrograde manner & surveillance procedures being revised STEWART, W P Florida Power Corp 79/04/16 2pp

--7905250396 Forwards IE Insp Rept 50-302/79-03 on 790115-19 & notice of violation LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 2pp

--7905250402 Notice of violation from insp on 790115-19 * Region 2, Atlanta, Office of the Director 79/03/23 1p

--7905250410 IE Insp Rept 50-302/79-03 on 790115-19 Noncompliance noted failure to review & approve radiation chemistry data sheet & failure to document supervisory review of surveillance test results SHAFER, W D, QUICK, D, WHITT, K W Region 2, Atlanta, Office of the Director 79/02/27 7pp

7905290493 Responds to IE Bulletin 79-04 Results of reanalysis indicate piping stresses to be very close to original values & well within seismic stress allowable STEWART, W P Florida Power Corp 79/05/01, 2pp

7905290013 Forwards response to IE Bulletin 79-05B B&W has provided guidelines to assist in writing procedures for establishing & maintaining natural circulation Procedures will describe actions to take in event feedwater flow is lost STEWART, W P Florida Power Corp, 79/05/04 3pp

R Periodic operating reports & related correspondence

7905030351 Forwards revised pages (Suppl 2) to "Annual Environ Operating Rept," Vol 1 STEWART, W P Florida Power Corp 79/04/27 7pp

7905210153 Forwards monthly operating rept for Apr 1979 STEWART, W P Florida Power Corp 79/05/15 1p

--7905210154 Monthly operating rept for Apr 1979 KENNEDY, R W Florida Power Corp 79/05/07 5pp

B Reportable occurrences, LERs & related correspondence

7905070538 Forwards LER 79-005/01T STEWART, W P Florida Power Corp 79/03/27 1p.

--7905070540 LER 79-005/01T-1 on 790123 until was notified that Rockwell Mfg Co HSIV may not close within Tech Spec 3-a limit during accident. Caused by discovery of addl forces on valve disc Valves to be modified COOPER, J. Florida Power Corp 79/04/25 10pp

7905040043 Forwards LER 79-034/03L-0. STEWART, W P Florida Power Corp 79/04/26 1p

--7905040050 LER 79-034/03L-0 on 790404 power supply breaker for reactor bldg radioactivity monitor RMA-6 was in tripped position Cause unknown. Breaker reset & RMA-6 returned to svc after satisfactory completion of SP-355 test. COOPER, J. Florida Power Corp 79/04/23 2pp

7905040088 Forwards LER 79-033/03L-0 STEWART, W P. Florida Power Corp 79/04/27 1p

--7905040094 LER 79-033/03L-0 on 790404 discovered A decay heat 114 discharge throttle valve DHV-110 would not control flow in automatic Cause unknown ECCS pump operability demonstration performed w/satisfactory results COOPER, J. Florida Power Corp 79/04/23 2pp

7905040630 Forwards LER 79-040/03L-0. STEWART, W P Florida Power Corp 79/05/01 1p

--7905040632 LER 79-040/03L-0 on 790405 containment purge supply valve AHV-1C would not fully open Caused by cracked right angle drive gear case Motor & drive assembly renewed COOPER, J. Florida Power Corp 79/04/27 2pp

7905070537 Forwards supplemental info re LER 79-016/04X-1 on 790309 environ sample analyzed w/inadequate procedures Caused by inadequate sample time No corrective action proposed STEWART, W P. Florida Power Corp 79/05/01 3pp

7905070597 Forwards LER 79-035/03L-0 STEWART, W P Florida Power Corp 79/05/01 1p

--7905070602 LER 79-035/03L-0 on 790404 radioactivity monitor RMA-6 to be incorrectly positioned while changing particulate filters. Detector repositioned & returned to svc Personnel instructed on proper method of installation COOPER, J. Florida Power Corp 79/04/23 2pp

7905070611 Forwards LER 79-036/03L-0 STEWART, W P Florida Power Corp, 79/05/01 1p

--7905070626 LER 79-036/03L-0 on 790404 failure of meteorological monitoring tower temp monitoring device discovered during reactor bldg purge Caused by loose terminal box at 175 feet elevation Terminal tightened & returned to svc on 790407 COOPER, J. Florida Power Corp 79/04/24 2pp

7905070624 Forwards supplemental info re LER 79-039/04L-0 on 790407 operational & preoperational studies of discharge salt marches differed more than two std deviations Caused by natural or seasonal variations & unit thermal output STEWART, W P Florida Power Corp 79/05/01 4pp

7905070645 Forwards LER 79-037/03L-0 STEWART, W P Florida Power Corp 79/05/01 1p

--7905070648 LER 79-037/03L-0 on 790407 RCB sample valve CAV 2 m. close Cause unknown CAV-2 cycled & returned to svc on 790425 COOPER, J. Florida Power Corp 79/04/26, 2pp

7905070652 Forwards LER 79-038/03L-0. STEWART, W P Florida Power Corp. 79/05/01 1p.

--7905070654 LER 79-038/03L-0 on 790409 pressurizer water sp. line isolation valve CAV-3 would not close Cause unknown CAV-3 tested & returned to svc on 790413. COOPER, J. Florida Power Corp 79/05/01 2pp

7905080429 Forwards supplemental info re LER 79-016/04L-1 in Jan 79 environ samples were not analyzed using procedures required in ETS. Caused by inadequate sample time STEWART, W P Florida Power Corp 79/05/01. 1p

7905090278 Forwards LER 79-041/03L-0 STEWART, W P Florida Power Corp 79/05/04. 1p

--7905090281 LER 79-041/03L-0 on 790409 methyl iodine removal sys was less than 99% Caused by flue gases & other site airbore pollutants deteriorating charcoal & its impregnant Charcoals will be renewed following plant refueling COOPER, J. Florida Power Corp 79/05/01. 2pp

7905110241 Forwards LER 79-042/03L-0 STEWART, W P Florida Power Corp 79/05/07 1p

--7905110244 LER 79-042/03L-0 on 790411 storage tank 1A level 6.5 L to 308,500 gallons. Caused by improper lineup Tank filled to Tech Spec limit. COOPER, J. Florida Power Corp. 79/05/02. 2pp

7905190023 Forwards LER 79-043/03L-0. STEWART, W P Florida Power Corp 79/05/14 1p

--7905190028 LER 79-043/03L-0 on 790420 channel functions & sys. operability of fire protection instrumentation BP-190 not performed in required time Caused by personnel error in scheduling surveillance procedure. COOPER, J. Florida Power Corp. 79/05/08 2pp

7903230369 Forwards LER 79-044/03L-0
STEWART, W P Florida Power Corp 79/03/18 1p

--7903230373 LER 79-044/03L-0 on 790423 while attempting to add boric acid to RCB, chemical addition pump 1B would not operate Cause under investigation Corrective actions will be based on evaluation results
COOPER, J Florida Power Corp 79/03/10 2pp

7903250375 Forwards LER 79-016/04X-2
STEWART, W P Florida Power Corp 79/03/18 1p

--7903250380 LER 79-016/04X-2 on 790511 environ samples not analyzed using procedures providing lowest level detectors equal to or less than Tech Specs requirements Caused by inadequate sample time
* Florida Power Corp 79/03/15 2pp

7903250383 Forwards LER 79-046/03L-0
STEWART, W P Florida Power Corp 79/03/22 1p

--7903250385 LER 79-046/03L-0 on 790423 during plant cooldown for refueling outage, decay heat removal valve 4 failed to open upon remote activation Caused by washer binding at stem nut interface & inadequate lubrication & torque limiter setting
COOPER, J Florida Power Corp 79/03/18 2pp

7903300477 Forwards LER 79-045/03L-0.
STEWART, W P Florida Power Corp 79/03/22 1p

--7903300503 LER 79-045/03L-0 on 790424, core flood valve CFV-5 annunciator did not actuate properly Cause unknown Corrective action to be taken prior to ascension into Mode 3
COOPER, J Florida Power Corp 79/03/14 2pp

7903300484 Forwards LER 79-048/03L-0
STEWART, W P Florida Power Corp 79/03/25 1p

--7903300491 LER 79-048/03L-0 on 790501 reactor coolant snubber RCH-90 found inoperable Caused by inadvertent damage to snubber by unknown persons Snubber replaced & spare tested satisfactorily
COOPER, J Florida Power Corp. 79/03/23 2pp

7903310391 Forwards LER 79-047/03L-0
STEWART, W P Florida Power Corp 79/03/25 1p

--7903310403 LER 79-047/03L-0 on 790428 boron concentration in boric acid tank exceeded level of Tech Spec Caused by inadequate design Request for engineering info was initiated to provide corrective measure.
COOPER, J Florida Power Corp 79/03/25 2pp

7903300711 Responds to State of IL's 790221 motion for continuance & request to allow future supplementation of intervenor's affidavits Certificate of Svc encl
GODDARD, R J Branch 2 79/03/13 4pp

7905070154 Forwards SER & EIA re spent fuel pool mods W/o encl
GODDARD, R J Branch 2 79/04/03 1p

7905250158 Provides list of witnesses for util in Zion spent fuel case
STEPTOE, P Isham, Lincoln & Beale 79/04/03 2pp

7905300022 Request by util on its own behalf & on behalf of State of IL & NRC, for ASLB to begin hearings on 790514 Certificate of Svc encl
BIELAWSKI, A P Isham, Lincoln & Beale 79/04/06 3pp

7905100121 Interrogatories submitted to state of IL per ASLB 790119 order Certificate of Svc encl
GODDARD, R J Branch 2 79/04/09 4pp

7905150256 Motion to file supplementary affidavits to response to util & NRC motions for summary disposition Affidavits of DO Bridenbaugh & QC Minor & Certificate of Svc encl
SEKULER, S N Illinois, State of 79/04/10 23pp

7905150248 Forwards unexecuted affidavit of M Resnikoff Certificate of Svc encl
SEKULER, S N Illinois, State of 79/04/13 4pp

7905150491 Forwards Chapter 1 of SAND77-1371, "Spent Fuel Heatup Following Loss of Water During Storage," which contains info relevant to util's application to increase spent fuel storage pool capacity Requests to be placed on svc list
WEBB, R E Affiliation Unknown 79/04/13 40pp

7905250367 Moves for summary disposition of State of IL's Contention 2(a)-(d) for lack of genuine issue of matl fact Affidavits, notices of appearance & withdrawal & Certificate of Svc encl
GOLDBERG, S C Branch 2 79/04/27 20pp

7905150243 Denies summary disposition of intervenors' Contentions 2(f) (2), 2(g), 2(h) & 2(i) Grants summary disposition of intervenors' Contention 2(n)
LUTON, E Atomic Safety and Licensing Board Panel 79/08/01 3pp

H General correspondence

7905070014 Responds to 790202 ltr requesting info re leakage of water through liner of spent fuel pool at facility NRC is monitoring util's efforts to control seepage
STELLO, V Division of Operating Reactors 79/04/19 7pp

J Insurance & indemnity information

7905100163 Endorsement 99 to MAELU Policy MF-22
GERAS, T Nuclear Energy Liability Insurance Association 79/03/27 1p

7905070497 Confirms increased liability limit to \$124.1 policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 167, 173, 174, 178, 179, 180, 182, 183, 186, 187, 188, 189, 192, 193, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & et.
QUATTROCHINI, J American Nuclear Insurers 79/05/01

7905070582 Confirms increase in liability limit to \$36.C policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwrit 1p

7905140470 Forwards Amend 9 to Indemnity Agreement B-59 changes re increase in liability insurance from \$140 r to \$160 million, effective 790501 Supporting document encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01

7905160399 Confirms 790507 & 08 agreement w/NRC that He need not sign Amend 7 to Indemnity Agreement B-36
CAMP, O T Johnson & Higgins Insurance 79/05/09 1

P Operating license stage documents & correspondence

7905250183 Amends 47 & 44 to Licenses DPR-39 & DPR-48, r revising Tech Specs re rod drop time
SCHWENGER, A Operating Reactors Branch 1 79/04/

DOCKET 80-303 CRYSTAL RIVER NUCLEAR PLANT, UNIT 4

P Operating license stage documents & correspondence

7905310298 Forwards Tech Specs Change Requests 40, 41, 43, 44, 45 & 48 for amend to Apps A & B of License DPR-72, consisting of changes to administrative controls, emergency feedwater sys & electrical power sys, Certificate of Svc encl
STEWART, W P Florida Power Corp 79/03/23 25pp

DOCKET 80-304 ZION NUCLEAR POWER STATION, UNIT 2

E NRC Safety Evaluation Report (SER), suppl & correspondence

7905240795 Forwards SER & EIA re plant spent fuel pool mods W/o encl
GODDARD, R J Branch 2, 79/04/03 1p

F Security, medical, emergency & fire protection plans

7905030346 Forwards modified physical security plan, Revision 5, Plan withheld (ref 10CFR2.790)
LEE, B Commonwealth Edison Co 79/04/26 1p.

7905240079 Forwards Chemtron drawings FL27652-7, sheets 1 through 5, w/design details for fire suppression sys to be installed for auxiliary feedwater sys & component cooling pumps Oversize drawings encl.
NAUGHTON, W F Commonwealth Edison Co 79/05/23 2pp

G Adjudicatory correspondence

7905230748 Affidavit of M Resnikoff re spent fuel issue Professional qualifications & Certificate of Svc encl.
RESNIKOFF, M R Illinois, State of. 79/02/23 12pp

DOCKETED ITEMS

--7903250187 Safety evaluation supporting Amends 47 & 44 to Licenses DPR-39 & DPR-48, respectively
* Office of Nuclear Reactor Regulation 79/04/09 3pp

--7903250190 Notice of issuance & availability of Amends 47 & 44 to Licenses DPR-39 & DPR-48, respectively
SCHWENCER, A Operating Reactors Branch 1 79/04/09 2pp

7903040482 Notices of intention to develop safety analysis using existing computer codes Request addl info
BOLBRIG, C W Commonwealth Edison Co 79/04/26 1p

7903040502 Requests amend to Tech Specs to require actuation of safety injection based on two out of three channels of low pressurizer pressure & to delete pressurizer level from safeguards logic Class I & II amend fees encl
REED, C Commonwealth Edison Co 79/04/30 7pp

7903100251 "Gamma Dose Measurements at Zion & Fort Calhoun Stations"
DYER, N C, BUNTING, R L, NIESCHMIDT, E B EO & O, Inc FIN A-6075
NUREG/CR-0755 79/04/30 137pp Available at NTIS \$7 25

7903070396 Forwards response to request for addl info re review of proposed license amend to increase allowable LOCA peaking factor limit to 1.93 based on ECCS reanalysis
NAUGHTON, W F Commonwealth Edison Co 79/05/03 4pp

7903250423 Forwards Amends 49 & 46 to Licenses DPR-39 & DPR-48, respectively, safety evaluation & notice of issuance & availability
SCHWENCER, A Operating Reactors Branch 1 79/05/03 2pp

--7903250432 Amends 49 & 46 to Licenses DPR-39 & DPR-48, respectively
SCHWENCER, A Operating Reactors Branch 1 79/05/03 16pp

--7903250435 Safety evaluation supporting Amends 49 & 46 to Licenses DPR-39 & DPR-48, respectively
* Operating Reactors Branch 1 79/04/03 3pp

--7903250440 Notice of issuance & availability of Amends 49 & 46 to Licenses DPR-39 & DPR-48, respectively
SCHWENCER, A Operating Reactors Branch 1 79/05/03 2pp

7903170237 Forwards revised Tech Specs re heating & cooldown curves & added provision for overpressure protection
REED, C Commonwealth Edison Co 79/05/11 2pp

--7903170255 Revised Tech Specs re startup & cooldown curves & added provision for overpressure protection
* Commonwealth Edison Co 79/05/11 4pp

7903250391 Forwards current licensing open items status list.
REED, C Commonwealth Edison Co 79/05/18 11pp

Q Inspection reports, IE Bulletins & correspondence

7903020421 Forwards response to IE Bulletins 78-12 & 78-12A, "Atypical Weld Metl in Reactor Pressure Vessel Welds"
REED, C Commonwealth Edison Co 79/03/22 10pp

7903010236 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/23

Forwards IE Info Notice 79-07, "Rupture of Radiowaste Tanks"
Region 3, Chicago, Office of the Director 79/03/26

7903010384 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/31p

7903030007 Forwards IE Bulletin 79-06, "Review of Operational Errors Sys Misalignments Identified During TMI Incident" Licensee action required
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/11p

7903250280 Responds to IE Bulletin 79-03 re welding defects in certain longitudinally welded pipe spools Plants inspected, no pipe found
REED, C Commonwealth Edison Co 79/04/12 2pp

7903010572 Forwards IE Bulletin 79-04A, "Review of Operational Errors Sys Misalignments Identified during TMI Incident" Licensee action required
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/11p

7903040334 Forwards IE Bulletin 79-06B, "Review of Operational Errors Sys Misalignments Identified During TMI Incident"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/11p

7903040527 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/11p

7903030206 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/11p

7903040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/11p

--7903040158 IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl" Supporting documentation encl
* Region 3, Chicago, Office of the Director 79/04/21, 12pp

--7903040170 ACRS recommendations re 790328 incident at TMI Suggests priority be placed on development of safety research on behavior of LWRs during anomalous transients
* ACRS - Advisory Committee on Reactor Safeguards 79/04/17 2pp

--7903040201 Forwards ACRS recommendations re TMI incident, presented 790417
FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards 79/04/18 1p

--7903040221 In response to NRC 790418 ltr, states all 790417 ACRS recommendations apply to all PWRs, but were not intended to require immediate changes Plant mods should be made after study of effects on overall safety, TMI excluded
CARBON, M X ACRS - Advisory Committee on Reactor Safeguards 79/04/20 2pp

7903240633 Forwards responses to IE Bulletin 79-07 requesting info seismic analysis of safety-related piping Reanalysis indicates method of intramodal combination has little effect on pipe stresses & equipment support loads.
REED, C Commonwealth Edison Co 79/04/24 4pp

7903150768 Forwards IE Insp Repts 59-295/79-06 & 50-304/79-07 on 790319-23 Notice of violation withheld (ref 10CFR2.790)
HIND, J. A Region 3, Chicago, Safeguards Branch 79/04/26 1

--7903150775 IE Insp Repts 50-295/79-06 & 50-304/79-07 on 790319-23 Noncompliance details withheld (ref 10CFR2.790)
BELANGER, J L., HOWELL, J C Region 3, Chicago, Office of the Director HIND, J. A Region 3, Chicago, Safeguards Branch 79/04/19 1p

7903000242 Responds to IE Bulletin 79-04 No 3, 4 or 6-inch Velan w check valves are in use at Dresden or Quad Cities. Review of Zion has identified use of subj valves in some piping sys but review is incomplete. Will rept later
REED, C Commonwealth Edison Co 79/03/01 2pp

DOCKETED ITEMS

93

R Periodic operating reports & related correspondence

7905090322 Forwards "Annual Operating Rept 1978 "
HANDKE,N F Commonwealth Edison Co 79/04/26 1p

--7905090323 "Annual Operating Rept 1978 "
* Commonwealth Edison Co 79/04/26 24pp

S Reportable occurrences, LERs & related correspondence

7905100300 Forwards LER 79-027/03L-0
HANDKE,N E Commonwealth Edison Co. 79/04/30 1p

--7905100302 LER 79-027/03L-0 on 790415 2LT-461 found to be 77 higher
than other two channels Caused by Barton sealed ref leg
level transmitter being out of calibr
HANSEN,P W Commonwealth Edison Co 79/04/30 1p

7905100306 Forwards LER 79-021/03L-0
HANDKE,N E Commonwealth Edison Co 79/04/30 1p

--7905100310 LER 79-021/03L-0 on 790330 transmitters 2FT-444, 445 & 446
for reactor coolant flow loop B high by 4.7%, 4.49% & 4.125%,
respectively Caused by instrument drift New calibr
technique being used
CAMPBELL,J Commonwealth Edison Co 79/04/30 1p

7905240550 Forwards LER 79-025/03L-0
HANDKE,N E Commonwealth Edison Co 79/05/08 1p

--7905240553 LER 79-025/03L-0 on 790412 temp control module TY-45
discovered missing on hydrogen recombiner. Caused by
mechanic's failure to notify shift engineer of removal for
repair Item reinstalled
JOOSTEN,J K Commonwealth Edison Co 79/05/08 1p

DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT-

Q Adjudicatory correspondence

7905230973 Notifies that prehearing conference & hearing will be held
re alleged violations by licensee & imposition of
penalties.
CHILK,B J Office of the Secretary of the Commission. 79/04/30
3pp

H General correspondence

7905160364 Notifies that ER Mathews is now vice president of company
EW James retired on 790301
FOX,B Wisconsin Public Service Corp 79/05/07 1p

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1, 29, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHHI,J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 84, 87,
88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS,D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01
1p

7905160273 Forwards Amend 6 to Indemnity Agreement B-53, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790301. Supporting documentation encl.
SALTZMAN,J Antitrust & Indemnity Group 79/05/01 5pp.

7905240384 Forwards accepted Amend 6 to Indemnity Agreement B-53,
effective 790301.
MATHEWS,E R Wisconsin Public Service Corp 79/05/18 3pp

P. Operating license stage documents & correspondence

7905020490 Discusses 790315 telcon w/R Bero of Westinghouse re
incorrect weights for Velan Model C658 6-inch check valves
used in safety injection sys
SCHWENCER,A Operating Reactors Branch 1 79/04/02 1p

7905240895 Forwards Amend 27 to License DPR-43 & notice of issuance
& availability.
SCHWENCER,A Operating Reactors Branch 1 79/04/05 3pp

--7905240905 Amend to License DPR-43, changing titles of functional
positions & recognizing addl positions
SCHWENCER,A Operating Reactors Branch 1 79/04/05 11pp

--7905240911 Notice of issuance & availability of Amend 27 to License
DPR-43
SCHWENCER,A Operating Reactors Branch 1 79/04/05 2pp

7905240373 Forwards Amend 28 to License DPR-43 & notice of issuance &
availability Security plan evaluation withheld
(ref 10CFR2 790)
SCHWENCER,A Operating Reactors Branch 1 79/04/10 3pp

--7905240378 Amend 28 to License DPR-43, incorporating industrial security
manual
SCHWENCER,A Operating Reactors Branch 1 79/04/10 2pp

--7905240382 Notice of issuance & availability of Amend 28 to License
DPR-43
SCHWENCER,A Operating Reactors Branch 1 79/04/10 3pp

7905150071 Forwards info in response to 790321 request re details of
plant shutdowns
DENTON,H R Office of Nuclear Reactor Regulation 79/04/18 4pp

7905240471 Discusses draft safety evaluation of mod to drop pressurizer
level as required ECCB initiating signal Mod 6 Tech Spec
changes acceptable
LAINAS,G Plant Systems Branch 79/04/27 1p

7905290050 Forwards Amend 29 to License DPR-43, safety evaluation &
notice of issuance & availability
SCHWENCER,A Operating Reactors Branch 1 79/04/27 2pp

--7905290054 Amend 29 to License DPR-43 revising Tech Specs to require
actuation of safety injection based on two out of three
channels of low pressurizer pressure
SCHWENCER,A Operating Reactors Branch 1 79/04/27 6pp

--7905290060 Safety evaluation supporting Amend 29 to License DPR-43
* Office of Nuclear Reactor Regulation 79/04/27 2pp

--7905290064 Notice of issuance & availability of Amend 29 to License
DPR-43
SCHWENCER,A Operating Reactors Branch 1 79/04/27 2pp

7905100289 Forwards Exxon Nuclear Co rept XN-NF-79-27, "Cycle 5 BAR" &
WI Nuclear Co repts "Reload Safety Evaluation," dtd 790431,
& "Reactor Test Program," dtd 790531
MATHEWS,E R Wisconsin Public Service Corp 79/05/08 1p

--7905100290 "Cycle 5 BAR "
JOHNSON,B L, CHERNO,J C, SKOGEN,F D Exxon Nuclear Co, Inc
(subs of Exxon Corp) XN-NF-79-27 79/04/30 33pp

--7905100291 "Reactor Test Program "
* Wisconsin Public Service Corp 79/05/01 27pp

--7905100292 "Reload Safety Evaluation "
HOLLY,J T, ROPSON,D J, WOZNIAK,B F Wisconsin Public Service
Corp 79/04/30 54pp

7905300028 Forwards "Reactor Test Program "
MATHEWS,E R Wisconsin Public Service Corp 79/05/22 1p

--7905300030 "Reactor Test Program, Revision 1 "
* Wisconsin Public Service Corp 79/05/22 30pp.

G Inspection reports, IE Bulletins & correspondence

7905010273 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping "
KEPPLER,J Q Region 3, Chicago, Office of the Director 79/03/23
1p

7905040065 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks "
KEPPLER,J Q Region 3, Chicago, Office of the Director 79/03/26
1p

7905010186 Forwards IE Info Notice 79-08, "Interconnection of
Contaminated Sys w/Svc Air Sys Used as Source of Breathing
Air "
KEPPLER,J Q Region 3, Chicago, Office of the Director 79/03/28
1p

DOCKETED ITEMS

7905030069 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/11 1p

7905010615 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040434 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040443 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040600 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident " Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905290501 Responds to IE Bulletin 79-03 Investigation of piping records reveals that welded seam pipe mfg by Youngstown Welding & Engineering Co not used in fabrication of safety-related sys at facility
MATHEWS, E R Wisconsin Public Service Corp 79/04/16 1p

7905030255 Forwards IE Bulletin 79-09, "Failures of OE Type AX-2 Circuit Breaker in Safety-Related Sys " Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/17 1p

7905080519 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl " Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/21 1p

7905240289 Responds to IE Bulletin 79-07 re seismic stress analysis of safety-related piping Method used in analysis of seismic loading is square root of sum of squares, not that mentioned in bulletin
MATHEWS, E R Wisconsin Public Service Corp 79/04/25 12pp

7905240319 Responds to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp " Accepted weights reanalyzed & found to be within allowable safety limits.
MATHEWS, E R Washington Public Power Supply System 79/04/26 3pp

R Periodic operating reports & related correspondence

7905150330 Forwards monthly operating rept for Apr 1979
MATHEWS, E R Wisconsin Public Service Corp. 79/05/07 1p

--7905150335 Monthly operating rept for Apr 1979.
WALLACE, J J Wisconsin Public Service Corp 79/04/30 4pp

table occurrences, LERs & related correspondence

--7905300399 LER 79-002/01X-2 on 790221 diesel generator 1A manual speed control failed on 790221, 0302 & 13 Caused by excessive wear to bronze pinion in synchro-motor gear housing due to improper gear alignment
RUITER, O H, MARCHI, M L Wisconsin Public Service Corp 79/05/2 5pp

DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

7905070439 Forwards info requested in NRC 790206 ltr re fire protection program Revision to 790518 fire protection outline encl.
MAYER, L D Northern States Power Co 79/05/02 13pp

7905300406 Forwards supplemental info on status of security plan implementation Info withheld (ref 10CFR2 790)
MAYER, L D Northern States Power Co 79/05/25 1p

I Financial information

7905150235 Forwards "Financial & Statistical Info" as suppl to "Annual Financial Rept 1978 "
BRUSVEN, A D Northern States Power Co 79/05/10 1p

--7905150231 "Financial & Statistical Info," submitted as suppl to "Annual Financial Rept 1978 "
* Northern States Power Co 79/03/31 21pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies MF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATRECHINI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 27, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905140477 Forwards Amend 7 to Indemnity Agreement B-60 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp

7905230394 Forwards Amend 9 to Indemnity Agreement B-42 & Amend 7 to Indemnity Agreement B-60.
JOHNSON, R O Northern States Power Co 79/05/18 5pp

P Operating license stage documents & correspondence

7905020490 Discusses 790315 telcon w/R Bero of Westinghouse re incorrect weights for Velan Model C65B 6-inch check valves used in safety injection sys
SCHWENCER, A. Operating Reactors Branch 1 79/04/02 1p.

7905020236 Forwards FWRPTS computer code input & affidavit requesting exemption from public disclosure Computer code input withheld (ref 10CFR2 790)
MAYER, L O Northern States Power Co 79/04/18 35pp

7905240308 Forwards Amends 35 & 29 to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability
SCHWENCER, A. Operating Reactors Branch 1 79/04/20 3pp.

--7905240322 Amends 35 & 29 to Licenses DPR-42 & DPR-60, respectively changing common station Tech Specs re refueling & incorporating changes to App A Tech Specs to support operation in Cycle 5 w/reload fuel by Exxon Nuclear Co.
SCHWENCER, A. Operating Reactors Branch 1. 79/04/20. 19pp

--7905240329 Safety evaluation supporting Amends 35 & 29 to Licenses DPR-42 & DPR-60, respectively.
* Office of Nuclear Reactor Regulation 79/04/20 19pp

--7905240333 Notice of issuance & availability of Amends 35 & 29 to Licenses DPR-42 & DPR-60, respectively.
SCHWENCER, A. Operating Reactors Branch 1. 79/04/20. 3pp.

DOCKETED ITEMS

95

7905010474 Forwards application for amend to Licenses DPR-42 & DPR-60, changing Tech Specs re pressurizer initiating signals for safety injection signals Amend fee & proposed Tech Spec changes encl
MAYER, L O Northern States Power Co 79/04/26 10pp

7905020462 Forwards ambient sound level survey in response to recent J Lehr request for addl info re ETB
WARD, E C Northern States Power Co 79/04/27 2pp

7905010479 Forwards amend fee of \$4,400 for Licenses DPR-42 & DPR-60
* Northern States Power Co 79/05/01 1p

7905140214 Submits Environ Event Rept 79-03 for 790424-0502 discharge canal gate structure under water, rendering control & monitoring of blowdown flow inoperable
WARD, E C Northern States Power Co 79/05/08 1p

D Inspection reports, IE Bulletins & correspondence

7905010262 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23 1p

7905040048 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26 1p

7905090126 Forwards IE Insp Repts 50-282/79-06 & 50-306/79-06 on 790227-28 & 0301-02
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/03/26 2pp

--7905090131 IE Insp Repts 50-282/79-06 & 50-306/79-06 on 790227-28 & 0301-02 No noncompliance noted Major areas inspected emergency plan, emergency facilities, equipment & supplies, radioactive effluent sys & emergency training
OESTHANN, M. J., EBBIG, T H Region 3, Chicago, Office of the Director 79/03/20 6pp

7905010174 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Evc Air Sys Used as Source of Breathing Air"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/28 1p

7905010410 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/30 1p

7905070344 Responds to IE Bulletin 79-03 All longitudinal welds of ASTM-A31 stainless steel piping 100% radiographed & free of defects Addl testing unnecessary.
WACHTER, L J Northern States Power Co 79/04/10 1p

7905030040 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/11 1p.

7905010600 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified during TMI Incident." Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040405 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040451 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
KEPPLER, J O, Region 3, Chicago, Office of the Director 79/04/14 1p.

7905040576 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director, 79/04/14 1p.

7905030237 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required.
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/17 1p.

7905080905 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/21 1p.

7905140100 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/79-03 & 50-306/79-03
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/23 1p

--7905140104 Responds to NRC 790323 ltr re violations noted in IE Insp Repts 50-282/79-03 & 50-306/79-03 Corrective actions torque values were reduced & new bolts were retorqued to specified value
WACHTER, L J Northern States Power Co 79/04/10 2pp

DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

G. Inspection reports, IE Bulletins & correspondence

7905290290 Responds to IE Bulletin 79-09 GE Type AK-2 breakers not in use at unit
WACHTER, L J Northern States Power Co 79/05/04 1p

R Periodic operating reports & related correspondence

7905010509 Forwards monthly operating rept for Feb 1979
MAYER, L O Northern States Power Co 79/04/25 1p

--7905010511 Monthly operating rept for Feb 1979
HUNSTAD, A A Northern States Power Co 79/03/01 2pp

7905130496 Forwards monthly operating rept for Apr 1979
MAYER, L O Northern States Power Co 79/03/10 1p

--7905130499 Monthly operating rept for Apr 1979
HUNSTAD, A A Northern States Power Co 79/03/01 6pp

B Reportable occurrences, LERs & related correspondence

7905030364 Forwards LER 79-009/01T-0
MAYER, L O Northern States Power Co 79/04/26 1p

--7905030367 LER 79-009/01T-0 on 790412 notified by vendor that small break in pressurizer indicator Lp may hang up while Pp decreases, delaying safety injection Westinghouse recommends manually initiating safety injection implements
HUNSTAD, A A Northern States Power Co 79/04/26 1p

7905110127 Forwards LER 79-008/03L-0
MAYER, L O Northern States Power Co 79/03/08 1pp.

--7905110131 LER 79-008/03L-0 on 790408 safety injection pump 11 failed to start automatically, started in manual. Cause unknown Event could not be repeated Feasibility of monitor light to detect failures being studied
HUNSTAD, A A Northern States Power Co 79/03/08 1p

7905210279 Forwards LER 79-011/03L-0.
MAYER, L O. Northern States Power Co 79/03/16 1p

--7905210283 LER 79-011/03L-0 on 790416: transformer failed, leaving plant w/one source of offsite power Caused by switching error Transformer replaced prior to restart. Investigation continuing
RUETHER, J.C. Northern States Power Co. 79/03/16 1p

7905220114 Forwards LER 79-013/03L-0.
MAYER, L O. Northern States Power Co 79/03/17 1p

--7905220118 LER 79-013/03L-0 on 790417, during investigation of discrepant status light indication, diesel cooling water pump 22 engine was inadvertently tripped Caused by personnel error. Personnel to review event.
HUNSTAD, A A Northern States Power Co 79/03/17 1p

DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

F Security, medical, emergency & fire protection plans

7905300019 Details expansion of fire brigade size.
MOODY, D.E. Maine Yankee Atomic Power Co 79/03/24 1p.

DOCKETED ITEMS

G Adjudicatory correspondence

7905250044 Forwards Legislative Util Consumers' Council's petition to intervene
JUDD, H T New Hampshire, State of 79/04/02 2pp

--7905250046 Petition to intervene re 790313 order to show cause
JUDD, H T New Hampshire, State of 79/04/02 2pp

7905230792 Ack receipt of 790314 telegram questioning shutdown of facility Director of Nuclear Reactor Regulation will shortly be in position to reconsider whether continued suspension of operations remains necessary
HENDRIE, J M Commission 79/04/12 1p

--7905230803 Protests show cause order mandating shutdown of facility & requests reconsideration of order
THURLOW, E W Maine Yankee Atomic Power Co 79/03/14 1p

H General correspondence

7905070011 Responds to 790312 request Forwards 790302 submittal re transformer failure & statistical rept for Sept 1978
W/o encl
REID, R H Operating Reactors Branch 4 79/03/16 1p

7905010549 Urges NRC to put facility back on line
RENY, R H Maine Merchants Association, Inc 79/03/24 1p

7905240819 In response to 790329 ltr, forwards addl info re control rod tube wear Ongoing reviews of guide tube wear & asymmetric LOCA loads do not require plant shutdown at this time
REID, R H Operating Reactors Branch 4 79/04/19 3pp

7905300681 Reviews NRC actions taken to expedite returning plant to operation
HENDRIE, J M Commission 79/05/02 2pp.

-7905300686 Reviews untimely energy impact of NRC decision to close plant Urges expeditious review
COHEN, W S Senate, 79/03/26 2pp

Financial information

7905230528 Forwards statement of capital requirements & sources for CY79, in response to 780203 request
CRABTREE, R A Maine Yankee Atomic Power Co 79/03/16 2pp

Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 29, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 183, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCIPI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
Maine Atomic Energy Liability Underwriters, 79/05/01

7905030135 Ack receipt of 790402-03 submittals in response to 790313 order to show cause Forwards request for addl info
REID, R H Operating Reactors Branch 4 79/04/10 4pp.

7905070373 Notification of 790420 meeting w/util in Bethesda, MD to discuss studies done in support of SHOCK 1 computer code application
NELSON, C C Operating Reactors Branch 4 79/04/14 1p

7905270038 Responds to 790413 request re GA program Suggests revision number of YOGAP-1-A not be designated
HEIDER, L H Yankee Atomic Electric Co 79/04/24 1p

7905240367 Summary of 790420 meeting w/util & S&W in Bethesda, MD re use of PBSTRESS/SHOCK 1 computer code
NELSON, C C Operating Reactors Branch 4, 79/04/26 3pp

7905040615 Forwards status rept on 790427 "Plan for Verification of Dynamic Analysis Codes"
JACOBS, B B Stone & Webster Engineering Corp 79/04/27 2pp.

7905090330 Forwards addl info in response to NRC 790402 ltr re independent review of SHOCK 1 & 2 computer runs & C-E's dynamic seismic analysis of reactor coolant sys
GROCE, R H Maine Yankee Atomic Power Co 79/04/27 11pp

7905070548 Forwards Revision 6 & Amend 1 to Revision 6 of operational GA program, as requested in 790410 ltr
GROCE, R H Yankee Atomic Electric Co 79/04/30 4pp.

--7905070553 Informs that revisions to GA program are acceptable
HAASS, W P Quality Assurance Branch 79/04/10 17pp.

7905040514 Submits info requested at 790420 meeting on piping sys seismic review spectrum curves, piping designs & other points Demonstrates satisfactory requirements of 790313 order to show cause Supporting documentation encl
JOHNSON, W P Maine Yankee Atomic Power Co, 79/05/02, 31pp

7905080435 Informs that program will be initiated to update analysis for all safety-related piping sys, consisting of field verification of piping & reanalysis following method detailed in 790601 ltr
GROCE, R H Maine Yankee Atomic Power Co 79/05/02 1p

7905090061 Forwards comparison of pipe stress results from SHOCK O/SHOCK 1 & SHOCK O/NUPIPE-8W for identical piping geometries
GROCE, R H Maine Yankee Atomic Power Co 79/05/04, 85pp.

7905090372 Forwards "Summary of Design Margins & Criteria for ME Yankee Atomic Power Station" for piping sys seismic review
GROCE, R H Maine Yankee Atomic Power Co 79/05/05 1p

--7905090373 "Summary of Design Margins & Criteria for ME Yankee Atomic Power Station" for piping sys seismic review
Maine Yankee Atomic Power Co, 79/05/05 37pp.

7905090382 Forwards responses to NRC 790504 questionnaire re total loss of offsite power, reactor coolant sys leak, major loss of reactor coolant, steam line rupture & engineered safeguards
WOOD, E C Maine Yankee Atomic Power Co 79/05/07 69pp

7905140239 Forwards proprietary documents requested during 790501-04 special insp
ERLEWINE, J A Stone & Webster Engineering Corp 79/05/08 1p

--7905140243 Requests withholding Technical Guideline EMT0-22-0 & Technical Rept EMTR-612 (ref IOCFR2 790), Affidavit encl
KENNEDY, W J Stone & Webster Engineering Corp 79/05/04 10pp

7905140382 Confirms 790504 telcon w/WT Russell re computer deck associated w/SHOCK O program.
KENNEDY, W J Stone & Webster Engineering Corp, 79/05/09 1p.

7905150434 Details status of piping seismic review of SHOCK O program Program to calculate natural frequencies will be evaluated to determine effects on original stress analysis results
GROCE, R H Maine Yankee Atomic Power Co 79/05/10 1p.

7905230467 Forwards response to NRC 790508 request for info re analysis of main feedwater & pressure relief sys
WOOD, E C Maine Yankee Atomic Power Co, 79/05/10 3pp

7905160335 Notifies that review of computer deck is completed, SHOCK O program still unrecovered. Piping sys conservatively designed & will perform intended function.
KENNEDY, W J Stone & Webster Engineering Corp 79/05/11, 1p

DOCKETED ITEMS

97

- 7905190191 Forwards response to 790514 request for info re thermocouple leads mfg by Reuter-Stokes Canada Ltd
WOOD, E C Maine Yankee Atomic Power Co 79/05/14 2pp
- 7905210111 Forwards SHOCK I computer program listing Supersedes submittal of 790406 Program listing withheld (ref 10CFR2 790)
KENNEDY, W J Stone & Webster Engineering Corp 79/05/14 1p
- 7905220243 Submits info re containment isolation sys, purging sys & ECCS, in response to 790509 request
WOOD, E C Maine Yankee Atomic Power Co 79/05/14 4pp
- 7905220251 Submits info re pressurizer heaters, feedwater & steam generators, in response to 790510 request
WOOD, E C Maine Yankee Atomic Power Co 79/05/14 9pp
- 7905210130 Forwards Shock O/Shock I piping comparisons
GROCE, R H Maine Yankee Atomic Power Co 79/05/13 23pp
- 7905210161 Requests 790313 order to show cause be lifted
VANDENBURGH, D Maine Yankee Atomic Power Co 79/05/13 4pp
- 7905250159 Submits info restating position re adequacy of good title seismic design & piping Piping stresses within FSAR criteria & in many cases lower than previously calculated
JOHNSON, W P Maine Yankee Atomic Power Co 79/05/18 2pp
- 7905290335 Summarizes procedures & calculational techniques used in reanalysis of piping sys designed w/SHOCK II computer program Reanalysis will satisfy 790313 order to show cause
KENNEDY, W J Stone & Webster Engineering Corp 79/05/18 6pp
- 7905240656 Forwards Offsite Dose Calculation Manual
GROCE, P H Maine Yankee Atomic Power Co 79/05/21 1p
- 7905240659 Offsite Dose Calculation Manual
* Maine Yankee Atomic Power Co 79/05/14 43pp
- Q Inspection reports, IE Bulletins & correspondence
- 7905010119 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/23 1p
- 7905010050 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/8vc Air Sys Used as Source of Breathing Air."
GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/28 1p
- 7905030185 Responds to IE Bulletin 79-03 re design & fabrication of piping sys No action necessary by util.
MOODY, D E Maine Yankee Atomic Power Co. 79/03/28 1p
- 7905010301 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/30, 1p
- 7905020055 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/11, 1p
- 7905290134 Forwards IE Insp Rept 50-309/79-05 on 790404-06 No noncompliance noted.
CARLBOM, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/13 2pp
- 7905290137 IE Insp Rept 50-309/79-05 on 790404-06 No noncompliance noted Major areas inspected seismic design concerns, review of as-built drawings for affected sys & walking of affected lines for one sys.
FABANO, A M, TRIPP, L Region 1, Philadelphia, Office of the Director 79/04/12 5pp
- 7905020342 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping," Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/14, 1p.
- 7905040046 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident," Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/14, 1p.
- 7905040211 Forwards IE Bulletin 79-0B, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p
- 7905030075 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/17 1p
- 7905020278 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/18 1p
- 7905250456 Responds to IE Bulletin 79-07 re seismic analysis of safety-related piping Currently addressing bulletin under NRC order to show cause, dtd 790313
GROCE, R H Maine Yankee Atomic Power Co 79/04/24 1p
- 7905250355 Responds to IE Bulletin 79-06B re TMI errors Forwards info re review of operational errors & sys misalignments identified during TMI
VANDENBURGH, D E Maine Yankee Atomic Power Co 79/04/26 8pp
- 7905210157 Submits addl info to IE Bulletin 79-06B re TMI errors Will evaluate design change to isolate component cooling to reactor coolant pumps on spray signal
GROCE, R H Maine Yankee Atomic Power Co 79/05/14 1p
- R Periodic operating reports & related correspondence
- 7905190516 Forwards monthly operating rept for Apr 1979
MOODY, D E Maine Yankee Atomic Power Co 79/05/12 1p
- 7905190520 Monthly operating rept for Apr 1979
BJOGREN, R M Maine Yankee Atomic Power Co 79/05/12 5pp
- T Hearing transcripts on non-antitrust matters
- 7905290031 Transcript of 790503 briefing in Washington, DC Pp i-55
HENDRIE, J M, GILINSKY, V, KENNEDY, R T Commission 79/05/03 55pp
- DOCKET 50-311 BALEM NUCLEAR GENERATING STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 7905300594 Notifies that demonstration of integrity of channelheads must be undertaken through direct monitoring
To maintain review schedule, monitoring plan should be forwarded promptly
PARR, O D Light Water Reactors Branch 3 79/04/23 2pp
- 7905040519 Forwards response to request for addl info re rept on structural integrity containment test & valve data for 36-inch & 10-inch valves associated w/containment purge & pressure vacuum relief sys
MITTL, R L Public Service Electric & Gas Co of New Jersey 79/04/24 4pp
- 7905190482 Notifies that 790330 application for extension of facility completion date was not accompanied by amend fee Requested action falls into fee Class II Requests prompt submittal of fee
MILLER, W O License Fee Management Branch 79/04/26 1p
- 7905240226 Requests addl info to continue evaluating request for extension of const completion date
PARR, O D Light Water Reactors Branch 3 79/05/01 2pp
- 7905080481 Forwards supplemental test data re seismic qualification of 5kV switchgear relays, to satisfy request for addl info established by review team during 790226-29 site audit
MITTL, R L Public Service Electric & Gas Co of New Jersey 79/05/02 2pp
- 7905080483 "Protective Relay Seismic Data, HFA, IAC & IAV, Ref Documentation for NRC SGRT Review, Response Item 2"
* Public Service Electric & Gas Co of New Jersey 79/04/23 400pp
- 7905090308 Forwards updated listings of items, including preoperational tests which may not be completed until after initial fuel loading Requests deferral of incomplete test items
MITTL, R L Public Service Electric & Gas Co of New Jersey 79/05/04 6pp

DOCKETED ITEMS

7905220349 Responds to Westinghouse 790328 notification of potential single dropped rod events which could lead to DNB ratios lower than reported. Units are four loop plants & do not have potential problem
MITTL, R L Public Service Electric & Gas Co of New Jersey
79/05/15 2pp

7905250100 Submits addl info re NPSH available for RHR pump during accident recovery recirculation mode
MITTL, R L Public Service Electric & Gas Co of New Jersey
79/05/17 4pp

7905250415 Forwards excerpts from Hyle Labs seismic qualification test repts
MITTL, R L Public Service Electric & Gas Co of New Jersey
79/05/23 30pp

H General correspondence

7905070450 Act receipt of 790216 resolution opposing storage of high level radioactive wastes in township. Objections should be made at ASLD hearing. Expansion of storage pools is unlikely. No independent facilities are planned
DENTON, H R Office of Nuclear Reactor Regulation 79/03/29 5pp

7905140291 Responds to 790312 ltr re resolution adopted on 790216 by Township of Lower Alloways Creek, NJ. Resolution opposes storage of high level wastes. Forwards NRC response
OBSBICK, L V Office of the Executive Director for Operations
79/04/11 1p

I Financial information

7905070647 Forwards "Annual Financial Rept. 1978" for Public Svc Electric & Gas Co, Atlantic City Electric Co, Delmarva Power & Light Co & Philadelphia Electric Co
FRVLING, R Public Service Electric & Gas Co of New Jersey
79/04/30 162pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 209, 210, 212, 214, 215, & others
QUATTROCCHI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-23, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905250089 Forwards Endorsements 33, 34 & 35 to ANI Policy NF-230
CORREA, C Marsh & McLennan, K & M Nuclear Consultants, Inc Div
79/05/22 4pp

G Inspection reports, IE Bulletins & correspondence

7905010140 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/03/23 1p

7905300743 Forwards IE Insp Rept 30-311/79-17 on 790306-08. No noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/23 2pp

--7905300752 IE Insp Rept 30-311/79-17 on 790306-08. No noncompliance noted. Major areas inspected: startup test program, test procedure review & verification, plans for plant operational tests & plant tour
BETTENHAUSEN, L, FASANO, A N Region 1, Philadelphia, Office of the Director
CAPTON, D L Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/21 5pp

790529065 Responds to IE Bulletin 79-03. No safety-related pipe assemblies from Youngstown Welding & Engineering Co are used.
SCHNEIDER, F W Public Service Electric & Gas Co of New Jersey
79/04/04 2pp

7905020100 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/11 1p

7905020369 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040093 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040282 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905030101 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/17 1p

7905020322 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/18 1p

7905250072 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Provides results of Westinghouse analysis of reactor coolant loop & large bore Class I piping
SCHNEIDER, F W Public Service Electric & Gas Co of New Jersey
79/05/03 27pp

R Periodic operating reports & related correspondence

7905080462 Forwards Mar 1979 operating rept for industrial waste treatment plant
MIDURA, H J Public Service Electric & Gas Co of New Jersey
79/04/03 2pp

7905080466 Forwards Mar 1979 wastewater treatment rept for sewage treatment plant
MIDURA, H J Public Service Electric & Gas Co of New Jersey
79/04/12 2pp

7905080489 Forwards rept of subsurface water diversion & chloride analysis of well water for quarter ending 790331
MIDURA, H J Public Service Electric & Gas Co of New Jersey
79/04/16 3pp

7905080421 Forwards Natl Pollution Discharge Elimination Sys discharge monitoring rept for Mar 1979
MIDURA, H J Public Service Electric & Gas Co of New Jersey
79/04/20 13pp

7905300417 Forwards "Operating Rept for Apr 1979 for Industrial Wastes Treatment Plant"
MIDURA, H J Public Service Electric & Gas Co of New Jersey
79/05/08 1p

--7905300421 "Operating Rept for Apr 1979 for Industrial Wastes Treatment Plant"
MIDURA, H J Public Service Electric & Gas Co of New Jersey
79/04/30 1p

7905300431 Forwards Apr 1979 wastewater treatment rept for sewage treatment plant
MIDURA, H J Public Service Electric & Gas Co of New Jersey
79/05/10 2pp

7905300363 Forwards discharge monitoring repts for Apr 1979
MIDURA, H J Public Service Electric & Gas Co of New Jersey
79/05/22 13pp

7905290408 RD 79-43/01P on 790322, procedure to demonstrate operability of steam driven auxiliary feedwater pump 13 permitted closure of discharge control valves. Procedure changed to ensure operability
MIDURA, H J Public Service Electric & Gas Co of New Jersey
79/05/22 1p

DOCKETED ITEMS

99

DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

H General correspondence

7905070143 Requests NRC honor Governor Brown's request to shutdown Rancho Seco
STEINER, R Affiliation Unknown 79/04/02 1p

7905140045 Requests closing of plant; respondent & husband are starting family & are concerned about radiation & cancer risk
TAVERNIER, S W Affiliation Unknown 79/04/02 1p

7905020011 Recommends temporary shutdown of Rancho Seco until present uncertainties re TMI-2 incident are clarified
MATSUI, R T House of Rep 79/04/24 2pp

7905100364 Requests temporary shutdown of Rancho Seco in view of incident of TMI-2
BROWN, E O California, State of 79/04/24 1p

7905240444 Favors precautionary shutdown of facility, in light of TMI-2 incident.
MCCARTHY, L T California, State of 79/04/24 1p

7905150053 Notifies that if Rancho Seco is shut down, availability of power from addl sources is subj to transmission limitations & other factors unique in sys
SHACKELFORD, B Sacramento Municipal Utility District 79/04/26 2pp

7905020286 Expresses gratitude re concern for safety problems of nuclear power plants
KNOTT, M Affiliation Unknown 79/04/27 1p

J Insurance & indemnity information

7905070477 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHINI, J American Nuclear Insurers 79/05/01 1p

7905160243 Forwards Amend 6 to Indemnity Agreement B-66, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 3pp

7905290369 Forwards executed Amend 6 to Indemnity Agreement B-66
MATTIMOE, J J Sacramento Municipal Utility District 79/05/21 3pp

P. Operating license stage documents & correspondence

7905110114 Forwards safety evaluation re loss of nonsafety-grade instrument power supply causing reactor turbine trips on 780320
EISENHUT, D. Division of Operating Reactors 78/03/30 1p

--7905110117 Safety evaluation re loss of nonsafety-grade instrument supply causing 780320 reactor & turbine trips B&W & independent staff analyses conducted B&W considered appropriate regions of steam generators Findings acceptable
* Engineering Branch 78/03/20 4pp

7905110050 Comments on 780320 cooldown transient points out significant deficiency in present custom & STS for RCS heatup/cooldown rates & pressure-temp limits
STELLEG, V Division of Operating Reactors 78/04/07 1p.

7905110004 Forwards committee rept on 780320 transient resulting from loss of non-nuclear instrumentation V power supply
DUNN, J D. Sacramento Municipal Utility District. 78/06/19 11pp

7905110153 Informs of intention to return to full power operation on 780701, pending approval of small break LOCA analysis B&W concurs w/continued plant operation
MATTIMOE, J J Sacramento Municipal Utility District 78/06/19 1p

7905220035 Determines 790316 application involves single safety issue & is therefore categorized as Class III fee
MILLER, W O License Fee Management Branch 79/04/19 1p

7905300451 Requests addl info re ground motion input
DAVIS, J F. California, State of 79/04/24. 2pp

7905020306 Responds to IE Bulletin 79-05B Requests extension to reply date due to sys mods underway as described in 790427 ltr
Answers will be provided prior to startup following 790428 shutdown
MATTIMOE, J J Sacramento Municipal Utility District 79/04/27 1p

7905110307 Forwards procedural change approval forms for turbine trip, loss of steam generator feed, loss of reactor coolant flow & auxiliary feedwater sys
COLONBOD, R W Sacramento Municipal Utility District 79/05/04 37pp

7905190156 Forwards procedural changes re auxiliary feedwater sys, load rejection, condensate & feedwater sys & main feedwater pump sys
MATTIMOE, J J Sacramento Municipal Utility District 79/05/14 241pp

7905240710 Submits current status of 790427 proposed actions re feedwater sys & load rejection, in response to 790507 order
Supporting documentation encl
MATTIMOE, J J Sacramento Municipal Utility District 79/05/14 20pp

7905190134 Forwards revised radiological effluent Tech Specs which include requirements of NUREG-0472
MATTIMOE, J J Sacramento Municipal Utility District 79/05/15 1p

G Inspection reports, IE Bulletins & correspondence

7905110083 Forwards IE Insp Rept 50-312/78-03 on 780321-22, 28-31 & 0417
CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 78/04/21 2pp

--7905110086 IE Insp Rept 50-312/78-03 on 780321-22, 28-31 & 0417
No noncompliance noted Major areas inspected design change control, procurement, procedures, safety limits & limiting conditions for operations
CANTER, H L, WDESSNER, J D Region 5, San Francisco, Office of the Director
CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 78/04/21 12pp

7905010271 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
ENGELKEN, R H Region 4, Dallas, Office of the Director 79/03/23 1p

7905150533 Forwards IE Insp Rept 50-312/79-05 on 790226-0302, 13 & 15
No noncompliance noted
CREWS, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/03/23 2pp

--7905150539 IE Insp Rept 50-312/79-05 on 790226-0302, 13 & 15
No noncompliance noted Major areas inspected calibr, startup testing, maint, followup on LERS & IE bulletins
JOHNSTON, O W, JOHNSON, A D, FAULKENBERRY, B Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/03/23 6pp

7905010222 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathin Air"
ENGELKEN, R H Region 5, San Francisco, Office of the I

DOCKETED ITEMS

7905040622 Forwards IF Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident " ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 1p

7905070108 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 1p

7905030300 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/17 1p

7905080374 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl " Licensee action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/21 1p

7905220465 Responds to IE Bulletin 79-07 re seismic analysis computer codes No analysis methods specified in bulletin were used in computer codes Lists computer codes which have been used in seismic stress analysis MALBRIDGE, W C Sacramento Municipal Utility District 79/04/24 2pp

7905100293 Believes proposed Amend 63, dtd 790316, re inservice insp requirements is exempt from license fees, per 10CFR170.22 MATTIMOE, J J Sacramento Municipal Utility District 79/04/30 1p

R Periodic operating reports & related correspondence

7905100281 Forwards monthly operating rept for Apr 1979 RODRIGUEZ, R J Sacramento Municipal Utility District 79/05/03 1p

--7905100282 Monthly operating rept for Apr 1979 COLOMBO, R W Sacramento Municipal Utility District 79/04/30 6pp

S Reportable occurrences, LERs & related correspondence

7905110006 PNO-78-36 loss of instrument power supply, resulting in reactor & turbine trips on 780320 Excessive cooldown caused reactor coolant pressure to decrease WHITT, K H, NOLAN, F J, SNIEZEK, J H Office of Inspection & Enforcement 78/03/21 1p

7905110023 Discusses lead transfer on B&W instrumentation, in response to 780517 request Task definitions encl REID, R W Operating Reactors Branch 3 78/06/06 3pp

--7905110028 Transfer of lead responsibility re 780320 non-nuclear instrumentation power loss & overheating of primary cooling sys Discusses recommendations for generic aspects WOODRUFF, R W Office of Inspection & Enforcement 78/04/25 3pp

--7905110032 Forwards LER 78-001/01T-D MATTIMOE, J J Sacramento Municipal Utility District 78/03/31

7905030028 Forwards PNO-79-67U ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/14 1p

7905020535 Forwards PNO-79-67AA ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/20 1p

7905010437 Forwards PNO-79-67AB ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/21 1p

7905010430 Forwards PNO-79-67AC & AD ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/23 1p

7905110009 PNO-79-69 on 790422, coolant sys pressure on 790422 resulted in automatic reactor shutdown Caused by failure of A inverter power supply Unit returned to operation on 790423 BRYAN, S E, KLINGLER, O R Office of Inspection & Enforcement 79/04/23 3pp

7905010460 Forwards PNO-79-67AE ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/24 1p

7905090045 Forwards PNO-79-67AF ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/25 1p

7905090058 Forwards PNO-79-67AG ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/26 1p

7905090120 Forwards PNO-79-67AH ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/27 1p

7905070033 Forwards PNO-79-67AI, AJ & AK per NRC 790401 ltr transmitting IE Bulletin 79-05 ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/04/30 1p

7905070015 Forwards PNO-79-67AL per NRC 790401 ltr transmitting IE Bulletin 79-05 ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/01 1p

7905310050 Forwards PNO-79-67AM ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/07 1p

7905250434 Forwards LER 79-003/03L-0 MATTIMOE, J J Sacramento Municipal Utility District 79/05/21 2pp

--7905250437 LER 79-003/03L-0 on 790422 reactor trip occurred when B1A inverter failed. Caused by 150 amp, 125 volts DC inverter input breaker tripping when breaker undervoltage trip coil failed COLOMBO, R W Sacramento Municipal Utility District 79/05/21 1p

7905290004 LER 79-003/03L-0 on 790422 B1A vital power inverter failed twice within four months Caused by undersigned UV trip coil Resistor added to circuit COLOMBO, R W Sacramento Municipal Utility District 79/05/21 1p

7905300405 Forwards LER 79-004/03L-0, MATTIMOE, J J Sacramento Municipal Utility District 79/05/23 2pp

--7905300409 LER 79-004/03L-0 on 790425 test revealed that bypass valve did not fully close. Caused by maladjustment of mechanical interlock/linkage Linkage adjusted & tested satisfactorily COLOMBO, R W Sacramento Municipal Utility District 79/05/23 1p

DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1

F Security, medical, emergency & fire protection plans

7905100318 Requests change in implementation date for complete installation of 3-h rated fire dampers in ventilation ducts Proposes to install dampers by end of fourth refueling outage. RUETER, D A Arkansas Power & Light Co 79/03/13, 2pp

DOCKETED ITEMS

101

7905070300 Responds to 790309 plans for testing cable penetration fire stops installed in metal lath & plaster walls Proposed test acceptable
REID,R W Operating Reactors Branch 4 79/04/05 2pp

7905020231 Informs that fire protection mods required to be implemented during this refueling outage will be completed as scheduled
TRIMBLE,D C Arkansas Power & Light Co 79/04/24 1p

7905040008 Forwards second revision to fire protection plan
TRIMBLE,D C Arkansas Power & Light Co 79/04/30 1p

--7905040019 Revision 2 to fire protection plan
* Arkansas Power & Light Co 78/11/14 23pp

General correspondence

7905240955 Responds to 790412 ltr to JM Hendrie re nuclear power plant near Russellville,AR Outlines steps for license review
Forwards "Transportation of Nuclear Fuel & Waste" & "Disposal of Radioactive Waste" W/o encl
DEYOUNG,R C Division of Site Safety & Environmental Analysis 79/05/07 2pp

--7905240965 Expresses concern re nuclear plants at Russellville,AR Requests public investigation re safety of facility Forwards policy statement of Arkansas for Safe Energy
DERKY,J A Affiliation Unknown 79/04/12 2pp

Insurance & indemnity information

7905070477 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,183,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215, & others
QUATTROCHI,J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96
ROBERTS,D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905140489 Forwards Amend B to Indemnity Agreement B-65 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
BALTIMAN,J Antitrust & Indemnity Group 79/05/01 6pp

7905190167 Forwards executed Amend B to Indemnity Agreement B-65
TRIMBLE,D C Arkansas Power & Light Co 79/05/10 3pp

Operating license stage documents & correspondence

7905250076 Forwards Amend 41 to License DPR-51, safety evaluation & notice of issuance & availability
REID,R W Operating Reactors Branch 4 79/04/11 2pp.

--7905250079 Amend 41 to License DPR-51, revising Tech Specs for steam generator tube surveillance
REID,R W Operating Reactors Branch 4 79/04/11 8pp

--7905250085 Safety evaluation supporting Amend 41 to License DPR-51
* Office of Nuclear Reactor Regulation 79/04/11 4pp

--7905250090 Notice of issuance & availability of Amend 41 to License DPR-51.
REID,R W Operating Reactors Branch 4. 79/04/11 2pp

7905100294 Agrees to take requested action to resolve problems associated w/B&W plants Necessary adjustments will be made re emergency feedwater sys equipment, procedures & operator training.
PETTIT,A P Arkansas Power & Light Co 79/04/26 2pp

7905150215 Forwards revised response to Question 1 re proposed Tech Specs for Cycle 4 operation
TRIMBLE,D C Arkansas Power & Light Co 79/04/26 2pp

7905070483 Responds to 790425 ltr re safety concerns Proposes upgrading emergency feedwater sys & completing sufficient small break LOCA analyses to develop & implement necessary operator instructions in emergency procedures.
CAVANAUGH,W Arkansas Power & Light Co 79/05/03 5pp

7905250049 Forwards Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively, safety evaluation & notice of issuance & availability
STDLZ,J F Light Water Reactors Branch 1 REID,R W Operating Reactors Branch 4 79/05/03 2pp

--7905250055 Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively, modifying App A & B Tech Specs re mgt organization
REID,R W Operating Reactors Branch 4 79/05/03 14pp

--7905250058 Safety evaluation supporting Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively
* Operating Reactors Branch 4 79/05/03 2pp

--7905250065 Notice of issuance & availability of Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively
REID,R W Operating Reactors Branch 4 79/05/03 2pp

7905150389 Requests presence at 790606 annual review meeting in Little Rock, AR re environ monitoring programs
SHINDLE,D L Arkansas Power & Light Co 79/05/08 1p

7905110082 Resubmits 790503 ltr w/minor wording changes re timeliness & reliability of emergency feedwater sys & increased margins of safety
CAVANAUGH,W Arkansas Power & Light Co 79/05/09 5pp

7905140279 Supersedes 790509 ltr responding to NRC safety concerns expressed in 790425 status rept Proposed corrective actions design change for emergency feedwater sys & implementation of hard-wired control-grade reactor trip
CAVANAUGH,W Arkansas Power & Light Co 79/05/10 5pp

7905190033 Provides addl requested info on safety concerns Supersedes 790510 ltr
CAVANAUGH,W Arkansas Power & Light Co 79/05/11 5pp

7905230020 Provides addl info re mods being used to provide reactor trip upon loss of main feedwater &/or turbine trip, per 790509 meeting request
TRIMBLE,D C Arkansas Power & Light Co 79/05/11 8pp

7905220248 Discusses util 790103 ltr re commitment to perform flow test of long-term small break mod following design change Design mod completed & flow test performed to verify required 70/30 flow split
TRIMBLE,D C Arkansas Power & Light Co 79/05/14 1p

7905210266 Responds to questions from 790515 util/NRC meeting Describes measures taken to assure that anticipatory scram on turbine trip & loss of main feedwater will be reset during power escalation Discusses applicability of B&W repts
TRIMBLE,D C Arkansas Power & Light Co 79/05/16 7pp

7905240365 Provides update on progress made in implementing commitments contained in 790511 ltr re emergency feedwater pump
TRIMBLE,D C Arkansas Power & Light Co 79/05/17 3pp

7905240712 Responds to NRC 790515 questions re actuation of anticipatory reactor scram, procedural training & existing emergency feedwater pump capacities.
TRIMBLE,D C Arkansas Power & Light Co 79/05/17 3pp

7905290155 Updates 790511 ltr re emergency feedwater sy verification of sys & progress of post-TMI operator program
TRIMBLE,D C Arkansas Power & Light Co 79/05/21 3pp

7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970.
PORTER,F L EDS Nuclear, Inc 79/05/21 9pp

--7905300263 Forwards EDS Nuclear, Inc list of BHRs & piping sys which could have been impacted by deficient computer program QE has no record of reanalysis for Cooper piping sys.
STEPHENS,P W General Electric Co, Nuclear Energy Products Div. 79/01/24 18pp

7905300488 Forwards info requested by NRC at 790227 meeting re results of voltage calculations Info is provided to clarify analysis performed to justify existing configuration re safety buses.
TRIMBLE,D C Arkansas Power & Light Co. 79/05/21 11pp

DOCKETED ITEMS

7905300001 Updates 790511 ltr re commitments & comments on 790517 order Test on reactor conducted w/o unusual occurrence Other tests on feedwater conducted w/only two reportable failures
TRIMBLE, D C Arkansas Power & Light Co 79/05/22 5pp

7905310370 Plans to qualify retainer described in BAW-1496, "BRPA Retainer Design Rept." for three cycles of operation Some retainers will be reinserted at facility during next refueling
TAYLOR, J H Babcock & Wilcox Co 79/05/23 1p

G Inspection reports, IE Bulletins & correspondence

7905010385 Forwards IE Insp Repts 50-313/79-02 & 50-368/79-02 on 790115-0211 & notice of violation
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/03/01 2pp

--7905010391 Notice of violation from insp on 790115-0211
* Region 4, Dallas, Office of the Director 79/03/01 1p

--7905010395 IE Insp Repts 50-313/79-02 & 50-368/79-02 on 790115-0211 Noncompliance noted failure to prepare weekly rept of overdue maint
WESTERMAN, T F Region 4, Dallas, Reactor Operations Nuclear Support Branch
BOYTER, N C Region 4, Dallas, Office of the Director
MADSEN, O L Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/01 13pp

7905150079 Forwards IE Circular 79-04, "Loose Locking Nut on Limbtorque Valve Operators"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/16 1p

7905010448 Forwards IE Bulletin 78-128, "Atypical Weld Matl in Reactor Pressure Vessel Welds"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/19 1p

7905020441 Forwards IE Circular 79-05, "Moisture Leakage in Stranded Wire Conductors"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/20 1p

7905020277 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/23 1p

7905020419 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/26 1p

7905020436 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as the Source of Breathing Air"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/28 1p

7905140132 Forwards IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp." Licensee action required
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/30 1p

7905150045 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/30 1p

7905100394 Forwards response to IE Bulletin 79-03A items 1-4b & 5 re TMI-2 errors. Remaining responses will be forwarded on or before 790416
TRIMBLE, D C Arkansas Power & Light Co 79/04/11 12pp

7905040488 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 1p

7905040606 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 1p

7905070043 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 1p

7905030128 Forwards responses to Items 4c-d & 6-12 of IE Bulletin 79-03A, & suppl info to response to Item 5 in 790411 ltr re reactor bldg & penetration room cooling
TRIMBLE, D C Arkansas Power & Light Co 79/04/16 13pp

7905090096 Forwards suppl to IE Bulletin 79-03A, "Nuclear Incident at TMI"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/16 1p

7905030265 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/17 1p

7905080346 Forwards IE Bulletin 79-08B, "Nuclear Incident at TMI-Suppl"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/21 1p

7905290494 Responds to IE Bulletin 79-07 re seismic stress analysis Computer codes specified in Item 1 not used in analysis of safety-related piping
TRIMBLE, D C Arkansas Power & Light Co 79/04/24 App.

7905210264 Responds to IE Bulletin 79-03A, "Nuclear Incident at TMI-Suppl." Forwards Tech Spec change to provide for rapid placement in cold shutdown mode following gloss of emergency feedwater equipment.
CAVANAUGH, H Arkansas Power & Light Co 79/05/16 App

R. Periodic operating reports & related correspondence

7905070490 Forwards "Semiannual Environ Monitoring Rept" for Jul-Dec 1978
TRIMBLE, D C Arkansas Power & Light Co 79/04/30 1p

--7905070494 "Semiannual Environ Monitoring Rept" for Jul-Dec 1978
* Arkansas Power & Light Co 79/04/30 550pp

7905110066 Forwards impingement intake monitoring data for Mar 1979
TRIMBLE, D C Arkansas Power & Light Co 79/04/30 20pp

7905150460 Forwards Natl Pollution Discharge Elimination Sys rept for first quarter 1979
TRIMBLE, D C Arkansas Power & Light Co 79/05/04 10pp

7905170254 Forwards monthly operating rept for Apr 1979
TRIMBLE, D C Arkansas Power & Light Co 79/05/10 1p

--7905170259 Monthly operating rept for Apr 1979
SHIVELY, C N Arkansas Power & Light Co 79/05/09 5pp

B Reportable occurrences, LERs & related correspondence

7905090280 Responds to generic aspects of BECV-79-90, which assigned abnormal occurrence status to 780916 event re degraded engineered safety sys. All licensees have been notified of potential problems.
BENTON, H R Office of Nuclear Reactor Regulation 79/04/05 App

--7905090283 Concurs in staff request of abnormal occurrence determination for degraded engineered safety sys incident RT Kennedy requested identification of generic implications
CHILK, B J Office of the Secretary of the Commission 79/02/23 1p

--7905090286 Requests info by 790313 on generic matters identified in 780916 abnormal occurrence involving degraded engineered safety sys
STELLD, V. Division of Operating Reactors 79/02/27 1p

7905150117 Forwards PNO-79-67R & 79-77(NRR)
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/11 1p

7905040106 Forwards PNO-79-67B
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/12 1p

7905150174 Operating Experience Memo 14. Unusual sequence of events reported 780919 re degraded voltage resulting from onsite causes. One transformer disconnected, causing second to overload w/voltage drop on station distribution sys.
STELLD, V. Division of Operating Reactors 79/04/12 6pp

7905100233 Forwards PNO-79-67T correction
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/13 1p

7905010529 Forwards PNO-79-67U, V & W
MADSEN, O L Region 4, Dallas, Office of the Director 79/04/16
1p

7905010538 Forwards PNO-79-67X & Y
MADSEN, O L Region 4, Dallas, Office of the Director 79/04/18
1p

7905010534 Forwards PNO-79-67Z
MADSEN, O L Region 4, Dallas, Office of the Director 79/04/19
1p

7905010367 Forwards PNO-79-67AA, AB, AC & AD
MADSEN, O L Region 4, Dallas, Office of the Director 79/04/24
1p

7905030008 Forwards PNO-79-67AE
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/28 1p

7905100096 Forwards PNO-79-67AF, AG, AH, AI & AJ, re nuclear incident at
THI
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/30 1p

7905240451 Forwards PNO-79-67AK & AL
MADSEN, O L Region 4, Dallas, Fuel Facility & Materials Safety
Branch 79/05/02 1p

7905140290 Forwards LER 79-003/01T-0
TRIMBLE, D C Arkansas Power & Light Co 79/05/08 1p

--7905140263 LER 79-003/01T-0 on 790425 leak discovered in heat affected
zone of 1 inch drainline socket weld in B decay heat
discharge cross connect to a loop Caused by vibration
fatigue Outer drainline isolation valves replaced
SHIVELY, C N Arkansas Power & Light Co 79/05/08 4pp

7905290103 Forwards LER 79-004/03L-0
TRIMBLE, D C Arkansas Power & Light Co 79/05/22 2pp

--7905290109 LER 79-004/03L-0 on 790424 reactor bldg spray pump
unresponsive to engineered safeguards signal Caused by
incorrect Agastat time relay setting Relay adjusted
SHIVELY, C N Arkansas Power & Light Co 79/05/22 1p

DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1

H General correspondence

7905240602 Notification of termination of License BOP-3099 due to
resignation of employee, JM Randolph
NELSON, D D, SHALLER, D V Indiana & Michigan Power Co 79/05/09
1p.

I Financial Information

7905040056 Forwards Endorsements 2 & 3 to NELIA Binders EB-45 & 64,
Endorsements 31 & 32 to MAELU policy MF-79 & Endorsements 38
& 39 to ANI policy NF-206
DOLAN, J E Indiana & Michigan Power Co 79/04/26. 8pp

J Insurance & indemnity information

7905020401 Forwards Endorsements 2 & 3 to NELIA policies EB-45 & EB-64,
Endorsements 31 & 32 to MAELU policy MF-79 & Endorsements
38 & 39 to ANI policy NF-206
DOLAN, J E. Indiana & Michigan Power Co 79/04/26 8pp

7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 181, 161, 164, 170,
173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTRUCHHI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters. 79/05/01.
1p.

7905140481 Forwards Amend 9 to Indemnity Agreement B-61 per 10CFR140
changes, re increase in liability insurance from \$140 million
to \$160 million, effective 790501 Supporting documentation
encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp

7905290366 Forwards executed Amend 9 to Indemnity Agreement B-61
DOLAN, J E Indiana & Michigan Power Co 79/05/21 4pp

7905310440 Forwards indemnity fee for Unit 1 for 790526-800525 & fee
for Unit 2 for 770818-790817
DOLAN, J E Indiana & Michigan Power Co 79/05/21 3pp

P Operating license stage documents & correspondence

7905020490 Discusses 790318 telcon w/R Bero of Westinghouse re
incorrect weights for Valan Model C698 6-inch check valves
used in safety injection sys
SCHWENCER, A Operating Reactors Branch 1 79/04/02 1p

7905040611 Forwards operating history info re pressurizer power
operated relief valves in response to 790427 request
SHALLER, D V Indiana & Michigan Power Co 79/04/27 2pp

7905240100 Ack receipt of 790327 application proposing App A & B Tech
Spec changes Application requires two Class III fees & two
Class I fees Requests addl fee
MILLER, W D License Fee Management Branch 79/04/27 1p

7905110183 Advises of removal of Foxboro transmitters on pressurizer
pressure & steam generator steam flow applications, as
identified in 780601 ltr. Transmitters will be replaced
during current refueling outage, no later than Oct-Nov 1979
MALONEY, O P Indiana & Michigan Power Co 79/05/04 3pp

7905230504 Describes correspondence w/NRC re application for expansion
of spent fuel storage capacity to 2,030 fuel assemblies
Requests addl info re technical review of related public
health & safety matters
REIZEN, M B Michigan, State of 79/05/14 1p

7905290149 Forwards \$4,400 addl fee for 790327 proposed Tech Spec
changes
DOLAN, J E Indiana & Michigan Power Co 79/05/21 2pp

G. Inspection reports, IE Bulletins & correspondence

7905020202 Forwards IE Insp Repts 50-315/79-02 & 50-316/79-02 on
790102-05, 08-11, 15-19, 22-26, 29-31 & 0201-02, & notice of
violation Portions withheld (ref 10CFR2 790)
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear
Support Branch 79/03/02 3pp.

--7905020205 Notice of violation from insp on 790102-05, 8-11, 15-19, 22-26
29-31 & 0201-02
* Region 3, Chicago, Office of the Director 79/02/21. 1p.

--7905020208 IE Insp Repts 50-315/79-02 & 50-316/79-02 on 790102-05,
08-11, 15-19, 22-26, 29-31 & 0201-02. Noncompliance noted,
failure to rept safety injection event & failure to sample
at specified interval
BAKER, K. R., WARNICK, R. F. Region 3, Chicago, Office of the
Director. 79/02/21 11pp

7905010233 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping"
KEPPLER, J. O Region 3, Chicago, Office of the Director 79/03/23
1p

7905040037 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/03/26
1p.

7905010171 Forwards IE Info Notice 79-08, "Interconnection of
Contaminated Sys w/Bvc Air Sys Used as Source of Breathing
Air."
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/03/28.
1p.

7905150817 Forwards IE Insp Repts 50-315/79-03 & 50-316/79-03 on
790313-16 & notice of violation
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety
Branch 79/03/28. 2pp.

--7905150819 Notice of violation from insp on 790313-16
* Region 3, Chicago, Office of the Director 79/03/27. 1p.

DOCKETED ITEMS

- 7905150820 IE Insp Repts 50-315/79-03 & 50-316/79-03 on 790313-16
Noncompliance noted failure to conduct required emergency
plan drill
GREER, R J NRC Regional Offices ESSIO, T H Region 3,
Chicago, Office of the Director 79/03/27 App
- 7905010404 Forwards IE Info Notice 79-09, "Spill of Radioactively
Contaminated Resin"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/30
1p
- 7905030006 Forwards IE Bulletin 79-06, "Review of Operational Errors &
Sys Misalignments Identified During TH1 Incident " Licensee
action required
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/11
1p
- 7905010392 Forwards IE Bulletin 79-06A, "Review of Operational Errors &
Sys Misalignments Identified During TH1 Incident " Licensee
action required
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
1p
- 7905040456 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of
Safety-Related Piping " Licensee action required
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
1p
- 7905040522 Forwards IE Bulletin 79-08, "Events Relevant to Boiling
Water Power Reactors Identified During TH1 Incident "
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
1p
- 7905170089 Forwards IE Bulletin 79-06B, "Review of Operational Errors &
Sys Misalignments Identified During TH1 Incident " Licensee
action required
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
1p
- 7905030204 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2
Circuit Breaker in Safety-Related Sys " Licensee action
required
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/17
1p
- 7905080499 Forwards IE Bulletin 79-09B, "Nuclear Incident at
TH1-Suppl "
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/21
1p
- 7905030386 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of
Safety-Related Piping " Forwards description of computer
program used in design of safety-related piping
DOLAN, J E American Electric Power Co., Inc 79/04/24 Bpp
- 7905150152 Ack receipt of 790329 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-315/79-02 &
50-316/79-02
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear
Support Branch 79/04/25 1p
- 7905150156 Responds to NRC 790302 ltr re violations noted in IE Insp
Repts 50-315/79-02 & 50-316/79-02 Corrective actions
withheld (ref 10CFR2 790)
DISBROW, R E Indiana & Michigan Power Co 79/04/25 1p
- 7905150345 Forwards responses to IE Bulletin 79-06A, Revision 1.
Discusses major differences between Westinghouse & B&W
designs
DOLAN, J E Indiana & Michigan Power Co 79/05/01 25pp
- 7905250371 Addl response to IE Bulletin 79-07 Twenty-three piping
lines analyzed using absolute summation technique proved
capable of withstanding seismic event. Remaining piping sys
also proved capable.
BIEN, F N Indiana & Michigan Power Co. 79/05/04. 4pp
- 7905310466 Responds to 790505 ltr requesting extension of time to
respond to IE Bulletins 78-12, 78-12a & 78-12B Request
denied
KEPPLER, J G. Region 3, Chicago, Office of the Director. 79/05/04
2pp.
- 7905310469 Requests time extension to respond to IE Bulletins 78-12,
78-12a & 78-12B
DOLAN, J E Indiana & Michigan Power Co 79/05/03 2pp
- R. Periodic operating reports & related correspondence
- 7905070428 Forwards "Annual Environ Operating Rept 1978 "
DOLAN, J E. Indiana & Michigan Power Co 79/04/16 2pp.
- 7905070437 "Annual Environ Operating Rept 1978 "
* Indiana & Michigan Power Co 79/04/16 50opp
- 7905250352 Forwards revised page 15 to 1978 Annual Radiological Environ
Monitoring Rept, transmitted 790328 Ltr from contractor encl
SHALLER, D V Indiana & Michigan Power Co 79/04/26 3pp
- 7905170248 Forwards monthly operating rept for Apr 1979
SHALLER, D V Indiana & Michigan Power Co 79/05/11 1p.
- 7905170252 Monthly operating rept for Apr 1979
GILLET, W T Indiana & Michigan Power Co 79/05/03 7pp
- B Reportable occurrences, LERs & related correspondence
- 7905070398 Forwards LERs 79-026/03L-0 & 79-025/03L-0
SHALLER, D V Indiana & Michigan Power Co 79/05/02 1p
- 7905070604 LER 79-026/03L-0 on 790406 during normal operation, 69/4,
offsite ac electrical supply became inoperable Caused by
high winds during severe windstorm Damaged jumper replaced
& sys returned to operable status
CHADWELL, H M Indiana & Michigan Power Co 79/05/02 2pp
- 7905070613 LER 79-025/03L-0 on 790416 time response data not collected
during Apr 1976 refueling outage for low steam pressure
engineered safety feature channeled Caused by inadvertent
procedural omission Checklist will be used in future
BEILMAN, T P. Indiana & Michigan Power Co 79/05/02 1p
- 7905110120 Forwards LER 79-010/03X-1
SHALLER, D V Indiana & Michigan Power Co 79/05/07 1p
- 7905110124 LER 79-010/03X-1 on 790223 diesel essential svc water circ
valves 1-ESW-111 & 1-ESW-114 not functioning properly Caused
by excessive wear at split disc hinge points Discs replaced
BROWN, M S Indiana & Michigan Power Co 79/05/07. 1p
- 7905150423 Forwards LERs 79-019/03L-0, 79-027/03L-0 & 79-028/03L-0
SHALLER, D V Indiana & Michigan Power Co 79/05/09 1p
- 7905150430 LER 79-019/03L-0 on 790413 while performing hydraulic
snubber surveillance insp, snubbers QBD-8573 & QBD-8574 found
w/draind reservoirs Caused by loose pipe unions between
snubbers & remote reservoirs Snubbers replaced
BROWN, M S Indiana & Michigan Power Co 79/05/09 1p
- 7905150438 LER 79-027/03L-0 on 790416 during refueling w/emergency
diesel generator AB inoperable, 600 volt bus 11D made
inoperable by removal of normal feed breaker T1112 for
cleaning Caused by personnel error Operators retrained
LEASE, R S Indiana & Michigan Power Co 79/05/09 1p
- 7905150441 LER 79-028/03L-0 on 790410 torque required to open lower
condenser inlet door 3-R exceeded Tech Specs Caused by
sheet metal screws loose at bottom of door Door frame edge
depressed
BEILMAN, T P Indiana & Michigan Power Co 79/05/09 2pp
- 7905210135 Forwards LER 79-029/03L-0
SHALLER, D V Indiana & Michigan Power Co. 79/05/14 1p
- 7905210142 LER 79-029/03L-0 on 790414 cracks discovered in divider
barrier seal Caused by excessive compression of seal matl by
steel plates Work in progress to replace cracked sections
WIZNER, D Q Indiana & Michigan Power Co. 79/05/14 1p
- 7905220320 Forwards LERs 79-030/03L-0, 79-031/03L-0 & 79-032/03L-0
SHALLER, D V Indiana & Michigan Power Co 79/05/16 1p
- 7905220326 LER 79-030/03L-0 on 790417 while performing routine
surveillance test on AB diesel generator, load conservation
circuitry did not fully function as design Cause under
investigation
BEILMAN, T P Indiana & Michigan Power Co 79/05/16 1p
- 7905220333 LER 79-031/03L-0 on 790419 during routine channel calibr.
bistable trip value discovered nonconservative w/respect to
Tech Spec limits Caused by excess drift. Bistable will be
repaired
BEILMAN, T P. Indiana & Michigan Power Co 79/05/16. 1p
- 7905220339 LER 79-032/03L-0 on 790416 during routine channel calibr.
bistable FB-310B trip point was nonconservative w/respect
to Tech Spec limit. Caused by excess drift Bistable
recalibr
BEILMAN, T P Indiana & Michigan Power Co 79/05/16. 1p.

DOCKETED ITEMS

105

DOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2

H General correspondence

7903240602 Notification of termination of License 80P-3099 due to resignation of employee, JM Randolph
NELSON, D D , SHALLER, D V Indiana & Michigan Power Co 79/03/09 1p

I Financial information

7905040036 Forwards Endorsements 2 & 3 to NELIA Binders EB-45 & 64, Endorsements 31 & 32 to MAELU policy MF-79 & Endorsements 38 & 39 to ANI policy NF-206
DOLAN, J E Indiana & Michigan Power Co 79/04/26 8pp

J Insurance & indemnity information

7903020401 Forwards Endorsements 2 & 3 to NELIA policies EB-45 & EB-64, Endorsements 31 & 32 to MAELU policy MF-79 & Endorsements 38 & 39 to ANI policy NF-206
DOLAN, J E Indiana & Michigan Power Co 79/04/26 8pp

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHINI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905140481 Forwards Amend 9 to Indemnity Agreement B-61 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp

7905290366 Forwards executed Amend 9 to Indemnity Agreement B-61
DOLAN, J E Indiana & Michigan Power Co 79/05/21 4pp

7905310440 Forwards indemnity fee for Unit 1 for 790526-80Q525 & fee for Unit 2 for 790818-790817
DOLAN, J E Indiana & Michigan Power Co 79/05/21 3pp

P Operating license stage documents & correspondence

7905020490 Discusses 790315 telcon w/R Baro of Westinghouse re incorrect weights for Velan Model C658 6-inch check valves used in safety injection sys
BCHWENCER, A Operating Reactors Branch 1 79/04/02 1p

7905040611 Forwards operating history info re pressurizer power operated relief valves in response to 790427 request
SHALLER, D V Indiana & Michigan Power Co 79/04/27 2pp

7905240100 Ack receipt of 790327 application proposing App A & B Tech Spec changes Application requires two Class III fees & two Class I fees Requests addl fee
MILLER, W O License Fee Management Branch 79/04/27 1p

7905110183 Advises of removal of Foxboro transmitters on pressurizer pressure & steam generator steam flow applications, as identified in 780601 ltr Transmitters will be replaced during current refueling outage, no later than Oct-Nov 1979
MALONEY, O P Indiana & Michigan Power Co 79/05/04 3pp

7905230504 Describes correspondence w/NRC re application for expansion of spent fuel storage capacity to 2,050 fuel assemblies. Requests addl info re technical review of related public health & safety matters.
REIZEN, M B Michigan, State of 79/05/14 1p.

7905290149 Forwards \$4,400 addl fee for 790327 proposed Tech Spec changes
DOLAN, J E Indiana & Michigan Power Co 79/05/21 2pp

7905310367 Notifies of leaks discovered 790520 in main feedwater lines to steam generators 1 & 4, caused by stress concentration due to type of weld & preparation of feedwater line Will completely replace affected pipe section
SHALLER, D V Indiana & Michigan Power Co 79/05/26 2pp

Q. Inspection reports, IE Bulletins & correspondence

7905020202 Forwards IE Insp Repts 50-315/79-02 & 50-316/79-02 on 790102-05, 08-11, 15-19, 22-26, 29-31 & 0201-02, & notice of violation Portions withheld (ref 10CFR2.790).
HEIBHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/03/02. 3pp.

--7905020205 Notice of violation from insp on 790102-05, 8-11, 15-19, 22-26, 29-31 & 0201-02
* Region 3, Chicago, Office of the Director 79/02/21 1p

--7905020208 IE Insp Repts 50-315/79-02 & 50-316/79-02 on 790102-05, 08-11, 15-19, 22-26, 29-31 & 0201-02 Noncompliance noted failure to rept safety injection event & failure to sample at specified interval
BAKER, K R , WARNICK, R F Region 3, Chicago, Office of the Director 79/02/21 11pp

7905010233 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23 1p.

7905040037 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26 1p

7905010171 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/28 1p

7905150817 Forwards IE Insp Repts 50-315/79-03 & 50-316/79-03 on 790313-16 & notice of violation
DAVIES, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/03/28 2pp

--7905150819 Notice of violation from insp on 790313-16
* Region 3, Chicago, Office of the Director 79/03/27 1p

--7905150820 IE Insp Repts 50-315/79-03 & 50-316/79-03 on 790313-16 Noncompliance noted failure to conduct required emergency plan drill
GREER, R J NRC Regional Offices, ESBIO, T H Region 3, Chicago, Office of the Director 79/03/27 6pp

7905010404 Forwards IE Info Notice 79-07, "Spill of Radioactively Contaminated Resin"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/30 1p

7905030006 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/11 1p

7905010392 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified during TMI Incident" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040456 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p.

7905040522 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905170089 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905030204 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/17. 1p

7905080499 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/21 1p

7905300386 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Forwards description of computer program used in design of safety-related piping.
DOLAN, J E American Electric Power Co, Inc 79/04/24 8pp.

DOCKETED ITEMS

- 7905150152 Ack receipt of 790329 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/79-02 & 50-316/79-02
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/04/25 1p
- 7905150156 Responds to NRC 790302 ltr re violations noted in IE Insp Repts 50-313/79-02 & 50-316/79-02 Corrective actions withheld (ref 10CFR2 790)
DIBEROW, R E Indiana & Michigan Power Co 79/04/25 1p
- 7905150349 Forwards responses to IE Bulletin 79-06A, Revision 1 Discusses major differences between Westinghouse & B&W designs
DOLAN, J E Indiana & Michigan Power Co. 79/05/01 25pp
- 7905250371 Addl response to IE Bulletin 79-07 Twenty-three piping lines analyzed using absolute summation technique proved capable of withstanding seismic event Remaining piping sys also proved capable
BIEN, F N Indiana & Michigan Power Co 79/05/04 4pp
- 7905310466 Responds to 790505 ltr requesting extension of time to respond to IE Bulletins 78-12, 78-12a & 78-12B Request denied.
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/04 2pp
- 7905310469 Requests time extension to respond to IE Bulletins 78-12, 78-12a & 78-12B
DOLAN, J E Indiana & Michigan Power Co 79/05/05 2pp
- R Periodic operating reports & related correspondence
- 7905070428 Forwards "Annual Environ Operating Rept 1978"
DOLAN, J E Indiana & Michigan Power Co 79/04/16 2pp
- 7905070437 "Annual Environ Operating Rept 1978"
* Indiana & Michigan Power Co 79/04/16 50pp
- 7905250352 Forwards revised page 15 to 1978 Annual Radiological Environ Monitoring Rept, transmitted 790328 Ltr from contractor encl
SHALLER, D V Indiana & Michigan Power Co 79/04/26 3pp
- 7905170261 Forwards monthly operating rept for Apr 1979
SHALLER, D V Indiana & Michigan Power Co 79/05/11 1p
- 7905170262 Monthly operating rept for Apr 1979
GILLEY, W T Indiana & Michigan Power Co 79/05/03 12pp
- B Reportable occurrences, LERs & related correspondence
- 7905040001 Forwards LER 79-012/03L-0
SHALLER, D V Indiana & Michigan Power Co 79/04/27 1p
- 7905040002 LER 79-012/03L-0 on 790330 hydraulic control valves did not return to normal position placing hydraulic lock on operator cylinder Caused by dirt in hydraulic pilot valve. Hydraulic fluid replaced
BROWN, M B Indiana & Michigan Power Co 79/04/27 1p
- 7905070383 Forwards LERs 79-013/03L-0 & 79-014/03L-0
SHALLER, D V Indiana & Michigan Power Co 79/05/02 1p
- 7905070390 LER 79-013/03L-0 on 790407 during rapid shutdown, pressure was allowed to drop to 2,190 lb psig. Caused by spray valve which was slow to respond Spray placed in manual & throttled back
MURPHY, C E Indiana & Michigan Power Co 79/05/02 2pp
- 7905070396 LER 79-014/03L-0 on 790404 on two occasions rod position indication exceeded 12-step limit. Caused by drifting of signal conditioning modules, which were adjusted for proper output
RIECHLING, J L Indiana & Michigan Power Co 79/05/27 2pp
- 7905150488 Forwards LERs 79-013/03L-0 & 79-016/03L-0
SHALLER, D V Indiana & Michigan Power Co. 79/05/09 1p
- 7905150493 LER 79-015/03L-0 on 790409 during plant startup, small crack & pinhole leak found in body of FWD-232 at inlet side of valve adjacent to weld. Cause of crack not determined. Radiographs of area reviewed
WIZNER, D O Indiana & Michigan Power Co. 79/05/09 1p
- 7905180501 LER 79-016/03L-0 on 790412 failure of interlock, which prevents opening both containment 690 ft level airlock doors Caused by slack in actuator cables & weak spring One cable & spring replaced
WIZNER, D O Indiana & Michigan Power Co 79/05/09 1p
- 7905230325 Forwards LER 79-017/03L-0
SHALLER, D V Indiana & Michigan Power Co 79/05/16 1p
- 7905230330 LER 79-017/03L-0 on 790423 while performing STP 022, essential svc water-142, essential svc valve to 2 CD diesel did not seat properly Caused by excessive wear of split disc hinge points Stainless steel discs were substituted
BROWN, M B Indiana & Michigan Power Co 79/05/16 1p
- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATROCHINI, J American Nuclear Insurers 79/05/01 1p
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies KF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p
- 7905140499 Forwards Amend B to Indemnity Agreement B-70 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp
- 7905160325 Submits executed copy of Indemnity Agreement B-70, Amend B, in response to 790501 request
SHOENAKER, C L Baltimore Gas & Electric Co 79/05/09 3pp
- P Operating license stage documents & correspondence
- 7905080123 Forwards request for addl info re Cycle 4 reload, in response to submittal
REID, R W Operating Reactors Branch 4 79/04/13 5pp
- 7905250002 Forwards Amends 38 & 21 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability
REID, R W Operating Reactors Branch 4 79/04/24 4pp
- 7905250003 Amends 38 & 21 to Licenses DPR-53 & DPR-69, respectively limiting max boron concentration in safety injection & refueling water tanks & allowing reduced shutdown cooling flow when coolant sys is partially drained.
REID, R W Operating Reactors Branch 4 79/04/24 64pp
- 7905250005 Safety evaluation supporting Amends 38 & 21 to Licenses DPR-53 & DPR-69, respectively
* Office of Nuclear Reactor Regulation. 79/04/24 6pp
- 7905250007 Notice of issuance & availability of Amends 38 & 21 to Licenses DPR-53 & DPR-69, respectively
REID, R W Operating Reactors Branch 4. 79/04/24 3pp
- 7905090049 Forwards proprietary & nonproprietary versions of responses to Cycle 4 reload questions Proprietary version available in Central Files.
LUNDVALL, A E Baltimore Gas & Electric Co 79/05/07 5pp
- 7905090055 "Response to NRC Questions on Calvert Cliffs Unit 1, Cycle 4 Reload Submittal, App 1-NP," 790425, nonproprietary version
* Combustion Engineering, Inc. GEN 107-(B)-NP. 79/04/26 23p
- 7905220282 Submits nonroutine radiological environ operating rept on cystar samples, per ETS App B requirements.
STOUT, J W Baltimore Gas & Electric Co. 79/05/17 2pp.
- 7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of FIBOL piping analysis computer program from Jan-Oct 1969. Review & reanalysis included all work through Dec 1970.
PORTER, F L EDS Nuclear, Inc 79/05/21 9pp.

DOCKETED ITEMS

107

--7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program
OE has no record of reanalysis for Cooper piping sys
STEPHENS, P W General Electric Co ,Nuclear Energy Products Div
79/01/24. 18pp

G Inspection reports, IE Bulletins & correspondence

7905140208 Forwards IE Insp Rept 50-317/76-03 on 760315-19
No noncompliance noted
BRUNNER, E J Region 1, Philadelphia, Office of the Director
76/04/07 2pp

--7905140210 IE Insp Rept 50-317/76-03 on 790315-19 No noncompliance noted Major areas inspected minutes, facility change request & operating & event logs
KELLQOG, P J , DAVIS, A B Region 1, Philadelphia, Office of the Director.
76/04/07 2pp.

7905010101 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/03/23 1p

7905030270 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/03/26 1p

7905010036 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Bys w/Bvc Air Bys Used as Source of Breathing Air"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/03/28 1p

7905010286 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/03/30 1p

7905020030 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident." Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/11 1p

7905180372 Notifies that in-pool fuel insp will be performed between 790430-0502 Site visit can be handled under "Escorted Access to Controlled Area" requirements
REID, R W Operating Reactors Branch 4 79/04/13 2pp

7905020389 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/14. 1p.

7905030328 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident" Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/14. 1p

7905040174 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director.
79/04/14 1p

7905030056 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Bys." Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/17 1p

7905010433 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/18. 1p.

7905290712 Responds to IE Bulletin 79-06B re changes in operating procedures, preventative measures & briefing of personnel since TMI, Addl info re RCB will be completed by 790430
LUNDVALL, A E. Baltimore Gas & Electric Co. 79/04/26. 11pp.

7905300742 Responds to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp." Should analysis indicate piping or support overstress, supports will be modified to accomodate increased valve weights.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 79/04/30 5pp.

R Periodic operating reports & related correspondence

7905230356 Forwards monthly operating rept for Apr 1979
MERSON, B D Baltimore Gas & Electric Co 79/05/15 1p

--7905230358 Monthly operating rept for Apr 1979
MERSON, B D Baltimore Gas & Electric Co 79/05/15 16pp

S Reportable occurrences, LERs & related correspondence

7905100348 RO-50-317/75/58 on 751203 condensate storage tank supply valve to auxiliary feedwater pumps found shut, cutting off water supply Caused by valve mispositioning Valve opened
RUSSELL, L B Baltimore Gas & Electric Co 75/12/05 2pp

7905110118 Forwards Abnormal Occurrence 50-317/75/58 on 751203
LUNDVALL, A E Baltimore Gas & Electric Co 75/12/16 1p

--7905110122 AD-50-317/75/58 on 751203 discovered condensate storage tank supply valve to auxiliary feedwater pumps shut, leaving pumps w/o water supply Caused by administrative error Valve opened Licked valve deviation form will be used
RUSSELL, L B Baltimore Gas & Electric Co 75/12/16 3pp

7905010524 Forwards LER 79-011/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 79/04/26 1p

--7905010528 LER 79-011/03L-0 on 790411 during surveillance testing, auxiliary high pressure safety injection header isolation valve (SI-686) required 29-s to open Operating instructions revised to maintain SI-656 in open modes 1, 2 & 3
CARROLL, J T Baltimore Gas & Electric Co 79/04/26 2pp

7905080555 Forwards LER 79-013/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 79/05/02 1p

--7905080561 LER 79-013/03L-0 on 790417 while performing routine surveillance test, discovered hydrogen analyzer was inoperable Caused by failure of internal power supply transformer Transformer & two associated capacitors replaced
CANDOVA, M A , DAVIS, B M Baltimore Gas & Electric Co 79/05/02 1p

7905190080 Forwards LER 79-014/01T-0
RUSSELL, L B Baltimore Gas & Electric Co 79/05/14 1p

--7905190083 LER 79-014/01T-0 on 790503 only 89 spray nozzles are installed on containment spray header 12, FBAR mandates 90 nozzles Engineering evaluation of effect indicates as-built spray header exceeds design sys flow rate
MIERNICKI, M J , CARROLL, J T Baltimore Gas & Electric Co 79/05/14 1p

7905290426 Forwards LER 79-016/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 79/05/19 1p

--7905290430 LER 79-016/03L-0 on 790421 one of eight main steam safety valves tested found out of tolerance in conservative direction Caused by difference in ambient conditions between time when valve last reset & time of test
CARROLL, J T , MIERNICKI, J Baltimore Gas & Electric Co 2pp.

DOCKETED ITEMS

7905160323 Submits executed copy of Indemnity Agreement B-70, Amend B in response to 790501 request
SHOEMAKER, C L Baltimore Gas & Electric Co 79/03/09 3pp

P Operating license stage documents & correspondence

7905080123 Forwards request for addl info re Cycle 4 reload, in response to submittal
REID, R W Operating Reactors Branch 4 79/04/13 5pp

7905250002 Forwards Amends 38 & 21 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability
REID, R W Operating Reactors Branch 4 79/04/24 4pp

--7905250003 Amends 38 & 21 to Licenses DPR-53 & DPR-69, respectively, limiting max boron concentration in safety injection & refueling water tanks & allowing reduced shutdown cooling flow when coolant sys is partially drained
REID, R W Operating Reactors Branch 4 79/04/24 64pp

--7905250005 Safety evaluation supporting Amends 38 & 21 to Licenses DPR-53 & DPR-69, respectively
* Office of Nuclear Reactor Regulation 79/04/24 6pp

--7905250007 Notice of issuance & availability of Amends 38 & 21 to Licenses DPR-53 & DPR-69, respectively
REID, R W Operating Reactors Branch 4 79/04/24 3pp

7905220282 Submits nonroutine radiological environ operating rept on oyster samples, per ETS App B requirements
STOUT, J W Baltimore Gas & Electric Co 79/05/17 2pp

7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969
Review & reanalysis included all work through Dec 1970
PORTER, F L EDS Nuclear, Inc 79/05/21 9pp

--7905300263 Forwards EDS Nuclear, Inc list of BHRs & piping sys which could have been impacted by deficient computer program
GE has no record of reanalysis for Cooper piping sys
STEPHENS, P W General Electric Co, Nuclear Energy Products Div 79/01/24 18pp

Q Inspection reports, IE Bulletins & correspondence

7905010101 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/23 1p

7905030270 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/26 1p

7905010036 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Avc Air Sys Used as Source of Breathing Air"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/28 1p

7905010286 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/30 1p

7905020030 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/11 1p

7905020389 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905030328 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident," Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905040174 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905030056 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/17 1p

7905010633 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/18 1p

7905290712 Responds to IE Bulletin 79-06B re changes in operating procedures, preventative measures & briefing of personnel since TMI Addl info re RCB will be completed by 790430
LUNDVALL, A E Baltimore Gas & Electric Co 79/04/26 11pp

7905300742 Responds to IE Bulletin 79-04, "Incorrect Weights for Sales Check Valves Mfg by Velan Engineering Corp." Should analysis indicate piping or support overstress, supports will be modified to accommodate increased valve weights
LUNDVALL, A E Baltimore Gas & Electric Co 79/04/30 5pp

R Periodic operating reports & related correspondence

7905230356 Forwards monthly operating rept for Apr 1979
HERSON, S D Baltimore Gas & Electric Co 79/05/13 1p

--7905230358 Monthly operating rept for Apr 1979
HERSON, S D Baltimore Gas & Electric Co 79/05/15 16pp

S Reportable occurrences, LERs & related correspondence

7905080494 Forwards LER 79-002/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 79/05/02 1p

7905090342 LER 79-002/03L-0 on 79040B fused circuit within power supply (W PRODAC 250, PT16) for plant process computer failed. Caused by internal high current drain function was restored using lab power supply units
DAVIS, S H Baltimore Gas & Electric Co 79/05/02 1p

DOCKET 90-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7905300325 Forwards preliminary review of Section 6.2 of FSAR
Section not adequately complete to allow initiation of detailed technical review
HENDRIE, J M Atomic Energy Commission (Pre 1973). 74/02/25, 2pp

7905110374 Forwards milestone & activity list for TMI, status did 740814, for period ending 740907 Explains extension of fuel load rate & const schedule
GUNN, W T GPU Service Corp 74/09/06 4pp

7905110337 Forwards list of differences identified from review of logli & activity descriptions between Feb & Mar 1975 issues of "Yellow Book"
GUNN, W T GPU Service Corp. 75/04/07 4pp

7905110370 Forwards milestone & activity list for TMI, status did 750430, for period ending 750507
GUNN, W T GPU Service Corp 75/05/05 4pp

7905110367 Forwards milestone & activity list for TMI, status did 750930, for period ending 751007
GUNN, W T GPU Service Corp 75/10/03 3pp

7905110357 Forwards milestone & activity list for TMI, status did 751231, for period ending 760107
GUNN, W T GPU Service Corp 76/01/14 3pp

7905110354 Forwards milestone & activity list for TMI, status did 760229, for period ending 760307
GUNN, W T GPU Service Corp 76/03/03 3pp

7905110401 Forwards milestone & activity list for TMI, status did 760430, for period ending 760507
GUNN, W T GPU Service Corp. 76/05/06 2pp

7905110397 Forwards milestone & activity list for TMI, status did 760531, for period ending 760607
GUNN, W T GPU Service Corp 76/06/07 2pp

DOCKETED ITEMS

109

7905110333 Ack receipt of NRC 760624 ltr re const status rept "Yellow Book " Forwards summary of NRC "Yellow Book" activity dates as submitted by General Public Utilis
ARNOLD,R C Metropolitan Edison Co 76/06/24 2pp

7905110395 Forwards milestone & activity list for TMI,status dtd 760630,for period ending 760707
GUNN,W T GPU Service Corp 76/07/06 2pp

7905110392 Forwards milestone & activity list for TMI,status dtd 760731,for period ending 760807
GUNN,W T GPU Service Corp 76/08/06 2pp

7905110165 Forwards application for byproduct matl license
ARNOLD,R C Metropolitan Edison Co 76/10/19 1p

--7905110170 Application for matl/byproduct license by Metropolitan Edison Co for possession of any byproduct matl w/atomic numbers between 1 & 83,Cs-137,Am-241 & Pu-239
ARNOLD,R C Metropolitan Edison Co 76/10/19 12pp

7905110393 Forwards milestone & activity list for TMI,status dtd 761031,for period ending 761107
GUNN,W T GPU Service Corp 76/11/05 2pp

7905110406 Forwards milestone & activity list for TMI,status dtd 761130,for period ending 761207 Fuel load date extended because of budgetary restrictions
GUNN,W T GPU Service Corp 76/12/03 2pp

7905110403 Forwards milestone & activity list for TMI,status dtd 761231,for period ending 770107
GUNN,W T GPU Service Corp 77/01/06 2pp

7905110405 Forwards milestone & activity list for TMI,status dtd 770131,for period ending 770207
GUNN,W T GPU Service Corp 77/02/04 2pp

7905110402 Forwards milestone & activity list for TMI,status dtd 770228,for period ending 770307
GUNN,W T GPU Service Corp 77/03/04 2pp

7905110160 Requests addl info for processing 761019 application for byproduct matl license Forwards matl lab use guide
BELL,J M Radioisotopes Licensing Branch (Pre 790501) 77/03/25 3pp

--7905110162 Draft "Guide for Preparation of Applications for Lab Use of Small Quantities of Byproduct Matl "
* Radioisotopes Licensing Branch (Pre 790501) 78/12/31 21pp

7905110400 Forwards milestone & activity list for TMI,status dtd 770331,for period ending 770407,Most recent fuel load date delay rept by util should read Dec 1976
GUNN,W T GPU Service Corp 77/04/04 2pp

7905110176 Application for matl/byproduct license to authorize possession of any byproduct matl w/atomic numbers 1 through 83 inclusive
ARNOLD,R C Metropolitan Edison Co 77/04/18 51pp

7905110396 Forwards milestone & activity list for TMI,status dtd 770429,for period ending 770507
GUNN,W T GPU Service Corp 77/05/06 2pp

7905110389 Forwards milestone & activity list for TMI,status dtd 770531,for period ending 770607
GUNN,W T GPU Service Corp. 77/06/03. 2pp

7905110156 Addl info requested on 770325 by NRC re application for matl/byproduct license dtd 761019 has not been received. Info must be received within 30 days.
BELL,J M Radioisotopes Licensing Branch (Pre 790501) 77/06/16 1p

7905110149 Forwards addl info re byproduct matl license requested in NRC 770325 & 770610 ltrs
HERBEIN,J Q. Metropolitan Edison Co. 77/06/29. 75pp.

7905110385 Forwards milestone & activity list for TMI,status dtd 770630,for period ending 770707
GUNN,W T GPU Service Corp 77/07/05 2pp

7905110384 Forwards milestone & activity list for TMI,status dtd 770831,for period ending 770907
GUNN,W T GPU Service Corp 77/09/02 2pp.

7905110144 Matl/Byproduct License 37-17297-01 for Metropolitan Edison Co,authorizing possession of any byproduct matl w/atomic numbers between 1 & 84,Cs-137,Am-241 & Pu-239
WRIGHT,E Q Radioisotopes Licensing Branch (Pre 790501) 77/09/26 3pp

7905110382 Forwards milestone & activity list for TMI,status dtd 770930,for period ending 771007 Lists reasons for extension of fuel load date
GUNN,W T GPU Service Corp 77/10/07 2pp

7905110378 Forwards milestone & activity list for TMI,status dtd 771031,for period ending 771107
GUNN,W T GPU Service Corp 77/11/02 2pp

7905110376 Forwards milestone & activity list for TMI,status dtd 771130,for period ending 771207
GUNN,W T GPU Service Corp 77/12/09 2pp

7905110174 Requests addl info for processing matl/byproduct license application dtd 770418 W/o encl
WRIGHT,E Q Radioisotopes Licensing Branch (Pre 790501) 77/12/19 1p

7905110373 Forwards milestone & activity list for TMI,status dtd 771231,for period ending 780107
GUNN,W T GPU Service Corp 78/01/09 2pp

7905090131 Various update sheets for Blue Book from 720417-780203
* Commission 78/02/03 279pp

7905110368 Forwards milestone & activity list for TMI,status dtd 780131,for period ending 780207
GUNN,W T GPU Service Corp 78/02/09 2pp

E NRC Safety Evaluation Report (BER), supp's & correspondence

7905220432 Submits draft input to BER section re degradation to core meltdown
CUNNINGHAM,M Office of Nuclear Regulatory Research. 79/04/13 5pp

7905160091 Outline for BER
HATTSON,R J Division of Systems Safety 79/05/14 2pp

F. Security, medical, emergency & fire protection plans

7905220423 Notifies of fulfillment of util security packet request
SHEENY,M Division of Security 76/08/26 1p

7905160166 Forwards \$30.00 security clearance fee from Metropolitan Edison representative,LL Lawyer W/o encl
DOPP,R A Personnel Security Branch 76/11/01 1p

7905160190 Forwards \$30.00 security clearance fee from Metropolitan Edison representative,WM Creitz W/o encl
DOPP,R A Personnel Security Branch 76/11/19 1p

7905160174 Forwards requested fingerprint card Provides addl info re Form 1
CREITZ,W M Metropolitan Edison Co 76/11/24 1p

7905160161 Notification of "L" access authorization for I Edison representative,LL Lawyer
BRADY,R J Personnel Security Branch 77/01/18

7905220419 Requests three personnel security packets be Metropolitan Edison Co
DOPP,R A Division of Security 77/03/17 1p

7905160159 Notification of receipt of request for access packet from Metropolitan Edison employee,JA Haverling
HIMMELBRACH,L Personnel Security Branch. 77/05/1

7905160173 Forwards \$30.00 security clearance fee from M Edison representative,JA Haverling, W/o encl.
DOPP,R A Personnel Security Branch 77/05/17. 1p

7905160179 Notification of "L" access authorization for I Edison representative,WM Creitz
BRADY,R A. Personnel Security Branch. 77/08/08

7905160140 "Emergency Procedure 2202-2.1,Station Blackout version
* Metropolitan Edison Co. 77/12/30. 5pp

DOCKETED ITEMS

7905160171 Notification of "L" access authorization to Metropolitan Edison representative, JA Hvarling
BRADY, R A Personnel Security Branch 78/08/26 1p

7905160107 Notes re emergency planning & evacuation
* Commission 79/03/31 9pp

7905140046 Discusses emergency procedures for major sequence of events following loss of forced circulation of RCG
* Office of Nuclear Reactor Regulation 79/04/01. 23pp

7905220416 Forwards review of salient evacuation points from FSAR & PA Disaster Operations Plan
ONG, C Office of Policy Evaluations 79/04/01 19pp

7905220457 Discusses Emergency Procedure 5 re loss of shutdown w/reactor coolant pump running
TEDESCO, R. L Assistant Director for Plant Systems 79/04/07 4pp

7905090252 Discusses emergency preparedness needs in light of TMI incident Urges assignment of 11 persons to State Programs until end of fiscal year & eight permanent positions
RYAN, R G Office of State Programs 79/04/10 10pp

7905300076 Notifies State of MA that NRC has not received acceptable emergency plan Offers assistance in resolving problem
HENDRIE, J M Commission 79/05/09 2pp

7905300094 Notifies State of ME that NRC has not received acceptable emergency plan Offers assistance in resolving problem
HENDRIE, J M Commission 79/05/09 2pp

7905300101 Notifies State of QA that NRC has not received acceptable emergency plan Offers assistance in resolving problem
HENDRIE, J M Commission 79/05/09 2pp

7905300103 Notifies State of IL that NRC has not received acceptable emergency plan Offers assistance in resolving problem
HENDRIE, J M Commission 79/05/09. 2pp

7905300107 Notifies State of VA that NRC has not received acceptable emergency plan Offers assistance in resolving problem
HENDRIE, J M Commission 79/05/09 2pp

7905300115 Notifies State of NE that NRC has not received acceptable emergency plan Offers assistance in resolving problem
HENDRIE, J M Commission 79/05/09. 2pp

7905300119 Notifies State of CO that NRC has not received acceptable emergency plan Offers assistance in resolving problem
HENDRIE, J M Commission 79/05/09 2pp.

7905300120 Notifies State of MN that NRC has not received acceptable emergency plan Offers assistance in resolving problem
HENDRIE, J M Commission 79/05/09 2pp

7905300123 Notifies State of MD that NRC has not received acceptable emergency plan Offers assistance in resolving problem
HENDRIE, J M. Commission 79/05/09 2pp

7905300124 Notifies State of RI that NRC has not received acceptable emergency plan Offers assistance in resolving problem
HENDRIE, J M Commission 79/05/09 2pp

7905300126 Notifies State of NC that NRC has not received acceptable emergency plan Offers assistance in resolving problem
HENDRIE, J M Commission 79/05/09 2pp

7905300128 Notifies State of KY that NRC has not received acceptable emergency plan Offers assistance in resolving problem
HENDRIE, J M. Commission. 79/05/09 2pp

7905300131 Notifies State of WI that NRC has not received acceptable emergency plan Offers assistance in resolving problem
HENDRIE, J M Commission. 79/05/09 2pp.

7905300134 Notifies State of OH that NRC has not received acceptable emergency plan Offers assistance in resolving problem
HENDRIE, J M Commission 79/05/09 2pp

7905300139 Notifies State of ME that NRC has not received acceptable emergency plan Offers assistance in resolving problem
HENDRIE, J M Commission 79/05/09 2pp

7905300144 Notifies State of PA that emergency plan must be updated Requests cooperation during review
HENDRIE, J M Commission 79/05/09 2pp

7905160063 Comments on security assistance at TMI
ROBERTSON, L Division of Security 79/05/10 2pp.

7905300428 Comments on fire protection & security deficiencies at TMI
NOTLEY, D P Engineering Methodology Standards Branch 79/05/11 2pp

O Adjudicatory correspondence

7905090235 Response to stay motion by intervenors Draft order denying intervenors' motion but directing ASLAB to consider Rn-222 issue encl
KELLEY, J L Office of the General Counsel BECY-A-78-10 78/02/24 12pp

--7905090247 Opposition by util to 780209 request from joint intervenors Citizens for Safe Environ. & York Committee for Safe Environ for stay of initial decision Affidavit of MO Runts & Certificate of Svc encl
TROWBRIDGE, O F, BLAKE, E L Shaw, Pittman, Potts, & Trowbridge 78/02/21 15pp

7905220426 Forwards requested documents re Chairman Hendrie's participation in review of Board decision.
BLAQUIE, E L Office of the General Counsel. 78/02/24 1p

7905090246 Reviews ALAB-465, issued by ASLAB on 780327 No petitions for review have been filed decision does not warrant Commission review.
KELLEY, J L Office of the General Counsel BECY-A-78-34 78/04/21 3pp

--7905090249 Remands radon issue to ASLB w/directions to reopen issue for receipt of new evidence & for further hearings Partial dissent of WR Johnson encl
DUFLO, MM E Atomic Safety and Licensing Appeal Panel 78/03/27 8pp

7905090222 Informs Commission of ASLAB ALAB-474 decision on which no petitions for review have been filed & does not warrant review on its own merits.
KELLEY, J. L Office of the General Counsel BECY-A-78-47 78/04/11 3pp.

7905220434 Forwards 780606 memo re Chairman's participation in review of ALAB-474 on TMI
CHOPKO, M Office of the General Counsel. 78/06/06. 1p

--7905220436 Supplies background info re Chairman's participation in ALAB-474 on TMI Since Board decision does not deal w/ substantive issues, no conflict of interest is involved
CHOPKO, M Office of the General Counsel 78/06/06 1p

7905090226 Informs Commission of ASLAB decision ALAB-486 for which petition for review has been filed. Decision concerned emergency plans & risk of heavy aircraft crashing into plant.
EILPERIN, B F. Office of the General Counsel. BECY-A-78-68 78/09/06. 13pp Available at NRC. nrc.

7905090221 Provides info re Kepford v NRC, DC Circuit Number 78-1933 Plaintiff seeks judicial review of ALAB-480 insofar as decision affects TMI proceeding. Not likely to be sustained by courts
EILPERIN, B. F. Office of the General Counsel 78/10/24 2pp

--7905090225 Provides info re Kepford v NRC, DC Circuit Number 78-1933 Plaintiff seeks judicial review of ALAB-480 only insofar as decision affects TMI proceeding. Will keep informed.
EILPERIN, B. F. Office of the General Counsel. 78/10/24 1p

--7905090230 Provides info re Kepford v NRC, DC Circuit Number 78-1933 Plaintiff seeks judicial review of ALAB-480 only insofar as decision affects TMI proceeding. Will keep informed.
EILPERIN, B. F. Office of the General Counsel. 78/10/24 1p

--7905090232 Provides info re Kepford v NRC, DC Circuit Number 78-1933 Plaintiff seeks judicial review of ALAB-480 only insofar as decision affects TMI proceeding. Will keep informed.
EILPERIN, B F Office of the General Counsel 78/10/24. 1p

ceotable

abla

DOCKETED ITEMS

131

- 7903100406 Notifies that Dir. of Executive Legal Director will assist in developing response to 790329 petition by Environ Coalition on Nuclear Power
MURRAY, J.P. Rulemaking & Enforcement Division 79/04/04 3pp
- 7903160216 Forwards final evaluation of items discussed in 790228 memo re B&W-designed nuclear plants. Requests addl info be forwarded to licensing boards
MOBLEY, N.C. Division of Reactor Operations Inspections 79/03/28 10pp
- 7903100403 Petition to suspend O&E for all PWRs
LOCHTCT, W.A. Environmental Coalition on Nuclear Power 79/03/29 2pp
- 7903160163 Forwards Board Notification 79/10 on reactor inspector concerns re B&W plants Certificate of (v) encl
SCINTO, J.F. Hearings Division 79/07/29 14pp
- 7903160185 Board notification reactor inspector concerns re B&W plants
VABGALL, D.B. Assistant Director for Light Water Reactors 79/03/06 2pp
- 7903160201 Forwards two Howley to Thompson memos for Board notification info
THOMPSON, D. Office of I & E Executive Officer for Operations Support 79/03/29 1p
- 7903160207 Informs that preliminary evaluation of Item J contained in 790128 memo will be reviewed in light of TMI transient Addl info may cause change in previous assessment
MOBLEY, N.C. Division of Reactor Operations Inspections 79/03/29 1p
- 7903160050 Comments on delay in processing 790106 Board notification request
SCINTO, J.F. Hearings Division 79/01/10 2pp
- 7903010115 Forwards request for Board notification re nonsafety grade equipment to mitigate transients
SCINTO, J.F. Hearings Division 79/04/02 11pp
- 7903010156 Board notification staff assessment re nonsafety-grade equipment to mitigate transients
VABGALL, D.B. Assistant Director for Light Water Reactors 79/03/24 2pp
- 7903010170 Board notification recent issue on nonsafety grade equipment to mitigate transients. More info is required
YERGEN, R.I. Assistant Director for Reactor Safety 79/03/16 3pp
- 7903000077 Forwards draft order to assume & confirm direct NRC regulatory authority over emergency situation at TMI-2
GOSBICK, L.V. Office of the Executive Director for Operations 79/04/02 3pp
- 7903090215 Draft of order to assume & confirm direct NRC regulatory authority over emergency situation at TMI-2
CHICK, B.J. Office of the Secretary of the Commission 79/04/03 2pp
- 7903140166 Recommends postponing determination of extraordinary nuclear occurrence at TMI until end of accident & assessment of consequence. Price Anderson questions should be delayed
BICKNIT, L. Office of the General Counsel 79/04/03 1p
- 7903160033 Discusses effects of TMI on pending Branch IV hearings
OLMSTAD, W.J. Branch 4 79/04/01 2pp
- 7903160039 Discusses effects of TMI on hearing schedules; lists proceedings scheduled from Apr through June forwards questions to be answered at 790404 hearing
REIB, E.J. Branch 3 79/04/03 2pp
- 7903160045 Lists questions to be answered at 790404 hearing re liquid pathway generic study & FFU
WOLFE, B. Atomic Safety and Licensing Board Panel 79/03/29 2pp
- 7903160112 Board notification nuclear incident at TMI Recommends boards on cases involving B&W reactors be provided w/IE Bulletin 79-05 & PNO-67 & 67A.N.C.D.E.P.O & H
VABGALL, D.B. Assistant Director for Light Water Reactors 79/04/03 2pp
- 7903160227 Reviews impact of TMI on upcoming hearings; lists hearings scheduled for Apr & May
CUNNINGHAM, O.H. Branch 2 79/04/03 2pp
- 7903090218 Details major issues & possible approaches re legal aspects of NRC inquiry into TMI incident.
STOIBER, C. Office of the General Counsel 79/04/04 4pp
- 7903160191 Reviews delay in processing requests for Board notifications Provides general background & outline of facts re 790306 notice
SCINTO, J.F. Hearings Division 79/04/05 6pp
- 7903160208 Forwards latest motion to reopen safety hearings by T Dattilo on behalf of Save the Valley - Save Marble Hill. Forwards revisions to draft motions attached to 790402 memo
MURRAY, J.P. Rulemaking & Enforcement Division 79/04/05 2pp
- 7903160212 Motion to suspend & revoke CP for proposed facility because of TMI incident
DATTILO, T.M. Metford & Dattilo 79/04/04 2pp
- 7903090223 Suggests appropriate response to Hart testimony re closed plants due to auxiliary feedwater pumps
STOIBER, C.R. Office of the General Counsel 79/04/09 1p
- 7903160086 Discusses legal authority to shut down Rancho Boco sister plants due to TMI incident
DIXON, P.D. Office of the General Counsel 79/04/10 6pp
- 7903110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Bvc encl.
SCINTO, J.F. Hearings Division BORDLNICK, B.M. Branch 4 LITTO, B.H. Branch 2 79/04/11 45pp
- 7903140519 Response to 790404 brief of Philadelphia Electric Co. Public Bvc Electric & Gas, & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Bvc encl
KLEPFORD, C.P. Citizens for Safe Environment 79/04/11 0pp
- 7903090213 Forwards list of actions underway re TMI-2
GHAFAR, H.K. Office of the Executive Legal Director 79/04/13 2pp
- 7903140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition
DUFFLO, M.I. Atomic Safety and Licensing Appeal Panel 79/04/25 13pp
- 7903020274 Lists complaints filed against several utils & companies associated w/TMI. Formal complaint encl
HARRISON, J. American Nuclear Insurers 79/04/27 10pp
- 7903150342 Postpones 790404 evidentiary hearing re aircraft crash probability issue Assessment of situation will be made by 791001
DUFFLO, M.E. Atomic Safety and Licensing Appeal Panel 79/05/02 2pp
- 7903080370 Forwards class action complaint CA 79-520, filed in US District Court, Middle District of PA, brought against utils associated w/TMI.
CARRIER, W.C. American Nuclear Insurers 79/03/04 14pp
- 7903220352 Forwards class action complaint Smith vs B&W, 79Civ2235, US District Court for Southern District of NY
CARRIER, W.C. American Nuclear Insurers. 79/03/15 11pp
- 7903290285 Forwards class action complaint re TMI accident filed against utils & vendors in C Robert Larson, et al, vs Metropolitan Edison Co, et al
CARRIER, W.C. American Nuclear Insurers 79/03/22 9pp
- H. General correspondence
- 7903160024 Forwards security packages to be completed by designated employees for access to certain technical repts. W/o encl
DOPP, R.A. Division of Security. 76/08/25 1p
- 7903160026 Forwards extra security packets & fingerprint cards W/o encl
DOPP, R.A. Division of Security 76/09/09 1p
- 7903070136 Requests immediate closing of nuclear power plants
SCINLER, U. Affiliation Unknown 79/03/27 1p.

DOCKETED ITEMS

- 790516003B Requests rough estimate of probability of TMI accident computed on basis of methodology used in reactor safety study
BRADFORD, P A Commission 79/03/29 1p
- 7905040277 Public comments on TMI incident. 790330-0409
* Affiliation Unknown 79/03/30 60pp
- 7905040285 Insists util has placed corporate interests far above concern for public welfare Util presence in area is no longer desired Suggests evacuation
MYERS, J A Cumberland County, PA 79/04/03 2pp
- 7905040297 Urges stationing of permanent onsite federal inspectors at nuclear power plants in operation & under const in USA
GLICKMAN, D House of Rep 79/04/04 1p
- 7905110202 Confirms 790329 request for telephone log re TMI situation
HODGSON, A Commission 79/03/30 1p
- 7905110235 Confirms telcon w/E Fay requesting names of Congressmen who were informed of TMI situation & at what time
HODGSON, A Commission 79/03/30 1p
- 7905160097 Suggests naming outside individuals & NRC members to accident review board
AHEARNE, J F Commission 79/03/30 1p
- 7905300901 Requests complete investigation of TMI-2 incident Since Licensing Board is to make decision on Diablo Canyon, requests comparison of structural & operational designs for both plants
PANETTA, L E House of Rep 79/03/30 1p
- 7905300244 Expresses concern re discharge of hazardous matl from TMI-2 Requests notification of NRC activities & offers assistance
MATHIAS, C M Senate 79/03/31 4pp
- 7904170110 Requests registry of all facility employees for health monitoring Dosimeters or film badges should be issued to all personnel
CALIFANO, J A Health, Education & Welfare, Dept of 79/04/01 1p
- 7905160113 Notes from Commissioners' 790401 meeting re precautionary evacuation
THOMPSON, H L Commission 79/04/01 2pp
- 7905070143 Requests NRC honor Governor Brown's request to shutdown Rancho Seco
STEINER, R Affiliation Unknown 79/04/02 1p
- 7905160071 Schedule for 790404 meeting w/ACRS subcommittee, NRC & util representatives in Washington, DC to discuss chronology of TMI incident; current plant status; generic & health aspects
MCKINLEY, J C ACRS - Advisory Committee on Reactor Safeguards 79/04/02 1p
- 7905160072 Suggests no more CRs or QLEs should be issued until TMI events have been analyzed
BRADFORD, P A Commission 79/04/02 1p
- 7905160077 Press concerns from H Denton's 790402 press conference on TMI conditions
CAMPBELL, M Commission 79/04/03 1p
- 7905160154 Tape of H Denton's press conference should arrive 3 PM on 790402. Expects PNO completion same day
QIBBON, T Commission 79/04/02 1p
- 7905140188 Discusses NRC response to Congressman Preyer 790402 ltr. All possible meetings will be open to public Transcripts of closed meetings will be released w/o proprietary info
BICKWIT, L Office of the General Counsel 79/04/03 1p
- 7905160015 Summary of telcon w/S Cubie re decommissioning costs for TMI
CALKINS, O D Fuel Process Systems Standards Branch 79/04/03. 1p.
- 7905160031 Describes telcon between J Calkin of NRC & J Cubie of Kennedy subcommittee re cost of decommissioning TMI
KENT, B Commission. 79/04/03. 1p
- 7905160081 Outlines action plan for developing regulatory options on sister B&W operating reactors.
* Commission. 79/04/03 2pp.
- 7905160084 Comments on areas which will be covered by NRC review & suggests a blue ribbon panel be established
AHEARNE, J F Commission 79/04/03 2pp
- 7905170270 Discusses NRC in-house review plans re TMI incident Suggests president establish blue ribbon panel to study technical issues
HENDRIE, J H Commission 79/04/03 2pp
- 7905160111 Forwards Chapter 9, "Reactor Coolant Sys" & Chapter 6, "Contingency Safety Features" from FBAR
WEISSBERG, S Office of State Programs 79/04/04 1p
- 7905160126 Forwards IE Bulletin 79-05 & PNOs on TMI through 790404 w/o encl.
WEISSBERG, S Office of State Programs 79/04/04 1p
- 7905100201 Requests info re Kr-85, levels of gamma radiation at nuclear facilities & instrument failures as they relate to TMI incident
BRINKER, W F Affiliation Unknown 79/04/05 4pp
- 7905110291 Expresses thanks for assistance re issue of oxygen source & sinks within sys
BUDNITZ, R J Office of Nuclear Regulatory Research 79/04/05 1p
- 7905110293 Expresses thanks for suggestions re hydrogen overpressure during incident
BUDNITZ, R J Office of Nuclear Regulatory Research 79/04/05 1p
- 7905110299 Expresses thanks for suggestions re assistance during TMI incident
BUDNITZ, R J Office of Nuclear Regulatory Research 79/04/05 1p
- 7905110301 Expresses thanks for assistance re hydrogen bubble problem during incident
BUDNITZ, R J Office of Nuclear Regulatory Research 79/04/05 1p
- 7905110302 Expresses thanks for assistance during TMI incident
BUDNITZ, R J Office of Nuclear Regulatory Research 79/04/05 1p
- 7905160073 Recommends formation of accident review commission Requests meeting
AHEARNE, J Commission 79/04/05 1p
- 7905160452 Expresses thanks for assistance during TMI incident
BUDNITZ, R J Office of Nuclear Regulatory Research 79/04/05 1p
- 7905160006 Forwards FBI communications re TMI incident w/o encl
BRADY, R J Division of Security 79/04/06 1p
- 7905160104 Forwards background questions & answers re reactor decontamination & decommissioning to support meeting between Hendrie & Senator Hart
STEYER, K O. Office of Standards Development 79/04/06 12pp
- 7905160125 Draft chronology of contacts between Commissioners, NRC staff & Governor of PA re TMI accident 790330-31.
QIBBON, T R Commission 79/04/06 2pp
- 7905300302 Forwards draft ltr to Secretary Schlesinger expressing appreciation for support provided by DOE re TMI incident & requesting continued support
OGBURN, L V Office of the Executive Director for Operations 79/04/06 4pp
- 7905100012 Ack receipt of 790402 ltr re TMI incident Complete response will be forwarded as soon as possible Forwards NRC press releases & preliminary notifications re incident
KAMMERER, C. Office of Congressional Affairs. 79/04/09 1p
- 7905100013 Requests info re hypothetical radiation dispersion pattern resulting from possible explosion &/or meltdown at TMI
WEISS, T, RANGEL, C House of Rep. 79/04/02 3pp
- 7905100040 Forwards 790401 ltr from T Franz expressing concern re aircraft flight paths over TMI during incident
NETGENBAUM, H M. Senate. 79/04/09. 4pp.
- 7905100212 Ack receipt of 790330 ltr re TMI incident. Complete response will be forwarded as soon as possible. Forwards NRC press releases & preliminary notifications re incident.
KAMMERER, C Office of Congressional Affairs. 79/04/09 3pp

DOCKETED ITEMS

113

7905160025 Forwards backup questions & answers to use in preparation for hearing on TMI before Senate Subcommittee on Nuclear Regulation
KAMMERER,C Office of Congressional Affairs 79/04/09 1p

--7905160027 Backup questions & answers to use in preparation for hearing on TMI before Senate Subcommittee on Nuclear Regulation
KAMMERER,C Office of Congressional Affairs 79/04/09 38pp

7905160076 Advises that JM Hendrie thinks it unnecessary to establish position on issuing licenses prior to hearing
OIBDON,T Commission 79/04/09 1p

7905160096 Discusses assessment of radiological doses from TMI accident by ad hoc group
PETERSON,H T Office of Standards Development 79/04/09 8pp

7905160110 Notification of time change for 790410 hearing HR Denton will not attend
OIBDON,T Commission 79/04/09 1p.

7905160134 Forwards proposed addition to JM Hendrie's TMI testimony before Senator Hart re evacuation plans
BRADFORD,P A Commission 79/04/09 2pp

7905300307 Forwards "Preliminary Description of Events at TMI-2 Facility Accident" & "Generic Considerations of TMI-2 Incident" as background info for 790410 Senate hearing
KAMMERER,C Office of Congressional Affairs 79/04/09 18pp

7905100061 In response to 790330 ltr re safety of nuclear power plants in CT in light of TMI, forwards JM Hendrie's testimony before Senate Subcommittee on Nuclear Regulation W/o encl
KAMMERER,C Office of Congressional Affairs 79/04/10 2pp

--7905100075 Requests info re TMI mechanical malfunctions & possibility of similar occurrences at CT nuclear plants
DODD,C J. House of Rep 79/03/30 1p

7905160040 Forwards congressional ltrs which NRC has answered w/interim responses, but containing questions which require further response Lists priorities W/o encl
KAMMERER,C Office of Congressional Affairs 79/04/10 1p.

7905160041 Comments on informing Congress about TMI situation
KAMMERER,C Office of Congressional Affairs 79/04/10 2pp

7905160137 Requests that TMI info be sent to J Dewick, MA Secretary for Environ Affairs
AHEARNE,J F Commission 79/04/10 1p

7905160051 List of individuals chosen to comprise Presidential Commission to investigate TMI
KAMMERER,C Office of Congressional Affairs 79/04/11 2pp

7905160254 Responds to suggestions to help improve conditions at facility Suggestions considered & appreciated
DENTON,H R Office of Nuclear Reactor Regulation 79/04/11 59pp

7905100181 Ack receipt of 790410 ltr forwarding correspondence from KL Pennabaker re TMI Response will be forwarded as soon as possible.
KAMMERER,C Office of Congressional Affairs 79/04/12 2pp

7905140196 Responds to 790412 memo re actions on TMI Lists contact persons in Ofc of Administration for FOIA request processing
FELTON,J M Division of Rules and Records. 79/04/12 3pp

7905160047 Comments on conversation w/H Myers, special consultant to House Subcommittee on Energy & Environ. re transcript of Commission closed meeting on TMI.
KENT,B. Office of Congressional Affairs. 79/04/12 1p

7905110253 Requests statement of basis for providing transcripts of closed TMI meetings to Congress on 790412
GILINSKY,V Commission. 79/04/13 1p

7905110285 Requests lists by 790420 of all TMI work
LEVINE,S Office of Nuclear Regulatory Research 79/04/13. 1p

7905210263 Summary of questions raised on inservice insp at TMI during current shutdown. Results of weld testing performed by Nuclear Energy Svcs were questioned by util re credibility
* Office of Nuclear Reactor Regulation 79/04/13. 3pp

7905110246 Recommends editorial review procedure for TMI transcripts
GILINSKY,V Commission 79/04/14. 1p.

7905110249 Describes status of TMI transcripts Records of 790330-31 & 0401-03 are in PDR Transcripts of 790406, 09, 10 & 13 will be available to Commissioners by 790417
HODGSON,A Commission 79/04/16 1p

7905160044 Forwards reconstruction by E Fay of circumstances surrounding transmittal of transcripts of closed Commission meetings on TMI
KAMMERER,C Office of Congressional Affairs 79/04/16 1p

--7905160046 Responds to request for chronology of events re release of transcripts of closed meetings of Commission during TMI emergency
FAY,E S Office of Congressional Affairs 79/04/16 4pp

7905160101 Submits chronological environmental monitoring info at TMI
BRADFORD,P A Commission 79/04/16 2pp

7905300175 Confirms 790405 telcon re willingness to attend any meeting re TMI Includes text of telex sent to General Public Utils re familiarity w/reverse osmosis & ion exchange
TILBE,H R London Nuclear Decontamination, Ltd 79/04/16 1p

7905110190 Expresses appreciation for contribution to NRC efforts at TMI
HENDRIE,J M Commission 79/04/17 1p

--7905110194 Expresses appreciation of DF Mossbury's work during TMI incident
DENTON,H R Office of Nuclear Reactor Regulation 79/04/13 1p

7905110308 Forwards LV Gossick 790419 memo directing NRC personnel to keep written record of actions pertaining to TMI Requests copies of all memos
BUDNITZ,R J Office of Nuclear Regulatory Research 79/04/17 1p

7905100206 Ack receipt of 790411 ltr re TMI incident Complete responses will be made as soon as possible Forwards D Eisenhower's Senate testimony summarizing significant events W/o encl
KAMMERER,C Office of Congressional Affairs 79/04/18 3pp

7905110198 Confirms understanding of 790416 meeting re coordination of NRC response to TMI incident Assigns K Cornell as focal point for info
GILINSKY,V Commission 79/04/18 1p

7905140020 Ack receipt of 790331 ltr Will consider suggestions in analyzing TMI incident
HENDRIE,J M Commission 79/04/18 1p

7905140171 Forwards transcripts released 790418 & preceding week More will be sent as they are released W/o encl
GILINSKY,V Commission 79/04/18 1p

7905140175 Forwards transcripts released 790418 & preceding week More will be sent as they are released W/o encl
GILINSKY,V Commission 79/04/18 1p

7905140178 Forwards transcripts released 790418 per V Gilinsky's directions W/o encl
BICKWIT,L Office of the General Counsel 78/04/18 1p

7905160023 Forwards proposed witness list for second Hart hearing on TMI
KAMMERER,CC Office of Congressional Affairs 79/04/18 2pp

7905230135 Lists addl personnel to be authorized for access to turbine bldg
STELLO,V Division of Operating Reactors 79/04/18 1p

7905020246 Believes nuclear power plants should be closed until emergency ctrs for times of crisis are available Wants no plants built pending improved safety assurances
WEBSTER,L Affiliation Unknown 79/04/19 1p

7905140258 Responds to 790418 invitation NRC representatives unable to attend European nuclear conference in Hamburg to discuss TMI
HENDRIE,J M. Commission 79/04/20 1p

--7905140260 Invites NRC representative to 790509 European nuclear conference in Hamburg re TMI.
BECKURTS,K.H European Nuclear Conference 79/04/18 1p

7905160146 Notification that OAD will conduct investigation of TMI incident
KAMMERER,C Office of Congressional Affairs 79/04/20. 1p

DOCKETED ITEMS

- 7905100338 Forwards update to partial response to Congressman Ertel & Goodling's 790209 ltr to JM Hendrie Update includes shutdown of TMI-2 from "dependable capability" provided by various Reliability Councils
YOUNGBLOOD, B J Cost Benefit Analysis Branch 79/04/23 3pp
- 7905160175 Suggests communication sys be upgraded to handle two events simultaneously, & maximize interface between incident response ctr & Commission during unusual events
KENNEDY, R T Commission 79/04/23 1p
- 7905230134 Requests addition of KE Plumlee & RF Fish to NRC Access List dtd 790413
MCOSCAR, J J Region I, Philadelphia, Office of the Director 79/04/23 3pp
- 7905230163 Request addition of RH Engellen to NRC Access List dtd 790413
MCOSCAR, J J Region I, Philadelphia, Office of the Director 79/04/23 1p
- 7905020011 Recommends temporary shutdown of Rancho Seco until present uncertainties re TMI-2 incident are clarified
HATBUL, R T House of Rep 79/04/24 2pp
- 7905020405 Requests NRC assistance for college survey re average citizen's feelings about nuclear power
MILLER, O Affiliation Unknown 79/04/24 2pp
- 7905100364 Requests temporary shutdown of Ranch Seco in view of incident of TMI-2
BROWN, E G California, State of 79/04/24 1p
- 7905020281 Believes that const waiting period should be enforced until nuclear cost & waste problems are solved Requests info re nuclear safety
MOORE, D Affiliation Unknown 79/04/25 1p
- 7905160021 Forwards 790412 ltr from AB Feldman to J Carter volunteering to work w/Presidential Commission on TMI accident
KAMMERER, C Office of Congressional Affairs 79/04/25 17pp
- 7905230165 Requests B Ebert be thanked for excellent job in preparing charts for briefings
VOLLMER, R H Assistant Director for Site Analysis 79/04/25 1p
- 7905300345 Discusses delay in appointing non-NRC individual to head TMI-2 investigation Suggests interim NRC coordinating staff
GININSKY, V Commission 79/04/25 1p
- 7905020123 Comments on TMI-2 NRC should order all operating B&W designed nuclear facilities shut down pending appropriate design corrections
WALKER, R S House of Rep 79/04/26 1p
- 7905020265 Expresses appreciation for way in which TMI incident was handled
PENNER, K L Affiliation Unknown 79/04/26 1p.
- 7905190053 Notifies that if Rancho Seco is shut down, availability of power from addl sources is subj to transmission limitations & other factors unique in sys
SHACKELFORD, B. Sacramento Municipal Utility District 79/04/26 2pp
- 7905150035 Favors thorough analysis before decision to shut down nine nuclear power plants
LIVINGSTON, R L Congress (Joint & Rotating Committees, etc) 79/04/26 1p
- 7905160152 Forwards 790420 ltr from Chairman Dingell to E Staats, Comptroller General of US, requesting GAO initiate comprehensive investigation of TMI incident
KAMMERER, C Office of Congressional Affairs 79/04/26 3pp
- 7905300112 Discusses methods of measurement for personnel radiation exposure, cause of radiation leaks & radiation levels prior to TMI incident Info submitted for review & update for Congressional input
* Office of Inspection & Enforcement 79/04/26 5pp
- 7905020447 Comments on current nuclear power plant problems in US and safety record at Canadian plants
SIMON, H R Affiliation Unknown 79/04/27 1p.
- 7905220414 Discusses bus transportation for 790504 Congressional visit
MCOSCAR, J J Region I, Philadelphia, Office of the Director 79/04/27 1p
- 7905020031 Public comments re incident at TMI & nuclear power in general
* Affiliation Unknown 79/05/01 103pp
- 7905140027 Responds to encl 790406 ltr documenting earlier suggestions concerning use of oxygen to reduce hydrogen bubbles Adding addl oxygen could have adversely affected plant safety
DENTON, H R Office of Nuclear Reactor Regulation 79/05/01 1p
- 7905140029 Suggests addition of oxygen to reduce hydrogen bubble
ANDERSON, L Affiliation Unknown 79/04/06 1p
- 7905140073 Forwards response to questions asked by Senator Harkin re NRC's FY80 authorization after TMI incident
HALLER, N M Office of Management and Program Analysis 79/05/01 11pp
- 7905160052 Advises that Joint Chiefs of Staff assigned nickname "I-2's Purpose" to operations in support of TMI incident
GOSBICK, L V Office of the Executive Director for Operations 79/05/10 1p
- 7905160087 Forwards antinuclear flyers
* Commission 79/05/10 6pp
- J Insurance & indemnity information
- 7905140486 Forwards Amend B to Indemnity Agreement B-64 per SN-ENR's changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501
encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp
- 7905220362 Returns unsigned Amend B to Indemnity Agreement B-64 Nuclear Liability Insurance Pools will not provide addl coverage
GERETY, H F GPU Service Corp 79/05/16 3pp
- G Advisory Committee on Reactor Safeguards reports & correspondence
- 7905140022 Submits summary of NRC 790329 briefing on TMI incident
LIBARKIN, M W ACRB - Advisory Committee on Reactor Safeguards 79/03/29 3pp
- 7905140021 Forwards portion of Bellefonte Subcommittee meeting transcript questioning whether operator could diagnose accident & assess core status
BENDER, M ACRB - Advisory Committee on Reactor Safeguards 79/04/05 13pp
- 7905300378 Discusses ACRB concerns re TMI-2 incident
* ACRB - Advisory Committee on Reactor Safeguards, 79/04/05 2pp
- 7905140011 Summary of 790410 hearing by Senate Subcommittee on Nuclear Regulation re TMI accident Investigation will last six months & rpt issued after one year
BESSETTE, D E ACRB - Advisory Committee on Reactor Safeguards 79/04/11 3pp
- 7905140026 Summary of ACRB 790409-14 site visit re plant status recovery plans & core assessment Forwards B&W 790410 rpt on natural circulation cooling
MCCKRELESS, T O ACRB - Advisory Committee on Reactor Safeguards 79/04/15 42pp
- 7905140028 "Summary of Natural Circulation Alternatives for Long Term Core Cooling at TMI-2."
KARRASCH, B A Babcock & Wilcox Co 79/04/10 33pp
- 7905110274 "Second Interim Rpt on Recent Incident at TMI." Draft rpt to be completed during 790510 meeting
* ACRB - Advisory Committee on Reactor Safeguards 79/04/11 1p
- 7905140012 Makes recommendations to NRC re TMI Recommends cessation of operator training, NRC weak in chemical expertise
SHEWMON, P O ACRB - Advisory Committee on Reactor Safeguards 79/04/18 2pp
- 7905300381 Forwards summary of highlights of special ACRB meeting re 790416-17 to discuss TMI incident.
CROCKER, L P Division of Project Management, 79/04/18 13pp
- 7905300391 Statement by vice president of Nuclear Power Generation to ACRB re B&W activities as result of TMI incident
Documentation encl
MACHILLAN, J H Babcock & Wilcox Co 79/04/16 30pp

DOCKETED ITEMS

115

- 7905300396 Details topics to be covered at special ACRS meeting on 790416 Topics include small breaks & transients in B&W plants in light of TMI incident
CROCKER, L P Division of Project Management 79/04/12 1p
- 7905040057 Responds to 790418 ltr ACRS 790417 recommendations are generic & apply to all PWRs Procedural changes should be made only after study of effect on overall safety
CARBON, M W ACRS - Advisory Committee on Reactor Safeguards 79/04/20 2pp
- 7905140013 Submits current preliminary chronology, package of operational charts & results of interviews w/operators & others re TMI incident
LIBARKIN, M W ACRS - Advisory Committee on Reactor Safeguards 79/04/25 49pp
- 7905140015 Forwards TE Hurley 790413 memo re research program changes resulting from TMI accident
MCSCRELESS, T ACRS - Advisory Committee on Reactor Safeguards 79/04/26 1p
- 7905140017 Details changes in safety research program as result of TMI incident
HURLEY, T E Division of Reactor Safety Research 79/04/13, 66pp
- 7905140014 Invitation for 790511 appearance before ACRS to discuss causes, lessons & corrective actions of TMI accident & whether to shut down other B&W reactors
FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards 79/04/27 1p
- 7905140154 Forwards 780413 memo re TMI core damage assessment, updating 790406 rept based on early data Memo also forwarded to ACRS members attending 790508 meeting on reactor fuel
BOEHMERT, P ACRS - Advisory Committee on Reactor Safeguards 79/04/27 1p.
- 7905140023 Forwards Metropolitan Edison 790424 ltr w/emergency shutdown procedures & preliminary sequence of TMI-2 accident events
MCSCRELESS, T O ACRS - Advisory Committee on Reactor Safeguards 79/04/28 1p
- 7905140025 Submits emergency procedures 2202-1 1, reactor trip; 22021 3, loss of reactor coolant/sys pressure; 2202-2 1, station blackout & preliminary sequence of events rept
ARNOLD, R C GPU Service Corp 79/04/24 58pp
- 7905250393 Responds to ACRS recommendations re TMI accident as requested in NRC 790517 ltr
ANDERSON, T M Westinghouse Electric Corp. 79/05/21 21pp
- 7905300326 Discusses initial review of task force to evaluate safety implications for nuclear plant design & operation of TMI accident individual ACRS recommendations will be evaluated as part of overall design review program.
SCHERER, A E C-E Power Systems 79/05/25 2pp
- P Operating license stage documents & correspondence
- 7905110171 Matl/Byproduct License 37-17257-02 for Metropolitan Edison Co, authorizing possession of any byproduct matl w/atomic numbers 1-83 inclusive.
WRIGHT, E O Radiotopes Licensing Branch (Pre 790501) 78/03/16 2pp
- 7905110366 Forwards milestone & activity list for TMI, status dtd 780228, for period ending 780307
QUINN, W T GPU Service Corp 78/03/15 2pp
- 7905110079 Rept on reactor trip/engineered sys of 790423 W/NRC routing slip
BEELINGER, J L Metropolitan Edison Co. 78/04/23 49pp
- 7905230239 "Nuclear Power Plant Evacuation Plans"
CLEARY, P O., COMEY, D D. Citizens for a Better Environment. CBE-7865 78/05/31 32pp
- 7905230242 Forwards statement issued by D Comey of Citizens for Better Environ re emergency planning for nuclear accidents
FOUCHARD, J J Office of Public Affairs. 78/05/25. 3pp.
- 7905230248 Responds to comments of IL Emergency Bycs representative's reactions to federal radiological emergency response planning effort.
COLLING, H. E Office of State Programs 78/02/21 5pp
- 7905140125 NRC examination results for 1975-1978 power reactor operator applicants; senior operator applicants previously licensed & senior operator applicants initial application
* Commission 78/12/31 3pp
- 7905140117 "Power Plant Examination Results Summary Sheet" for various plants for 1977-1979
COOLEY, R A Operator Licensing Branch 79/02/13 180pp
- 7905190248 Tech Spec changes re emergency feedwater sys
* Metropolitan Edison Co 79/03/04 6pp
- 7905190099 Notification of breakdown in communication lines for TMI info
DAVIES, S New York, State of 79/03/16 2pp
- 7905110361 Updates announcement re 790328 incident no injuries reported & turbine shutdown caused by reduction in flow of feedwater to steam generators
* Office of Inspection & Enforcement 79/03/28 2pp
- 7905160194 Comments on TMI morning release of radioactivity
CAMPBELL, M Commission 79/03/30 1p
- 7905300216 Summarizes info re technical experts called to TMI site
* Office of Nuclear Reactor Regulation 79/03/31 1p
- 7905300288 "Preliminary Test Results, Semiscale Pressurizer Relief Valve Venting from TMI-Type Conditions"
* Office of Nuclear Reactor Regulation 79/03/31 16pp
- 7905110272 Test results of hydrogen solubility experiment 1 at Provo, UT
* Office of Nuclear Regulatory Research 79/04/01 1p.
- 7905140112 Forwards viewgraphs used at Commission meeting
EISENHUT, D O Assistant Director for Systems & Projects 79/04/01 7pp
- 7905190246 Tech Specs for ECCB
* Metropolitan Edison Co 79/04/01 4pp
- 7905300211 Discusses NRC procedures for decision to recommend evacuation
* Commission 79/04/01 7pp
- 7905090256 Forwards 790402 memo from C Stoiber re issues which NRC should consider in approaching demands for investigation into TMI incident
BICKWIT, L Office of the General Counsel 79/04/02 1p
- 7905090257 Forwards preliminary thoughts on decontamination of TMI-2 in response to JF Ahearne request
KENNEKE, A Office of Policy Evaluations 79/04/02 6pp
- 7905110158 Board notification recommends IE evaluation of reactor inspector concerns re B&W plants be sent to Boards now
VASSALLO, D B Assistant Director for Light Water Reactors 79/04/02 1p
- 7905110227 Rept 4 TMI update on situation as of 790402, re evacuation options
WILCOX, W H Housing & Urban Development, Dept of 79/04/02 3pp
- 7905140163 Forwards possible action plan by J Kelley & L Slaggie for consideration of regulatory options on B&W operating sister plants to TMI
BICKWIT, L Office of the General Counsel 79/04/02 3pp
- 7905160099 Forwards Facilities & Sys Security Branch notes on TMI & Division of Security 79/04/02 3pp
- 7905160103 Meeting notes re legal issues for TMI
HALLORY, R. Office of the General Counsel 79/04/02 1p
- 7905160141 Forwards personnel exposure & monitoring rept for 1978
HERBEIN, J O Metropolitan Edison Co. 79/04/02 2pp
- 7905160177 Outlines methods of accident review for TMI
AHEARNE, J. F. Commission 79/04/02. 4pp.

DOCKETED ITEMS

- 7905160204 Summary of info re nuclear incident as of 790402 Describes plant & environ status
LAFLEUR, J D Office of International Programs 79/04/02 3pp
- 7905160225 Forwards three sets of TLD data collected near TMI facility
W/o encl
KAMMERER, C Office of Congressional Affairs 79/04/02 1p
- 7905300403 Discusses possible determination of extraordinary nuclear occurrence at TMI-2 re application of Price-Anderson Act
BENTON, H R Office of Nuclear Reactor Regulation SHAPAR, H K
Office of the Executive Legal Director SECY-79-235 79/04/02 15pp
- 7905090233 Forwards statement of PA Governor Thornburgh re iodine in milk & background info on federal guidelines for radioactive levels in milk
KENNEKE, A Office of Policy Evaluations 79/04/03 3pp
- 7905090237 Forwards excerpts of documents relevant to emergency planning EPA protective action guides, PA action guides & FSAR conditions for general emergency action
KENNEKE, A Office of Policy Evaluations 79/04/03 83pp
- 7905090238 Lists points to be included in TMI-2 study & forwards proposed public announcement re incident prepared by F Ingram
KENNEKE, A Office of Policy Evaluations 79/04/03 10pp
- 7905110209 Requests background info for Commission re status of B&W reactors, IE Bulletin 79-05, description of IE action re B&W plants & description of task group on feedwater transient
EYBHMONT, G Commission 79/04/03 2pp
- 7905110229 Discusses requirements for requalification of TMI pumps & valves & possible changes in Tech Specs
REIFF, D Office of Nuclear Regulatory Research 79/04/03 5pp
- 7905110238 Lists status of B&W reactors as of 790402
* Commission 79/04/03 1p
- 7905110270 Test results of hydrogen solubility experiments 2 & 3 run at Provo, UT
* Office of Nuclear Regulatory Research 79/04/03 1p
- 7905160017 Notifies OELD of telcon numbers & individual to be contacted re TMI inquiries
SHAPAR, H K Office of the Executive Legal Director 79/04/03 1p
- 7905160035 Forwards three sets of thermoluminescent dosimeter data collected around TMI W/o encl
KAMMERER, C Office of Congressional Affairs 79/04/03 6pp
- 7905160036 Suggests actions in response to TMI accident Forwards possible series of events at TMI & requests comments
AHEARNE, J Commission 79/04/03 8p
- 7905190139 Summary of 790403 meeting w/GPU Svc Corp & Metropolitan Edison re base case
* Commission 79/04/03 4pp
- 7905210328 Comments on reactor pressure oscillations at TMI possibility of real oscillations between two gas vols seems likely
HARRIOTT, P W General Electric Co 79/04/03 2pp
- 7905220438 Discusses radiation levels in industrial waste treatment sampling & hydrogen recombiner
LAWYER, B GPU Service Corp 79/04/03 1p
- 7905230019 Forwards organizational chart, prerequisites for reactor coolant recovery & charts of pressure & heat curves
BERGER, D W Babcock & Wilcox Co. 79/04/03 9pp
- 7905230023 Forwards JO Herbelin 790403 memo & agenda for 790404 daily planning meeting
VOLLMER, R H Assistant Director for Site Analysis 79/04/03, 6pp.
- 7905230307 Submits brief summary of results of review of radiochemistry data reported to date.
ROY, D H Babcock & Wilcox Co 79/04/03 2pp
- 7905300430 Forwards miscellaneous handwritten notes on TMI-2
* Office of Nuclear Reactor Regulation 79/04/03 6pp
- 7904180377 Suggests program to alleviate concern among pregnant women, evaluate effects to fetus & develop epidemiologic data base for possible future studies
GOLDSMITH, R. PARSONT, M A Radiological Health Standards Branch 79/04/04 2pp
- 7905090229 Notification of development of preliminary plan to conduct series of health impact studies related to TMI incidents
TOKUHATA, G K Health, Education & Welfare, Dept of 79/04/04 2pp
- 7905110213 Draft text on TMI requested by Vice President Mondale's Cfr for possible use
* Commission 79/04/04 3pp
- 7905110290 Recommends change to natural circulation at TMI-2 when present cooling mode becomes untenable
TEDESCO, R L Assistant Director for Plant Systems 79/04/04 3pp
- 7905110316 Notes on 790404 telcon w/R Denning
HANAUER, S H Assistant Director for Plant Systems 79/04/04 1p
- 7905110387 Discusses engineering fit to hydrogen solubility data of Pray, Schweickert & Minnich
KELDER, C Assistant Director for Advanced Reactor Safety Research 79/04/04 1p
- 7905140031 Submits background info on TMI-2 incident
ETHERINGTON, H, BATES, A ACRS - Advisory Committee on Reactor Safeguards 79/04/04 5pp
- 7905140032 Summarizes assumptions in SANDIA-ORIGEN calculations re TMI operating history Provides fuel composition data, decay phase data & long-term data w/tabulated reactor operating summary
BENNETT, D E Sandia Laboratories 79/04/04 3pp
- 7905140034 Submits background info on TMI-2 incident
ETHERINGTON, H, BATES, A ACRS - Advisory Committee on Reactor Safeguards 79/04/04 2pp
- 7905140048 Discusses opinion that scenario surrounding TMI-2 incident was thoroughly evaluated by WASH-1400
BICKEL, J H ACRS - Advisory Committee on Reactor Safeguards 79/04/04 22pp.
- 7905140136 Handwritten notes of 790404 meeting at TMI
GOLDSMITH, R Office of Standards Development 79/04/04 3pp
- 7905140234 Discusses causes for hydrogen levels produced at TMI Suggests use of chemical inhibitors in ECCB &/or regular coolant to minimize potential hydrogen production
KRAMISH, A R & D Associates 79/04/04 2pp
- 7905160013 Discusses implications of TMI incident for licensed power reactors & reactors undergoing review
GRAY, J R Branch 1 79/04/04 12pp
- 7905160022 Handwritten notes re schedules as result of TMI
* Office of the Executive Legal Director. 79/04/04 13pp
- 7905160169 Outlines options for TMI accident review
AHEARNE, J. F. Commission 79/04/04 3pp
- 7905160184 Discusses estimated radiological exposure doses & B&W plan for cold shutdown
OIBSDON, T Commission 79/04/04 1p
- 7905160226 Lists licensing actions scheduled to occur between 790401-790601, including evidentiary hearings, prehearing conferences & TMI impact on future actions
TREBY, B A, Branch 1 79/04/04 3pp
- 7905190135 Discusses natural recirculation questions/concerns
* Office of Inspection & Enforcement 79/04/04. 3pp
- 7905190198 Notices of NRC procedure maintaining telephone logs from outside operations ctr
GOSBICK, L. V Office of the Executive Director for Oper 79/04/04 1p

DOCKETED ITEMS

117

- 7905210047 Discusses problems identified at B&W facilities re TMI occurrence. Identified problems include pressurizer level instrumentation, integrated control sys & lack of hydrogen. LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/04 13pp
- 7905230029 Forwards JQ Herbein 790404 memo & agenda for 790405 daily planning meeting. VOLLMER, R H Assistant Director for Site Analysis 79/04/04 5pp
- 7905230117 Requests attendance at first meeting of TMI recovery organization to be held on 790405 in Trailer 23 Organization chart encl. ARNOLD, R C OPU Service Corp 79/04/04 3pp
- 7905230123 Summary of meetings w/TMI-2 study groups re reaching natural circulation & depressurization status. STELLG, V Division of Operating Reactors MATTSO, R Division of Systems Safety 79/04/04 10pp
- 7905230126 Requests info re daily planning meeting in Trailer 22 Daily planning meeting agenda encl. VOLLMER, D Assistant Director for Site Analysis 79/04/04 5pp
- 7905090242 Notifies that Commissioner H Uchida of the Japanese Nuclear Safety Commission will arrive 790407 to review status & activities of TMI-2 events. LAFLEUR, J D Office of International Programs 79/04/05 2pp
- 7905110243 Questions & answers for Vice President Mondale on TMI * Commission 79/04/05 4pp
- 7905110271 Details efforts re equipment survivability * Office of Nuclear Reactor Regulation 79/04/05 6pp
- 7905110278 Description of proposed organization for NRC operation at TMI-2 * Office of the Executive Director for Operations 79/04/05 5pp
- 7905110280 "Evaluation of Failure Modes for Reactor Pressure Vessels, Containments & Other Safety-Related Equipment Subjected to Internal Explosive Environments" Proposes investigation. O'BRIEN, J Office of Nuclear Regulatory Research 79/04/05 1p
- 7905110281 Lists new or augmented research projects suggested as result of TMI incident & shutdown of five plants for seismic reasons. Project details encl. RICHARDSON, J E Mechanical Engineering Branch 79/04/05 14pp
- 7905110315 Lists info required from Battelle Columbus Labs. CUNNINGHAM, M Probabilistic Analysis Branch 79/04/05 1p
- 7905110323 Describes areas where General Reactor Safety Research can provide assistance re TMI incident. REIFF, D D Division of Reactor Safety Research 79/04/05 5pp
- 7905110334 Considers value of running natural circulation test on reactor, in hopes of obtaining info helpful to TMI-2 situation. TEDESCO, R L Assistant Director for Plant Systems 79/04/05 3pp
- 7905140132 Handwritten notes of 790405 meeting at PA State Health Dept. GOLDSMITH, R Office of Standards Development 79/04/05 6pp
- 7905160083 Handouts from 790405 briefing. LEVINE, B Office of Nuclear Regulatory Research 79/04/05 10pp
- 7905160239 Suggests steps to be taken following TMI. Forwards list of options, summary of investigations into civil air accidents, A Kenneke 790404 memo & C Stoiber 790404 memo. HEARNE, J Commission 79/04/05 12pp
- 7905190068 Responds to General Public Utils query re alternative methods for long-term cooling. Procedures for natural circulation flow dtd 790404 encl. ROY, D H Babcock & Wilcox Co 79/04/05 4pp
- 7905190070 Special Operating Procedure Z-57 re pressure reduction during degassification. Operations support plans encl. WALLACE, A Babcock & Wilcox Co 79/04/05 6pp
- 7905190072 Discusses pressure reduction for head cavity degassification. KOSIBI, R E Babcock & Wilcox Co 79/04/04 2pp
- 7905190074 Notes re NRC comments on special operating procedure Z-57, re pressure reduction during degassification. * Babcock & Wilcox Co 79/04/05 4pp
- 7905190077 Forwards status of B&W procedures & site comments/emergency procedures as of 6 AM on 790405. WRIGHT, R L Babcock & Wilcox Co 79/04/05 6pp
- 7905190079 Forwards cross-reference of major B&W contingency procedures w/TMI procedures. ROY, D H Babcock & Wilcox Co 79/04/05 3pp
- 7905190140 Forwards organization charts for TMI-2 recovery. DIECKAMP, H M OPU Service Corp. 79/04/05 2pp
- 7905190155 Responds to R Mattson & D Ross concerning value of running natural circulation test on B&W reactor. TEDESCO, R L Assistant Director for Plant Systems 79/04/05 4pp
- 7905230032 Forwards JQ Herbein 790405 memo & agenda for 790406 daily planning meeting. VOLLMER, R H Assistant Director for Site Analysis 79/04/05 5pp
- 7905230035 Forwards organizational chart for General Public Utils' recovery operations. Provides guidelines for communicating w/organization. DENTON, H R Office of Nuclear Reactor Regulation 79/04/05 4pp
- 7905230099 Summary of 790404 meeting of Technical Working Group to discuss desirability of reducing RCS temp from 280 F to 230 F. * OPU Service Corp 79/04/05 1p
- 7905300255 Discusses iodine & xenon concentrations in containment sumps. BARRETT, L Environmental Evaluation Branch 79/04/05 3pp
- 7904270178 Notification of plans to conduct systematic review of stds to determine their adequacy, accuracy & completeness. MINOQUE, R B Office of Standards Development 79/04/06 1p
- 7905090212 Forwards estimated core inventory of important fission & actinide products for TMI reactor. KENNEKE, A Office of Policy Evaluations 79/04/06 4pp
- 7905110245 Minutes of 790405 meeting of technical working group * Commission 79/04/06 18pp
- 7905110417 Discusses events within primary sys re core assessment. KAUFMAN, N Commission 79/04/06 7pp
- 7905140037 Notifies of 1A primary coolant pump tripped offline & 2A pump started 3 minutes later. Some change in thermocouple temp distribution noted, but not serious. FRALEY, R F ACRB - Advisory Committee on Reactor Safeguards 79/04/06 1p
- 7905140129 Handwritten notes of 790406 meeting w/Natl Cancer Inst. GOLDSMITH, R Office of Standards Development 79/04/06 2pp
- 7905160202 Submits summary of population dose for accident 790328-0405. BATTIST, L Environ Protect Standards Branch. 79/04/06 2pp
- 7905190082 TMI-2 control room manning assignments * Office of Nuclear Reactor Regulation. 79/04/06 1p
- 7905190098 Notification of reduction in IE personnel at TMI. Organizational chart encl. GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/06 3pp.
- 7905190158 Notification of completion of RELAP-4 TMI simulations. FISCHER, S R EO & O, Inc. 79/04/06 2pp.
- 7905190196 Forwards draft of chronology of events & 790406 memo from B Conner. HOWARD, M Office of Inspection & Enforcement 79/04/06 1p.
- 7905190199 Forwards chronology of events from 790328 at 7 00 am to 790402 at midnight. CONNER, B Office of Management and Program Analysis 79/04/06 18pp

DOCKETED ITEMS

- 7905210030 Forwards 790406 memo to R Graber which lists NRC personnel who have been trained in radiation safety per 10CFR19
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/06 1p
- 7905210035 Submits list of NRC personnel who have been trained in radiation safety per 10CFR19 & should be allowed unescorted access to areas requiring radiation work permits
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/06 2pp
- 7905210324 Responds to 790403 memo & suggests another possible cause of TMI pressure oscillation
HARRIOTT, P W General Electric Co 79/04/06 1p
- 7905230037 Notifies that Trailer 27 will be used as working area for technical review team & safety assessment team. Lists principal staff at work area
ROSS, D F Assistant Director for Reactor Safety 79/04/06 1p
- 7905230040 Forwards JG Herbein 790406 memo & agenda for 790407 daily planning meeting
VOLLMER, R H Assistant Director for Site Analysis 79/04/06 10pp
- 7905230107 Summary of 790405 technical working group meeting re venting waste gas in containment & long-term cooling
* GPU Service Corp 79/04/06 3pp
- 7905230273 Forwards description of staff organization & personnel assignments for NRC operations at TMI-2
BENTON, H R Office of Nuclear Reactor Regulation 79/04/06 7pp
- 7905230494 Notes on hydrogen in RCS & procedure for measuring reactor coolant hydrogen concentration
HASKIN, F E, THIESING, J W Industry Advisory Group 79/04/06 3pp
- 7905300259 Provides calculations of heat load in containment due to decay of airborne fission products & activity in sump water
TAYLOR, R H Office of Nuclear Reactor Regulation 79/04/06 11pp
- 7905110292 Forwards concept for design control of TMI-2 primary cooling sys
MATTSON, R J Division of Systems Safety 79/04/07 4pp
- 7905190153 Summary of 790407 meeting w/Metropolitan Edison to discuss auxiliary control bldg exhaust, progress rpt of waste mgmt group & radiation exposure tracking
PETERSON, T Safeguards Standards Branch, 79/04/07 3pp
- 7905190203 Discusses plans for post-event liquid radwaste. No apparent mgmt program for immediate future exists. Suggests using zeolite/charcoal/sand filters to eliminate iodine
BENARDY, V Auxiliary Systems Branch 79/04/07 4pp
- 7905190250 Forwards concept for design control of TMI primary coolant sys proposed by Levinson's study group. Believes long-term water level in reactor vessel can conceivably be controlled by using accumulator line fill
MATTSON, R J Division of Systems Safety 79/04/07 3pp
- 7905210086 Minutes of 790407 technical working group meeting w/Metropolitan Edison Co re spent fuel pool, makeup tank leakage rates, mass balance & noise analysis
* Office of Nuclear Reactor Regulation 79/04/07 2pp
- 7905230056 Forwards JG Herbein 790407 memo & agenda for 790408 daily planning meeting
COLLINS, J T Effluent Treatment Systems Branch 79/04/07 11pp
- 7905230110 Summary of 790407 planning meeting re establishment of task actions for TMI-2 study groups
ARNOLD, R C GPU Service Corp 79/04/07 14pp
- 7905230468 Observations & estimates re containment bldg & estimates of lower bound for total metal-water reaction
THIESING, J W Industry Advisory Group, 79/04/07 2pp
- 7905110212 Forwards Commissioner Gilinsky's mark-up of Chairman Hendrie's testimony before Senate Subcommittee on Nuclear Regulation on 790410.
HODGSON, A. Commission, 79/04/08, 14pp.
- 7905110219 Discusses 790407 briefing by Westinghouse re preliminary
- 7905110282 Details procedures to be followed to ensure coordination w/ natl lab support for NRC activities at TMI per 790407 discussion Summary of natl lab effort encl
MATTSON, R Division of Systems Safety 79/04/08 1p
- 7905110287 Summary of natl lab support work for TMI
BIXBY, W W, YBARRONDO, L J EO & O, Inc 79/04/07 13pp
- 7905190116 Requests authorization to ship four charcoal filters from WPPSS plant in Richland, WA to Harrisburg, PA
WILSON, R C GPU Service Corp 79/04/08 1p
- 7905190252 Recommends deferral of permission to use addl boron pending next water sample
ROSS, D F Division of Project Management 79/04/08 1p
- 7905210036 Submits revised list of IE personnel who should be authorized access to Unit 2 control room
ALLAN, J M Region 1, Philadelphia, Office of the Director 79/04/08 2pp
- 7905210091 Provides agenda for 790408 planning meeting includes task lists & 72-h lists
DAVIS, J O Office of Inspection & Enforcement 79/04/08 23pp
- 7905210238 Suggests realignment in senior personnel at TMI. Long shifts are unacceptable & fatigue is omen of ill-considered decision process
ROSS, D F Division of Project Management 79/04/08 1p
- 7905210253 Summary of 790407 meeting w/IE personnel at site to better understand overall response to event & onsite capabilities & activities
BNIEZEK, J H Office of Inspection & Enforcement 79/04/08 2pp
- 7905230048 Discusses B&W recommendation that addl boron be added to primary coolant sys
ROSS, D F Assistant Director for Reactor Safety 79/04/08 1p
- 7905230053 Discusses Westinghouse proposal to build decay heat removal sys to serve as backup to existing sys. Suggests mods to proposed sys design
* Office of Nuclear Reactor Regulation 79/04/08 8pp
- 7905230058 Preliminary thoughts on lessons learned from TMI incident
PALLADINO, N J Pennsylvania State Univ 79/04/08 6pp
- 7905230070 Discusses Westinghouse 790407 briefing on preliminary conceptual design of mods of TMI-2 decay heat removal sys. Mods intended to increase long-term reliability of sys.
MATTSON, R J Division of Systems Safety 79/04/08 3pp
- 7905230074 Forwards JG Herbein 790408 memo & agenda for 790409 TMI recovery daily planning meeting
COLLINS, J T Effluent Treatment Systems Branch, 79/04/08 10pp
- 7905300075 Submits procedures to be followed to assume coordination of natl lab support for NRC activities.
MATTSON, R Division of Systems Safety 79/04/08 2pp
- 7905100335 Forwards questions & answers for hearing backup tool re TMI incident, to be provided to chairman
MIRALIA, F Technical Section, 79/04/09, 24pp
- 7905110128 Summarizes 790405 offer by London Nuclear Decontamination Ltd to assist in TMI cleanup. Recommends meetings w/London Nuclear, PNL & BNL consultants re decontamination
O'CONNOR, P W Operating Reactors Branch 2 79/04/09 2pp
- 7905110358 Preliminary chronology of 790328 TMI incident.
* Division of Project Management 79/04/09 70pp
- 7905110369 Requests continuing repts re analysis of TMI incident
JENNEKENS, J. H. Atomic Energy Control Board, Canada 79/04/09 41p
- 7905160102 Outlines scope of fact finding board investigation. Includes technical & procedural viewpoints
SNYDER, B. J. Office of Policy Evaluations, 79/04/09 2pp
- 7905160158 Lists options for authorizing new mode of operation for TMI-2 discussion w/B Traky & L Chandler.
GRAY, J. Branch 1, 79/04/09, 3pp.

DOCKETED ITEMS

119

- 7905160223 Ack receipt of info re decontamination & recovery procedures following nuclear incident
RUSS, G D Atomic Industrial Forum 79/04/09 12pp
- 7905190121 Discusses establishment of data reduction & mgt group Copies of all TMI-2 related documents must be provided to group
Collection baskets will be placed in each trailer.
LDNO, R L Metropolitan Edison Co 79/04/09 2pp
- 7905210039 Submits revised list of IE personnel who should be authorized access to Unit 2 control room
ALLAN, J M Region 1, Philadelphia, Office of the Director 79/04/09 5pp
- 7905210095 Requests NRC staff members at TMI site provide summary rept of activities
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/09 1p
- 7905210097 Describes new organizational arrangements for shift activities to improve IE coordination
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/09 2pp
- 7905230081 Forwards 790409 planning meeting agenda & action items discusses in 790408 technical mgt meeting
STELLO, V Division of Operating Reactors 79/04/09 25pp
- 7905230082 Announces establishment of data reduction & mgt group responsible for collecting matl re incident
LDNO, R L Metropolitan Edison Co ARNOLD, R C GPU Service Corp 79/04/09 4pp
- 7905300135 Forwards flow chart delineating procedure path to be followed, key control group members & 790404 technical working group minutes
PORTER, I, Metropolitan Edison Co 79/04/09 4pp
- 7905300268 Advises that NRC has decided to defer any determination of extraordinary nuclear occurrence & should not consider Price-Anderson Act implications
CHILK, S J Office of the Secretary of the Commission 79/04/09 1p
- 7905090400 Part 21 rept ASCO solenoid HT-8331A45 disc holder is Delrin plastic which can become inoperable if subjected to max environ conditions 35" butterfly valve may fail
BAAR, R P Affiliation Unknown 79/04/10 3pp
- 7905110123 Discusses need for containing radioactive tank spills at site since island is permeable Recommends tankage on firm footing & processing waste through demineralizers
KNIGHTON, G W Environmental Evaluation Branch 79/04/10 1p
- 7905110140 Forwards rept on penetration availability for info Summarizes ability to monitor TMI reactor pressure & level using instruments outside containment.
MIRAGLIA, F J Program Support Branch 79/04/10 6pp
- 7905110193 Testimony of DO Eisenhower before Subcommittee on Nuclear Regulation of Senate Committee on Environ & Public Works, re TMI-2 incident
EISENHUT, D O Assistant Director for Systems & Projects 79/04/10, 9pp
- 7905110197 Testimony of Chairman Hendrie on 790410 before Subcommittee on Nuclear Regulation of Senate Committee on Environ & Public Works, re TMI incident IE Bulletins 79-05 & OSA encl
HENDRIE, J M Commission 79/04/10 42pp
- 7905110230 Forwards summary statement for vice president's trip, 790410 testimony before Senator Hart's subcommittee & addl background matl.
HENDRIE, J. M. Commission 79/04/10, 6pp
- 7905110286 Directs preparation of vented containment conceptual design at TMI within five days, per H Denton request
BUDNITZ, R. J Office of Nuclear Regulatory Research 79/04/10 1p
- 7905110289 Describes telcon from JB Read re chemical behavior of boric acid in primary coolant sys during incident Suggests research into behavior of boric acid under pressure.
BUDNITZ, R. J. Office of Nuclear Regulatory Research 79/04/10 1p
- 7905110296 Submits advisory rept on cooldown from 280 F to 150 F at 1,000 psia.
DAVIS, D, Office of Nuclear Reactor Regulation. 79/04/10 29pp
- 7905160068 Forwards questions & answers re containment liner & decontamination, stainless steel covering over insulation & reactor coolants prepared 790403 for use by R Minogus
HENRY, J Transportation & Product Standards Branch 79/04/10 2pp
- 7905160092 Forwards questions & answers as backup for 790410 Congressional hearing re TMI incident
* Office of Policy Evaluations 79/04/10 18pp
- 7905190176 "Behavior of RCS w/Steam Generators in Condensing Mode "
* Industry Advisory Group 79/04/10 8pp
- 7905190226 Issues temporary Tech Spec mod re operability of reactor bldg emergency cooling booster pumps
VOLLMER, R H Assistant Director for Site Analysis 79/04/10 1p
- 7905190247 Submits temporary changes to Tech Specs re operability of reactor bldg emergency cooling booster pumps
VOLLMER, R H Assistant Director for Site Analysis 79/04/10 1p
- 7905210082 Forwards Westinghouse responses to NRC 790408 questions re resolution of TMI incident
MATTEON, R Division of Systems Safety 79/04/10, 5pp
- 7905210102 Provides ground rules for conducting interviews w/licensee employees during TMI investigation
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/10 2pp
- 7905230065 Assesses RCS behavior in percolating mode before buildup of large amounts of noncondensibles
THIESING, J W Industry Advisory Group 79/04/09 1p
- 7905230067 Suppl 790409 memo re RCS behavior, stating percolation frequency estimated at 0.3 to 0.5-s
THIESING, J W Industry Advisory Group 79/04/09 1p
- 7905230080 Forwards mod criteria for use of steam generators for short & long-term cooldown
CAPODANNO, G R GPU Service Corp 79/04/10 16pp
- 7905230085 Forwards 790410 planning meeting agenda, lists of action items discussed in 790409 technical review meeting & status of plant mods
STELLO, V Division of Operating Reactors. 79/04/10, 22pp
- 7905230086 Agenda for 790410 technical review meeting
* Office of Nuclear Reactor Regulation. 79/04/10 1p
- 7905230094 Submits evaluation of General Public Utils/Burns & Row design for short- & long-term water solid steam generator operation
* Office of Nuclear Reactor Regulation. 79/04/10 7pp
- 7905230097 Notes of 6 PM 790410 technical mgt meeting
* Office of Nuclear Reactor Regulation 79/04/10 2pp.
- 7905230178 Forwards list of action items being carried out by Metropolitan Edison or consultants. Requests prompt notification of progress
VOLLMER, R H Assistant Director for Site Analysis 2pp
- 7905230278 Forwards NRC lists of licensee's priority ac
TELFORD, J T Office of Nuclear Reactor Regulation
- 7905300034 Submits status of "requests for work" to nat have been made since 790408. Forwards documentation of Lab work
BIXBY, W. W Commission 79/04/10 2pp
- 7905300061 Submits brief synopses of info furnished b personnel to NRC re TMI accident.
SNYDER, A W Sandia Laboratories 79/04/09 3pp
- 7904300123 Assessment of pressurizer level instrumentat
TMI-2.
BATTERFIELD, R M Electric, Instrumentation & Contr Branch 79/04/11 8pp
- 7905090245 Recommends that Commission host lunch for re Japanese Nuclear Safety Commission investigating stat activities of TMI-2 events
LAFLEUR, J. D Office of International Programs 79/0

DOCKETED ITEMS

- 7905110121 Forwards preliminary primary coolant analysis results for 790411 sample Final results available 790412
MIRAGLIA, F J Program Support Branch 79/04/11 2pp
- 7905110136 Forwards update on 790410 advisory rept re condenser integrity & containment isolation
DAVIS, D K Systematic Evaluation Programs Branch 79/04/11 4pp
- 7905110328 Assesses impact of TMI incident on existing emergency control ctr bypass programs Analysis & reporting expected to slip due to diversion of key staff
BECKNER, W D Division of Reactor Safety Research 79/04/11 1p
- 7905140038 Forwards LER, IE insp rept & IE circular re Zion experience w/pressurizer level instruments w/o encl
AYCOCK, K Office of Nuclear Reactor Regulation 79/04/11 1p
- 7905160140 Forwards alternative drafts of policy statement for TMI accident review
AHEARNE, J F Commission 79/04/11 25pp
- 7905190096 Discusses inquiry re decrease in reactor bldg negative pressure
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/11 1p
- 7905190113 Authorizes NRC to locate & obtain railroad tank cars for use at facility NRC will be reimbursed reasonable costs
ARNOLD, R C GPU Service Corp 79/04/11 1p
- 7905190169 Submits criteria for use of steam generator for short- & long-term cooldown
HERBEIN, J G Metropolitan Edison Co 79/04/11 1p
- 7905190172 Discusses acceptability of sys criteria for use of steam generators for short- & long-term cooldown Acceptable but for one exception re design flow rate for A&B mods
MATTSON, R J Division of Systems Safety 79/04/11 2pp
- 7905190229 Responds to NRC 790411 ltr & discusses criteria for use of steam generator for short- & long-term cooldown
HERBEIN, J G Metropolitan Edison Co 79/04/11 1p
- 7905210076 Discusses reduction of reactor pressure for gas removal Pressure gauge w/most conservative reading should be used
* Babcock & Wilcox Co 79/04/11 1p
- 7905210108 Evaluate TMI personnel dosimetry Ability to assess doses to personnel is adequate
SLOBODIEN, M J Region 1, Philadelphia, Office of the Director 79/04/11 4pp
- 7905210110 Requests daily written summary statement re public whole body counting
SMITH, Q H Office of Inspection & Enforcement 79/04/11 1p
- 7905210112 Requires revised schedule to include visit to NRC trailer at TMI observation ctr after each daily briefing
SMITH, Q H Office of Inspection & Enforcement 79/04/11 1p
- 7905210117 Items presented at 790411 health physics planning meeting Correction factors not used for results of iodine air samples collected on charcoal cartridges
* Office of Inspection & Enforcement 79/04/11 1p
- 7905220442 Submits marked-up draft SER on WASH-1400 relevancy to TMI
CUNNINGHAM, M Office of Nuclear Regulatory Research 79/04/11 3pp
- 7905230026 Discusses installation of backup deep-bed filter for containment purge
RODGERS, W Industry Advisory Group, 79/04/11 6pp
- 7905230109 Lists current or planned plant mods & status of Ofc of Nuclear Reactor Regulation technical review group review
NOVAK, T M Division of Systems Safety, 79/04/11 3pp
- 7905230116 Submits power conversion sys results from Savannah River.
VOLLMER, R H Assistant Director for Site Analysis 79/04/11. 1p
- 7905230220 Agenda for TMI tour on 790411-12.
OILINSKY, V., KENNEDY, R T Commission 79/04/11 1p
- 7905230476 Status re leak from vent header & potential problem w/access hole to make up tank
LAHROSKI, S ACRS - Advisory Committee on Reactor Safeguards 79/04/11. 1p.
- 7905230480 Tentative qualification of makeup tank sys up to MW 413 notes
LAHROSKI, S ACRS - Advisory Committee on Reactor Safeguards, 79/04/12 1p
- 7905230486 List of RELAP-4 TMI natural convection simulations which have been performed Plot & addl info available
FISCHER, S. BEHLING, S EQ & G, Inc 79/04/11 2pp
- 7905300232 Notification of 790423-25 meeting w/ANS in Chicago, IL to discuss TMI-2 effort Requests NRC participation
BUDENHOLZER, R Illinois Institute of Technology 79/04/11 1p
- 7905090228 Forwards lists of NRC regulations & Reg Guides classified Category "A" & "B"
ARLOTTO, G A Division of Engineering Standards 79/04/12 10pp
- 7905090241 Forwards notice of extension of public comment period for NUREG-0396
RYAN, R O Office of State Programs 79/04/12 1p
- 7905090244 Notice of extension of comment period re "Planning Basis Development of State & Local Govt Radiological Emergency Response Plans in Support of LWR Power Plants," NUREG-0396
RYAN, R O Office of State Programs 79/04/11 2pp
- 7905090253 Agenda of conference to be held 790412 in PA concerning health impact of TMI incident
* Commission 79/04/12 2pp
- 7905100384 Summary of 790411 meeting w/Westinghouse in Bethesda, MD re corrective actions for its PWR plants, as result of TMI-2 incident
ROSS, D F Division of Project Management 79/04/12 6pp
- 7905110119 Forwards primary coolant sample analysis info developed by S Bland & F Kantor
MIRAGLIA, F J Program Support Branch 79/04/12 4pp
- 7905110133 Forwards addl detail on 790411 headquarters advisory repl re specific valve designation for containment isolation penetrations
DAVIS, D K, Systematic Evaluation Programs Branch 79/04/12 8pp
- 7905110138 Forwards preliminary data re primary coolant sample at TMI taken on 790410
MIRAGLIA, F J Office of Nuclear Reactor Regulation 79/04/12 2p
- 7905110233 Questions & answers to questions posed by S Herberich re:
* Commission, 79/04/12 16pp
- 7905110295 Submits advisory rept on boration & criticality aspects re cooldown from points A to C.
DAVIS, D Office of Nuclear Reactor Regulation 79/04/12 36pp
- 7905110322 Forwards info received from Ofc of Nuclear Reactor Regulation team at facility re cooldown
MIRAGLIA, F J Office of Nuclear Reactor Regulation 79/04/12 18pp
- 7905140134 Handwritten notes of 790412 meeting w/PA State Health Dept
GOLDENRITH, R Office of Standards Development 79/04/12 7pp
- 7905160001 Requests notification of possible meeting date between D Eisenhower of NRC & M Uchida of Japanese Nuclear Safety Commission
LAFLEUR, J D Office of International Programs 79/04/12 1p
- 7905160004 Submits preliminary info re 790328 incident Bulk coolant inlet & outlet temps remain at 280 F.
LAFLEUR, J D Office of International Programs 79/04/10 2pp
- 7905160005 Forwards FBI communication re TMI incident w/o encl
BRADY, R J Division of Security 79/04/12 1p
- 7905160155 Offers services in maint procedures re parts & manpower to help NRC establish procedures for nuclear power plants.
MCCULLOUGH, H. Affiliation Unknown 79/04/12 2pp
- 7905190111 Authorizes NRC to ship skid-mounted hoist from Henschel Co for use at facility. NRC will be reimbursed reasonable costs
ARNOLD, R C GPU Service Corp 79/04/12 1p

DOCKETED ITEMS

121

- 7905190173 Lists info requirements for in-plant data for inclusion in daily PNO
SMITH, Q H Office of Inspection & Enforcement 79/04/12 1p
- 7905190175 Lists requested replacements for IE Region 1 personnel at TMI-2 site
KEIMIG, R R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/12 1p
- 7905190177 Guidelines to facilitate NRC info exchange w/DOE & other agencies
STOHR, J P Region 1, Philadelphia, Office of the Director 79/04/12 2pp
- 7905190236 Forwards safety analysis rept re proposed transition to natural circulation as requested at NRC 790409 meeting
Long-term natural circulation is viable for stability
HERBEIN, J G Metropolitan Edison Co 79/04/12 1p
- 7905190243 Agenda of meeting re recovery from incident
* Metropolitan Edison Co 79/04/12 15pp
- 7905210034 Catalytic, Inc can provide technical & field support
CAPHTON, D L Region 1, Philadelphia, Office of the Director 79/04/12 1p
- 7905210042 Forwards Insp Plan IP-1 for operating reactors in PA, effective immediately
BRUNNER, E J Region 1, Philadelphia, Office of the Director 79/04/11. 7pp
- 7905210044 Final version of testimony before Senate Subcommittee on Nuclear Regulation re six main factors causing accident
Supporting documentation encl
HENDRIE, J M Commission 79/04/10 16pp
- 7905210056 Recommends duty officer program for immediate notification of incidents, effective 790413
DAVIS, J G Office of Inspection & Enforcement 79/04/12 2pp
- 7905210133 Forwards DOE illustrative matl re releases near plant site
STOHR, J P Region 1, Philadelphia, Office of the Director 79/04/12 7pp
- 7905210140 Requests environ info to be gathered & picked up regularly at IE command post re facilitating info exchange w/DOE & other agencies
STOHR, J P Region 1, Philadelphia, Office of the Director 79/04/12 2pp
- 7905210144 Lists Metropolitan Edison Co & contractor exposures by group to 790411
SLOBODIEN, M J Region 1, Philadelphia, Office of the Director 79/04/12 1p
- 7904270088 Summarizes meeting w/Ctr for Disease Control & PA Dept of Health re possible epidemiologic studies
OODBENITH, R. Radiological Health Standards Branch 79/04/13 2pp
- 7904270152 Forwards advisory on effect of loss of recombiner operation on hydrogen concentration in containment, due to 790413 failure of Atomic Intl recombiner heater assembly
MIRAGLIA, F. J Office of Nuclear Reactor Regulation 79/04/13 7pp
- 7904270399 Forwards preliminary evaluations & bases of meltdown analysis for TMI covering core melt penetration, hydrogen generation & potential for explosion
MARCHEBE, A , LONG, J , CARTER, T Advanced Reactors Branch 79/04/13 1p
- 7904270576 Forwards list of TMI related followup actions currently underway or planned in response to LV Gossick 790412 memo
MINGOUE, R B Office of Standards Development 79/04/13 2pp
- 7905090280 Discusses how transcript of NRC meetings held 790506, 09, 10 & 13 re TMI-2 incident will be made available
BICKWIT, L Office of the General Counsel 79/04/13. 4pp.
- 7905090254 Summary of 790412 meeting w/Busquehanna River Basin Commission to discuss TMI-2, Stated .5 Ci of I-131 discharged to river; described water monitoring program & NRC role re water quality during TMI-2 cleanup
ELBASSER, T C Office of State Programs. 79/04/13. 2pp
- 7905110130 Forwards list of useful electrical, instrumentation & control schematics
LAINAS, O Plant Systems Branch 79/04/13. 5pp.
- 7905110133 Forwards NRC advisory by RD Meyer recommending all incore thermocouples be read in continuous manner w/provisions for rapid retrieval & permanent storage
LAINAS, O Plant Systems Branch 79/04/13 2pp
- 7905110381 Lists Division actions re TMI w/contact person, descriptive title of action & estimate completion dates
* Office of Nuclear Regulatory Research 79/04/13 4pp
- 7905210040 Lists IE personnel who are on duty at TMI
MCDESCAR, J J Region 1, Philadelphia, Office of the Director 79/04/13 2pp
- 7905210120 Forwards interoffice memos routed to NRC re radioactive sample analysis, alternate method to measure steam generator level & modified criteria for use of steam generators for cooldown.
DANIEL, J A GPU Service Corp 79/04/13 24pp
- 7905210124 Recommends procedures re util effluent monitoring
STOHR, J P Region 1, Philadelphia, Office of the Director 79/04/13 2pp
- 7905210240 Discusses nondestructive examinations of weld joints
Requests resolution of inconsistencies on data sheets & rationale for util taking credit for insp
TRIPP, L Metropolitan Edison Co 79/04/13 2pp
- 7905220439 Summary of 790412 meeting w/Busquehanna River Basin Commission re TMI incident
ELBASSER, T C Region 1, Philadelphia, Office of the Director 79/04/13 2pp
- 7905230002 Summary of 790413 meeting to plan TMI-2 strategy
* Office of Nuclear Reactor Regulation 79/04/13 4pp
- 7905230041 Forwards list of electrical, instrumentation & control schematics w/o enclosure
LAINAS, O. C Office of Inspection & Enforcement 79/04/13 1p
- 7905210247 Exposure summary of Metropolitan Edison Co & contractor personnel on 790414
SLOBODIEN, M J Region 1, Philadelphia, Office of the Director 79/04/14 1p
- 7905230471 Comments on Task 1 qualifications of vent header sys (qualifications of make up tank sys).
LAWROSKI, N ACRS - Advisory Committee on Reactor Safeguards 79/04/14 1p
- 7905160129 "Preliminary Estimates of Population on Dose & Health Effects"
BATTIST, L., BUCHANAN, J , CONGEL, F Division of Site Safety & Environmental Analysis 79/04/13 73pp
- 7905190107 Ad hoc interagency dose assessment group preliminary estimates of population dose & health effects re TMI-2 events
BATTIST, L , BUCHANAN, J Environ Protect Standards Branch
CONGEL, F Division of Site Safety & Environmental Analysis 79/04/13 60pp
- 7905210018 Forwards TMI/General Public Utils Data Reduction & Mgt Group Status Rept 1. Includes info re temp & environ readings
WEIBER, J L. GPU Service Corp 79/04/13 9pp
- 7905210189 Agenda of 790413 technical group meeting w/Metropolitan Edison
* Commission 79/04/13 4pp.
- 7905230036 Conceptual design for TMI-2 venting Supersedes previous versions
DISALVO, R Office of Nuclear Regulatory Research. 79/04/13 3pp.
- 7905230118 Requests clearance for JT Collins to drive to processing bldg
VOLLMER, R H Assistant Director for Site Analysis 79/04/13 1p
- 7905020468 Forwards preliminary sequence of events for first 20-h following accident on 790228
HERBEIN, J O. Metropolitan Edison Co. 79/04/16. 16pp
- 7905090248 Forwards requested telephone log & states no significant contacts made on 790401.
ELBASSER, T. Office of State Programs. 79/04/16 5pp

DOCKETED ITEMS

- 7905090253 Forwards request for info re involvement in NRC activities relating to TMI during period from 790328-0401
ENDELHARDT, T F Office of the Executive Legal Director 79/04/16 1p
- 7905090260 Request that all personnel engaged in NRC response to TMI accident record their actions on paper
GOSSICK, L V Office of the Executive Director for Operations 79/04/13 1p
- 7905110151 Forwards compilation of analysis of 790329 & 0410 primary coolant samples
MIRAGLIA, F J Office of Nuclear Reactor Regulation 79/04/16 5pp
- 7905110330 Summarizes Branch recommendations for addl operational safety research based on preliminary review of TMI incident
BENNETT, G L Research Support Branch 79/04/16 12pp
- 7905160119 Suggests actions in response to ACRS TMI reprimands should be provided to get direct water level reading in reactor core
AHEARNE, J F Commission 79/04/19 2pp
- 7905160132 Requests comments on encl J Vellin 790402 ltr re TMI incident
KENNEDY, R T Commission 79/04/19 1p
- 7905160138 Suggests that ground dose measurements, isotopic composition & time pattern of activity released from plant & number of exposed workers be recorded for later analysis
VELLIN, J Harvard Univ 79/04/02 1p
- 7905160142 Requests chronology of arrival times of federal & state representatives at site, copy of Interagency Radiological Assistance Plan & NRC regulations re emergency planning
KENNEDY, R T Commission 79/04/19 1p
- 7905160124 Confirms 790405 telcon re willingness to attend TMI related meeting
TILBE, H E London Nuclear Decontamination, Ltd. 79/04/16 1p.
- 7905210228 Tank car lease agreement between Union Tank Car Co & General Public Utils
* QPU Service Corp 79/04/16 19pp
- 7905230125 Summarizes NRC comments on acceptability of design criteria for mods to facility electrical power sys Design criteria for two new diesel generators & use of 13.8 kV const power source is acceptable
STELLD, V Division of Operating Reactors 79/04/16 2pp
- 7905230128 Requests retention of IH Peters & DL Ebersole as drivers until 790421
STELLD, V Division of Operating Reactors 79/04/16 1p
- 7905230281 Forwards updated status of various proposals for achieving cold shutdown
NOVAH, T M Office of Nuclear Reactor Regulation 79/04/16 44pp
- 7905230297 Provides summary of QA practices associated w/facility mods reviewed to date.
OILRAY, J Quality Assurance Branch. 79/04/16 5pp.
- 7905300100 Forwards inventory of current TMI-2 related actions
GOSSICK, L V Office of the Executive Director for Operations 79/04/16 1p.
- 7905300105 Forwards inventory of current TMI-2 related actions.
GOSSICK, L V Office of the Executive Director for Operations 79/04/16 3pp
- 7905300111 Responds to LV Gossick 790412 memo listing current TMI related actions
SHEA, J.R. Office of International Programs 79/04/13 5pp
- 7905300118 Details personnel actions re TMI incident
BIRD, P.E Office of Administration. 79/04/13. 2pp
- 7905300156 Forwards info requested in 790412 memo re personnel in Div of Contracts who will review & list all procurement actions resulting from TMI incident.
HALMAN, E L Division of Contracts 79/04/13 2pp
- 7905300162 Responds to 790413 memo listing personnel from Ofc of Administration involved in communications at TMI-2 site
HALLACE, J.R Division of Facilities & Operations. 79/04/13 3pp.
- 7905300169 Responds to 790412 memo listing current div projects re TMI incident
BEGAN, W J Technical Information & Document Control. 79/04/16 4pp
- 7905100016 Ack receipt of 790413 memo & accompanying proposal re NRC command & control center to improve communications sys for dealing w/events similar to TMI Improved communication sys will be considered
HENDRIE, J M Commission 79/04/17 1p
- 7905100017 Forwards proposal for NRC command & control center for nuclear reactors & transport of BNH
PODOLAK, E M Radiological Health Standards Branch 79/04/13 4pp
- 7905100018 Proposes study of feasibility of NRC command & control ctr for nuclear reactors & transportation of BNH
PODOLAK, E M Radiological Health Standards Branch. 76/02/17 3pp.
- 7905100022 Forwards 790329 & 790403 suggestions by E Podolak re computer controlled communications link & legislative authority to prosecute for felonies Requests 60-day review period
COBB, L I Office of I&E, Executive Officer for Management & Analysis 79/04/16 1p
- 7905100034 Suggests that NRC bolster enforcement sys by seeking legislative authority to prosecute individuals who are personally responsible for serious NRC violations
PODOLAK, E M Radiological Health Standards Branch 79/04/03 1p
- 790510265 Discusses Sandia Lab study of coolability of rubblised core debris High safety margin exists for cooling TMI core at atmospheric pressure by boiling cellular natural convection
WRIGHT, R W Experimental Fast Reactor Safety Research Branch 79/04/17 3pp.
- 7905160114 Requests further info re Ofc of Nuclear Reactor Regulation action on TMI
AHEARNE, J F Commission. 79/04/17. 1p
- 7905160220 Forwards 790409 ltr from G Russ of AIF re background articles used in attempt to put TMI in perspective
BERNERD, R Assistant Director for Materials Safety Branch 79/04/17 1p
- 7905190093 Authorizes NRC to ship breathing air manifolds & 350 cubic ft per minute compressor w/hoses, manifolds & air suit tops
NRC will be reimbursed all reasonable expenses
ARNOLD, R.C. QPU Service Corp. 79/04/17 1p.
- 7905190120 Authorizes NRC to ship three charcoal filters from TMI-2 to Columbus, OH NRC will be reimbursed reasonable costs
ARNOLD, R.C. QPU Service Corp 79/04/17 1p.
- 7905190187 Authorizes shipment of three charcoal filters from TMI to Columbus, OH
ARNOLD, R.C QPU Service Corp 79/04/17 1p.
- 7905210021 Forwards TMI/General Public Utils Data Reduction Mgt Group Status Rpt 3 Info includes reactor & reactor bldg temp & pressure 790401-0416.
WEISER, J L QPU Service Corp 79/04/17 6pp
- 7905210070 Forwards summary rept on gas analyses performed on TMI primary water sample received 790418.
EMAL, W.A. Allied Chemical Corp. 79/04/17 14pp.
- 7905220433 Describes Task 11 ex-core monitoring of core conditions Four groups of detectors provide info re core conditions
Discusses neutron sources & location
BALL, R Special Instrument Group 79/04/17 2pp.
- 7905300420 Requests that Missions pass TMI-related info to NRC official contacts
LAFLEUR, J D Office of International Programs. 79/04/17. 1p.
- 7905190089 Discusses sequence of events to be followed if reactor coolant pump 2A fails. Forwards operations support plans.
ARNOLD, R.C., KEAYEN, R W. QPU Service Corp. 79/04/18. 6pp
- 7905210246 Summary of 790418 visit to Susquehanna River Islands, Pa to take soil & grass samples. No evidence of recent const or activity.
MCCLINTOCK, R.O., SLOBODIEN, H Region 1, Philadelphia, Office of the Director. 79/04/18 1p.

DOCKETED ITEMS

123

- 7905300319 Forwards recommendations re handling FOIA requests for documents on TMI-2 Requests comments & concurrences by
790419
BICKHIT, L Office of the General Counsel 79/04/18 3pp
- 7905020041 Responds to 790417 memo re need to apply special measures for transportation of radioactive wastes from TMI-2 site for disposal Requests to be kept informed of shipments
BURNETT, R F Division of Safeguards 79/04/19 1p
- 7905110231 Summary of 790419 meeting w/H Turpolak of HEW re response he is preparing for Secretary Califano re recent iodine releases at TMI & nature of final cleanup efforts
ORIMEG, B K Assistant Director for Engineers & Projects 79/04/19 1p
- 7905210027 Forward requested questions re loss of main coolant pump, RHR heat removal sys, loss of air conditioning power & loss of pressurizer vent capability
MURPHY, J A Office of Nuclear Regulatory Research 79/04/19 8pp
- 7905210068 Forwards KA Power & Light answers to effectiveness of adding hydrazine to primary sys to scavenge oxygen since there is indication of dissolved oxygen in primary coolant
MATHEWS, P R Division of Systems Safety 79/04/19 2pp
- 7905210073 Forwards analysis results of boron measurements from 790411 primary sys sample (non-pressurized)
TELFORD, T Division of Operating Reactors 79/04/19 5pp
- 7905210293 Review & evaluation of personnel dosimetry data from 790328-0403.
BLODDEIEN, M J Region 1, Philadelphia, Office of the Director 79/04/19 3pp
- 7905210295 Forwards list of people to be interviewed, list of procedures to be certified, list of requested documents & list of addl procedures in effect on 790328
MARTIN, R Division of Systems Safety, 79/04/19 11pp
- 7905230014 Changes designation of new diesel generator to "grey" to avoid confusion w/Class IE blue div
CRONENBERGER, D K GPU Service Corp 79/04/19. 1p
- 7905230015 Technical support procedures group has developed variation on method to predict pressurizer level from indicated temp Recommends procedure be initiated
WALLACE, E G GPU Service Corp 79/04/19 1p.
- 7905230265 Discusses analyses of boron measurements from 790411 non-pressurized primary sys sample
TELFORD, J T Office of Nuclear Reactor Regulation 79/04/19 5pp
- 7905230445 Concerns re cleanup of auxiliary bldg & containment
LAHROBK, H ACRB - Advisory Committee on Reactor Safeguards 79/04/19. 1p.
- 7905300437 Discusses current status of safety-related operator action study
MILHMAN, J L Reactor Systems Standards Branch 79/04/19 2pp
- 7905300438 Draft rept. "Safety-Related Operator Action."
BOYD, T. F., HAAB, P H Oak Ridge National Laboratory FIN E-0421 ORNL/TM-6853 79/04/13. 113pp.
- 7905090210 Responds to LV Gossick 790413 request for record of actions on TMI accident. Summarizes 790402-0404 discussions re reactor coolant pumps & containment integrity
HARRING, E. C. Reactor Systems Standards Branch 79/04/20. 1p
- 7905090219 Forwards scopes on Categories A & B reg guides being considered for revision as result of TMI-2 event data
EIDEN, A L Division of Engineering Standards 79/04/20. 123pp.
- 7905090231 Summary of 790412 meeting w/PA State Health Dept in Harrisburg, PA re strategy for evaluating health impact of TMI incident
GOLDSMITH, R Radiological Health Standards Branch 79/04/20 2pp.
- 7905090237 Responds to 790420 request for names of candidates for TMI internal team to investigate accident Suggests M Collins, R Jaska, W Kerr, B Schwartz
RYAN, R. J. Office of Nuclear Regulatory Research 79/04/20. 1p
- 7905110126 Forwards requested info prepared by R Emch & F Akstulewicz showing dose rate from 12-inch RHR pipe containing primary coolant.
MIRAGLIA, F J Office of Nuclear Reactor Regulation 79/04/20 3pp.
- 7905110266 Forwards Sandia Lab rept on calculations of coolability of rubblized TMI core debris
WRIGHT, R W Experimental Fast Reactor Safety Research Branch 79/04/20 2pp
- 7905110267 Forwards rept "Cooling of TMI Core Debris"
RIVARD, J B Sandia Laboratories 79/04/19 1p
- 7905110269 "Cooling of TMI Core Debris"
* Sandia Laboratories 79/04/12 6pp
- 7905160079 Suggests improvements in sys of communications for emergency response situations & need for mobile radiation monitoring units available to each ofc Requests rept
KENNEDY, R T Commission 79/04/20 1p
- 7905160088 Requests info re TMI including license conditions re flood levels, status of spent fuel pools & whether any addl plants are planned for area
AHEARNE, J F Commission 79/04/20 1p
- 7905160147 Forwards ltr from Logistics Management Institute offering to discuss maint procedures to help NRC establish procedures for nuclear power plants
AHEARNE, J F Commission 79/04/20 1p
- 7905210055 Updates R Ball's 790417 memo detailing rationale for high counting rate of B-F-3 neutron detecting startup channel
STELLO, V. Division of Operating Reactors 79/04/20 10pp
- 7905210261 Details synopsis of environ analyses performed since 790418 All results are for I-131
SMITH, G Office of Inspection & Enforcement 79/04/20 2pp
- 7905210319 Requests addition of JS Creswell, Dr Hunter, DC Kirkpatrick, T Shaub, R Summers, P Blissett to list for IE per Amend 3 to NRC access list dtd 790413
MCOSCAR, J J Region 1, Philadelphia, Office of the Director 79/04/20 2pp
- 7905220428 Notifies that Ofc of Executive Legal Director TMI documents w/released info must be transmitted to FOIA officer, per encl Announcement 39
MONDICH, D Administrative Branch 79/04/20 1p
- 7905220429 Announcement 39 re preservation of records re TMI incident Forwards list of FOIA coordinators
FELTON, J M Division of Rules and Records 79/04/12 3pp
- 7905230088 Forwards list of Region I personnel dispatched to site from 790328-0401.
MARTIN, R Division of Systems Safety 79/04/20 3pp
- 7905230011 Forwards "Criteria for Loss of Offsite Balance of Plant Electrical Power"
CRONENBERGER, D GPU Service Corp 79/04/21 1p
- 7905230012 "Criteria for Loss of Offsite Balance of Plant Electrical Power"
* GPU Service Corp 79/04/22 6pp
- 7905230138 Lists IE personnel to be added to NRC Access List dtd 790413
MCOSCAR, J J. Region 1, Philadelphia, Office of the Director 79/04/21 1p

DOCKETED ITEMS

- 7905230293 Discusses L Kovach's recommendations re carbon adsorbers in auxiliary bldg Trays should be removed from sys and cleaned of carbon
COLLINS, J T Effluent Treatment Systems Branch 79/04/22 1p
- 7905070035 Synopsis of info obtained re operating history of TMI-2 Info re inventories of significant fission products expected in core will be collected Plots of decaying inventories made where feasible
NELLIS, D O Transportation & Product Standards Branch 79/04/23 2pp
- 7905090216 Comments on Commissioner Ahearn's 790403 "set of thoughts on how we could possibly go about TMI accident review" Review must distinguish why & what happened
MOORE, R H Office of Management and Program Analysis 79/04/23 1p
- 7905090220 "Testimony of R Moore & L Abramson"
MOORE, R, ABRAMSON, L Office of Management and Program Analysis 79/11/30 16pp
- 7905090224 Supplemental Testimony of R Moore & L Abramson in response to ALAB-525
MOORE, R Office of Management and Program Analysis 79/03/16 14pp
- 7905110220 Ack receipt of 790413 offer to serve on safety review panel Offer will be considered
HENDRIE, J M Commission. 79/04/23 1p
- 7905110223 Offers to serve on review committees re TMI
HOCEVAR, C J Affiliation Unknown 79/04/13 1p
- 7905110234 Testimony before Subcommittee on Nuclear Regulation of Senate Committee on Environ & Public Works re TMI-2 incident
DIECKAMP, H General Public Utilities 79/04/23 21pp
- 7905110248 Suggests Nuclear Regulatory Research staff members to serve on TMI incident investigation
LEVINE, S Office of Nuclear Regulatory Research, 79/04/23 1p
- 7905110312 Handwritten notes re TMI incident for period 790404-0423
CUNNINGHAM, H Probabilistic Analysis Branch 79/04/23 24pp
- 7905110331 Responds to 790406 memo requesting comments re environ qualification & instrumentation to follow course of an accident
MILLER, C F Electric, Instrumentation & Control Systems Branch 79/04/23 2pp
- 7905140034 Observations made at meeting of Senate Subcommittee on Nuclear Regulation, Committee on Environ & Public Works concerning TMI Accident
JOHNSON, D. H Office of the Secretary of the Commission 79/04/23 8pp.
- 7905140098 Forwards prepared testimony given at hearing before 790423 Senate Subcommittee on Nuclear Regulation w/o testimony
KAMMERER, C Office of Congressional Affairs 79/04/23 2pp
- 7905160018 Details actions taken in response to RJ Budnitz 790410 memo to file re vented containment conceptual design at TMI
DISALVO, R Office of Nuclear Regulatory Research 79/04/23 7pp
- 7905160144 Requests info re min requirements for control room manning by licensed reactor operators & advantages & disadvantages of presence of third operator
KENNEDY, R. T. Commission 79/04/23 1p
- 7905230009 Forwards Revision 3 of "Reactor Coolant Pressure Control Sys Design Criteria-Makeup Portion," dtd 790420
CRONEBERGER, D GPU Service Corp 79/04/23 1p
- 7905230010 Task 4B: "Reactor Coolant Pressure Control Sys Design Criteria-Makeup Portion," Revision 3
ZANIS, L., LU, T GPU Service Corp, 79/04/23, 11pp.
- 7905230013 Lists members of newly formed Natural Circulation Initiation Task Force
ARNOLD, R C GPU Service Corp 79/04/23 1p.
- 7905230171 Forwards draft of work statement for contract to review federal agency interaction.
GREHER, E Office of Inspection & Enforcement 79/04/23 4pp
- 7905300424 Requests that TMI bulletins & NRC plans for future info dissemination be forwarded to NRC official contacts.
LAFLEUR, J D Office of International Programs 79/04/23, 2pp.
- 7905070005 Forwards H Masatis' comments on review of Emergency Procedure 5
MIRAGLIA, F J Office of Nuclear Reactor Regulation 79/04/24 2pp
- 7905110218 Telcon summary Describes valve misalignment at TMI during change of feedwater flow from main to auxiliary sys
BRYAN, S Office of Inspection & Enforcement 79/04/24 1p
- 7905160131 Forwards rough estimate of initial source term that was potentially available in auxiliary bldg for release to atmosphere
BLOND, R Office of Nuclear Regulatory Research 79/04/24 3pp
- 7905190040 Submits evaluation re sys analysis of filling & operation of once-through steam generator B water solid
* Office of Inspection & Enforcement 79/04/24 3pp
- 7905190061 Requests info re site related activities from 790328 re 790331 at 12 01 AM
O'BRIEN, A Region 1, Philadelphia, Office of the Director 79/04/24 3pp
- 7905230001 Savannah River life support air sys will be used by site personnel
ROBISON, J D GPU Service Corp 79/04/24 1p
- 7905230005 Outlines priorities & procedures for waste disposal w/ organizational chart & list of responsibilities encl
RUSCHE, B, ARNOLD, R C GPU Service Corp HERBEIN, J O Metropolis, Edison Co 79/04/24 9pp
- 7905230006 Forwards revised criteria for use in designing plant side to use A & B steam generators as high pressure water to water heat exchangers for decay heat removal
CAPODANNO, O GPU Service Corp 79/04/24 2pp
- 7905230007 "TMI-2 Sys Criteria for Use of Steam Generator A for shut & Long-Term Cooldown," Revision 3
* GPU Service Corp 79/04/24 11pp
- 7905230008 "TMI-2 Sys Criteria for Use of Steam Generator B for Cooldown at High Pressure," Revision 3
* GPU Service Corp 79/04/24 9pp
- 7905230024 Details reorganization of waste mgt activities
RUSCHE, B, HERBEIN, J O, ARNOLD, R C GPU Service Corp, 79/04/24 9pp
- 7905230152 Discusses effluent & process gas monitoring sys & Victorian air monitor
STODDART, P Division of Site Safety & Environmental Analysis 79/04/24 2pp
- 7905230172 Informs that main turbine was manually tripped when wiser was heard in steam line around turbine control valves
OLSHINSKI, J Division of Systems Safety 79/04/24 1p
- 7905230175 Unexecuted memo of understanding to exchange environ info data between NRC, EPA, & HEW. Forwards morning repts for 790423-25
STELLO, V Division of Operating Reactors COX, C Health, Education & Welfare, Dept of BRETTHAUER, E Environmental Protection Agency 79/04/24 4pp
- 7905230298 Forwards comments on sys analyses of filling and operating once-through steam generator B water solid Secondary side should be filled slowly to avoid water hammer
NOVAK, T. M Office of Nuclear Reactor Regulation 79/04/24 3pp
- 7905300347 Discusses security assistance for NRC press ctr in Middletown Borrow Hall, Middletown, PA
BURCH, C. L Division of Security 79/04/24 2pp
- 7905110215 Questions for Commission 790425 meeting on B&W plants
* Commission 79/04/23 2pp
- 7905110255 Forwards correspondence summarizing evaluation of hydrogen gas in primary coolant sys & containment bldg atmosphere.
RIB, L. N. Assistant Director for Advanced Reactor Safety Research 79/04/25 2pp
- 7905110257 Forwards table summarizing calculation of hydrogen gas at several pressure & temp conditions corresponding to sys cooldown, pressure reduction & rapid depressurization
RIB, L. N. Assistant Director for Advanced Reactor Safety Research, 79/04/23 2pp.
- 7905110258 Presents results of parametric appraisal of hydrogen solubility data base & estimated hydrogen releases at TMI
PERSON, L. E Fuel Reprocess. & Recycle Branch 79/04/11 4pp

DOCKETED ITEMS

125

- 7905110259 Discusses upper limit estimates of hydrogen formation via zirconium-water reaction & from radiolysis
LARKINS, J T Experimental Gas-Cooled Reactor Safety Research Branch 79/04/11 3pp
- 7905110261 Discusses need for thorough review of radiation & physical chemistry of LWR primary coolant Suggest formation of task force & review of SARs & SERs
WITTF, F J Fuel Process Systems Standards Branch 79/04/25 6pp
- 7905110263 Summarizes info on hydrogen reduction methods
RIB, L N Assistant Director for Advanced Reactor Safety Research 79/04/25 3pp
- 7905110343 Provides preliminary assesment of core damage at TMI Forwards & discusses calculations by NRC & others to determine extent of damage
MARINO, G P Fuel Behavior Branch 79/04/25 22pp
- 7905110348 Discusses GRA88-BST calculations for TMI to explain release of 20-40% total core inventory of fission gas
REST, J Argonne National Laboratory 79/04/16 2pp
- 7905110351 Discusses max steady-state clad temp reached in TMI after voiding Any means of assuring moderate flow of steam should have prevented serious rod damage
MARINO, G P Fuel Behavior Branch 79/04/04 3pp
- 7905110363 Discusses preliminary calculations for outside limits of possible core damage Believes 25-35% core damage near ctr is upper limit at 18 hours transient
BECKNER Division of Reactor Safety Research 79/04/06 2pp
- 7905210057 Notifies NRC investigative team is onsite & available for private meetings by appointment
MAR5CH, R Region 3, Chicago, Office of the Director 79/04/25 2pp
- 7905230189 Recommends actions to be taken in case of work delays due to conflict of std operating procedures
MULLEARY, T Metropolitan Edison Co 79/04/25 2pp
- 7905230194 Summary of 790425 meeting w/DOE re future support of NRC operations at site
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/25 1p
- 7905300098 Forwards list of communications equipment sent to TMI that cannot be properly accounted for Requests identification of custodian of property during tour of duty at Trailer City
JONES, J O Telecommunications Branch 79/04/25 3pp
- 7905090240 In response to 790419 memo, forwards assessment of impact of TMI-2 on ofc resources
RYAN, R O Office of State Programs 79/04/26 9pp
- 7905110275 Documents supply of emergency instrumentation at TMI site to collect air samples & measure radioactivity
SHANBERG, F. Environmental Effects Research Branch 79/04/26 2pp
- 7905110304 Forwards proposed mods on supplis to LV Cassick 790420 memo re actions re TMI
DAVIDSON, E Office of Nuclear Regulatory Research 79/04/26 8pp
- 7905140035 Discusses 790330-0408 actions while part of NRC team at TMI Duties involved review of handling of accident & radwaste & gathering of info re plant sys status from logs & personnel
BELL, M J Assistant Director for Waste Management (Pre 790501) 79/04/26 2pp
- 7905160028 Forwards record of actions involving NMSS staff which are not logged in Incident Response Ctr
BROWN, R S Office of Nuclear Material Safety & Safeguards 79/04/26 1p
- 7905160029 Comments on rept on hydrogen solubility database & estimated hydrogen releases at TMI
PERSON, L S. Fuel Reprocess & Recycle Branch 79/04/11 3pp
- 7905160036 Discusses actions of group working on radwaste sys at TMI Licensee procedures for handling radioactive wastes generated by accident are under review.
BELL, M J Low Level Waste Branch (Pre 790501) 79/05/10 1p
- 7905230202 Rept of activities on 790329 at site, initial assignment
COLLINS, D. M. Region 2, Atlanta, Office of the Director 79/04/26 2pp
- 7905300108 Responds to questions of C Kepford re radiation releases at TMI No info substantiating claim of 0.5 millirems/hour 30 miles upwind from TMI TLDs have been limited, but calibr sensitivity to beta radiation
SMITH, O H Region 1, Philadelphia, Office of the Director 79/04/26 2pp
- 7905110273 Summarizes Branch actions associated w/TMI accident
SOLBERG, D E Systems Performance Branch 79/04/27 1p
- 7905220412 Discusses health physics coverage for transition to natural circulation, both offsite & onsite
BNIEZEK, J H Office of Inspection & Enforcement 79/04/27 1p
- 7905210308 Recommends procedure for badging NRC employees
SMITH, O Office of Inspection & Enforcement 79/04/28 3pp
- 7905220450 Provides data re sys/component & instrument operability status
WILBER, M Office of Inspection & Enforcement 79/04/28 3pp
- 7905210273 Forwards Revision 1 of procedure for badging NRC employees
SMITH, O H Region 1, Philadelphia, Office of the Director 79/04/29 4pp
- 7905230316 Forwards liquid discharge data for 790410-28
KINNEY, W Office of Inspection & Enforcement 79/04/29 5pp
- 7905230523 Forwards info re sys/component operability status
GRIMES, B Assistant Director for Engineers & Projects 79/04/29 10pp
- 7905110279 "Generic Considerations of TMI-2 Incident "
* Office of Nuclear Reactor Regulation 79/04/30 5pp
- 7905110319 Input for items needed for requalification of TMI Discusses decontamination, insp of primary coolant sys & type of water chemistry
MUSCARA, J Office of Nuclear Regulatory Research 79/04/30 2pp
- 7905140051 Suggests proposed Westinghouse decay heat removal sys design be modified to better prevent sys leakage Flanged connections should be welded & sealed pumps should be used
* Office of Nuclear Reactor Regulation. 79/04/30 3pp
- 7905160008 Summary of reactor decommissioning study
* Commission 79/04/30 6pp
- 7905210299 Transition of IE in-house health effort to normal regulatory position
SMITH, O H Office of Inspection & Enforcement 79/04/30 2pp
- 7905230103 Chart of review committee responsibilities
* OPU Service Corp 79/04/30 1p
- 7905230527 Forwards results of analysis of addl liquid discharge data
PERROTTI, D Science Applications, Inc 79/04/30 15pp
- 7905090243 Informs that Joint Chiefs of Staff assigned nickname "Ivery Purpose" to operations in support of TMI incident
OOSBICK, L V Office of the Executive Director for Operations. 79/05/01 1p
- 7905090337 Forwards "Preliminary Licensing Rept for Westinghouse Decay Heat Removal Sys " Final rept will follow
HERBEIN, J O Metropolitan Edison Co. 79/05/01 1p
- 7905090339 "Preliminary Licensing Rept for Westinghouse Decay Heat Removal Sys "
* Westinghouse Electric Corp. WP-TMI-003. 79/05/01 27pp
- 7905190118 Agenda for 790420-0501 planning meetings
* Office of Nuclear Reactor Regulation. 79/05/01 131pp.
- 7905300352 Discusses telcons for 3-day period following TMI-2 incident.
ROBERT, A. W Region 5, San Francisco, Office of the Director 79/05/01 1p
- 7905210018 Discusses plans for epidemiology followup studies on populations exposed during TMI-2 event Contractor will be selected soon.
MINOQUE, R B. Office of Standards Development. 79/05/02 2pp

DOCKETED ITEMS

- 7905090320 Notifies that submission of final rpt re impingement/entrainment monitoring program at THI will be delayed to 790715
MELBISH, J F , TROFFER, O J Metropolitan Edison Co 79/05/03 1p
- 7905140052 Summarizes 790328 telcon from C Heath of Ctr for Disease Control re ctr's role in responding to THI incident Forwards summary of subsequent telcon w/K Gollier
ROBERTS, I C Assistant Director for Siting Standards 79/05/03 1p
- 7905300053 Details agenda of Natl Conference of State Legislatures, Energy & Resources Committees/ 790517 presentation to Congress re THI
SCHWARTZ, G A Office of State Programs 79/05/04 1p
- 7905140267 Forwards analysis results for sample of primary coolant water from THI.
OVERMAN, R F E I du Pont de Nemours & Co, Inc 79/05/07 3pp
- 7905230479 FR notice of ACRS 790510-12 meeting in Washington, DC to discuss repts on THI accident
CHILK, B J Office of the Secretary of the Commission 79/05/07 8pp
- 7905090236 Proposes temporary freeze on any new CP or DL & assessment of ongoing const projects Forwards draft instructions from BJ Chilk to HR Denton
HENDRIE, J M Commission 79/05/08 3pp
- 7905110277 "Pictorial Representation of Second Semicircle Relief Valve Venting Test from THI Conditions"
* Office of Nuclear Regulatory Research 79/05/10 6pp
- 7905160002 Plant computer print-out for 790328
* Probabilistic Analysis Branch 79/05/10 16pp
- 7905160003 Miscellaneous notes on various Commission meetings
GIBBON, T Commission 79/05/10 15pp
- 7905160007 Miscellaneous notes re THI
CAMPBELL, M Commission 79/05/10 34pp
- 7905160042 Various sheets for updating Mar 1978 Yellow Book
* Commission 79/05/10 5pp
- 7905160049 Commission meeting notes for 790328-31
GIBBON, T R Commission 79/05/10 71pp
- 7905160059 Various sheets for updating Feb 1978 Gray Book to Feb 1979
* Commission 79/05/10 33pp
- 7905300300 "Population Dose & Health Impact of Accident at THI Nuclear Station"
BATTIST, L, BUCHANAN, J, CONGEL, F Commission NUREG-0558 79/05/10 104pp
- 7905160064 Lists info required re Battelle Columbus Lab analysis
CUNNINGHAM, M Probabilistic Analysis Branch 79/05/11 1p
- 7905160139 Discusses definition of THI-2 event in nomenclature of WASH-1400
CUNNINGHAM, M Probabilistic Analysis Branch 79/05/11 1p
- 7905160143 Questions natural circulation if main coolant pumps are lost
* Probabilistic Analysis Branch 79/05/11 1p
- 7905160149 Draft chronology of 790328 accident until core cooling restored
* Probabilistic Analysis Branch 79/05/11 3pp.
- 7905300433 Forwards rept "Recriticality Potential of THI-2 Core"
MARTITA, C R Transportation Branch 79/05/14 1p
- 7905300434 "Recriticality Potential of THI-2 Core."
MARTITA, C R Transportation Branch 79/05/14 22pp
- 7905190081 Comments on Special Operation Procedure Z-37.
* Office of Nuclear Reactor Regulation 79/05/17 1p.
- 7905210012 Amends Tech Specs to permit channel calibr currently required to be performed by 790429 to be extended up to 14 days following cold shutdown.
VOLLMER, R H Assistant Director for Site Analysis 79/05/17 1p
- 7905210049 Charts organizational responsibility in control room, sys, health physics & effluent sys
* Office of Nuclear Reactor Regulation 79/05/17 1p
- 7905210052 Requests assistance in locating documents re THI-2 incident for onsite reproduction Related manual page & sample documents which may be disclosed encl for guidance
ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/17 6pp.
- 7905230157 Discusses radiological consequences of operation of once-through steam generator B in solid mode
COLLINS, J T Effluent Treatment Systems Branch 79/05/17 4p
- 7905190168 Procedures for environ shift leaders re preparation of daily PNO
BYOHR, J P Office of Inspection & Enforcement 79/05/18 1p
- 7905190170 Procedures for environ shift leaders re daily TLD data
BYOHR, J P Office of Inspection & Enforcement 79/05/18 1p
- 7905210230 Discusses radiological assessment of operation of once-through steam generator B in solid mode Comments on radioactive matl inventory, leakage paths & effluents
COLLINS, J T Effluent Treatment Systems Branch 79/04/22 4p
- 7905210276 Discusses restrictions on use of masks w/cartridges during decontamination of auxiliary/fuel bldg
* Office of Inspection & Enforcement 79/05/18 1p
- 7905210284 Requests info re incident investigation
ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/18 5pp
- 7905230130 Notifies of amend to Tech Spec 4 3 3 4, adding 14 days to 790429 deadline for performance of channel calibr
VOLLMER, R H Assistant Director for Site Analysis 79/05/18 1p
- 7905210305 Results of analysis of Ag zeolite cartridges from three mobile labs
MONTGOMERY, D M Region 1, Philadelphia, Office of the Director 79/05/21 1p
- 7905210314 Recommends establishment of QA staff & delineation of responsibilities to ensure supervision re V Stello 790421 memo
KELLOGG, P J Office of Inspection & Enforcement 79/05/21 1p
- 7905210323 Forwards info from Bettis lab & GE re potential for radiolysis contributing oxygen to bubble over reactor core
* Office of Nuclear Reactor Regulation 79/05/21 7pp
- 7905230018 Forwards procedure production flow chart
PORTER, I Metropolitan Edison Co 79/05/21 2pp
- 7905230206 Reading file index for THI-2 incident
* Office of Nuclear Reactor Regulation 79/05/21 3pp
- 7905230212 Requests core coolability review in natural circulation w/ decay heat removal & review of Natl Lab work summary
ROSB, D F Assistant Director for Reactor Safety 79/05/21 1p
- 7905220445 Forwards background matl on NRC actions re B&W reactors since THI incident & DK Davis to EO Case memo re establishment of Task Group on Generic Review of Feedwater Transient in B&W-Designed Reactors.
EYSKONTT, G Commission 79/05/22 24pp
- G Inspection reports, IE Bulletins & correspondence
- 7905230385 IE Bulletin 78-07, "Protection Afforded by Air-Line Respirators & Supplied-Air Hoods."
* Region 1, Philadelphia, Office of the Director 78/06/12 3p
- 7905300122 Forwards proposed IE circular re interconnections of contaminated sys w/svc air sys used as source of breathing air. Circular describes 781004 leak from radwaste sys to breathing air source at Peach Bottom Unit 2.
ORIER, B H Region 1, Philadelphia, Office of the Director 79/01/25 3pp
- 7905010118 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/23 1p.

DOCKETED ITEMS

127

7905010047 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air " ORIER,B H Region 1, Philadelphia, Office of the Director 79/03/28 1p

7905010300 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin " ORIER,B H Region 1, Philadelphia, Office of the Director 79/03/30 2pp.

7905090257 Ack request to close plant in light of TMI events. Actions are being taken to reassess individual situations IE Bulletin 79-03 encl HENDRIE,J H Commission 79/04/02 12pp

7905090234 Requested investigation into scope, procedures, & current status of NRR & IE analysis of TMI is complete Task force organized to examine B&W reactors KENNEDY,A Office of Policy Evaluations 79/04/04 2pp

7904170040 IE Bulletin 79-05A, "Nuclear Incident at TMI-Suppl " W/ 790405 telegram from JM Hendrie to all B&W licensees * Office of Inspection & Enforcement 79/04/05 13pp

7905230016 Forwards temporary instruction 2595/02, "Insp Requirements to Review B&W Licensee Actions Taken in Response to IE Bulletin 79-05 & 79-05A " * Office of Inspection & Enforcement 79/04/06 8pp

7905190209 Discusses steps to be taken prior to returning TMI-2 to power operation IE bulletins, circulars, & info notices will be properly addressed HERBEIN,J O Metropolitan Edison Co 79/04/10 1p

7905110187 Forwards IE Bulletin, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident," & draft cover letters MOSELEY,N C Office of Inspection & Enforcement 79/04/11 3pp

7905110413 Forwards IE Bulletin 79-06B, "Review of Operation Errors & Sys Misalignments Identified During TMI Incident " MOSELEY,N C Division of Reactor Operations Inspections 79/04/13 3pp

7905190215 Discusses schedule for completing actions required by IE Bulletin 79-03 Search of procurement documents to determine use of specified welded pipe will be complete by 790831 HERBEIN,J O Metropolitan Edison Co 79/04/13 1p

7905210245 Forwards requested revision to development of policies & implementation programs for insp. STOKER,J P Region 1, Philadelphia, Office of the Director 79/04/16 4pp.

7905300192 Lists IE reactor operations shift organization, 790416-0423, re TMI-2 KEIMIG,R.R. Office of Inspection & Enforcement 79/04/16 1p.

7905210252 Amend 1 to NRC 790413 access list for IE personnel MCSGAR,J J Region 1, Philadelphia, Office of the Director 79/04/18 2pp

7905230334 Forwards IE Bulletin 79-06A Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident," list of licensees & CP holders receiving bulletin & sample information & action-required ltrs ORIER,B H Region 1, Philadelphia, Office of the Director 79/04/18 1p.

7905300063 Forwards proposed outline & draft scope paragraph for TMI investigation rept Requests review. ALLEN,J Region 1, Philadelphia, Office of the Director. 79/04/20 3pp

7905110184 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI," & draft cover ltrs. MOSELEY,N.C. Office of Inspection & Enforcement 79/04/21 3pp.

--7905110186 IE Bulletin 79-05B, "Nuclear Incident at TMI " W/extract of B&W 790420 communication encl * Office of Inspection & Enforcement. 79/04/21 8pp

7905140047 Suggests IE Bulletin 79-05B be dispatched for action by 790421 to all B&W reactors w/OL & by 790423 to facilities w/CP. Draft ltr to facilities encl. MOSELEY,N C. Division of Reactor Operations Inspections 79/04/21. 2pp.

--7905140053 Responds to 790418 ltr requesting advice on action needed on 790417 oral recommendations Recommendations involve all PWRs & careful study should precede any action CARBON,M W ACRS - Advisory Committee on Reactor Safeguards 79/04/20 2pp

7905090214 Forwards PNOs & IE bulletins re TMI incident COLLINS,H E Assistant Director for Emergency Preparedness 79/04/23 1p

--7905090217 Forwards NUREG-0553 std 790330 & requests comments by 790509 w/o encl RYAN,R O Office of State Programs 79/04/10 1p

7905300090 Submits draft response to 790411 ltr requesting permission to accompany inspectors during insp of nuclear reactor operated by Saxton Nuclear Experimental Corp in Saxton, PA Invitation must be extended by licensee BNYDER,O L Region 1, Philadelphia, Office of the Director 79/04/26 3pp

7905230326 Summary of 790504 site visit to TMI re plans for monitoring worker radiation exposure KNIGHTON,O Environmental Evaluation Branch 79/05/15 4pp

7905300151 File Index - IE 2B. * Office of Inspection & Enforcement 79/05/23 3pp

R Periodic operating reports & related correspondence

7905190223 Summary paper re B&W results for size & composition of bubble in reactor vessel, in response to NRC 790402 request ROY,D H Babcock & Wilcox Co 79/04/02 3pp

7905190194 Recommends log books for control room personnel as opposed to procedures outlined in L Gossick 790404 memo STELLIO,V. Division of Operating Reactors HATTSON,R J Division of Systems Safety ORIER,B.H Region 1, Philadelphia, Office of the Director 79/04/05 2pp

7905220461 Plant status info BRUNNER,E J Region 1, Philadelphia, Office of the Director 79/04/07 3pp

7904260272 Forwards summary of preliminary estimates of radioactivity releases as of 790407 As of midday 790409, population dose due to noble gases is estimated to be 2400 man-rems w/max individual exposure at less than 100 man-rems BARRETT,L H Environmental Evaluation Branch 79/04/12 20pp

7905210032 Rept update of environ monitoring data for 790409 to 790412 * Energy, Dept of 79/04/12 4pp

7905160135 Forwards monthly operating report for Mar 1979 HERBEIN,J O Metropolitan Edison Co. 79/04/18 1p

--7905160380 Monthly operating rept for Mar 1979. LEGEL,R.A Metropolitan Edison Co 79/04/18 4pp

7905020155 Forwards "Decay Heat Removal During Very Small Break LOCA for B&W 205 Fuel Assembly PWR," prepared for TVA MCKINLEY,J C. ACRS - Advisory Committee on Reactor Safeguards 79/04/20 1p.

--7905020159 "Decay Heat Removal During Very Small Break LOCA for B&W 205 Fuel Assembly PWR," preliminary copy MCKINLEY,J C. ACRS - Advisory Committee on Reactor Safeguards 79/04/21 26pp

DOCKETED ITEMS

- 7905210060 Requests assistance in responding to questions proposed at meeting w/Commission for Advancement for Public Interest Organizations
HIGENBOTHAM, L Division of Fuel Facility & Materials Safety
79/04/25 1p
- 7905210062 Describes testing conditions used by NBS for thermoluminescence dosimeters to radiation per NRC request
Blank TMI waste shipment log encl
EISENHOWER, E H Commerce, Dept of 79/04/20 1p
- 790503033B Forwards monthly operating rept for Mar 1979 w/o encl
TROFFER, P J Metropolitan Edison Co 79/04/27 1p
- 7905080521 Forwards "Environ Operating Rept 1978," "Hydraulic Survey, June 1978," & "Monitoring of Cooling Tower Operation Effects on Vegetation in Vicinity of TMI, 1978"
HERBEIN, J O Metropolitan Edison Co 79/05/01 2pp
- 7905080926 "Environ Operating Rept 1978"
* Metropolitan Edison Co 79/04/30 18pp
- 7905080928 "Hydraulic Survey, June 1978"
* Metropolitan Edison Co 79/06/31 15pp
- 7905080931 "Monitoring of Cooling Tower Operational Effects on Vegetation in Vicinity of TMI-2, 1978"
* Metropolitan Edison Co 78/12/31 41pp
- S Reportable occurrences, LERs & related correspondence
- 7905090231 LER 78-029/03L-0 on 780415 ventilation damper D-409B did not close as required upon receipt of high chlorine signal
Caused by improperly adjusted damper linkage
* Metropolitan Edison Co 78/09/10 1p
- 7905160150 Info re emergency situation & investigation
LAFLEUR, J D Office of International Programs 79/03/28 3pp
- 7905110203 Board notification Seabrook refueling water storage tank design deficiency
SCINTO, J Hearings Division 79/03/29 30pp
- 7905160093 Provides preliminary unclassified info re incident
LAFLEUR, J D Office of International Programs 79/03/29 3pp
- 7905160156 Suppl info re TMI emergency situation for dispatch abroad
LAFLEUR, J D Office of International Programs 79/03/29 4pp
- 7905160196 Provides details of plant & environ status as of 790330 Unit 2 continuing to remove decay heat through A-loop steam generator using one reactor
LAFLEUR, J D Office of International Programs 79/03/30 6pp.
- 7905160193 Provides preliminary info re plant & environ status as of 790330 Gaseous radioactivity from primary coolant sys shutdown has been contained in waste gas decay tanks
LAFLEUR, J D Office of International Programs 79/03/31 4pp
- 7905160165 Provides details of plant & environ status as of 790331 for dispatch abroad
LAFLEUR, J D Office of International Programs 79/03/31 5pp.
- 7905160012 Preliminary plant status as of 790331 No change in method of cooling since last rept
LAFLEUR, J D Office of International Programs 79/04/01 4pp
- 7905160211 Summary of info re nuclear incident as of 7 AM 790401 Describes plant & environ status
LAFLEUR, J D Office of International Programs 79/04/01 5pp
- 7905160011 Preliminary info re plant status as of 790402 Measurements indicate vol of gases within bubble significantly reduced
LAFLEUR, J D Office of International Programs 79/04/02 3pp
- 7905160010 Preliminary info re plant status as of 790403 Reactor pressure remains at 1,000 psi w/bulk cond & coolant temp at 280 F
LAFLEUR, J D Office of International Programs 79/04/03 2pp.
- 7905160178 Summary of info re nuclear incident as of 790403 Reactor pressure remains near 1,000 psi w/bulk core coolant inlet & outlet temperatures at 280 F
LAFLEUR, J D Office of International Programs 79/04/03 3pp
- 7905300085 Discusses release of preliminary notices on TMI-2 & staffing of executive mgt team of NRC operations ctr
ODSSICK, L V Office of the Executive Director for Operations
79/04/03 3pp
- 7905300089 Forwards results of preliminary radiological impact analysis of TMI incident
ODSSICK, L V Office of the Executive Director for Operations
79/04/03 12pp
- 7905160035 Summary of preliminary info re nuclear incident as of 790404 Cooling path to remove core decay heat continues to be through A-loop steam generator
LAFLEUR, J D Office of International Programs 79/04/04 2pp
- 7905160214 Summary of info re nuclear incident as of 7 AM 790404 Describes plant & environ status
LAFLEUR, J D Office of International Programs 79/04/04 3pp
- 7905300096 Discusses possible determination of extraordinary nuclear occurrence at TMI-2
KENNEDY, R T Commission 79/04/04 1p
- 7905160009 Preliminary info re plant status Containment atmosphere measurements indicate about 2% hydrogen
LAFLEUR, J D Office of International Programs 79/04/05 4pp
- 7905160181 Provides details of plant & environ status
LAFLEUR, J D Office of International Programs 79/04/05 4pp
- 7905140055 Forwards excerpts of LERs re feedwater related & other transients at B&W facilities other than TMI Related correspondence encl
ORNSTEIN, H L Office of the Executive Director for Operations
79/04/06 18pp
- 7905140067 PHD-79-91 vapor binding of shutdown cooling sys purg
790314 Suction restored; no radioactive matl released to environ
KILINGER, G J, NOLAN, F, BRYAN, S E Office of Inspection & Enforcement 79/04/23 1p
- 7905160066 Summary of info re incident as of 790406 Reactor continues stable shutdown Will forward IE Bulletin 79-05A
LAFLEUR, J D Office of International Programs 79/04/06 2pp
- 7905160188 Provides details of plant status as of 790406 Reactor continues stable shutdown heat removal cooling at 1,075 psi, using one primary coolant pump & one steam generator
LAFLEUR, J D Office of International Programs 79/04/06 3pp
- 7905140110 Provides preliminary chronology of NRC actions in connection w/TMI Forwards description of events, generic considerations, summary of surveys, health effects & insp.
ODSSICK, L V Office of the Executive Director for Operations
79/04/09 52pp
- 7905160121 Preliminary chronology of TMI incident on 790328 & subsequent status through 790407
* Commission 79/04/09 6pp
- 7905160195 Provides details of plant status as of 790410, including evacuation & environ status
LAFLEUR, J D Office of International Programs 79/04/10 3pp
- 7905110200 PNO-79-78 facility shutdown on 790410 due to feedwater regulating valve malfunction which caused reactor to trip as result of low steam generator water level.
NOLAN, F, BRYAN, S E Office of Inspection & Enforcement 79/04/11 1p
- 7905190231 Discusses schedule for repts re 790328 event & follow up. Because of incident & corrective actions involved, details will be delayed until 790515
HERBEIN, J O Metropolitan Edison Co. 79/04/11 1p
- 7905300407 Reviews TMI-2 incident. Requests that TMI-related info be sent to NRC contracts in host govt
LAFLEUR, J D Office of International Programs. 79/04/11 2pp
- 7905300187 Discusses IE responsibility for drafting daily preliminary notice re TMI status Suggests procedures be established to ensure necessary info is available for input
ORIER, B H Region 1, Philadelphia, Office of the Director
79/04/16 1p

DOCKETED ITEMS

129

7905090227 "LER Output on events at TMI-1 & TMI-2 from 1969 to Present"
* Health, Education & Welfare, Dept of 79/04/18 83pp

7905100388 Forwards PNO-79-67X & Y related to TMI-2 incident W/o encl
VASSALLO, D B Assistant Director for Light Water Reactors
79/04/20 1p

--7905100389 Forwards PNO-79-67U, V & W related to TMI-2 incident
W/o encl
VASSALLO, D B Assistant Director for Light Water Reactors
79/04/17 1p

--7905100390 Forwards PNO-79-67G, R, S & T related to TMI-2 incident
W/o encl
VASSALLO, D B Assistant Director for Light Water Reactors
79/04/13 1p

--7905100392 Suppl 790403 memo re submittal of info on TMI-2 Forwards
PNO-67I, J, K, L, M, N & P W/o encl
VASSALLO, D B Assistant Director for Light Water Reactors
79/04/09 1p

--7905100395 Recommends available info re TMI-2 incident be provided to
Boards considering cases involving B&W reactors
VASSALLO, D B Assistant Director for Light Water Reactors
79/04/03 2pp

7904300484 Forwards PNO-79-67AE
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/24 1p

7905020230 PNO-79-67AF summary of info re nuclear incident as of
790425 Describes plant status & environ status Highest
thermocouple reading 312 F
* Office of Inspection & Enforcement 79/04/25 5pp

7905020260 PNO-79-67AG summary of info re nuclear incident as of
790426 Describes plant status & environ status Highest
incore temp reading is 311 F
PAULUS, R C, THOMPSON, D Office of Inspection & Enforcement
79/04/26 2pp

7905040391 Forwards PNO-79-67AC
GEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/26 1p

--7905040406 PNO-79-67AE summary of info re nuclear incident as of
790424 Describes plant & environ status
* Office of Inspection & Enforcement 79/04/24 3pp

7905040296 PNO-79-67AH summary of info re nuclear incident as of
790427 Describes plant & environ status Highest incore temp
310 F Offsite radiation consistent w/background levels
PAULUS, R C, THOMPSON, D Office of Inspection & Enforcement
79/04/27 2pp

7905300410 Requests info re TMI followup be forwarded to official NRC
contacts in host governments & visiting senior US officials
LAFLEUR, J D Office of International Programs 79/04/27 2pp

7905300415 Requests info re TMI natural circulation cooling be
forwarded to official NRC contacts in host governments &
visiting senior US officials
LAFLEUR, J D Office of International Programs 79/04/28 2pp

7905040262 PNO-79-67AJ summary of info re nuclear incident as of
790429 Describes plant & environ status Highest incore temp
320 F Offsite radiation consistent w/background levels
CHAPELL, D Office of Inspection & Enforcement 79/04/29 2pp

7905040359 Forwards PNO-79-67AI, AJ & AK per NRC 790401 ltr transmitting
IE Bulletin 79-05
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/30 1p

--7905040360 PNO-79-67AI summary of info re nuclear incident as of
790428 Describes plant & environ status
* Office of Inspection & Enforcement 79/04/28 2pp

--7905040365 PNO-79-67AK summary of info re nuclear incident as of
790429 Describes plant & environ status
* Office of Inspection & Enforcement 79/04/30 2pp

7905040358 PNO-79-67AL summary of info re nuclear incident as of
790501 Describes plant & environ status
* Office of Inspection & Enforcement 79/05/01 3pp

7905140253 PNO-79-67AM summary of info re nuclear incident as of
790507 Describes operational & environ status Environ
radiation levels consistent w/natural background
PAULUS, R C, THOMPSON, D Office of Inspection & Enforcement
79/05/07 2pp

7905110251 Lists chronology of personnel-related events
* Office of Nuclear Reactor Regulation 79/05/10 1p

7905230198 PNO-79-67AN summary of info re nuclear incident as of
790514 Describes operational & environ status highest incore
temp 308 F, pressure maintained at 650 psi Environ radiation
consistent w/background levels
* Office of Inspection & Enforcement 79/05/14 2pp

7905300250 "LER Output on Events of TMI-2 from 1969 to Present" output
sorted by facility & event date
* Office of Inspection & Enforcement 79/05/18 20pp

T Hearing transcripts on non-antitrust matters

7905020024 Transcript of 790409 update briefing on TMI-2 Pp 1-217
HENDRIE, J M, OILINSKY, V, KENNEDY, R T Commission 79/04/05
200pp

7905190251 PA Governor D Thornburgh's press conference on 790409 re
TMI incident
THORNBURGH, D Pennsylvania, State of 79/04/09 13pp

7905020046 Transcript of 790417 joint meeting w/ACRS in Washington, DC
Pp 1-22
HENDRIE, J M, OILINSKY, V, KENNEDY, R T Commission 79/04/17
23PP

7905020163 Transcripts of 790417 press conference on TMI in Middletown,
PA Pp 1-20
FOUCHARD, J J Office of Public Affairs DENTON, H R Office of
Nuclear Reactor Regulation 79/04/17 20pp

7905210069 Agenda for 790417 planning meeting re "Top Priorities" list;
action items from 790416 technical review meeting, 790417
tasks lists & review schedules
* Office of Nuclear Reactor Regulation 79/04/17 14pp

7905140339 FOIA request for transcript of NRC deliberations occurring
in aftermath of Harrisburg incident
PERDUE, W D Eastern Washington Univ 79/04/18 1p

7905080125 Transcript of 790420 briefing in Washington, DC on procedures
for qualifying reactor operators Pp 1-90
OILINSKY, V, KENNEDY, R T, BRADFORD, P A Commission 79/04/20
200pp

7905030055 Transcript of 790423 open meeting in Washington, DC for
briefing on principal factors re current status of operating
plants Pp 1-84
HENDRIE, J M, OILINSKY, V, KENNEDY, R T Commission 79/04/23
85pp

7905140065 Statement of WQ Kuhns, Chairman of General Public Utilis Corp,
before Subcommittee on Nuclear Regulation of Senate
Committee on Environ & Public Works
KUHN, W Q General Public Utilities 79/04/23 14pp

--7905140072 Statement of M Bancroft, Public Citizen Litigation Group
before Senate Subcommittee on Nuclear Regulation dtd 790423
BANCROFT, M Public Citizen Litigation Group 79/04/23 14pp

--7905140090 Statement by JT Conway, President, American Nuclear Energy
Council before Subcommittee on Nuclear Regulation, Senate
Committee on Environ & Public Works
CONWAY, J T American Nuclear Energy Council 79/04/23 13pp

--7905140094 Statement of AZ Roisman, NRDC Atty, before Subcommittee on
Nuclear Regulation of Senate Public Works Committee
ROISMAN, A Z Natural Resources Defense Council 79/04/23 12pp

7905140092 Statement of D Thornburgh, Governor of PA, before Senate
Subcommittee on Nuclear Regulation
THORNBURGH, D Pennsylvania, State of 79/04/23 9pp

7905020128 Transcript of 790424 press briefing on TMI in Middletown, PA
Pp 1-26
WISNER, C Region 4, Dallas, Office of the Director STELLO, V
Office of Nuclear Reactor Regulation, VOLLMER, R H Assistant
Director for Site Analysis 79/04/24 26pp

DOCKETED ITEMS

7905030212 Transcript of 790427 press conference in Middletown, PA
Pp 1-25
STELLO, V Division of Operating Reactors 79/04/27 26pp

7905030210 Transcript of 790430 Ad Hoc Subcommittee on TMI Incident in
Washington, DC. Pp 1-360
OKRENT, D., CARBON, M. W., SIESS, C. ACRS - Advisory Committee on
Reactor Safeguards 79/04/30 361pp.

7905100032 Transcript of 790501 Ad Hoc Subcommittee on TMI Incident
meeting in Washington, DC. Pp 1-544
OKRENT, D., CARBON, M. W., SIESS, C. ACRS - Advisory Committee on
Reactor Safeguards 79/05/01 183pp

7905190233 Transcript of 790503 briefing on offsite radiation levels
at TMI & radiological assistance program Pp 1-67
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission 79/05/03
68pp

7905100034 Transcript of 790507 press briefing in Middletown, PA
STELLO, V Division of Operating Reactors VOLLMER, R. H.
Assistant Director for Site Analysis 79/05/07 30pp

7905220459 Forwards transcripts of interviews w/TMI-2 operators at time
of incident
TROUBRIDGE, G. F. Shaw, Pittman, Potts, & Trowbridge, 79/05/07
63pp

7905140537 Response to FOIA request for transcripts of NRC closed
meetings re Harrisburg incident Gives price list of
transcripts available in PDR
FELTON, J. M. Division of Rules and Records 79/05/09 1p

7905190235 Transcript of ACRS Ad Hoc Subcommittee 790509 on TMI-2
meeting Pp 1-309
OKRENT, D., CARBON, M. W., EYERINGTON, H. ACRS - Advisory Committee on
Reactor Safeguards 79/05/09 310pp

7905190127 Transcript of 790510 public meeting re Pp 1-129 W/copies of
presentation transparencies.
HENDRIE, J. M., GILINSKY, V., KENNEDY, R. T. Commission 79/05/10
157pp.

7905220451 Responds to 790514 memo Advises that transcripts of
interviews w/TMI-2 operators have been submitted to PDR &
Off of Congressional Affairs.
CORNELL, E. K. Office of the Executive Director for Operations
79/05/17 1p.

--7905220455 Forwards OF Trowbridge to E Case 790507 ltr submitting
transcript of interviews w/TMI-2 operators Transcripts will
be considered in IE investigation of accident
MATTHEW, R. J. Division of Systems Safety, 79/05/14 1p

DOCKET 50-321 EDWIN I. HATCH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

7905150089 Responds to 790302 ltr reporting reasons for delays on
implementing 10CFR73.55 requirements & describing
compensatory measures provided to meet these requirements
Measures are acceptable.
BFOULI, T. A. Operating Reactors Branch 3, 79/04/18 2pp

I Financial information

7905080497 Forwards "Annual Financial Rept 1978"
VABOUEZ, R. D. Metropolitan Electric Authority of Georgia 79/05/02
1p.

--7905080508 "Annual Financial Rept 1978"
Metropolitan Electric Authority of Georgia 78/12/31. 24pp

7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1, 25, 43, 74, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 178, 179, 180, 182, 183, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHI, J. American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies NF-22, 26, 27, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01
1p.

7905080427 Forwards Amend 10 to Indemnity Agreement B-69
WHITHER, C. F. Georgia Power Co 79/05/01. 3pp.

7905140493 Forwards Amend 11 to Indemnity Agreement B-69 per 10CFR
changes, re increase in liability insurance from \$140 million
to \$160 million, effective 790501. Supporting documentation
encl
SALTZMAN, J. Antitrust & Indemnity Group 79/05/01 6pp

7905080430 Forwards Endorsement 49 to NELIA Policy NF-213
FIELDER, J. Marsh & McLennan, M & H Nuclear Consultants, Inc Div
79/05/03 2pp

7905080432 Forwards Endorsement 50 to NELIA Policy NF-213
FIELDER, J. Marsh & McLennan, M & H Nuclear Consultants, Inc Div
79/05/03 2pp

P Operating license stage documents & correspondence

7905070569 Responds to 790319 ltr questioning license amend fee
requirement for 781221 application Fees paid are justified
MILLER, W. D. License Fee Management Branch 79/04/05 1p.

7905190213 Amends 790332 submittal of Tech Spec changes in support of
Reload 3 licensing application Class IV amend fee encl
WHITHER, C. F. Georgia Power Co 79/05/11 32pp.

7905170234 Forwards schedule for implementation & resolution of Marl
containment long-term program Only vent header deflectors
are necessary as major mod for conformance to long-term
program acceptance criteria
WHITHER, C. F. Georgia Power Co 79/05/14 4pp

7905190039 Forwards proposed amend to Tech Specs re turbine control
valve fast closure trip setpoint
WHITHER, C. F. Georgia Power Co 79/05/14 5pp

7905230047 Forwards Errata & Addenda Sheet 1 to NEDO-24175,
"Supplemental Reload Licensing Submittal for Edwin I Hatch
Unit 1, Reload 3."
WHITHER, C. F. Georgia Power Co 79/05/16 4pp

7905230538 Responds to D Verrilli's request for addl info re add of
feedwater nozzle & sparger OE licensing rept NEDE-21821, dtd
Mar 1978, provides discussion of causes & proposed solutions
to cracking problems in BWRs
WHITHER, C. F. Georgia Power Co 79/05/16 1p

7905300006 Requests change to Tech Spec App A to OL modifying
Surveillance Requirement 4.9 D due to incorporation of
redundant breaker on output of reactor protection sys motor
generator sets
WHITHER, C. F. Georgia Power Co 79/05/22 5pp

Q. Inspection reports, IE Bulletins & correspondence

7905010200 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/23 2pp

7905020489 Forwards IE Insp Repts 50-321/79-09 & 50-366/79-11 re
790210-0302 No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Branch
Branch, 79/03/23 2pp.

--7905020497 IE Insp Repts 50-321/79-09 & 50-366/79-11 on 790210 (3)
noncompliance noted Major areas inspected, Unit 1 plant
operations, Unit 2 startup testing, Tech Specs compliance,
reportable occurrences & Unit 2 transient test witnessing
ROBERTS, R. F. Region 2, Atlanta, Office of the Director
BANCHE, H. C. Region 2, Atlanta, Reactor Operations Nuclear
Support Branch 79/03/23 4pp.

7905030312 Forwards IE Info Notice 79-07, "Rupture of Radwaste Isolation
Piping"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/26. 2pp

7905010107 Forwards IE Info Notice 79-08, "Interconnection of
Contaminated Sys w/Bvc Air Sys Used as Source of Breathing
Air."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/28 2pp

7905010360 Forwards IE Info Notice 79-09, "Spill of Radioactive
Contaminated Resin"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/30. 2pp

7905230098 Requests page 6 of IE Insp Repts 50-321/79-08 & 50-366/79-11
be replaced w/encl corrected page.
MILLER, J. H. Georgia Power Co. 79/04/04 2pp.

DOCKETED ITEMS

131

- 7905250105 Forwards IE Insp Repts 50-321/79-06 & 50-366/79-07 on 790214-16 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear -
Support Branch 79/03/21 2pp
- 7905250110 IE Insp Repts 50-321/79-06 & 50-366/79-07 on 790214-16 No noncompliance noted Major areas inspected plant operations, followup of unresolved items, LERs & test witnessing
DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear
Support Branch HINCKLEY, D O Region 2, Atlanta, Office of the Director 79/03/21 8pp
- 7905040216 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp
- 7905040304 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p
- 7905040413 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p.
- 7905100244 Responds to IE Bulletin 79-03 No evidence of Youngstown Welding & Engineering seam welded ASME SA-312 Type 304 stainless steel piping is being used in safety-related sys ASME SA-398 Type 304 spool is used
STAFFA, R W Georgia Power Co 79/04/16 1p
- 7905030165 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp
- 7905020467 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp
- 7905290029 Responds to IE Bulletin 79-08 Addresses events relevant to BWRs identified during TMI incident Response to Item 11 will be forwarded in 30 days
WIDNER, W A Georgia Power Co 79/04/25 15pp
- 7905300309 Responds to IE Bulletin 79-04, Review of design records indicates there are no 3, 4 or 6-inch diameter Veian swing check valves used at facility
STAFFA, R W Georgia Power Co. 79/05/02 1p
- 7905290035 Forwards revised responses to IE Bulletin 79-08, "Events Relevant to BWRs Identified During TMI Incident" Replaces previous 790425 submittal (mentioned as 790415 in present ltr) Includes response to Item 11
WIDNER, W A Georgia Power Co 79/05/09 16pp.
- B Reportable occurrences, LERs & related correspondence**

- 7905140316 Notifies that LERs 50-366/1979-27 & 50-321/1979-16 have been voided They were later determined to be not reportable
MANRY, M Georgia Power Co 79/03/13 1p
- 7905010502 LER 50-321/1979-22 has been voided. Rept will be incorporated into LER 79-23
MANRY, M. Georgia Power Co. 79/04/19 1p
- 7905080546 Forwards LER 79-023/03L-0
MANRY, M. Georgia Power Co 79/04/24 1p.
- 7905080550 LER 79-023/03L-0 on 790410 during steady state operation: "HPCI isolation trip logic A initiated" alarm received, closing inboard isolation valve E41-F002 Caused by high delta temp in HPCI room Sys reset
GREENE, T V Georgia Power Co 79/04/24 2pp
- 7905080473 Forwards LER 79-021/03L-2
MANRY, M. Georgia Power Co 79/04/30 1p.
- 7905080479 LER 79-021/03L-2 on 790320 during steady state power operation, radioactive water observed bubbling from ground near diesel generator bldg. Caused by burned open line. Line closed immediately
ROGERS, W. H Georgia Power Co 79/04/30 8pp.
- 7905080520 Forwards LER 79-023/03L-0.
MANRY, M. Georgia Power Co 79/04/30 1p.
- 7905080524 LER 79-023/03L-0 on 790427 during steady state power operation, H202 analyzer pumps were inoperative Caused by incomplete HNP-1-3653 procedure Procedure will be revised by 790701
BAXLEY, S X Georgia Power Co 79/04/27 1p
- 7905150519 Forwards LER 79-026/03L-0
MANRY, M Georgia Power Co 79/05/07 1p
- 7905150523 LER 79-026/03L on 790422 while performing procedure HNP-1-3111, valves B21-F028A & B21-F028B closed too fast Caused by snubber adjustment drift Followup rept of corrective action will be sent
NIX, R T Georgia Power Co 79/05/07 1p
- 7905150543 Forwards LER 79-027/01T-0
MANRY, M Georgia Power Co 79/05/07 1p
- 7905150549 LER 79-027/01T-0 on 790427 initial tests of various Type C low level radiation test containment isolation valves proved unacceptable during local leak rate testing Caused by scratches on valve seat from valve closing on debris
GREENE, T V Georgia Power Co 79/05/07 2pp
- 7905300591 Forwards LER 79-024/03L-0
MANRY, M Georgia Power Co 79/05/18 1p
- 7905300603 LER 79-024/03L-0 on 790420 both doors of airlock R106 were opened simultaneously Caused by personnel error Glass installed to cover emergency override pushbuttons of both airlock doors
GREENE, T V Georgia Power Co 79/05/18 1p
- 7905300627 Forwards LER 79-028/03L-0
MANRY, M Georgia Power Co 79/05/17 1p
- 7905300638 LER 79-028/03L-0 on 790505 five containment isolation valves did not meet acceptance criteria during initial tests Cause under investigation Corrective maint will be performed to allow satisfactory leakage rate for valves
GREENE, T V Georgia Power Co 79/05/17 2pp
- 7905300644 Forwards LER 79-029/03L-0
MANRY, M Georgia Power Co 79/05/17 1p
- 7905300660 LER 79-029/03L-0 on 790505, door interlock defeated & both bldg airlock doors were open at same time Caused by personnel error Personnel retrained & engineering design is being reevaluated
BAXLEY, S X Georgia Power Co 79/05/17 1p
- 7905300664 Forwards LER 79-031/03L-0
MANRY, M Georgia Power Co 79/05/21 1p
- 7905300676 LER 79-031/03L-0 on 790508 main steam line tunnel temp switch B21-N011B opened at 203F Caused by setpoint drift Switch recalibr & functionally tested.
NIX, R T Georgia Power Co 79/05/21 1p
- 7905300683 Forwards LER 79-033/03L-0
MANRY, M Georgia Power Co 79/05/17 1p
- 7905300688 LER 79-033/03L-0 on 790508 air oper were improperly installed. Caused by insuffic installation info Maint procedures revised & installation
GREENE, T V. Georgia Power Co 79/05/17 2p
- DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION**

- A. Application/construction stage documents & co**

- 7905300656 Responds to 790320 memo re policy on meetings to public
DENTON, H R Office of Nuclear Reactor Regulat
- 7905300667 Requests NRC views on whether proce NRC & util representatives should be open to
BRADFORD, P A Office of Nuclear Reactor Reg 1p.
- 7905040316 Summary of 790321 meeting of Mark II Jose, CA re intermediate plant program tasks
ANDERSON, C J Containment Systems Branch

DOCKETED ITEMS

7905030212 Transcript of 790427 press conference in Middletown, PA
Pg 1-25
STELLID, V Division of Operating Reactors 79/04/27 26pp

7905030210 Transcript of 790430 Ad Hoc Subcommittee on TMI Incident in
Washington, DC Pg 1-360
OKRENT, D, CARBON, M W, BIESS, C ACRB - Advisory Committee on
Reactor Safeguards 79/04/30 361pp

7905100052 Transcript of 790501 Ad Hoc Subcommittee on TMI Incident
meeting in Washington, DC Pg 361-544
OKRENT, D, CARBON, M W, BIESS, C ACRB - Advisory Committee on
Reactor Safeguards 79/05/01 183pp

7905190233 Transcript of 790503 briefing on offsite radiation levels
at TMI & radiological assistance program Pg 1-67
HENDRIE, J M, QILINSKY, V, KENNEDY, R T Commission 79/05/03
68pp

7905100054 Transcript of 790507 press briefing in Middletown, PA
STELLID, V Division of Operating Reactors VOLLMER, R H
Assistant Director for Site Analysis 79/05/07 30pp

7905220459 Forwards transcripts of interviews w/TMI-2 operators at time
of incident
TROWBRIDGE, G. F Shaw, Pittman, Potts, & Trowbridge 79/05/07
63pp

7905140337 Response to FOIA request for transcripts of NRC closed
meetings re Harrisburg incident Gives price list of
transcripts available in PDR
FELTON, J M Division of Rules and Records 79/05/09 1p.

7905190235 Transcript of ACRB Ad Hoc Subcommittee 790509 on TMI-2
meeting Pg 1-309
OKRENT, D, CARBON, M W, ETHERINGTON, K ACRB - Advisory Committee on
Reactor Safeguards 79/05/09 310pp

7905190127 Transcript of 790510 public meeting re Pp 1-129 W/copies of
presentation transparencies
HENDRIE, J M, QILINSKY, V, KENNEDY, R T Commission 79/05/10
157pp.

7905220451 Responds to 790514 memo Advises that transcripts of
interviews w/TMI-2 operators have been submitted to PDR &
Ofc of Congressional Affairs.
CORNELL, E K Office of the Executive Director for Operations
79/05/17 1p

--7905220455 Forwards OF Trowbridge to E Case 790507 ltr submitting
transcript of interviews w/TMI-2 operators Transcripts will
be considered in IE investigation of accident
MATTBON, R J Division of Systems Safety 79/05/14 1p

DOCKET 30-321 EDWIN I HATCH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

7905150089 Responds to 790302 ltr reporting reasons for delays on
implementing 10CFR73.55 requirements & describing
compensatory measures provided to meet these requirements
Measures are acceptable.
IPPOLITO, T A Operating Reactors Branch 3. 79/04/18. 2pp.

I. Financial information

7905080497 Forwards "Annual Financial Rept 1978 "
VASQUEZ, R O Metropolitan Electric Authority of Georgia 79/03/02.
1p

--7905080508 "Annual Financial Rept 1978 "
* Metropolitan Electric Authority of Georgia 78/12/31 24pp.

7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 178, 179, 180, 182, 183, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHI, J. American Nuclear Insurers 79/03/01. 1p.

7905070382 Confirms increase in liability limit to \$36,000,000 for
policies NF-22, 28, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D H. Mutual Atomic Energy Liability Underwriters 79/03/01
1p.

7905080427 Forwards Amend 10 to Indemnity Agreement B-69
WHITNER, C. F. Georgia Power Co. 79/05/01. 3pp.

7905140493 Forwards Amend 11 to Indemnity Agreement B-69 per 10CFR316
changes; re increase in liability insurance from \$140 million
to \$160 million, effective 790501 Supporting documentation
encl
SALTZMAN, J Antitrust & Indemnity Group 79/03/01 6pp

7905080430 Forwards Endorsement 49 to NELIA Policy NF-215
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc Div
79/05/03 2pp

7905080432 Forwards Endorsement 50 to NELIA Policy NF-215
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc Div
79/05/03 2pp

F Operating license stage documents & correspondence

7905070669 Responds to 790319 ltr questioning license amend fee
requirement for 781221 application Fees paid are justified
MILLER, W O License Fee Management Branch 79/04/03 1p

7905190213 Amends 790322 submittal of Tech Spec changes in support of
Reload 3 licensing application Class IV amend fee encl
WHITNER, C F Georgia Power Co 79/05/11 32pp

7905170234 Forwards schedule for implementation & resolution of Unit 1
containment long-term program Only vent header deflectors
are necessary as major mod for conformance to long-term
program acceptance criteria
WHITNER, C F Georgia Power Co 79/05/14. 4pp

7905190039 Forwards proposed amend to Tech Specs re turbine control
valve fast closure trip setpoint.
WHITNER, C F Georgia Power Co 79/05/14 5pp

7905230047 Forwards Errata & Addenda Sheet 1 to NEDO-24175.
"Supplemental Reload Licensing Submittal for Edwin I Hatch
Unit 1, Reload 3."
WHITNER, C F Georgia Power Co 79/05/16 4pp.

7905230538 Responds to D Verrilli's request for addl info re addl
feedwater nozzle & sparger OE licensing rept NEDE-21821, dtd
Mar 1978, provides discussion of causes & proposed solutions
to cracking problems in BWRs
WHITNER, C F Georgia Power Co. 79/05/16. 1p

7905300006 Requests change to Tech Spec, App A to OL, modifying
Surveillance Requirement 4.9 D due to incorporation of
redundant breaker on output of reactor protection sys motor
generator sets
WHITNER, C. F Georgia Power Co 79/05/22 5pp

G Inspection reports, IE Bulletins & correspondence

7905010200 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping."
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/03/23. 2pp

7905020489 Forwards IE Insp Repts 30-321/79-09 & 30-366/79-11 re
790210-0302 No noncompliance noted
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 79/03/23 2pp

--7905020497 IE Insp Repts 30-321/79-09 & 30-366/79-11 on 790210-0302
noncompliance noted. Major areas inspected Unit 1 plant
operations, Unit 2 startup testing, Tech Specs compliance,
reportable occurrences & Unit 2 transient test witnessing
ROBERTS, R F Region 2, Atlanta, Office of the Director
DANCE, H C. Region 2, Atlanta, Reactor Operations Nuclear
Support Branch 79/03/23 4pp

7905030312 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/03/26 2pp.

7905010107 Forwards IE Info Notice 79-08, "Interconnection of
Contaminated Sys w/Bvc Air Sys Used as Source of Breathing
Air."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/28 2pp.

7905010360 Forwards IE Info Notice 79-09, "Spill of Radioactively
Contaminated Resin"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/30 2pp.

7905250098 Requests page 6 of IE Insp Repts 30-321/79-06 & 30-366/79-11
be replaced w/encl corrected page
MILLER, J. H. Georgia Power Co. 79/04/04. 2pp.

DOCKETED ITEMS

131

--7905250105 Forwards IE Insp Repts 50-321/79-06 & 50-366/79-07 on 790214-16 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/21 2pp

--7905250110 IE Insp Repts 50-321/79-06 & 50-366/79-07 on 790214-16 No noncompliance noted Major areas inspected plant operations, followup of unresolved items, LERs & test witnessing
DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch HINCKEY, D O Region 2, Atlanta, Office of the Director 79/03/21 8pp

7905040216 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp

7905040304 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905040413 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905100244 Responds to IE Bulletin 79-03 No evidence of Youngstown Welding & Engineering seam welded ASME SA-312 Type 304 stainless steel piping is being used in safety-related sys
ASME SA-358 Type 304 spool is used
STAFFA, R W Georgia Power Co 79/04/16 1p

7905030165 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp

7905020467 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp

7905290029 Responds to IE Bulletin 79-08 Addresses events relevant to BHRs identified during TMI incident Response to Item 11 will be forwarded in 30 days
WIDNER, W A Georgia Power Co 79/04/25 15pp

7905300309 Responds to IE Bulletin 79-04 Review of design records indicates there are no 3/4 or 6-inch diameter Valen swing check valves used at facility
STAFFA, R W Georgia Power Co 79/05/02 1p

7905290035 Forwards revised responses to IE Bulletin 79-08, "Events Relevant to BHRs Identified During TMI Incident" Replaces previous 790425 submittal (mentioned as 790413 in present ltr). Includes response to Item 11
WIDNER, W A Georgia Power Co. 79/05/09 16pp

8. Reportable occurrences, LERs & related correspondence

7905140316 Notifies that LERs 50-366/1979-27 & 50-321/1979-16 have been voided They were later determined to be not reportable
MANRY, M Georgia Power Co 79/03/13 1p

7905010502 LER 50-321/1979-22 has been voided Rept will be incorporated into LER 79-23
MANRY, M Georgia Power Co 79/04/19. 1p

7905080546 Forwards LER 79-023/03L-0
MANRY, M Georgia Power Co 79/04/24 1p

--7905080550 LER 79-023/03L-0 on 790410 during steady state operation, "HPCI isolation trip logic A initiated" alarm received, closing inboard isolation valve E41-F002 Caused by high delta temp in HPCI room. Sys reset.
GREENE, T V Georgia Power Co 79/04/24 2pp

7905080473 Forwards LER 79-021/03L-2
MANRY, M Georgia Power Co 79/04/30 1p.

--7905080479 LER 79-021/03L-2 on 790320 during steady state power operation, radioactive water observed bubbling from ground near diesel generator bldg. Caused by burned open line. Line closed immediately.
RODRIGUEZ, W H Georgia Power Co 79/04/30. 8pp.

7905080520 Forwards LER 79-025/03L-0.
MANRY, M. Georgia Power Co 79/04/30. 1p.

--7905080524 LER 79-025/03L-0 on 790427 during steady state power operation, H2O2 analyzer pumps were inoperative Caused by incomplete HNP-1-3653 procedure Procedure will be revised by 790701
BAXLEY, B X Georgia Power Co. 79/04/27 1p

7905150519 Forwards LER 79-026/03L-0
MANRY, M Georgia Power Co 79/05/07 1p

--7905150525 LER 79-026/03L on 790422 while performing procedure HNP-1-3111, valves B21-F02BA & B21-F02BB closed too fast Caused by snubber adjustment drift Followup rept of corrective action will be sent
NIX, R T Georgia Power Co 79/05/07 1p

7905150343 Forwards LER 79-027/01T-0
MANRY, M Georgia Power Co. 79/05/07 1p

--7905150549 LER 79-027/01T-0 on 790427 initial tests of various Type C low level radiation test containment isolation valves proved unacceptable during local leak rate testing Caused by scratches on valve seat from valve closing on debris
GREENE, T V Georgia Power Co 79/05/07 2pp

7905300391 Forwards LER 79-024/03L-0
MANRY, M Georgia Power Co 79/05/18 1p

--7905300603 LER 79-024/03L-0 on 790420 both doors of airlock R106 were opened simultaneously Caused by personnel error Glass installed to cover emergency override pushbuttons of both airlock doors
GREENE, T V Georgia Power Co 79/05/18 1p

--7905300627 Forwards LER 79-028/03L-0
MANRY, M Georgia Power Co 79/05/17 1p

--7905300638 LER 79-028/03L-0 on 790505 five containment isolation valves did not meet acceptance criteria during initial tests Cause under investigation Corrective maint will be performed to allow satisfactory leakage rate for valves
GREENE, T V Georgia Power Co 79/05/17 2pp

--7905300644 Forwards LER 79-029/03L-0
MANRY, M Georgia Power Co 79/05/17 1p

--7905300660 LER 79-029/03L-0 on 790505 door interlock defeated & both bldg airlock doors were open at same time Caused by personnel error Personnel retrained & engineering design is being reevaluated
BAXLEY, B X Georgia Power Co 79/05/17 1p

--7905300664 Forwards LER 79-031/03L-0
MANRY, M. Georgia Power Co 79/05/21 1p

--7905300676 LER 79-031/03L-0 on 790508 main steam line tunnel temp switch B21-N011D opened at 203F Caused by setpoint drift Switch recalibr & functionally tested
NIX, R. T Georgia Power Co. 79/05/21 1p

--7905300683 Forwards LER 79-033/03L-0.
MANRY, M Georgia Power Co 79/05/17. 1p

--7905300688 LER 79-033/03L-0 on 790508 air operators on 2B21-F01BA & C were improperly installed Caused by insufficient installation info Maint procedures revised to assure proper installation
GREENE, T V. Georgia Power Co. 79/05/17. 2pp

DOCKET

A. Appl

7905300656 Responds to 790320 memo re policy on opening procedural meetings to public
DENTON, H R. Office of Nuclear Reactor Regulation. 79/04/04 2pp.

--7905300667 Requests NRC views on whether procedural meetings between NRC & Util representatives should be open to public.
BRADFORD, P A Office of Nuclear Reactor Regulation 79/03/20. 1p

7905040316 Summary of 790321 meeting of Mark II owners group in San Jose, CA re intermediate plant program tasks.
ANDERSON, C J. Containment Systems Branch. 79/04/13 150pp.

DOCKETED ITEMS

7903100258 Summary of 790410 meeting w/Cincinnati Gas & Electric Co, Long Island Lighting Co & Commonwealth Edison Co re vibratory loads & equipment qualification Presentation matl encl
 PELTIER, I A Light Water Reactors Branch 1 79/04/19 15pp

7903230558 Notification of 790315-17 meeting w/Cincinnati Gas & Electric Co, Long Island Lighting Co, Commonwealth Edison Co & GE in San Jose, CA to audit NSSS equipment for seismic & other dynamic qualification
 PELTIER, I A Light Water Reactors Branch 1 79/04/23 3pp

7903040318 Responds to 790223 ltr Reevaluation of balance of plants & NSSS Seismic Category I equipment has begun Outlines plans for reevaluation programs
 NOVARRO, J P Long Island Lighting Co 79/03/01 3pp

7903080500 Forwards list of GE Seismic Category I equipment for seismic qualification review List identifies equipment required for safe shutdown & includes brief list of plant sys noun designators.
 NOVARRO, J P Long Island Lighting Co 79/03/04 37pp

7903300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969 Review & reanalysis included all work through Dec 1970
 PORTER, F L EDS Nuclear, Inc 79/03/21 9pp

--7903300263 Forwards EDS Nuclear, Inc list of BHRs & piping sys which could have been impacted by deficient computer program GE has no record of reanalysis for Cooper piping sys
 STEPHENS, P H General Electric Co, Nuclear Energy Products Div 79/01/24 18pp

F Security, medical, emergency & fire protection plans

7903240941 Requests copy of QAD rept re insufficient state & local emergency evacuation plans & NRC response to plan
 SHAPIRO, R Cammer & Shapiro 79/04/03 1p

G Adjudicatory correspondence

7903240234 First set of interrogatories & notice to produce, submitted by County of Suffolk, NY to util Certificate of Bvc encl
 LIKE, I Suffolk County, NY 79/03/28 10pp

7903080053 Responds to request for info re possible shutdown of facility due to possible design deficiencies caused by computer model design Computer model in question not used for facilities
 HOEFLING, R K Branch 4 79/04/03 2pp

7903230156 Opposes licensing of plant
 OWEN, B Affiliation Unknown 79/04/03 2pp

7903230053 Directs recipient to QAD for rept, EMB-78-110, requested in 790403 ltr. NRC response is being prepared & will be provided when available
 HOEFLING, R K Branch 4 79/04/13 1p

7903130207 Response to Suffolk County's 790328 discovery requests contained in Apps A & B of first set of interrogatories & notice to produce Affidavit of WJ Musler, supporting documentation & Certificate of Bvc encl.
 WHITTEMORE, F C Long Island Lighting Co 79/04/17 57pp

7903240913 Requests details on allegation that ECCS failed on six different occasions
 SHAPIRO, R Cammer & Shapiro 79/04/17, 1p

7903230311 Forwards response to questions from 790420 meeting re util's first two sets of motions for summary disposition. Submits unexecuted third set of summary disposition motions Supporting documentation & affidavits encl
 WHITTEMORE, F C Munton & Williams 79/04/27 51pp.

K Utility Final Safety Analysis Report (FSAR) & amends

7903240369 Forwards Amend 32 to license application consisting of Revision 16 to FSAR Affidavit encl
 WOFFORD, A. H. Long Island Lighting Co 79/03/15 2pp

--7903240376 Amend 32 to FSAR re containment design Oversized drawings encl.
 * Long Island Lighting Co. 79/03/15 450pp

7903290210 Certificate of Bvc of Revision 16 to FSAR.
 MORIN, J P Long Island Lighting Co. 79/03/22, 1p.

P Operating license stage documents & correspondence

7903040439 Util will invoice Code Case N-224 to ASME Section III which allows use of ASTM A500 Grade B & ASTM A501 structural tubing for welded attachments to ASME Section III Code Class 2 & 3 components This ltr supplements 790327 ltr
 NOVARRO, J P Long Island Lighting Co 79/04/23 1p

Q Inspection reports, IE Bulletins & correspondence

7903010116 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
 GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/23 1p

7903240668 Forwards IE Insp Rept 50-322/79-03 on 790227-0302 No noncompliance noted
 CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/23 2pp

--7903240673 IE Insp Rept 50-322/79-03 on 790227-0302 No noncompliance noted Major areas inspected quality verification records for reactor pressure vessel internals storage & installation & licensee action on NRC findings
 TOTI, A D, MCBREARTY, R A Region 1, Philadelphia, Office of the Director
 MCQUAGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/22 9pp

7903240976 Responds to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Forwards addl info to clarify SER open items & confirmatory issues
 NOVARRO, J P Long Island Lighting Co 79/03/28 1p

7903020051 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
 GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/11 1p

7903020395 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
 GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7903040038 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
 GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7903040208 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
 GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7903030070 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
 GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/17 1p

7903020263 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
 GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/18 1p

7903240639 Forwards revised procedures of preservice insp program
 NOVARRO, J P Long Island Lighting Co 79/03/01 2pp

--7903240645 Automated ultrasonic examination procedures for reactor vessel nozzle welds
 * Long Island Lighting Co 78/11/03 33pp

--7903240648 Remote ultrasonic examination procedures for reactor vessel nozzle safe-end welds
 * Long Island Lighting Co 78/11/03, 31pp

--7903240650 Automated ultrasonic examination procedures for reactor vessel welds
 * Long Island Lighting Co 78/11/03 29pp

--7903240654 Ultrasonic examination procedures for piping butt welds longitudinal welds
 * Long Island Lighting Co, 78/09/01 31pp

DOCKETED ITEMS

133

DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

7903070674 Forwards replacement pages for Amends 1 & 4 to CPPR-39 & CPPR-69
STOLZ, J F Light Water Reactors Branch 1 79/03/29 10pp

7903230578 Extends const completion dates to 790630 for Unit 1 & 800229 for Unit 2
STOLZ, J F Light Water Reactors Branch 1 79/04/13 6pp

--7905230582 FR notice ordering extension of const completion dates to 790630 for Unit 1 & 800229 for Unit 2
BOYD, R S Division of Project Management 79/04/13 2pp

7905020302 Forwards \$1,600 fee to extend CP, in response to NRC 790410 ltr Requests acknowledgment
CRANE, P A Pacific Gas & Electric Co 79/04/27 2pp

7905210172 Forwards addl info on containment electrical penetrations in response to NRC questions
CRANE, P A Pacific Gas & Electric Co 79/05/17 3pp

7905210169 Forwards info on bolted connections in linear supports in response to NRC 781208 ltr
CRANE, P A Pacific Gas & Electric Co 79/05/18 9pp

7905300361 Forwards application to extend completion date for CPPR-39 to 791031
CRANE, P A Pacific Gas & Electric Co 79/05/24 1p

--7905300364 Application to extend completion date for CPPR-39 to 791031
SHACKELFORD, B , CRANE, P A Pacific Gas & Electric Co 79/05/23 1p

F Security, medical, emergency & fire protection plans

7905190054 Forwards modified physical security plan Plan withheld (ref 10CFR2 790)
CRANE, P A Pacific Gas & Electric Co 79/05/15 1p

G Adjudicatory correspondence

7905030166 Request by intervenors Scenic Shoreline Preservation Conference, San Luis Obispo Mothers for Peace, Ecology Action Club, SA Silver & JJ Foster for late filing of proposed findings of fact & conclusions of law w/Certificate of Svc encl
FLEISCHAKER, D B Fleischaker, D B, 79/03/25 4pp

--7905030174 Proposed findings of fact & conclusions of law by intervenors Scenic Shoreline Preservation Conference, San Luis Obispo Mothers for Peace, Ecology Action Club, SA Silver & JJ Foster
FLEISCHAKER, D B Fleischaker, D B PHILLIPS, J R , KRISTOVICH, S Center for Law in the Public Interest 79/03/25 69pp

7905250052 Informs of inability to submit proposed findings of fact on adequacy of plant security system denied access to evidence & access to hearing on security plan Certificate of Svc encl
BALDWIN, W A San Luis Obispo Mothers for Peace 79/03/29 3pp

7905230789 Group of 15 ltrs protesting opening of facility
MARQOLIS, K. R , WYLER, B Affiliation Unknown 79/03/30 19pp

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients.
SCINTO, J F Hearings Division 79/04/02 31pp

--7905010156 Board notification, staff assessment re nonsafety-grade equipment to mitigate transients
VABGALL, D B Assistant Director for Light Water Reactors 79/03/29 2pp.

--7905010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients More info is required.
TEDESCO, R L Assistant Director for Reactor Safety 79/03/16 3pp

7905240256 Requests info on facility & earthquake Unhappy w/nuclear power
GARCIA, O Affiliation Unknown 79/04/04 1p

--7905240279 Requests that facility not be allowed to operate.
MANZER, N , MANZER, R Affiliation Unknown 79/03/30. 1p.

7905300044 Motion of extension of time until 790410 to file proposed findings of fact & conclusions of law Certificate of Svc encl
KETCHEN, E O Branch 3 79/04/04 4pp

7905290114 Grants NRC 790404 motion for extension until 790410 in which to file findings of fact
BOMERS, E S Atomic Safety and Licensing Board Panel 79/04/05 1p

7905310104 Errata sheet to joint intervenors' proposed findings of fact & conclusions of law Certificate of Svc encl
FLEISCHAKER, D B Fleischaker, D B PHILLIPS, J R , KRISTOVICH, S Center for Law in the Public Interest 79/04/05 7pp

7905250330 Responds to 790326 ltr re status of facility licensing Evidentiary record in proceeding closed 790312, last pleading scheduled to be filed by 790416 Precise date for initial decision cannot be made
VORE, J R Atomic Safety and Licensing Board Panel 79/04/06 1p

--7905250335 Forwards 790315 ltr from Solar Use Now for Resources & Employment, expressing concern about licensing of facility Requests info on status of licensing process
ROUSSELOT, M C House of Rep 79/03/26 2pp

7905140554 Rebuttal to joint intervenors' 790325 proposed findings of fact & conclusions of law Certificate of Svc encl
CRANE, P A Pacific Gas & Electric Co 79/04/09 36pp

--7905140556 Errata & suppl to proposed findings of fact & conclusions of law
CRANE, P A Pacific Gas & Electric Co 79/04/09 2pp

7905100157 Initial decision authorizing Director of Ofc of Nuclear Reactor Regulation to make such addl findings on uncontested matters as may be necessary to issue full-term OL Certificate of Svc encl
TOURTELLOTT, J , KETCHEN, E O Branch 4 STAENBERG, M R Regulations Division 79/04/10 114pp

7905250490 Requests that rebuttal to Joint Intervenors' proposed finding of fact be amended to ref ASLB 780803 order
CRANE, P A Pacific Gas & Electric Co 79/04/11 1p

7905100370 Forwards corrected pages to NRC 790410 proposed findings, changing words "Initial Decision" to "Conclusions of Law"
TOURTELLOTT, J Branch 4 79/04/12 3pp

7905150726 Responds to 790216 & 790321 ltrs requesting denial of OLs ASLB will consider issue Views to be included in docket file of proceeding
ENDELHARDT, T F Deputy Executive Legal Director 79/04/17 1p

7905150598 Forwards resolution adopted on 790416 Resolution requests deferment of action on license application, pending determination that safety sys are adequate to assure public safety
MENZEL, H C Santa Barbara County, CA 79/04/18 1p

--7905150603 Resolution of Board of Supervisors of Santa Barbara County, CA urging NRC to defer final action on license application until facility safety systems are adequate to ensure public safety
YAGER, D M Santa Barbara County, CA 79/04/16 1p

7905150118 Responds to encl ltr opposing operation of facility because of proximity to active earthquake fault & concern for disposal of high level radioactive wastes Matters being considered by ASLB
BOYD, R S Division of Project Management 79/04/30 3pp

7905240564 Requests denial w/o prejudice of joint intervenors' motion to withhold issuance of OL Certificate of Svc encl
TOURTELLOTT, J Branch 4 79/05/02 8pp

7905300007 Response in opposition to joint intervenors' request to withhold issuance of OL Motion is untimely, in wrong form & poorly taken
MORRISSEY, J C Pacific Gas & Electric Co. OEHRA C Snell & Wilmer NORTON, B Bruce Norton 79/05/09 6pp

7905300716 Ack receipt of 790425 & 790426 ltrs re opposition to operation of facility due to proximity to Hosgr Fault Facility designed to withstand seismic event of 7.5 ASLB is preparing decision re licensing based on 790215 hearing.
DENTON, H R Office of Nuclear Reactor Regulation 79/05/14 2pp

DOCKETED ITEMS

134

--7903300719 Expresses opposition to operation of facility due to proximity to Hosgri Fault
WATERHOUSE, H Affiliation Unknown 79/04/26 1p

--7903300720 Expresses opposition to operation of facility due to proximity to Hosgri Fault
WATERHOUSE, E Affiliation Unknown 79/04/25 1p

H General correspondence

7903200452 Requests immediate halt to const of facility
ANDREWS, M House of Rep 79/04/02 1p

7903070551 Notifies of change of address for DO Brindenbaugh & RB
Hubbard to 1723 Hamilton Ave, Suite X, San Jose, CA 95123
COOPER, K F MHB Technical Associates 79/04/25 1p

7903240713 Requests suspension of DL until necessary safety mods are implemented
BROWN, E O California, State of 79/05/04 2pp

7903240265 Responds to 790320 ltr re constituent concerns re granting of license to facility seismic event of 7.5 magnitude can be withstood & quality of const is controlled by licensee QA program
OGBURN, L V Office of the Executive Director for Operations 79/05/08 3pp

I Financial information

7903300168 Forwards "Annual Financial Rept 1978"
CRANE, P A Pacific Gas & Electric Co 79/05/23 1p

--7903300174 "Annual Financial Rept 1978"
* Pacific Gas & Electric Co 78/12/31 40pp

7903300510 Forwards "Estimated Internal Fund Generation for CY79" & "Annual Financial Rept 1978"
CRANE, P A Pacific Gas & Electric Co 79/05/24 3pp

--7903300529 "Annual Financial Rept 1978"
* Pacific Gas & Electric Co 79/02/23 36pp

J Insurance & indemnity information

7903140512 Forwards Amend 4 to Indemnity Agreement B-75 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790301 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp

7903140406 Forwards Amends executed Amends 21 & 4 to Indemnity Agreements B-21 & B-75, respectively
CRANE, P A Pacific Gas & Electric Co 79/05/08 3pp

O Advisory Committee on Reactor Safeguards reports & correspondence

7903100325 Responds to request for written rept after cancellation of ACRS 790331 meeting re possibility of problem w/instrument guide tubes Staff rept encl
CROCKER, L P Division of Project Management 79/03/30 5pp

P Operating license stage documents & correspondence

7903020244 Responds to NRC 790314 request for addl info re containment purge valves Forwards results of CSBREV1 program to calculate containment purge valve closing data coincident w/LOCA
CRANE, P A Pacific Gas & Electric Co 79/04/13 45pp

Q Inspection reports, IE Bulletins & correspondence

7903230656 Forwards IE Insp Rept 50-323/79-09 on 790220-23 No noncompliance noted
BOOK, H E Region 3, San Francisco, Fuel Facility & Materials Safety Branch 79/03/19 2pp

--7903230664 IE Insp Rept 50-323/79-09 on 790220-23 No noncompliance noted Major areas inspected training in emergency planning & radiation protection, staffing, respiratory protection, radioactive waste sys & Offsite Dose Calculation Manual
NORTH, H B Region 3, San Francisco, Office of the Director
BOOK, H E Region 3, San Francisco, Fuel Facility & Materials Safety Branch 79/03/19 4pp

7903230617 Forwards IE Insp Repts 50-275/79-05 & 50-323/79-03 on 790305-09 & 15 No noncompliance noted
CRENS, J L Region 3, San Francisco, Reactor Operations Nuclear Support Branch 79/03/21 2pp

--7903230640 IE Insp Repts 50-275/79-05 & 50-323/79-03 on 790306-07 1 No noncompliance noted Major areas inspected preoperational testing, evaluation & verification of test results, IE bulletins & circulars Followup
MORRILL, P O Region 3, San Francisco, Office of the Director
STERNBERG, D M Region 3, San Francisco, Reactor Operations Nuclear Support Branch 79/03/20 4pp

7903010287 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
ENGELKEN, R H Region 4, Dallas, Office of the Director 79/03/2 1p

7903040081 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tank"
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/03/26 1p

7903010023 Forwards IE Bulletin 79-06A, "Review of Operational Events By Misalignments Identified During TH1 Incident"
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/04/14 1p

7903040509 Forwards IE Bulletin 79-06B, "Review of Operational Events By Misalignments Identified During TH1 Incident"
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/04/14 1p

7903070099 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/04/14 1p

7903030291 Forwards IE Bulletin 79-09, "Failures of OK Type AA 2 Circuit Breaker in Safety-Related Sys." Licensee action required
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/04/17 1p

7903080366 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1-Suppl"
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/04/21 1p

G Reportable occurrences, LERs & related correspondence

7903102003 Board notification Beabrook refueling water storage tank design deficiency
SCINTO, J Hearings Division 79/03/29 30pp

7903130060 Forwards PNO-79-67L
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/04/06 1p

7903130167 Forwards PNO-79-67R
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/04/11 1p

7903040123 Forwards PNO-79-67B
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/04/12 1p

7903130141 Forwards PNO-79-67T
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/04/13 1p

7903030045 Forwards PNO-79-67U
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/04/14 1p

7903020527 Forwards PNO-79-67AA
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/04/20 1p

7903010425 Forwards PNO-79-67AB
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/04/21 1p

7903010444 Forwards PNO-79-67AC & AD
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/04/23 1p

DOCKETED ITEMS

136

7905020227 Forwards PNO-79-67AF
ENOEKLEN, R H Region 5, San Francisco, Office of the Director
79/04/25 1p

7905020256 Forwards PNO-79-67AQ
ENOEKLEN, R H Region 5, San Francisco, Office of the Director
79/04/26 1p

7905090005 Forwards PNO-79-67AH
ENOEKLEN, R H Region 5, San Francisco, Office of the Director
79/04/27 1p

7905070007 Forwards PNO-79-67AL, per NRC 790401 ltr transmitting IE
Bulletin 79-05
ENOEKLEN, R H Region 5, San Francisco, Office of the Director.
79/05/01 1p

7905090380 Submits followup rept to 790404 notification of RO. During
progress of routine weld repairs on pipe rupture restraints,
cracking discovered in immediate vicinity of repairs Full
rept will be submitted
CRANE, P A Pacific Gas & Electric Co 79/05/03 3pp

7905170072 Forwards PNO-79-67AM
ENOEKLEN, R H Region 5, San Francisco, Office of the Director
79/05/07 1p

7905240651 Ack receipt of 790503 ltr providing preliminary rept re
cracking found in pipe rupture restraints
ENOEKLEN, R H Region 5, San Francisco, Office of the Director
79/05/16, 1p.

--7905240701 Discusses situation reported to IE on 790404 re cracking
in pipe rupture restraints Details program of investigation
Suppl on crack severity will be forwarded
CRANE, P A Pacific Gas & Electric Co 79/05/03 3pp

T. Hearing transcripts on non-antitrust matters

7905030244 Corrections to transcripts from Dec 1978 & Jan 1979
Hearings Certificate of Evc encl
MORRISBEY, J C , FURBUSH, M. H. , CRANE, P A Pacific Gas & Electric Co
79/04/04 25pp

7905240273 Requests info re C Maschke 790315 ltr of concerns about
granting of license to util
LAGOMARINO, R House of Rep 79/03/20 1p

DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

J Insurance & indemnity information

7905040599 Forwards Endorsement 30 to MALEU Policy MF-80
GRAHAM, W E Carolina Power & Light Co 79/04/25, 2pp

7905040607 Forwards Endorsement 33 to NELIA Policy NF-218
GRAHAM, W E Carolina Power & Light Co 79/04/25 2pp

7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters 79/05/01
1p

7905140508 Forwards Amend 9 to Indemnity Agreement B-71 per 10CFR140
changes, re increase in liability insurance from \$140 million
to \$160 million, effective 790501 Supporting documentation
encl.
SALTZMAN, J Antitrust & Indemnity Group 79/05/01, 6pp

7905170233 Forwards Amend 9 to Indemnity Agreements B-42 & B-71
reflecting increase in primary liability insurance provided
by ANI/MAELU.
BARHAM, C. D. Douglass & Barham 79/05/11, 3pp

P. Operating license stage documents & correspondence

7905030353 Submits exceptions & corrections to operations GA pProgram
re ANSI codes for instrumentation & electrical equipment, &
mechanical equipment & sys for const phase.
UTLEY, E. E. Carolina Power & Light Co 79/04/23 3pp

7905150108 Responds to 790112 request for termination of leveling
portion of 790610 Phase 1 "BSEP Program for Seismic
Monitoring " Approves request to terminate program
IPPOLITO, T A Operating Reactors Branch 3 79/04/25 2pp

7905040624 Requests Tech Specs change re trip feature, annunciator
clarity to minimize operator confusion & stop valve
UTLEY, E E Carolina Power & Light Co 79/04/27 13pp

7905080402 Submits schedule for implementing augmented offgas sys in
response to 780912 ltr Earliest feasible date for completing
mod, testing & demonstration of sys operability is 811231
UTLEY, E E Carolina Power & Light Co 79/05/01 1p

7905080417 Responds to 781129 ltr re containment purging during normal
plant operation Should LOCA occur during operations,
operation of ECCB sys would not be affected Supporting info
encl
UTLEY, E E Carolina Power & Light Co 79/05/01 4pp

7905080436 Provides results of GE analysis of prompt recirculation pump
trip for Cycle 3 operation NRC should be able to license
Cycle 3 operation until mid-cycle Recirculation pump trip
will be tested during facility startup
UTLEY, E E Carolina Power & Light Co 79/05/01 1p

790510379 Responds to NRC 780912 ltr re schedule for implementing
augmented offgas sys New hydrogen recombiners installed on
front end Sys will be operable by 811231
UTLEY, E E Carolina Power & Light Co 79/05/01 1p

7905080453 Forwards oversized maps & photo attachments to util 781129
rept on main dam core trench features W/o drawings
FLOYD, B D Carolina Power & Light Co 79/05/08 5pp

7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation
of elbow flexibility error which existed in versions of
PIBOL piping analysis computer program from Jan-Oct 1969
Review & reanalysis included all work through Dec 1970
PORTER, F L. EDS Nuclear, Inc 79/05/21 9pp

--7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which
could have been impacted by deficient computer program
GE has no record of reanalysis for Cooper piping sys
STEPHENS, P W General Electric Co , Nuclear Energy Products Div
79/01/24 18pp

7905290370 Confirms & formalizes 790521 verbal commitment re seismic
comparison & insp of safety-related piping Documents
statements re reanalysis of circulation loops
UTLEY, E E Carolina Power & Light Co 79/05/22 2pp

Q Inspection reports, IE Bulletins & correspondence

7905010465 Forwards IE Insp Repts 50-324/79-05 & 50-325/79-05 on
790122-26 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 79/03/14 2pp

--7905010468 IE Insp Repts 50-325/79-05 & 50-324/79-05 on 790122-26. No
noncompliance noted Major areas inspected radiological
environ monitoring program, environ monitoring station &
data, analytical sensitivity & control measures
PERRY, W. W. Region 2, Atlanta, Reactor Operations Nuclear
Support Branch 79/03/09 5pp

7905010168 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping "
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/03/23 2pp

7905030294 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks "
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/03/26 2pp

7905010095 Forwards IE Info Notice 79-08, "Interconnection of
Contaminated Sys w/Bvc Air Sys Used as Source of Breathing
Air."
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/03/28, 2pp.

7905010346 Forwards IE Info Notice 79-09, "Spill of Radioactively
Contaminated Resin "
O'REILLY, J P Region 2, Atlanta, Office of the Director.
79/03/30, 2pp.

7905240661 Forwards IE Insp Repts 50-324/79-10 & 50-325/79-10 on
790304-07 No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Office of the Director. 79/04/06
2pp

DOCKETED ITEMS

136

--7903246665 IE Insp Repts 50-324/79-10 & 50-325/79-10 on 790304-07 No noncompliance noted Major areas inspected inservice insp program, procedures & insp data & evaluation & special ultrasonic insp of recirculation loop inlet safe-ends BLAKE, J J Region 2, Atlanta, Office of the Director 79/04/03 4pp

7903100241 Responds to IE Bulletin 79-03 No welded pipe from Youngstown Welding & Engineering is used or planned for use UTLEY, E E Carolina Power & Light Co 79/04/12 1p

7903230209 Ack receipt of 790402 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-324/79-07 & 50-325/79-07 LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/12 1p

--7903230223 Responds to NRC 790309 ltr re violations noted in IE Insp Repts 50-324/79-07 & 50-325/79-07 Corrective actions individuals have been counseled on performing data reviews & on corrective actions FURR, B J Carolina Power & Light Co 79/04/02 2pp

--7903230229 Forwards IE Insp Repts 50-324/79-07 & 50-325/79-07 on 790130-0202 & notice of violation LEWIS, P C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/09 2pp

--7903230237 Notice of violation from insp on 790130-0202 e Region 2, Atlanta, Office of the Director 79/03/09 1p

--7903230243 IE Insp Repts 50-324/79-07 & 50-325/79-07 on 790130-0202 Noncompliance noted stroke time for valve FD46 was above max time required by Tech Specs Three independent reviews failed to note problem RILEY, B W, MESSITT, B R Region 2, Atlanta, Office of the Director DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/09 6pp

7903040163 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp

7903040281 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7903150696 Forwards IE Bulletin 79-08, "Events Relevant to BHRs Identified During TMI Incident " Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp

7903030141 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp

7903020373 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp

7903010517 Forwards restated paragraph from 770330 ltr, submitted as revision to QA program, in response to IE Insp Repts 50-324/79-02 & 50-325/79-02 Paragraph discusses radiation survey/measuring instruments UTLEY, E E Carolina Power & Light Co 79/04/23 2pp

7903240192 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Will reanalyze all remaining safety-related piping as soon as NRC ack that specified criteria is acceptable, w/supporting documentation UTLEY, E E Carolina Power & Light Co 79/04/24 3pp

7903000283 Responds to IE Bulletin 79-01 Search of plant documentation indicates no Valen swing check valves w/diameter of 3-10 inches are used at facility UTLEY, E E Carolina Power & Light Co 79/04/30, 1p.

7903210165 Supplements 790424 response to IE Bulletin 79-07 re reanalysis of computer programs used for safety-related piping Addl program verification has been performed by running NRC-approved benchmark cases UTLEY, E E Carolina Power & Light Co, 79/05/16 7pp

7905230344 Forwards response to 790516 request for addl info re seismic analysis of safety-related piping Supplements until's 790424 & 790516 responses to IE Bulletin 79-07 FURR, B J Carolina Power & Light Co 79/05/21 34pp

R Periodic operating reports & related correspondence

7905150631 Forwards monthly operating rept for Apr 1979 FURR, B J Carolina Power & Light Co 79/05/09 1p

--7905150638 Monthly operating rept for Apr 1979 WILLIS, E Carolina Power & Light Co 79/05/01 13pp

B Reportable occurrences, LERs & related correspondence

7905030345 Forwards LER 79-017/03L-0 FURR, B J Carolina Power & Light Co 79/04/30 1p

--7905030347 LER 79-017/03L-0 on 790404 RHR pumps 2B & 2D would not tie on manual signal Caused by poor connection between fuses & fuse block Fuses soldered to fuse block TOLLISON, A C Carolina Power & Light Co 79/04/30, 3pp

7905090282 Forward LER 79-018/03L-0 FURR, B J Carolina Power & Light Co 79/05/07 1p

--7905090289 LER 79-018/03L-0 ON 790419 pressure switch 2-EHC-PQ-1733 failed to meet Tech Specs response time Caused by actuation time on installed switch being too slow Alternative switching methods under evaluation TOLLISON, A C Carolina Power & Light Co 79/05/07 1p

7905090302 Forwards LER 79-019/03L-0 FURR, B J Carolina Power & Light Co 79/05/07 1p.

--7905090311 LER 79-019/03L-0 on 790420 electrical open circuit fault re V2 power lead to fan motor Caused by junction box splice between motor & contactor, TOLLISON, A C Carolina Power & Light Co 79/05/07 1p

7905230615 Submits 14-day radiological environ event rept radioactive waste was shipped on 790803 w/radiation levels exceeding ETS Incident to be reviewed & health physics radwaste shipment procedures revised BANKS, H R Carolina Power & Light Co 79/05/16 2pp

7905220406 Forwards LER 79-020/03L-0, BANKS, H R Carolina Power & Light Co 79/05/18 1p

--7905220411 LER 79-020/03L-0 on 790421, while performing standby liquid control relief valve test, relief valve lifted at 1.250 lb Caused by setpoint drift Setpoint reset, tested satisfactorily & returned to svc TOLLISON, A C Carolina Power & Light Co 79/05/18 1p

7905300384 Forwards LER 79-030/03L-0 BANKS, H R Carolina Power & Light Co 79/05/24 1p

--7905300390 LER 79-030/03L-0 on 790425, 13 snubbers failed insp, 1st failed to lock up No apparent cause discerned Eight were rebuilt w/new seals & poppets, three replaced Remaining three snubbers failed to bleed Two rebuilt, one replaced TOLLISON, A C Carolina Power & Light Co 79/05/24 2pp

7905300371 Forwards LER 79-011/03L-0 BANKS, H R Carolina Power & Light Co 79/05/25 1p

--7905300377 LER 79-011/03L-0 on 790419 during insp, five Bergen Ballins, snubbers failed Caused by low fluid level & seal failure Snubbers rebuilt & returned to svc. TOLLISON, A C Carolina Power & Light Co 79/05/25 2pp

7905300375 Forwards LER 79-022/03L-0, BANKS, H. R. Carolina Power & Light Co. 79/05/25, 1p

--7905300380 LER 79-022/03L-0 on 790425, while in cold shutdown, near completion of refueling outage, water chemistry Tech Spec limits exceeded Caused by excessive condenser tube leakage causing rapid saltwater breakthrough TOLLISON, A C Carolina Power & Light Co 79/05/25, 3pp

7905300387 Forwards LER 79-032/03L-0, BANKS, H. R. Carolina Power & Light Co. 79/05/25, 1p.

DOCKETED ITEMS

137

--7905300377 LER 79-032/031-O on 790425, while performing visual insp of inaccessible snubbers, seven Grinnell snubbers failed. Caused by low fluid level. All snubbers disassembled, inspected & rebuilt.
TOLIBSON, A C Carolina Power & Light Co 79/09/25 1p

POCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1 J Insurance & Indemnity Information

7905040577 Forwards Endorsement 30 to MALEU Policy MF-80
ORAHAM, W E Carolina Power & Light Co 79/04/25 2pp

7905040607 Forwards Endorsement 33 to NCLIA Policy NF-218
ORAHAM, W E Carolina Power & Light Co 79/04/25 2pp

7905070477 Confirms increased liability limit to \$124,000,000 for policies MF-1, 25, 43, 76, 83, 100, 111, 140, 146, 181, 161, 164, 170, 173, 174, 178, 179, 180, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHINI, J American Nuclear Insurers 79/05/01 1p

7905070502 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905140508 Forwards Amend 9 to Indemnity Agreement B-71 per IOCFR140 changes, i.e. increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp

7905170233 Forwards Amend 9 to Indemnity Agreements B-42 & B-71 reflecting increase in primary liability insurance provided by ANI/MAE I.U.
BARHAM, C D Douglas & Barham 79/05/11 3pp

P. Operating license stage documents & correspondence

7905070133 Submits exceptions & corrections to operations QA program re ANSI codes for instrumentation & electrical equipment, & mechanical equipment & sys for const phase.
UTLEY, E E Carolina Power & Light Co 79/04/23 3pp

7905R10620 Notification of 790424 meeting w/util & OE in Bethesda, MD to resolve questions on proposed recirculation pump trip feature for end-of-cycle margin enhancement.
HANNON, J N Operating Reactors Branch 3 79/04/23 1p

7905190104 Responds to 790112 request for termination of leveling portion of 790610 Phase I "BOLP" Program for Seismic Monitoring. Approves request to terminate program.
IPPOLITO, T A Operating Reactors Branch 3 79/04/25 2pp

7905040624 Requests Tech Specs change re trip feature, annunciator clarity to minimize operator confusion & stop valve.
UTLEY, E E Carolina Power & Light Co 79/04/27 13pp

7905190822 Notification of 790430 meeting w/util & OE in Bethesda, MD to resolve questions on proposed recirculation pump trip feature for end-of-cycle margin enhancement.
HANNON, J N Operating Reactors Branch 3 79/04/30 1p

7905080402 Submits schedule for implementing augmented offgas sys in response to 790712 ltr. Earliest feasible date for completing mod, testing & demonstration of sys operability is 8/1/83.
UTLEY, E E Carolina Power & Light Co 79/05/01 1p

7905080417 Responds to 781129 ltr re containment purging during normal plant operation. Should LOCA occur during operations, operation of ECCS sys would not be affected. Supporting info encl.
UTLEY, E E Carolina Power & Light Co 79/05/01 4pp

7905100379 Responds to NRC 780912 ltr re schedule for implementing augmented offgas sys. New hydrogen recombiners installed on front end Sys will be operable by 8/1/83.
UTLEY, E E Carolina Power & Light Co 79/05/01 1p

7905080433 Forwards oversized maps & photo attachments to util 781129 rpt on main dam core trench features w/o drawings.
FLOYD, B D Carolina Power & Light Co 79/05/08 5pp

7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969. Review & reanalysis included all work through Dec 1970.
PORTER, F L EDS Nuclear, Inc 79/05/21 9pp

--7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program. OE has no record of reanalysis for Cooper piping sys.
STEPHENS, P W General Electric Co, Nuclear Energy Products Div 79/01/24 18pp

7905290370 Confirms & formalizes 790521 verbal commitment re seismic comparison & insp of safety-related piping. Documents statements re reanalysis of circulation loops.
UTLEY, E E Carolina Power & Light Co 79/05/22 2pp

Q Inspection reports, IE Bulletins & correspondence

7905010465 Forwards IE Insp Repts 50-324/79-05 & 50-325/79-05 on 790122-26. No noncompliance noted.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/14 2pp

--7905010465 IE Insp Repts 50-325/79-05 & 50-324/79-05 on 790122-26. No noncompliance noted. Major areas inspected: radiological environ monitoring program, environ monitoring station & data, analytical sensitivity & control measures.
PERRY, W W Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/09 3pp

7905010168 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping".
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905030294 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks".
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/26 2pp

7905010095 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air".
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/28 2pp

7905010346 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin".
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/30 2pp

7905240661 Forwards IE Insp Repts 50-324/79-10 & 50-325/79-10 on 790304-07. No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Office of the Director 79/04/06 2pp

--7905240665 IE Insp Repts 50-324/79-10 & 50-325/79-10 on 790304-07. No noncompliance noted. Major areas inspected: inservice insp program, procedures & insp data & evaluation & special ultrasonic insp of recirculation loop inlet safe-ends.
BLAKE, J J Region 2, Atlanta, Office of the Director 79/04/05 4pp

7905100241 Responds to IE Bulletin 79-03. No welded pipe from Youngstown Welding & Engineering is used or planned for use.
UTLEY, E E Carolina Power & Light Co 79/04/12 1p

7905230207 Ack receipt of 790402 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-324/79-07 & 50-325/79-07.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 79/04/12 1p

--7905230223 Responds to NRC 790309 ltr re violations noted in IE Insp Repts 50-324/79-07 & 50-325/79-07. Corrective actions individuals have been counseled on performing data reviews & on corrective actions.
FURR, B J Carolina Power & Light Co 79/04/02 2pp

--7905230229 Forwards IE Insp Repts 50-324/79-07 & 50-325/79-07 on 790130-0202 & notice of violation.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 79/03/09 2pp

--7905230237 Notice of violation from insp on 790130-0202.
* Region 2, Atlanta, Office of the Director 79/03/09 1p

DOCKETED ITEMS

- 7903230243 IE Insp Repts 30-324/79-07 & 30-325/79-07 on 790130-0202
Noncompliance noted stroke time for valve F046 was above
max time--required by Tech Specs Three independent reviews
failed to note problem
RILEY, B W, MESSITT, B R Region 2, Atlanta, Office of the
Director DANCE, H C Region 2, Atlanta, Reactor Operations
Nuclear Support Branch 79/03/09 6pp
- 7903040163 Forwards IE Bulletin 79-06B, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 2pp
- 7903040281 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of
Safety-Related Piping" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 1p
- 790310696 Forwards IE Bulletin 79-08, "Events Relevant to BWRs
Identified During TMI Incident" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 2pp
- 7903030141 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2
Circuit Breaker in Safety-Related Sys" Licensee action
required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/17 1p
- 7903020373 Forwards IE Bulletin 79-06A, Revision 1, "Review of
Operational Errors & Sys Misalignments Identified During TMI
Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/18 2pp
- 7903010517 Forwards restated paragraph from 770330 ltr, submitted as
revision to QA program in response to IE Insp Repts
30-324/79-02 & 30-325/79-02 Paragraph discusses radiation
survey/measuring instruments
UTLEY, E E Carolina Power & Light Co 79/04/23 2pp
- 7903240192 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of
Safety-related Piping" Will reanalyze all remaining
safety-related piping as soon as NRC act that specified
criteria is acceptable w/supporting documentation
UTLEY, E E Carolina Power & Light Co 79/04/24 5pp
- 7903300283 Responds to IE Bulletin 79-01 Search of plant documentation
indicates no Valen swing check valves w/diameter of 3-10
inches are used at facility
UTLEY, E E Carolina Power & Light Co 79/04/30 1p
- 7903210163 Supplements 790424 response to IE Bulletin 79-07 re
reanalysis of computer programs used for safety-related
piping Addl program verification has been performed by
running NRC-approved benchmark cases
UTLEY, E E Carolina Power & Light Co 79/05/15 7pp
- 7903230344 Forwards response to 790516 request for addl info re seismic
analysis of safety-related piping Supplements util's 790424
& 790516 responses to IE Bulletin 79-07
FURR, B J Carolina Power & Light Co, 79/05/21 34pp.
- R. Periodic operating reports & related correspondence
- 1's monthly operating rept for Apr 1979,
Carolina Power & Light Co 79/05/09 1p
- rept for Apr 1979
Carolina Power & Light Co 79/05/01 13pp
- related correspondence
- 7905080504 Forwards LER 79-013/03L-0 W/o encl
FURR, B J Carolina Power & Light Co 79/05/04 1p
- 7903080518 LER 79-013/03L-0 on 790406 several Tech Spec items not
performed at proper intervals Caused by oversight in
procedures. Periodic testing procedures revised.
TOLLISON, A C Carolina Power & Light Co, 79/05/04 3pp
- 7903090321 Forwards LER 79-020/03L-0
FURR, B J Carolina Power & Light Co 79/05/07 1p.
- 7903090324 LER 79-020/03L-0 on 790408 during containment isolation
valve local leak rate test, isolation valves did not seat &
held pressure. Caused by valve bushing wear. Bushings
replaced
TOLLISON, A C Carolina Power & Light Co 79/05/07 1p
- 7905090340 Forwards LER 79-016/03L-0
FURR, B J Carolina Power & Light Co 79/05/07 1p
- 7905090344 LER 79-016/03L-0 on 790417 during insp of fire protection
sys, isolation valves for makeup water treatment area
sprinkler sys were shut Caused by isolation valves being
isolated due to extensive mod of fire protection sys
TOLLISON, A C Carolina Power & Light Co 79/05/07 2pp
- 7903150427 Forwards LER 79-011/03L-0
FURR, B J Carolina Power & Light Co 79/05/09 1p.
- 7903150432 LER 79-011/03L-0 on 790419 while performing normal purg
of drywell, operator discovered i-CAV-V10 isolation valve
would not shut Caused by pneumatic flow restrictor in
closing circuit being closed, preventing valve from closing
TOLLISON, A C Carolina Power & Light Co 79/05/09 1p
- 7903150506 Forwards LER 79-018/03L-0
FURR, B J Carolina Power & Light Co 79/05/09 1p
- 7903150518 LER 79-018/03L-0 on 790414 main steam relief valve opens
520 lb psig & immediately reseated, causing reactor scram due
to high flux spike on intermediate range monitors
TOLLISON, A C Carolina Power & Light Co 79/05/09 1p
- 7903230615 Submits 14-day radiological environ event rept radioactiv
waste was shipped on 790303 w/radiation levels exceeding
ETS Incident to be reviewed & health physics radwaste
shipment procedures revised
BANKS, H R Carolina Power & Light Co 79/05/16 2pp
- 7903220342 Forwards LER 79-008/03X-1
BANKS, H R Carolina Power & Light Co 79/05/18 1p
- 7903220345 LER 79-008/03X-1 on 790112 while performing svc water is
component test, high vibration levels discovered Caused by
restrictor bushing seized to & rotating w/shaft. New impeller
installed
TOLLISON, A C Carolina Power & Light Co 79/05/18 2pp
- 7903220361 Forwards LER 79-015/03X-1
BANKS, H R Carolina Power & Light Co 79/05/18 1p
- 7903220369 LER 79-015/03X-1 on 790308 Bergen-Peterson snubber
1011-16881 failed to lock up Cause undetermined Snubber
disassembled & new seals installed
TOLLISON, A C Carolina Power & Light Co 79/05/18 1p
- 7903220367 Forwards LER 79-001/03X-1
BANKS, H R Carolina Power & Light Co 79/05/18 1p
- 7903220373 LER 79-001/03X-1 on 790104 while performing HPCI initial
response test, HPCI turbine failed response time requirement
Caused by misalignment of parameters on governor assembly
Assembly realigned
TOLLISON, A C Carolina Power & Light Co 79/05/18 2pp
- 7903240630 Forwards LER 79-021/03L-0
FURR, B J Carolina Power & Light Co 79/05/21 1p
- 7903240637 LER 79-021/03L-0 on 790420 i-CAC-1263 drywell hydrogen i
oxygen monitor gave abnormally low reading Caused by rusted
level switch for condensate pot preventing moisture buildup
from draining.
TOLLISON, A C Carolina Power & Light Co 79/05/21 2pp
- 7903250413 Forwards LER 79-017/03L-0,
BANKS, H R Carolina Power & Light Co 79/05/22 1p
- 7903250419 LER 79-017/03L-0 on 790417 while auxiliary operator was
hanging clearance on RHR pumps 2A & 2C, control operator
noticed pumps were still energized Caused by clearance
listing Unit 1 instead of Unit 2. Clearance was corrected
TOLLISON, A C Carolina Power & Light Co, 79/05/22 2pp
- 7903300425 Forwards LER 79-012/03L-0,
BANKS, H R Carolina Power & Light Co, 79/05/24 1p
- 7903300432 LER 79-012/03L-0 on 790423: no indication at notch 34 for
control rod 34-27 Caused by short in switch for notch 34
Wire insulated & switch returned to svc
TOLLISON, A C Carolina Power & Light Co, 79/05/24 1p
- 7903300512 Forwards LER 79-023/03L-0,
BANKS, H R Carolina Power & Light Co 79/05/25 1p.

--7905300518 LER 79-023/03L-0 on 790429 control rod 10-07 did not have indication at notch Caused by electrical problem in prototypic inlet piping probe located in drywell Problem will be corrected at next outage when drywell is accessible
FOLLISSON, A.C. Carolina Power & Light Co 79/05/25 1p

DOCKET 50-326 UNIV OF CALIFORNIA AT IRVINE RES REACTOR

J Insurance & indemnity information

7905160221 Forwards Amend B to Indemnity Agreement E-53, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

7905030080 Responds to 790412 ltr requesting facility be responsible for monitoring discharges Monitoring is planned by TVA & required by NRC Ltr is being referred to NRC for more specific response
KAPLAN, C H Environmental Protection Agency 79/04/26 1p

DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

7905040500 Forwards description of filters to remove air discharged from auxiliary bldg Changes implemented pursuant to 790730-31 OL hearings
HILLS, L M Tennessee Valley Authority 79/04/30 6pp

7905070934 Requests mod of state certification of Natl Pollution Discharge Elimination Sys permit TN0026430 re conditions 4d & 4f,
MOORE, H O Tennessee Valley Authority 79/05/01 2pp

7905010314 Submits Amend 61 to application consisting of revisions to certain chapters, responses & revised responses to NRC questions, further documentation to items already transmitted & FBAR text changes W/o encl
GILLELAND, J E Tennessee Valley Authority 79/05/24 1p

E NRC Safety Evaluation Report (SER), supp & correspondence

7905110008 Forwards TVA's responses to five SER outstanding confirmatory items Responses will be incorporated into Amend 61 of FBAR
GILLELAND, J E Tennessee Valley Authority 79/05/08 43pp

7905230319 Forwards comments from review of Mar 1979 SER apparent discrepancies between SER content & info provided to NRC supporting license application
GILLELAND, J F Tennessee Valley Authority 79/05/17 5pp

F Security, medical, emergency & fire protection plans

7905150649 Forwards comments which should be incorporated into modified amended security plan Comments withheld (ref 10CFR2.790)
VARDA, B A Light Water Reactors Branch 4 79/04/27 2pp

7905070420 Forwards revisions to physical security plan Revisions withheld (ref 10CFR2.790)
GILLELAND, J E Tennessee Valley Authority 79/05/01 1p

7905090341 Submits requested info on radiological emergency plan. Changes make plan consistent w/TVA responses to NRC questions on Watts Bar Nuclear Plant. Will forward final revision by 790615.
GILLELAND, J E Tennessee Valley Authority 79/05/07 190pp

J. Insurance & indemnity information

7905010327 Forwards ANI Secondary Financial Protection Binder EB-66
BUCK, J.R. Marsh & McLennan, M & M Nuclear Consultants, Inc. Div 79/04/25. 6pp

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
GUATTROCHHI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905160230 Forwards Amend 3 to Indemnity Agreement B-82, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

K Utility Final Safety Analysis Report (FSAR) & amends

7905300299 Amend 61 to FSAR
* Tennessee Valley Authority 79/05/25 250pp

7905300305 Forwards nonproprietary version of FSAR Table G7 60-1, as revised by Amend 61
GILLELAND, J E Tennessee Valley Authority 79/05/25 5pp

P Operating license stage documents & correspondence

7905020490 Discusses 790315 telcon w/R Bero of Westinghouse re incorrect weights for Velan Model C658 6-inch check valves used in safety injection sys
SCHWENGER, A Operating Reactors Branch 1 79/04/02 1p

Q Inspection reports, IE Bulletins & correspondence

7905020435 Forwards IE Insp Repts 50-327/79-13 & 50-328/79-08 on 790206-09 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/08 2pp

--7905020442 IE Insp Repts 50-327/79-13 & 50-328/79-08 on 790206-09 No noncompliance noted Major areas inspected auxiliary bldg const status, storage & housekeeping of electrical panels & review of instrumentation records
WALTERS, D K Region 2, Atlanta, Office of the Director.
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/07 3pp

7905070078 Forwards IE Insp Repts 50-327/79-14 & 50-328/79-09 on 790212-15 No noncompliance noted
BUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/14 2pp

--7905070084 IE Insp Repts 50-327/79-14 & 50-328/79-09 on 790212-15 No noncompliance noted Major areas inspected mgt control, environ monitoring data, analytical sensitivity for radiological samples & GC measures.
PERY, W W Region 2, Atlanta, Fuel Facility & Materials Safety Branch
MACARTHUR, T C, HUFHAM, J W Region 2, Atlanta, Office of the Director 79/03/13 3pp

7905240292 Forwards IE Insp Repts 50-327/79-11 & 50-328/79-06 on 790205-07 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/20 2pp

--7905240307 IE Insp Repts 50-327/79-11 & 50-328/79-06 on 790205-07 No noncompliance noted Major areas inspected licensee action on previous insp findings & environ qualification of safety-related electrical equipment
O'BONN, T D Region 2, Atlanta, Office of the Director
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/14 3pp.

7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905010113 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/28 2pp

7905010363 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/30 2pp.

DOCKETED ITEMS

7905240483 Forwards IE Insp Rept 50-327/79-16 on 790213-0216 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/04 2pp

--7905240491 IE Insp Rept 50-327/79-16 on 790213-0216 No noncompliance noted Major areas inspected startup test procedures, crane testing, fuel handling equipment testing & review of boron analysis procedures
BURNETT, P Y, SAUER, R C Region 2, Atlanta, Office of the Director MARTIN, R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/03 5pp

79053030368 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp

79053040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp

7905110365 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905010341 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts "
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/04/16 1p

7905030172 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp

7905020495 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp

7905300253 Submits supplemental response to IE Bulletin 77-07 Original response submitted 780120 Provides addl info received from manufacturer & describes plans in area of electrical penetrations
GILLELAND, J E Tennessee Valley Authority 79/04/27 5pp

7905140272 Responds to IE Bulletins 79-06A & 79-06A, Revision 1, re review of operational errors during TMI, Pressurizer level bistables in coincident safety injection logic circuits will remain tripped except during testing
GILLELAND, J F Tennessee Valley Authority 79/05/07 1p

7905290363 Forwards Revision 7 to "Preservice Baseline Insp & Inservice Insp Program for TVA" incorporating responses to Matl Engineering Branch 781208 questions
GILLELAND, J E Tennessee Valley Authority 79/05/22 83pp

----- & related correspondence -----

deficiency rept re vibration in
authority 79/03/09 1p

during preoperational pipe
occurred near
stallation of RHR flow
studied.
09 2pp

frequency
GILLELAND, J E Tennessee Valley Authority 79/03/27 1p

--7905140497 Final deficiency rept forced vibration test showed RHR pump 1A natural frequency does not meet design requirements RHR sys was reanalyzed, resulting in changed nozzle loads on pump & local pipe supports to meet new support loads
* Tennessee Valley Authority 79/03/27 1p

7905140446 Forwards final deficiency rept re safety injection sys accumulator level transmitter lines.
GILLELAND, J E Tennessee Valley Authority, 79/03/30, 1p

--7905140451 Final deficiency rept use of Class O instead of Class G safety injection sys accumulator level transmitter lines from root valves to flanges. Nonsafety-grade, nonseismic Category I piping will be replaced
* Tennessee Valley Authority 79/03/30 1p

7905140352 Forwards final deficiency rept re overheating of bearings motor-driven auxiliary feedwater pumps.
GILLELAND, J E Tennessee Valley Authority 79/04/09 1p

--7905140363 Final deficiency rept, during initial operation, bearings motor-driven auxiliary feedwater pumps were overheating
Caused by design error Ingersoll-Rand presently modifying pumps
* Tennessee Valley Authority 79/04/09 1p

7905140468 Forwards first deficiency rept re incorrect analysis of essential raw cooling water sys piping over total temp range
GILLELAND, J E Tennessee Valley Authority 79/04/18 2pp

--7905140473 First interim deficiency rept essential raw cooling water sys piping in auxiliary bldg Piping not analyzed for full thermal range defined in ASME code. Reanalysis in progress
* Tennessee Valley Authority 79/04/18, 1p

7905140458 Forwards deficiency rept re incorrect weight of swing check valves
GILLELAND, J E Tennessee Valley Authority 79/04/19 1p

--7905140464 Deficiency rept weight of swing check valves mfg by Vels Engineering Co was incorrect on Velan drawing 78704 Weight shown was 225 lb should have been 450 lb Piping containing valves being analyzed
* Tennessee Valley Authority 79/04/19 1p

7905140495 Forwards first interim deficiency rept re overstressed penetrations in containment shell.
GILLELAND, J E Tennessee Valley Authority 79/04/19 1p

--7905140500 First interim rept deficient design of four penetrations insert plate around containment spray & residual heat removal sys containment nozzles Computer models of piping supports revised & info sent to contractor for analysis
* Tennessee Valley Authority 79/04/19 1p

7905040562 Forwards final deficiency rept re diesel generator relay tachometer failures reported 790130 All overheated diodes replaced & tachometers closely monitored
GILLELAND, J E Tennessee Valley Authority 79/04/30 3pp

7905090333 Forwards final rept re installation of improper coils in auxiliary feedwater & emergency gas treatment sys
GILLELAND, J E Tennessee Valley Authority, 79/05/01, 2pp

--7905090336 Final deficiency rept, during preoperational testing four instances were found where improper coils were installed in control circuits Design drawing altered & correct coils procured
GILLELAND, J E Tennessee Valley Authority 79/05/01 1p

7905110191 Forwards final rept of deficiency initially reported 790411 re fire hazard analysis.
GILLELAND, J E Tennessee Valley Authority 79/05/04 1p

--7905110195 Deficiency rept, vapor barrier is combustible & constitutes fire load not considered in fire hazard analysis Batt will be covered w/1-inch thick stainless steel plate in Units 1 & 2
* Tennessee Valley Authority 79/05/04, 1p

7905190197 Provides second interim rept of 790208 deficiency re vibration in RHR piping. Variable spring supports added to valve operators & one pipe support installed. Vibration problems resolved.
GILLELAND, J E Tennessee Valley Authority 79/05/08 1p

7905160303 Provides final deficiency rept on control loop bistables failing to an undesirable position on loss of control power
w/o encl
GILLELAND, J E Tennessee Valley Authority 79/05/10, 1p

7905230562 Forwards final deficiency rept on potential excessive water hammer forces in main feedwater sys
GILLELAND, J E Tennessee Valley Authority 79/05/16 1p

--7905230569 Final deficiency rept: potential excessive water hammer forces in main feedwater sys Procedures implemented at design stage to prevent recurrence.
* Tennessee Valley Authority, 79/05/16 2pp.

7905230645 Forwards final deficiency rept on incorrect thermal analysis of piping
GILLELAND, J E Tennessee Valley Authority, 79/05/17 1p.

DOCKETED ITEMS

141

--7905230654 Final deficiency rept incorrect thermal analysis of piping which was not analyzed over total temp range as defined by ANSI std. New analyses performed for some piping in auxiliary bldg & Unit 1 reactor bldg
* Tennessee Valley Authority 79/05/17 2pp

DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

7905030080 Responds to 790412 ltr requesting facility be responsible for monitoring discharges. Monitoring is planned by TVA & required by NRC. Ltr is being referred to NRC for more specific response
KAPLAN, C. H. Environmental Protection Agency 79/04/26 1p

7905040500 Forwards description of filters to remove air discharged from auxiliary bldg. Changes implemented pursuant to 790730-31 OL hearings
MILLS, L. M. Tennessee Valley Authority 79/04/30 6pp

7905070554 Requests mod of state certification of Natl Pollution Discharge Elimination Sys permit TN0026450 re conditions Ad & 4e
MOORE, H. G. Tennessee Valley Authority 79/05/01 2pp

790510314 Submits Amend 61 to application consisting of revisions to certain chapters, responses & revised responses to NRC questions. Further documentation to items already transmitted & FSAR text changes w/o encl
OILLELAND, J. E. Tennessee Valley Authority 79/05/24 1p

E NRC Safety Evaluation Report (SER), supplis & correspondence

7905110008 Forwards TVA's responses to five SER outstanding confirmatory items. Responses will be incorporated into Amend 61 of FSAR.
OILLELAND, J. E. Tennessee Valley Authority 79/05/08 43pp

7905230519 Forwards comments from review of Mar 1979 SER apparent discrepancies between SER content & info provided to NRC supporting license application
OILLELAND, J. F. Tennessee Valley Authority 79/05/17 5pp

F Security, medical, emergency & fire protection plans

7905150649 Forwards comments which should be incorporated into modified amended security plan. Comments withheld (ref 10CFR2 790)
VARGA, S. A. Light Water Reactors Branch 4 79/04/27 2pp

7905070420 Forwards revisions to physical security plan. Revisions withheld (ref 10CFR2 790)
OILLELAND, J. E. Tennessee Valley Authority 79/05/01 1p

7905090341 Submits requested info on radiological emergency plan. Changes made plan consistent w/TVA responses to NRC questions on Watts Bar Nuclear Plant. Will forward final revision by 790615
OILLELAND, J. E. Tennessee Valley Authority 79/05/07 150pp.

J Insurance & indemnity information

7905010527 Forwards ANI Secondary Financial Protection Binder EB-46
DUCK, J. R. Marsh & McLennan, M & M Nuclear Consultants, Inc Div 79/04/25 6pp

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHHI, J. American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01 1p

K Utility Final Safety Analysis Report (FSAR) & amends

7905300299 Amend 61 to FSAR
* Tennessee Valley Authority. 79/05/25 250pp

7905300305 Forwards nonproprietary version of FSAR Table G7 60-1, as revised by Amend 61
OILLELAND, J. E. Tennessee Valley Authority 79/05/25 5pp

P Operating license stage documents & correspondence

7905020490 Discusses 790315 telcon w/R Sero of Westinghouse re incorrect weights for Velan Model C638 6-inch check valves used in safety injection sys
SCHWENGER, A. Operating Reactors Branch 1 79/04/02 1p

Q Inspection reports, IE Bulletins & correspondence

7905020435 Forwards IE Insp Repts 50-327/79-13 & 50-328/79-08 on 790206-09 No noncompliance noted
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/08 2pp

--7905020442 IE Insp Repts 50-327/79-13 & 50-328/79-08 on 790206-09 No noncompliance noted. Major areas inspected auxiliary bldg const status, storage & housekeeping of electrical panels & review of instrumentation records
WALTERS, D. K. Region 2, Atlanta, Office of the Director
BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/07 3pp

7905070078 Forwards IE Insp Repts 50-327/79-14 & 50-328/79-09 on 790212-15 No noncompliance noted.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/14 2pp

--7905070084 IE Insp Repts 50-327/79-14 & 50-328/79-09 on 790212-15 No noncompliance noted. Major areas inspected mgt control, environ monitoring data, analytical sensitivity for radiological samples & QC measures
PERY, W. W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch
MACARTHUR, T. C., HUFHAM, J. W. Region 2, Atlanta, Office of the Director 79/03/13 3pp

7905240292 Forwards IE Insp Repts 50-327/79-11 & 50-328/79-06 on 790205-07 No noncompliance noted
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/20 2pp

--7905240307 IE Insp Repts 50-327/79-11 & 50-328/79-06 on 790205-07 No noncompliance noted. Major areas inspected licensee action on previous insp findings & environ qualification of safety-related electrical equipment
OIBBONS, T. D. Region 2, Atlanta, Office of the Director
BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/14 3pp

7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905030368 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 3pp

7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 3pp

DOCKETED ITEMS

7905140272 Responds to IE Bulletins 79-06A & 79-06A, Revision 1, re review of operational errors during TMI Pressurizer level bistables in coincident safety injection logic circuits will remain tripped except during testing
GILLELAND, J F Tennessee Valley Authority 79/05/07 1p

7905290363 Forwards Revision 7 to "Preservice Baseline Insp & Inservice Insp Program for TVA" incorporating responses to Matl Engineering Branch 781208 questions
GILLELAND, J E Tennessee Valley Authority 79/05/22 83pp

B Reportable occurrences, LERs & related correspondence

7905160455 Forwards first interim deficiency rept re vibration in RHR piping
GILLELAND, J E Tennessee Valley Authority 79/03/09 1p

--7905160460 First interim deficiency rept during preoperational pipe vibration testing, excessive vibration occurred near butterfly valves Caused by improper installation of RHR flow control valves Corrective actions being studied
* Tennessee Valley Authority 79/03/09 2pp

7905140496 Forwards final deficiency rept re RHR pump 1A natural frequency
GILLELAND, J E Tennessee Valley Authority 79/03/27 1p

--7905140497 Final deficiency rept forced vibration test showed RHR pump 1A natural frequency does not meet design requirements RHR sys was reanalyzed, resulting in changed nozzle loads on pump & local pipe supports to meet new support loads
* Tennessee Valley Authority 79/03/27 1p

7905140446 Forwards final deficiency rept re safety injection sys accumulator level transmitter lines
GILLELAND, J E Tennessee Valley Authority 79/03/30 1p

--7905140451 Final deficiency rept use of Class O instead of Class C safety injection sys accumulator level transmitter lines from root valves to flanges Nonsafety-grade, nonseismic Category I piping will be replaced
* Tennessee Valley Authority 79/03/30 1p

7905140352 Forwards final deficiency rept re overheating of bearings in motor-driven auxiliary feedwater pumps
GILLELAND, J E Tennessee Valley Authority 79/04/09 1p

--7905140363 Final deficiency rept during initial operation, bearings in motor-driven auxiliary feedwater pumps were overheating Caused by design error Ingersoll-Rand presently modifying pumps
* Tennessee Valley Authority 79/04/09 1p

7905140468 Forwards first deficiency rept re incorrect analysis of essential raw cooling water sys piping over total temp range
GILLELAND, J E Tennessee Valley Authority 79/04/18 2pp

--7905140473 First interim deficiency rept essential raw cooling water sys piping in auxiliary bldg Piping not analyzed for full thermal range defined in ASME code Reanalysis in progress
* Tennessee Valley Authority, 79/04/18 1p

7905140458 Forwards deficiency rept re incorrect weight of swing check valves
GILLELAND, J E Tennessee Valley Authority 79/04/19 1p

--7905140464 Deficiency rept weight of swing check valves mfg by Velan Engineering Co was incorrect on Velan drawing 78704 Weight shown was 228 lbs, should have been 450 lb Piping containing valves being analyzed
* Tennessee Valley Authority 79/04/19 1p

7905140495 Forwards first interim deficiency rept re overstressed penetrations in containment shell
GILLELAND, J E Tennessee Valley Authority, 79/04/19 1p

--7905140500 First interim rept deficient design of four penetrations in insert plate around containment spray & residual heat removal sys containment nozzles Computer models of piping supports revised & info sent to contractor for analysis
* Tennessee Valley Authority 79/04/19 1p

7905040562 Forwards final deficiency rept re diesel generator relay tachometer failures reported 790130 All overheated diodes replaced & tachometers closely monitored
GILLELAND, J E Tennessee Valley Authority 79/04/30 3pp

7905110191 Forwards final rept of deficiency initially reported 790404 re fire hazard analysis
GILLELAND, J E Tennessee Valley Authority 79/05/04 1p.

--7905110195 Deficiency rept vapor barrier is combustible & const fire load not considered in fire hazard analysis Bolt will be covered w/1-inch thick stainless steel plate in Units 1 & 2
* Tennessee Valley Authority 79/05/04 1p

7905190197 Provides second interim rept of 790208 deficiency re vibration in RHR piping Variable spring supports added to valve operators & one pipe support installed Vibration problem resolved
GILLELAND, J E Tennessee Valley Authority 79/05/08 1p

7905160303 Provides final deficiency rept on control loop bistable failing to an undesirable position on loss of control power w/o encl
GILLELAND, J E Tennessee Valley Authority 79/05/10 1p

7905230562 Forwards final deficiency rept on potential excessive hammer forces in main feedwater sys.
GILLELAND, J E Tennessee Valley Authority 79/05/16 1p

--7905230569 Final deficiency rept potential excessive water hammer forces in main feedwater sys Procedures implemented at design stage to prevent recurrence
* Tennessee Valley Authority 79/05/16 2pp

7905230645 Forwards final deficiency rept on incorrect thermal analysis of piping
GILLELAND, J E Tennessee Valley Authority, 79/05/17 1p

--7905230654 Final deficiency rept incorrect thermal analysis of which was not analyzed over total temp range, as defined by ANSI std New analyses performed for some piping in auxiliary bldg & Unit 1 reactor bldg
* Tennessee Valley Authority 79/05/17 2pp

DOCKET 50-329 MIDLAND PLANT, UNIT 1

A Application/construction stage documents & correspondence

7905290415 Notification of 790509 meeting w/util in Bethesda, MD to discuss status of safety & environmental review schedule Date changed from 790403
HOOD, D B Light Water Reactors Branch 4 79/03/23 3pp

7905040462 Responds to NRC 790412 ltr. Discusses analysis of cool lake impact on local traffic due to icing & fogging NRC requires fog/ice monitoring programs Describes relevant studies
CARBON, J E Argonne National Laboratory 79/04/23 3pp.

7905310360 Indicates state will withhold Section 401(a)(1) of certification of facilities until EIS is approved by MI Environ Review Board
TANNER, H A Michigan, State of 79/05/17 2pp

7905250526 Responds to NRC 781011 ltr. Forwards "Investigation of Thermal Plume in Shallow River, Hydrothermal Model Studies, Cooling Pond Blowdown Discharge" & "Midland Power Plant Cooling Pond Operation Study"
HOWELL, B H Consumers Power Co 79/05/21 1p.

--7905250528 "Investigation of Thermal Plume in Shallow River, Hydrothermal Model Studies, Cooling Pond Blowdown Discharge," prepared by Alden Research Lab for facility.
ROBERGE, J C, NYQUIST, R O Consumers Power Co. 45-79/M124F 79/04/30. 79pp

--7905250530 "Midland Plant Cooling Pond Operation Study," prepr
Bechtel
LIQU, C. P., PAPADAKIS, C N Consumers Power Co. 45-79/M124F 79/03/31 60pp.

C Utility Environmental Report (ER), amends & correspondence

7905030358 Forwards Amend 64 to CP & DL.
HOWELL, B H Consumers Power Co. 79/04/30 1p

--7905030362 Amend 64 to CP & DL, consisting of revised pages for Revision 8 to environ rept.
HOWELL, B H Consumers Power Co 79/04/30 41pp.

7905110207 Forwards affidavit of distribution of environ rept. DL Amend 64, Revision 8
DADUD, L. Consumers Power Co 79/05/07. 4pp.

DOCKETED ITEMS

143

Q Adjudicatory correspondence

790525023B Forwards IOCR50 55(a) repts re spray piping supports
QIBBS, M E Isham, Lincoln & Beale 79/03/23 1p

7905160216 Forwards final evaluation of items discussed in 790228 memo
re B&W-designed nuclear plants Requests addl info be
forwarded to licensing boards
MOSELEY, N C Division of Reactor Operations Inspections 79/03/28
10pp

7905160163 Forwards Board Notification 79-10 on reactor inspector
concerns re B&W plants Certificate of Svc encl
SCINTO, J F Hearings Division 79/03/29 14pp

--7905160185 Board notification reactor inspector concerns re B&W plants
VASSALLO, D B Assistant Director for Light Water Reactors
79/03/06 2pp

--7905160201 Forwards two Moseley-to-Thompson memos for Board
notification info
THOMPSON, D Office of I & E Executive Officer for Operations
Support 79/03/29 1p

--7905160209 Informs that preliminary evaluation of Item 3 contained in
790328 memo will be reviewed in light of TMI transient Addl
info may cause change in previous assessment
MOSELEY, N C Division of Reactor Operations Inspections
79/03/29 1p

7905240493 Notice of appearance on behalf of NRC
DAMBLY, D C Operations & Administrative Division 79/03/30 1p

7905290438 Response to 790104 order by all intervenors except Dow
Chemical Co Urges thorough examination of util's conduct.
Certificate of Svc encl
FLYNN, P Cherry, M M /Cherry, Flynn & Kanter 79/03/30 20pp

7905310028 NRC response to ASLB 790104 order requesting addl info from
parties. Designates portions of prior record for
consideration Provides names of persons having relevant
info Certificate of Svc encl
OLMSTEAD, W J, HOEFLING, R K Branch 4 DAMBLY, D Operations &
Administrative Division 79/03/30 9pp

7905160112 Board notification nuclear incident at TMI. Recommends boards
on cases involving B&W reactors be provided w/IE Bulletin
79-05 & PND-67 & 67A, B, C, D, E, F, G & H
VASSALLO, D B Assistant Director for Light Water Reactors
79/04/03 2pp

7905250163 Revises description of cooling sys for special preheating
conference order
QIBBS, M E Isham, Lincoln & Beale 79/04/03 2pp

7905290340 Forwards interim rept re discrepancies discovered in inboard
terminal boxes of electrical penetration assemblies.
QIBBS, M E Isham, Lincoln & Beale 79/04/03 1p

7905290108 Notice of preheating conference to begin on 790501 in
Bethesda, MD
HILLER, M E Atomic Safety and Licensing Board Panel 79/04/09 1p.

7905130240 Opposes 790330 motion by util for summary disposition re
Part 2 of ASLB 790104 order re remanded issues Motion is
premature since no preheating conference has yet been held
Certificate of Svc encl
OLMSTEAD, W J Branch 4 79/04/19 3pp

7905130233 Memo & order ALAB-541 denies 790424 motion by intervenors to
postpone & relocate 790501 preheating conference Allows ASLB
to reconsider 790409 order
DUFLD, M E Atomic Safety and Licensing Appeal Panel 79/04/27
5pp

7905240885 Denies intervenors 790424 motion to reschedule 790501
preheating conference or change location of hearing
HILLER, M E Atomic Safety and Licensing Board Panel 79/04/27
7pp

--7905240891 Motion by intervenors to schedule 790501 preheating
conference & change location of hearing
FLYNN, P Cherry, M M /Cherry, Flynn & Kanter 79/04/24 3pp

--7905240899 Urges postponement of 790501 preheating conference, due to
inability of intervenor's counsel to attend
FLYNN, P Cherry, M M /Cherry, Flynn & Kanter 79/04/24 5pp

H General correspondence

7905090307 Forwards Certificate of Svc of Amend 63 (Revision 20 to
F8AR) to application for CP & OL
BACON, J L Consumers Power Co 79/05/02 2pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHINI, J American Nuclear Insurers 79/05/01 1p

K Utility Final Safety Analysis Report (F8AR) & amends

7905030308 Forwards Amend 63 to application for CP & OL which
constitutes Revision 20 to F8AR Certificate of Svc & revised
matl to supplemental ref drawings encl
HOWELL, B H Consumers Power Co 79/04/26 2pp

--7905030311 Revision 20 to F8AR
* Consumers Power Co 79/04/26 240pp

M Antitrust correspondence

7905230832 Requests antitrust info for addl ownership participants to
expedite processing of amend or transfer of licenses
TOALSTON, A L Antitrust & Indemnity Group 79/04/23 4pp

Q Inspection reports, IE Bulletins & correspondence

7905020166 Forwards IE Insp Repts 50-329/78-20 & 50-330/78-20 on
781211-13, 18-20, 790104-05, 09-11, 22-25, 0223 & 0305
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/22
2pp

--7905020172 IE Insp Repts 50-329/78-20 & 50-330/78-20 on 781211-13,
18-20, 790104-05, 09-11, 22-25, 0223 & 0305 No noncompliance
noted Major areas inspected diesel generator bldg
foundations & unusual settlement of bldg
FIORELLI, G Region 3, Chicago, Reactor Construction &
Engineering Support Branch NORELIUS, C E, HAYES, D W Region 3,
Chicago, Office of the Director 79/03/19 29pp

7905010249 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/23
1p

7905080329 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/26
1p

7905290283 Forwards IE Insp Repts 50-329/79-04 & 50-330/79-04 on
790207 No noncompliance noted
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/03/29 2pp

--7905290296 IE Insp Repts 50-329/79-04 & 50-330/79-04 on 790207 No
noncompliance noted Major areas inspected project status;
concerns re recent developments onsite & upcoming insp
activity
COOK, R J, HANSEN, W A Region 3, Chicago, Office of the
Director KNOPF, R C Region 3, Chicago, Reactor Construction &
Engineering Support Branch 79/03/27 4pp

7905240724 Forwards IE Insp Repts 50-329/79-06 & 50-330/79-06 on
790328-29 No noncompliance noted
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/04/09, 2pp

--7905240734 IE Insp Repts 50-329/79-06 & 50-330/79-06 on 790328-29 No
noncompliance noted Major areas inspected followup
IOCR50 55(a) rept re settlement of diesel generator bldg
& plant area fill
CALLAGHER, E J, HAYES, D W Region 3, Chicago, Office of the
Director 79/04/04 7pp

7905030022 Forwards IE Bulletin 79-06, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/11
1p

DOCKETED ITEMS

7905010583 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
1p

7905040331 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
1p

7905040465 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
1p

7905040546 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
1p

7905010387 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/16
1p

7905030219 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/17
1p

7905080404 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl 1"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/21
1p

R Periodic operating reports & related correspondence

7905300478 Forwards nonconformance repts for Apr 1979
HOWELL, S H Consumers Power Co 79/05/25 1000pp

B Reportable occurrences, LERs & related correspondence

7905290330 Ack receipt of 790309 final rept re air filtering units
Review will be finished upon completion of corrective action
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/23 1p

7905240349 Ack receipt of 790330 rept re electrical penetration
assembly final rept will be reviewed upon receipt
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/06 1p

7905140219 Forwards nonconformance repts for Mar 1979, consisting of
Bechtel nonconformance repts, Bechtel nonconformance log,
Bechtel quality audit findings, Bechtel quality action requests, B&W repts of nonconformity & util repts.
HOWELL, S H Consumers Power Co 79/04/25 440pp

7905070501 Final deficiency rept reactor bldg spray anchor discrepancy
Local pipe stresses may potentially exceed ASME Code Section III allowable at points Existing procedural methods are adequate
* Consumers Power Co 79/04/27 4pp.

7905090082 Provides interim deficiency rept on actions to resolve
settlement of diesel generator foundations & bldg
HOWELL, S H Consumers Power Co 79/04/30 2pp

--7905090084 Interim Deficiency Rept 5: settlement of diesel generator foundations & bldg Caused by insufficient compaction in area
fill re seismic Category I structures. Lists status & corrective actions. W/62 oversized drawings.
* Consumers Power Co 79/04/16 10pp

7905030327 Final rept re reactor bldg spray piping supports. Analysis
has verified adequacy of support design & ASME Section III Code allowable stresses Bechtel mgt corrective action
rept MCAR 22 encl.
HOWELL, S H Consumers Power Co 79/05/01 7pp

7905080522 Forwards interim rept on status of component qualification
test documentation re review Forwards Bechtel "Qualification Test Status Rept." Similar B&W rept will be reviewed Another
rept will be sent by 790706.
HOWELL, S H Consumers Power Co 79/05/04 2pp.

--7905080536 Interim rept on seismic & environ component qualification,
forwarding "Qualification Test Status Rept." Revision 7, dtd
790406,
BALTAZAR, R Z Bechtel Power Corp (subs of Bechtel Corp)
79/04/20 39pp

7905300252 Forwards final rept re discrepancies discovered in inboard
terminal boxes
HOWELL, S H Consumers Power Co 79/05/25 5pp

--7905300256 Final deficiency rept on 790523 defects discovered in
penetration assemblies in inboard terminal boxes, possibly
caused by type of termination lug used insp of terminations
conducted
* Consumers Power Co 79/05/23 4pp

T Hearing transcripts on non-antitrust matters

7905140564 Transcript of 790501 prehearing conference in Bethesda, MD
Pp 50, 601-50, 171
MILLER, M E LUEBKE, LEEDS Atomic Safety and Licensing Board Panel
79/05/01 171pp

DOCKET 50-330 MIDLAND PLANT, UNIT 2

A Application/construction stage documents & correspondence

7905290415 Notification of 790509 meeting w/util in Bethesda, MD to
discuss status of safety & environmental review schedule
Date changed from 790403
HOOD, D S Light Water Reactors Branch 4 79/03/23 3pp

7905040462 Responds to NRC 790412 ltr Discusses analysis of cooling
lake impact on local traffic due to icing & fogging
NRC requires fog/ice monitoring programs Describes relevant
studies
CARSON, J E Argonne National Laboratory 79/04/23 3pp

7905310360 Indicates state will withhold Section 401(a)(1) of
certification of facilities until EIS is approved by MI
Environ Review Board
YANNER, M A Michigan, State of 79/05/17 2pp

7905250526 Responds to NRC 781011 ltr Forwards "Investigation of
Thermal Plume in Shallow River, Hydrothermal Model Studies,
Cooling Pond Blowdown Discharge" & "Midland Power Plant
Cooling Pond Operation Study"
HOWELL, S H Consumers Power Co 79/05/21 1p

--7905250528 "Investigation of Thermal Plume in Shallow River,
Hydrothermal Model Studies, Cooling Pond Blowdown Discharge,"
prepared by Alden Research Lab for facility
ROBERGE, J C, NYQUIST, R G Consumers Power Co. 45-79/H124AF
79/04/30 79pp

--7905250530 "Midland Plant Cooling Pond Operation Study," prepared by
Bechtel.
LIDU, C P, PAPADAKIS, C N Consumers Power Co 45-79/H124AF
79/03/31 60pp.

C Utility Environmental Report (ER), amendments & correspondence

7905030338 Forwards Amend 64 to CP & QL.
HOWELL, S H Consumers Power Co 79/04/30 1p

--7905030362 Amend 64 to CP & QL, consisting of revised pages for
Revision 8 to environ rept.
HOWELL, S H Consumers Power Co 79/04/30 41pp.

7905110207 Forwards affidavit of distribution of environ rept. QL steps.
Amend 64, Revision 8
DACUD, L Consumers Power Co 79/05/07 4pp.

D Adjudicatory correspondence

7905250239 Forwards 10CFR50.55(a) repts re spray piping supports
OIBBS, M E, Isham, Lincoln & Beale, 79/03/23 1p.

7905160216 Forwards final evaluation of items discussed in 790228 memo
re B&W-designed nuclear plants Requests addl info be
forwarded to licensing boards.
MOBLEY, N C Division of Reactor Operations Inspections. 79/03/28
10pp

7905160163 Forwards Board Notification 79-10 on reactor inspector concerns re B&W plants Certificate of Svc encl
SCINTO, J F Hearings Division 79/03/29 14pp

--7905160185 Board notification reactor inspector concerns re B&W plants
VASSALLO, D B Assistant Director for Light Water Reactors
79/03/06 2pp

--7905160201 Forwards two Mosley-to-Thompson memos for Board notification info
THOMPSON, D Office of I & E Executive Officer for Operations Support 79/03/29 1p

--7905160209 Informs that preliminary evaluation of Item 3 contained in 790328 memo will be reviewed in light of TMI transient Addl info may cause change in previous assessment
MOSELY, N C Division of Reactor Operations Inspections
79/03/29 1p

7905240493 Notice of appearance on behalf of NRC
DAMBLY, D C Operations & Administrative Division 79/03/30 1p

7905250438 Response to 790104 order by all intervenors except Dow Chemical Co Urges thorough examination of util's conduct Certificate of Svc encl
FLYNN, P Cherry, M M /Cherry, Flynn & Kanter 79/03/30 20pp

7905310028 NRC response to ASLB 790104 order requesting addl info from parties Designates portions of prior record for consideration Provides names of persons having relevant info Certificate of Svc encl
OLMSTEAD, W J ; HOEFLING, R K Branch 4 DAMBLY, D Operations & Administrative Division 79/03/30 9pp

7905160112 Board notification nuclear incident at TMI Recommends boards on cases involving B&W reactors be provided w/IE Bulletin 79-05, & PNO-67 & 67A, B, C, D, E, F, G & H
VASSALLO, D B Assistant Director for Light Water Reactors
79/04/03 2pp

7905250163 Revises description of cooling sys for special prehearing conference order
GIBBS, M E Isham, Lincoln & Beale 79/04/03 2pp

7905290540 Forwards interim rept re discrepancies discovered in inboard terminal boxes of electrical penetration assemblies
GIBBS, M E Isham, Lincoln & Beale 79/04/03 1p

7905290108 Notice of prehearing conference to begin on 790501 in Bethesda, MD
MILLER, M E Atomic Safety and Licensing Board Panel 79/04/09 1p

7905150240 Opposes 790330 motion by util for summary disposition re Part 2 of ASLB 790104 order re remanded issues Motion is premature since no prehearing conference has yet been held Certificate of Svc encl
OLMSTEAD, W J Branch 4 79/04/19 5pp

7905150233 Memo & order ALAD-541 denies 790424 motion by intervenors to postpone & relocate 790301 prehearing conference Allows ASLB to reconsider 790409 order
DUFFLO, M E Atomic Safety and Licensing Appeal Panel 79/04/27 5pp.

7905240885 Denies intervenors 790424 motion to reschedule 790301 prehearing conference or change location of hearing.
MILLER, M E Atomic Safety and Licensing Board Panel 79/04/27 7pp

--7905240891 Motion by intervenors to schedule 790301 prehearing conference & change location of hearing.
FLYNN, P Cherry, M M /Cherry, Flynn & Kanter 79/04/24 3pp.

--7905240899 Urges postponement of 790301 prehearing conference, due to inability of intervenor's counsel to attend
FLYNN, P Cherry, M M /Cherry, Flynn & Kanter. 79/04/24 5pp

H General correspondence

7905090307 Forwards Certificate of Svc of Amend 63 (Revision 20 to FSAR) to application for CP & OL
BACON, J. L. Consumers Power Co 79/05/02 2pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 183, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHI, J American Nuclear Insurers 79/05/01 1p.

K Utility Final Safety Analysis Report (FSAR) & amends

7905030308 Forwards Amend 63 to application for CP & OL which constitutes Revision 20 to FSAR Certificate of Svc & revised matl to supplemental ref drawings encl
HOWELL, S M Consumers Power Co. 79/04/26 2pp

--7905030311 Revision 20 to FSAR
* Consumers Power Co 79/04/26 240pp

M Antitrust correspondence

7905230832 Requests antitrust info for addl ownership participants to expedite processing of amend or transfer of license
TOALSTON, A L Antitrust & Indemnity Group 79/04/23 2pp

Q Inspection reports, IE Bulletins & correspondence

7905020166 Forwards IE Insp Repts 50-329/78-20 & 50-330/78-20 on 781211-13, 18-20, 790104-05, 09-11, 22-25, 0223 & 0305
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/22 2pp

--7905020172 IE Insp Repts 50-329/78-20 & 50-330/78-20 on 781211-13, 18-20, 790104-05, 09-11, 22-25, 0223 & 0305 No noncompliance noted Major areas inspected diesel generator bldg foundations & unusual settlement of bldg
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch NORELIUS, C E, HAYES, D W Region 3, Chicago, Office of the Director 79/03/19 29pp

7905010249 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23 1p

7905080529 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26 1p

7905250283 Forwards IE Insp Repts 50-329/79-04 & 50-330/79-04 on 790207 No noncompliance noted
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/29 2pp

--7905250296 IE Insp Repts 50-329/79-04 & 50-330/79-04 on 790207 No noncompliance noted Major areas inspected project status, concerns re recent developments onsite & upcoming insp activity
COOK, R J, HANSEN, W A Region 3, Chicago, Office of the Director KNOPF, R C Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/27 4pp

7905240724 Forwards IE Insp Repts 50-329/79-06 & 50-330/79-06 on 790328-29 No noncompliance noted
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/09 2pp.

--7905240734 IE Insp Repts 50-329/79-06 & 50-330/79-06 on 790328-29 No noncompliance noted Major areas inspected followup 10CFR50.55(a) rept re settlement of diesel generator bldg & plant area fill
GALLAGHER, E J, HAYES, D W Region 3, Chicago, Office of the Director 79/04/04 7pp

7905030022 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/11 1p

7905010583 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/14 1p.

7905040631 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14. 1p

7905040463 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" License action required.
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040546 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14. 1p

DOCKETED ITEMS

7905010387 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/16 1p

7905030219 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/17 1p

7905080404 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI-Suppl."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/21 1p

R Periodic operating reports & related correspondence

7905300478 Forwards nonconformance repts for Apr 1979
HOWELL, S H Consumers Power Co 79/05/25 1000pp

S Reportable occurrences, LERs & related correspondence

7905290330 Ack receipt of 790309 final rept re air filtering units. Review will be finished upon completion of corrective action
FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/23 1p

7905240549 Ack receipt of 790330 rept re electrical penetration assembly. Final rept will be reviewed upon receipt
FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/06 1p

7905140219 Forwards nonconformance repts for Mar 1979, consisting of Bechtel nonconformance repts, Bechtel nonconformance log, Bechtel quality audit findings, Bechtel quality action requests, B&W repts of nonconformity & util repts
HOWELL, S H Consumers Power Co 79/04/25 440pp

7905070501 Final deficiency rept reactor bldg spray anchor discrepancy. Local pipe stresses may potentially exceed ASME Code Section III allowable at points existing procedural methods are adequate
* Consumers Power Co 79/04/27 4pp

7905090082 Provides interim deficiency rept on actions to resolve settlement of diesel generator foundations & bldg
HOWELL, S H Consumers Power Co 79/04/30 2pp

--7905090086 Interim Deficiency Rept 5 settlement of diesel generator foundations & bldg. Caused by insufficient compaction in area fill re seismic Category I structures. Lists status & corrective actions W/62 oversized drawings
* Consumers Power Co 79/04/16 10pp

7905030327 Final rept re reactor bldg spray piping supports. Analysis has verified adequacy of support design & ASME Section III Code allowable stresses. Bechtel mgt corrective action rept MCAR 22 encl
HOWELL, S H Consumers Power Co 79/05/01 7pp

7905080332 Forwards interim rept on status of component qualification test documentation re review. Forwards Bechtel "Qualification Test Status Rept." Similar B&W rept will be reviewed. Another rept will be sent by 790706
HOWELL, S H Consumers Power Co 79/05/04 2pp

--7905080536 Interim rept on seismic & environ component qualification, forwarding "Qualification Test Status Rept," Revision 7, dtd 790406
BALTAZAR, R Z Bechtel Power Corp (subs of Bechtel Corp) 79/04/20 39pp

7905300252 Forwards final rept re discrepancies discovered in inboard terminal boxes
HOWELL, S H Consumers Power Co 79/05/25 5pp

--7905300256 Final deficiency rept on 790523 defects discovered in penetration assemblies in inboard terminal boxes, possibly caused by type of termination lug used. Insp of terminations conducted.
* Consumers Power Co 79/05/23 4pp

T Hearing transcripts on non-antitrust matters

7905140544 Transcript of 790501 prehearing conference in Bethesda, MD. Ps 50,001-50,171
MILLER, M E, LUEBKE, LEEDS Atomic Safety and Licensing Board Panel 79/05/01, 171pp

DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

F Security, medical, emergency & fire protection plans

7905040491 Forwards modified physical security plan. Plan withheld (ref 10CFR2 790)
LIU, L Iowa Electric Light & Power Co 79/04/30 1p

7905090368 Informs that fire hazard analysis rept will be submitted by 790610, due to add analysis required by engineering staff & consultants
LIU, L Iowa Electric Light & Power Co 79/05/02 1p

7905080465 Advises of delay in security mod project, due to labor disagreement & supplier's delay in mfg of critical computer components
LIU, LEE Iowa Electric Light & Power Co 79/05/04 1p

7905310447 Discusses schedule delays re plant security program. Local electrical union contract will expire on 790601 & work stoppage may ensue
LIU, L Iowa Electric Light & Power Co 79/05/18 1p

Q Adjudicatory correspondence

7905150307 Forwards request to institute proceeding to suspend technical Amend 9 to License DPR-49. Also forwards pertinent FR notice
DENTON, H R Office of Nuclear Reactor Regulation 79/04/12 2pp

--7905150312 Request for suspension of technical Amend 9 to License DPR-49
HAGER, J E Citizens United for Responsible Energy 79/03/20 2pp

7905250025 Ack receipt of request to institute proceeding to suspend Amend 9 to License DPR-49. Request is presently under consideration. Relevant FR notice & petitioner's request for action encl
DENTON, H R Office of Nuclear Reactor Regulation 79/04/12 2pp

--7905250027 Notice of request to suspend Amend 9 to License DPR-49
DENTON, H R Office of Nuclear Reactor Regulation 79/04/12 1p

7905250439 Notification that Citizens for Responsible Energy filed petition seeking proceedings to suspend Amend 9 to License DPR-49
BOYD, R S Office of Nuclear Reactor Regulation 79/04/12 1p

7905150315 FR notice of request to suspend technical Amend 9 to License DPR-49
BOYD, R S Office of Nuclear Regulatory Research 79/04/12 1p

7905250031 Request for action to institute proceeding to suspend Amend 9 to License DPR-49 re handling of BNM
MEYERS, J E Citizens United for Responsible Energy 79/03/20 2pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
GUATRONGHINI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905160275 Forwards Amend 6 to Indemnity Agreement B-68, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 8pp

P Operating license stage documents & correspondence

7905090196 Forwards Amend 50 to License DPR-49, security plan evaluation (withheld ref 10CFR2 790) & notice of issuance & availability.
IPPOLITO, T A Operating Reactors Branch 3, 79/04/19 3pp

--7905090199 Amend 50 to License DPR-49, incorporating security plan which became effective on 790223.
IPPOLITO, T A Operating Reactors Branch 3, 79/04/19 2pp

DOCKETED ITEMS

147

--7903090201 Notice of issuance & availability of Amend 50 to License DPR-49
IPPOLITO, T A Operating Reactors Branch 3 79/04/19 2pp

7903080469 Informs of delay until 790630 of App I Tech Spec submittal originally scheduled for 790430 Consultant engaged on TMI project
LIU, L Iowa Electric Light & Power Co 79/03/02 1p

7903230522 Forwards bar-chart schedule showing time periods for installation of specific plant mods as part of Mark I containment long-term program Installation currently scheduled for Feb 1981 refueling outage
LIU, L Iowa Electric Light & Power Co 79/03/17 2pp

G Inspection reports, IE Bulletins & correspondence

7903090165 Forwards IE Insp Rept 50-331/79-07 on 790227-0301 No noncompliance noted
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/03/22 2pp

--7903090169 IE Insp Rept 50-331/79-07 on 790227-0301 No noncompliance noted Major areas inspected fire protection/prevention program & review of Tech Specs surveillance requirements for fire protection equipment
WRIGHT, O C Region 3, Chicago, Reactor Operations Nuclear Support Branch LITTLE, W S Region 3, Chicago, Office of the Director 79/03/16, 4pp.

7903010254 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/23 1p

7903230412 Forwards IE Insp Rept 50-331/79-06 on 790307-09 & notice of violation
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/03/23 2pp

--7903230420 Notice of violation from insp on 790307-09
* Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/03/21 1p

--7903230426 IE Insp Rept 50-331/79-06 on 790307-09 Noncompliance noted failure to submit QA program description for shipping packages as required.
MILLER, D F, HIATT, J W, Region 3, Chicago, Office of the Director FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/03/21 6pp

7903040031 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/26 1p

7903080204 Forwards IE Insp Rept 50-331/79-10 on 790206-07 & 0301-02
FIGURELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/27 2pp

--7903080211 IE Insp Rept 50-331/79-10 on 790206-07 & 0301-02 Major areas inspected ultrasonic baseline test results for welds involved in recirculation inlet piping repair & recirculation inlet nozzle N2O lead plug
KEY, W J, WILLIAMS, C C, DANIELSON, D H Region 3, Chicago, Office of the Director 79/03/23, 3pp

7903150126 Forwards IE Insp Rept 50-331/79-05 on 790127-31, 0205-06, 11-13 & 27 & notice of violation
HEISHMAN, R B Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/03/27, 2pp.

--7903150129 Notice of violation from insp on 790127-31, 0205-06, 11-13 & 27
* Region 3, Chicago, Office of the Director 79/03/23 1p

--7903150134 IE Insp Rept 50-331/79-05 on 790127-31 & 0205-06, 11-13 & 27 Noncompliance noted: failure to adhere to welding procedures
JACKIWI, I N, WALKER, R D Region 3, Chicago, Office of the Director SPEBBARD, R L Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/03/23 8pp

7903150424 Forwards IE Insp Rept 50-331/79-09 on 790108-12, 17-19, 24 & 29-31 & notice of violation
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/27 3pp.

--7903150429 Notice of violation from insp on 790108-12, 17-19, 24 & 29-31
* Region 3, Chicago, Office of the Director 79/03/27 1p

--7903150436 IE Insp Rept 50-331/79-09 on 790108-12, 17-19, 24 & 29-31 Noncompliance noted nonconformance repts improperly resolved & documented
WILLIAMS, C C, KEY, W J Region 3, Chicago, Office of the Director DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/23 21pp

7903010167 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/28 1p

7903010398 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/30 1p

7903230266 Forwards replacement pages for IE insp rept documents Revision reflects addition of insp dates 781212-13, 781218-21 & 781226-29, which were not previously included
FIGURELLI, O Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/04/06 1p

7903030031 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/11 1p

7903010588 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14 1p

7903040389 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14 1p

7903040435 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14 1p

7903040560 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14, 1p

7903190030 Responds to IE Bulletin 79-03 re pipe mfg by Youngstown Welding & Engineering Co Pipe is neither used nor planned for use in any safety-related sys at facility
LIU, L Iowa Electric Light & Power Co 79/04/16 1p

7903030227 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required.
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/17 1p

7903080496 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl 1"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/21 1p

7903030272 Responds to IE Bulletin 79-07 No methods specified in bulletin have been used Responses from NSSB supplier & A/E encl
LIU, L Iowa Electric Light & Power Co 79/04/24 3pp

7903110139 Ack receipt of 790413 ltr informing NRC of steps taken to correct violations noted in IE insp conducted on 790307-09
DAVIS, A Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/04/25, 3pp

--7903110163 Responds to NRC ltr re violation noted in IE insp conducted on 790307-09 Corrective actions QA program will be implemented by 790601.
LIU, L Iowa Electric Light & Power Co. 79/04/13 4pp

7903230213 Responds to IE Bulletin 79-08, Items 1-10, re TMI effect on BWRs. Response to Item 11 will be sent before 790518.
WALLACE, J A Iowa Electric Light & Power Co. 79/04/27 18pp

7903240902 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase."
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/02 1p.

DOCKETED ITEMS

R Periodic operating reports & related correspondence

7905210220 Forwards monthly operating rept for Apr 1979
HAMMOND, E L Iowa Electric Light & Power Co RC 79/03/14 1p

--7905210224 Monthly operating rept for Apr 1979
VAN SICKEL, J Iowa Electric Light & Power Co NRC 79/05/14
7pp

B Reportable occurrences, LERs & related correspondence

7905020251 Forwards LER 79-008/03L-0
HAMMOND, E L Iowa Electric Light & Power Co 79/04/25 1p

--7905020253 LER 79-008/03L-0 on 790326 pin hole leak discovered in
reactor water cleanup sys pipe Caused by linear indication
in weld attributed to intergranular stress corrosion
cracking Elbow & pipe on both ends replaced
VAN SICKEL, P J Iowa Electric Light & Power Co 79/04/25 1p

7905160363 Forwards LER 79-010/03L-0
HAMMOND, E L Iowa Electric Light & Power Co 79/05/08 1p

--7905160368 LER 79-010/03L-0 on 790410 containment purge inlet valve
CV 4306 & torus purge outlet valve CV 4300 not sealing
properly due to tee ring seals not being pressurized Caused
by actuator valve linkage being out of adjustment
VAN SICKEL, J Iowa Electric Light & Power Co 79/05/08 1p

7905160386 Forwards LER 79-009/03L-0
HAMMOND, E L Iowa Electric Light & Power Co 79/03/08 1p

--7905160387 LER 79-009/03L-0 on 790408 drain sump discharge valve
CV 3704 stuck Caused by corrosion in valve operator cylinder
was lubricated & design review will be initiated to
determine if oiling device can be installed
VAN SICKEL, J Iowa Electric Light & Power Co 79/03/08 2pp

7905290182 Forwards LER 79-011/03L-0
HAMMOND, E L Iowa Electric Light & Power Co 79/05/18 1p

--7905290191 LER 79-011/03L-0 on 790424 main exhaust radiation monitors
RIM 7606A & 7606B tripped at out-of-spec setpoints Caused
by instrument drift Monitors recalibr
VAN SICKEL, J Iowa Electric Light & Power Co 79/05/18 1p

DOCKET 50-332 BARNWELL REPROCESSING PLANT

G Inspection reports, IE Bulletins & correspondence

7905230782 Informs of deferral of corrective actions discussed in
IE Insp Rept 50-332/77-02 re bellow seal angle valves Future
facility operation uncertain due to NRC 771223 order
terminating licensing proceedings
BAXTER, R C Allied General Nuclear Services 79/03/14 1p

7905010132 Forwards IE Info Notice 79-08, "Interconnection of
Contaminated Sys w/Bvc Air Sys Used as Source of Breathing
Air."
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/03/28 1p

DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

7905140307 Forwards addl responses to draft safety evaluation of fire
protection program Discusses diesel fire room sprinkler head
spacing detector testing, piping penetration seal
qualification & flame retardant coating
EARLY, P J Power Authority State of New York, 79/03/07 9pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for
policies MF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHINI, J American Nuclear Insurers 79/03/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 84, 87,
88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters, 79/05/01.
1p

7905160162 Forwards Amend 7 to Indemnity Agreement B-63, per 10CFR140
changes, re liability insurance increase from \$140 million to
\$160 million, effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/03/01 3pp

7905110175 Forwards Endorsement 34 to MAELU Policy MF-77
DEEO, F H Power Authority State of New York 79/03/07 1p

7905220387 Forwards Amend 7 to Indemnity Agreement B-63, in response to
790501 request
CLARK, F R Power Authority State of New York 79/03/16 3pp

P Operating license stage documents & correspondence

7905080347 Assigns responsibility for prompt meeting notification re
790313 show cause orders
STELLID, V Division of Operating Reactors 79/03/29 3pp

7905210046 Responds to 790316 ltr Apologizes for difficulty in
obtaining info re space shutdown Clarifies role of Region I
re state notification
ORIER, B H Region I, Philadelphia, Office of the Director
79/04/12 2pp

7905040615 Forwards status rept on 790427 "Plan for Verification of
Dynamic Analysis Codes"
JACOBS, B B Stone & Webster Engineering Corp 79/04/27 2pp

7905040505 Responds to 790319 ltr Info requested re skyshine radiation
can be found in GE Nuclear Energy Sys Div rept, "Radiation
Measurements at JA Fitzpatrick Nuclear Power Plant"
EARLY, P J Power Authority State of New York 79/04/30 1p

7905080365 Forwards list of piping analyzed during original design of
plant using SHOCK II computer code
EARLY, P J Power Authority State of New York 79/04/30 7pp

7905090315 Proposes 790504 technical meeting w/NRC to discuss util
piping stress reanalysis & to show startup is reasonable
EARLY, P J Power Authority State of New York 79/03/01 1p

7905100175 Forwards application for amend to OL
EARLY, P J Power Authority State of New York 79/05/02 2pp

--7905100179 Application for amend to OL changing Tech Specs to add
limiting condition for operating & surveillance
requirements & revising administrative controls for
radiological effluents
EARLY, P J Power Authority State of New York 79/03/07 1p

--7905100183 Proposed Tech Spec changes re radiological effluents &
monitoring
Power Authority State of New York, 79/04/30 43pp

7905140239 Forwards proprietary documents requested during 790501-01
special insp.
ERLEWINE, J A Stone & Webster Engineering Corp 79/05/08 1p

--7905140245 Requests withholding Technical Guideline EMTG-22-0 &
Technical Rept EMTR-612 (ref 10CFR2, 790) Affidavit encl.
KENNEDY, W J Stone & Webster Engineering Corp 79/05/04 10pp

7905140382 Confirms 790504 telcon w/WT Russell re computer deci
associated w/SHOCK O program
KENNEDY, W J Stone & Webster Engineering Corp 79/05/09 1p

7905210111 Forwards SHOCK I computer program listing. Supersedes
submital of 790406 Program listing withheld (ref
10CFR2 790)
KENNEDY, W J Stone & Webster Engineering Corp 79/05/14 1p

7905190073 Ack receipt of 790315 & 21 ltrs re spent fuel racks Requests
extension of response time until 790525 Start of new spent
fuel rack installation scheduled for 790702 Requests
approval by 790611
EARLY, P J Power Authority State of New York, 79/05/15 1p

7905290335 Summarizes procedures & calculational techniques used in
reanalysis of piping sys designed w/SHOCK II computer
program. Reanalysis will satisfy 790313 order to show cause
KENNEDY, W J Stone & Webster Engineering Corp, 79/05/18, 4pp.

Q Inspection reports, IE Bulletins & correspondence

7905010127 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping."
ORIER, B. H. Region I, Philadelphia, Office of the Director.
79/03/23 1p.

DOCKETED ITEMS

149

7905010060 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Bys w/Bvc Air Sys Used as Source of Breathing Air"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/03/28 1p

7905010584 Responds to IE Bulletin 79-03 Welded pipe was not used at Facility
LEONARD, J D Power Authority State of New York 79/03/29 1p

7905010310 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/03/30, 2pp

7905230162 Responds to IE Bulletin 78-14, "Deterioration of Buna-N Components" Replacement of components during outage dependent upon plant startup, in view of pipe stress problems Replacement within seven years of packaging date
LEONARD, J D Power Authority State of New York 79/04/04 2pp

7905020072 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/11 1p

7905080246 Requests addl info to complete inservice testing program Info needed includes pumps, valves, core spray, reactor core isolation cooling sys, reactor water cleanup sys, control room area svc & chilled water
IPPOLITO, T A Operating Reactors Branch 3 79/04/12 8pp

7905020321 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040074 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/14, 1p

7905040249 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905240290 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" A/E currently testing seismic stress on safety-related piping, Results will be reported per show cause order issued 790313
LEONARD, J D Power Authority State of New York 79/04/16 1p

7905030083 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys" Licensee action required
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/17 1p

7905020296 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director
79/04/18 1p

7905250194 Responds to IE Bulletin 79-08, Mgt personnel reviewed procedures in operations dept which dealt w/operations & sys under abnormal conditions. Containment isolation & initiation design reviewed
LEONARD, J D Power Authority State of New York, 79/04/25 36pp.

7905150452 Informs that response to 790412 inquiry re inservice testing program was provided at 790425-26 meeting w/NRC & BNL Revised program based on meeting resolutions will be submitted.
EARLY, P J Power Authority State of New York 79/05/08 1p

7905230430 Supplements 790425 response to IE Bulletin 79-08 re TMI incident implications for BWRs Amend being developed to correct instrumentation tables in Tech Specs identified in bulletin. Summarizes nonsafety-related discrepancies
EARLY, P J Power Authority State of New York 79/05/18 2pp

R. Periodic operating reports & related correspondence

7905090343 Submits weekly status rept of B&W piping reanalysis, as of 790430.
EARLY, P J Power Authority State of New York, 79/05/01 2pp.

7905110254 Forwards monthly operating rept for Apr 1979.
LEONARD, J D Power Authority State of New York 79/05/08, 1p.

--7905110256 Monthly operating rept for Apr 1979
ZUFELT, E Power Authority State of New York 79/05/31 8pp

7905240697 Forwards weekly status rept of S&W piping reanalysis, as of 790513
EARLY, P J Power Authority State of New York 79/05/18 2pp

S. Reportable occurrences, LERs & related correspondence

7905010499 Forwards LER 79-022/04L-0
LEONARD, J D Power Authority State of New York 79/04/24 1p

--7905010303 LER 79-022/04L-0 on 790409 monitor 17-RH-50B did not activate local & remote high-high alarms as required by surveillance test F-BT-13 Caused by drift in trip setpoint Pulse height discriminator adjusted
CHILDS, W V Power Authority State of New York 79/04/24 2pp

7905010505 Forwards LER 79-021/03L-0
LEONARD, J D Power Authority State of New York 79/04/24 1p

--7905010508 LER 79-021/03L-0 on 790327 offsite power lost while in cold shutdown Emergency svc water sys started automatically Caused by loose wire in controller of motor operated valves Connection repaired
CHILDS, W V Power Authority State of New York 79/04/24 2pp

7905150475 Forwards LER 79-023/99L-0
LEONARD, J D Power Authority State of New York 79/05/09 1p

--7905150477 LER 79-023/099-0 on 790411 HPCI turbine disassembled for internal insp. requiring disassembly of piping for fired fire suppression sys. contrary to Tech Specs Will remain disabled until 790515, when reassembly is complete
CHILDS, W V Power Authority State of New York 79/05/09 2pp

7905300411 Forwards LER 79-024/03L-0
LEONARD, J D Power Authority State of New York 79/05/24 1p

--7905300416 LER 79-024/03L-0 on 790428 emergency svc water pump B could not be demonstrated to produce min shutoff head of 120 psig Caused by normal wear Tech Spec amend to reduce shutoff head requirement under consideration
CHILDS, W V Power Authority State of New York 79/05/24 2pp

7905300506 Forwards LER 79-017/03L-1
LEONARD, J D Power Authority State of New York 79/05/24 1p

--7905300514 LER 79-017/03L-1 on 790320, while surveillance test F-BT-34B was being conducted, standby gas treatment sys A in valve 01 125-HDV-14A would not open Caused by failure of auxiliary contractor in valve motor controller Contractor replaced
CHILDS, W V Power Authority State of New York 79/05/24 2pp

7905300522 Forwards LER 79-025/03L-0
LEONARD, J D Power Authority State of New York 79/05/24 1p

--7905300527 LER 79-025/03L-0 on 790428 while conducting surveillance test F-BT-76J16, master valve did not appear to be opening fully. Damaged gasket may have been causing sluggish operation of valve Gasket replaced
CHILDS, W V Power Authority State of New York 79/05/24 2pp

DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

0 Adjudicatory correspondence

7905210058 Requests plant shutdown because of threat of accident as severe as rupture to reactor vessel
ROMANO, F R Affiliation Unknown 79/04/12 5pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 177, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHINI, J American Nuclear Insurers, 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p.

DOCKETED ITEMS

7905100199 Forwards Amend 5 to Indemnity Agreement B-73, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 5pp.

P. Operating license stage documents & correspondence

7905020347 Assigns responsibility for prompt meeting notification re 790313 show cause orders.
STELLON, V. Division of Operating Reactors. 79/03/29. 3pp.

7905020490 Discusses 790315 telcon w/R Sero of Westinghouse re incorrect weights for Velan Model C658 6-inch check valves used in safety injection sys.
SCHWENGER, A. Operating Reactors Branch 1. 79/04/02. 1p.

7905290723 Summary of 790329-30 meeting w/util & S&W in Boston, MA re progress to date & early analysis of pipe stresses in safety-related sys.
WIGGINTON, D. Operating Reactors Branch 1. 79/04/10. 3pp.

7905090066 Submits engineering info re pipe stress reanalysis. Oversized diagrams available in Central Files only.
DUNN, C.N. Duquesne Light Co. 79/04/19. 2pp.

7905040615 Forwards status rept on 790427 "Plan for Verification of Dynamic Analysis Codes."
JACOBS, S.B. Stone & Webster Engineering Corp. 79/04/27. 2pp.

7905080370 Forwards response to Questions 362.1, 362.2 & 362.3 of NRC 790109 ltr. Also forwards soil analysis of turbine bldg & northern yard area, dtd 790430, in response to Question 362.4.
WOOLEVER, E.J. Duquesne Light Co. 79/05/02. 600pp.

7905110011 Responds to NRC 780913 ltr. Forwards reanalysis of effects of major LOCA. Requests permission to remove present administrative limit of 2.31 & to restore existing Tech Spec limit of 2.32.
DUNN, C.N. Duquesne Light Co. 79/05/07. 75pp.

7905110070 Forwards addl info re new steam line break protection sys. in response to informal questions during review.
DUNN, C.N. Duquesne Light Co. 79/05/07. 10pp.

7905140239 Forwards proprietary documents requested during 790501-04 special insp.
ERLEWINE, J.A. Stone & Webster Engineering Corp. 79/05/08. 1p.

--7905140245 Requests withholding Technical Guideline EMTG-22-0 & Technical Rept EMTR-612 (ref 10CFR2.790). Affidavit encl.
KENNEDY, W.J. Stone & Webster Engineering Corp. 79/05/04. 10pp.

7905140382 Confirms 790504 telcon w/WT Russell re computer deck associated w/SHOCK O program.
KENNEDY, W.J. Stone & Webster Engineering Corp. 79/05/09. 1p.

7905160335 Notifies of review completion of computer deck. SHOCK O program still unrecovered. Piping sys conservatively designed & will perform intended function.
KENNEDY, W.J. Stone & Webster Engineering Corp. 79/05/11. 1p.

7905210111 Forwards SHOCK 1 computer program listing. Supersedes submittal of 790406. Program listing withheld (ref 10CFR2.790).
KENNEDY, W.J. Stone & Webster Engineering Corp. 79/05/14. 1p.

7905220081 Requests amend to OL changing ETS to eliminate aquatic monitoring except for fish impingement. W/proposed ETS, App B to License DPR-66 & special study on aquatic monitoring reduction.
DUNN, C.N. Duquesne Light Co. 79/05/15. 225pp.

7905220093 Forwards proposed amend to OL, consisting of revised versions of previously submitted Offsite Dose Calculation Manual & "Process Control Program."
DUNN, C.N. Duquesne Light Co. 79/05/15. 2pp.

--7905220099 Offsite Dose Calculation Manual.
* Duquesne Light Co. 79/05/01. 131pp.

--7905220104 "Process Control Program."
* Duquesne Light Co. 79/05/01. 31pp.

7905240583 Discusses monitoring capabilities of reactor incore thermocouples. Fifty operable thermocouples may be defective or have insecure head connectors.
CAREY, J.J. Duquesne Light Co. 79/05/16. 2pp.

7905290335 Summarizes procedures & calculational techniques used in reanalysis of piping sys designed w/SHOCK II computer program. Reanalysis will satisfy 790313 order to show cause.
KENNEDY, W.J. Stone & Webster Engineering Corp. 79/05/18. 6pp.

Q. Inspection reports, IE Bulletins & correspondence

7905010105 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/03/23. 1p.

7905010042 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/03/28. 1p.

7905010277 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/03/30. 1p.

7905290123 Forwards IE Insp Rept 50-334/79-06 on 790227-0302. No noncompliance noted.
BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/04/03. 2pp.

--7905290126 IE Insp Rept 50-334/79-06 on 790227-0302. No noncompliance noted. Major areas inspected: previously identified unresolved items & sequence of events re recent high river water level.
MARKOWSKI, R. Region 1, Philadelphia, Office of the Director. KISTER, H.B. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/03/28. 6pp.

7905290154 Forwards IE Insp Rept 50-334/79-07 on 790315-16. No noncompliance noted.
BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/04/10. 2pp.

--7905290157 IE Insp Rept 50-334/79-07 on 790315-16. No noncompliance noted. Major areas inspected: compliance w/790313 order to show cause.
BECKMAN, D.A. Region 1, Philadelphia, Office of the Director. KEITHIG, R.R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/04/14. 3pp.

7905020039 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/11. 1p.

7905140322 Informs that pipe type described in IE Bulletin 79-03 has not been used in safety-related sys.
DUNN, C.N. Duquesne Light Co. 79/04/11. 1p.

7905020346 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

7905040018 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

7905040198 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

7905030060 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/17. 1p.

7905010643 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/18. 1p.

7905250461 Responds to IE Bulletin 79-07 re analysis of safety-related piping. Currently reanalyzing piping, per NRC 790313 order to show cause.
DUNN, C.N. Duquesne Light Co. 79/04/23. 1p.

DOCKETED ITEMS

151

7905090373 Forwards proposed "Inservice Insp Program" for 20-month period starting 790301. Program prepared per NRC 780110 request. Encl available in Central Files.
DUNN, C. N. Duquesne Light Co. 79/05/02. 1p.

R. Periodic operating reports & related correspondence

7905010491 Forwards "1978 Annual Environ Rept. Radiological," Vol 2.
DUNN, C. N. Duquesne Light Co. 79/04/24. 1p.

--7905010493 "1978 Annual Environ Rept. Radiological," Vol 2.
* Duquesne Light Co. 79/04/24. 120pp.

7905010532 Forwards national pollution discharge elimination sys monthly discharge monitoring rept for Mar 1979.
MOORE, G. W. Duquesne Light Co. 79/04/27. 3pp.

--7905010537 National pollution discharge elimination sys monthly discharge monitoring rept for Mar 1979.
MOORE, G. W. Duquesne Light Co. 79/04/27. 12pp.

7905030342 Forwards Nov 1978 "Reactor Containment Integrated Leak Rate Test Rept."
NUNN, C. N. Duquesne Light Co. 79/04/30. 1p.

--7905030344 "Reactor Containment Integrated Leak Rate Test Rept."
* Duquesne Light Co. 78/11/30. 83pp.

7905140300 Forwards monthly operating rept for Apr 1979.
DUNN, C. N. Duquesne Light Co. 79/05/04. 1p.

--7905140302 Monthly operating rept for Apr 1979.
TIMKO, D. R. Duquesne Light Co. 79/05/02. 4pp.

B. Reportable occurrences, LERs & related correspondence

7905310384 RO 79-8/01P on 790329: notified by vendor of potential for single dropped control rod to lead to calculated DNB ratios lower than reported to NRC in safety analysis. Caused by inconsistency between control settings used & those assumed.
WERLING, J. A. Duquesne Light Co. 79/03/30. 2pp.

7905080460 Forwards LER 79-010/01T-0.
WERLING, J. A. Duquesne Light Co. 79/04/30. 2pp.

--7905080468 LER 79-010/01T-0 on 790416: OE notified util of potential for failure of inside recirculation spray pump motor. Analysis indicates problem may occur when all bearing part tolerances & bearing housings are at extreme end of spectrum.
WERLING, J. A. Duquesne Light Co. 79/04/30. 2pp.

7905080545 Forwards LER 79-011/04T-0.
WERLING, J. A. Duquesne Light Co. 79/05/02. 2pp.

--7905080551 LER 79-011/04T-0 on 790430: tritium activity in quarterly composite of grab samples collected in OH River exceeded ETS limits. Caused by tritium discharge during normal plant operation.
WERLING, T. A. Duquesne Light Co. 79/05/02. 1p.

7905150531 Forwards LER 79-012/04T-0.
WERLING, J. A. Duquesne Light Co. 79/05/10. 2pp.

--7905150536 LER 79-012/04T-0 on 790430: gross beta in monthly composite grab samples from OH River exceeded ETS reporting level. Caused by naturally occurring radioactivity in sediments.
WERLING, J. A. Duquesne Light Co. 79/05/10. 1p.

7905240568 Submits special rept on diesel driven fire pump removed from svc on 790416 when intake bay was drained for maint. Motor-driven pump remained operable. Diesel pump returned to svc on 790503.
WERLING, J. A. Duquesne Light Co. 79/05/14. 2pp.

DOCKET 50-335 ST. LUCIE PLANT, UNIT 1

G. Adjudicatory correspondence

7905150125 Forwards NRC rept "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Grid Serving St Lucie."
SCHINKI, S. M. Branch 3. 79/04/11. 1p.

--7905150130 "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Grid Serving St Lucie."
MCTIERMAN, T. J. Office of Inspector & Auditor. 78/06/30. 85pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
GUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

7905160198 Forwards Amend 5 to Indemnity Agreement B-76, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 5pp.

7905100309 Forwards Endorsement 31 to NELIA Policy NF-227.
FIELDER, J. Marsh & McLennan, M & M Nuclear Consultants, Inc. Div. 79/05/04. 2pp.

7905100311 Forwards Endorsement 32 to NELIA Policy NF-227.
FIELDER, J. Marsh & McLennan, M & M Nuclear Consultants, Inc. Div. 79/05/04. 2pp.

7905250397 Forwards executed Amend 5 to Indemnity Agreement B-76, increasing coverage to \$160 million.
UHRIG, R. E. Florida Power & Light Co. 79/05/21. 3pp.

M. Antitrust correspondence

7905150234 Motion by FL Cities seeking antitrust hearing. Renews request to argue position re review & consolidation of antitrust issue. Certificate of Svc encl.
JABLON, R. A. Spiegel & McDiarmid. 79/03/28. 2pp.

7905150729 Forwards motion for consolidated hearings on behalf of FL Cities.
JABLON, R. A. Spiegel & McDiarmid. 79/04/02. 1p.

--7905150733 Motion for consolidated hearings by FL Cities. Certificate of Svc encl.
JABLON, R. A. Spiegel & McDiarmid. 79/04/02. 4pp.

7905230622 Responds to 790328 & 790402 motions filed by FL Cities to initiate antitrust hearing, in response to NRC 780727 order. Certificate of Svc encl.
DEWEY, L., CHANANIA, F. D., EVANS, D. J. Anti-Trust Division. 79/04/17. 5pp.

P. Operating license stage documents & correspondence

7905070231 Forwards Amend 31 to License DPR-67, safety evaluation & notice of issuance & availability.
REID, R. W. Operating Reactors Branch 4. 79/04/05. 2pp.

--7905070236 Amend 31 to License DPR-67, modifying Tech Specs to allow replacement of selected safety-related hydraulic snubbers w/mechanical snubbers & to revise snubber surveillance requirements.
REID, R. W. Operating Reactors Branch 4. 79/04/05. 15pp.

--7905070277 Safety evaluation supporting Amend 31 to License DPR-67.
* Office of Nuclear Reactor Regulation. 79/04/05. 3pp.

--7905070299 Notice of issuance & availability of Amend 31 to License DPR-67.
REID, R. W. Operating Reactors Branch 4. 79/04/05. 2pp.

7905150798 Notifies of adequacy of licensee's sys for insuring feeding is maintained full of water at all times. Suggests auxiliary feedwater flow be actuated automatically to obtain time lapse of less than one minute.
LAINAS, G. Plant Systems Branch. 79/04/13. 2pp.

DOCKETED ITEMS

7905130278 Requests addl info re review of proposed pump & valve test program submitted by 770916 & 780908 ltrs. Encl 1 identifies info needed on certain check valves.
REID, R.W. Operating Reactors Branch 4. 79/04/20. 5pp.

7905250263 Forwards safety evaluations re fuel handling accident inside containment.
REID, R.W. Operating Reactors Branch 4. 79/04/27. 2pp.

--7905250275 Safety evaluation re fuel handling accident inside containment. Reveals fuel handling accident w/one or two assemblies would provide doses within 10CFR100 guideline values.
* Office of Nuclear Reactor Regulation. 79/04/27. 4pp.

7905040585 Forwards addl info for Cycle 3 reload application re anticipated burnup for clad collapse for each fuel batch, combining of fuel pin powers & augmentation factors & investigation of control elements assembly sticking.
UGRIG, R.E. Florida Power & Light Co. 79/04/30. 12pp.

7905070410 Provides status of verification program for technique of measuring resistance temp detectors time constants.
UGRIG, R.E. Florida Power & Light Co. 79/05/01. 2pp.

7905140310 Reviews impact of using NRC fission gas release enhancement factors on results of Cycle 3 safety analyses. Application of factors does not adversely affect Cycle 3 results of 790222.
UGRIG, R.E. Florida Power & Light Co. 79/05/08. 1p.

7905210121 Forwards startup testing info as suppl to Cycle 3 reload safety evaluation.
UGRIG, R.E. Florida Power & Light Co. 79/05/10. 2pp.

7905220027 Forwards response to questions re reload safety evaluation.
UGRIG, R.E. Florida Power & Light Co. 79/05/18. 13pp.

7905310214 Forwards responses to questions re reload safety evaluation.
UGRIG, R.E. Florida Power & Light Co. 79/05/22. 10pp.

7905300014 Forwards responses to reload safety evaluation questions.
UGRIG, R.E. Florida Power & Light Co. 79/05/23. 6pp.

7905310305 Submits info in response to NRC request. Zero power physics tests after reload performed according to procedures. Review criteria will be established. Evaluation of difference in individual assemblies power to be sent in two weeks.
UGRIG, R.E. Florida Power & Light Co. 79/05/25. 2pp.

7905310309 Confirms 790524 discussion during which util agreed to limit containment purging in operational Modes 1 & 2 to 90-h/year.
UGRIG, R.E. Florida Power & Light Co. 79/05/25. 1p.

G. Inspection reports, IE Bulletins & correspondence

7905010195 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/23. 2pp.

7905030310 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/26. 2pp.

7905010104 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/28. 2pp.

7905010358 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/30. 2pp.

7905240045 Ack receipt of IE Insp Rept 50-335/79-04 on 790207-09. No proprietary info.
UGRIG, R.E. Florida Power & Light Co. 79/04/10. 1p.

--7905240054 Forwards IE Insp Rept 50-335/79-04 on 790207-09. No noncompliance noted.
KENNA, W.B. Region 2, Atlanta, Safeguards Branch. 79/03/12. 2pp.

--7905240069 IE Insp Rept 50-335/79-04 on 790207-09. No noncompliance noted. Major areas inspected: facility organization & operation, measurement & controls, shipping & receiving, storage & internal control, inventory & records.
TODD, G.A., CLAY, E.L. Region 2, Atlanta, Office of the Director.
WILLIAMS, G.H. Region 2, Atlanta, Safeguards Branch. 79/03/08. 4pp.

7905020127 Forwards IE Bulletin 79-06, "Review of Operational Errors Sys Misalignments Identified During TMI Incident." Licensee action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/11. 1p.

7905040141 Forwards IE Bulletin 79-06B, "Review of Operational Errors Sys Misalignments Identified During TMI Incident." Licensee action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp.

7905040308 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.

7905040404 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.

7905030164 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/17. 2pp.

7905020465 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/18. 2pp.

7905240169 Responds to IE Bulletin 79-07 re seismic analysis of safety-related piping. No such computer codes used.
UGRIG, R.E. Florida Power & Light Co. 79/04/26. 3pp.

7905290130 Ack receipt of 790403 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-335/79-01.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/05/01. 1p.

--7905290139 Responds to NRC 790308 ltr re violations noted in IE Insp Rept 50-335/79-01. Corrective actions: calibr info sheet 039 corrected & appropriate personnel instructed on correct method of making changes.
UGRIG, R.E. Florida Power & Light Co. 79/04/03. 3pp.

--7905290167 Forwards IE Insp Rept 50-335/79-01 on 790109-12 & notice violation.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/08. 2pp.

--7905290170 Notice of violation from insp on 790109-12.
* Region 2, Atlanta, Office of the Director. 79/03/07. 1p.

--7905290174 IE Insp Rept 50-335/79-01 on 790109-12. Noncompliance not failure to review calibr procedures.
WEBSTER, E.H., MOSSITT, B.R., CANTRELL, F.S. Region 2, Atlanta, Office of the Director. 79/03/07. 13pp.

S. Reportable occurrences, LERs & related correspondence

7905150241 Forwards LER 79-009/03L-0.
SCHLMIDT, A.D. Florida Power & Light Co. 79/04/04. 1p.

--7905150249 LER 79-009/03L-0 on 790305: control element assembly 2 was not withdraw fully from misalignment to check control element assembly position alarms. Caused by faulty upper electric limit reed switch. Switch will be replaced.
JAMES, D.K. Florida Power & Light Co. 79/04/04. 1p.

7905090062 Forwards LER 79-013/03L-0.
SCHLMIDT, A.D. Florida Power & Light Co. 79/04/30. 1p.

--7905090064 LER 79-013/03L-0 on 790331: during surveillance testing of diesel generator, solenoid-operated fill valve for engine mounted fuel oil tank failed to open, causing tank level to drop below limit. Caused by burnt contacts in relay.
SCHOPPMAN, M.A. Florida Power & Light Co. 79/04/30. 1p.

7905220091 Forwards LER 79-014/03L-0.
SCHLMIDT, A.D. Florida Power & Light Co. 79/05/09. 1p.

--7905220098 LER 79-014/03L-0 on 790409: notified by vendor that crankshaft coupling for cooling fans used on diesels failed in other applications. Couplings replaced w/couplings of improved design, under directions from diesel vendor.
SCHOPPMAN, M.A. Florida Power & Light Co. 79/05/09. 1p.

DOCKETED ITEMS

153

DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

7905290073 Forwards response to NRC verbal questions re fire protection. Engineering & design of most mods in progress.
COUNCIL, W.G. Northeast Utilities. 79/05/18. 16pp.

J. Insurance & indemnity information

7905140422 Forwards Amend 14 to Indemnity Agreement B-39 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 6pp.

7905190075 Forwards executed Amend 14 to Indemnity Agreement B-39.
O'CONNOR, L.A. Northeast Utilities. 79/05/15. 4pp.

P. Operating license stage documents & correspondence

7905070332 Forwards Amend 50 to License DPR-65, safety evaluation & notice of issuance & availability.
REID, R.W. Operating Reactors Branch 4. 79/03/23. 2pp.

--7905070337 Amend 50 to License DPR-65, incorporating low temp overpressure protection sys requirements.
REID, R.W. Operating Reactors Branch 4. 79/03/23. 20pp.

--7905070347 Safety evaluation supporting Amend 50 to License DPR-65.
* Office of Nuclear Reactor Regulation. 79/03/23. 17pp.

--7905070351 Notice of issuance & availability of Amend 50 to License DPR-65.
REID, R.W. Operating Reactors Branch 4. 79/03/23. 2pp.

7905240253 Forwards draft safety evaluation re proposed neutron shield design to reduce radiation level outside containment. Load analysis to be completed 800101.
LAINAS, G. Plant Systems Branch. 79/04/17. 7pp.

7905290007 Forwards Amends 60 & 51 to Licenses DPR-21 & DPR-65, respectively, EIA & notice of issuance & negative declaration.
ZIEHMANN, D.L. Operating Reactors Branch 2. 79/04/24. 3pp.

--7905290012 Amends 60 & 51 to Licenses DPR-21 & DPR-65, respectively, revising ETS to provide more flexibility in sampling schedules & collection for aquatic monitoring & reflecting improved & modified program objectives.
ZIEHMANN, D.L. Operating Reactors Branch 2. 79/04/24. 13pp.

--7905290016 EIA supporting Amends 60 & 51 to Licenses DPR-21 & DPR-65, respectively.
* Office of Nuclear Reactor Regulation. 79/04/24. 11pp.

--7905290019 Notice of issuance of Amends 60 & 51 to Licenses DPR-21 & DPR-65, respectively, & negative declaration.
ZIEHMANN, D.L. Operating Reactors Branch 2. 79/04/24. 2pp.

7905040135 Responds to NRC 780419 request for insulation resistance tests. Forwards electrical penetration testing evaluation. Modified conductor configuration is acceptable for Cycle 3 operation.
COUNCIL, W.G. Northeast Utilities. 79/04/26. 8pp.

7905070359 Forwards proposed revision to Tech Specs to allow unlimited containment purges. Revisions deal w/containment isolation valves.
COUNCIL, W.G. Northeast Utilities. 79/04/27. 16pp.

7905080406 Forwards responses to request for addl info re Cycle 3 safety analysis. Nonproprietary rept encl. Proprietary version withheld (ref 10CFR2.790).
COUNCIL, W.G. Northeast Utilities. 79/05/03. 17pp.

7905100320 Discusses addl info re control element assembly guide tube insp. Fuel assemblies suitable for continued use during Cycle 3 operation.
COUNCIL, W.G. Northeast Utilities. 79/05/07. 2pp.

7905160262 Notifies that stem-mounted limit switches on valves SI-614, SI-624, SI-634 & SI-644 will not be replaced; valves do not perform safety-related function.
COUNCIL, W.G., SWITZER, D.C. Northeast Utilities. 79/05/08. 2pp.

7905160376 Discusses results of six tasks which utilized ADLPIPE computer program for reanalysis of piping sys. Mods involved minor changes to small portions of existing sys.
COUNCIL, W.G., SWITZER, D.C. Northeast Utilities. 79/05/11. 3pp.

7905300645 Informs of forthcoming detailed reply to 790507 ltr re CT nuclear power plants. Plants will not start up until all post-TMI items & requirements are implemented & confirmed.
HENDRIE, J.M. Commission. 79/05/11. 1p.

--7905300647 Requests assurance that action required by IE info notices & bulletins have been implemented before CT plants return to operation. Also requests info on other anticipated NRC actions or anticipated problems.
GRASSO, E. Connecticut, State of. 79/05/07. 2pp.

7905220116 Forwards addl info re performance of control element assembly guide tube sleeves, in response to 790512 ltr.
COUNCIL, W.G. Northeast Utilities. 79/05/17. 6pp.

7905300009 Comments on need for repairing or replacing aerated radwaste evaporator. Replacement not warranted, based on discharge criteria, actual plant releases & ALARA considerations.
COUNCIL, W.G. Northeast Utilities. 79/05/21. 2pp.

7905310183 Forwards proprietary & nonproprietary versions of "Sleeved CEA Guide Tube Eddy Current Test Results." Proprietary version withheld (ref 10CFR2.790). W/affidavit re withholding.
COUNCIL, W.G. Northeast Utilities. 79/05/23. 6pp.

--7905310189 "Sleeved CEA Guide Tube Eddy Current Test Results."
* Northeast Utilities. CEN-108(N)-NP. 79/05/02. 6pp.

G. Inspection reports, IE Bulletins & correspondence

7905240692 Forwards IE Insp Repts 50-245/78-42 & 50-336/78-39 on 781208-790105. No noncompliance noted.
BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/03/21. 2pp.

--7905240704 IE Insp Repts 50-245/78-42 & 50-336/78-39 on 781208-790105. No noncompliance noted. Major areas inspected: Unit 1 reactor, turbine & radwaste bldgs; Unit 2 auxiliary & turbine bldgs, condensate polishing facility & radiation protection.
SHEDLOSKEY, J.T. Region 1, Philadelphia, Office of the Director.
MCCABE, E.C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/03/20. 13pp.

7905010121 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/03/23. 1p.

7905010053 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/03/28. 1p.

7905010304 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/03/30. 2pp.

7905290160 Forwards IE Insp Rept 50-336/79-04 on 790220-23. No noncompliance noted.
BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/04/10. 2pp.

--7905290166 IE Insp Rept 50-336/79-04 on 790220-23. No noncompliance noted. Major areas inspected: administrative controls of facility procedures & safety related calibr.
ZIMMERMAN, R.P., BAUNACK, W.H. Region 1, Philadelphia, Office of the Director.
KISTER, H.B. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/03/27. 16pp.

7905020061 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/11. 1p.

7905020300 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

DOCKETED ITEMS

7905040049 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/14 1p

7905040214 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/14 1p

7905030077 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/17 1p

7905020284 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/18 1p

7905040053 Discusses guide tube insp program. Pull tests performed on 354 sleeves. Evaluation of data indicates sleeves are functioning as expected.
COUNCIL, W. G. Northeast Utilities. 79/04/26. 2pp.

7905300261 Provides info in response to NRC request re impact of mods & reanalyses on high energy pipe break. Topic discussed in util 790511 response to IE Bulletin 79-07.
COUNCIL, W. G. Northeast Utilities. 79/05/23. 2pp.

R. Periodic operating reports & related correspondence

7905150502 Forwards monthly operating rept for Apr 1979.
OPEKA, J. F. Northeast Utilities. 79/05/09. 1p.

--7905150505 Monthly operating rept for Apr 1979.
HOWLETT, G. H. Northeast Utilities. 79/05/02. 5pp.

S. Reportable occurrences, LERs & related correspondence

7905140067 PNO-79-91: vapor binding of shutdown cooling sys pump on 790314. Suction restored; no radioactive matl released to environ.
KILINGER, G., NOLAN, F., BRYAN, S. E. Office of Inspection & Enforcement. 79/04/23. 1p.

7905080456 Forwards LER 78-022/03X-1.
OPEKA, J. F. Northeast Utilities. 79/04/30. 1p.

--7905080461 LER 78-022/03X-1 on 780906: loss of efficiency noted in methyl iodide removal sys for encl bldg A filtration sys train. Caused by normal degradation through use.
MCCANN, W. J. Northeast Utilities. 79/04/30. 1p.

7905300452 Forwards LER 79-011/03L-0.
OPEKA, J. F. Northeast Utilities. 79/05/18. 1p.

--7905300457 LER 79-011/03L-0 on 790514: one electrical penetration & several boundary valves had leakage. Caused by inadvertent omission of pre-repair leak rate measurement for some valves. Test procedures to be revised.
STRATHMAN, R. A. Northeast Utilities. 79/05/18. 3pp.

7905290221 RD 79-12/1P: inoperable linear power range channels. Caused by open connections between channels A & D detector cables. Connections repaired.
OPEKA, J. F. Northeast Utilities. 79/05/22. 1p.

DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1

G. Adjudicatory correspondence

7905030262 Petition for formal intervenor status on turbine missile issue. If denied, requests permission to present evidence & cross-examine as amicus curiae. Certificate of Svc encl.
WEISS, E. R. Sheldon, Harmon & Roisman. 79/03/14. 9pp.

7905030207 Agreement via stipulation of contentions, including withdrawal of previous contentions. Notice of appearance of RJ Gaddard on behalf of NRC & Certificate of Svc encl.
DOUGHERTY, J. B. Potomac Alliance. GOLDBERG, S. C. Regulations Division. CHRISTMAN, J. Virginia Electric & Power Co. 79/03/23. 10pp.

--7905030209 Agreement via stipulation of contentions, including withdrawal of previous contentions.
KRODT, I. Citizens Energy Forum. GOLDBERG, S. C. Branch 2. CHRISTMAN, J. Virginia Electric & Power Co. 79/03/23. 7pp.

7905030258 Answer by util in opposition to UCS 790314 petition to intervene. Claims untimeliness, intervention during appellate stage & lack of standing. Certificate of Svc encl.
RINACA, J. M. Hunton & Williams. 79/03/29. 22pp.

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients.
SCINTO, J. F. Hearings Division. 79/04/02. 31pp.

--7905010156 Board notification: staff assessment re nonsafety-grade equipment to mitigate transients.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/03/29. 2pp.

--7905010198 Board notification: recent issue on nonsafety-grade equipment to mitigate transients. More info is required.
TEDESCO, R. L. Assistant Director for Reactor Safety. 79/03/16. 3pp.

7905230668 Notifies that recent info may affect licensing of high density spent fuel storage racks. Svc water temp & component cooling water temp will exceed values in FSAR.
CHRISTMAN, J. N. Hunton & Williams. 79/04/04. 2pp.

7905240135 ALAB-536, denying UCS 790314 petition to intervene or participate in hearing as amicus curiae.
DUFLD, M. E. Atomic Safety and Licensing Appeal Panel. 79/04/05. 8pp.

7905240487 Directs parties to submit responsive prepared testimony re pumphouse settlement & turbine missile issues before 790531. Evidentiary hearing to be held during week of 790618. Lists procedures for informal discovery process.
DUFLD, M. E. Atomic Safety and Licensing Appeal Panel. 79/04/09. 4pp.

7905100137 Forwards EIA re proposed increase of storage capacity of spent fuel pool.
GOLDBERG, S. C. Branch 2. 79/04/10. 1p.

--7905100140 EIA supporting proposed increase in storage capacity of spent fuel pool.
* Office of Nuclear Reactor Regulation. 79/04/02. 32pp.

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record. Certificate of Svc encl.
SCINTO, J. F. Hearings Division. 79/04/11. 45pp.

7905140519 Response to 790404 brief of Philadelphia Electric Co, PSE&O & Atlantic City (NJ) Electric Co re de minimus theory. Certificate of Svc encl.
KEPPORD, C. R. Citizens for Safe Environment. 79/04/11. 8pp.

7905241006 Corrects info submitted on 790334 re deficiency in Westinghouse ECCS evaluation model. Model reanalysis indicates North Anna 1 & 2 still in compliance w/10CFR50.46.
SWANSON, D. T. Branch 1. 79/04/13. 1p.

7905240255 Requests extension of time to 790504 in which to prepare testimony. Granted by ASLAB on 790420. Certificate of Svc encl.
SWANSON, D. T. Branch 1. 79/04/20. 5pp.

7905230655 Grants interventions of Citizens Energy Forum & Potomac Alliance. Provides for hearing & designates contentions of intervenors.
DEALE, V. B. Atomic Safety and Licensing Board Panel. 79/04/21. 4pp.

7905030330 Affidavit of Svc for applicant's Amend 66 in proceeding.
NEIL, R. M. Virginia, State of. 79/04/25. 2pp.

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue. Parties have until 790525 in which to file for summary disposition.
DUFLD, M. E. Atomic Safety and Licensing Appeal Panel. 79/04/25. 13pp.

7905240814 Forwards second copy of util's testimony re probability of generating turbine missiles & turbine overspeed protection sys. W/o encl.
CHRISTMAN, J. N. Hunton & Williams. 79/04/30. 2pp.

DOCKETED ITEMS

155

7905240455 Ack receipt of 790405 ltr requesting NRC to revoke OLs. Ltr is currently under consideration. Forwards FR notice re Allen 790405 ltr.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/04. 1p.

--7905240461 FR notice re J Allen 790405 request for revocation of OLs.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/04. 2pp.

7905240510 Extends time for NRC review of ALAB-536 until 790511.
CHILK, S. J. Office of the Secretary of the Commission. 79/05/04. 1p.

7905240571 Following 790626 prehearing conference, hearing shall commence re application by util for OL amend to increase spent fuel pool storage capacity, per 790423 order granting intervention.
DEALE, V. B. Atomic Safety and Licensing Board Panel. 79/05/04. 5pp.

7905310033 Forwards J Allen 790405 ltr requesting NRC revoke facility OLs & FR notice of revocation request. W/790330 ltr to ASLAB re Westinghouse ECCS deficiency.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/04. 3pp.

7905250233 Request to amend petition to intervene by adding contention re svc water cooling sys. Notice of appearance of GM Gilman on behalf of intervenors. Certificate of Svc & supporting documentation encl
DOUGHERTY, J. B., GILMAN, G. Putomac Alliance. 79/05/09. 11pp.

I. Financial information

7905020439 Discusses SEC 790321 ltr & registration statement Util will file another statement which NRC will be able to review.
DROMERICK, A. W. Light Water Reactors Branch 3. 79/04/09. 1p.

--7905020466 Forwards SEC 790316 registration statement filed by util. Requests comments by 790330; util wishes statement to become effective by 790402
MORIN, H. F. Securities & Exchange Commission. 79/03/21. 60pp.

J. Insurance & indemnity information

7905110107 Amend to Endorsement 51 to NELIA Policy NF-186. Constitutes Endorsement 54
* Nuclear Energy Liability Insurance Association. 79/04/27. 1p.

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHINI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

7905110090 Endorsements 16, 30, 36 & 47 to NELIA Policy NF-186.
BARDES, C. R. Nuclear Energy Liability Insurance Association. 79/05/01. 1p.

7905140523 Forwards Amend 5 to Indemnity Agreement B-80 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 6pp.

7905240342 Forwards executed Amend 5 to Indemnity Agreement B-80.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/21. 2pp.

7905300334 Forwards Endorsements 17, 20 & 21 to NELIA Policy NF-240.
KELLEY, P. J. Johnson & Higgins Insurance. 79/05/23. 4pp.

D. Advisory Committee on Reactor Safeguards reports & correspondence

7905100325 Responds to request for written rept after cancellation of ACRS 790331 meeting re possibility of problem w/instrument guide tubes Staff rept encl
CROCKER, L. P. Division of Project Management. 79/03/30. 5pp.

P. Operating license stage documents & correspondence

7905020490 Discusses 790315 telcon w/R Sero of Westinghouse re incorrect weights for Velan Model C658 6-inch check valves used in safety injection sys.
SCHWENK, R. A. Operating Reactors Branch 1. 79/04/02. 1p.

7905070087 Forwards EIA re expansion of spent fuel storage pool.
REGAN, W. H. Environmental Projects Branch 2. 79/04/06. 1p.

--7905070090 EIA re proposed increase in storage capacity of spent fuel pool.
* Environmental Projects Branch 2. 79/04/02. 32pp.

7905090304 Informs of completion of review of 781226 revised plant staff organization. Revisions acceptable if addl level is added & if appointment of alternates is clarified.
PARR, O. D. Light Water Reactors Branch 4. 79/04/09. 5pp.

7905020358 Ack receipt of 790409 ltr re reorganization. Modified requirements for personnel qualifications will be incorporated into FSAR in upcoming amend.
STALLINGS, C. M. Virginia Electric & Power Co. 79/04/27. 1p.

7905040126 Responds to AW Dromerick request re elevation marker readings located on svc water piping at svc water pumphouse.
BROWN, S. C. Virginia Electric & Power Co. 79/05/01. 1p.

7905240407 Submits 790903 elevations of three settlement markers at svc water pumphouse.
BROWN, S. C. Virginia Electric & Power Co. 79/05/01. 1p.

7905100317 Forwards drawings of stainless steel pressure-balanced expansion joints for svc water piping at svc water pumphouse, in response to AW Dromerick request. Oversized drawings encl.
BROWN, S. C. Virginia Electric & Power Co. 79/05/03. 1p.

7905080428 Notifies of plans to test Unit 2 auxiliary svc water pump 2-swp-4 on monthly bases, as outlined in inservice testing program submitted on 790131. Will test 1-swp-4 before OL is issued for Unit 2. Piping mod presently unnecessary.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/04. 1p.

7905080443 Supplements 790308 rept "Svc Water Reservoir & Spray Sys Performance Testing & Evaluation." Spent fuel pool temp will exceed 110 F FSAR limit. Lists methods to meet limits. Fuel rack license application & FSAR will be amended.
BROWN, S. C. Virginia Electric & Power Co. 79/05/04. 1p.

7905080506 Lists completed Tech Specs testing requirements which should be deleted from list of tests requiring deferral for amend to OL.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/04. 1p.

7905190062 Forwards fee for issuance of Amend 10 to License NPF-4.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/07. 1p.

7905150270 Forwards replacement pages to 780501 application to amend License NPF-4 to expand spent fuel storage capacity.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/11. 10pp.

7905210176 Forwards suppl to proposed Tech Spec Change 12 re increasing amount of allowable settlement for svc water pumphouse.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/17. 23pp.

7905230536 Suppl to proposed Tech Spec Change 12, "Settlement of Class I Structures," increasing amount of allowable settlement for svc waterpump house. Forwards revised Tech Spec, marked-up original & discussion of change.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/17. 23pp.

7905230022 Forwards response to NRC 790503 evaluation & request for addl info re "Svc Water Reservoir & Spray Sys Performance Testing & Evaluation."
BROWN, S. C. Virginia Electric & Power Co. 79/05/18. 8pp.

7905290375 Responds to AW Dromerick 790503 questions re containment depressurization, net positive suction head, analyses & effects of increased calculated svc water temps on design of charging pump coolers.
BROWN, S. C. Virginia Electric & Power Co. 79/05/23. 14pp.

G. Inspection reports, IE Bulletins & correspondence

7905010255 Forwards IE Insp Repts 50-338-79-01 & 50-339-79-01 on 790102-0202 & notice of violation.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/16. 2pp.

--7905010264 Notice of violation from insp on 790102-0202.
* Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/14. 1p.

DOCKETED ITEMS

- 7905010275 IE Insp Repts 50-338/79-01 & 50-339/79-01 on 790102-0202. Noncompliance noted: failure to document approval of change to test procedure. KIDD, N. S., CANTRELL, F. S. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/14. 19pp.
- 7905010224 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/23. 2pp.
- 7905010129 Forwards IE Insp Repts 50-338/79-04 & 50-339/79-04 on 790122-25 & notice of violation. LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/23. 2pp.
- 7905090132 Notice of violation from insp on 790122-25. * Region 2, Atlanta, Office of the Director. 79/03/13. 1p.
- 7905090135 IE Insp Repts 50-338/79-04 & 50-339/79-04 on 790122-25. Noncompliance noted: failure to identify Tech Spec-listed snubbers prior to removal for testing. DYER, J. A., JOHNSON, A. H. Region 2, Atlanta, Office of the Director. MARTIN, R. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/13. 8pp.
- 7905030319 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/26. 2pp.
- 7905010123 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/28. 2pp.
- 7905010369 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/30. 2pp.
- 7905080534 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/11. 1p.
- 7905040254 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp.
- 7905040271 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.
- 7905040448 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.
- sends to IE Bulletin 79-03, "Longitudinal Weld Defects in pipe 304 Stainless Steel Pipe Spools Mfg by King & Engineering Co." North Anna 1 uses no Surry 1 & 2 records are still under review. Virginia Electric & Power Co. 79/04/16. 2pp.
- re IE Bulletin 79-09, "Failures of OE Type AK-2 in Safety-Related Sys." Licensee action required. Region 2, Atlanta, Office of the Director.
- re IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Region 2, Atlanta, Office of the Director.
- receipt of 790411 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-338/79-03. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/04/18. 1p.
- ponds to NRC 790320 ltr re violation noted in IE Insp Rept 50-338/79-03. Corrective actions: health physics technician training w/inadequate experience used in responsible position. JENKINS, G. R. Region 2, Atlanta, Office of the Director. GIBSON, A. F. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/03/19. 3pp.
- ponds to IE Bulletin 79-07 re seismic analysis of safety-related piping. No computer codes identified using methods described. SPENCER, W. C. Virginia Electric & Power Co. 79/04/24. 10pp.
- 7905240181 Responds to IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Review committee was established & detailed review of TMI incident has been completed. STALLINGS, C. M. Virginia Electric & Power Co. 79/04/26. 9pp.
- 7905290119 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/79-11 & 50-339/79-16. SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/05/01. 1p.
- 7905290125 Responds to NRC 790316 ltr re violations noted in IE Insp Repts 50-338/79-11 & 50-339/79-16. Corrective actions: applicable emergency plan implementing procedures put into action. STALLINGS, C. M. Virginia Electric & Power Co. 79/04/10. 3pp.
- 7905290130 Forwards IE Insp Repts 50-338/79-11 & 50-339/79-16 on 790228-0302 & notice of violation. SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/03/16. 2pp.
- 7905290138 Notice of violation from insp on 790228-0302. * Region 2, Atlanta, Office of the Director. 79/03/16. 1p.
- 7905290142 IE Insp Repts 50-338/79-11 & 50-339/79-16 on 790228-0302. Noncompliance noted: release of radioactivity to unrestricted area. ZAVADOSKI, R. W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/03/16. 5pp.
- 7905300734 Ack receipt of IE Insp Rept 50-338/79-13 on 790305-15. No proprietary info. STALLINGS, C. M. Virginia Electric & Power Co. 79/05/01. 1p.
- 7905300023 Forwards IE Insp Repts 50-338/79-12 & 50-339/79-19 on 790416-20. No noncompliance noted. KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 79/05/02. 2pp.
- 7905300026 IE Insp Repts 50-338/79-12 & 50-339/79-19 on 790416-20. No noncompliance noted. Major areas inspected: security plan, protected area barriers, vital area barriers & access controls. Details withheld (ref 10CFR.790). HENNESSEY, R. J. Region 2, Atlanta, Office of the Director. TOBIN, W. J. Region 2, Atlanta, Safeguards Branch. 79/05/02. 1p.
- 7905240481 Confirms 790426 response to IE Bulletin 79-06A re actions taken on Unit 1. All commitments for Unit 1 will apply to Unit 2. STALLINGS, C. M. Virginia Electric & Power Co. 79/05/03. 1p.
- 7905300706 Forwards response to IE Bulletin 79-04. Velan swing check valves of three & six inches installed in chemical vol & control & safety injection sys. STALLINGS, C. N. Virginia Electric & Power Co. 79/05/03. 4pp.
- 7905210275 Responds to IE Bulletin 79-06A, Revision 1. Provides requested info on design changes re containment sump pump trip valve actuation & safety injection logic. STALLINGS, C. M. Virginia Electric & Power Co. 79/05/17. 2pp.
- 7905290032 Responds to IE Bulletin 79-09. OE Type AK-2 circuit breakers not in use or planned for use. STALLINGS, C. M. Virginia Electric & Power Co. 79/05/23. 1p.
- 7905300018 Responds to IE Bulletin 79-10. Forwards requalification training program statistics. STALLINGS, C. M. Virginia Electric & Power Co. 79/05/24. 5pp.

DOCKETED ITEMS

157

R. Periodic operating reports & related correspondence

7905190191 Forwards monthly operating rept for Apr 1979.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/15. 1p.

--7905190193 Monthly operating rept for Apr 1979.
MADISON, W.R. Virginia Electric & Power Co. 79/05/08. 4pp.

S. Reportable occurrences, LERs & related correspondence

7905110203 Board notification: Seabrook refueling water storage tank design deficiency.
SCINTO, J. Hearings Division. 79/03/29. 30pp.

7905140401 Responds to 790411 notification of defect in computer program allowing vital area access by unauthorized personnel. Security personnel deployed to prevent recurrence.
STALLINGS, C.M. Virginia Electric & Power Co. 79/04/12. 2pp.

7905230631 Forwards addl info re significant potential safety hazard reported on 790421. Software program failure caused degraded mode, allowing unrestricted access to any cardholder. Vital entrances guarded while sys restored.
STALLINGS, C.M. Virginia Electric & Power Co. 79/04/23. 2pp.

7905020245 Forwards LER 79-047/01T-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/04/26. 1p.

--7905020248 LER 79-047/01T-0 on 790412: during reanalysis of regenerative heat exchanger, nozzle loading by vendor discovered loads exceed vendor umbrella loading, caused by miscalculation of nozzle loading during initial analysis.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/04/26. 2pp.

7905020474 Forwards LER 79-043/01T-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/04/26. 1p.

--7905020484 LER 79-043/01T-0 on 790411: manufacturer determined generic problem exists w/ lower radial bearings of recirculation spray sys motors. Bearing failure could result. Installed bearings tested.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/04/24. 3pp.

7905020391 Forwards LERs 79-029/03L-0 & 79-042/03L-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/04/27. 1p.

--7905020396 LER 79-029/03L-0 on 790330: component cooling was lost to reactor coolant pump during steady state operation at 97% power. Caused by burned out air solenoid coil. Coil replaced.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/04/24. 2pp.

--7905020403 LER 79-042/03L-0 on 790330: auxiliary feedwater pump 1-FW-P-2 turbine governor/trip valve tripped closed at 40% power. Caused by overspeed trip signal from auxiliary feedwater pump turbine. Further testing performed.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/04/24. 2pp.

7905040626 Significant deficiency rept on 790425. Computer program would not correctly operate sys, allowing unauthorized person access to vital area. Computer program currently being revised.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/01. 2pp.

7905070530 Forwards LER 79-052/01T-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/03. 1p.

--7905070533 LER 79-052/01T-0 on 790419: util informed by S&W of potential problem w/ seismic pipe stress analysis on safety injection piping. Caused by error in computer program input for design of pipe supports. Program corrected & mods made.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/02. 2pp.

7905070656 Forwards LERs 79-045/03L-0 & 79-046/03L-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/03. 1p.

--7905070659 LER 79-045/03L-0 on 790404: level transmitter found out of calibr. Caused by instrument drift. Transmitter recalibr.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/02. 3pp.

--7905070662 LER 79-046/03L-0 on 790408: during cold shutdown, changing pumps 1A & 1B were tagged out w/o racking in alternate feeder breaker for pump 1C. Caused by personnel error. Pump 1C alternate feeder breaker racked in.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/02. 2pp.

7905080444 Forwards LERs 79-056/01T-0 & 79-057/01T-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/04. 1p.

--7905080447 LER 79-056/01T-0 on 790421: 12 expansion joints on svc water side of component cooling heat exchangers were deflected greater than alignment allowances. Caused by failure to install correct number of tie-rods on expansion joints.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/04. 2pp.

--7905080449 LER 79-057/01T-0 on 790424: transfer bus & feeder cables not capable of continually carrying full load current for certain conditions. Caused by improper sizing of equipment. Final solution being analyzed.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/04. 3pp.

7905110142 Forwards LERs 79-034/03L-0 & 79-051/03L-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/07. 1p.

--7905110147 LER 79-034/03L-0 on 790410: snubber 1-RC-HSS-B5 had empty reservoir & declared inoperable. Caused by improperly seated O ring resulting in leak. Snubber replaced.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/04. 1p.

--7905110152 LER 79-051/03L-0 on 790416: RHR isolation valve MOV-1701 failed to close automatically in response to trip signal. Caused by misaligned limit switch contact in valve "close" circuitry. Contact realigned & valve retested satisfactorily.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/04. 2pp.

7905160432 Forwards LERs 79-048/03L-0, 79-049/03L-0, 79-050/03L-0 & 79-055/03L-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/11. 1p.

--7905160437 LER 79-048/03L-0 on 790412: foreign substance found on valve seat & valve disc during repair on MOV-RS-100B. Caused by substance being left on seat by repair crew.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/11. 3pp.

--7905160444 LER 79-049/03L-0 on 790412: recalibr of steam generator 1B revealed nonconservative drift. Caused by instrument drift. Recalibr for level channel corrected problem.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/11. 2pp.

--7905160454 LER 79-050/03L-0 on 790412: recalibr on containment pressure channel P-LM-100A revealed nonconservative instrument drift. Caused by excessive drift of power supply in instrument.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/11. 2pCp./.

--7905160458 LER 79-055/03L-0 on 790401: during Mode 3 operation, three rod position indicators read high while rods were actually at 0 steps. Caused by electrical drift in indicator circuitry. Recalibr solved problem.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/11. 2pp.

7905210258 Forwards LER 79-062/01T-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/17. 1p.

--7905210260 LER 79-062/01T-0 on 790503: temporary iron corner braces discovered on exhaust ducting of diesel generator cooling fans. Caused by braces left in place after ducting fabrication. Braces removed.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/17. 2pp.

7905220287 Forwards LER 79-053/03L-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/18. 1p.

--7905220296 LER 79-053/03L-0 on 790419: while performing penetration leak testing, 20 valves discovered to have leakage exceeding allowable limits. Caused by deterioration of valve seats. Valves reworked.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/18. 2pp.

7905230060 Forwards LER 79-065/01T-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/21. 1p.

--7905230071 LER 79-065/01T-0 on 790507: informed by A/E that solenoid valves in sample sys did not meet proper environ qualifications. Caused by use of valves which were not environmentally qualified.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/21. 2pp.

7905300401 Forwards LERs 79-061/03L-0, 79-072/03L-0 & 79-058/03L-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/23. 1p.

--7905300404 LER 79-061/03L-0 on 790430: temp indicator TI-RS-100A on casing cooling tank read out of specs at greater than 50 F. Caused by slipping belt on mechanical refrigerator unit.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/28. 2pp.

DOCKETED ITEMS

--7905300408 LER 79-072/03L-O on 790514: main steam trip valve TV-MS-111B would not fully shut. Caused by deteriorated internal gasket. Gasket replaced.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/28. 2pp.

--7905300412 LER 79-058/03L-O on 790430: safety injection valve MOV-1865B failed to open. Caused by dried packing around valve stem. Valve manually opened & broken free from closed position.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/28. 2pp.

DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905290296 Requests NRC reconsider its 3-month moratorium on issuance of new OL because of large addl costs of replacement power.
RAGONE, S. Virginia Electric & Power Co. 79/05/22. 2pp.

7905070087 Forwards EIA re expansion of spent fuel storage pool.
REGAN, W.H. Environmental Projects Branch 2. 79/04/06. 1p.

--7905070090 EIA re proposed increase in storage capacity of spent fuel pool.
* Environmental Projects Branch 2. 79/04/02. 32pp.

7905040126 Responds to AW Dromerick request re elevation marker readings located on svc water piping at svc water pumphouse.
BROWN, S.C. Virginia Electric & Power Co. 79/05/01. 1p.

7905240407 Submits 790903 elevations of three settlement markers at svc water pumphouse.
BROWN, S.C. Virginia Electric & Power Co. 79/05/01. 1p.

7905100317 Forwards drawings of stainless steel pressure-balanced expansion joints for svc water piping at svc water pumphouse, in response to AW Dromerick request. Oversized drawings encl.
BROWN, S.C. Virginia Electric & Power Co. 79/05/03. 1p.

7905080428 Notifies of plans to test Unit 2 auxiliary svc water pump 2-sw-p-4 on monthly bases, as outlined in inservice testing program submitted on 790131. Will test 1-sw-p-4 before OL is issued for Unit 2. Piping mod presently unnecessary.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/04. 1p.

7905080443 Supplements 790308 rept "Svc Water Reservoir & Spray Sys Performance Testing & Evaluation." Spent fuel pool temp will exceed 110 F FSAR limit. Lists methods to meet limits. Fuel rack license application & FSAR will be amended.
BROWN, S.C. Virginia Electric & Power Co. 79/05/04. 1p.

7905190062 Forwards fee for issuance of Amend 10 to License NPF-4.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/07. 1p.

7905150270 Forwards replacement pages to 780501 application to amend License NPF-4 to expand spent fuel storage capacity.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/11. 10pp.

7905210176 Forwards suppl to proposed Tech Spec Change 12 re increasing amount of allowable settlement for svc water pumphouse.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/17. 23pp.

7905230536 Suppl to proposed Tech Spec Change 12, "Settlement of Class I Structures," increasing amount of allowable settlement for svc waterpump house. Forwards revised Tech Spec, marked-up original & discussion of change.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/17. 23pp.

7905230022 Forwards response to NRC 790503 evaluation & request for addl info re "Svc Water Reservoir & Spray Sys Performance Testing & Evaluation."
BROWN, S.C. Virginia Electric & Power Co. 79/05/18. 8pp.

7905290375 Responds to AW Dromerick 790503 questions re containment depressurization, net positive suction head analyses & effects of increased calculated svc water temps on design of charging pump coolers.
BROWN, S.C. Virginia Electric & Power Co. 79/05/23. 14pp.

7905080441 Forwards corrections to Table A.5.1 & other matl in 790410 ltr from CM Stallings re startup physics testing program, description of input error in original computer code calculation & steps taken to preclude recurrence.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/02. 20pp.

G. Adjudicatory correspondence

7905030262 Petition for formal intervenor status on turbine missile issue. If denied, requests permission to present evidence & cross-examine as amicus curiae. Certificate of Svc encl.
WEISS, E.R. Sheldon, Harmon & Roisman. 79/03/14. 9pp.

7905030207 Agreement via stipulation of contentions, including withdrawal of previous contentions. Notice of appearance of RJ Goddard on behalf of NRC & Certificate of Svc encl.
DOUGHERTY, J.B. Potomac Alliance. GOLDBERG, S.C. Regulations Division. CHRISTMAN, J. Virginia Electric & Power Co. 79/03/23. 10pp.

--7905030209 Agreement via stipulation of contentions, including withdrawal of previous contentions.
KRODT, I. Citizens Energy Forum. GOLDBERG, S.C. Branch 2. CHRISTMAN, J. Virginia Electric & Power Co. 79/03/23. 7pp.

7905030258 Answer by util in opposition to UCS 790314 petition to intervene. Claims untimeliness; intervention during appellate stage & lack of standing. Certificate of Svc encl.
RINACA, J.M. Hunton & Williams. 79/03/29. 22pp.

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients.
SCINTO, J.F. Hearings Division. 79/04/02. 31pp.

--7905010156 Board notification: staff assessment re nonsafety-grade equipment to mitigate transients.
VASSALLO, D.B. Assistant Director for Light Water Reactors. 79/03/29. 2pp.

--7905010198 Board notification: recent issue on nonsafety-grade equipment to mitigate transients. More info is required.
TEDESCO, R.L. Assistant Director for Reactor Safety. 79/03/16. 3pp.

7905230668 Notifies that recent info may affect licensing of high density spent fuel storage racks. Svc water temp & component cooling water temp will exceed values in FSAR.
CHRISTMAN, J.N. Hunton & Williams. 79/04/04. 2pp.

7905240135 ALAB-536, denying UCS 790314 petition to intervene or participate in hearing as amicus curiae.
DUFLO, M.E. Atomic Safety and Licensing Appeal Panel. 79/04/05. 8pp.

7905240487 Directs parties to submit responsive prepared testimony re pumphouse settlement & turbine missile issues before 790531. Evidentiary hearing to be held during week of 790618. Lists procedures for informal discovery process.
DUFLO, M.E. Atomic Safety and Licensing Appeal Panel. 79/04/09. 4pp.

7905100137 Forwards EIA re proposed increase of storage capacity of spent fuel pool.
GOLDBERG, S.C. Branch 2. 79/04/10. 1p.

--7905100140 EIA supporting proposed increase in storage capacity of spent fuel pool.
* Office of Nuclear Reactor Regulation. 79/04/02. 32pp.

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record. Certificate of Svc encl.
SCINTO, J.F. Hearings Division. 79/04/11. 45pp.

7905140319 Response to 790404 brief of Philadelphia Electric Co/PSE&G Atlantic City (NJ) Electric Co re de minimus theory. Certificate of Svc encl.
KEPFORD, C.R. Citizens for Safe Environment. 79/04/11. 8pp.

7905241006 Corrects info submitted on 790334 re deficiency in Westinghouse ECCS evaluation model. Model reanalysis indicates North Anna 1 & 2 still in compliance w/10CFR50.46.
SWANSON, D.T. Branch 1. 79/04/13. 1p.

7905240255 Requests extension of time to 790504 in which to prepare testimony. Granted by ASLAB on 790420. Certificate of Svc encl.
SWANSON, D.T. Branch 1. 79/04/20. 5pp.

7905030330 Affidavit of Svc for applicant's Amend 66 in proceeding NEIL, R.M. Virginia, State of. 79/04/25. 2pp.

DOCKETED ITEMS

159

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue. Parties have until 790525 in which to file for summary disposition.
BUFLO, M.E. Atomic Safety and Licensing Appeal Panel. 79/04/25. 12pp

7905240814 Forwards second copy of util's testimony re probability of generating turbine missiles & turbine overspeed protection sys. w/o encl.
CHRISTMAN, J.N. Hunton & Williams. 79/04/30. 2pp.

7905240510 Extends time for NRC review of ALAB-536 until 790511.
CHILK, S.J. Office of the Secretary of the Commission. 79/05/04. 1p.

7905240571 Following 790626 prehearing conference, hearing shall commence re application by util for OL amend to increase spent fuel pool storage capacity, per 790423 order granting intervention.
DEALE, V.B. Atomic Safety and Licensing Board Panel. 79/05/04. 3pp.

7905250233 Request to amend petition to intervene by adding contention re svc water cooling sys. Notice of appearance of GM Gilman on behalf of intervenors. Certificate of Svc & supporting documentation encl.
DOUGHERTY, J.B., GILMAN, G. Potomac Alliance. 79/05/09. 11pp.

I. Financial information

7905020459 Discusses SEC 790321 ltr & registration statement. Util will file another statement which NRC will be able to review.
DRUMERICK, A.W. Light Water Reactors Branch 3. 79/04/09. 1p.

--7905020466 Forwards SEC 790316 registration statement filed by util. Requests comments by 790330; util wishes statement to become effective by 790402.
MORIN, H.F. Securities & Exchange Commission. 79/03/21. 60pp.

J. Insurance & indemnity information

7905110107 Amend to Endorsement 51 to NELIA Policy NF-186. Constitutes Endorsement 34.
* Nuclear Energy Liability Insurance Association. 79/04/27. 1p.

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHCHI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

7905110090 Endorsements 16, 30, 36 & 47 to NELIA Policy NF-186.
BARDES, C.R. Nuclear Energy Liability Insurance Association. 79/05/01. 1p.

7905140523 Forwards Amend 5 to Indemnity Agreement B-80 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 6pp.

7905240342 Forwards executed Amend 5 to Indemnity Agreement B-80.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/21. 2pp.

7905300334 Forwards Endorsements 17, 20 & 21 to NELIA Policy NF-240.
KELLEY, P.J. Johnson & Higgins Insurance. 79/05/23. 4pp.

K. Inspection reports, IE Bulletins & correspondence

7905010235 Forwards IE Insp Repts 50-338-79-01 & 50-339/79-01 on 790102-0202 & notice of violation.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/16. 2pp.

--7905010264 Notice of violation from insp on 790102-0202.
* Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/14. 1p.

--7905010275 IE Insp Repts 50-338/79-01 & 50-339/79-01 on 790102-0202. Noncompliance noted: failure to document approval of change to test procedure.
KIDDS, N.B., CANTRELL, F.S. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/14. 19pp.

7905230129 Forwards IE Insp Rept 50-339/79-12 on 790215-16. No noncompliance noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/20. 2pp.

--7905230169 IE Insp Rept 50-339/79-12 on 790215-16. No noncompliance noted. Major areas inspected: 10CFR50.55(e) & 10CFR21 items.
MCFARLAND, C.R. Region 2, Atlanta, Office of the Director.
HERDT, A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/19. 4pp.

7905090051 Forwards IE Insp Rept 50-339/79-11 on 790129-0202. No noncompliance noted.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/21. 2pp.

--7905090056 IE Insp Rept 50-339/79-11 on 790129-0202. No noncompliance noted. Major areas inspected: procedures & activities necessary to implement operational GA program.
JENKINS, H.D., McDONALD, J.A. Region 2, Atlanta, Office of the Director.
KELLOGG, P.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/19. 30pp.

7905010224 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/23. 2pp.

7905020458 Forwards IE Insp Rept 50-339/79-13 on 790212-15. No noncompliance noted.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/23. 2pp.

--7905020471 IE Insp Rept 50-339/79-13 on 790212-15. No noncompliance noted. Major areas inspected: comparison of as-built plant to FSAR description.
SKOLDS, J.L. Region 2, Atlanta, Office of the Director.
CANTRELL, F.S. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/12. 3pp.

7905090129 Forwards IE Insp Repts 50-338/79-04 & 50-339/79-04 on 790122-25 & notice of violation.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/23. 2pp.

--7905090132 Notice of violation from insp on 790122-25.
* Region 2, Atlanta, Office of the Director. 79/03/13. 1p.

--7905090135 IE Insp Repts 50-338/79-04 & 50-339/79-04 on 790122-25. Noncompliance noted: failure to identify Tech Spec-listed snubbers prior to removal for testing.
DYER, J.A., JOHNSON, A.H. Region 2, Atlanta, Office of the Director.
MARTIN, R.D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/13. 8pp.

7905030319 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/26. 2pp.

7905010123 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/28. 2pp.

7905010369 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/30. 2pp.

7905240530 Forwards IE Insp Rept 50-339/79-18 on 790314-0316. No noncompliance noted.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/04/05. 2pp.

--7905240534 IE Insp Rept 50-339/79-18 on 790314-16. No noncompliance noted. Major areas inspected: startup procedures reviewed & pre-operational test witnessed.
BURNETT, P.T., DYER, J.A. Region 2, Atlanta, Office of the Director.
MARTIN, R.D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/04/04. 5pp.

7905020133 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/11. 1p.

7905040254 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp.

DOCKETED ITEMS

- 7905040271 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/14 1p
- 7905040448 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/14 1p
- 7905010317 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/16 2pp
- 7905030191 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/17 2pp
- 7905020502 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/18 2pp
- 7905240783 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." No S&W computer codes were identified which used methods described in bulletin.
SPENCER, W. C. Virginia Electric & Power Co. 79/04/25 2pp
- 7905290119 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/79-11 & 50-339/79-16.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/05/01 1p
- 7905290125 Responds to NRC 790316 ltr re violations noted in IE Insp Repts 50-338/79-11 & 50-339/79-16. Corrective actions: applicable emergency plan implementing procedures put into action.
STALLINGS, C. M. Virginia Electric & Power Co. 79/04/10 3pp
- 7905290130 Forwards IE Insp Repts 50-338/79-11 & 50-339/79-16 on 790228-0302 & notice of violation.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/03/16 2pp
- 7905290138 Notice of violation from insp on 790228-0302.
* Region 2, Atlanta, Office of the Director. 79/03/16 1p
- 7905290142 IE Insp Repts 50-338/79-11 & 50-339/79-16 on 790228-0302. Noncompliance noted: release of radioactivity to unrestricted area.
ZAVADOSKI, R. W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/03/16 5pp
- 7905300023 Forwards IE Insp Repts 50-338/79-12 & 50-339/79-19 on 790416-20. No noncompliance noted.
KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 79/05/02 2pp
- 7905300026 IE Insp Repts 50-338/79-12 & 50-339/79-19 on 790416-20. No noncompliance noted. Major areas inspected: security plan, protected area barriers, vital area barriers & access controls. Details withheld (ref 10CFR 7901).
HENNESSEY, R. J. Region 2, Atlanta, Office of the Director.
TOBIN, W. J. Region 2, Atlanta, Safeguards Branch. 79/05/02 1p
- 7905240481 Confirms 790426 response to IE Bulletin 79-06A re actions taken on Unit 1. All commitments for Unit 1 will apply to Unit 2.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/03 1p
- 7905210273 Responds to IE Bulletin 79-06A, Revision 1. Provides requested info on design changes containment sump pump trip valve actuation & safety injection logic.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/17 2pp
- 7905290032 Responds to IE Bulletin 79-09, GE Type AK-2 circuit breakers not in use or planned for use.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/23 1p
- S. Reportable occurrences, LERs & related correspondence**
- 7905100070 Provides info re overweight check valves used in safety injection sys. Error could result in pipes being overstressed during design basis test. Pipes being re-evaluated.
BROWN, S. C. Virginia Electric & Power Co. 79/03/26 2pp
- 7905100076 Submits info re valve limit switch actuating arms flexing each time valve operates. Actuating arms being reworked.
BROWN, S. C. Virginia Electric & Power Co. 79/03/26 2pp
- 7905100055 Submits info re cracked splinter plate in reactor coolant sys. Weldment samples of splinter plate/weld metal/pipe boss transition being analyzed.
BROWN, S. C. Virginia Electric & Power Co. 79/03/27 3pp
- 7905110203 Board notification: Seabrook refueling water storage tank design deficiency.
SCINTO, J. Hearings Division. 79/03/29 30pp
- 7905230235 Submits addl info to 790329 rept re failure of reversing motor starter supplied by Klockner-Moeller Corp. Discusses corrective actions re checkout procedure for discovering failures prior to startup.
* Virginia Electric & Power Co. 79/04/03 2pp
- 7905290529 Submits final rept on valve malfunction. All actuating arms on valve limit switch replaced & tested satisfactorily. New arms will provide reliable valve position information.
BROWN, S. C. Virginia Electric & Power Co. 79/04/19 2pp
- 7905070404 Rubber expansion joints in svc water piping found to be beyond misalignment tolerance acceptable to manufacturer. Svc water piping realigned & all expansion joints replaced.
BROWN, S. C. Virginia Electric & Power Co. 79/05/02 2pp
- 7905080511 Submits final rept re deficiency in analysis of DNBR following single rod drop. Proposes to assure that all dropped rods will result in reactor trip via negative rate trip function.
BROWN, S. C. Virginia Electric & Power Co. 79/05/03 1p
- 7905080434 Follows up 790406 & 11 repts re failure of inside recirculation spray pump motor. Mods & tests in progress.
BROWN, S. C. Virginia Electric & Power Co. 79/05/04 1p
- 7905080452 Final rept re cracked flow splitter plate on reactor coolant loop piping. Cracks are characteristic of high cycle fatigue, which was probably caused by fluid flow-induced resonance in splitter plates.
BROWN, S. C. Virginia Electric & Power Co. 79/05/04 2pp
- 7905090297 Notifies of completion of evaluation of cracks in loops C & A flow splitter plates. Cracks are characteristic of high cycle fatigue.
BROWN, S. C. Virginia Electric & Power Co. 79/05/04 2pp
- 7905110214 Submits final 10CFR50.55(e) rept re overweight check valves in safety injection sys. New loads for nozzles, where pipes affected by overweight valves connect to reactor coolant loop piping, are acceptable.
BROWN, S. C. Virginia Electric & Power Co. 79/05/08 1p
- 7905160418 Discusses pipe stress analysis deficiency for pipes passing through main steam valve house (MSVH). Analyses completed using appropriate MSVH seismic structural response. Revised nozzle loads on quench spray pumps sent to vendor.
BROWN, S. C. Virginia Electric & Power Co. 79/05/10 2pp
- 7905220344 Provides final rept re potential deficiency in regenerative heat exchanger support. Installation of bolt-on mod complete.
BROWN, S. C. Virginia Electric & Power Co. 79/05/17 1p
- 7905290404 Forwards revised one-line diagram showing changes to alleviate potential overload situation of electrical sys which supply offsite power for startup & emergency loads.
BROWN, S. C. Virginia Electric & Power Co. 79/05/23 3pp
- 7905300017 Reportable occurrence on 790521: weight of three 12-inch motor operated valves greater than that used by S&W in their original pipe stress analysis. Reanalysis of pipe stresses & support loads underway.
BROWN, S. C. Virginia Electric & Power Co. 79/05/24 2pp
- DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2**
- A. Application/construction stage documents & correspondence**
- 7905130630 Notifies of cancellation of 790424 meeting w/util in Bethesda, MD to discuss OL review.
KINTNER, L. L. Light Water Reactors Branch 1. 79/03/08 2pp
- 7905140251 Notifies of pending two-phase environ impact study at cooling water intake structure. Phase I will begin when plant begins drawing up water from Lake Erie. Phase II will commence when commercial operation begins.
TURNER, W. G. Michigan, State of. 79/05/03 2pp

DOCKETED ITEMS

161

7905310083 Requests addl info to complete review of FSAR Requests FSAR be amended by 790615 to comply w/requirements
STOLZ, J. F. Light Water Reactors Branch 1 79/05/07. 4pp.

F. Security, medical, emergency & fire protection plans

7905290528 Forwards request for addl info re security plan as result of review of OL application Request withheld (ref 10CFR 790)
STOLZ, J. F. Light Water Reactors Branch 1 79/04/13 2pp.

G. Adjudicatory correspondence

7905300025 Applicants' interrogatories submitted to Citizens for Employment & Energy Certificate of Svc encl
VOIGHT, H. H. Tolbuef, Lamb, Leiby & MacRae 79/03/27 9pp

H. General correspondence

7905160443 Forwards Certificate of Svc indicating avr of Amend 22 to amended & substituted application for licenses to appropriate parties
MATERS, B. R. Detroit Edison Co. 79/05/04 3pp

I. Financial information

7905040007 forwards 1978 Annual Repts of each of three co-owners Encl available in Central Files only
THOMAS, E. B. 79/04/24 1p

G. Inspection reports, II Bulletins & correspondence

7905010253 Forwards II Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J. C. Region 3, Chicago, Office of the Director 79/03/23 1p

7905230302 Forwards II Insp Rept 50 341/79 06 on 790308-09 No noncompliance noted
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/23 2pp

--7905230308 II Insp Rept 50 341/79 06 on 790308-09 No noncompliance noted Major areas inspected (HAZOP) program, preservice insp work activities & nondestructive examination repts
WARD, K. D., DANIELSON, D. H. Region 3, Chicago, Office of the Director 79/03/23 4pp

7905040030 Forwards II Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J. C. Region 3, Chicago, Office of the Director 79/03/26 1p

7905150410 Forwards II Insp Rept 50 341/79 05 on 790306-09 & notice of violation
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/27 2pp

--7905150413 Notice of violation from insp on 790506-09
* Region 3, Chicago, Office of the Director 79/03/27 2pp

--7905150419 IE Insp Rept 50 341/79 05 on 790306-09 Noncompliance noted density test was not performed & procedures re nonconforming backfill were not followed
HUOHES, J., BARRETT, P. A. Region 3, Chicago, Office of the Director HAYES, D. W. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/22 11pp

7905030029 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J. C. Region 3, Chicago, Office of the Director 79/04/11 1p

7905010586 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J. C. Region 3, Chicago, Office of the Director 79/04/14 1p

7905040387 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J. C. Region 3, Chicago, Office of the Director 79/04/14 1p

7905040460 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
KEPPLER, J. C. Region 3, Chicago, Office of the Director 79/04/14 1p

7905040556 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
KEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/04/14. 1p.

7905010415 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
KEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/04/16. 1p.

7905030224 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
KEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/04/17. 1p.

7905080492 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."
KEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/04/21. 1p.

790524089B Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase."
KEPPLER, J. C. Region 3, Chicago, Office of the Director. 79/05/02. 1p

G Reportable occurrences, LERs & related correspondence

7905080024 Ack receipt of 790322 interim report, per 10CFR50.55(e), re handling damage to core spray pump motor.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/04/04. 1p.

7905090351 Forwards final status rept EF2-46,047 of 790419 deficiency rept on "Toros Ring Beam Weld Indications."
FAHRNER, W. J. Detroit Edison Co. 79/05/01. 2pp.

--7905090355 Deficiency rept: defects in toe of ring beam attachment weld. Cracks caused hydrogen cracking, characterized by intergranular fracture of coarse grained HAZ. Corrected by grinding & new welding procedures.
* Detroit Edison Co. 79/04/19. 3pp.

DOCKET 50-344 TROJAN NUCLEAR PLANT, UNIT 1

G Adjudicatory correspondence

7905250260 Submits contentions for Phase 2 of mod proceedings. Certificate of Svc & notice of change of address encl.
BELL, N. Affiliation Unknown. 79/02/26. 7pp.

7905250279 Contentions of E Rosolie & Coalition for Safe Power re seismic capacity, cost/benefit analysis & insp procedures. Certificate of Svc encl.
ROSOLIE, E. Coalition for Safe Power. 79/02/26. 5pp.

7905030158 Response to 790130 contentions of N Bell, Consolidated Intervenor, E Rosolie & Coalition for Safe Power, Notice of appearance of AV Carr on behalf of Portland General Electric Co & Certificate of Svc encl.
JOHNSON, R. W. Portland General Electric Co. AXELRAD, M., CARR, A. V. Lowenstein, Newman, Reis, Axelrad & Toll. 79/03/16. 59pp.

7905250273 Responds to 790305 interrogatories re adequacy of plant staff review, radioactive isotopes, core meltdown & QA programs. Certificate of Svc encl.
ROSOLIE, E. Coalition for Safe Power. 79/03/19. 5pp.

7905150722 Motion for order to compel E Rosolie & Coalition for Safe Power to respond fully to util's 790305 interrogatories.
JOHNSON, R. W. Portland General Electric Co. AXELRAD, M., CARR, A. V. Lowenstein, Newman, Reis, Axelrad & Toll. 79/03/23. 27pp.

7905100067 Affirms ASLB 781221 denial of appeal by Coalition for Safe Power & Consolidated Intervenor re interim operation issue.
DUFLO, M. E. Atomic Safety and Licensing Appeal Panel. 79/03/27. 7pp.

7905100208 Position on contentions of Consolidated Intervenor & E Rosolie on behalf of Coalition for Safe Power, dtd 790226. Certificate of Svc encl.
GRAY, J. R. Branch 1. 79/03/27. 46pp.

7905070147 Informs of corrected address for Columbia Environ Council.
GRAY, J. R. Branch 1. 79/04/02. 1p.

DOCKETED ITEMS

7905250030 Offers no objection to intervenor State of OR motion for extension of time in which to file petition for review of 790321 ASLAB decision, ALAB-531.
GRAY, J. R. Branch 1. 79/04/05. 1p.

7905140033 Notifies parties that time for filing petitions for ALAB-531 review is extended until 790417. Time for NRC review is extended until 790430.
CHILK, S. J. Office of the Secretary of the Commission. 79/04/06. 1p.

7905250148 Requests answers to Contentions 1 & 18 of NRC 790309 interrogatories by 790416 & identification of any addl security concerns.
GRAY, J. R. Branch 1. 79/04/09. 1p.

7905150811 Forwards info re PWRs. Discusses NUREG-0409, "Iodine Behavior in PWR Sys Following Postulated Steam Generator Tube Rupture Accident."
GRAY, J. R. Branch 1. 79/04/10. 7pp.

7905250357 Petitions for review of 790321 ALAB-531 decision by ASLAB. Commission must ack strong possibility that each commercial reactor may become a de facto waste storage facility.
GARRETT, S. M. Coalition for Safe Power. 79/04/10. 7pp.

7905230550 Supplemental response to 790305 interrogatories from util. Certificate of Svc encl.
ROSOLIE, E. Coalition for Safe Power. 79/04/13. 7pp.

7905230546 Response to 790309 interrogatories from NRC. Certificate of Svc encl.
ROSOLIE, E. Coalition for Safe Power. 79/04/17. 6pp.

7905300104 Licensees' response to 790402 request of PA Public Util Commission for hearing & petition to intervene re 790313 show cause order. Urges NRC to hold ruling in abeyance.
CHURCHILL, B. W. Shaw, Pittman, Potts, & Trowbridge. 79/04/17. 4pp.

7905290042 Forwards revised pp 1 & 3 of util's answer opposing review of intervenor Garrett's 790410 petition.
HASTINGS, W. Portland General Electric Co. 79/04/23. 3pp.

7905230661 Orders extension until 790503 to review ALAB-534, dtd 790324.
CHILK, S. J. Office of the Secretary of the Commission. 79/04/24. 1p.

7905240948 Forwards list of requests for design charges re rept on design mods for control bldg. Certificate of Svc encl.
JOHNSON, R. W. Portland General Electric Co. 79/04/24. 6pp.

7905240224 Opposes 790411 motion by SM Garrett & Coalition for Safe Power for NRC review of ASLAB 790321 order re storage pool mod. Certificate of Svc encl.
GRAY, J. R. Branch 1. 79/04/26. 12pp.

mits info re work & workers involved in control bldg used in 790420 response to intervenors in proceeding. Requests analysis.
Portland General Electric Co. 79/05/02. 1p.

1978. "
79/03/31. 36pp.

in Eugene Water & Electric
SEC.
35pp.

1503 extension of ltr of
&
79/05/25. 3pp.

--7905300429 Discusses financial obligations under agreement w/Eugene Water & Electric Board re retrospective premiums under Price-Anderson Act.
HITTLE, L. G. Energy, Dept. of. 79/05/21. 2pp.

J. Insurance & indemnity information

7905020388 Forwards Endorsement 30 to MAELU Policy MF-86.
WILSON, F. R. Portland General Electric Co. 79/04/23. 2p.

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

7905160187 Forwards Amend 4 to Indemnity Agreement B-78, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 3pp.

7905220078 Forwards Endorsements 37 & 38 to ANI Policy NF-225, increasing limit of liability & establishing premium for increase, respectively.
WILSON, R. F. Portland General Electric Co. 79/05/16. 3pp.

P. Operating license stage documents & correspondence

7905020478 Forwards response to NRC 790126 comments on "Containment Structure Tendon Surveillance - One Year Surveillance," prepared by Bechtel Corp. Comments have been applied to third-year program now underway.
GOODWIN, C. Portland General Electric Co. 79/04/25. 38pp.

7905030361 Responds to DOE 790411 ltr. Unable to provide supplemental info by 790430. Response dependent upon preparation & approval of Offsite Dose Calculation Manual. Response will be ready by 790531.
GOODWIN, C. Portland General Electric Co. 79/04/27. 1p.

7905080431 Submits info re facility design, in response to J Holman 790418 request.
WITHERS, D. B. Portland General Electric Co. 79/04/30. 4pp.

7905040520 Forwards License Change Application 52. Certificate of Svc & \$4,000 Class III encl.
BRDEHL, D. J. Portland General Electric Co. 79/05/01. 2pp.

--7905040523 License Change Application 52 to License NPF-1. W/Tech Spec changes.
Portland General Electric Co. 79/05/01. 13pp.

7905150387 Forwards responses to 790508 & 790510 requests for info re pressurizer code safety valves, main feedwater sys & containment isolation valve functionality. Info needed for meeting on 790512.
BRDEHL, D. J. Portland General Electric Co. 79/05/11. 4pp.

7905230492 Notifies that Offsite Dose Calculation Manual & process control program require further review & will be submitted by 790630, instead of 790515.
GOODWIN, C. Portland General Electric Co. 79/05/15. 1p.

7905230407 Forwards response to NRC 790509 request for info re feedwater sys.
GOODWIN, C. Portland General Electric Co. 79/05/18. 4pp.

7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969. Review & reanalysis included all work through Dec 1970.
PORTER, F. L. EDS Nuclear, Inc. 79/05/21. 9pp.

--7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program. GE has no record of reanalysis for Cooper piping sys.
STEPHENS, P. W. General Electric Co., Nuclear Energy Products Div. 79/01/24. 18pp.

A. Inspection reports, IE Bulletins & correspondence

- 7905010289 Forwards II Info Notice 79-06, "Stress Analysis of Safety Related Piping"
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/03/23. 1p.
- 7905290078 Requests extension until 790715 for response to IE Bulletin 78-12, 78-12A & 78-12B
GOODWIN, C. Portland General Electric Co. 79/03/23. 1p.
- 7905040086 Forwards II Info Notice 79-07, "Rupture of Radwaste Tanks"
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/03/26. 1p.
- 7905040062 Forwards II Insp Rept 50-1447/79-05 on 790226-0302 No noncompliance noted
BOOK, H. E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch. 79/03/27. 2pp.
- 7905040366 II Insp Rept 50-1447/79-05 on 790226-0302 No noncompliance noted Major areas inspected: environ monitoring, radiation protection, spent fuel pool rack installation & followup on Part 21 rept
DAIRD, J. B., NORTON, H. G. Region 5, San Francisco, Office of the Director. BOOK, H. E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch. 79/03/27. 11pp.
- 7905010218 Forwards II Info Notice 79-08, "Interconnection of Contaminated Gas w/low Air Sys Used as Source of Breathing Air"
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/03/28. 1p.
- 7905010420 Forwards II Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/03/30. 1p.
- 7905010027 Forwards II Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During IMI Incident" licensee action required
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.
- 7905040497 Forwards II Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During IMI Incident"
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.
- 7905040416 Forwards II Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During IMI Incident"
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.
- 7905010102 Forwards II Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" licensee action required
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.
- 7905030293 Forwards II Bulletin 79-09, "Failures of GI Type AK-2 Circuit Breaker in Safety Related Sys" licensee action required
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/17. 1p.
- 7905080369 Forwards II Bulletin 79-05B, "Nuclear Incident at TH1-Suppl"
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/21. 1p.
- 7905130812 Responds to II Bulletin 79-07 Details computer program used in seismic stress analysis of safety related piping
GOODWIN, C. Portland General Electric Co. 79/04/23. 1p.
- 7905240908 Responds to II Bulletin 79-06A re IMI-2 event Describes actions taken
GOODWIN, C. Portland General Electric Co. 79/04/24. 15pp.

R. Periodic operating reports & related correspondence

- 7905110167 Forwards monthly operating rept for Apr 1979
WITHERS, B. D. Portland General Electric Co. 79/05/04. 1p.
- 7905110169 Monthly operating rept for Apr 1979
BAIR, C. G. Portland General Electric Co. 79/05/04. 4pp.

B. Reportable occurrences, LERs & related correspondence

- 7905150062 Forwards PNO-79-67L.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/06. 1p.
- 7905150168 Forwards PNO-79-67R.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/11. 1p.
- 7905040125 Forwards PNO-79-67S.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/12. 1p.
- 7905150142 Forwards PNO-79-67T.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/13. 1p.
- 7905030030 Forwards PNO-79-67U.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.
- 7905020529 Forwards PNO-79-67AA.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/20. 1p.
- 7905040449 Forwards LER 79-002/03L-0.
WITHERS, B. D. Portland General Electric Co. 79/04/20. 3pp.
- 7905040458 LER 79-002/03L-0 on 790322: automatic isolation feature of control room emergency ventilation sys on high chlorine & high radiation not verified during two 18-month periods. Caused by personnel error.
PERRY, J. C. Portland General Electric Co. 79/04/19. 1p.
- 7905010422 Forwards PNO-79-67AB.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/21. 1p.
- 7905010445 Forwards PNO-79-67AC & AD.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/23. 1p.
- 7905010458 Forwards PNO-79-67AE.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/24. 1p.
- 7905090039 Forwards PNO-79-67AF.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/25. 1p.
- 7905090054 Forwards PNO-79-67AG.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/26. 1p.
- 7905090116 Forwards PNO-79-67AH.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/27. 1p.
- 7905100267 Forwards LER 79-003/01T-0.
WITHERS, B. D. Portland General Electric Co. 79/04/27. 1p.
- 7905100270 LER 79-003/01T-0 on 790414: CV-2256 & CV-2276 valves failed to respond to manually initiated closing signal during periodic surveillance testing. Caused by valve packing binding stem. Packing adjusted.
PERRY, J. C. Portland General Electric Co. 79/04/27. 3pp.
- 7905070028 Forwards PNO-79-67AI, AJ & AK per NRC 790401 ltr transmitting IE Bulletin 79-05.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/30. 1p.
- 7905070010 Forwards PNO-79-67AL per NRC 790401 ltr transmitting IE Bulletin 79-05.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/05/01. 1p.
- 7905310053 Forwards PNO-79-67AM.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/05/07. 1p.

DOCKETED ITEMS

7905170238 Forwards LER 79-004/03L-0.
WITHERS, B. D. Portland General Electric Co. 79/05/10. 1p.

--7905170247 LER 79-004/03L-0 on 790411: 1-h surveillance test of emergency diesel generator not performed as required by Tech Specs. Caused by personnel error. Personnel reinstructed.
PERRY, J. C. Portland General Electric Co. 79/05/10. 3pp.

7905220289 Forwards LER 79-005/03L-0.
WITHERS, B. D. Portland General Electric Co. 79/05/14. 2pp.

--7905220293 LER 79-005/03L-0 on 790414: feedwater isolation valve failed following reactor trip. Backup valve closed properly so feedwater line was isolated. Caused by failure of hydraulic fitting.
PERRY, J. C. Portland General Electric Co. 79/05/14. 1p.

7905220311 Forwards LER 79-006/03L-0.
WITHERS, B. D. Portland General Electric Co. 79/05/15. 1p.

--7905220316 LER 79-006/03L-0 on 790415: leak discovered in auxiliary feedwater pump fuel line fitting. Caused by vibration. Fitting replaced. Fuel line design will be modified.
PERRY, J. C. Portland General Electric Co. 79/05/15. 2pp.

7905310350 RO: util cannot assure containment ventilation sys supply valves will remain leak tight following postulated LOCA while ventilating containment. Analysis shows damage to sys may result.
WITHERS, B. D. Portland General Electric Co. 79/05/21. 1p.

DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

G. Adjudicatory correspondence

7905070239 Requests denial of J. Doherty's 790404 motion for postponement of 790418 prehearing conference. Combustible gas control issue was not dropped from case.
NEWMAN, J. R. Lowenstein, Neuman, Reis, Axelrad & Toll. 79/04/06. 3pp.

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
GUATTROCHINI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

7905160231 Forwards Amend 4 to Indemnity Agreement B-79, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 5pp.

7905140361 Forwards Endorsements 28 & 29 to NELIA Policy NF-236.
LLOYD, R. D. Marsh & McLennan, M & M Nuclear Consultants, Inc. Div. 79/05/07. 3pp.

7905300418 Forwards executed Amend 4 to Indemnity Agreement B-79.
ROE, L. E. Toledo Edison Co. 79/05/25. 3pp.

P. Operating license stage documents & correspondence

7905240933 Confirms 790401 discussions. Will notify NRC prior to resuming operations. Postpones meeting scheduled for 790404.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/02. 1p.

7905240129 Ack receipt of 790116 ltr providing info re coolant sys flow data & total pressure drops. Review requires Class III fee.
DIOGS, R. M. License Fee Management Branch. 79/04/24. 1p.

7905240662 Expresses appreciation for 790305 ltr providing util views on NRC activities. Describes development of STS & radiological effluent Tech Specs.
BOYD, R. S. Division of Project Management. 79/05/01. 5pp.

--7905240671 Requests evaluation of NRC Tech Spec requirements, which util believes are often counterproductive and unnecessary.
ROE, L. E. Toledo Edison Co. 79/03/05. 3pp.

7905080416 As result of commitments contained in 790427 ltr, details addl actions to be taken prior to startup. In order to meet requirements, will initiate mod to provide control room verification of auxiliary feedwater flow to steam generator.
ROE, L. E. Toledo Edison Co. 79/05/04. 2pp.

7905090353 Forwards response to G. Vissing 790226 request for addl info re spent fuel pool capacity mod, to finalize environ assessment.
ROE, L. E. Toledo Edison Co. 79/05/04. 3pp.

7905150402 Forwards Chapters 1, 2, 8-10, 12 & 13, revised by Suppl 4 of initial startup rept. W/instructions for insertion.
GRANT, J. S. Toledo Edison Co. 79/05/09. 2pp.

--7905150405 Initial startup rept, Suppl 4, revising Chapters 1, 2, 8-10, 12 & 13. Covers testing completed 790106-0405.
* Toledo Edison Co. 79/05/09. 80pp.

7905190031 Forwards interim anticipatory reactor trip sys design (Drawing SK-E-409, Revision 1). Oversized drawing available in Central Files.
ROE, L. E. Toledo Edison Co. 79/05/11. 1p.

7905240586 In response to NRC 790424 ltr, forwards Class III amend fee.
ROE, L. E. Toledo Edison Co. 79/05/15. 1p.

7905220095 Forwards Offsite Dose Calculation Manual, to aid review of radiological ETS, submitted 790316.
ROE, L. E. Toledo Edison Co. 79/05/18. 67pp.

7905240403 Forwards addl info re auxiliary feedwater turbine dynamic brake installation, dual level setpoints for auxiliary feedwater controls & actuation signals, pressurizer level indication & water source & cross-connect requirements.
ROE, L. E. Toledo Edison Co. 79/05/19. 7pp.

7905290419 Forwards "Evaluation of Transient Behavior & Small Reactor Coolant Sys Breaks in 177 Fuel Assembly Plant, 790516," Vol 3, Revision 1.
ROE, L. E. Toledo Edison Co. 79/05/22. 1p.

--7905290422 "Evaluation of Transient Behavior & Small Reactor Coolant Sys Breaks in 177 Fuel Assembly Plant, 790516," Vol 3, Revision 1.
* Toledo Edison Co. 79/05/19. 66pp.

7905310450 Forwards info re auxiliary feedwater flow indicators, surveillance test/maint mode procedures & valve alignment requirements.
ROE, L. E. Toledo Edison Co. 79/05/22. 3pp.

7905300483 Forwards info requested at NRC 790508 meeting. Info includes overall reliability of auxiliary feedwater sys w/regard to operating history & design improvements.
ROE, L. E. Toledo Edison Co. 79/05/23. 16pp.

7905310375 Submits matrix to cross-reference station procedures w/operating procedure mods re NRC 790517 order & RN Reid 790518 ltr.
ROE, L. E. Toledo Edison Co. 79/05/23. 4pp.

G. Inspection reports, IE Bulletins & correspondence

7905100357 Notice of deviation from insp on 771116-18 & 30 & 1201-02.
* Region 3, Chicago, Reactor Operations Nuclear Support Branch. 77/12/16. 1p.

--7905100362 IE Insp Rept 50-346/77-34 on 771116-18 & 30 & 1201-02. No noncompliance noted. Major areas inspected: surveillance testing & investigation & followup associated w/loss of offsite power on 771129.
TAMBLING, T. N., KNOY, R. C. Region 3, Chicago, Office of the Director. 77/12/16. 7pp.

7905110097 Ack receipt of 771214 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-346/77-32.
FIORELLI, G. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/01/13. 1p.

--7905110099 Responds to NRC 771122 ltr re violation noted in IE Insp Rept 50-346/77-32. Corrective actions: Administrative Procedure AD 1823.00 revised & supervisors reinstructed re importance of filling out log sheets.
GRANT, J. S. Toledo Edison Co. 77/12/14. 2pp.

DOCKETED ITEMS

165

--7905110100 Forwards IE Insp Rept 50-346/77-02 on 770926-30, 1005-07, 18-21 & 27.
FIORELLI, G. Region 3, Chicago, Reactor Operations Nuclear Support Branch 77/11/22 2pp

--7905110108 Notice of violation from insp on 770926-30, 1005-07, 18-21 & 27.
* Region 3, Chicago, Office of the Director 77/11/18 1p

--7905110111 IE Insp Rept 50-346/77-02 on 770926-30, 1005-07, 18-21 & 27.
Noncompliance noted failure to properly implement procedure for jumper-lifted wire.
TAMBLING, I. N., HARTSHORN, I. L., KNOPF, R. C. Region 3, Chicago, Office of the Director 77/11/18 19pp

7905110089 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/77-06.
FIORELLI, G. Region 3, Chicago, Reactor Operations Nuclear Support Branch 78/07/12 1p

--7905110091 Responds to NRC 790430 ltr re violations noted in IE Insp. Rept 50-346/77-06. Corrective actions test deficiency documented on 790417 & proper review & changes to dropped rod control test obtained on 790615.
GRANT, J. S. Toledo Edison Co. 78/07/10 1p

--7905110092 Forwards IE Insp Rept 50-346/77-06 on 771206-08 & 790306-08 & notice of violation.
FIORELLI, G. Region 3, Chicago, Reactor Operations Nuclear Support Branch 78/04/20 2pp

--7905110093 Notice of violation from insp on 771206-08 & 790306-08.
* Region 3, Chicago, Office of the Director 78/04/19 1p

--7905110094 IE Insp Rept 50-346/77-06 on 771206-08 & 790306-08.
Noncompliance noted failure to perform rod drop testing at 40% power & failure to file test deficiency rept.
CRESWELL, J. S. Region 3, Chicago, Office of the Director
LITTLE, W. S. Region 3, Chicago, Reactor Operations Nuclear Support Branch 78/04/19 12pp

7905010267 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping".
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/03/20 1p

7905040053 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks".
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/03/26 1p

7905010176 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/50% Air Sys Used as Source of Breathing Air".
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/03/28 1p

7905010413 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin".
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/03/30 1p

7905030053 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident".
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/11 1p

7905010604 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident".
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14 1p

7905040427 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident".
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14 1p

7905040591 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident".
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14 1p

7905070174 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping". Licensee action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14 1p

7905240097 Responds to IE Bulletin 79-03 re defects in pipes mfg by Youngstown Welding & Engineering Co. Ultrasonic exam of containment spray sys piping revealed some defects, which are being evaluated.
GRANT, J. S. Toledo Edison Co. 79/04/16 3pp

7905250198 Forwards revision to 790411 response to IE Bulletin 79-05/ re auxiliary feedwater trains.
GRANT, J. S. Toledo Edison Co. 79/04/16 2pp.

7905030245 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/17 1p.

7905080509 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl." Licensee action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/21 1p.

7905150113 Ack receipt of 790403 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/79-05.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/04/25 1p.

--7905150121 Responds to NRC 790314 ltr re violations noted in IE Insp Rept 50-346/79-05. Corrective actions: reemphasized importance of review of surveillance test data & personnel instructed on proper work method re safety-related equipment.
GRANT, J. S. Toledo Edison Co. 79/04/03 2pp.

7905100354 Forwards IE Insp Rept 50-346/77-34 on 771116-18 & 30 & 1201-02. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 77/12/16 3pp.

R. Periodic operating reports & related correspondence

7905140233 Forwards monthly operating rept for Apr 1979.
MURRAY, T. D. Toledo Edison Co. 79/05/08 1p.

--7905140235 Monthly operating rept for Apr 1979.
CABA, E. C. Toledo Edison Co. 79/05/08 6pp.

S. Reportable occurrences, LERs & related correspondence

7905100375 PNO-77-171 as of 770926 no radioactive releases occurred at Davis-Besse 1, as result of loss of coolant pressure due to failure of pressurizer power operated relief valve.
KLINGER, D., NOLAN, F., SNIEZEK, J. H. Office of Inspection & Enforcement 77/09/26 1p

--7905100378 Reviews available info re reactor coolant sys depressurization event at Davis-Besse 2. No current indication of fuel damage or other serious problems at plant.
MCDERMOTT, R. J. Quality Assurance Branch. 77/10/06 2pp.

--7905100380 LER NP-32-77-16(Suppl) on 770924: depressurization of primary sys from normal operating pressure occurred, resulting in steam formation.
MURRAY, T. D. Toledo Edison Co. 77/11/14 60pp.

7905100341 Forwards LER 77-096/03L-0.
MURRAY, T. D. Toledo Edison Co. 77/12/16 2pp.

--7905100345 LER 77-096/03L-0 on 771129: diesel generator 1-1 started, but failed to supply power during temporary loss of power. Caused by diesel tripping on overspeed due to governor setting. Switches reset & diesel generator declared operable.
BEYER, B. Toledo Edison Co. 77/12/16 3pp.

7905020266 Notifies of reportable event on 790413: certain starters for essential motors had overload heaters installed which were smaller than capacity specified on relay data sheets, causing possible overload heater burnout. Heater being replaced.
MURRAY, T. D. Toledo Edison Co. 79/04/16 1p.

7905100286 RO on 790423: unplanned reactivity insertion of more than 0.3% occurred. Caused by valve MU39 leaking demineralized water. Procedure mod rewritten to prevent valve leakage & increase sampling frequency.
MURRAY, T. D. Toledo Edison Co. 79/04/23 1p.

7905020303 Forwards LER 79-046/03L-0.
MURRAY, T. D. Toledo Edison Co. 79/04/25 1p.

--7905020330 LER 79-046/03L-0 on 790330: diesel generator declared inoperable after loud, unusual noises & placed in action statement. Caused by bearing failure in turbocharger. Turbocharger replaced.
HARTIGAN, J. P. Toledo Edison Co. 79/04/25 3pp.

7905020418 Forwards LER 79-047/03L-0.
MURRAY, T. D. Toledo Edison Co. 79/04/25 1p.

DOCKETED ITEMS

--7905020438 LER 79-047/03L-0 on 790329: on 790331 makeup pump 1-1 taken out of svc for maint due to increased vibration & decreased pump performance. Caused by failure of first stage impeller which cut large groove in shaft.
HARTIGAN, J.P. Toledo Edison Co. 79/04/25. 3pp.

7905020488 Forwards LER 79-045/03L-0.
MURRAY, T.D. Toledo Edison Co. 79/04/25. 1p.

--7905020500 LER 79-045/03L-0 ON 790330: borated water storage tank low level trip setpoint in Safety Features Actuation Sys Channel II discovered out of tolerance. Caused by instrument drift & analog amplifier. Analog amplifier recalibrated.
NELSON, J.M. Toledo Edison Co. 79/04/25. 3pp.

7905020427 Forwards LER 79-048/01T-0.
MURRAY, T.D. Toledo Edison Co. 79/04/26. 1p.

--7905020443 LER 79-048/01T-0 on 790413: starters for essential motors had overload heaters installed which were smaller than capacity specified. Caused by error in initial installation due to procedural inadequacy. Check of overload heaters conducted.
MURRAY, T.D. Toledo Edison Co. 79/04/26. 3pp.

7905040129 Forwards LER 79-049/03L-0.
MURRAY, T.D. Toledo Edison Co. 79/04/26. 1p.

--7905040132 LER 79-049/03L-0 on 790331: during surveillance testing half of steam safety valves discovered to be out of design setpoint range. Caused by changing ambient conditions. Valves adjusted & retested.
BROWN, R.A. Toledo Edison Co. 79/04/27. 3pp.

7905090269 Forwards LER 79-050/01T-0.
MURRAY, T.D. Toledo Edison Co. 79/05/04. 1p.

--7905090273 LER 79-050/01T-0 on 790423: boron concentration dropped lower than anticipated final value, resulting in unplanned reactivity insertion. Caused by mechanical personnel & procedural error. Valve being repaired.
BROWN, D.H. Toledo Edison Co. 79/05/04. 3pp.

7905150455 Forwards LER 79-051/03L-0.
MURRAY, T.D. Toledo Edison Co. 79/05/09. 1p.

--7905150456 LER 79-051/03L-0 on 790410: fire alarm point F-056 sounded when no fire existed. Caused by lack of proper control room annunciation & procedure control. Procedure mods being prepared & installation of annunciator investigated.
LINGENFELTER, J. Toledo Edison Co. 79/05/09. 3pp.

7905160404 Forwards LER 79-052/03L-0.
MURRAY, T.D. Toledo Edison Co. 79/05/11. 1p.

--7905160409 LER 79-052/03L-0 on 790416: piece of duct tape found blocking inlet to containment pressure sampling line, rendering instruments inoperable. Tape removed.
NELSON, J.M. Toledo Edison Co. 79/05/11. 2pp.

7905220124 Forwards LER 79-035/03L-1.
MURRAY, T.D. Toledo Edison Co. 79/05/15. 1p.

--7905220125 LER 79-035/03L-1 on 790228: reactor coolant pump 1-1-2 tripped, resulting in reactor runback to 74%. Caused by loosening of inservice filter cover during maint. Cover retightened & add'l nameplates being made.
ROHRER, E. Toledo Edison Co. 79/03/27. 3pp.

7905220096 Forwards LER 79-053/03L-0.
MURRAY, T.D. Toledo Edison Co. 79/05/16. 1p.

--7905220101 LER 79-053/03L-0 on 790417: while in Mode 5, position indication for control rod 3 became erratic. Caused by defective connection in penetration butt splice. Butt splice reconnected. Tests will be made when in Mode 3.
NAYLOR, R.W. Toledo Edison Co. 79/05/16. 2pp.

7905220117 Forwards LER 79-054/03L-0.
MURRAY, T.D. Toledo Edison Co. 79/05/16. 1p.

--7905220121 LER 79-054/03L-0 on 790409: control room isolation damper HV53118 stuck open during surveillance test. Caused by corrosion of bushing in damper shaft. Damper removed & returned to manufacturer for reconditioning.
RUDOLPH, J.J. Toledo Edison Co. 79/05/16. 2pp.

7905230371 Forwards review of 770924 event re depressurization of primary sys. Similarities to 790328 incident at TMI-2 noted.
ROE, L.E. Toledo Edison Co. 79/05/18. 3pp.

7905250134 Forwards LER 79-055/03L-0.
MURRAY, T.D. Toledo Edison Co. 79/05/18. 1p.

--7905250142 LER 79-055/03L-0 on 790423: low reactor coolant pressure block bistable BA103 did not reset automatically on increasing surveillance test signal. Caused by sticking of relay K-4. Relay replaced.
NELSON, J.M. Toledo Edison Co. 79/05/18. 2pp.

DOCKET 50-348 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7905140357 Notifies of potential reportable inconsistency in calculated DNB ratios, as reported to util by Westinghouse.
HAIRSTON, W.G. Alabama Power Co. 79/03/30. 2pp.

F. Security, medical, emergency & fire protection plans

7905070631 Forwards check to replace check sent 790323 w/safeguards security contingency plan.
CLAYTON, F.L. Alabama Power Co. 79/05/01. 2pp.

I. Financial information

7905150391 Forwards "Annual Financial Rept 1978," unaudited financial statements for quarter ending 790331 & cash flow projections for 1979.
BOWDEN, T.J. Alabama Power Co. 79/05/10. 7pp.

--7905150395 "Annual Financial Rept 1978."
* Alabama Power Co. 78/12/31. 47pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHINI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

7905160224 Forwards Amend 4 to Indemnity Agreement B-81, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 3pp.

7905100304 Forwards Endorsement 23 to NELIA Policy NF-238.
DUCK, J.R. Marsh & McLendon, M & M Nuclear Consultants, Inc. Div. 79/05/04. 2pp.

7905150357 Forwards signed Amend 4 to Indemnity Agreement B-81.
BARTON, A.R. Alabama Power Co. 79/05/11. 2pp.

7905160396 Forwards Endorsement 24 to ANI Policy NF-238.
DUCK, J.R. Marsh & McLendon, M & M Nuclear Consultants, Inc. Div. 79/05/11. 2pp.

7905300468 Forwards Endorsement 25 to ANI Policy NF-238.
DUCK, J.R. Marsh & McLendon, M & M Nuclear Consultants, Inc. Div. 79/05/25. 2pp.

M. Antitrust correspondence

7905100196 AL Electric Cooperative's Response to applicant's "Memo re Impact of Public Regulatory Policies Act of 1978." Certificate of Svc & supporting documentation encl.
BOSKEY, B., MACGUINEA, D.B. Volpe, Boskey & Lyons. 79/03/28. 23pp.

7905100217 Response of Municipal Electric Util Association of AL to applicant's memo re impact of Public Util Regulatory Policies Act of 1978. Certificate of Svc encl. GOLDBERG, R. Goldberg, Fieldman & Letham, P.C. HJELMFELT, D.C. Affiliation Unknown. 79/03/28. 10pp.

7905240978 Notice of appearance of DJ Evans on behalf of NRC. Certificate of Svc encl. EVANS, D.J. Anti-Trust Division. 79/03/28. 3pp.

7905100269 Reply memo re impact of "Public Util Regulatory Policies Act of 1978" on proceeding. Act neither changes legal status of case nor impacts on decisions of liability. Certificate of Svc encl. AXELRAD, J.A. Regulations Division. EVANS, D.J. Anti-Trust Division. 79/03/29. 12pp.

7905240985 Responds to applicant's memo re impact of Public Util Regulatory Policies Act of 1978. Certificate of Svc & supporting documentation encl. WHITLER, J.D. Justice, Dept. of. 79/03/29. 22pp.

P. Operating license stage documents & correspondence

7905090079 Forwards Amend 11 to License NPF-2, safety evaluation & notice of issuance & availability. SCHWENCER, A. Operating Reactors Branch 1. 79/04/13. 3pp.

--7905090080 Amend 11 to License DPR-26, maintaining & implementing all provisions of approved fire protection plan. * Operating Reactors Branch 1. 79/04/13. 2pp.

--7905090083 Safety evaluation supporting Amend 11 to License DPR-26. * Office of Nuclear Reactor Regulation. 79/02/12. 30pp.

--7905090084 Notice of issuance & availability of Amend 11 to License DPR-26. SCHWENCER, A. Operating Reactors Branch 1. 79/04/13. 2pp.

7905020242 Forwards proposed amends to Tech Specs for Unit 1 incorporating radiological effluent Tech Specs into App A & proposed draft radiological effluent Tech Specs for Unit 2. Proposed draft App B Tech Specs encl. CLAYTON, F.L. Alabama Power Co. 79/04/16. 190pp.

7905040267 Ack receipt of 790104 application & 790321 supplementary filing. Requests payment of Class III fee. MILLER, W.O. License Fee Management Branch. 79/04/16. 2pp.

7905170266 Forwards proposed Tech Specs revision modifying safety injection logic by deleting coincident low pressurizer pressure/level logic actuation. CLAYTON, F.L. Alabama Power Co. 79/05/11. 10pp.

7905230414 Requests informal facility info re TMI incident be withheld from public disclosure unless util conducts proprietary review. CLAYTON, F.L. Alabama Power Co. 79/05/16. 2pp.

7905310376 Submits addl info re pressurizer pressure safety injection logic, in ref to 790523 telcon w/E Reeves & T Dunning. Pressurizer pressure transmitters 444, 445, 456 & 457 have control or protection functions. CLAYTON, F.L. Alabama Power Co. 79/05/23. 2pp.

7905010161 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/23. 2pp.

7905230777 Informs of delay in responding to IE Bulletin 78-12, 78-12A & 78-12B re weld mats used for each reactor vessel primary boundary ferritic weldment. Westinghouse is unable to provide needed data until 791031. CLAYTON, F.L. Alabama Power Co. 79/03/23. 1p.

7905030290 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/26. 2pp.

7905010093 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/28. 2pp.

7905010339 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/30. 2pp.

7905240514 Forwards IE Insp Rept 50-348/79-10 on 790313-0316 & 21-23. No noncompliance noted. MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/04. 2pp.

--7905240518 IE Insp Rept 50-348/79-10 on 790313-0316 & 21-23. No noncompliance noted. Major areas inspected: inservice insp, welding & nondestructive examination. CROWLEY, B.R. Region 2, Atlanta, Office of the Director. CONLON, T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/04. 7pp.

7905240523 Forwards IE Insp Rept 50-348/79-12 on 790306-0309. No noncompliance noted. LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/04/04. 2pp.

--7905240527 IE Insp Rept 50-348/79-12 on 790306-09. No noncompliance noted. Major areas inspected: LERS, Part 21 repts, open items, operations review & independent insp. HARDIN, A.K. Region 2, Atlanta, Office of the Director. CANTRELL, F.S. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/04/03. 6pp.

7905020124 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/11. 1p.

7905100279 Requests extension of time until 790512 to respond to IE Bulletin 79-03, "Longitudinal Weld Defects in Pipe Spools Mfg by Youngstown Welding & Engineering Co." CLAYTON, F.L. Alabama Power Co. 79/04/11. 1p.

7905150568 Confirms 790412 telcon to AK Hardin re IE Bulletin 79-02. Test program was initiated; enough failures found in anchor bolt installations to justify expansion of test scope. Further details will come in 14-day followup. HAIRSTON, W.G. Alabama Power Co. 79/04/12. 1p.

7905040148 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp.

7905040298 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp.

7905040322 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.

7905030137 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/17. 2pp.

7905020370 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/18. 2pp.

7905240443 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Methods specified by Item 1 have never been used. Therefore, specific concerns are not applicable to facility. CLAYTON, F.L. Alabama Power Co. 79/04/24. 3pp.

7905300710 Forwards response to IE Bulletins 79-06A & 79-06, Revision 1. Training program for personnel w/operational duties is being developed; actions required by operating procedures re transients & accidents have been reviewed. CLAYTON, F.L. Alabama Power Co. 79/04/24. 21pp.

7905300554 Responds to IE Bulletin 79-03. No SA-312 or other welded pipe mfg by Youngstown Welding & Engineering has been received on site or will be used in future. CLAYTON, F.L. Alabama Power Co. 79/04/26. 1p.

7905090075 Forwards "Inservice Testing Program for Class 1, 2 & 3 Pumps & Valves." Encl available in Central Files. CLAYTON, F.L. Alabama Power Co. 79/05/01. 2pp.

DOCKETED ITEMS

7905250036 Responds to IE Bulletin 79-04 "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp." One discrepancy found between weights specified in bulletin & actual weight of valve.
CLAYTON, F. L. Alabama Power Co. 79/05/01. 2pp.

R. Periodic operating reports & related correspondence

7905230361 Forwards monthly operating rept for Apr 1979.
CLAYTON, F. L. Alabama Power Co. 79/05/15. 2pp.

--7905230362 Monthly operating rept for Apr 1979.
HAIRSTON, W. G. Alabama Power Co. 79/05/01. 3pp.

S. Reportable occurrences, LERs & related correspondence

7905140368 Confirms 790328 telcon re LER 79-015/01T-0. While performing inservice insp on 790327, five linear surface indications discovered on ECCS line. Currently evaluating nondestructive examination on similar components.
HAIRSTON, W. G. Alabama Power Co. 79/03/28. 1p.

7905020247 Forwards LER 79-021/01T-0.
CLAYTON, F. L. Alabama Power Co. 79/04/26. 1p.

--7905020249 LER 79-021/01T-0 on 790412: in response to IE Bulletin 79-02, program initiated to randomly test anchor bolts installed in Seismic Category 1, safety-related, 2.5-inch grater piping sys. Statistical sample too small. Program expanded.
HAIRSTON, W. G. Alabama Power Co. 79/04/26. 3pp.

7905110242 Forwards LER 79-018/03L-0.
CLAYTON, F. L. Alabama Power Co. 79/05/07. 1p.

--7905110247 LER 79-018/03L-0 on 790409: discovered outer personnel air lock door not operating properly. Caused by inadequate procedural controls. Fuel handling procedures revised to verify that both air lock doors are closed.
* Alabama Power Co. 79/05/07. 3pp.

7905140306 Forwards LER 79-021/01T-1.
CLAYTON, F. L. Alabama Power Co. 79/05/08. 1p.

--7905140311 LER 79-021/01T-1 on 790412: statistical sampling of anchor bolt reliability not sufficient to provide high probability of greater than 95% reliability. Program expanded to include 100% testing.
HAIRSTON, W. G. Alabama Power Co. 79/05/08. 4pp.

7905160403 Forwards LERs 79-020/03L-0 & 79-015/01T-0.
CLAYTON, F. L. Alabama Power Co. 79/05/10. 1p.

--7905160414 LER 79-020/03L-0 on 790411: alarm received on BIJ sequencer. Sequencer found in test, rendering IO dc inoperable & violating min requirement for one dc set. Caused by faulty key switch breaking internal parts. Switch replaced.
* Alabama Power Co. 79/05/11. 1p.

--7905160407 LER 79-015/01T-1 on 790327: linear surface indications found on 2-inch ECCS line to Loop 1 cold leg, Loop 2 cold leg & Loop 3 hot leg. Probably caused during piping mfg. Affected part of Loop 1 replaced. Loop 2 & 3 indications ground out.
* Alabama Power Co. 79/05/10. 3pp.

7905300500 Forwards LER 79-019/03L-0.
CLAYTON, F. L. Alabama Power Co. 79/05/22. 1p.

--7905300504 LER 79-019/03L-0 on 790420: chemical analysis of reactor coolant revealed overconcentrations of chloride & fluoride. Cause undetermined. Engineering evaluation in progress.
HAIRSTON, W. G. Alabama Power Co. 79/05/22. 1p.

DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905040316 Summary of 790321 meeting of Mark II owners group in San Jose, CA re intermediate plant program tasks.
ANDERSON, C. J. Containment Systems Branch. 79/04/13. 150pp.

G. Adjudicatory correspondence

7905210058 Requests plant shutdown because of threat of accident as severe as rupture to reactor vessel.
ROMANO, F. R. Affiliation Unknown. 79/04/12. 5pp.

H. General correspondence

7905230711 Requests const review of facility. Expresses concern re insufficient supply of water near plant for cooling reactor.
BUGNANNO, N. A. Affiliation Unknown. 79/04/02. 1p.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

G. Inspection reports, IE Bulletins & correspondence

7905010134 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/03/23. 1p.

7905020077 Forwards IE Bulletin 79-06, "Review of Operational Errors: Sys Misalignments Identified During TMI Incident."
ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/11. 1p.

7905020372 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

7905040083 Forwards IE Bulletin 79-08, "Review of Operational Errors: Sys Misalignments Identified During TMI Incident."
ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

7905040264 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

7905030086 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/17. 1p.

7905020305 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/18. 1p.

DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905210058 Requests plant shutdown because of threat of accident as severe as rupture to reactor vessel.
ROMANO, F. R. Affiliation Unknown. 79/04/12. 5pp.

7905040316 Summary of 790321 meeting of Mark II owners group in San Jose, CA re intermediate plant program tasks.
ANDERSON, C. J. Containment Systems Branch. 79/04/13. 150pp.

H. General correspondence

7905230711 Requests const review of facility. Expresses concern re insufficient supply of water near plant for cooling reactor.
BUGNANNO, N. A. Affiliation Unknown. 79/04/02. 1p.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.

DOCKETED ITEMS

169

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

H. General correspondence

7905070450 Ack receipt of 790216 resolution opposing storage of high level radioactive wastes in township. Objections should be made at ASLB hearing. Expansion of storage pools is unlikely. No independent facilities are planned.
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/03/29. 5pp.

G. Inspection reports, IE Bulletins & correspondence

7905010134 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/03/23. 1p.

7905140291 Responds to 790312 ltr re resolution adopted on 790216 by Township of Lower Alloways Creek, NJ. Resolution opposes storage of high level wastes. Forwards NRC response.
GOSSICK, L.V. Office of the Executive Director for Operations. 79/04/11. 1p.

7905020077 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/11. 1p.

I. Financial information

7905070647 Forwards "Annual Financial Rept, 1978" for Public Svc Electric & Gas Co, Atlantic City Electric Co, Delmarva Power & Light Co & Philadelphia Electric Co.
FRYLING, R. Public Service Electric & Gas Co. of New Jersey. 79/04/30. 162pp.

7905020372 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

J. Insurance & indemnity information

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

7905040083 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

7905040264 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

G. Inspection reports, IE Bulletins & correspondence

7905010140 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/03/23. 1p.

7905030086 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/17. 1p.

7905020100 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/11. 1p.

7905020305 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/18. 1p.

7905020369 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905070552 Submits revised schedule re response to NRC's position on NUREG-0313, "Technical Rept on Matl Selection & Processing Guidelines for BWR Coolant Pressure Boundary Piping." Response will be submitted no later than Sept 1979.
MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 79/04/23. 1p.

7905040093 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

O. Adjudicatory correspondence

7905230512 Util response to briefs opposing de minimus approach of Perkins proceeding. Licensees in Peach Bottom & Hope Creek proceedings conted approach is valid; no need to consider health effects further. W/Certificate of Svc.
CONNER, T.B. Conner, Moore & Corber. 79/04/04. 30pp.

7905040282 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record. Certificate of Svc encl.
SCINTO, J.F. Hearings Division. 79/04/11. 45pp.

7905030101 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/17. 1p.

7905140519 Response to 790404 brief of Philadelphia Electric Co, PSE&G & Atlantic City (NJ) Electric Co re de minimus theory. Certificate of Svc encl.
KEPFORD, C.R. Citizens for Safe Environment. 79/04/11. 8pp.

7905020322 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/18. 1p.

DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue. Parties have until 790525 in which to file for summary disposition.
DUFLD, M.E. Atomic Safety and Licensing Appeal Panel. 79/04/25. 13pp.

7905070552 Submits revised schedule re response to NRC's position on NUREG-0313, "Technical Rept on Matl Selection & Processing Guidelines for BWR Coolant Pressure Boundary Piping." Response will be submitted no later than Sept 1979.
MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 79/04/23. 1p.

7905240585 Memo & order ALAB-546. Denies applicants' petition for reconsideration of ALAB-540, which consolidates applicants re radon issue.
DUFLD, M.E. Atomic Safety and Licensing Appeal Panel. 79/05/08. 3pp.

DOCKETED ITEMS

G. Adjudicatory correspondence

7905230512 Util response to brief opposing de minimus approach of Perkins proceeding. Licensees in Peach Bottom & Hope Creek proceedings contend approach is valid; no need to consider health effects further. W/Certificate of Svc.
CONNERT, T. B. Conner, Moore & Corber. 79/04/04. 30pp.

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record. Certificate of Svc encl.
SCINTO, J. F. Hearings Division. 79/04/11. 45pp.

7905140519 Response to 790404 brief of Philadelphia Electric Co. PSE&G & Atlantic City (NJ) Electric Co re de minimus theory. Certificate of Svc encl.
KEPFORD, C. R. Citizens for Safe Environment. 79/04/11. 8pp.

7905140332 Notices of consolidation of five intervenor groups re radon emissions issue. Parties have until 790525 in which to file for summary disposition.
DUFLD, M. E. Atomic Safety and Licensing Appeal Panel. 79/04/23. 13pp.

7905240565 Memo & order ALAB-546. Denies applicants' petition for reconsideration of ALAB-540, which consolidates applicants re radon issue.
DUFLD, M. E. Atomic Safety and Licensing Appeal Panel. 79/05/08. 3pp.

H. General correspondence

7905070450 Ack receipt of 790216 resolution opposing storage of high level radioactive wastes in township. Objections should be made at ASLB hearing. Expansion of storage pools is unlikely. No independent facilities are planned.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/03/29. 5pp.

7905140291 Resonds to 790312 ltr re resolution adopted on 790216 by Township of Lower Alloways Creek, NJ. Resolution opposes storage of high level wastes. Forwards NRC response.
GOSSICK, L. V. Office of the Executive Director for Operations. 79/04/11. 1p.

I. Financial information

7905070647 Forwards "Annual Financial Rept. 1978" for Public Svc Electric & Gas Co. Atlantic City Electric Co. Delmarva Power & Light Co & Philadelphia Electric Co.
FRYLING, R. Public Service Electric & Gas Co. of New Jersey. 79/04/30. 162pp.

J. Insurance & indemnity information

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

K. Inspection reports, IE Bulletins & correspondence

7905010140 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/03/23. 1p.

Forwards IE Bulletin 79-06, "Review of Operational Errors & Incidents Identified During TMI Incident."
Region 1, Philadelphia, Office of the Director.

Seismic Stress Analysis of
required.
of the Director.

Operational Errors &
Director.

7905030101 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Svs." Licensee action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/17. 1p.

7905020322 Forwards IE Bulletin 79-06A. Revision 1, "Review of Operational Errors & Svs Misalignments Identified During TMI Incident."
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/18. 1p.

DOCKET 50-358 WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905040316 Summary of 790321 meeting of Mark II owners group in San Jose, CA re intermediate plant program tasks.
ANDERSON, C. J. Containment Systems Branch. 79/04/13. 150pp.

7905100258 Summary of 790410 meeting w/Cincinnati Gas & Electric Co. Long Island Lighting Co & Commonwealth Edison Co re vibratory loads & equipment qualification. Presentation matl encl.
PELTIER, I. A. Light Water Reactors Branch 1. 79/04/19. 15pp.

7905230558 Notification of 790515-17 meeting w/Cincinnati Gas & Electric Co. Long Island Lighting Co. Commonwealth Edison Co & GE in San Jose, CA to audit NSSS equipment for seismic & other dynamic qualification.
PELTIER, I. A. Light Water Reactors Branch 1. 79/04/23. 3pp.

7905020451 Response to 790223 ltr requesting plans & schedule for re-qualification of equipment for seismic & hydrodynamic loads. All Category I equipment has been evaluated as qualified.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 79/04/26. 3pp.

7905080439 Forwards requested info re seismic Category I equipment, scenario for accomplishing cold shutdown & Sargent & Lundy Balance of Plant equipment for Category I.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 79/05/04. 49pp.

E. NRC Safety Evaluation Report (SER), suppls & correspondence

7905010659 Summary of 790328 meeting w/util re status of implementation of SER issues.
PELTIER, I. A. Light Water Reactors Branch 1. 79/04/12. 7pp.

F. Security, medical, emergency & fire protection plans

7905240572 Summarizes progress in fire protection review. Because redundant electrical divisions are in same fire area, they are suby to identical fire exposure. Fire ratings must be verified prior to OL issuance.
STOLZ, J. F. Light Water Reactors Branch 1. 79/04/19. 3pp.

7905140156 Forwards intervenor Miami Valley Power Project's 790223 answers to util's second set of interrogatories. Questions application of lead plant Mark II acceptance criteria.
KOSIK, L. S. Kosik, L. S. 79/02/21. 1p.

7905140157 Motion by intervenor Miami Valley Power Project to applicant's motion to dismiss. Certificate of Svc encl.
KOSIK, L. S. Kosik, L. S. 79/02/22. 2pp.

7905140369 Answer by intervenor Miami Valley Power Project to applicant's second set of interrogatories. Supporting documentation & Certificate of Svc encl.
KOSIK, L. S. Kosik, L. S. 79/02/22. 8pp.

7905150131 Discusses answers to Cincinnati Gas & Electric Co's interrogatories. Propounds third set of interrogatories to obtain specific responses to second set of questions.
WETTERHAHN, M. J. Conner, Moore & Corber. 79/03/05. 2pp.

7905150133 Applicants' third set of interrogatories to Miami Valley Power Project. Certificate of Svc encl.
WETTERHAHN, M. J. Conner, Moore & Corber. 79/03/05. 6pp.

7905010223 Requests to know if NRC has funds available for use by intervenors to obtain expert witnesses in licensing hearings.
KOSIK, L. S. Kosik, L. S. 79/03/07. 1p.

DOCKETED ITEMS

171

- 7905150144 Interrogatories of intervenor D Fankhauser submitted to applicant. Certificate of Svc encl.
WOLIVER, J.D. Woliver, J.D. 79/03/08. 5pp.
- 7905290171 Opposes D Fankhauser response to 790306 proposed timetable of events. Certificate of Svc encl.
CONNER, T.B., WETTERHAHN, M.J. Conner, Moore & Corber. 79/03/08. 3pp.
- 7905290176 Motion to order answering of fourth set of interrogatories directed to Miami Valley Power Project. Certificate of Svc encl.
CONNER, T.B., WETTERHAHN, M.J. Conner, Moore & Corber. 79/03/08. 3pp.
- 7905290180 Serves fourth set of interrogatories on Miami Valley Power Project. Certificate of Svc encl.
WETTERHAHN, M.J. Conner, Moore & Corber. 79/03/08. 4pp.
- 7905290464 Submits supplementary answers to applicant's second set of interrogatories. Affidavit encl.
KOSIK, L.S., Kosik, L.S. RIGBERG, S. Miami Valley Power Project. 79/03/13. 6pp.
- 7905290468 Memo in opposition to applicant's motion to require response to fourth set of interrogatories.
RIGBERG, S. Miami Valley Power Project. 79/03/13. 4pp.
- 7905290520 Response to proposed prehearing conference schedule. Schedule reflects impatience rather than sound judgment. Certificate of Svc encl.
RIGBERG, S. Miami Valley Power Project. 79/03/13. 5pp.
- 7905150151 Opposition by applicant to Miami Valley Power Project 790307 motion to admit addl contentions & to extend time for discovery. Project does not satisfy requirements of 10CFR2.715. Certificate of Svc encl.
CONNER, T.B., WETTERHAHN, M.J. Conner, Moore & Corber. 79/03/19. 9pp.
- 7905100210 Responds to intervenor Miami Valley Power Project's set of interrogatories. Affidavit & Certificate of Svc encl.
BORGMANN, E.A. Cincinnati Gas & Electric Co. 79/03/21. 45pp.
- 7905300062 Forwards applicant's objections to Miami Valley Power Project first set of interrogatories & motion for protective order.
WETTERHAHN, M.J. Conner, Moore & Corber. 79/03/21. 1p.
- 7905300067 Applicant's objections to certain of Miami Valley Power Project's first set of interrogatories & motion for protective order. Certificate of Svc encl.
WETTERHAHN, M.J., CONNER, T.B. Conner, Moore & Corber. 79/03/21. 6pp.
- 7905010215 NRC is not legally obligated to financially assist intervenors.
SHAPAR, H.K. Office of the Executive Legal Director. 79/03/22. 2pp.
- 7905240412 Ack receipt of 790307 ltr. Informs that US Court of Appeals held that agencies cannot fund participants in proceedings w/o special grant of authority from Congress. NRC will not fund participants in rulemaking proceedings.
SHAPAR, H.K. Office of the Executive Legal Director. 79/03/22. 1pp.
- 7905080379 Opposes applicant's 790308 motion to require response by intervenor Miami Valley Power Project to interrogatories submitted by applicant. Certificate of Svc encl.
BARTH, C.A. Branch 3. 79/03/26. 7pp.
- 7905100222 Responds to interrogatories served by intervenor D Fankhauser upon applicant. Certificate of Svc encl.
BORGMANN, E.A. Cincinnati Gas & Electric Co. 79/03/27. 23pp.
- 7905170301 Forwards applicant's objections to intervenor Fankhauser's interrogatories & motion for protective order.
WETTERHAHN, M.J. Conner, Moore & Corber. 79/03/27. 1p.
- 7905170303 Applicant's objections to intervenor D Fankhauser's interrogatories & motion for protective order. Three interrogatories exceed scope of proceeding. Certificate of Svc encl.
WETTERHAHN, M.J. Conner, Moore & Corber. 79/03/27. 6pp.
- 7905300091 NRC opposition to Miami Valley Power Project's motion to admit two addl contentions re adequacy of cable trays & control rods. Recommends denial of motion according to 10CFR2.714(a)&(b). Certificate of Svc encl.
BARTH, C.A. Branch 3. 79/03/27. 5pp.
- 7905150757 Response in support of admission of addl contentions & extension of time for discovery. Certificate of Svc encl.
RIGBERG, S., McDONALD, T. Miami Valley Power Project. 79/04/02. 13pp.
- 7905020334 NRC expects to issue suppl to SER prior to end of May.
BARTH, C.A. Branch 3. 79/04/04. 1p.
- 7905220075 Forwards summary of "Rept to Commission--Inquiry into an Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Grid Serving St Lucia."
BARTH, C.A. Branch 3. 79/04/04. 2pp.
- 7905220084 Discusses inquiries into charges of possible NRC employee misconduct by restricting investigations of power grid disturbances. Available evidence does not support such allegations.
MCTIERNAN, T.J. Office of Inspector & Auditor. 78/06/26. 5pp.
- 7905080341 NRC has recently discovered document possibly relevant to issue of sabotage of spent fuel. Info is classified & may never be published in final form. NRC assessment of info will follow as soon as available.
BARTH, C.A. Branch 3. 79/04/05. 2pp.
- 7905100169 Memo by Cincinnati Gas & Electric in support of 771031 motion for summary judgment re certain admitted contentions. Affidavits of KL Rooney, JR Schott & QC Ficke encl.
WETTERHAHN, M.J. Conner, Moore & Corber. 79/04/06. 66pp.
- 7905140083 Response to second set of interrogatories submitted by intervenor Miami Valley Power Project. Certificate of Svc encl.
BORGMANN, E.A. Cincinnati Gas & Electric Co. 79/04/06. 24pp.
- 7905250117 Objections by util to portions of intervenor Miami Valley Power Project's 790319 second set of interrogatories. Also seeks protective order.
WETTERHAHN, M.J. Conner, Moore & Corber. 79/04/06. 3pp.
- 7905250123 Request by util that Miami Valley Power Project be dismissed as party for violations of discovery rules, or in the alternative, that util be granted extension of time to file motion of summary judgment re project's contentions.
WETTERHAHN, M.J. Conner, Moore & Corber. 79/04/06. 4pp.
- 7905300690 Notification of new schedule, including new dates for prehearing conference.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 79/04/06. 4pp.
- 7905250208 Notice of prehearing conference on 790521-23, to be held per ASLB 790406 order.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 79/04/09. 2pp.
- 7905150227 Motion to delay OL hearings & to extend time for discovery re Contention 13. Certificate of Svc encl.
KOSIK, L.S. Miami Valley Power Project. 79/04/16. 6pp.
- 7905240506 Forwards request for ASLAB decisions from C Richards & summary of NRC 790327 meeting w/util to discuss fire protection.
BARTH, C.A. Branch 3. 79/04/16. 5pp.
- 7905240515 Requests copies of ALAB-444 & ALAB-462 be sent to aid in research re use & availability of U fuel.
RICHARDS, C. Affiliation Unknown. 79/04/10. 1p.
- 7905150218 Motion by intervenor D Fankhauser to reopen discovery & for continuance of hearing, pending NRC review of TMI-2 incident. Certificate of Svc encl.
WOLIVER, J.D. Woliver, J.D. 79/04/17. 4pp.
- 7905150212 Opposes util's motion to dismiss intervenor Miami Valley Power Project as party. Does not oppose util's alternative request for extension of time. Certificate of Svc encl.
KOSIK, L.S. Miami Valley Power Project. 79/04/18. 4pp.
- 7905150221 Third set of interrogatories to applicant. Certificate of Svc encl.
KOSIK, L.S. Miami Valley Power Project. 79/04/20. 11pp.
- 7905240092 Requests joint appearance for A Shapiro & EJ Torchia at ASLB hearings in Moscow, OH on 790522 & Cincinnati, OH on 790523. Requests notification of meeting schedule.
TORCHIA, E.J. Affiliation Unknown. 79/04/20. 1p.

DOCKETED ITEMS

7905240104 Complaints that date of 790423 is unrealistic; objections & protective order were filed after receipt of discovery motions.
KOSIK, L.S. Kosik, L. S. 79/04/20. 1p.

7905310093 Fifth set of interrogatories submitted by util to Miami Valley Power Project. Certificate of Svc encl.
WETTERHAHN, M.J. Conner, Moore & Corber. 79/04/20. 7pp.

7905290036 Grants extension until 790502 for NRC to respond to util's 790406 motion for summary disposition.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 79/05/01. 2pp.

7905150284 Orders one-day extension until 790502 for City of Cincinnati to respond to util's 790406 motion for summary disposition.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 79/05/02. 1p.

7905300749 Requests opportunity to present limited statement at 790523 prehearing conference in Moscow, OH.
ZITT, K.L. Affiliation Unknown. 79/05/04. 1p.

H. General correspondence

7905300284 Requests deletion of PH Forster of Dayton Power & Light Co from svc list & replacement w/SG Smith.
FLYNN, J.D. Cincinnati Gas & Electric Co. 79/05/25. 1p.

J. Insurance & indemnity information

7905160272 Forwards Amend 2 to Indemnity Agreement B-85, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 5pp.

7905110148 Forwards Indemnity Agreement B-85 & Amend 1.
BORGMANN, E.A. Cincinnati Gas & Electric Co. 79/05/04. 15pp.

K. Utility Final Safety Analysis Report (FSAR) & amendments

7905290449 Forwards Amend 92 to application, consisting of Revision 57 to FSAR.
BORGMANN, E.A. Cincinnati Gas & Electric Co. 79/04/30. 2pp.

---7905290456 Amend 92 to application, FSAR Revision 57. Submitted in response to second round questions.
* Cincinnati Gas & Electric Co. 79/04/30. 400pp.

7905160434 Forwards Certificate of Svc of Amend 92, in form of Revision 57 to FSAR.
BORGMANN, E.A. Cincinnati Gas & Electric Co. 79/05/10. 2pp.

G. Inspection reports, IE Bulletins & correspondence

7905010242 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/03/23. 1p.

7905030372 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/03/26. 1p.

7905240719 Forwards IE Insp Rept 50-358/79-08 on 790305-06. No noncompliance noted.
HEISHMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/03/27. 2pp.

---7905240729 IE Insp Rept 50-358/79-08 on 790305-06. No noncompliance noted. Major areas inspected: operational QA program & station staffing.
HARPSTER, T.L., MENNING, J.E., WERNICK, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/03/15. 2pp.

7905150529 Forwards IE Insp Rept 50-358/79-10 on 790319-20. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/03/29. 2pp.

---7905150535 IE Insp Rept 50-358/79-10 on 790319-20. No noncompliance noted. Major areas inspected: review of procedures, work activities & quality records for hangers, snubbers & restraints design.
YIN, L.T., NAIDUK, R. Region 3, Chicago, Office of the Director.
DANIELSON, D.H. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/03/28. 5pp.

7905290699 Forwards IE Insp Rept 50-358/79-09 on 790321-23. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/04/09. 2pp.

---7905290720 IE Insp Rept 50-358/79-09 on 790321-23. No noncompliance noted. Major areas inspected: followup of previously identified noncompliance & unresolved matters & review of electrical & instrumentation activities in progress.
VANDEL, T.E., HUGHES, J., KNOP, R.C. Region 3, Chicago, Office of the Director. 79/04/06. 8pp.

7905030017 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/11. 1p.

7905010574 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/14. 1p.

7905040351 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/14. 1p.

7905040452 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/14. 1p.

7905040534 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/14. 1p.

7905010400 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/16. 1p.

7905030215 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/17. 1p.

7905040368 Responds to 781017 phone call re Sargent & Lundy control of stress rept documentation. NRC review discloses weakness in control of outdated procedures & will be pursued until open item is adequately resolved. W/o encl.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/19. 1p.

7905080397 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/21. 1p.

7905140107 Ack receipt of 790411 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/79-07.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/04/25. 1p.

---7905140111 Responds to NRC 790305 ltr re violations noted in IE Insp Rept 50-358/79-07. Corrective actions: approved calibr procedure implemented & uncontrolled rods & stubs removed.
BORGMANN, E.A. Cincinnati Gas & Electric Co. 79/04/11. 3pp.

7905240887 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/05/02. 1p.

S. Reportable occurrences, LERs & related correspondence

7905070009 Ack receipt of 790313 final rept re control rod interference, per 10CFR50.55(e).
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/04/04. 1p.

DOCKETED ITEMS

173

DOCKET 50-360 BATTELLE MEMORIAL INST. CRITICAL FACILITY

J. Insurance & indemnity information

7905160233 Forwards Amend 7 to Indemnity Agreement B-58, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl. SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 5pp.

7905300523 Forwards Amend 7 to Indemnity Agreement B-58. FRANSEN, C. D. Battelle Memorial Institute, Pacific Northwest Laboratory. 79/05/24. 2pp.

DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905010553 Comments on "Cultural Resource Mgt Repts for San Onofre-to-Mission-to-Encino 230 kV Transmission Lines & Mapping & Data Recovery Program for Site W-1527." Repts are suitable as baseline studies. Identifies questions for clarification. MELLON, K. California, State of. 79/03/20. 2pp.

7905230589 Notification of 790426 meeting w/util in Bethesda, MD to discuss fuel design & analysis. ROOD, H. Light Water Reactors Branch 2. 79/04/19. 3pp.

7905290411 Notification of 790504 meeting w/util in Bethesda, MD to discuss San Onofre geology. ROOD, H. Light Water Reactors Branch 2. 79/05/02. 3pp.

7905210160 Forwards equipment seismic qualification summary info, in response to NRC 790111 request in preparation for site visit. Drawings available in Central Files only. BASKIN, K. P. Southern California Edison Co. 79/05/16. 700pp.

I. Financial information

7905150400 Forwards "Annual Financial Rept 1978" for Southern CA Edison Co & San Diego Gas & Electric Co. DRAKE, J. H. Southern California Edison Co. 79/05/08. 1p.

--7905150404 "Annual Financial Rept 1978." * Southern California Edison Co. 79/02/15. 31pp.

--7905150406 "Annual Financial Rept 1978." * San Diego Gas & Electric Co. 79/02/20. 43pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others. GUATTROCHMI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96. ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

M. Antitrust correspondence

7905310373 Submits request for addl info to complete antitrust review of OL application. TOALSTON, A. L. Antitrust & Indemnity Group. 79/05/11. 3pp.

Q. Inspection reports, IE Bulletins & correspondence

7905010292 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping." ENGELKEN, R. H. Region 4, Dallas, Office of the Director. 79/03/23. 1p.

7905010025 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905040512 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905040619 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905070104 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905030296 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/17. 1p.

7905080371 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl." ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/21. 1p.

S. Reportable occurrences, LERs & related correspondence

7905150064 Forwards PNO-79-67L. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/06. 1p.

7905150170 Forwards PNO-79-67R. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/11. 1p.

7905040128 Forwards PNO-79-67S. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/12. 1p.

7905150145 Forwards PNO-79-67T. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/13. 1p.

7905030024 Forwards PNO-79-67U. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905020332 Forwards PNO-79-67AA. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/20. 1p.

7905010434 Forwards PNO-79-67AB. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/21. 1p.

7905010449 Forwards PNO-79-67AC & AD. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/23. 1p.

7905010462 Forwards PNO-79-67AE. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/24. 1p.

7905090041 Forwards PNO-79-67AF. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/25. 1p.

7905090057 Forwards PNO-79-67AG. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/26. 1p.

7905310012 Ack receipt of 790406 interim rept on Taylor Forge pipe defects pursuant to 10CFR50.55(a). ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/26. 1p.

7905090119 Forwards PNO-79-67AH. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/27. 1p.

7905070031 Forwards PNO-79-67AI, AJ & AK, per NRC 790401 ltr transmitting IE Bulletin 79-05. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/30. 1p.

7905070012 Forwards PNO-79-67AL, per NRC 790401 ltr transmitting IE Bulletin 79-05. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/05/01. 1p.

DOCKETED ITEMS

7905090277 Provides followup on 790108 final rept on reportable condition re fillet weld design. Revised drawings for remaining 78 pipe support assemblies will be issued for const use by 790904.
MOORE, J. B. Southern California Edison Co. 79/05/02. 1p.

7905310044 Forwards PNO-79-67AM.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/05/07. 1p.

7905300265 Forwards interim rept of Marine Review Committee re ECCS.
WONG, S. California, State of. 79/05/15. 1p.

--7905300270 "Interim Rept of Marine Review Committee to CA Coastal Commission, Part I: General Summary of Findings, Predictions & Recommendations Concerning Cooling Sys."
CONNELL, J. H., MECHALAS, B. J., MIHURSKY, J. A. California, State of. 79/05/12. 22pp.

--7905300277 "Interim Rept of Marine Review Committee to CA Coastal Commission, Part II: App of Technical Evidence in Support of General Summary."
CONNELL, J. H., MECHALAS, B. J., MIHURSKY, J. A. California, State of. 79/05/12. 197pp.

7905310423 Forwards final deficiency rept, "Undersized Safety-Related Heating, Ventilating & Air Conditioning Damper Actuators," identified in 790419 ltr.
MOORE, J. B. Southern California Edison Co. 79/05/18. 1p.

--7905310426 Final deficiency rept: "Undersized Safety-Related Heating, Ventilating & Air Conditioning Damper Actuators."
Appropriate drawing changes will be issued for design changes by 790715. Fifteen actuators will require rework.
* Southern California Edison Co. 79/05/18. 3pp.

DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3

A. Application/construction stage documents & correspondence

7905010553 Comments on "Cultural Resource Mgt Repts for San Onofre-to-Mission-to-Encino 230 kV Transmission Lines & Mapping & Data Recovery Program for Site W-1527." Repts are suitable as baseline studies. Identifies questions for clarification.
MELLON, K. California, State of. 79/03/20. 2pp.

7905230589 Notification of 790426 meeting w/util in Bethesda, MD to discuss fuel design & analysis.
ROOD, H. Light Water Reactors Branch 2. 79/04/19. 3pp.

7905290411 Notification of 790504 meeting w/util in Bethesda, MD to discuss San Onofre geology.
ROOD, H. Light Water Reactors Branch 2. 79/05/02. 3pp.

7905210160 Forwards equipment seismic qualification summary info, in response to NRC 790111 request in preparation for site visit. Drawings available in Central Files only.
BASKIN, K. P. Southern California Edison Co. 79/05/16. 700pp.

I. Financial information

7905150400 Forwards "Annual Financial Rept 1978" for Southern CA Edison Co & San Diego Gas & Electric Co.
DRAKE, J. H. Southern California Edison Co. 79/05/08. 1p.

--7905150404 "Annual Financial Rept 1978."
* Southern California Edison Co. 79/02/15. 31pp.

--7905150406 "Annual Financial Rept 1978."
* San Diego Gas & Electric Co. 79/02/20. 43pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
GUATTROCHI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

M. Antitrust correspondence

7905310373 Submits request for addl info to complete antitrust review of OL application.
TOALSTON, A. L. Antitrust & Indemnity Group. 79/05/11. 3pp.

G. Inspection reports, IE Bulletins & correspondence

7905010292 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
ENGELKEN, R. H. Region 4, Dallas, Office of the Director. 79/03/23.

7905010020 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905040512 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905040619 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905070104 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905030296 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/17. 1p.

7905080371 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/21. 1p.

S. Reportable occurrences, LERs & related correspondence

7905150064 Forwards PNO-79-67L.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/06. 1p.

7905150170 Forwards PNO-79-67R.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/11. 1p.

7905040128 Forwards PNO-79-67S.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/12. 1p.

7905150145 Forwards PNO-79-67T.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/13. 1p.

7905030024 Forwards PNO-79-67U.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905020532 Forwards PNO-79-67AA.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/20. 1p.

7905010434 Forwards PNO-79-67AB.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/21. 1p.

7905010449 Forwards PNO-79-67AC & AD.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/23. 1p.

7905010462 Forwards PNO-79-67AE.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/24. 1p.

7905090041 Forwards PNO-79-67AF.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/25. 1p.

DOCKETED ITEMS

175

7905090057 Forwards PNO-79-67AG.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/04/26. 1p.

7905310012 Ack receipt of 790406 interim rept on Taylor Forge pipe defects pursuant to 10CFR50.55(e).
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/04/26. 1p.

7905090119 Forwards PNO-79-67AH.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/04/27. 1p.

7905070031 Forwards PNO-79-67AI, AJ & AK, per NRC 790401 ltr transmitting IE Bulletin 79-05.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/04/30. 1p.

7905070012 Forwards PNO-79-67AL, per NRC 790401 ltr transmitting IE Bulletin 79-05.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/05/01. 1p.

7905090277 Provides followup on 790108 final rept on reportable condition re fillet weld design. Revised drawings for remaining 78 pipe support assemblies will be issued for const use by 790904.
MOORE, J. B. Southern California Edison Co. 79/05/02. 1p.

7905310044 Forwards PNO-79-67AM.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/05/07. 1p.

7905300265 Forwards interim rept of Marine Review Committee re ECCB.
MONO, B. California, State of. 79/05/15. 1p.

--7905300270 "Interim Rept of Marine Review Committee to CA Coastal Commission, Part I: General Summary of Findings, Predictions & Recommendations Concerning Cooling Sys."
CONNELL, J. H., MECHALAG, B. J., MIHURSKY, J. A. California, State of.
79/05/12. 22pp.

--7905300277 "Interim Rept of Marine Review Committee to CA Coastal Commission, Part II: App of Technical Evidence in Support of General Summary."
CONNELL, J. H., MECHALAG, B. J., MIHURSKY, J. A. California, State of.
79/05/12. 197pp.

7905310423 Forwards final deficiency rept: "Undersized Safety-Related Heating, Ventilating & Air Conditioning Damper Actuators," identified in 790419 ltr.
MOORE, J. B. Southern California Edison Co. 79/05/18. 1p.

--7905310426 Final deficiency rept: "Undersized Safety-Related Heating, Ventilating & Air Conditioning Damper Actuators."
Appropriate drawing changes will be issued for design changes by 790715. Fifteen actuators will require rework.
* Southern California Edison Co. 79/05/18. 3pp.

DOCKET 50-363 FORKED RIVER NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905070466 Forwards "Design Info, Submittal 2, Structural Reorientation," w/current design features reflecting new licensing concerns of post-CP period.
FINFROCK, J. R. Jersey Central Power & Light Co. 79/03/05. 2pp.

--7905070470 "Design Info, Submittal 2, Structural Reorientation."
FINFROCK, J. R. Jersey Central Power & Light Co. 79/02/23. 54pp.

7905150287 Forwards 790307 ltr from S Rush, of Sea Alliance of Ocean County, NJ, for placement in docket file.
ABRAHAM, K. Region 1, Philadelphia, Office of the Director.
79/03/20. 1p.

--7905150293 Requests that planned salt water cooling tower not be built because of disastrous effects on natural beauty of area.
RUSH, S. Sea Alliance of Ocean County. 79/03/07. 1p.

--7905150298 Responds to 790307 ltr objecting to proposed cooling tower. Ltr forwarded to NRC headquarters.
ABRAHAM, K. Region 1, Philadelphia, Office of the Director.
79/03/20. 1p.

H. General correspondence

7905090144 Ack receipt of 790206 ltr requesting list of publications re nuclear-powered electric generating facilities & related issues. List of repts re cooling towers, transmission lines & socioeconomic impacts encl.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/04/04. 3pp.

7905040343 Ack receipt of encl 790202 ltr to President Carter expressing concern over proposed facility. Describes environ review process. Const is about 5% complete.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/04/13. 4pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATROCHCHI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

G. Inspection reports, IE Bulletins & correspondence

7905010112 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
ORIER, B. H. Region 1, Philadelphia, Office of the Director.
79/03/23. 1p.

7905240679 Forwards IE Insp Rept 50-363/79-03 on 790306-07. No noncompliance noted.
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/03/23. 2pp.

--7905240684 IE Insp Rept 50-363/79-03 on 790306-07. No noncompliance noted. Major areas inspected: containment concrete placement activities & associated quality records.
CERNE, A. C. Region 1, Philadelphia, Office of the Director.
MCQUAGHY, R. W. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/03/22. 5pp.

7905020045 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/11. 1p.

7905020393 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
ORIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/14. 1p.

7905040020 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/14. 1p.

7905040204 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
ORIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/14. 1p.

7905030065 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
ORIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/17. 1p.

7905010650 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/18. 1p.

DOCKETED ITEMS

176

DOCKET 50-364 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7905140357 Notifies of potential reportable inconsistency in calculated DNS ratios, as reported to util by Westinghouse.
HAIRSTON, W. G. Alabama Power Co. 79/03/30. 2pp.

7905240109 Notifies of 790531 expiration of Certificate of Compliance 5364 for Model NPI-67-0442 Renewal must be requested.
MACDONALD, C. E. Transportation Branch. 79/04/12. 1p.

7905020242 Forwards proposed amends to Tech Specs for Unit 1 incorporating radiological effluent Tech Specs into App A & proposed draft radiological effluent Tech Specs for Unit 2. Proposed draft App B Tech Specs encl.
CLAYTON, F. L. Alabama Power Co. 79/04/16. 190pp.

7905230414 Requests informal facility info re TMI incident be withheld from public disclosure unless util conducts proprietary review
CLAYTON, F. L. Alabama Power Co. 79/05/16. 2pp.

F. Security, medical, emergency & fire protection plans

7905070631 Forwards check to replace check sent 790323 w/safeguards security contingency plan.
CLAYTON, F. L. Alabama Power Co. 79/05/01. 2pp.

I. Financial information

7905150391 Forwards "Annual Financial Rept 1978," unaudited financial statements for quarter ending 790331 & cash flow projections for 1979.
BOWDEN, T. J. Alabama Power Co. 79/05/10. 7pp.

--7905150395 "Annual Financial Rept 1978."
* Alabama Power Co. 78/12/31. 47pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHINI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01.

Forwards Endorsement 23 to NELIA Policy NF-238.
March & McLanahan, M & M Nuclear Consultants, Inc. Div.

sent 24 to ANI Policy NF-238.
Nuclear Consultants, Inc. Div.

by NF-238.
Nuclear Consultants, Inc. Div.

to applicant's "Memo re 1978," encl.
79/03/28. 23pp.

Association of AL to regulatory
HJELMFIELT, D. C.

behalf of NRC.
3pp.

Regulatory Policies Act
status of
certificate of
Anti-Trust

7905240985 Responds to applicant's memo re impact of Public Util Regulatory Policies Act of 1978. Certificate of Svc & supporting documentation encl.
WHITLER, J. D. Justice, Dept. of. 79/03/29. 22pp.

G. Inspection reports, IE Bulletins & correspondence

7905010161 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/23. 2pp.

7905030290 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/26. 2pp.

7905100279 Requests extension of time until 790512 to respond to IE Bulletin 79-03, "Longitudinal Weld Defects in Pipe Spools Mfg by Youngstown Welding & Engineering Co."
CLAYTON, F. L. Alabama Power Co. 79/04/11. 1p.

7905150568 Confirms 790412 telcon to AK Hardin re IE Bulletin 79-02. Test program was initiated; enough failures found in anchor bolt installations to justify expansion of test scope. Further details will come in 14-day followup.
HAIRSTON, W. G. Alabama Power Co. 79/04/12. 1p.

7905040148 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp.

7905040298 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp.

7905040322 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.

7905010331 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/18. 2pp.

7905030137 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/17. 2pp.

7905020365 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/18. 2pp.

7905240443 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Methods specified by Item 1 have never been used. Therefore, specific concerns are not applicable to facility.
CLAYTON, F. L. Alabama Power Co. 79/04/24. 3pp.

7905300710 Forwards response to IE Bulletins 79-06A & 79-06, Revision 1. Training program for personnel w/operational duties is being developed; actions required by operating procedures re transients & accidents have been reviewed.
CLAYTON, F. L. Alabama Power Co. 79/04/24. 21pp.

7905300554 Responds to IE Bulletin 79-03, No SA-312 or other welded pipe mfg by Youngstown Welding & Engineering has been received on site or will be used in future.
CLAYTON, F. L. Alabama Power Co. 79/04/26. 1p.

DOCKET 50-366 EDWIN I. HATCH NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

7905150089 Responds to 790302 ltr reporting reasons for delays on implementing 10CFR73.35 requirements & describing compensatory measures provided to meet these requirements. Measures are acceptable.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/04/18. 2pp.

I. Financial information

7905080497 Forwards "Annual Financial Rept 1978."
VASQUEZ, R. D. Metropolitan Electric Authority of Georgia. 79/05/02. 1p.

DOCKETED ITEMS

177

--7905080508 "Annual Financial Rept 1978."
* Metropolitan Electric Authority of Georgia. 78/12/31. 24pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 29, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others. QUATTROCHMI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96. ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

7905080427 Forwards Amend 10 to Indemnity Agreement B-69. WHITMER, C.F. Georgia Power Co. 79/05/01. 3pp.

7905140493 Forwards Amend 11 to Indemnity Agreement B-69 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl. SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 6pp.

7905080430 Forwards Endorsement 49 to NELIA Policy NF-215. FIELDER, J. Marsh & McLennan, M & M Nuclear Consultants, Inc. Div. 79/05/03. 2pp.

P. Operating license stage documents & correspondence

7905090183 Forwards Amend 7 to License NPF-5 & notice of issuance & availability. IPPOLITO, T.A. Operating Reactors Branch 3. 79/04/03. 3pp.

--7905090186 Amend 7 to License NPF-5, changing Tech Spec deadline for initial startup rept. IPPOLITO, T.A. Operating Reactors Branch 3. 79/04/03. 5pp.

--7905090189 Notice of issuance & availability of Amend 7 to License NPF-5. IPPOLITO, T.A. Operating Reactors Branch 3. 79/04/03. 2pp.

7905070669 Responds to 790319 ltr questioning license amend fee requirement for 781221 application. Fees paid are justified. MILLER, W.O. License Fee Management Branch. 79/04/05. 1p.

7905170234 Forwards schedule for implementation & resolution of Mark I containment long-term program. Only vent header deflectors are necessary as major mod for conformance to long-term program acceptance criteria. WHITMER, C.F. Georgia Power Co. 79/05/14. 4pp.

7905290184 Forwards changes to Unit 2 Tech Specs re reactor protection sys instrumentation, isolation actuation instrumentation & bases for applicability spec per 790201 request. WHITMER, C.F. Georgia Power Co. 79/05/22. 9pp.

G. Inspection reports, IE Bulletins & correspondence

7905010200 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/23. 2pp.

7905020489 Forwards IE Insp Repts 50-321/79-09 & 50-366/79-11 on 790210-0302. No noncompliance noted. LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/23. 2pp.

--7905020497 IE Insp Repts 50-321/79-09 & 50-366/79-11 on 790210-0302. No noncompliance noted. Major areas inspected: Unit 1 plant operations, Unit 2 startup testing, Tech Specs compliance, reportable occurrences & Unit 2 transient test witnessing. ROGERS, R.F. Region 2, Atlanta, Office of the Director. DANCE, H.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/23. 4pp.

7905030312 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/26. 2pp.

7905010107 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/28. 2pp.

7905010360 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/30. 2pp.

7905250098 Requests page 6 of IE Insp Repts 50-321/79-06 & 50-366/79-07 be replaced w/encl corrected page. MILLER, J.H. Georgia Power Co. 79/04/04. 2pp.

--7905250105 Forwards IE Insp Repts 50-321/79-06 & 50-366/79-07 on 790214-16. No noncompliance noted. LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/21. 2pp.

--7905250110 IE Insp Repts 50-321/79-06 & 50-366/79-07 on 790214-16. No noncompliance noted. Major areas inspected: plant operations, followup of unresolved items, LERs & test witnessing. DANCE, H.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. HINCKLEY, D.G. Region 2, Atlanta, Office of the Director. 79/03/21. 8pp.

7905040216 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp.

7905040304 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.

7905040413 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.

7905100244 Responds to IE Bulletin 79-03. No evidence of Youngstown Welding & Engineering seam welded ASME SA-312 Type 304 stainless steel piping is being used in safety-related sys. ASME SA-358 Type 304 spool is used. STAFFA, R.W. Georgia Power Co. 79/04/16. 1p.

7905030165 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/17. 2pp.

7905020467 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/18. 2pp.

7905290029 Responds to IE Bulletin 79-08. Addresses events relevant to BWRs identified during TMI incident. Response to Item 11 will be forwarded in 30 days. WIDNER, W.A. Georgia Power Co. 79/04/25. 13pp.

7905030039 Responds to IE Bulletin 79-04. Review of design records indicates there are no 3/4 or 6-inch diameter Velan swing check valves used at facility. STAFFA, R.W. Georgia Power Co. 79/05/02. 1p.

7905290035 Forwards revised responses to IE Bulletin 79-08, "Events Relevant to BWRs Identified During TMI Incident." Replaces previous 790425 submittal (mentioned as 790415 in present ltr). Includes response to Item 11. WIDNER, W.A. Georgia Power Co. 79/05/09. 16pp.

R. Periodic operating reports & related correspondence

7905150344 Forwards monthly operating rept for Apr 1979. HANRY, M. Georgia Power Co. 79/05/09. 1p.

--7905150348 Monthly operating rept for Apr 1979. STANCIL, R. Georgia Power Co. 79/05/01. 11pp.

S. Reportable occurrences, LERs & related correspondence

7905140316 Notifies that LERs 50-366/1979-27 & 50-321/1979-16 have been voided. They were later determined to be not reportable. HANRY, M. Georgia Power Co. 79/03/13. 1p.

7905010469 Forwards LERs 79-025/01X-1 & 79-025/01T-0. HANRY, M. Georgia Power Co. 79/04/19. 1p.

DOCKETED ITEMS

--7905010470 LER 79-025/01X-1 on 790223: torus insp revealed several upper clevis pins of torus vent header support columns displaced. Caused by vibration of vent header causing roll pins to be sheared. Design changes issued.
GREENE, T.V. Georgia Power Co. 79/04/17. 2pp.

7905070639 Forwards LER 79-031/03L-0.
MANRY, M. Georgia Power Co. 79/05/01. 2pp.

--7905070646 LER 79-031/03L-0 on 781129: quick start test failed. Sys declared inoperable. Quick start surveillance procedure rewritten & personnel re-instructed.
BAXLEY, S.X. Georgia Power Co. 79/05/01. 2pp.

7905150465 Forwards LER 79-030/03L-0.
MANRY, M. Georgia Power Co. 79/05/04. 1p.

--7905150467 LER 79-030/03L-0 on 790418: during surveillance on water level instrument 2B21-N024A, limit switch failed to actuate, tripping recirculation pump A on low level. Caused by fouled switch contacts. Contacts cleaned.
NIX, R.T. Georgia Power Co. 79/05/04. 1p.

7905300683 Forwards LER 79-033/03L-0.
MANRY, M. Georgia Power Co. 79/05/17. 1p.

--7905300688 LER 79-033/03L-0 on 790508: air operators on 2B21-F018A & C were improperly installed. Caused by insufficient installation info. Maint procedures revised to assure proper installation.
GREENE, T.V. Georgia Power Co. 79/05/17. 2pp.

DOCKET 50-367 BAILLY GENERATING STATION

A. Application/construction stage documents & correspondence

7905020400 Forwards NUREG-0531, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability. W/o encl.
VASSALLO, D.B. Assistant Director for Light Water Reactors. 79/03/23. 2pp.

7905040316 Summary of 790321 meeting of Mark II owners group in San Jose, CA re intermediate plant program tasks.
ANDERSON, C.J. Containment Systems Branch. 79/04/13. 150pp.

G. Adjudicatory correspondence

7905240223 Requests that NRC grant hearing on Northern IN Public Svc 790207 petition for extension of CP Certificate of Svc encl.
ANDREWS, W.; DLSZANSKI, S.M. Affiliation Unknown. 79/03/27. 3pp.

G. Inspection reports, IE Bulletins & correspondence

7905010258 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/03/23. 1p.

7905040041 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/03/26. 1p.

7905030036 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/11. 1p.

7905010593 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/14. 1p.

7905040398 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/14. 1p.

7905040568 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/14. 1p.

7905070164 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/14. 1p.

7905010429 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/16. 1p.

7905030232 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/17. 1p.

7905080502 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/21. 1p.

7905240907 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/05/02. 1p.

R. Periodic operating reports & related correspondence

7905010534 Forwards well charts for 790404-790411, well levels, Bailly wells w/o recorders, pond levels, pneumatic pressure transducers, & water meter readings for 790411.
BOHN, R.J. Northern Indiana Public Service Co. 79/04/23. 33pp.

7905140308 Forwards well charts for 790411-18, well levels for 790412, 13, 17 & 18, Bailly wells w/o recorders for 790418, pond levels for 790418, pneumatic pressure transducers for 790418 & water meter readings for 790418.
BOHN, R.J. Northern Indiana Public Service Co. 79/04/27. 17pp.

7905110306 Forwards 790418-25 well charts, 790419-25 well levels, 790425 Bailly wells w/o recorders, 790425 pond levels, 790425 pneumatic pressure transducers, 790425 water meter readings & 790201-0316 rainfall at Flint Lake pump station.
BOHN, R.J. Northern Indiana Public Service Co. 79/05/04. 19pp.

7905220207 Forwards well charts for 790425-790502, Bailly wells w/o recorders, pond levels, pneumatic pressure transducers, water meter reading & USGS wells, all for 790502.
BOHN, R.J. Northern Indiana Public Service Co. 79/05/11. 16pp.

7905210277 Forwards "Winter 1979 Quarterly Rept" on ecological monitoring program.
SHORB, E.M. Northern Indiana Public Service Co. 79/05/15. 1p.

--7905210280 "Winter 1979 Quarterly Rept" on ecological monitoring program for Jan-Mar 1979.
* Northern Indiana Public Service Co. 79/04/30. 126pp.

7905300329 Forwards well charts for 790502-09, Bailly wells w/o recorders, pond levels, pneumatic pressure transducers & water meter readings for 790509.
BOHN, R.J. Northern Indiana Public Service Co. 79/05/18. 31pp.

DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

H. General correspondence

7905240955 Responds to 790412 ltr to JM Hendrie re nuclear power plant near Russellville, AR. Outlines steps for license review. Forwards "Transportation of Nuclear Fuel & Waste" & "Disposal of Radioactive Waste." W/o encl.
DEYOUNG, R.C. Division of Site Safety & Environmental Analysis. 79/05/07. 2pp.

--7905240965 Expresses concern re nuclear plants at Russellville, AR. Requests public investigation re safety of facility. Forwards policy statement of Arkansas for Safe Energy.
BERKY, J.A. Affiliation Unknown. 79/04/12. 2pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHCHI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

DOCKETED ITEMS

179

7905140489 Forwards Amend 8 to Indemnity Agreement B-65 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 6pp.

7905190167 Forwards executed Amend 8 to Indemnity Agreement B-65.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/05/10. 3pp.

P. Operating license stage documents & correspondence

7905070491 Responds to 771205 request. Forwards addl info re fracture toughness & potential for lamellar tearing of steam generator & reactor coolant pump support matl. Oversized encl available in Central Files only.
WILLIAMS, D. H. Arkansas Power & Light Co. 78/12/19. 8pp.

7905230840 Requests verification to assure adequacy of onsite distribution of power from offsite circuits. Also requests review of electric power sys to determine if potential exists for violation of General Design Criteria 17.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/05/02. 8pp.

7905250210 Summary of 790425 meeting w/C-E re natural circulation capability for C-E plants.
THADANI, A. C. Reactor Systems Branch. 79/05/02. 43pp.

7905250049 Forwards Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively, safety evaluation & notice of issuance & availability.
STOLZ, J. F. Light Water Reactors Branch 1. REID, R. W. Operating Reactors Branch 4. 79/05/03. 2pp.

--7905250055 Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively, modifying App A & B Tech Specs re mgt organization.
REID, R. W. Operating Reactors Branch 4. 79/05/03. 14pp.

--7905250058 Safety evaluation supporting Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively.
* Operating Reactors Branch 4. 79/05/03. 2pp.

--7905250065 Notice of issuance & availability of Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively.
REID, R. W. Operating Reactors Branch 4. 79/05/03. 2pp.

7905230087 Forwards summary of 790301 meeting w/C-E re natural circulation conditions in C-E operating reactors.
THADANI, A. C. Reactor Systems Branch. 79/05/09. 1p.

7905170265 Forwards proposed radiological Tech Specs changes & Class III amend fee.
CAVANAUGH, W. Arkansas Power & Light Co. 79/05/10. 2pp.

--7905170267 Proposed radiological Tech Spec changes covering engineered safety feature response time, physics tests liquid & gaseous radwaste treatment sys.
* Arkansas Power & Light Co. 79/05/10. 56pp.

7905300002 Forwards amend to 790417 ltr proposing change to Tech Spec 3.7.1. Seeks to include addl fire barriers in request for temporary relief. Plant can be operated w/o fire dampers in ventilation ducts.
CAVANAUGH, W. Arkansas Power & Light Co. 79/05/18. 4pp.

7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969. Review & reanalysis included all work through Dec 1970.
PORTER, F. L. EDS Nuclear, Inc. 79/05/21. 9pp.

--7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program. GE has no record of reanalysis for Cooper piping sys.
STEPHENS, P. M. General Electric Co., Nuclear Energy Products Div. 79/01/24. 18pp.

G. Inspection reports, IE Bulletins & correspondence

7905010385 Forwards IE Insp Repts 50-313/79-02 & 50-368/79-02 on 790115-0211 & notice of violation.
MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/03/01. 2pp.

--7905010391 Notice of violation from insp on 790115-0211.
* Region 4, Dallas, Office of the Director. 79/03/01. 1p.

--7905010395 IE Insp Repts 50-313/79-02 & 50-368/79-02 on 790115-0211. Noncompliance noted: failure to prepare weekly rept of overdue maint.
WESTERMAN, T. F. Region 4, Dallas, Reactor Operations Nuclear Support Branch. BOYTER, N. C. Region 4, Dallas, Office of the Director. MADSEN, G. L. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/03/01. 15pp.

7905150079 Forwards IE Circular 79-04, "Loose Locking Nut on Limitorque Valve Operators."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/16. 1p.

7905310387 Responds to IE Bulletin 78-12, "Atypical Weld Matl in Reactor Pressure Vessels." Records search initiated & final rept expected from GE by 790813.
RUETER, D. A. Arkansas Power & Light Co. 79/03/16. 1p.

7905010448 Forwards IE Bulletin 78-12B, "Atypical Weld Matl in Reactor Pressure Vessel Welds."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/19. 1p.

7905020441 Forwards IE Circular 79-05, "Moisture Leakage in Stranded Wire Conductors."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/20. 1p.

7905020277 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/23. 1p.

7905020419 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/26. 1p.

7905020436 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as the Source of Breathing Air."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/28. 1p.

7905140152 Forwards IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp." Licensee action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/30. 1p.

7905150045 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/30. 1p.

7905020325 Responds to 790228 ltr & forwards procedures re obtaining emergency relief from Tech Specs.
MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/04/05. 2pp.

--7905020343 Clarifies response to 781214 notice of violation. Quorum meetings will be held to review items in Safety Review Committee's purview. Voices concern re ability to obtain emergency Tech Spec mods in absence of quorum.
RUETER, D. A. Arkansas Power & Light Co. 79/02/28. 2pp.

7905140088 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/11. 1p.

7905040606 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/14. 1p.

7905070043 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/14. 1p.

7905090096 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at TMI."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/16. 1p.

DOCKETED ITEMS

- 7905030263 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/17. 1p
- 7905080348 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl." Applicable ACRB recommendations & list of IE Bulletins issued in last 12 months encl
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/21 1p
- 7905290494 Responds to IE Bulletin 79-07 re seismic stress analysis Computer codes specified in Item 1 not used in analysis of safety-related piping
TRIMBLE, D C Arkansas Power & Light Co 79/04/24 4pp
- 7905110007 Forwards page 12a, omitted from original responses to IE Bulletin 79-06B
TRIMBLE, D C Arkansas Power & Light Co 79/04/25 1p
- 7905110010 Forwards responses to IE Bulletin 79-06B re preliminary chronology of TMI-2 To further increase margin of safety, design change is being evaluated for items in Category III & IV
TRIMBLE, D C Arkansas Power & Light Co 79/04/24 19pp
- R Periodic operating reports & related correspondence
- 7905070490 Forwards "Semiannual Environ Monitoring Rept" for Jul-Dec 1978
TRIMBLE, D C Arkansas Power & Light Co 79/04/30 1p
- 7905070494 "Semiannual Environ Monitoring Rept" for Jul-Dec 1978
Arkansas Power & Light Co 79/04/30 550pp
- 7905170227 Forwards monthly operating rept for Apr 1979, corrected copy of monthly operating rept for Mar 1979 &
LER 79-N/A/99X-O
TRIMBLE, D C Arkansas Power & Light Co 79/05/10 2pp
- 7905170232 Monthly operating rept for Apr 1979
SHIVELY, C N Arkansas Power & Light Co 79/05/09 5pp
- 7905170239 LER 79-N/A/99X-O on 790315 diesel generator 1 failed to achieve rated voltage & speed Caused by blown fuse in starting circuit for one of two air-starting solenoids
LER submitted per Tech Spec 4 B 1 1 3
SHIVELY, C N Arkansas Power & Light Co 79/05/01 1p
- S Reportable occurrences, LERs & related correspondence
- 7905040106 Forwards PNO-79-67B
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/12 1p
- 'ence Memo 14 unusual sequence of events
1d voltage resulting from onsite
connected, causing second to
tribution sys
tors 79/04/12 6pp
- Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/13 1p
- 7905010329 Forwards PNO-79-67U, V & W
MADSEN, O L Region 4, Dallas, Office of the Director. 79/04/16 1p
- 7905010338 Forwards PNO-79-67X & Y
MADSEN, O L Region 4, Dallas, Office of the Director 79/04/18. 1p
- 7905010354 Forwards PNO-79-67Z
MADSEN, O L Region 4, Dallas, Office of the Director 79/04/19 1p
- 7905010367 Forwards PNO-79-67AA, AB, AC & AD.
MADSEN, O L Region 4, Dallas, Office of the Director. 79/04/24 1p
- 7905030008 Forwards PNO-79-67AE
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/25 1p
- 7905130096 Forwards PNO-79-67AF, AG, AH, AI & AJ, re nuclear incident at TMI
MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/30 1p
- 7905140172 Forwards LERs 79-026/03L-O, 79-027/03L-O & 79-028/03L-O
TRIMBLE, D C Arkansas Power & Light Co 79/05/01 2pp
- 7905140176 LER 79-026/03L-O on 790323 during review of heating, ventilation & air conditioning installation, 32 fire dampers discovered not installed as required Caused by installation GA Fire watch established Dampers to be installed
SHIVELY, C N Arkansas Power & Light Co 79/05/01. 1p
- 7905140182 LER 79-027/03L-O on 790330 high pressure safety injection header relief valve 2PBV-5112 body leaked Cause not reported Pressure setting verified, cap & gag screw gaskets replaced & ECCS subsystem returned to svc
SHIVELY, C N Arkansas Power & Light Co 79/05/01 1p
- 7905140183 LER 79-028/03L-O on 790403 emergency feedwater pump 2P78 removed from svc Caused by packing leak Pump shaft repacked & returned to svc
SHIVELY, C N Arkansas Power & Light Co 79/05/01. 1p
- 7905240451 Forwards PNO-79-67AK & AL
MADSEN, O L Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/05/02 1p
- 7905150572 Forwards LERs 79-029/03L-O, 79-030/03L-O & 79-026/03L-1
TRIMBLE, D C Arkansas Power & Light Co 79/05/09. 1p
- 7905150580 LER 79-029/03L-O on 790415 during Mode 3 operation, condensate storage tank A dropped below Tech Spec min of 80%. Caused by inability of makeup plants to produce condensate to meet high demand during blowdown testing
SHIVELY, C N Arkansas Power & Light Co. 79/05/09 1p
- 7905150587 LER 79-030/03L-O on 790421: while investigating ground problem in battery bank 2D02, inverter 2-1/22 switched to alternate source Caused by dc supply opening while attempting to locate 2D02 ground, Supply reestablished
SHIVELY, C N Arkansas Power & Light Co 79/05/09. 1p
- 7905150601 LER 79-026/03L-1 on 781216: 2CV-1039-2 failed to operate from control room, rendering pump 2 P7A feed to steam generator 2E248 inoperable Caused by solid state relay actuating 2 CV-1039-2 & sealing in closed command
SHIVELY, C N Arkansas Power & Light Co 79/01/15 1p
- 7905220398 Forwards LERs 79-031/03L-O & 79-032/03L-O
TRIMBLE, D C. Arkansas Power & Light Co. 79/05/17 1p
- 7905220400 LER 79-031/03L-O on 790418: leak found on charging pump A suction pipe at 2-inch coupling to 2PBV4834, Caused by vibration Leak located in heat affected zone of 2-inch weld-onlet Pipe section replaced
SHIVELY, C N Arkansas Power & Light Co 79/05/17 1p.
- 7905220405 LER 79-032/03L-O on 790419: excessive vibration found in B emergency diesel engine Caused by failure of forward half of upper main bearings due to poor lubrication Main bearing caps relocated by redwelling
SHIVELY, C N Arkansas Power & Light Co 79/05/17 1p
- 7905300509 Forwards LER 79-033/01T-O.
TRIMBLE, D C Arkansas Power & Light Co 79/05/25 1p.
- 7905300517 LER 79-033/01T-O on 790514: unisolatable leak discovered on reactor coolant pump 2P32A seal cavity pressure sensing line for 2PT-6006, Cause undetermined. Affected portion of schedule 80 pipe replaced w/160 pipe.
SHIVELY, C N Arkansas Power & Light Co 79/05/25 1p
- DOCKET 50-369 WILLIAM B. MCQUIRE NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 7905070481 Informs of delay in submitting addl info re status of outstanding review matters & evaluation of conformance of plant design w/NRC requirements
PARKER, W D Duke Power Co. 79/04/30. 1p.

DOCKETED ITEMS

181

Q. Adjudicatory correspondence

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients
SCINTO, J F Hearings Division 79/04/02 31pp.

--7905010156 Board notification staff assessment re nonsafety-grade equipment to mitigate transients
VASSALLO, D B Assistant Director for Light Water Reactors
79/03/29, 2pp

--7905010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients More info is required
TEDESCO, R L Assistant Director for Reactor Safety 79/03/16 3pp.

7905290576 Denies motion to reopen safety phases of licensing procedures as sought by Carolina Environ Study Group in 790128 petition & opposed by NRC & Duke Power Co 790323 answers.
LAZO, R M Atomic Safety and Licensing Board Panel 79/04/10 14pp

7905100186 Orders issuance of OL to applicant, contingent upon procedural & factual conditions Orders stay of present initial decision until further order after issuance of suppl to GER re any unresolved generic safety issues
LUEBKE, E A, HAND, C H, LAZO, R M Atomic Safety and Licensing Board Panel, 79/04/18 122pp.

J Insurance & indemnity information

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/03/01 1p

7905140538 Forwards Amend 2 to Indemnity Agreement B-83 per 10CFR140 changes re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group 79/03/01, 6pp

Q Inspection reports, IE Bulletins & correspondence

7905230770 Informs that response to IE Bulletins 78-12 & 78-12A is being prepared by Westinghouse info being gathered from C-E & Rotterdam reactor vessel manufacturers Util's response will be provided by 791001.
PARKER, W O Duke Power Co 79/03/16, 1p

7905010177 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/03/23, 2pp

7905030307 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/26 2pp

7905010098 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air."
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/28, 2pp

7905010350 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/30, 2pp

7905020408 Ack receipt of IE Insp Rept 50-369/79-13 on 790205-08. No proprietary info
PARKER, W. D. Duke Power Co. 79/04/09, 1p.

--7905020412 Forwards IE Insp Rept 50-369/79-13 on 790205-08 No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/14 2pp

--7905020423 IE Insp Rept 50-369/79-13 on 790205-08. No noncompliance noted. Major areas inspected verification of preoperational test procedures & follow-up of previous enforcement matters
COTTL, W. T, DYER, J. A Region 2, Atlanta, Office of the Director
CANTRELL, F. B. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/13 7pp

7905020285 Ack receipt of 790411 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-369/79-11 Does not consider info proprietary
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/11 2pp

--7905020301 Responds to NRC 790308 ltr re violation noted in IE Insp Rept 50-369/79-11 Corrective actions burnt cable was result of molten metal falling on cable after welding
PARKER, W O Duke Power Co 79/04/11 1p

--7905020326 Forwards IE Insp Rept 50-369/79-11 on 790206-09 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/08 2pp

--7905020339 Notice of violation from insp on 790206-09
* Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/07 1p.

--7905020352 IE Insp Rept 50-369/79-11 on 790206-09 Noncompliance noted safety-related cable had 1-inch diameter burn hole
HARDWICK, T J, BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/07 6pp

7905290700 Ack receipt of IE Insp Rept 50-369/79-17 on 790226-28 No proprietary info
PARKER, W O. Duke Power Co 79/04/13 1p

--7905290707 Forwards IE Insp Rept 50-369/79-17 on 790226-28 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/21 2pp

--7905290717 IE Insp Rept 50-369/79-17 on 790226-28 No noncompliance noted Major areas inspected hot functional testing activities & followup on unresolved items
CANTRELL, F B, COTTL, W T Region 2, Atlanta, Office of the Director 79/03/20 4pp

7905040176 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14, 1p

7905040381 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905010335 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/16 2pp

7905030160 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp

7905020460 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P 79/04/18 2p

7905240426 Ack
Agrees to
PARKER, W O

7905250173 Nc
790420 ltr,
50-369/79-1
LEWIS, R C.
Branch. 7'

S Reportable

7905110203 B
design def
SCINTO, J.

7905150254 F
PARKER, W O

DOCKETED ITEMS

--7905150262 Deficiency rept BD-369/370-79-01 on 790412 during test of pressurizer power operated relief valves, one valve stuck in partially open position. Caused by valve plug binding in valve bonnet recess area. Configuration will be revised.
* Duke Power Co 79/04/12 2pp

DOCKET 50-370 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7905070481 Informs of delay in submitting addl info re status of outstanding review matters & evaluation of conformance of plant design w/NRC requirements
PARKER, W O Duke Power Co 79/04/30 1p

Q Adjudicatory correspondence

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients
SCINTO, J F Hearings Division 79/04/02 31pp

--7905010156 Board notification staff assessment re nonsafety-grade equipment to mitigate transients
VASSALLO, D B Assistant Director for Light Water Reactors
79/03/29 2pp

--7905010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients. More info is required
TEDESCO, R L Assistant Director for Reactor Safety 79/03/16 3pp

7905290576 Denies motion to reopen safety phases of licensing procedures as sought by Carolina Environ Study Group in 790128 petition & opposed by NRC & Duke Power Co 790323 answers
LAZO, R M Atomic Safety and Licensing Board Panel 79/04/10 14pp

7905100186 Orders issuance of OL to applicant, contingent upon procedural & factual conditions. Orders stay of present initial decision until further order after issuance of supp'l to SER re any unresolved generic safety issues
LUEBKE, E A ; HAND, C W ; LAZO, R M Atomic Safety and Licensing Board Panel 79/04/18 122pp

J Insurance & indemnity information

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905140538 Forwards Amend 2 to Indemnity Agreement B-83 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp.

Q Inspection reports, IE Bulletins & correspondence

response to IE Bulletin 78-12 & 78-12A is
house info being gathered from C-E
& manufacturers Util's response
1001,
r Co 79/03/16 1p

* Notice 79-06, "Stress Analysis of
, Atlanta, Office of the Director,

Notice 79-07, "Rupture of Radwaste Tanks "
, Atlanta, Office of the Director

etin 79-06B, "Review of Operational Errors &
led During TMI Incident "
, Atlanta, Office of the Director

etin 79-08, "Events Relevant to Boiling
tified During TMI Incident "
, Atlanta, Office of the Director,

7905010335 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support
Struts "
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/16 2pp

7905030160 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2
Circuit Breaker in Safety-Related Sys " Licensee action
required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/17 2pp

7905020429 Forwards IE Bulletin 79-06A, Revision 1, "Review of
Operational Errors & Sys Misalignments Identified During TMI
Incident "
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/18 2pp

S Reportable occurrences, LERs & related correspondence

7905110203 Board notification Seabrook refueling water storage tank
design deficiency.
SCINTO, J Hearings Division 79/03/29 30pp.

7905150254 Forwards Significant Deficiency Rept BD-369-370/79-01
PARKER, W O Duke Power Co 79/04/13 1p.

--7905150262 Deficiency rept BD-369/370-79-01 on 790412 during test of pressurizer power operated relief valves, one valve stuck in partially open position. Caused by valve plug binding in valve bonnet recess area. Configuration will be revised.
* Duke Power Co 79/04/12 2pp

DOCKET 50-373 LABALLE COUNTY STATION, UNIT 1

A Application/construction stage documents & correspondence

7905040316 Summary of 790321 meeting of Mark II owners group in Ban
Jose, CA re intermediate plant program tasks
ANDERSON, C J Containment Systems Branch 79/04/13 150pp

7905040260 Requests addl info re soil-structure interaction effect
based on elastic half-space model & finite element model
PARR, D D Light Water Reactors Branch 3, 79/04/16 4pp

7905100258 Summary of 790410 meeting w/Cincinnati Gas & Electric Co,
Long Island Lighting Co & Commonwealth Edison Co re
vibratory loads & equipment qualification. Presentation matl
encl
PELTIER, I A Light Water Reactors Branch 1 79/04/19 15pp

7905230358 Notification of 790515-17 meeting w/Cincinnati Gas &
Electric Co, Long Island Lighting Co, Commonwealth Edison Co
& GE in San Jose, CA to audit NBBS equipment for seismic &
other dynamic qualification
PELTIER, I A Light Water Reactors Branch 1, 79/04/23 3pp

7905070393 Summarizes reevaluation of equipment qualification for
seismic & hydrodynamic loads, in response to RS Boyd to B Lee
790223 ltr Supporting info encl
DELOERGE, L O Commonwealth Edison Co, 79/04/25 64pp

7905040482 Notifies of intention to develop safety analysis using
existing computer codes. Requests addl info.
BOLBRIG, C W Commonwealth Edison Co, 79/04/26 1p

7905080396 Clarifies status of acquisition of transmission line rights-
of-way. Necessary property has been acquired for first of two
pys. Final offers have been made to acquire remaining
parcels.
DELOERGE, L O Commonwealth Edison Co 79/05/02 1p

7905290021 Notification of 790511 meeting w/util in Bethesda, MD to
discuss open items on containment sys
BOURNIA, A Light Water Reactors Branch 3, 79/05/03 2pp

7905140312 Forwards IL EPA request to be removed from distribution list
for FEAR & amends, effective as of Amend 46
DELOERGE, L O Commonwealth Edison Co, 79/05/07 2pp.

7905300020 Application to use ASME Code Case N-240 to exempt certain
piping from hydrostatic testing
DELOERGE, L O Commonwealth Edison Co, 79/05/21 3pp

DOCKETED ITEMS

183

7905310361 Informs NRC of erosion on portions of makeup & blowdown water pipeline corridor Plan submitted by Soil Conservation Svc will be implemented.
REED, C. Commonwealth Edison Co. 79/05/23 2pp.

F. Security, Medical, emergency & fire protection plans

7905010523 Forwards Revision 4 to physical security plan Plan withheld (ref 10CFR2.790)
REED, C. Commonwealth Edison Co 79/04/17 1p

J. Insurance & indemnity information

7905100163 Endorsement 99 to MAELU Policy MF-22
OCERAB, T. Nuclear Energy Liability Insurance Association. 79/03/27 1p.

7905070497 Confirms increased liability limit to \$124,000,000 for policies MF-22, 26, 29, 30, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
QUATTROCIAMI, J. American Nuclear Insurers 79/05/01. 1p

7905070582 Confirms increase in liability limit to \$34,000,000 for policies MF-22, 26, 29, 30, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

7905140546 Forwards Amend 1 to Indemnity Agreement B-84 per 10CFR140 changes re increase in liability insurance from \$140 million to \$160 million; effective 790501 Supporting documentation encl.
BALTZMAN, J. Antitrust & Indemnity Group 79/05/01 6pp

K. Utility Final Safety Analysis Report (FSAR) & amends

7905020312 Forwards Amend 45 to FSAR which responds to 34 second round questions.
REED, C. Commonwealth Edison Co 79/04/20. 1p.

--7905020320 Amend 45 to FSAR Oversized charts available in Central Files.
Commonwealth Edison Co. 79/04/30. 260pp.

7905110155 Forwards affidavit for distribution of Amend 45 to FSAR.
DELOEDGE, L. O. Commonwealth Edison Co 79/05/04. 2pp.

G. Inspection reports, IE Bulletins & correspondence

7905030054 Forwards IE Insp Repts 50-373/79-11 & 50-374/79-08 on 790221-23 & notice of violation.
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/15. 2pp.

--7905030061 Notice of violation from insp on 790221-23
Region 3, Chicago, Office of the Director. 79/03/14 2pp.

--7905030074 IE Insp Repts 50-373/79-11 & 50-374/79-08 on 790221-23. Noncompliance noted; failure to maintain min bend radius for cables & failure to take measures to assure that max cable gull tensions were not exceeded.
BARRETT, P.A., NEIBLER, J.M., KNOP, R.C. Region 3, Chicago, Office of the Director. 79/03/14. 8pp.

7905070020 Forwards IE Insp Rept 50-373/79-06 on 790130-31, 0201 & 07-08 & notice of violation.
HEIGHMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/03/19. 2pp

--7905070023 Notice of violation from insp on 790130, 0201 & 07-08
Region 3, Chicago, Office of the Director. 79/03/15. 3pp.

--7905070027 IE Insp Rept 50-373/79-06 on 790130-31, 0201 & 07-08. Noncompliance noted; failure to comply w/10CFR50 App B, Criterion 5 & 14.
MAURA, F.A., DETENWEIER, R.W. Region 3, Chicago, Office of the Director. STREETER, J.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/03/15. 9pp

7905020421 Forwards response to IE Bulletin 78-12 & 78-12A, "Atypical Weld Metl in Reactor Pressure Vessel Welds."
REED, C. Commonwealth Edison Co. 79/03/22. 10pp.

7905010234 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
KEPPLER, J.O. Region 3, Chicago, Office of the Director. 79/03/23. 1p.

7905030370 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
KEPPLER, J.O. Region 3, Chicago, Office of the Director 79/03/26 1p

7905030013 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J.O. Region 3, Chicago, Office of the Director 79/04/11 1p.

7905240711 Forwards IE Insp Rept 50-373/79-14 on 790402-03 No noncompliance noted
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/04/11 2pp

--7905240716 IE Insp Rept 50-373/79-14 on 790402-03 No noncompliance noted. Major areas inspected preservice insp work activities & nondestructive examination data repts.
WARD, K.D., DANIELSON, D.M. Region 3, Chicago, Office of the Director 79/04/10. 6pp.

7905010569 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J.O. Region 3, Chicago, Office of the Director 79/04/14 1p.

7905040334 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J.O. Region 3, Chicago, Office of the Director 79/04/14 1p.

7905040329 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
KEPPLER, J.O. Region 3, Chicago, Office of the Director 79/04/14 1p

7905010380 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Brackets."
KEPPLER, J.O. Region 3, Chicago, Office of the Director 79/04/16 1p

7905030206 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
KEPPLER, J.O. Region 3, Chicago, Office of the Director 79/04/17 1p

7905040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"
KEPPLER, J.O. Region 3, Chicago, Office of the Director. 79/04/21 1p.

--7905040158 IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl" Supporting documentation encl.
Region 3, Chicago, Office of the Director 79/04/21. 12pp

--7905040170 ACRS recommendations re 790328 incident at TMI. Suggests high priority be placed on development of safety research on behavior of LWRs during anomalous transients
ACRS - Advisory Committee on Reactor Safeguards 79/04/17. 2pp.

--7905040201 Forwards ACRS recommendations re TMI incident; presented on 790417.
FRALEY, R.F. ACRS - Advisory Committee on Reactor Safeguards. 79/04/18. 1p.

--7905040221 In response to NRC 790418 ltr, states all 790417 ACRS recommendations apply to all PWRs, but were not intended to require immediate changes. Plant mods should be made after study of effects on overall safety. TMI excluded.
CARSON, M.X. ACRS - Advisory Committee on Reactor Safeguards. 79/04/20. 2pp.

7905240633 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping. Reanalysis indicates method of intramodal combination has little effect on pipe stresses & equipment support loads.
REED, C. Commonwealth Edison Co. 79/04/24. 4pp.

7905140488 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase."
KEPPLER, J.O. Region 3, Chicago, Office of the Director 79/05/02. 1p.

S. Reportable occurrences, LERs & related correspondence

7905300435 Notifies that all super strut Type 1202 hangers which were galvanized prior to welding are subj to same defect reported in 790419 ltr. Complete insp will be performed on Type 1202 hangers
DELOEDGE, L.O. Commonwealth Edison Co. 79/05/21. 5pp.

DOCKETED ITEMS

DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905040316 Summary of 790321 meeting of Mark II owners group in San Jose, CA re intermediate plant program tasks
ANDERSON, C J Containment Systems Branch 79/04/13 150pp.

7905040260 Requests addl info re soil-structure interaction effect based on elastic half-space model & finite element model
PARR, D D Light Water Reactors Branch 3 79/04/16 4pp

7905100258 Summary of 790410 meeting w/Cincinnati Gas & Electric Co, Long Island Lighting Co & Commonwealth Edison Co re vibratory loads & equipment qualification Presentation matl encl
PELTIER, I A Light Water Reactors Branch 1 79/04/19 15pp

7905230358 Notification of 790513-17 meeting w/Cincinnati Gas & Electric Co, Long Island Lighting Co, Commonwealth Edison Co & GE in San Jose, CA to audit NGSB equipment for seismic & other dynamic qualification
PELTIER, I A Light Water Reactors Branch 1 79/04/23 3pp.

7905070393 Summarizes reevaluation of equipment qualification for seismic & hydrodynamic loads, in response to RS Bgnd to B Lee 790223 ltr Supporting info encl
DELGEORGE, L O Commonwealth Edison Co 79/04/25 64pp

7905040482 Notifies of intention to develop safety analysis using existing computer codes Requests addl info
BOLBRIG, C W Commonwealth Edison Co 79/04/26 1p

7905080396 Clarifies status of acquisition of transmission line rights-of-way. Necessary property has been acquired for first of two sys. Final offers have been made to acquire remaining parcels
DELGEORGE, L O Commonwealth Edison Co 79/05/02 1p.

7905290021 Notification of 790511 meeting w/util in Bethesda, MD to discuss open items on containment sys
BOURNIA, A Light Water Reactors Branch 3 79/05/03 2pp

7905140312 Forwards IL EPA request to be removed from distribution list for FSAR & amends, effective as of Amend 45
DELGEORGE, L O Commonwealth Edison Co 79/05/07 2pp.

7905300020 Application to use ASME Code Case N-240 to exempt certain piping from hydrostatic testing
DELGEORGE, L O Commonwealth Edison Co 79/05/21 3pp

7905310361 Informs NRC of erosion on portions of makeup & blowdown water pipeline corridor. Plan submitted by Soil Conservation Svc will be implemented
REED, C Commonwealth Edison Co 79/05/23 2pp

P. Security, medical, emergency & fire protection plans

7905010323 Forwards Revision 4 to physical security plan. Plan withheld (ref 10CFR2 790),
REED, C Commonwealth Edison Co 79/04/17 1p

J. Insurance & indemnity information

7905100163 Endorsement 99 to MAELU Policy MF-22
QERAS, T Nuclear Energy Liability Insurance Association 79/03/27 1p

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATROCHI, J. American Nuclear Insurers. 79/05/01 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D M Mutual Atomic Energy Liability Underwriters. 79/05/01 1p.

7905140546 Forwards Amend 1 to Indemnity Agreement B-84 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation encl
BALTZMAN, J. Antitrust & Indemnity Group 79/05/01 6pp.

K. Utility Final Safety Analysis Report (FSAR) & amends

7905020312 Forwards Amend 45 to FSAR which responds to 34 second round questions
REED, C Commonwealth Edison Co 79/04/20 1p

--7905020320 Amend 45 to FSAR Oversized charts available in Central Files
* Commonwealth Edison Co 79/04/30 260pp

7905110155 Forwards affidavit for distribution of Amend 45 to FSAR
DELGEORGE, L O Commonwealth Edison Co 79/05/04 2pp

G. Inspection reports, IE Bulletins & correspondence

7905030054 Forwards IE Insp Repts 50-373/79-11 & 50-374/79-08 on 790221-23 & notice of violation
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/15 2pp

--7905030061 Notice of violation from insp on 790221-23.
* Region 3, Chicago, Office of the Director 79/03/14 2pp

--7905030074 IE Insp Repts 50-373/79-11 & 50-374/79-08 on 790221-23 Noncompliance noted. Failure to maintain min bend radius for cables & failure to take measures to ensure that max cable pull tensions were not exceeded
BARRETT, P A, NEISLER, J H, KNOP, R C Region 3, Chicago, Office of the Director 79/03/14 8pp

7905020421 Forwards response to IE Bulletins 78-12 & 78-12A, "Atypical Weld Matl in Reactor Pressure Vessel Welds"
REED, C Commonwealth Edison Co 79/03/22 10pp

7905010236 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23 1p.

7905030370 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26 1p.

7905030013 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/11 1p

7905010569 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/14 1p

7905040334 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040529 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/14 1p

7905010380 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/16 1p.

7905030206 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/17 1p.

7905040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/21 1p

--7905040158 IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl" Supporting documentation encl
* Region 3, Chicago, Office of the Director 79/04/21 12pp

DOCKETED ITEMS

185

--7903040170 ACRS recommendations re 790328 incident at TMI. Suggests high priority be placed on development of safety research on behavior of LWRs during anomalous transients.
* ACRB - Advisory Committee on Reactor Safeguards 79/04/17 2pp

--7903040201 Forwards ACRS recommendations re TMI incident, presented on 790417.
FRALEY, R F ACRB - Advisory Committee on Reactor Safeguards 79/04/18 1p.

--7903040221 In response to NRC 790418 ltr, states all 790417 ACRS recommendations apply to all PWRs, but were not intended to require immediate changes. Plant mods should be made after study of effects on overall safety. TMI excluded.
CARBON, M X ACRB - Advisory Committee on Reactor Safeguards 79/04/20 2pp

7905240633 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping. Reanalysis indicates method of intramodal combination has little effect on pipe stresses & equipment support loads.
REED, C Commonwealth Edison Co 79/04/24 4pp.

7905140488 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase".
KEPLER, J O Region 3, Chicago, Office of the Director 79/05/02 1p.

B Reportable occurrences, LERs & related correspondence

7905300435 Notifies that all super strut Type 1202 hangers which were galvanized prior to welding are subj to same defect reported in 790419 ltr. Complete insp will be performed on Type 1202 hangers.
DELOEDRGE, L O Commonwealth Edison Co 79/05/21 5pp

DOCKET 30-375 NUCLEAR EXAMINATION REACTOR

J. Insurance & indemnity information

7905160320 Forwards Amend 15 to Indemnity Agreement B-13, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
BALTZMAN, J. Antitrust & Indemnity Group 79/05/01 5pp

R Periodic operating reports & related correspondence

7905080510 Forwards "L-85 Reactor, Annual Operations for 1978" & "Energy Sys Group Environ Monitoring & Facility Effluent Annual Rpt, 1978".
BRINDLEY, J H Rockwell International Corp 79/05/04 1p.

--7905080513 "L-85 Reactor, Annual Operations for 1978".
SWANSON, V. A. Rockwell International Corp 79/02/08 3pp.

--7905080517 "Energy Sys Group Environ Monitoring & Facility Effluent Annual Rpt, 1978".
MOORE, J D. Rockwell International Corp. E80-79-7 79/04/30 57pp

DOCKET 30-376 NORTH COAST NUC PLANT

A. Application/construction stage documents & correspondence

7905100113 Forwards "Site Safety Evaluation Rpt" for early site review of Isote site in Puerto Rico. Site is suitable for plant, provided 0.45 g seismic design level is used & outstanding items in rpt are resolved.
MOORE, V A. Assistant Director for Environmental Projects. 79/04/27 1p.

--7905110016 "Site Safety Evaluation Rpt" re determination of suitability of Isote site for eventual const of plant by Puerto Rican Water Resources Authority.
* Office of Nuclear Reactor Regulation. NUREG-0541 79/04/30. 62pp.

7905150128 Forwards site safety evaluation rpt review by ACRB.
W/o encl.
BALLARD, R. L. Environmental Projects Branch 1 79/04/27 2pp.

--7905150132 Notice of availability of site safety evaluation rpt for facility.
BALLARD, R. L. Environmental Projects Branch 1 79/04/27 2pp.

O Adjudicatory correspondence

7905240959 Forwards status rpt, as of 790430, on developments in Puerto Rico concerning facility application.
AXELRAD, M Lowenstein, Newman, Reis, Axelrad & Toll 79/04/30 1p

--7905240970 Status rpt by Puerto Rico Water Resources Authority re facility application, as of 790430. Electric Power Sys will issue rpt by late May. Certificate of Svc encl.
AXELRAD, M Lowenstein, Newman, Reis, Axelrad & Toll 79/04/30 3pp

DOCKET 30-382 WATERFORD GENERATING STATION, UNIT 3

A Application/construction stage documents & correspondence

7905020406 Forwards NUREG-0331, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability W/o encl.
VASSALLO, D B Assistant Director for Light Water Reactors 79/03/23 2pp

7905140516 Forwards summary of major milestones re OL application safety review. Review of schedule concludes B10923 is realistic date for issuance of OL.
BOYD, R S Division of Project Management 79/04/19 3pp

7905100112 Requests addl info to complete review of FSAR. Complete responses should be provided by 790720 in order to maintain review schedule.
BAER, R L Light Water Reactors Branch 4 79/04/26 70pp

C Utility Environmental Report (ER), amends & correspondence

7905230855 Forwards request for addl info to complete environ review. Answers should consist of sequentially numbered revisions to environ rpt.
BALLARD, R L Environmental Projects Branch 1 79/05/03 28pp

O Adjudicatory correspondence

7905290300 Contentions of LA Consumers League. Amends original petition. Affidavit of L Samuel & Certificate of Svc encl.
IRVING, S M Louisiana Consumer's League, Inc 79/04/04 5pp

7905290131 Contentions of Save Our Wetlands, Inc & Oystershell Alliance, Inc. Amends original petition. Affidavits of N Haskell & B King & Certificate of Svc encl.
FONTANA, L Fontana, L JONES, L L Gillespie & Jones 79/04/11 14pp

7905250340 Notices of appearance on behalf of LA Power & Light Co. Certificate of Svc encl.
TROWBRIDGE, O F, YUSPEH, A. R Shaw, Pittman, Potts, & Trowbridge 79/04/13 4pp

7905220037 Notice of appearance on behalf of LA Power & Light Co. Certificate of Svc encl.
STEVENSON, M M. Monroe & Lemann 79/04/17 3pp

7905290049 Suppl to petition to intervene. Discusses NRC positions re contentions of Save Our Wetlands, Inc & Oystershell Alliance, Inc. Certificate of Svc encl.
MCOURRAN, H J, Branch 1. 79/04/25 26pp.

7905250541 Discusses 790426 prehearing conference. Intervenor's Contentions 2, 3, 4 & 6 were admitted. NRC will file submission re Contentions 5 & 7 by 790801.
WOLFE, S J Atomic Safety and Licensing Board Panel 79/05/09 3pp

I. Financial information

7905070166 Forwards registration statement filed by LA Power & Light Co on 790321 W/o encl.
BOROCHOFF, I D. Securities & Exchange Commission 79/03/23 1p

7905110260 Forwards "Annual Financial Rpt 1978".
ABWELL, D L Louisiana Power & Light Co 79/04/30 1p.

--7905110262 "Annual Financial Rpt 1978".
* Louisiana Power & Light Co 79/03/19 19pp

K Utility Final Safety Analysis Report (FSAR) & amends

7905170228 Forwards Amend 3 to FSAR.
ABWELL, D. L. Louisiana Power & Light Co. 79/05/10 2pp

DOCKETED ITEMS

--7903170231 Amend 3 to FSAR
ASWELL, D L Louisiana Power & Light Co 79/05/10 500pp

7905240590 Certificate of Svc for Amend 3 to FSAR
* Louisiana Power & Light Co 79/05/17 1p

G Inspection reports, IE Bulletins & correspondence

7905010274 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/23
1p

7905150541 Forwards IE Insp Rept 50-382/79-03 on 790226-0309 & notice
of violation
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/03/28 2pp

--7903150544 Notice of violation from insp on 790226-0309
* Region 4, Dallas, Office of the Director 79/03/27 2pp

--7903150550 IE Insp Rept 50-382/79-03 on 790226-0309 Noncompliance
noted improper mounting of Class IE 4160 volt switchgear &
failure to follow approved drawings
STEWART, R C, OILBERT, L D, MATIN, L E Region 4, Dallas, Office
of the Director 79/03/27 9pp

7905010461 Forwards IE Bulletin 79-05A, "Nuclear Incident at
THI - Suppl"
SEYFRIT, K V, Region 4, Dallas, Office of the Director, 79/04/05
1p

7905040496 Forwards IE Bulletin 79-06B, "Review of Operational Errors &
Bus Misalignments Identified During THI Incident"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14
1p

7905040618 Forwards IE Bulletin 79-08, "Events Relevant to Boiling
Water Power Reactors Identified During THI Incident"
SEYFRIT, K V, Region 4, Dallas, Office of the Director 79/04/14
1p

7905070066 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of
Safety-Related Piping" Licensee action required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14
1p

7905010435 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support
Struts"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/16
1p

7905090101 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at
THI."
SEYFRIT, K V, Region 4, Dallas, Office of the Director 79/04/16
1p.

7905030274 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2
Circuit Breaker in Safety-Related Sys" Licensee action
required.
SEYFRIT, K V, Region 4, Dallas, Office of the Director, 79/04/17
1p

B Reportable occurrences, LERs & related correspondence

7905030134 Forwards PNO-79-67H, I, J & K.
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/06
1p.

7905030113 Forwards PNO-79-67L, M, N & P.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/09 1p

Reactor Construction & Engineering

Reactor Construction & Engineering

Reactor Construction & Engineering

Reactor Construction & Engineering

7905030066 Forwards PNO-79-67U & V
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/16 1p

7905030250 Forwards PNO-79-67W
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/17 1p

7905020324 Forwards PNO-79-67AA
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/20 1p

7905020311 Forwards PNO-79-67AB, AC & AD
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/23 1p

7905040579 Forwards PNO-79-67AE.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/26 1p

7905070188 Forwards PNO-79-67AF & AG
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/27 1p

7905310222 Forwards PNO-79-67AH, AI & AJ
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/30 1p

7905240374 Forwards PNO-79-67AK & AL
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/05/04 1p

7905150264 Forwards Significant Deficiency Rept 11 re switchgear
breaker position switch operator defect
ASWELL, D L Louisiana Power & Light Co 79/05/10 1p

--7905150273 Significant Deficiency Rept 11 switchgear breaker position
switch operator defect Switch may become bent due to
interference w/circuit breaker New switch operator designed
to be more rigid & protected by guide
BARATHY, P. K, SANDIFORTH, D, COSTELLO, J Louisiana Power & Light
Co 79/05/10 8pp

7905150408 Forwards Interim Rept 12 re significant const deficiency
ASWELL, D L Louisiana Power & Light Co 79/05/10 1p

--7905150415 Interim Rept 12 of significant const deficiency on 790404
McJunkin Corp notified Ebasco Svcs, Inc that pipe fittings
bearing lot identification W6719 were subj to matl failures.
All installed fittings identified & tagged
CRNICH, J, MILHIBER, R J, COSTELLO, J Louisiana Power & Light Co
79/05/10 3pp

--7905150417 Summarizes 790409 discussion w/RC Stewart Elbow cracking
identified in lot W6719 Recall program initiated Six elbows
from defective lot found at facility. After testing, defective
fittings will be replaced
GEORGE, H H Chemetron Corp, Tube Turns Div. 79/04/12 2pp

T Hearing transcripts on non-antitrust matters

7905140565 Transcript of 790426 hearing in New Orleans, LA Pp 1-111
WOLF, B, JORDAN, W, FOREMAN, H Atomic Safety and Licensing Board
Panel. 79/04/26 112pp.

DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905040316 Summary of 790321 meeting of Mark II owners group in San
Jose, CA re intermediate plant program tasks.
ANDERSON, C J Containment Systems Branch. 79/04/13 150pp

7905100224 Notification of 790515-16 meeting w/util at Susquehanna
site in PA to discuss const schedule. Agenda encl
MINER, S Light Water Reactors Branch 3. 79/04/19 4pp.

7905240806 Informs of possible six month delay in OL review schedule
from util
MINER, S. Light Water Reactors Branch 3. 79/05/03 2pp.

7905090346 Notifies of plans to replace reactor pressure vessel
recirculation nozzle safe-end & thermal sleeves. Mod aimed at
increasing reliability & protection against intergranular
stress corrosion cracking
CURTIS, N W Pennsylvania Power & Light Co. 79/05/04 2pp

DOCKETED ITEMS

187

7905090365 Forwards affidavit of svc for Amend 9 to OL application
CURTIS, N W Pennsylvania Power & Light Co. 79/05/07 2pp

7905110300 Discusses 78103 deficiency rept re SBE sys standby diesel
generator Safety impact to be evaluated & results
transmitted by 790525, W/781103 rept
CURTIS, N W Pennsylvania Power & Light Co 79/05/11 2pp

7905240574 Lists EPA-approved herbicides used along transmission lines
to replace suspended herbicide 2,4,5-T
CURTIS, N W Pennsylvania Power & Light Co. 79/05/21 1p.

F. Security, medical, emergency & fire protection plans

7905130794 Forwards request for addl info re physical security plan to
complete review of OL application Encl withheld
(ref 10CFR2.790)
PARR, O D. Light Water Reactors Branch 3 79/04/13 2pp

O Adjudicatory correspondence

7905250186 Investigation completed re allegations made at 790130
prehearing conference by MK Creasy. Investigation did not
substantiate allegations.
CURTIS, N W Pennsylvania Power & Light Co 79/03/29 1p

7905240081 Daily transcript of hearings will be loaned to intervenors
whenever possible, as aid in preparation of case
CUTCHIN, J M Branch 3 79/04/10 2pp.

7905240625 Requests info re procedure to make limited appearance at
hearing
NEMETHY, E Affiliation Unknown 79/04/15 1p

K Utility Final Safety Analysis Report (FSAR) & amends

7905020262 Forwards Amend 9 to application for OL, submitted as Revision
7 to FSAR
CURTIS, N W Pennsylvania Power & Light Co 79/04/30 124pp

7905130224 Forwards Amend 10 to OL application containing Revision 8 to
FSAR Amend withheld (ref 10CFR2.790)
CURTIS, N W Pennsylvania Power & Light Co 79/05/11 2pp

Q Inspection reports, IE Bulletins & correspondence

7905100428 Forwards IE Insp Rept 50-387/79-07 on 790222 No
noncompliance noted
CARLBON, R T Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 79/03/19 2pp.

--7905100433 IE Insp Rept 50-387/79-07 on 790222 No noncompliance noted
Major areas inspected power generator control complex &
areas containing electrical/instrumentation equipment
installations
KOLYAY, P B Region 1, Philadelphia, Office of the Director
EBNETER, B D Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 79/03/16. 3pp.

7905010136 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping."
ORIER, B H Region 1, Philadelphia, Office of the Director
79/03/23. 1p

7905040140 Ack receipt of 790319 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-387/79-03
CARLBON, R T Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 79/04/06. 1p

--7905040146 Responds to NRC 790220 ltr re violations noted in IE Insp
Rept 50-387/79-03. Corrective actions revised procedure for
field touch-ups & reinspected structural steel members for
arc strikes
BAROL, A R Pennsylvania Power & Light Co. 79/03/19. 3pp

--7905040149 Forwards IE Insp Rept 50-387/79-03 on 790130-0202 & notice
of violation.
CARLBON, R T Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch. 79/02/20 2pp.

--7905040153 Notice of violation from insp on 790130-0202
&
Region 1, Philadelphia, Office of the Director. 79/02/20
1p

--7905040156 IE Insp Rept 50-387/79-03 on 790130-0202 Noncompliance
noted failure to control structural steel arc strikes
MCBREARY, R A FASANO, A N Region 1, Philadelphia, Office of
the Director TRIPP, L Region 1, Philadelphia, Reactor
Construction & Engineering Support Branch. 79/02/16. 8pp.

7905020085 Forwards IE Bulletin 79-06, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident "
ORIER, B H Region 1, Philadelphia, Office of the Director
79/04/11 1p

7905020402 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of
Safety-Related Piping " Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040091 Forwards IE Bulletin 79-06B, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident "
ORIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040269 Forwards IE Bulletin 79-08, "Events Relevant to Boiling
Water Power Reactors Identified During TMI Incident "
ORIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905030093 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2
Circuit Breaker in Safety-Related Sys " Licensee action
required
ORIER, B H Region 1, Philadelphia, Office of the Director
79/04/17. 1p

7905020314 Forwards IE Bulletin 79-06A, Revision 1, "Review of
Operational Errors & Sys Misalignments Identified During TMI
Incident "
ORIER, B H Region 1, Philadelphia, Office of the Director
79/04/18 1p

R Periodic operating reports & related correspondence

7905040504 Forwards annual environ rept. "Sound Level Measurements Near
Plant Site Const 1978" prepared by Bolt Beranek & Neuman
Inc
CURTIS, N W Pennsylvania Power & Light Co 79/05/01 1p

--7905040506 "Sound Level Measurements Near Plant Site Const 1978. "
annual environ rept, const noise progress rept prepared by
Bolt Beranek & Neuman Inc
BARNES, J D , WOOD, E F Pennsylvania Power & Light Co 79/03/31
28pp

S Reportable occurrences, LERs & related correspondence

7905030129 Ack receipt of 790323 interim deficiency rept re J-69B
solenoid valves.
CARLBON, R T Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch. 79/04/10 1p

--7905030149 Confirms info re potentially reportable deficiency in
circle seal Model J-69B solenoid valves w/defective diodes
Valves have been removed from installed locations & are in
jobsite warehouse awaiting return to vendor
CURTIS, N W Pennsylvania Power & Light Co 79/03/23 2pp

7905160424 Forwards corrected page 1 of PLA-352 which includes missing
date of 790507
BARTO, M C Pennsylvania Power & Light Co 79/05/11 2pp

7905250421 Updates deficiency rept re Circle Seal Model J-69B solenoid
valves Defective valves presently controlled per Bechtel
procedure. Final rept to be submitted by 790701.
CURTIS, N W Pennsylvania Power & Light Co. 79/05/22 2pp

DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

A Application/construction stage documents & correspondence

7905040316 Summary of 790321 meeting of Mark II owners group in San
Jose, CA re intermediate plant program tasks
ANDERSON, C J. Containment Systems Branch. 79/04/13 150pp

7905100224 Notification of 790315-16 meeting w/util at Susquehanna
site in PA to discuss const schedule. Agenda encl
MINER, S. Light Water Reactors Branch 3. 79/04/19 4pp

7905240806 Informs of possible six month delay in OL review schedule
from util.
MINER, S. Light Water Reactors Branch 3 79/05/03 2pp

7905090346 Notifies of plans to replace reactor pressure vessel
recirculation nozzle safe-end & thermal sleeves Mod aimed at
increasing reliability & protection against intergranular
stress corrosion cracking.
CURTIS, N W. Pennsylvania Power & Light Co. 79/05/04. 2pp.

DOCKETED ITEMS

7905090365 Forwards affidavit of svc for Amend 9 to OL application
CURTIS, N W Pennsylvania Power & Light Co 79/05/07. 2pp

7905110300 Discusses 781103 deficiency rept re SSE sys standby diesel
generator Safety impact to be evaluated & results
transmitted by 790525 H/781103 rept
CURTIS, N W Pennsylvania Power & Light Co 79/05/11 2pp

7905240574 Lists EPA-approved herbicides used along transmission lines
to replace suspended herbicide 2,4,5-T
CURTIS, N W Pennsylvania Power & Light Co 79/05/21 1p

F Security, medical, emergency & fire protection plans

7905150794 Forwards request for addl info re physical security plan to
complete review of OL application Encl withheld
(ref 10CFR2 790)
PARR, D D Light Water Reactors Branch 3 79/04/13 2pp

G Adjudicatory correspondence

7905250186 Investigation completed re allegations made at 790130
prehearing conference by HK Cressy Investigation did not
substantiate allegations
CURTIS, N W Pennsylvania Power & Light Co 79/03/29 1p

7905240081 Daily transcript of hearings will be loaned to intervenors
whenever possible, as aid in preparation of case
CUTCHIN, J H Branch 3 79/04/10 2pp

7905240625 Requests info re procedure to make limited appearance at
hearing
NEMETHY, E Affiliation Unknown 79/04/15 1p

K Utility Final Safety Analysis Report (FSAR) & amends

7905020262 Forwards Amend 9 to application for OL, submitted as Revision
7 to FSAR
CURTIS, N W Pennsylvania Power & Light Co 79/04/30 124pp

7905150224 Forwards Amend 10 to OL application containing Revision B to
FSAR Amend withheld (ref 10CFR2 790)
CURTIS, N W Pennsylvania Power & Light Co 79/05/11 2pp

G Inspection reports, IE Bulletins & correspondence

7905010136 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping"
ORIER, B H Region 1, Philadelphia, Office of the Director
79/03/23 1p

7905020085 Forwards IE Bulletin 79-06, "Review of Operational Errors &
Sys Misalignments Identified During TH1 Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director
79/04/11 1p

7905020402 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of
Safety-Related Piping" Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040091 Forwards IE Bulletin 79-06B, "Review of Operational Errors &
Sys Misalignments Identified During TH1 Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p.

7905040269 Forwards IE Bulletin 79-08, "Events Relevant to Boiling
Water Power Reactors Identified During TH1 Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905030093 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2
Circuit Breaker in Safety-Related Sys" Licensee action
required
ORIER, B H Region 1, Philadelphia, Office of the Director.
79/04/17. 1p

7905020314 Forwards IE Bulletin 79-06A, Revision 1, "Review of
Operational Errors & Sys Misalignments Identified During TH1
Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director
79/04/18 1p

R. Periodic operating reports & related correspondence

7905040504 Forwards annual environ rept, "Sound Level Measurements Near
Plant Site Const 1978" prepared by Britt Beranek & Newman
Inc
CURTIS, N W Pennsylvania Power & Light Co 79/05/01 1p

--7905040506 "Sound Level Measurements Near Plant Site Const 1978,"
annual environ rept, const noise progress rept prepared by
Britt Beranek & Newman Inc
BARNES, J D ; WOOD, E F Pennsylvania Power & Light Co. 79/03/31
28pp

S Reportable occurrences, LERs & related correspondence

7905160424 Forwards corrected page 1 of PLA-352 which includes missing
date of 790507
BARTO, H C Pennsylvania Power & Light Co 79/05/11. 2pp.

7905250421 Updates deficiency rept re Circle Seal Model J-678 solenoid
valves, Defective valves presently controlled per Bechtel
procedure Final rept to be submitted by 790701
CURTIS, N W Pennsylvania Power & Light Co 79/05/22 2pp.

DOCKET 30-389 ST LUCIE PLANT, UNIT 2

G Adjudicatory correspondence

7905240207 Response by util to 790301 ABLAB memo & order re radon
release rates, concentrations & health effects Certificate
of Bvc encl
BAUSER, M A Lowenstein, Newman, Reis, Axelrad & Toll 79/04/03 9pp

7905100402 Notifies new info re fuel blockage model for ECCB is
presently being evaluated Review will be forwarded upon
completion
PATON, W D Branch 4 79/04/11 1p

7905110418 Response to ALAB-309 re radon emissions & de minimus theory
from Perkins record Certificate of Bvc encl.
SCINTO, J F Hearings Division 79/04/11. 45pp

7905140519 Response to 790404 brief of Philadelphia Electric Co, PSE&C &
Atlantic City (NJ) Electric Co re de minimus theory.
Certificate of Bvc encl
KEPFORD, C R Citizens for Safe Environment 79/04/11. 8pp.

7905150125 Forwards NRC rept "Inquiry into Allegation of Employee
Misconduct by Restricting Investigation to Determine
Reliability of Power Grid Serving St Lucie"
BOHINKI, B M Branch 3 79/04/11. 1p.

--7905150130 "Inquiry into Allegation of Employee Misconduct by
Restricting Investigation to Determine Reliability
of Power Grid Serving St Lucie,"
MC TIERNAN, T J Office of Inspector & Auditor. 78/06/30. 83pp

7905100130 Notifies continuance will be needed for preparation of info
re ALAB-537 Vital witness is currently assigned to TH1-2,
but may return 790501. Present estimate for submittal date
is 790615 or later
TOURTELLOTTE, J Branch 4. 79/04/12 2pp

7905100009 Forwards motion for reconsideration of 790405 ALAB-537 or
scheduling of prehearing conference. Explains & exposes
Basis of ABLAB decision re manner of proceeding in captioned
matter
REIS, H F Lowenstein, Newman, Reis, Axelrad & Toll 79/04/13 3pp

--7905100011 Moves for reconsideration of 790405 ALAB-537 or scheduling
prehearing conference Refers to accompanying memo containing
justifications Certificate of Bvc encl
REIS, H F Lowenstein, Newman, Reis, Axelrad & Toll. 79/04/13 2pp

--7905100019 Supports 790413 motion for reconsideration of ALAB-537 or
scheduling prehearing conference. Certificate of Bvc encl
REIS, H F Lowenstein, Newman, Reis, Axelrad & Toll. 79/04/13 9pp

7905240154 Forwards draft Reg Guide 1. XXX, "Lightning Protection for
Nuclear Power Plants" W/o encl.
PATON, W D Branch 4. 79/04/17. 1p.

DOCKETED ITEMS

189

7903270289 Motion by intervenors for initiation of discovery procedures & submittal of interrogatories to util re util's electrical grid stability & emergency power sys Certificate of Bvc encl
HODDER, M H Hodder, M H 79/04/17 5pp

7903230035 Notifies that telcon to AGLAB from MH Hodder, counsel for intervenors, had little relationship to recently released ALAB-537
DUFLO, M E Atomic Safety and Licensing Appeal Panel 79/04/18 2pp

7903240838 Requests denial of intervenors' 790417 motion to permit discovery Certificate of Bvc encl
COLL, M A Steel, Hector & Davis 79/04/19 5pp

7903140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition
DUFLO, M E Atomic Safety and Licensing Appeal Panel 79/04/25 13pp

7903230203 Extends until 790517 time for Commission review of portion of ALAB-537 re steam generator tubes
CHILL, B J Office of the Secretary of the Commission 79/05/08 1p

J Insurance & indemnity information

7903070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 183, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATROCHILL, J American Nuclear Insurers 79/05/01 1p

7903070982 Confirms increase in liability limit to \$36,000,000 for policies HF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7903100309 Forwards Endorsement 31 to NELIA Policy NF-227
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc. Div 79/03/04 2pp

7903100311 Forwards Endorsement 32 to NELIA Policy NF-227
FIELDER, J Marsh & McLennan, M & M Nuclear Consultants, Inc. Div 79/03/04 2pp

H Antitrust correspondence

7903130232 Forwards addl info re testimony preparation W/o encl
EVANS, D J Anti-Trust Division 79/03/27 1p

7903240105 Supplements discovery rulings as result of parties' memos responding to 790209 memo & order Parties may negotiate mod of prehearing schedule First interim rept re progress of discovery will be due 790301
SHITH, I W Atomic Safety and Licensing Board Panel 79/03/28 13pp

7903230622 Responds to 790328 & 790402 motions filed by FL Cities to initiate antitrust hearing, in response to NRC 780727 order Certificate of Bvc encl.
DEWEY, L. Anti-Trust Division. 79/04/17 5pp.

7903240853 Joint motion of util & FL Cities for suspension of discovery procedures to permit settlement discussions to be pursued Certificate of bvc encl.
JABLON, R. A., QUITMAN, D., Spiegel & McDiamid, BOUKNIGHT, J A Lowenstein, Newman, Reis, Axelrad & Toll 79/04/20 4pp.

7903130796 Grants 790420 joint motion by applicant & FL Cities seeking delay in discovery until 790801.
SHITH, I. W. Atomic Safety and Licensing Board Panel 79/04/23 1p

0. Inspection reports, IE Bulletins & correspondence

7903070352 Forwards IE Insp Rept 50-389/79-02 on 790131-0202. No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/13 2pp.

--7903070358 IE Insp Rept 50-389/79-02 on 790131-0202 No noncompliance noted. Major areas inspected: concrete procedures, specs & records & concrete placement & backfill operations.
HARRIS, J. R., BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/13. 4pp.

7903010235 Forwards IE Insp Rept 50-389/79-03 on 790213-15 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/16 2pp

--7903010243 IE Insp Rept 50-389/79-03 on 790213-15 No noncompliance noted. Major areas inspected: reactor vessel internals procedures, work observation & quality records, equipment storage, & QA records storage
ANG, W. P., BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/15 3pp

7903230137 Forwards IE Insp Rept 50-389/79-04 on 790227-0302 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/21 2pp

--7903230153 IE Insp Rept 50-389/79-04 on 790227-0302 No noncompliance noted. Major areas inspected: concrete lab, intake structure, concrete placement, weld repair to containment vessel & site GA audit
WRIGHT, R. W., GOUGE, M. J. Region 2, Atlanta, Office of the Director
HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/20 8pp

7903010195 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/23 2pp

7903030310 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/26 2pp

7903040212 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 2pp

7903040308 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 1p

7903040404 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 1p

7903010337 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/18 2pp.

7903030164 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/17 2pp

7903020465 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/18 2pp

B Reportable occurrences, LERs & related correspondence

790310203 Board notification: Seabrook refueling water storage tank design deficiency
SCINTQ, J. Hearings Division. 79/03/29 30pp

DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

790310220 Notification of 790301-02 meeting w/util in Spring City, TN to review status of plant const in order to make independent estimate of fuel loading date
STAHL, C. R. Light Water Reactors Branch 4. 79/04/25 2pp

7903040348 Requests completion dates specified in CPs be extended to Jul 1980 for Unit 1 & Mar 1981 for Unit 2 Factors contributing to delay include ice condenser embedments & installation of large cable tray supports
GILLELAND, J. E. Tennessee Valley Authority 79/04/27. 2pp

790310225 Approval of Tefzel 200 as snubber matl requiring surveillance interval no more stringent than that required for ethylene propylene equipped snubbers.
GILLELAND, J. E. Tennessee Valley Authority. 79/03/04. 21pp.

DOCKETED ITEMS

7905290390 Responds to NRC questions re plant containment sump. Forwards "NPSH Calculations for RHR & Containment Spray Pumps Operating in Recirculation Mode" & "Model Study of Plant RHR Sump" GILLELAND, J E Tennessee Valley Authority. 79/05/23 1p

--7905290393 "NPSH Calculations for RHR & Containment Spray Pumps Operating in Recirculation Mode," Apr 1979
* Tennessee Valley Authority 79/04/30 10pp

--7905290399 "Model Study of RHR Sump"
FAIN, T G Tennessee Valley Authority WH28-1-85-101 79/03/31 29pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 78, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others GUATTROCHINI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96 ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905130802 Forwards IE Insp Rept 50-390/79-08 & 50-591/79-05 on 790129-0223. No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/22 2pp

--7905130805 IE Insp Rept 50-590/79-08 & 50-591/79-05 on 790129-0223 No noncompliance noted. Major areas inspected: welding of pressurizer spray pipe; RHR piping; containment spray piping & work on reactor internals
COCHRAN, B J Region 3, Chicago, Office of the Director
HERDT, A R Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/21 7pp

7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905010113 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/28 2pp

7905010363 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/30 2pp

7905030368 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 3pp

7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/4/14 3pp.

Forwards IE Bulletin 79-08, "Events Relevant to Boiling water Reactors Identified During TMI Incident"
J P Region 2, Atlanta, Office of the Director 1p.

79-10, "Nonconforming Pipe Support

Office of the Director

lures of OE Type AK-2
Licensee action

Director

7905020479 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp

7905010564 Forwards Revisions 2 & 3 to Preservice Baseline & Inservice Insp Program SI-4 4, LO 1,
GILLELAND, J E Tennessee Valley Authority. 79/04/24, 1p.

--7905010567 Surveillance Instruction, SI-4, 4, LO 1, Preservice Insp & Inservice Insp Program
BELEN, G L, ENNIS, E R Tennessee Valley Authority 78/10/25 30pp

7905300293 Submits supplemental response to IE Bulletin 77-07, Original response submitted 780120 Provides addl info received from manufacturer & describes plans in area of electrical penetrations
GILLELAND, J E Tennessee Valley Authority 79/04/27 5pp

B. Reportable occurrences, LERs & related correspondence

7905140490 Forwards first interim deficiency rept re defective Phillips self-drill concrete anchors
GILLELAND, J E Tennessee Valley Authority 79/04/18 1p

--7905140491 First interim deficiency rept, defective Phillips self-drill concrete anchors. Deficiency reported by manufacturer ITT Phillips Drill Div. Search initiated to locate all anchors supplied in defective lot
* Tennessee Valley Authority 79/04/18 1p

7905140503 Forwards first interim rept re incorrect analysis of piping sys over total temp range
GILLELAND, J E Tennessee Valley Authority 79/04/19 1p

--7905140504 First interim rept, incorrect analysis of piping sys over operating temp range. Util is reanalyzing stressing of all sys, subj to temp below ambient.
* Tennessee Valley Authority 79/04/19 1p

7905010481 Fourth interim rept of status of review of possible unconservative pressurizer relief & safety line blowdown analysis. Next rept to be submitted by 790531 Awaiting Westinghouse review of nozzle loads
GILLELAND, J E Tennessee Valley Authority. 79/04/23 1p.

7905010518 Forwards final rept on deficiency re omitted heating & ventilating ductwork hangers.
GILLELAND, J E Tennessee Valley Authority 79/04/23, 1p

--7905010519 Final rept re omitted heating & ventilating ductwork hangers failing to provide seismic Category I integrity. Design drawings being revised. Required addl hangers will be added
* Tennessee Valley Authority 79/04/23 1p.

7905040562 Forwards final deficiency rept re diesel generator relay tachometer failures reported 790130 All overheated diodes replaced & tachometers closely monitored.
GILLELAND, J E Tennessee Valley Authority. 79/04/30 3pp

790510228 Forwards first interim deficiency rept re QA program implementation breakdown
GILLELAND, J E Tennessee Valley Authority. 79/05/04, 1p.

--790510228 First interim deficiency rept on 790504 QA program breakdown re structural integrity of high density spent fuel storage racks. Objective documentary evidence will be obtained from supplier.
* Tennessee Valley Authority. 79/05/04, 2pp

7905160317 Forwards first deficiency rept re failure of power operated relief valves to meet frequency requirements
GILLELAND, J E Tennessee Valley Authority. 79/05/08, 1p.

--7905160331 First interim deficiency rept, power operated relief valves (SIABRO) do not meet frequency requirements. Westinghouse is developing math model to consider valve frequency, which will be incorporated in piping analysis.
* Tennessee Valley Authority 79/05/08 1p

7905170217 Forwards final deficiency rept re failure of control loop bistables.
GILLELAND, J E Tennessee Valley Authority. 79/05/10, 1p

--7905170220 Final deficiency rept, control loop bistables fail in undesirable position on loss of control power. Caused by error in wiring of bistable. Bistable wiring corrected so that bistables will fail open on loss of power.
* Tennessee Valley Authority. 79/05/10, 1p

7905230381 Provides second interim rept re deficiency in tensile anchor capacities lower than design allowables. Testing of stud anchors still in progress. Next rept to be submitted by 790806
GILLELAND, J E Tennessee Valley Authority. 79/05/17 1p

DOCKETED ITEMS

191

DOCKET 30-391 WATTS BAR NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

7905100220 Notification of 790501-02 meeting w/util in Spring City, TN to review status of plant const in order to make independent estimate of fuel loading date.
STAHLER, C.R. Light Water Reactors Branch 4 79/04/29 2pp.

7905040348 Requests completion dates specified in CPs be extended to Jul 1980 for Unit 1 & Mar 1981 for Unit 2. Factors contributing to delay include ice condenser embedments & installation of large cable tray supports.
GILLELAND, J.E. Tennessee Valley Authority 79/04/27 2pp.

7905100225 Approval of Tefzel 200 as snubber matl requiring surveillance interval no more stringent than that required for ethylene propylene equipped snubbers
GILLELAND, J.E. Tennessee Valley Authority 79/05/04 21pp

7905290390 Responds to NRC questions re plant containment sump Forwards "NPSH Calculations for RHR & Containment Spray Pumps Operating in Recirculation Mode" & "Model Study of Plant RHR Bump."
GILLELAND, J.E. Tennessee Valley Authority 79/05/23. 1p

--7905290393 "NPSH Calculations for RHR & Containment Spray Pumps Operating in Recirculation Mode," Apr 1979
* Tennessee Valley Authority 79/04/30 10pp

--7905290399 "Model Study of RHR Bump"
FAIN, T.O. Tennessee Valley Authority WM28-1-85-101 79/03/31 29pp.

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215, & others.
QUATTRACHIL, J. American Nuclear Insurers. 79/05/01. 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96.
ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters 79/05/01 1p

Q Inspection reports, IE Bulletins & correspondence

7905150802 Forwards IE Insp Rept 50-390/79-08 & 50-591/79-05 on 790129-0223. No noncompliance noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/22. 2pp.

--7905150805 IE Insp Rept 50-390/79-08 & 50-591/79-05 on 790129-0223 No noncompliance noted. Major areas inspected: welding of pressurizer spray pipe/RHR piping; containment spray piping & work on reactor internals.
COCHRAN, B.J. Region 3, Chicago, Office of the Director.
HERDT, A.R. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/03/21 7pp.

7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/23. 2pp.

7905020074 Ack receipt of 790402 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-391/79-04.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/12 2pp.

--7905020097 Forwards IE Insp Rept 50-391/79-04 on 790130-0202 & notice of violation
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/09 2pp

--7905020102 Notice of violation from insp on 790130-0202
* Region 2, Atlanta, Office of the Director. 79/03/08. 1p.

--7905020117 IE Insp Rept 50-391/79-04 on 790130-0202 Noncompliance noted: failure to follow reactor vessel internals procedures.
AND, W.P. Region 2, Atlanta, Office of the Director BRYANT, J.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/08. 4pp.

7905030368 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/14 3pp

7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/14 3pp

7905100365 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/14 1p

7905010341 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/18 1p

7905030172 Forwards IE Bulletin 79-09, "Failures of OE Type AX-2 Circuit Breaker in Safety-Related Sys" Licensee action required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/17 2pp

7905020479 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/18 2pp

7905010564 Forwards Revisions 2 & 3 to Preservice Baseline & Inservice Insp Program SI-4.4 LD 1
GILLELAND, J.E. Tennessee Valley Authority 79/04/24 1p

--7905010567 "Surveillance Instruction, SI-4.4.10.1, Preservice Insp & Inservice Insp Program"
BELEW, Q.L., ENNIS, E.R. Tennessee Valley Authority 78/10/23 30pp

7905030253 Submits supplemental response to IE Bulletin 77-07 Original response submitted 780120 Provides addl info received from manufacturer & describes plans in area of electrical penetrations
GILLELAND, J.E. Tennessee Valley Authority. 79/04/27 5pp

B Reportable occurrences, LERs & related correspondence

7905140490 Forwards first interim deficiency rept re defective Phillips self-drill concrete anchors
GILLELAND, J.E. Tennessee Valley Authority 79/04/18. 1p

--7905140491 First interim deficiency rept defective Phillips self-drill concrete anchors Deficiency reported by manufacturer ITT Phillips Drill Div. Search initiated to locate all anchors supplied in defective lot
* Tennessee Valley Authority 79/04/18 1p

7905140503 Forwards first interim rept re incorrect analysis of piping sys over total temp range
GILLELAND, J.E. Tennessee Valley Authority. 79/04/19 1p

--7905140504 First interim rept incorrect analysis of piping sys over operating temp range Util is reanalyzing stressing of all sys, subj to temp below ambient
* Tennessee Valley Authority 79/04/19 1p.

7905010481 Fourth interim rept unconservative pressurizer re analysis Next rept to be subm Westinghouse review of nozzle
GILLELAND, J.E. Tennessee Va

7905010518 Forwards final rept ventilating ductwork hangers
GILLELAND, J.E. Tennessee Va

--7905010519 Final rept re omi hangers failing to provide Design drawings being rev'd added
* Tennessee Valley Author

7905040362 Forwards final defi tachometer failures reporter replaced & tachometers close
GILLELAND, J.E. Tennessee Va

DOCKETED ITEMS

790510228 Forwards first interim deficiency rept re GA program implementation breakdown
GILLELAND, J E Tennessee Valley Authority 79/05/04 1p

--790510236 First interim deficiency rept on 790504 GA program breakdown re structural integrity of high density spent fuel storage racks Objective documentary evidence will be obtained from supplier
* Tennessee Valley Authority 79/05/04 2pp

7905160317 Forwards first deficiency rept re failure of power operated relief valves to meet frequency requirements
GILLELAND, J E Tennessee Valley Authority 79/05/08 1p

--7905160331 First interim deficiency rept power operated relief valves (31A88RQ) do not meet frequency requirements Westinghouse is developing math model to consider valve frequency, which will be incorporated in piping analysis
* Tennessee Valley Authority 79/05/08 1p

7905190217 Forwards final deficiency rept re failure of control loop bistables
GILLELAND, J E Tennessee Valley Authority 79/05/10 1p

--7905190220 Final deficiency rept control loop bistables fail in undesirable position on loss of control power. Caused by error in wiring of bistable Bistable wiring corrected so that bistables will fail open on loss of power
* Tennessee Valley Authority 79/05/10 1p

7905230381 Provides second interim rept re deficiency in tensile anchor capacities lower than design allowables Testing of stud anchors still in progress Next rept to be submitted by 790806
GILLELAND, J E Tennessee Valley Authority 79/05/17 1p.

DOCKET 50-394 CALIFORNIA STATE POLYTECH COLLEGE RES REACTOR

J Insurance & indemnity information

7905160222 Forwards Amend 7 to Indemnity Agreement E-55, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01. 5pp

7905150458 Forwards Amend 7 to Indemnity Agreement E-55.
PATTERSON, K P California Polytech State Univ 79/05/08 2pp

DOCKET 50-395 VIROIL C SUMNER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

7905020414 Forwards NUREG-0531, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability W/o encl
VASSALLO, D B Assistant Director for Light Water Reactors. 79/03/23 3pp

7905240340 Summary of 790327 meeting w/util. Gilbert Associates, Inc & Westinghouse in Bethesda, MD re second round requests for info on Section 7 O of FBAR
TIBBITTS, D L Light Water Reactors Branch 2 79/04/27. 7pp.

7905300692 Forwards Technical Rept 79-8, "Oct-Dec 1978 Seismicity Near Plant," & Technical Rept 79-1, "Seismic Activity Near Plant for Jan-Mar 1979"
CRENS, E. H South Carolina Electric & Gas Co. 79/05/25 1p.

--7905300696 Technical rept 79-8, "Oct-Dec 1978 Seismicity Near Plant."
* South Carolina Electric & Gas Co 79/05/01 66pp

--7905300700 Technical rept 79-1, "Seismic Activity Near Plant, Jan-Mar 1979."
TALMANT, P. South Carolina Univ. of 79/05/01 26pp.

F Security, medical, emergency & fire protection plans

7905230686 Notification of 790430, 0501-03 meeting w/util. Gilbert/Commonwealth Companies & Gage-Babcock in Fairfield County, SC to visit meteorological monitoring installations & review fire protection program
TIBBITTS, D L Light Water Reactors Branch 2. 79/04/11. 3pp.

O Adjudicatory correspondence

7905290583 Dismisses intervenor B Bursley's Contentions A6 & A7; grants NRC 781003 motion for summary disposition
LINENBERGER, O A, HOOPER, F F, SMITH, I. W Atomic Safety and Licensing Board Panel 79/04/09 14pp

J Insurance & indemnity information

7905160193 Forwards Amend 1 to Indemnity Agreement B-86, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group. 79/05/01. 5pp

M Antitrust correspondence

7905030214 Motion by SC Electric & Gas to strike Central Electric & Gas 790322 brief or, in alternative, for leave to file reply.
Certificate of Svc encl.
CONNER, T B., RADER, R M Conner, Moore & Corber. 79/03/23 8pp

7905030268 Opposition to 790323 SC Electric & Gas motion to strike Requests right to answer as due process of law or as matter of right from SC move for summary disposition in two 790327 pleadings Certificate of Svc encl
BRAND, W E, HALL, E E Central Electric Power Cooperative, Inc 79/03/27 8pp

7905140137 Response of SC Electric & Gas Co in opposition to Central Electric Power Cooperative, Inc reply brief, Urges denial of latter's request for further antitrust review
Certificate of Svc & supporting documentation encl
CONNER, T. B., RADER, R M Conner, Moore & Corber 79/04/19 35pp

7905150216 Responds to reply brief of Central Electric Power Cooperative NRC should deny petition. Certificate of Svc encl
CHANANIA, F D Anti-Trust Division. 79/04/24 7pp

7905230743 Forwards corrected page to NRC 790319 response to amended petition of Central Electric Power Cooperative
CHANANIA, F. D Anti-Trust Division 79/04/24. 2pp

G Inspection reports, IE Bulletins & correspondence

7905010466 Forwards IE Insp Rept 50-395/79-07 on 790227-0301 No noncompliance noted.
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/16. 2pp

--7905010467 IE Insp Rept 50-395/79-07 on 790227-0301 No noncompliance noted Major areas inspected: mgt interview, preoperational test procedure review & plant tour.
DONAT, T. J., MARTIN, R D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/16. 2pp

7905010205 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P. Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905030317 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
O'REILLY, J P. Region 2, Atlanta, Office of the Director 79/03/26 1p.

7905240464 Forwards IE Insp Rept 50-395/79-08 on 790312-15 No noncompliance noted
MURPHY, G. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/02. 2pp.

--7905240468 IE Insp Rept 50-395/79-08 on 790312-15 No noncompliance noted. Major areas inspected: licensee action on previous Insp findings, IE bulletins & circulars, const activities & implementation of 10CFR21
BURDETTE, T E. Region 2, Atlanta, Office of the Director.
HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/30 3pp

7905090420 Ack receipt of IE Insp Rept 50-395/79-06 on 790212-14 No proprietary info
JOHNSON, M. C. South Carolina Electric & Gas Co. 79/04/11 1p.

--7905090424 Forwards IE Insp Rept 50-395/79-06 on 790212-14. No noncompliance noted.
MURPHY, G. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/22 2pp.

DOCKETED ITEMS

193

--7905090426 IE Insp Rept 50-395/79-06 on 790212-14 No noncompliance noted Major areas inspected Class A & B storage, containment prestressing QA/QC controls, quality records & const status
LENAHAN, J. J. Region 2, Atlanta, Office of the Director
BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/22 6pp

7905230605 Responds to IE Bulletin 79-04 "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp " No 3, 4 or 6-inch valves are installed or scheduled to be installed
CREWS, E. H. South Carolina Electric & Gas Co. 79/04/11 1p

7905030198 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/14 1p

7905040225 Forwards IE Bulletin 79-04B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/14 2pp.

7905040424 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/14 1p

7905010374 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts "
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/16 1p

7905030167 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/17 2pp

7905020473 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/18. 2pp

7905020475 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/18. 2pp

7905290103 Ack receipt of IE Insp Rept 50-395/79-09 on 790320-23 No proprietary info.
JOHNSON, M. C. South Carolina Electric & Gas Co. 79/04/25 1p

--7905290112 Forwards IE Insp Rept 50-395/79-09 on 790320-23 No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Office of the Director
79/04/05. 2pp

--7905290117 IE Insp Rept 50-395/79-09 on 790320-23 No noncompliance noted. Major areas inspected: instrumentation of QA procedures, work activities, quality records, electrical cables & terminations work.
O'BIBBONS, T. D., BRYANT, J. C. Region 2, Atlanta, Office of the Director 79/04/04 5pp

B. Reportable occurrences, LERs & related correspondence

7905100107 Informs that injection pumps have been removed from engines, returned to factory, inspected per newly established criteria returned to site & reinstalled engines. All injection pumps in good condition
MORIARTY, J. M. Colt Industries, Inc. 79/03/23. 1p

7905010483 Interim rept updating status of previously identified items re full penetration butt weld splices in electrical support members.
JOHNSON, M. C. South Carolina Electric & Gas Co. 79/04/23 3pp

DOCKET 50-396 UNIV. OF VIRGINIA CAVALIER REACTOR

G. Inspection reports, IE Bulletins & correspondence

7905070148 Forwards IE Bulletins 79-05, 79-05A & 79-06 re nuclear incident at TMI
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/13. 1p

DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2

A Application/construction stage documents & correspondence

7905070319 "Air Products & Chemicals, Inc Post LOCA Recombiner Test Summary "
* Washington Public Power Supply System APCI-78-B 78/07/31 175pp

7905040316 Summary of 790321 meeting of Mark II owners group in San Jose, CA re intermediate plant program tasks
ANDERSON, C. J. Containment Systems Branch 79/04/13 150pp

7905150607 Notification of 790419 meeting w/util in Bethesda, MD to discuss Chapter 7 of FSAR
LYNCH, M. D. Light Water Reactors Branch 4 79/04/13 2pp

7905010486 Repts on geological studies' status Generic rept expected in Fall 1979 Requests meeting to discuss plans for submitting repts of studies, as well as mechanism for identification & review of studies in Hanford area
RENNBERGER, D. L. Washington Public Power Supply System 79/04/27 2pp

7905240411 Forwards NRC positions on WPPSS-QA-004, "Operational QA Program Description " Response to positions should be submitted by 790501 as amend to original rept
HAASS, W. P. Quality Assurance Branch 79/05/01 2pp

7905110232 Forwards util responses to round one, set four questions from Accident Analysis Branch (Emergency Planning) re OL application
RENNBERGER, D. L. Washington Public Power Supply System 79/05/07 2pp

--7905110237 Responses by util to round one, set four questions from Accident Analysis Branch (Emergency Planning) re OL application
* Washington Public Power Supply System 79/05/04 53pp

7905190117 Proposes course of action to facilitate round two review Outlines most efficient utilization of manpower & resources at NRC, util & contractors Requests NRC to provide generic concerns for similarly-designed plants
RENNBERGER, D. L. Washington Public Power Supply System 79/05/11 4pp

7905230337 Forwards util responses to round one, set three questions from Auxiliary Sys Branch Responses will be incorporated into FSAR.
RENNBERGER, D. L. Washington Public Power Supply System 79/05/16 83pp

F Security, medical, emergency & fire protection plans

7905230795 Forwards request for addl info re physical security plan to complete review of application for OL Encl withheld (ref 10CFR2 790)
VARGA, S. A. Light Water Reactors Branch 4 79/04/05 2pp

7905080568 Forwards preliminary fire protection questions prior to site visit.
BARNES, R. D. Gage-Babcock Associates, Inc. 79/05/02 20pp

7905040601 Forwards safeguards contingency plan Plan withheld (ref 10CFR2 790)
RENNBERGER, D. L. Washington Public Power Supply System 79/05/03 2pp.

H General correspondence

7905070499 Forwards affidavit & Certificate of Svc for Amend 3 to FSAR
RENNBERGER, D. L. Washington Public Power Supply System 79/05/01 3pp.

G Inspection reports, IE Bulletins & correspondence

7905010294 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping "
ENGELKEN, R. H. Region 4, Dallas, Office of the Director. 79/03/23 1p.

7905070453 Forwards "Preservice Insp Program Plan, Vols 1 & 2."
RENNBERGER, D. L. Washington Public Power Supply System 79/03/28 2pp.

--7905070456 "Preservice Insp Program Plan, Vols 1 & 2 "
* Washington Public Power Supply System 79/01/08. 1200pp.

DOCKETED ITEMS

7905010015 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ENGELKEN, R H Region 3, San Francisco, Office of the Director
79/04/14 1p

7905040516 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ENGELKEN, R H Region 3, San Francisco, Office of the Director
79/04/14 1p

7905040625 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
ENGELKEN, R H Region 3, San Francisco, Office of the Director
79/04/14 1p

7905070110 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required
ENGELKEN, R H Region 3, San Francisco, Office of the Director
79/04/14 1p

7905030305 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required
ENGELKEN, R H Region 3, San Francisco, Office of the Director
79/04/17 1p

7905080378 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"
ENGELKEN, R H Region 3, San Francisco, Office of the Director
79/04/21 1p

7905190075 Responds to NRC 790417 ltr re violations noted in IE insp on 790227-28, 0301-02 & 14-16 Corrective actions process
instrument pipe & other parts of reactor vessel nozzle were taped
RENNBERGER, D L Washington Public Power Supply System 79/05/10, 6pp

S Reportable occurrences, LERs & related correspondence

7905150069 Forwards PNO-79-67L
ENGELKEN, R H Region 3, San Francisco, Office of the Director
79/04/06 1p

7905150173 Forwards PNO-79-67R
ENGELKEN, R H Region 3, San Francisco, Office of the Director
79/04/11 1p

7905040134 Forwards PNO-79-67S
ENGELKEN, R H Region 3, San Francisco, Office of the Director
79/04/12 1p

Forwards PNO-79-67T.
H Region 3, San Francisco, Office of the Director.
1p

1-79-67U.
on 3, San Francisco, Office of the Director.

of the Director.

ie Director

rector.

deficiency

04/23.

rector

rector

rector.

7905090121 Forwards PNO-79-67AH
ENGELKEN, R H Region 3, San Francisco, Office of the Director
79/04/27 1p

7905070034 Forwards PNO-79-67AL, AJ & AK per NRC 790401 ltr transmitting IE Bulletin 79-05
ENGELKEN, R H Region 3, San Francisco, Office of the Director
79/04/30 1p

7905090069 Forwards rept on deficient basic inflow valves used in standby gas treatment sys.
RENNBERGER, D L Washington Public Power Supply System 79/04/30 1p

--7905090073 Deficiency rept possible failure of basic inflow butterfly valves w/limitorque motor & manual operators Valve may become inoperable due to vibration All 19 valves are being repaired per manufacturer's recommendation
* Washington Public Power Supply System 79/04/30 1p

7905070018 Forwards PNO-79-67AL per NRC 790401 ltr transmitting IE Bulletin 79-05
ENGELKEN, R H Region 3, San Francisco, Office of the Director
79/05/01 1p

7905310037 Forwards PNO-79-67AM
ENGELKEN, R H Region 3, San Francisco, Office of the Director
79/05/07 1p.

DOCKET 30-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

7905240459 Notification of 790508 meeting w/util in Bethesda, MD to discuss preparation of environ rept.
BAJWA, S S. Environmental Projects Branch 2 79/04/27 1p

7905080453 Forwards oversized maps & photo attachments to util 790129 rept on main dam core trench features W/o drawings
FLOYD, S D Carolina Power & Light Co 79/05/08 5pp

7905090348 Informs of design change notices re moisture content of backfill against Category I structures & of central core matl for main & auxiliary dam & separating dike Resolution of problem will be documented in FSAR
MCBUFFIE, M A Carolina Power & Light Co 79/05/09 2pp

7905290380 Responds to Region II 790504 request for criteria used to approve previously placed backfill.
MCBUFFIE, M A Carolina Power & Light Co 79/05/18 7pp.

G Adjudicatory correspondence

7905250368 Responds to intervenors Conservation Council of NC & Wake Environ, Inc 790226 motion to remand to ABLB for further hearings &/or petition to reopen record Certificate of Svc encl
BARTH, C. A. Branch 3 79/03/16 6pp.

7905300698 Responds to 790313 request of Kudzu Alliance & W Eddleman re 790213 ALAB-526 affirming 790110 order denying series of petitions filed by intervenors Supporting documentation & Certificate of Svc encl.
TROWBRIDGE, O F. Shaw, Pittman, Potts, & Trowbridge. 79/03/21 11pp

7905230829 NRC motion to accept exhibits into evidence re mgt capability of applicant to construct & operate proposed facility Certificate of Svc encl.
BARTH, C. A. Branch 3 79/03/30 4pp

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients
SCINTO, J F Hearings Division. 79/04/02 31pp

--7905010156 Board notification staff assessment re nonsafety-grade equipment to mitigate transients.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/03/29 2pp.

--7905010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients. More info is required.
TEDESCO, R L. Assistant Director for Reactor Safety. 79/03/16 3pp.

7905080232 Applicant has no objection to NRC 790330 motion to accept into evidence Exhibits 12, 13, 14, 15, 19 & 20 from recent proceedings. Certificate of Svc encl.
TROWBRIDGE, O F. Shaw, Pittman, Potts, & Trowbridge. 79/04/04 3pp

DOCKETED ITEMS

195

- 7905250093 Forwards 790119 Press Release 79-19 re issuance of NRC policy statement on Reactor Safety Study, its review by Lewis panel & WASH-1400 use survey
BARTH, C A Branch 3 79/04/04 1p.
- 7905070216 Informs ASLB of review of natl security info re sabotage of spent nuclear fuel Forwards transmittal memo NRC assessment of significance of info to be forwarded when available
BARTH, C A Branch 3 79/04/05 2pp
- 7905220443 Forwards draft memo discussing aspects of accumulator delivery identified in NRC studies of ECCS performance characteristics NRC does not consider issue relevant to proceeding
BARTH, C A Branch 3 79/04/05 5pp
- 7905240703 Forwards memo re behavior of iodine during postulated steam generator tube rupture accidents
BARTH, C A Branch 3 79/04/05 1p
- 7905030152 Forwards NRC 781211 survey re use of WASH-1400 in licensing process
BARTH, C A Branch 3 79/04/10 90pp
- 7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Evc encl
SCINTO, J F Hearings Division 79/04/11 45pp.
- 7905140519 Response to 790404 brief of Philadelphia Electric Co, PSE&O & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Evc encl.
KEFFORD, C R Citizens for Safe Environment 79/04/11 8pp.
- 7905150562 Forwards 790330 motion All requested exhibits mentioned in motion were submitted during Raleigh, NC hearing, which respondent attended w/o encl
REIB, E J Branch 3 79/04/13 1p
- 7905140221 Forwards applicant's transcript corrections & applicant's proposed findings of fact & conclusions of law in the form of supplemental initial decision Certificate of Evc encl
TROWBRIDGE, O F Shaw, Pittman, Potts, & Trowbridge 79/04/17 3pp
- 7905140255 Lists corrections to be made in transcripts of evidentiary hearing conducted on 790227-0202 & 790306-08 in Raleigh, NC
O'NEILL, J H Shaw, Pittman, Potts, & Trowbridge 79/04/17 3pp
- 7905140261 Proposed findings of fact & conclusion of law in form of supplemental initial decision (CP). List of exhibits encl
TROWBRIDGE, O F, O'NEILL, J H Shaw, Pittman, Potts, & Trowbridge 79/04/17 54pp
- 7905290078 Gives evident error in proposed findings of fact of Carolina Power & Light Co counsel: no statement allowed by Kudzu Alliance or other parties Requests more participation be allowed
EDDLEMAN, W Kudzu Alliance 79/04/21 1p
- 7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue. Parties have until 790525 in which to file for summary disposition
DUFFLO, M E Atomic Safety and Licensing Appeal Panel 79/04/25 13pp.
- 7905240821 Comments on ASLB findings re util operating record Suggests Board condition facility OLS in light of util operating problems.
EDDLEMAN, W Affiliation Unknown. 79/04/27 2pp.
- 7905250165 Summary of 790502 Affirmation Session 79-10 in Washington, DC re BECY-A-79-20 motion to reopen hearings in Shearon Harris proceeding & BECY-79-16A, Kranish FOIA Appeal 78-A-20.
CHILK, B J Office of the Secretary of the Commission. 79/05/04 1p.
- 7905250362 Informs parties of possibility of taking official notice re test for viscosity. Objections to ASLB procedure must be filed within ten days. Supporting documentation & Certificate of Evc encl.
SMITH, I W Atomic Safety and Licensing Board Panel 79/05/10 3pp.
- 7905010168 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2PP.
- 7905030294 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/03/26 2pp.
- 7905040163 Forwards IE Bulletin 79-04B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp
- 7905040281 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p
- 7905040329 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p
- 7905010324 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts "
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp
- 7905010324 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts "
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/16 2pp
- 7905030141 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys " Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp
- 7905080325 Ack receipt of 790406 ltr informing NRC of steps taken to correct-violations noted in IE Insp Repts 50-400/79-02, 50-401/79-02, 50-402/79-01 & 50-403/79-01
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/17 1p
- 7905080330 Responds to NRC 790227 ltr re violations noted in IE Insp Repts 50-400/79-02, 50-401/79-02, 50-402/79-01 & 50-403/79-01
Corrective actions appropriate personnel instructed in document close-out procedures
HOWE, P W Carolina Power & Light Co 79/04/06 3pp
- 7905020373 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp
- 7905250015 Ack receipt of IE Insp Repts 50-400/79-06, 50-401/79-06, 50-402/79-05 & 50-403/79-05 on 790402-05 No proprietary info.
HOWE, P W Carolina Power & Light Co 79/04/26 2pp
- 7905250017 Forwards IE Insp Repts 50-400/79-06, 50-401/79-06, 50-402/79-05 & 50-403/79-05 on 790402-05 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/19 2pp
- 7905250020 IE Insp Repts 50-400/79-06, 50-401/79-06, 50-402/79-05 & 50-403/79-05 on 790402-05 No noncompliance noted M. areas inspected project status, const contract rev' licensee action on previous insp findings
BRADLEY, R D Region 2, Atlanta, Office of the Director
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/19 5p1
- R Periodic operating reports & related correspond
- 7905070473 Forwards "Seismic Monitoring Program, First
790930-790331.
MC DUFFIE, M A Carolina Power & Light Co 79/04/30
- 7905070480 "Seismic Monitoring Program, First Del
* Carolina Power & Light Co. 79/04/30, 8pp.
- B. Reportable occurrences, LERs & related correspond
- 7905140419 Informs that during 781027 site audit inspectors notified of potential reportable item: containment water proofing membrane leakage Rep not yet determined. Final decision by 781201.
CHIANG, N J Carolina Power & Light Co. 78/11
- 7905110203 Board notification Seabrook refueling design deficiency
SCINTO, J. Hearings Division 79/03/29 30pp

DOCKETED ITEMS

DOCKET 90-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

7905240499 Notification of 790508 meeting w/utl in Bethesda, MD to discuss preparation of environ rept
BAJWA, B B Environmental Projects Branch 2 79/04/27 1p

7905080453 Forwards oversized maps & photo attachments to util 781129 rept on main dam core trench features. W/o drawings
FLQYD, S D Carolina Power & Light Co 79/03/08 5pp

7905090348 Informs of design change notices re moisture content of backfill against Category I structures & of central core matl for main & auxiliary dam & separating dike Resolution of problem will be documented in FSAR
MCDUFFIE, M A Carolina Power & Light Co 79/03/09 2pp

7905290380 Responds to Region II 790304 request for criteria used to approve previously placed backfill
MCDUFFIE, M A Carolina Power & Light Co 79/03/18 7pp

G Adjudicatory correspondence

7905290368 Response to intervenors Conservation Council of NC & Wake Environ. Inc 790226 motion to remand to ASLB for further hearings &/or petition to reopen record Certificate of Svc encl
BARTH, C A Branch 3 79/03/16 6pp

7905300498 Responds to 790313 request of Kudzu Alliance & W Eddieman re 790213 ALAB-526 affirming 790110 order denying series of petitions filed by intervenors Supporting documentation & Certificate of Svc encl
TROUBRIDGE, G F Shaw, Pittman, Potts, & Trowbridge 79/08/21 11pp

7905230829 NRC motion to accept exhibits into evidence re mgt capability of applicant to const & operate proposed facility Certificate of Svc encl
BARTH, C A Branch 3 79/03/30 4pp

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients
SCINTO, J F Hearings Division 79/04/02 31pp.

--7905010136 Board notification staff assessment re nonsafety-grade equipment to mitigate transients
VASSALLO, D B Assistant Director for Light Water Reactors, 79/03/29 2pp

--7905010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients More info is required
TEDESCO, R L Assistant Director for Reactor Safety 79/03/16 3pp.

7905080232 Applicant has no objection to NRC 790330 motion to accept into evidence Exhibits 12, 13, 14, 15, 19 & 20 from recent proceedings. Certificate of Svc encl
TROUBRIDGE, G F Shaw, Pittman, Potts, & Trowbridge 79/04/04 3pp

7905250093 Forwards 790119 Press Release 79-19 re issuance of NRC policy statement on Reactor Safety Study. Its review by Lewis panel & WASH-1400 use survey.
BARTH, C A Branch 3, 79/04/04 1p

7905070216 Informs ASLB of review of matl security info re sabotage of spent nuclear fuel Forwards transmittal memo. NRC assessment of significance of info to be forwarded when available
BARTH, C A Branch 3, 79/04/05 2pp

7905220443 Forwards draft memo discussing aspects of accumulator delivery identified in NRC studies of ECCB performance characteristics NRC does not consider issue relevant to proceeding.
BARTH, C A Branch 3, 79/04/05 5pp.

7905240703 Forwards memo re behavior of iodine during postulated steam generator tube rupture accidents
BARTH, C A Branch 3, 79/04/05 1p.

7905030152 Forwards NRC 781211 survey re use of WASH-1400 in licensing process
BARTH, C A Branch 3, 79/04/10 90pp

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl.
SCINTO, J F Hearings Division 79/04/11 45pp.

7905140519 Response to 790404 brief of Philadelphia Electric Co. FSE&Q & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Svc encl
KEPFORD, C R Citizens for Safe Environment 79/04/11 8pp.

7905150562 Forwards 790330 motion All requested exhibits mentioned in motion were submitted during Raleigh, NC hearing, which respondent attended W/o encl
REIS, E J Branch 3 79/04/13 1p

7905140221 Forwards applicant's transcript corrections & applicant's proposed findings of fact & conclusions of law in the form of supplemental initial decision Certificate of Svc encl
TROUBRIDGE, G F Shaw, Pittman, Potts, & Trowbridge 79/04/17 3pp

--7905140255 Lists corrections to be made in transcripts of evidentiary hearing conducted on 790227-0302 & 790306-08 in Raleigh, NC
O'NEILL, J H Shaw, Pittman, Potts, & Trowbridge 79/04/17 3pp

--7905140261 Proposed findings of fact & conclusion of law in form of supplemental initial decision (CP) List of exhibits encl
TROUBRIDGE, G F, O'NEILL, J H Shaw, Pittman, Potts, & Trowbridge 79/04/17 54pp

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790523 in which to file for summary disposition
DUFLO, M E Atomic Safety and Licensing Appeal Panel 79/04/23 13pp

7905240821 Comments on ASLB findings re util operating record Suggests Board condition facility QIs in light of util operating problems
EDDLEMAN, W Affiliation Unknown 79/04/27 2pp

7905250165 Summary of 790302 Affirmation Session 79-10 in Washington, DC re SECY-A-79-20 motion to reopen hearings in Shearon Harris proceeding & SECY-79-16A, Kranish FOIA Appeal 78-A-20
CHILK, S J Office of the Secretary of the Commission 79/03/04 1p

7905250362 Informs parties of possibility of taking official notice re test for viscosity Objections to ASLB procedure must be filed within ten days Supporting documentation & Certificate of Svc encl
SMITH, I W Atomic Safety and Licensing Board Panel 79/03/10 3pp

G Inspection reports, IE Bulletins & correspondence

7905010168 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905030294 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/26 2pp

7905040163 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TH1 Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/04/14 2pp

7905040281 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/04/14 1p

7905040329 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TH1 Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905010324 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/04/16 2pp

7905030141 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 1p.

7905080325 Ack receipt of 790406 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-400/79-02, 90-401/79-02, 90-402/79-01 & 90-403/79-01.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 79/04/17 1p.

DOCKETED ITEMS

197

7905020373 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp

7905250015 Ack receipt of IE Insp Repts 50-400/79-06, 50-401/79-06, 50-402/79-05 & 50-403/79-05 on 790402-05. No proprietary info HOWE, P W Carolina Power & Light Co 79/04/26 2pp

--7905250017 Forwards IE Insp Repts 50-400/79-06, 50-401/79-06, 50-402/79-05 & 50-403/79-05 on 790402-05 No noncompliance noted MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/19 2pp

--7905250020 IE Insp Repts 50-400/79-06, 50-401/79-06, 50-402/79-05 & 50-403/79-05 on 790402-05 No noncompliance noted Major areas inspected project status, const contract review & licensee action on previous insp findings BRADLEY, R D Region 2, Atlanta, Office of the Director HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/19 5pp

R Periodic operating reports & related correspondence

7905070475 Forwards "Seismic Monitoring Program, First Data Rept," 770930-790331 MCDUFFIE, M A Carolina Power & Light Co. 79/04/30 1p

--7905070480 "Seismic Monitoring Program, First Data Rept," 770930-790331 * Carolina Power & Light Co. 79/04/30 8pp

S Reportable occurrences, LERs & related correspondence

7905140419 Informs that during 781027 site audit of const activities, inspectors notified of potential reportable item re containment water proofing membrane leakage Reportability not yet determined Final decision by 781201 CHITANOI, N J. Carolina Power & Light Co 78/11/22. 1p

7905110203 Board notification Seabrook refueling water storage tank design deficiency SCINTO, J Hearings Division. 79/03/29. 30pp

DOCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3

A Application/construction stage documents & correspondence

7905240459 Notification of 790508 meeting w/util in Bethesda, MD to discuss preparation of environ rept BAJWA, S B. Environmental Projects Branch 2 79/04/27. 1p

7905080453 Forwards oversized maps & photo attachments to util 781129 rept on main dam core trench features W/O drawings FLOYD, S D. Carolina Power & Light Co. 79/05/08 3pp

7905070348 Informs of design change notices re moisture content of backfill against Category I structures & of central core mat'l for main & auxiliary dam & separating dike Resolution of problem will be documented in FSAR MCDUFFIE, M. A. Carolina Power & Light Co 79/05/09 2pp

7905290380 Responds to Region II 790504 request for criteria used to approve previously placed backfill MCDUFFIE, M A. Carolina Power & Light Co. 79/05/18. 7pp.

D. Adjudicatory correspondence

7905250368 Response to intervenors Conservation Council of NC & Wake Environ, Inc 790226 motion to remand to ASLB for further hearings &/or petition to reopen record. Certificate of Svc encl. BARTH, C A Branch 3. 79/03/16 4pp.

7905300698 Responds to 790313 request of Kudzu Alliance & W Eddleman re 790213 ALAB-526 affirming 790110 order denying series of petitions filed by intervenors. Supporting documentation & Certificate of Svc encl. TROWBRIDGE, O. F. Shaw, Pittman, Potts, & Trowbridge. 79/03/21. 11pp.

7905230829 NRC motion to accept exhibits into evidence re mg't capability of applicant to const & operate proposed facility. Certificate of Svc encl. BARTH, C. A. Branch 3. 79/03/30 4pp.

--7905080330 Responds to NRC 790227 ltr re violations noted in IE Insp Repts 50-400/79-02, 50-401/79-02, 50-402/79-01 & 50-403/79-01 Corrective actions appropriate personnel instructed in document close-out procedures HOWE, P W Carolina Power & Light Co 79/04/06 3pp

7905010115 Forwards request for Board notification re non-safety-grade equipment to mitigate transients SCINTO, J F Hearings Division 79/04/02 31pp

--7905010156 Board notification staff assessment re non-safety-grade equipment to mitigate transients VASSALLO, D B Assistant Director for Light Water Reactors 79/03/29 2pp

--7905010198 Board notification recent issue on non-safety-grade equipment to mitigate transients More info is required TEDESCO, R. L. Assistant Director for Reactor Safety 79/03/16 3pp

7905080232 Applicant has no objection to NRC 790330 motion to accept into evidence Exhibits 12, 13, 14, 15, 19 & 20 from recent proceedings Certificate of Svc encl TROWBRIDGE, O. F. Shaw, Pittman, Potts, & Trowbridge 79/04/04 3pp

7905250093 Forwards 790119 Press Release 79-19 re issuance of NRC policy statement on Reactor Safety Study, its review by Lewis panel & WASH-1400 use survey BARTH, C A Branch 3 79/04/04 1p

7905070216 Informs ASLB of review of nat'l security info re sabotage of spent nuclear fuel Forwards transmittal memo NRC assessment of significance of info to be forwarded when available BARTH, C. A. Branch 3 79/04/05 2pp

7905220443 Forwards draft memo discussing aspects of accumulator delivery identified in NRC studies of ECCB performance characteristics NRC does not consider issue relevant to proceeding BARTH, C A Branch 3 79/04/05 5pp

7905240703 Forwards memo re behavior of iodine during postulated steam generator tube rupture accidents BARTH, C A Branch 3 79/04/05 1p.

7905030152 Forwards NRC 781211 survey re use of WASH-1400 in licensing process BARTH, C. A. Branch 3 79/04/10 90pp

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl SCINTO, J F Hearings Division 79/04/11 45pp

7905140519 Response to 790404 brief of Philadelphia Electric Co, PSE&Q & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Svc encl KEFFORD, C. R Citizens for Safe Environment. 79/04/11 8pp

7905130562 Forwards 790330 motion All requested exhibits mentioned in motion were submitted during Raleigh, NC hearing, which respondent attended W/O encl. REIB, E J Branch 3 79/04/13 1p

7905140221 Forwards applicant's transcript corrections & applicant's proposed findings of fact & conclusions of law in the form of supplemental initial decision Certificate of Svc encl. TROWBRIDGE, O. F. Shaw, Pittman, Potts, & Trowbridge 79/04/17. 3pp

--7905140255 hearing O'NEILL,

--7905140261 supplements TROWBRIDGE 79/04/17

7905140332 A emissions for summer DUFGLO, M. E. 13pp.

7905240821 C Board const problems. EDDLEMAN, L

DOCKETED ITEMS

7905250165 Summary of 790502 Affirmation Session 79-10 in Washington, DC re SECY-A-79-20 motion to reopen hearings in Shearon Harris proceeding & SECY-79-16A, Kranish FOIA Appeal 78-A-20
CHILK, S J Office of the Secretary of the Commission 79/05/04 1p

7905250362 Informs parties of possibility of taking official notice re test for viscosity Objections to ASLB procedure must be filed within ten days Supporting documentation & Certificate of Svc encl
SMITH, T W Atomic Safety and Licensing Board Panel. 79/05/10 3pp

G Inspection reports, IE Bulletins & correspondence

7905010168 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905030294 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/26 2pp

7905040163 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp

7905040281 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905040329 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905010324 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/16 2pp

7905030141 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 1p

7905080325 Ack receipt of 790406 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/79-02, 50-401/79-02, 50-402/79-01 & 50-403/79-01
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/17 1p.

--7905080330 Responds to NRC 790227 ltr re violations noted in IE Insp Repts 50-400/79-02, 50-401/79-02, 50-402/79-01 & 50-403/79-01
Corrective actions appropriate personnel instructed in document close-out procedures
HOWE, P W Carolina Power & Light Co. 79/04/06 3pp

7905020373 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp

7905250015 Ack receipt of IE Insp Repts 50-400/79-06, 50-401/79-06, 50-402/79-05 & 50-403/79-05 on 790402-05 No proprietary info.
HOWE, P W Carolina Power & Light Co. 79/04/26 2pp.

--7905250017 Forwards IE Insp Repts 50-400/79-06, 50-401/79-06, 50-402/79-05 & 50-403/79-05 on 790402-05 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/19 2pp.

--7905250020 IE Insp Repts 50-400/79-06, 50-401/79-06, 50-402/79-05 & 50-403/79-05 on 790402-05. No noncompliance noted Major areas inspected, project status, const contract review & licensee action on previous insp findings.
BRADLEY, R. D. Region 2, Atlanta, Office of the Director.
HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/19 5pp.

R. Periodic operating reports & related correspondence

7905070475 Forwards "Seismic Monitoring Program, First Data Rept," 770930-790331.
MC DUFFIE, M A. Carolina Power & Light Co 79/04/30. 1p

--7905070480 "Seismic Monitoring Program, First Data Rept," 770930-790331
* Carolina Power & Light Co 79/04/30 8pp

B Reportable occurrences, LERs & related correspondence

7905140419 Informs that during 781027 site audit of const activities, inspectors notified of potential reportable item re containment water proofing membrane leakage Reportability not yet determined Final decision by 781201
CHIANG, N J Carolina Power & Light Co 78/11/22 1p

7905110203 Board notification Seabrook refueling water storage tank design deficiency
SCINTO, J Hearings Division 79/03/29 30pp

DOCKET 50-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4

A Application/construction stage documents & correspondence

7905240459 Notification of 790508 meeting w/util in Bethesda, MD to discuss preparation of environ rept
BAWHA, B S Environmental Projects Branch 2 79/04/27 1p

7905080433 Forwards oversized maps & photo attachments to util 781129 rept on main dam core trench features. W/o drawings
FLOYD, S D Carolina Power & Light Co 79/05/08 5pp

7905090348 Informs of design change notices re moisture content of backfill against Category I structures & of central core matl for main & auxiliary dam & separating dike Resolution of problem will be documented in FSAR.
MC DUFFIE, M A Carolina Power & Light Co 79/05/09 2pp

7905290380 Responds to Region II 790504 request for criteria used to approve previously placed backfill
MC DUFFIE, M A Carolina Power & Light Co 79/05/18 7pp

G Adjudicatory correspondence

7905250368 Response to intervenors Conservation Council of NC & Va's Environ. Inc 790226 motion to remand to ASLB for further hearings &/or petition to reopen record Certificate of Svc encl
BARTH, C A Branch 3 79/03/16 6pp

7905300698 Responds to 790313 request of Kudzu Alliance V W Eddleman re 790213 ALAB-526 decision affirming 790110 order denying series of petitions filed by intervenors Supporting documentation & Certificate of Svc encl
TROWBRIDGE, O F Shaw, Pittman, Potts, & Trowbridge. 79/03/21 11pp

7905230829 NRC motion to accept exhibits into evidence re mgt capability of applicant to const & operate proposed facility Certificate of Svc encl
BARTH, C A Branch 3. 79/03/30 4pp

7905010113 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients
SCINTO, J F Hearings Division. 79/04/02 31pp.

--7905010156 Board notification staff assessment re nonsafety-grade equipment to mitigate transients
VASSALLO, D B Assistant Director for Light Water Reactors. 79/03/29. 2pp.

--7905010198 Board notification: recent issue on nonsafety-grade equipment to mitigate transients. More info is required.
TEDESCO, R L Assistant Director for Reactor Safety 79/03/16 3pp.

7905080232 Applicant has no objection to NRC 790330 motion to accept into evidence Exhibits 12, 13, 14, 15, 19 & 20 from recent proceeding Certificate of Svc encl.
TROWBRIDGE, O F Shaw, Pittman, Potts, & Trowbridge. 79/04/04. 3pp

7905250093 Forwards 790119 Press Release 79-19 re issuance of NRC policy statement on Reactor Safety Study, its review by Lewis panel & WASH-1400 use survey.
BARTH, C A Branch 3. 79/04/04. 1p.

7905070216 Informs ASLB of review of natl security info re sabotage of spent nuclear fuel Forwards transmittal memo NRC assessment of significance of info to be forwarded when available
BARTH, C A Branch 3. 79/04/05 2pp

7905220443 Forwards draft memo discussing aspects of accumulator delivery identified in NRC studies of ECCS performance characteristics NRC does not consider issue relevant to proceeding
BARTH, C A Branch 3 79/04/05 5pp

7905240703 Forwards memo re behavior of iodine during postulated steam generator tube rupture accidents
BARTH, C A Branch 3 79/04/05 1p

7905303132 Forwards 781211 NRC survey re use of WASH-1400 in licensing process.
BARTH, C A Branch 3 79/04/10 90pp

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl
SCINTO, J F Hearings Division 79/04/11 45pp

7905140519 Response to 790404 brief of Philadelphia Electric Co, PBE&O & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Svc encl
KEPFORD, C R Citizens for Safe Environment 79/04/11 8pp

7905130562 Forwards 790330 motion All requested exhibits mentioned in motion were submitted during Raleigh, NC hearing, which respondent attended W/o encl
REIB, E J Branch 3 79/04/13 1p

7905140221 Forwards applicant's transcript corrections & applicant's proposed findings of fact & conclusions of law in the form of supplemental initial decision Certificate of Svc encl
TROWBRIDGE, G F Shaw, Pittman, Potts, & Trowbridge 79/04/17 1p

--7905140255 Lists corrections to be made in transcripts of evidentiary hearing conducted on 790227-0302 & 790306-08 in Raleigh, NC
O'NEILL, J H Shaw, Pittman, Potts, & Trowbridge 79/04/17 3pp

--7905140261 Proposed findings of fact & conclusion of law in form of supplemental initial decision (CP) List of exhibits encl
TROWBRIDGE, G F, Shaw, Pittman, Potts, & Trowbridge 79/04/17 54pp

7905290098 Cites evident error in proposed findings of fact of Carolina Power & Light Co counsel no statement allowed by Kudzu Alliance or other parties Requests more participation be allowed
EDBLEMAN, W Kudzu Alliance 79/04/21 1p

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition
DUFLO, M E Atomic Safety and Licensing Appeal Panel. 79/04/25 13pp

7905240821 Comments on ASLB findings re util operating record Suggests Board condition facility OLS in light of util operating problems
EDBLEMAN, W Affiliation Unknown 79/04/27 2pp.

7905250165 Summary of 790502 Affirmation Session 79-10 in Washington, DC re BECY-A-79-20 motion to reopen hearings in Shearon Harris proceeding & BECY-79-16A, Kranish FOIA Appeal 78-A-20
CHILK, S J Office of the Secretary of the Commission. 79/05/04 1p

7905250362 Informs parties of possibility of taking official notice re test for viscosity Objections to ASLB procedure must be filed within 10 days. Supporting documentation & Certificate
Svc encl
SMITH, I W Atomic Safety and Licensing Board Panel 79/05/10 3pp

G Inspection reports, IE Bulletins & correspondence

7905010168 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/03/23 2pp

7905030294 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/03/26 2pp.

7905040163 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/14 2pp

7905040281 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/14 1p.

7905040329 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/14 1p.

7905010324 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/18 2pp

7905030141 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/17 1p

7905080325 Act receipt of 790406 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/79-02, 50-401/79-02, 50-402/79-01 & 50-403/79-01
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/17 1p

--7905080330 Responds to NRC 790227 ltr re violations noted in IE Insp Repts 50-400/79-02, 50-401/79-02, 50-402/79-01 & 50-403/79-01. Corrective actions appropriate personnel instructed in document close-out procedures
HOWE, P W Carolina Power & Light Co. 79/04/06 3pp

7905020373 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/18 2pp

7905250015 Act receipt of IE Insp Repts 50-400/79-06, 50-401/79-06, 50-402/79-03 & 50-403/79-03 on 790402-05. No proprietary info
HOWE, P W Carolina Power & Light Co 79/04/26 2pp

--7905250017 Forwards IE Insp Repts 50-400/79-06, 50-401/79-06, 50-402/79-03 & 50-403/79-03 on 790402-05. No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/19 2pp

--7905250020 IE Insp Repts 50-400/79-06, 50-401/79-06, 50-402/79-03 & 50-403/79-03 on 790402-05. No noncompliance noted. Major areas inspected project status, const contract review & licensee action on previous insp findings.
BRADLEY, R D Region 2, Atlanta, Office of the Director. 79/04/19 5pp

R. Periodic operating reports & related correspondence

7905070475 Forwards "Seismic Monitoring Program, First Data Rept," 770930-790331
HCUFFIE, M A Carolina Power & Light Co 79/04/30 1p

--7905070480 "Seismic Monitoring Program, First Data Rept," 770930-790331, * Carolina Power & Light Co. 79/04/30 8pp

B. Reportable occurrences, LERs & related correspondence

7905140419 Informs that during 781027 site audit of const activities, inspectors notified of potential reportable item re containment water proofing membrane leakage. Reportability not yet determined Final decision by 781201.
CHIANG, N J Carolina Power & Light Co 78/11/22 1p

7905110203 Board notification: Seabrook refueling water storage tank design deficiency
SCINTO, J Hearings Division 79/03/29 30pp.

DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3

A. Application/construction stage documents & correspondence

7905090393 Forwards info re calculating flux at various locations in reactor vessel. Flux values provided at core edge at inside radius of reactor vessel & at outside radius of reactor vessel
BOYER, R L Babcock & Wilcox Co 79/05/03 2pp.

7905110277 Advises that util position is not in accordance w/Reg Guide 1.1, "Net Positive Suction Head for ECCB & Containment Heat Removal Sys Pumps"
BROWN, S C Virginia Electric & Power Co. 79/05/08 1p.

DOCKETED ITEMS

7905220111 Defines util's nonconforming position on Reg Guide 1.35, "Concrete Placement in Category I Structures"
BROWN, S C Virginia Electric & Power Co 79/05/17 2pp

I Financial information

7905020459 Discusses SEC 790321 ltr & registration statement Util will file another statement which NRC will be able to review
DROMERICK, A W Light Water Reactors Branch 3 79/04/09 1p

--7905020466 Forwards SEC 790316 registration statement filed by util Requests comments by 790330; util wishes statement to become effective by 790402
MORIN, H F Securities & Exchange Commission 79/03/21 60pp

J Insurance & indemnity information

7905110107 Amend to Endorsement 31 to NELIA Policy NF-186 Constitutes Endorsement 34
* Nuclear Energy Liability Insurance Association 79/04/27 1p

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215, & others
GUATTROCHCHI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905110090 Endorsements 16,30,36 & 47 to NELIA Policy NF-186
BARDES, C R Nuclear Energy Liability Insurance Association 79/05/01 1p

7905300334 Forwards Endorsements 17,20 & 21 to NELIA Policy NF-240
KELLEY, P J Johnson & Higgins Insurance 79/05/23 4pp

G Inspection reports, IE Bulletins & correspondence

7905010224 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905030319 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/26 2pp

7905020133 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/11 1p

7905040234 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp

7905040271 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905040448 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905010317 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/16 2pp

7905030191 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17, 2pp

7905020502 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18, 2pp

DOCKET 50-405 NORTH ANNA POWER STATION, UNIT 4

A Application/construction stage documents & correspondence

7905090383 Forwards info re calculating flux at various locations in reactor vessel Flux values provided at core edge at inside radius of reactor vessel & at outside radius of reactor vessel
BOYER, R L Babcock & Wilcox Co 79/05/03 2pp

7905110297 Advises that util position is not in accordance w/Reg Guide 1.1, "Net Positive Suction Head for ECCB & Containment Heat Removal Sys Pumps"
BROWN, S C Virginia Electric & Power Co 79/05/08 1p.

7905220111 Defines util's nonconforming position on Reg Guide 1.35, "Concrete Placement in Category I Structures"
BROWN, S C Virginia Electric & Power Co 79/05/17 2pp

I Financial information

7905020459 Discusses SEC 790321 ltr & registration statement Util will file another statement which NRC will be able to review
DROMERICK, A W Light Water Reactors Branch 3, 79/04/09 1p

--7905020466 Forwards 790316 SEC registration statement. Requests comments by 790330; as util wishes statement to become effective by 790402
MORIN, H F. Securities & Exchange Commission 79/03/21 60pp

J Insurance & indemnity information

7905110107 Amend to Endorsement 31 to NELIA Policy NF-186 Constitutes Endorsement 34
* Nuclear Energy Liability Insurance Association 79/04/27 1p

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215, & others.
GUATTROCHCHI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905300334 Forwards Endorsements 17,20&21 to NELIA Policy NF-240
KELLEY, P J Johnson & Higgins Insurance 79/05/23 4pp

7905110090 Endorsements 16,30,36 & 47 to NELIA Policy NF-186
BARDES, C R Nuclear Energy Liability Insurance Association 79/05/01. 1p.

G Inspection reports, IE Bulletins & correspondence

7905010224 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/03/23 2pp

7905030319 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/03/26, 2pp

7905020133 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/11. 1p

7905040234 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp

7905040271 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14. 1p.

7905040448 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14. 1p

7905010317 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/16 2pp

7905030191 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/17 2pp

7905020502 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/18 2pp

DOCKET 50-406 TUSKEGEE INST RESEARCH REACTOR

J Insurance & indemnity information

7905160284 Forwards Amend 5 to Indemnity Agreement E-57, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905240675 Amend 5 to Indemnity Agreement E-57 increasing amount of coverage to \$160,000,000
SALTZMAN, J Antitrust & Indemnity Group * Tuskegee Inst
79/05/15 1p

0 Inspection reports, IE Bulletins & correspondence

7905070152 Forwards IE Bulletins 79-05, 79-05A & 79-06, re nuclear incident at TMI
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/13 1p

DOCKET 50-407 UNIV OF UTAH RESEARCH REACTOR

J Insurance & indemnity information

7905300034 Forwards Amend 10 to Indemnity Agreement E-31, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 6pp.

7905140281 Amend 10 to Indemnity Agreement E-31
SALTZMAN, J Antitrust & Indemnity Group 79/05/07 1p

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

J Insurance & indemnity information

7905160137 Forwards Amend 5 to Indemnity Agreement B-62, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group. 79/05/01 5pp.

7905110303 Forwards Amend 5 to Indemnity Agreement B-62.
LINDER, F. Duke Power Co 79/05/07 2pp

7905310337 Forwards Endorsements 31 & 32 to ANI Policy NF-217
DEVINE, H F Dairyland Power Cooperative 79/05/22 3pp

P. Operating license stage documents & correspondence

7905030332 Forwards draft rept "Review of Liquefaction Potential, LACBWR near Genoa, Vernon County, WI"
BIGH, H.; NATARAJA, M Dames & Moore 79/03/12 1p

7905100174 Notification of 790424 meeting w/util in Bethesda, MD to discuss LACBWR Cycle 5 fuel performance & reload Cycle 6.
ZIEHANN, D L. Operating Reactors Branch 2 79/04/18 1p

7905100324 Notification of 790426 meeting w/util in Silver Spring, MD to discuss Cycle 5 fuel performance & reload Cycle 6. Meeting notes new date.
METHORE, J B Operating Reactors Branch 2 79/04/18 1p

7905230399 Requests info on HFCS discharge line for systematic evaluation program review. Requests response within 15 days
ZIEHANN, D L Operating Reactors Branch 2 79/04/18 3pp

7905100132 Forwards draft evaluation of systematic evaluation program Topic IV-1 A Requests review & response within 30 days
ZIEHANN, D L Operating Reactors Branch 2 79/04/19 7pp

7905290074 Forwards list of topics deleted from systematic evaluation program review for facility
ZIEHANN, D L Operating Reactors Branch 2 79/04/19 6pp

7905040373 Forwards "Structural Analysis Design Rept for LACBWR Replacement Peripheral Shroud"
LINDER, F Dairyland Power Cooperative 79/04/30 2pp

--7905040375 "Structural Analysis Design Rept for LACBWR Replacement Peripheral Shroud"
OBLIGADO, A ; MILOS, R ; YALE, A H Nuclear Energy Service, Inc
78/11/17 60pp

7905090043 Responds to NRC 790108 ltr re ATWS requirements & recirculation pump trip designs ATWS procedures added to operating manual, operator training accomplished & recirculation pump trip design effort is in progress
LINDER, F Dairyland Power Cooperative 79/04/30 2pp

7905160425 Forwards "Cycle 5 Fuel Performance & Finalized Refueling Plan for Cycle 6," Apr 1979 Includes responses to NRC 790424 request for addl info re rod withdrawal error & other transient analyses
LINDER, F Dairyland Power Cooperative 79/05/09 21pp

--7905160427 "Cycle 5 Fuel Performance & Finalized Refueling Plan for Cycle 6," Apr 1979
RAFFETY, S J Dairyland Power Cooperative BUCK, P Nuclear Energy Service, Inc 79/04/30 25pp

7905220401 Requests amend to License DPR-45, changing Tech Specs re inservice insp program, which is in conflict w/1974 edition of ASME Section XI Supporting documentation encl
LINDER, F Dairyland Power Cooperative 79/05/11 6pp

7905290086 Ack receipt of NRC 790430 ltr re Cycle 5 fuel performance Applies for amend to provisional DL Submits proposed Tech Spec change
LINDER, F Dairyland Power Cooperative 79/05/23 6pp

7905300012 Submits application to amend provisional License DPR-45 by proposing changes to Tech Specs re off gas activity W/reply to NRC 790522 query re verification of core configuration for Cycle 6 operation
LINDER, F Dairyland Power Cooperative 79/05/23 6pp

7905300314 Requests amend to provisional DL Proposes changes re isolation of forced circulation loops & increase of operational condition for reactor vessel water level safety limits
LINDER, F Dairyland Power Cooperative 79/05/25 4pp.

7905090173 Forwards IE Insp Rept 50-409/79-03 on 790221-23 No noncompliance noted
HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/03/22 2pp

--7905090175 IE Insp Rept 50-409/79-03 on 790221-23 No noncompliance noted Major areas inspected core thermal power evaluation, control rod scram time test, comparison of calculated power shape w/incore monitor & determination of shutdown margin
CHOW, E. T ; STREETER, J F Region 3, Chicago, Reactor Operations Nuclear Support Branch CRESWELL, J S Region 3, Chicago, Office of the Director 79/03/16 4pp

7905010231 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPLER, J G Region 3, Chicago, Office of the Director 79/03/23. 1p

7905090155 Requests immediate action re implementation of 10CFR73.55 as result of 790312-14 insp & 790321 meeting. Anticipated actions withheld (ref 10CFR2 790)
KEPLER, J G Region 3, Chicago, Office of the Director 79/03/23 1p

7905040027 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPLER, J G Region 3, Chicago, Office of the Director 79/03/26 1p

7905010165 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air"
KEPLER, J G Region 3, Chicago, Office of the Director 79/03/28. 1p

DOCKETED ITEMS

- 7905010394 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/03/30 1p
- 7905290336 Responds to IE Bulletin 79-04 No check valves manufactured by Velan Engineering Corp are in use at facility
LINDER, F. Dairyland Power Cooperative 79/04/10 1p
- 7905030026 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/11 1p
- 7905010385 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/14 1p
- 7905040384 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/14 1p
- 7905040440 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/14 1p.
- 7905040553 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/14 1p
- 7905030222 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/17 1p
- 7905080490 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/04/21 1p.
- 7905240316 Requests extension until 790502 to respond to IE Bulletin 79-08 re TMI effects on BWRs.
LINDER, F. Dairyland Power Cooperative. 79/04/27 1p
- 7905240698 Responds to IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
Personnel have participated in review of TMI incident
LINDER, F. Dairyland Power Cooperative. 79/05/02. 13pp
- 7905240896 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase"
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/05/02. 1p.
- 7905290417 Responds to IE Bulletin 79-07, Forwards info re seismic stress analysis of safety-related piping.
LINDER, F. Dairyland Power Cooperative 79/05/23 16pp.
- R. Periodic operating reports & related correspondence**
- 7905090352 Forwards "Radioactive Effluent Rept & Environ Monitoring Rept" for 1978
LINDER, F. Dairyland Power Cooperative. 79/04/30 1p.
- 7905090356 "Radioactive Effluent Rept & Environ Monitoring Rept" for 1978.
* Dairyland Power Cooperative. 78/12/31 37pp
- 7905140231 Forwards monthly operating rept for Apr 1979.
LINDER, F. Dairyland Power Cooperative. 79/05/08. 1p.
- 7905140234 Monthly operating rept for Apr 1979.
PAPWORTH, L. O. Dairyland Power Cooperative. 79/05/07. 10pp.
- B. Reportable occurrences, LERs & related correspondence**
- 7905020238 Notifies of 790410 RD 79-06; fuel assembly 2-13 contains fuel rod w/ degraded cladding.
LINDER, F. Dairyland Power Cooperative 79/04/10. 1p
- 7905010504 Forwards LERs 79-005/01T-0 & 79-006/01T-0.
LINDER, F. Dairyland Power Cooperative. 79/04/19. 7pp
- 7905010510 LER 79-005/01T-0 on 790403, during refueling, insp of irradiated fuel assembly 2-13 revealed abnormal degradation in stainless steel fuel cladding of fuel rod. Caused by pellet/clad interaction Assembly will not be reused
PAPWORTH, L. O. Dairyland Power Cooperative. 79/04/19 1p
- 7905010520 LER 79-006/01T-0 on 790410 during refueling, insp of irradiated fuel assembly 2-13 revealed abnormal degradation in stainless steel fuel cladding of fuel rod. Caused by pellet/clad interaction Assembly will not be reused.
PAPWORTH, L. O. Dairyland Power Cooperative 79/04/19. 1p.
- 7905020243 RD 79-07 on 790425, abnormal degradation discovered in primary reactor containment during type B & C surveillance leakage rate testing Electrical penetration repairs started.
LINDER, F. Dairyland Power Cooperative 79/04/26 2pp
- 7905130517 Forwards LER 79-007/01T-0.
LINDER, F. Dairyland Power Cooperative. 79/05/09 4pp.
- 7905150530 LER 79-007/01T-0 on 790425 electrical penetration unit 3 & 4 did not meet Type B test criteria during periodic leakage rate testing Caused by cracked individual penetration glands Penetrations replaced & sealing compound applied
PAPWORTH, L. O. Dairyland Power Cooperative 79/05/09 1sp
- 7905250404 Forwards LER 79-005/01T-1
LINDER, F. Dairyland Power Cooperative 79/05/09. 1p.
- 7905250407 LER 79-005/01T-1 on 790403 during refueling, insp of irradiated fuel assembly 2-33 revealed abnormal degradation in fuel cladding of fuel rod Caused by pellet/clad interaction w/oxygen-assisting stress corrosion.
SHIMSHAK, R. E. Dairyland Power Cooperative. 79/04/19 1p
- DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2**
- A. Application/construction stage documents & correspondence**
- 7905040316 Summary of 790321 meeting of Mark II owners group in San Jose, CA re intermediate plant program tasks.
ANDERSON, C. J. Containment Systems Branch 79/04/13 130pp
- J Insurance & indemnity information**
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHINI, J. American Nuclear Insurers. 79/05/01 1p
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters 79/05/01 1p
- G Inspection reports, IE Bulletins & correspondence**
- 7905010123 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/03/23 1p
- 7905020071 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORIER, B. H. Region 1, Philadelphia, Office of the Director 79/04/11. 1p
- 7905020329 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
ORIER, B. H. Region 1, Philadelphia, Office of the Director 79/04/14. 1p.
- 7905040068 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p
- 7905040233 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
ORIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

7905030081 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
O'RIER, B. H. Region 1, Philadelphia, Office of the Director
79/04/17 1p

7905020292 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'RIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/18 1p

DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

790510058 Requests plant shutdown because of threat of accident as severe as rupture to reactor vessel
ROMANO, F. R. Affiliation Unknown 79/04/12 5pp.

G Adjudicatory correspondence

7905100267 Forwards CP amend request for extension of expiration date to 841231
DUNN, C. N. Duquesne Light Co 79/05/09 2pp

--7905100269 Application for amend of CFP-105 to extend const completion date to 841231
DUNN, C. N. Duquesne Light Co 79/05/09 4pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHHI, J. American Nuclear Insurers 79/05/01 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. H. Mutual Atomic Energy Liability Underwriters. 79/05/01 1p.

Q. Inspection reports, IE Bulletins & correspondence

7905010106 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'RIER, B. H. Region 1, Philadelphia, Office of the Director.
79/03/23 1p.

7905020043 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'RIER, B. H. Region 1, Philadelphia, Office of the Director
79/04/11. 1p

7905020398 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
O'RIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/14 1p.

7905040014 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'RIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/14 1p.

7905040200 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
O'RIER, B. H. Region 1, Philadelphia, Office of the Director
79/04/14 1p.

7905030063 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
O'RIER, B. H. Region 1, Philadelphia, Office of the Director
79/04/17. 1p

7905010645 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'RIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/18. 1p.

B. Reportable occurrences, LERs & related correspondence

7905100103 Informs that injection pumps have been removed from engines, inspected per newly established criteria & reinstalled on engines. All injection pumps in good condition.
MORIARTY, J. M. Colt Industries, Inc. 79/03/23 1p.

7905010541 Forwards 790329 initial interim rept on Significant Deficiency 79-01 re Birgham-Hillamette Co stop work directive Possibility of significant deficiency reported on 790330 Final rept to be issued by 790604.
MOOLEVER, E. J. Duquesne Light Co 79/04/25 1p

--7905010551 Interim rept on Significant Deficiency 79-01 re Birgham-Hillamette Co stop work directive for quench spray, recirculation spray & auxiliary feedwater pumps Describes QA problem & corrective action.
* Duquesne Light Co 79/04/25 2pp

DOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

7905100435 Act receipt of 790321 ltr forwarding OL application Acceptance review to determine completeness has begun
VARDA, S. A. Light Water Reactors Branch 4. 79/04/25 3pp.

7905190100 Forwards info in response to request for approval of flexible hoses in const of Class II & III piping
DAIL, L. C. Duke Power Co 79/05/18 5pp.

--7905190101 "Documentation of Compliance of Metal Bellows Corp Part 76863 to Requirements of ASME Section III N D3649 for Use in Class II & Class III Piping."
* Duke Power Co. 79/02/26 8pp

--7905190103 "Documentation of Compliance of Metal Bellows Corp Part 76864 to Requirements of ASME Section III N D3649 for Use in Class II & Class III Piping."
* Duke Power Co. 79/02/26 8pp

--7905190104 "Documentation of Compliance of Metal Bellows Corp Part 76865 to Requirements of ASME Section III N D3649 for Use in Class II & Class III Piping."
* Duke Power Co 79/02/26 8pp.

--7905190106 "Design Rept for House Assembly, Flexible Metal," prepared by Metal Bellows Corporation ABME Boiler & Pressure Vessel Code Section III, Subsection NC/ND, Classes II & III
* Duke Power Co 79/02/23. 50pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. H. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p

Q. Inspection reports, IE Bulletins & correspondence

7905010183 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/03/23 2pp

7905030301 Forwards IE Info Notice 79-07, "Rupture of Radwa
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/26. 2pp.

7905040185 Forwards IE Bulletin 79-06B, "Review of Operational Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/14 2pp.

7905040266 Forwards IE Bulletin 79-07, "Seismic Stress Analysis Safety-Related Piping." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/14. 2pp.

7905040346 Forwards IE Bulletin 79-08, "Events Relevant to B Water Power Reactors Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/14. 1p.

7905010356 Forwards IE Info Notice 79-10, "Nonconforming Pipe Struts."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/14. 1p.

DOCKETED ITEMS

7905030153 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys " Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director.
79/04/17, 2pp

7905020453 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/18 2pp

7905140162 Ack receipt of 790419 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/79-04 & 50-414/79-04
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/30 1p

--7905140167 Responds to NRC 790322 ltr re violations noted in IE Insp Repts 50-413/79-04 & 50-414/79-04. Corrective actions weld identifications on both mats & tags were corrected Piping stored correctly
DAIL, L C Duke Power Co 79/04/19 3pp

DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7905190100 Forwards info in response to request for approval of flexible hoses in const of Class II & III piping
DAIL, L C Duke Power Co 79/05/18 5pp

--7905190101 "Documentation of Compliance of Metal Bellows Corp Part 76863 to Requirements of ASME Section III N D3649 for Use in Class II & Class III Piping "
* Duke Power Co 79/02/26 8pp

--7905190103 "Documentation of Compliance of Metal Bellows Corp Part 76864 to Requirements of ASME Section III N D3649 for Use in Class II & Class III Piping "
* Duke Power Co 79/02/26 8pp

--7905190104 "Documentation of Compliance of Metal Bellows Corp Part 76865 to Requirements of ASME Section III N D3649 for Use in Class II & Class III Piping "
* Duke Power Co. 79/02/26, 8pp.

--7905190106 "Design Rept for House Assembly, Flexible Metal," prepared by Metal Bellows Corp, per ASME Boiler & Pressure Vessel Code Section III, Subsection NC/NB, Classes II & III
* Duke Power Co 79/02/23 30pp.

7905100435 Ack receipt of 790321 ltr forwarding OL application. Acceptance review to determine completeness has begun.
VARCA, B A. Light Water Reactors Branch 4 79/04/23 3pp

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATROCHHI, J. American Nuclear Insurers 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 84, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p.

G Inspection reports, IE Bulletins & correspondence

7905010183 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/03/23 2pp.

7905030301 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks "
O'REILLY, J P. Region 2, Atlanta, Office of the Director.
79/03/26, 2pp

7905040185 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/04/14, 2pp

7905040266 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 2pp

7905040346 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident "
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14. 1p

7905010356 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts "
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/16 1p

7905030153 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys " Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/17 2pp

7905020453 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident "
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/18 2pp

7905140162 Ack receipt of 790419 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/79-04 & 50-414/79-04
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/30 1p

--7905140167 Responds to NRC 790322 ltr re violations noted in IE Insp Repts 50-413/79-04 & 50-414/79-04. Corrective actions weld identifications on both mats & tags were corrected Piping stored correctly
DAIL, L.C. Duke Power Co 79/04/19 3pp.

DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905100431 Forwards first round request for addl info re sys analysis for FBAR review.
STOLZ, J F Light Water Reactors Branch 1. 79/04/25. 4pp

H General correspondence

7905080450 Forwards affidavit of svc re distribution of Amend 29, per encl to NRC 780627 ltr
DALE, L F. Mississippi Power & Light Co 79/04/30 2pp

K Utility Final Safety Analysis Report (FSAR) & amends

7905300439 Forwards Amend 30 to FSAR & schedule for completing outstanding first round questions
STAMPLEY, N L Mississippi Power & Light Co 79/05/25. 4pp

--7905300441 Amend 30 to FSAR Copies of plant area drainage drawings, equipment test plans & response spectra curves available in Central Files
* Mississippi Power & Light Co 79/05/25. 2000pp

G. Inspection reports, IE Bulletins & correspondence

7905010204 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping "
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/03/23 2pp.

7905030314 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/03/26. 1p.

7905040223 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/04/14. 1p.

7905040312 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/04/14. 1p.

DOCKETED ITEMS

205

7905040420 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14, 1p

7905010371 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/16 1p

7905030167 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/17 2pp

7905020472 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J P Region 2, Atlanta, Office of the Director.
79/04/18 2pp

7905290061 Ack receipt of IE Insp Repts 50-416/79-01 & 50-417/79-01 on 790123-26 No proprietary info
MCOAUGHY, J P. Mississippi Power & Light Co 79/04/18, 1p

7905040636 Responds to NRC 790322 ltr re violations noted in IE Insp Repts 50-416/79-02 & 50-417/79-02 Corrective actions Bechtel quality action request issued on welding electrodes found in drywell area & supervisors instructed in rod control duties
MCOAUGHY, J P Mississippi Power & Light Co. 79/04/23 2pp

8 Reportable occurrences, LERs & related correspondence

7905140339 Forwards final deficiency rept for weld separation on strut type hanger matl
MCOAUGHY, J P Mississippi Power & Light Co. 79/03/22 1p.

--7905140340 Final rept on potentially Reportable Deficiency 78/03 investigation by Bechtel revealed factory weld separation on Unistrut Part P1001 matl. All spot welds, except one lot, meet required safety factors Unacceptable lot isolated
* Mississippi Power & Light Co 79/03/22, 1p.

7905020455 Interim rept on potentially reportable deficiency re circuit separation discrepancies in power generation control complexes. Final rept will be submitted by 790620
MCOAUGHY, J P Mississippi Power & Light Co 79/03/23 1p

7905140354 Informs of potential Reportable Deficiency 79/05 improper drawings supplied by OE. Reportability is being determined; final rept will be issued by 790531
MCOAUGHY, J P Mississippi Power & Light Co 79/03/27 1p.

7905250373 Informs of possible defective matl shipment purchased from Tube Turns & shipped to Bechtel Power. Manufacturer's recall notice encl.
REILLY, M K Liberty Equipment & Supply Co 79/04/04 5pp

7905040510 Informs that deficiency reported on 790323 re failure of solid state trip devices was caused by inadequate or incomplete older joints on printed circuit boards. Boards returned to vendor for analysis.
MCOAUGHY, J P. Mississippi Power & Light Co 79/04/23, 1p

7905040631 Interim Rept 1 for potentially reportable Deficiency 79-07 re circuit separation discrepancies. Final rept will be submitted by 790620.
MCOAUGHY, J P Mississippi Power & Light Co N 79/04/23 1p

DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905100431 Forwards first round request for addl info re sys analysis for FSAR review.
STOKLZ, J F. Light Water Reactors Branch 1 79/04/25, App.

H General correspondence

7905080430 Forwards affidavit of svc re distribution of Amend 29, per encl to NRC 780627 ltr.
DALE, L. F. Mississippi Power & Light Co. 79/04/30 2pp.

K Utility Final Safety Analysis Report (FSAR) & amends

7905000439 Forwards Amend 30 to FSAR & schedule for completing outstanding first round questions.
BAMFLEY, N L Mississippi Power & Light Co. 79/05/25, App

--790530044, Amend 30 to FSAR Copies of plant area drainage drawing, equipment test plans & response spectra curves available in Central Files
* Mississippi Power & Light Co 79/05/25 2000pp

G Inspection reports, IE Bulletins & correspondence

7905010204 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/03/23 2pp

7905030314 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/03/26 1p

7905040223 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 1p

7905040312 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 1p

7905040420 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 1p

7905010371 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/16 1p

7905030167 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/17 2pp

7905020472 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/18 2pp

7905290061 Ack receipt of IE Insp Repts 50-416/79-01 & 50-417/79-01 on 790123-26 No proprietary info
MCOAUGHY, J P Mississippi Power & Light Co 79/04/18 1p

7905040636 Responds to NRC 790322 ltr re violations noted in IE Insp Repts 50-416/79-02 & 50-417/79-02 Corrective actions Bechtel quality action request issued on welding electrodes found in drywell area & supervisors instructed in rod control duties
MCOAUGHY, J P Mississippi Power & Light Co 79/04/23 2pp

B. Reportable occurrences, LERs & related correspondence

7905140339 Forwards final deficiency rept for weld separation on strut type hanger matl
MCOAUGHY, J P Mississippi Power & Light Co 79/03/22 1p

--7905140340 Final rept on potentially Reportable Deficiency 78/03 investigation by Bechtel revealed factory weld separation on Unistrut Part P1001 matl. All spot welds, except one lot, meet required safety factors Unacceptable lot isolated
* Mississippi Power & Light Co 79/03/22 1p

7905020455 Interim rept on potentially reportable deficiency re circuit separation discrepancies in power generation control complexes. Final rept will be submitted by 790620
MCOAUGHY, J P Mississippi Power & Light Co 79/03/23 1p

7905140354 Informs of potential Reportable Deficiency 79/05 improper drawings supplied by OE. Reportability is being determined; final rept will be issued by 790531.
MCOAUGHY, J P Mississippi Power & Light Co. 79/03/27, 1p

7905250373 Informs of possible defective matl shipment purchased from Tube Turns & shipped to Bechtel Power. Manufacturer's recall notice encl
REILLY, M K Liberty Equipment & Supply Co 79/04/04, 5pp

7905040510 Informs that deficiency reported on 790323 re failure of solid state trip devices was caused by inadequate or incomplete older joints on printed circuit boards. Boards returned to vendor for analysis.
MCOAUGHY, J P. Mississippi Power & Light Co 79/04/23 1p

DOCKETED ITEMS

7905040631 Interim Rept 1 for potentially reportable Deficiency 79-07 re circuit separation discrepancies. Final rept will be submitted by 790620
MCGAUGHY, J P Mississippi Power & Light Co N 79/04/23. 1p.

DOCKET 50-423 HILLSTONE NUCLEAR POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

7905150439 Forwards draft application for extension of CPPR-113 to Nov 1985
FOSTER, E.R Northeast Utilities 79/03/09 5pp

J. Insurance & indemnity information

7905140422 Forwards Amend 14 to Indemnity Agreement B-39 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/03/01 6pp

7905190075 Forwards executed Amend 14 to Indemnity Agreement B-39
O'CONNOR, L.A Northeast Utilities 79/03/13 4pp.

G. Inspection reports, IE Bulletins & correspondence

7905101021 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
ORIER, B.H Region 1, Philadelphia, Office of the Director 79/03/23 1p

7905100033 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/BVC Air Sys Used as Source of Breathing Air."
ORIER, B.H Region 1, Philadelphia, Office of the Director 79/03/28 1p

7905101034 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."
ORIER, B.H Region 1, Philadelphia, Office of the Director. 79/03/30 2pp.

7905020066 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B.H Region 1, Philadelphia, Office of the Director. 79/04/11 1p

7905020300 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
ORIER, B.H Region 1, Philadelphia, Office of the Director. 79/04/14 1p.

7905040039 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B.H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905040214 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
ORIER, B.H Region 1, Philadelphia, Office of the Director. 79/04/14 1p

7905030077 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required
ORIER, B.H Region 1, Philadelphia, Office of the Director. 79/04/17 1p.

7905020284 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B.H Region 1, Philadelphia, Office of the Director. 79/04/18 1p.

B. Reportable occurrences, IERs & related correspondence

7905100099 Informs of completion of analysis of injection pump failures. Failures were result of surface irregularities on barrel &/or plunger, incorrect matl, &/or new pumps. Pumps removed from facility.
MORIARTY, J.M. Colt Industries, Inc. 79/03/22 1p.

DOCKET 50-424 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7905020241 Informs that spare multipoint discharge diffuser will not be installed. Evaluation at other operating plants indicates no need for addl diffuser.
EHRENSPERGER, W Georgia Power Co. 79/04/25 2pp

7905230398 Submits clarification of use of 91-day compressive strength concrete specified in const spec versus 28-day compressive strength concrete referenced in PSAR Section 3.8 Requests prompt concurrence.
EHRENSPERGER, W Georgia Power Co 79/03/11 8pp

D Adjudicatory correspondence

7905150080 Denies 781031 request by Georgians Against Nuclear Power to suspend CP.
BOYD, R.B Office of Nuclear Reactor Regulation 79/04/13. 3pp

7905240201 Forwards denial of suspension of facility CP. Supporting documentation encl.
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/04/13 1pp

--7905240211 Director's denial of 10CFR2.206 request
BOYD, R.B. Office of Nuclear Reactor Regulation. 79/04/13. 8pp

--7905240219 Analysis of need for facility
Division of Site Safety & Environmental Analysis. 79/04/13 5pp.

--7905240227 Responds to RW Froelich 781207 request Forwards mail on Georgians Against Nuclear Energy request to suspend facility CP
WHITMER, C.F Georgia Power Co. 78/12/19. 13pp

--7905240232 TX PIRO's motion for admission of 781101 addl Contention 1
SCOTT, J.M. Texas Public Interest Research Group. 79/03/22 3pp

7905300392 Denies 781031 request of Georgians Against Nuclear Power to suspend CP issued to OA Power Co & to hold hearings re alleged new evidence
BOYD, R.B. Division of Project Management 79/04/13. 2pp

7905150075 Forwards 790413 ltr denying Georgians Against Nuclear Energy request to suspend CP. Also forwards FR notice of denial.
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/04/19 2pp.

7905240918 Orders extension of time for NRC to review Ofc of Nuclear Reactor Regulation 790405 denial of request for enforcement action
CHILK, B.J. Office of the Secretary of the Commission 79/04/30 1p.

I. Financial information

7905080477 Forwards "Annual Financial Rept 1978."
VASQUEZ, R.D Metropolitan Electric Authority of Georgia. 79/05/02 1p

--7905080508 "Annual Financial Rept 1978."
Metropolitan Electric Authority of Georgia. 78/12/31. 2pp

J. Insurance & indemnity information

7905070477 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHI, J. American Nuclear Insurers. 79/05/01. 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D.M Mutual Atomic Energy Liability Underwriters. 79/05/01 1p.

DOCKETED ITEMS

207

G Inspection reports, IE Bulletins & correspondence

7905010200 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905030312 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks" O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/26 2pp

7905040216 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 2pp

7905040304 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 1p

7905040413 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident" O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 1p

7905010366 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts." O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/16 1p

7905030165 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/17 2pp

7905020467 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/18 2pp

7905240489 Ack receipt of IE Insp Repts 50-424/79-05 & 50-425/79-05 on 790326-29. No proprietary info. STAFFA, R. W. Georgia Power Co 79/05/03 1p.

--7905240500 Forwards IE Insp Repts 50-424/79-05 & 50-425/79-05 on 790326-29 No noncompliance noted. MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/10 2pp

--7905240509 IE Insp Repts 50-424/79-05 & 50-425/79-05 on 790326-29. No noncompliance noted. Major areas inspected: const status, concrete procedures & specs, concrete placement & records & action on previously identified items. HARRIS, J. R. Region 2, Atlanta, Office of the Director. BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/10 4pp.

DOCKET 50-425 ALVIN W. VOOTLE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

7905020241 Informs that spare multipoint discharge diffuser will not be installed. Evaluation at other operating plants indicates no need for addl diffuser. EHRENSPERGER, W. Georgia Power Co. 79/04/25 2pp

7905230398 Submits clarification of use of 91-day compressive strength concrete specified in const spec versus 28-day compressive strength concrete referenced in PSAR Section 3.8. Requests prompt concurrence. EHRENSPERGER, W. Georgia Power Co. 79/05/11 8pp.

G Adjudicatory correspondence

7905150080 Denies 781031 request by Georgians Against Nuclear Power to suspend CP. BOYD, R. B. Office of Nuclear Reactor Regulation. 79/04/13 2pp.

7905240201 Forwards denial of suspension of facility CP. Supporting documentation encl DENTON, H. R. Office of Nuclear Reactor Regulation. 79/04/13 1pp.

--7905240211 Director's denial of 10CFR2.206 request. BOYD, R. B. Office of Nuclear Reactor Regulation. 79/04/13 8pp.

--7905240219 Analysis of need for facility * Division of Site Safety & Environmental Analysis 79/04/13 3pp.

--7905240227 Responds to RW Froslich 781207 request. Forwards matl on Georgians Against Nuclear Energy request to suspend facility CP WHITMER, C. F. Georgia Power Co. 78/12/19 13pp.

--7905240232 TX PIRO's motion for admission of 781101 addl Contention 1 SCOTT, J. M. Texas Public Interest Research Group 79/03/22 3pp.

7905300392 Denies 781031 request of Georgians Against Nuclear Power to suspend CP issued to GA Power Co & to hold hearings re alleged new evidence BOYD, R. B. Division of Project Management. 79/04/13 2pp.

7905150075 Forwards 790413 ltr denying Georgians Against Nuclear Energy request to suspend CP. Also forwards FR notice of denial. DENTON, H. R. Office of Nuclear Reactor Regulation 79/04/19 2pp.

7905240918 Orders extension of time for NRC to review Ofc of Nuclear Reactor Regulation 790405 denial of request for enforcement action CHILK, S. J. Office of the Secretary of the Commission 79/04/30 1p

I. Financial information

7905080497 Forwards "Annual Financial Rept 1978." VASQUEZ, R. O. Metropolitan Electric Authority of Georgia. 79/05/02 1p.

--7905080508 "Annual Financial Rept 1978." * Metropolitan Electric Authority of Georgia 78/12/31 24pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others. GUATTROCHCHI, J. American Nuclear Insurers. 79/05/01 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96. ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01 1p.

G Inspection reports, IE Bulletins & correspondence

7905010200 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping." O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/23 2pp.

7905030312 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/26 2pp

7905040216 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 2pp

7905040304 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14 1p.

7905040413 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14 1p.

7905010366 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/16 1p.

7905030165 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/17 2pp.

DOCKETED ITEMS

7905020467 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director.
79/04/18. 2pp

7905240489 Ack receipt of IE Insp Repts 50-424/79-05 & 50-425/79-05 on 790326-29 No proprietary info
STAFFA, R W Georgia Power Co 79/03/03 1p

--7905240500 Forwards IE Insp Repts 50-424/79-05 & 50-425/79-05 on 790326-29 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/10 2pp

--7905240509 IE Insp Repts 50-424/79-05 & 50-425/79-05 on 790326-29 No noncompliance noted Major areas inspected const status, concrete procedures & specs, concrete placement & records & action on previously identified items
HARRIS, J R Region 2, Atlanta, Office of the Director
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/10 4pp

DOCKET 50-426 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 3

I Financial information

7905080497 Forwards "Annual Financial Rept 1978"
VASQUEZ, R D Metropolitan Electric Authority of Georgia 79/05/02 1p

--7905080508 "Annual Financial Rept 1978"
* Metropolitan Electric Authority of Georgia 78/12/31 24pp

DOCKET 50-427 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 4

I Financial information

7905080497 Forwards "Annual Financial Rept 1978"
VASQUEZ, R D Metropolitan Electric Authority of Georgia 79/05/02 1p.

--7905080508 "Annual Financial Rept 1978"
* Metropolitan Electric Authority of Georgia 78/12/31 24pp

DOCKET 30-430 ASCO, UNIT 1

I. Hearing transcripts on non-Antitrust matters

7905140086 Statement of C Walste, President, Atomic Industrial Forum, Inc before Subcommittee on Nuclear Regulation of Senate Committee on Environ & Public Works.
WALSTE, C. Atomic Industrial Forum 79/04/23 5pp

DOCKET 50-433 UC-SANTA BARBARA RESEARCH REACTOR

J Insurance & indemnity information

7905140219 Forwards Amend 4 to Indemnity Agreement E-5B, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790901 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01. 3pp

50-437 FLOATING NUCLEAR PLANT

Construction stage documents & correspondence

REG-0531, "Investigation & Evaluation of Stress in Piping of LWR Plants" & notice of ity w/o encl.
istant Director for Light Water Reactors.

chnical staff be informed that longer holdup re should be required to avoid to ocean & air.
Resources Defense Council 79/04/09. 1p

Review of OPS Rept 7270-RP-16A51, Buckling ing Nuclear Plant," draft Revision B, & Application of Criteria to Design of all.
of Nuclear Reactor Regulation. 79/04/17. 1p

--7905030034 Requests repts "Buckling Criteria & Application of Criteria to Design of Steel Containment Shell" & "Review of OPS Rept 7270-RP-16A51"
BDSMAN, A Z Natural Resources Defense Council 79/03/27 1p

--7905030042 "Review of OPS Rept 7270-RP-16A51, Buckling Criteria & Application of Criteria to Preliminary Design of Steel Containment Shell for Floating Nuclear Power Plant,"
Revision B, 780501
* International Structural Engineers, Inc NRC-03-77-131 79/03/31 32pp

--7905030051 "Buckling Criteria & Application of Criteria to Design of Steel Containment Shell"
HASRI, B F, BEIDE, P, WEINGARTEN, V I International Structural Engineers, Inc NRC-03-77-131 79/03/31 106pp

7905240108 Notification of 790507-08 meetings w/Harblson-Walker Refractories, OPS & NRC consultant to discuss Harblson-Walker's experience w/magnesium oxide refractories & OPS' floating nuclear plant core ladle
BIRKEL, R A Light Water Reactors Branch 2 79/04/20 4pp

7905030339 Forwards list of items to be addressed by Harblson & Walker Refractories & OPS at 790507-08 meeting in Jacksonville, FL.
SHANSON, D Q Aerospace Corp 79/04/24 5pp

7905040133 Forwards Amend 27 to plant design rept re cancellation of PSE& Q contract, incorporation of refractory ladle & recommendations of NRC consultant re containment shell buckling analysis
HAGA, P B Offshore Power Systems (subs of Westinghouse Electric Corp.) 79/04/30 121pp

7905190112 Discusses current activities of product assurance organization review & approval of drawings & spec seeks to obtain mfg license & customers as soon as possible & approve drawings & specifications
HAGA, P B Offshore Power Systems (subs of Westinghouse Electric Corp.) 79/05/11 2pp

7905220022 Forwards errata sheet to correct errors in Amend 27 to 790430 plant design rept
HAGA, P B Offshore Power Systems (subs of Westinghouse Electric Corp.) 79/05/14. 7pp

7905310455 Forwards "Buckling Criteria & Application of Criteria to Preliminary Design of Steel Containment Shell for Floating Nuclear Power Plant," Revision B.
HAGA, P B Offshore Power Systems (subs of Westinghouse Electric Corp.) 79/05/23. 1p

--7905310458 "Buckling Criteria & Application of Criteria to Preliminary Design of Steel Containment Shell for Floating Nuclear Plant," Revision B
* Offshore Power Systems (subs of Westinghouse Electric Corp.) 7270-RP-16A51 79/05/31. 350pp

O Adjudicatory correspondence

7905250313 Statement of matl facts which are not in dispute, Applicant not able to build eight plants by 1985, Statement filed in opposition to NRDC statement of matl facts
HAGA, P B, NUTANT, J. A. Offshore Power Systems (subs of Westinghouse Electric Corp.) 79/03/08 7pp

7905250290 Identification of evidence for 790404 hearing, submitted in response to ASLB 790312 order, Professional qualifications of TW Philbin encl.
CONAN, B. Z., DOUGHERTY, T. M., KENDRICK, J. R. Offshore Power Systems (subs of Westinghouse Electric Corp.) 79/03/23 6pp

7905250177 Responds to ASLB 790315 ltr re applicant's plans for conveyance of reactor pressure vessel to site Applicant will not channelize either Brazos River or San Bernard River. Willing to begin responding to discovery motions.
COPELAND, J O, Baker & Botts. 79/03/27. 2pp

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients.
SCINTO, J. F. Hearings Division. 79/04/02. 31pp

DOCKETED ITEMS

209

--7905010155 Board notification staff assessment re nonsafety-grade equipment to mitigate transients
VASSALLO, D B Assistant Director for Light Water Reactors
79/03/29 2pp

--7905010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients More info is required
TEDESCO, R L Assistant Director for Reactor Safety 79/03/16
3pp

7905160039 Discusses effects of TMI on hearing schedules; lists proceedings scheduled from Apr through June Forwards questions to be answered at 790404 hearing
REIB, E. J. Branch 3 79/04/03 2pp

--7905160045 Lists questions to be answered at 790404 hearing re liquid pathway generic study & FES
WOLFE, B Atomic Safety and Licensing Board Panel 79/03/29 2pp

7905080184 Replies to applicant & NRC opposition to motion for summary disposition Opposes applicant motion for summary disposition Certificate of Svc encl
ROISHAN, A Z Natural Resources Defense Council 79/04/06 14pp

--7905080202 Statement of matl facts in dispute to applicant motion for summary disposition. Supporting affidavit & resume of TB Cochran encl
ROISHAN, A Z Natural Resources Defense Council 79/04/06 10pp

7905250292 No comment on proposed schedule submitted by applicant. If all proposed findings of fact & conclusions of law re NRDC contention are filed after completion of Board action & hearings on contention.
ROISHAN, A Z Natural Resources Defense Council 1 79/04/09 3pp

7905180125 Forwards NRC rept "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Grid Serving St Lucie"
SCHINK, B. M Branch 3 79/04/11. 1p

--7905180130 "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Grid Serving St Lucie"
MCNIERNAN, T. J Office of Inspector & Auditor 78/06/30 85pp

7905180677 Ack receipt of 790411 ltr transmitting rept of investigation in connection w/St Lucie proceeding Requests Board be advised of any relevance to proceeding.
WOLFE, B. J Atomic Safety and Licensing Board Panel 79/04/12. 1p

7905100122 Informs that written responses to ASLB 790329 ltr are being delayed; NRC staff originally assigned to work on response are presently involved at TMI-2
SCHINK, B. M Branch 3 79/04/17 1p

H General correspondence

7905230625 Expresses concern about safety of floating nuclear power plants, due to unpredictability of weather & oceanic conditions
TOOHER, J L Affiliation Unknown. 79/04/08. 1p

Q. Inspection reports, IE Bulletins & correspondence

7905010158 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/03/23 1p

7905030323 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/26. 1p

7905030188 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/14. 1p.

7905040145 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/14. 1p

7905040457 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/14. 1p

7905030133 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/17 1p

7905140093 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/18 1p

B Reportable occurrences, LERs & related correspondence

7905110203 Board notification Seabrook refueling water storage tank design deficiency
SCINTO, J Hearings Division 79/03/29 30pp

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

7905300376 Notifies that radiological safety review schedule has been reevaluated & revised New schedule encl
PARR, O D Light Water Reactors Branch 3 79/04/30 3pp

7905310461 Forwards request for info re initial test program
PARR, O D Light Water Reactors Branch 3 79/05/01 16pp

7905110225 Approval of Tefzel 200 as snubber matl requiring surveillance interval no more stringent than that required for ethylene propylene equipped snubbers
GILLELAND, J. E Tennessee Valley Authority 79/05/04 21pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHI, J American Nuclear Insurers 79/05/01 1p

7905070982 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D. M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

Q Inspection reports, IE Bulletins & correspondence

7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/23 2pp

7905030368 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/14. 3pp

7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/14. 3pp

7905110365
Water Po
O'REILLY
79/04/14

7905010341
Struts "
O'REILLY
79/04/14

7905030171
Circuit
require
O'REILLY
79/04/14

790502047
Operati
Inciden
O'REILLY
79/04/14

DOCKETED ITEMS

7905300253 Submits supplemental response to IE Bulletin 77-07. Original response submitted 780120. Provides addl info received from manufacturer & describes plans in area of electrical penetrations
GILLELAND, J E Tennessee Valley Authority 79/04/27 5pp

B. Reportable occurrences, LERs & related correspondence

7905230348 Forwards second interim rept of tensile anchor capacities lower than design allowables.
GILLELAND, J E Tennessee Valley Authority 79/05/17 1p

--7905230357 Second interim rept tensile anchor capacities lower than assumed in design allowables Testing of stud anchors still in progress Final results expected 790801.
* Tennessee Valley Authority. 79/05/17 1p.

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7905300376 Notifies that radiological safety review schedule has been reevaluated & revised New schedule encl
PARR, O D Light Water Reactors Branch 3 79/04/30 3pp

7905310461 Forwards request for info re initial test program
PARR, O D Light Water Reactors Branch 3 79/05/01 16pp.

7905110225 Approval of Tefzel 200 as snubber matl requiring surveillance interval no more stringent than required for ethylene propylene equipped snubbers
GILLELAND, J E Tennessee Valley Authority 79/05/04 21pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATROCHINI, J American Nuclear Insurers. 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p.

G. Inspection reports, IE Bulletins & correspondence

7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/23 2pp.

7905030368 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14 3pp.

7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 3pp

7905110365 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14. 1p

7905010341 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/18. 1p.

7905030172 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/17. 2pp.

7905020479 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/18. 2pp.

7905300253 Submits supplemental response to IE Bulletin 77-07. Original response submitted 780120. Provides addl info received from manufacturer & describes plans in area of electrical penetrations
GILLELAND, J E Tennessee Valley Authority 79/04/27. 5pp.

B. Reportable occurrences, LERs & related correspondence

7905230348 Forwards second interim rept of tensile anchor capacities lower than design allowables
GILLELAND, J E Tennessee Valley Authority. 79/05/17. 1p.

--7905230357 Second interim rept tensile anchor capacities lower than assumed in design allowables Testing of stud anchors still in progress Final results expected 790801
* Tennessee Valley Authority 79/05/17 1p

DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7905020424 Forwards NUREG-0531, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability W/o encl
VASSALLO, D B Assistant Director for Light Water Reactors 79/03/23 2pp

G. Inspection reports, IE Bulletins & correspondence

7905010246 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/03/23 1p

7905040021 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/03/26 1p

7905030019 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/04/11 1p.

7905010376 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/14 1p.

7905040382 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/04/14. 1p

7905040337 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/14 1p.

7905070170 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/04/14 1p.

7905010396 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/16 1p.

7905030217 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/04/17 1p.

7905080400 Forwards IE Bulletin 79-03B, "Nuclear Incident at TMI-Suppl."
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/04/21. 1p.

7905240892 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase."
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/03/02 1p.

DOCKETED ITEMS

211

DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7905020424 Forwards NUREG-0531, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability W/O encl.
VASSALLO, D B Assistant Director for Light Water Reactors
79/03/23 2pp

G. Inspection reports, IE Bulletins & correspondence

7905010246 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23, 1p

7905040021 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks,"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26 1p

7905030019 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/11 1p.

7905010576 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident,"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p.

7905040382 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/14, 1p

7905040537 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/14, 1p.

7905070170 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/14 1p.

7905010396 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/16 1p.

7905030217 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Bys." Licensee action required.
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/17, 1p.

7905080400 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/21, 1p.

7905240892 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Bat Resulted in Reactor Power Increase."
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/05/02 1p.

DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905080398 Raises questions by Seacoast Anti-Pollution League re financing plan proposed in Public Svc Co 790321 & 790427 ltrs.
BACKUS, R.A. O'Neil, Backus, Spielman. 79/05/04. 4pp.

7905170243 Forwards Amend 40 to license application. Certificate of Bvc, amend fee & supporting documentation encl.
RITCHER, J A. Ropes & Gray. 79/05/16. 1p.

--7905170251 Appointment of agent & signature of applicant.
CLARY, J.V. Green Mountain Power Corp. 79/04/30. 2pp.

--7905170253 Forwards Amend 40 to 790330 license application; request for partial transfer of ownership of CPPR-135 & CPPR-136 & supporting financial info of owners.
HERRILL, D.N. Green Mountain Power Corp. 79/05/14. 315pp.

F. Security, medical, emergency & fire protection plans

7905240343 Forwards Ofc of Nuclear Reactor Regulation 780929 memo to Commissioners re results of fire protection research test
Will provide all generic board notifications in all proceedings involving facilities.
BRENNER, L Branch 3 79/04/03. 2pp

G. Adjudicatory correspondence

7905010323 Forwards request for order to show cause why CP should not be suspended or revoked. NRC position on not reviewing consequences of Class 9 facility accident should be reevaluated in light of BECV-78-137.
BACKUS, R.A. O'Neil, Backus, Spielman 79/03/12 2pp

--7905010329 Requests order to show cause why CP should not be suspended or revoked for lack of financial qualifications of lead applicant & other participating companies Certificate of Bvc encl
BACKUS, R A O'Neil, Backus, Spielman 79/03/12 7pp

7905070026 Responds to Seacoast Anti-Pollution League request for order to show cause why CP should not be suspended or revoked
Calls for investigation into util's financial qualifications Certificate of Bvc encl
BURT, L Massachusetts, State of 79/03/26. 5pp

7905020410 Forwards 790312 order to show cause & request for order to show cause
DENTON, H R. Office of Nuclear Reactor Regulation 79/03/29. 3pp

--7905020416 Forwards request for order to show cause why CP should not be suspended or revoked
O'Neil, Backus, Spielman 79/03/12 1p

--7905020422 Request for order to show cause why CP for proposed nuclear power plants should not be suspended or revoked.
BACKUS, R A O'Neil, Backus, Spielman 79/03/12 5pp

--7905020430 Request for order to show cause, filed by Seacoast Anti pollution League.
DENTON, H R Office of Nuclear Reactor Regulation 79/03/12 1p.

7905030336 Requests NRC immediately stop const until design changes are made.
WEINHOLD, E H. Affiliation Unknown. 79/04/01. 3pp

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record. Certificate of Bvc encl
SCINTO, J.F. Hearings Division. 79/04/11. 45pp.

7905140519 Response to 790404 brief of Philadelphia Electric Co, PSE&O & Atlantic City (NJ) Electric Co re de minimus theory.
Certificate of Bvc encl.
KEPFORD, C.R. Citizens for Safe Environment. 79/04/11. 8pp.

7905240251 Urges swift conclusion to seismic issue for facilities in light of closing of five nuclear plants
LEWIS, R. Seacoast Anti-Pollution League. 79/04/18. 1p.

7905290353 Opposes EH Weinhold 790401 request for seismic design changes & for halt in const until implementation of such changes. EH Weinhold should be permitted to file brief amicus curiae.
BRENNER, L. Branch 3 79/04/23. 9pp.

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue. Parties have until 790525 in which to file for summary disposition.
DUFLO, M.E. Atomic Safety and Licensing Appeal Panel. 79/04/23. 13pp.

I. Financial information

7905010477 Responds to NRC 790314 request for addl info re design, analysis, & fabrication for proposed mod of storing reactor cavity annular seal plate during operation. Info will be provided by 790731.
WALBRIDGE, W.C. Sacramento Municipal Utility District. 79/04/26. 1pp.

7905010447 Forwards util 790626 preliminary prospectus offering 1,000,000 shares of preferred stock at \$23 par value.
RITCHER, J.A. Ropes & Gray 79/04/27. 81pp.

7905210129 Forwards 790513 final prospectus re sinking fund stock, 11.24% dividend series.
RITCHER, J A. Ropes & Gray. 79/05/16. 53pp.

DOCKETED ITEMS

G Inspection reports, IE Bulletins & correspondence

7905010143 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
ORIER, B.H. Region 1, Philadelphia, Office of the Director.
79/03/23 1p

7905020103 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORIER, B.H. Region 1, Philadelphia, Office of the Director.
79/04/11 1p.

7905020364 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
ORIER, B.H. Region 1, Philadelphia, Office of the Director.
79/04/14 1p

7905040100 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORIER, B.H. Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040284 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
ORIER, B.H. Region 1, Philadelphia, Office of the Director.
79/04/14 1p

7905030105 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required
ORIER, B.H. Region 1, Philadelphia, Office of the Director
79/04/17 1p

7905020324 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORIER, B.H. Region 1, Philadelphia, Office of the Director
79/04/18 1p

7905290083 Responds to IE Bulletin 79-09, GE type AK-2 circuit breakers not planned for use
SHEPARD, A.M. Public Service Co of New Hampshire 79/04/23 1p

DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2

7905010447 Forwards until 790626 preliminary prospectus, offering 1,000,000 shares of preferred stock at \$25 per value
RITTSHER, J.A. Ropes & Gray 79/04/27 51pp

A Application/construction stage documents & correspondence

7905080398 Raises questions by Seacoast Anti-Pollution League re financing plan proposed in Public Bvc Co 790321 & 790427 ltrs.
BACKUS, R.A. O'Neil, Backus, Spielman 79/05/04 4pp

7905170245 Forwards Amend 40 to license application, Certificate of Bvc, amend fee & supporting documentation encl
RITTSHER, J.A. Ropes & Gray. 79/05/16 1p

--7905170231 Appointment of agent & signature of applicant.
CLEARY, J.V. Green Mountain Power Corp 79/04/30 2pp.

--7905170253 Forwards Amend 40 to 790330 license application, request for partial transfer of ownership of CPPR-135 & CPPR-136 & supporting financial info of owners.
MERRILL, D.N. Green Mountain Power Corp. 79/05/14. 315pp.

F. Security, medical, emergency & fire protection plans

7905240343 Forwards Ofc of Nuclear Reactor Regulation 780929 memo to Commissioners re results of fire protection research test. Will provide all generic board notifications in all proceedings involving facilities.
BRENNER, L. Branch 3. 79/04/05. 2pp.

D Adjudicatory correspondence

7905010323 Forwards request for order to show cause why CP should not be suspended or revoked, NRC position on not reviewing consequences of Class 9 facility accident should be reevaluated in light of BECY-78-137.
BACKUS, R.A. O'Neil, Backus, Spielman. 79/03/12. 2pp.

--7905010329 Requests order to show cause why CP should not be suspended or revoked for lack of financial qualifications of lead applicant & other participating companies Certificate of Bvc encl
BACKUS, R.A. O'Neil, Backus, Spielman 79/03/12 7pp.

7905070026 Responds to Seacoast Anti-Pollution League request for order to show cause why CP should not be suspended or revoked Calls for investigation into util's financial qualifications Certificate of Bvc encl.
BURT, L. Massachusetts, State of 79/03/26 5pp

7905020410 Forwards 790312 order to show cause & request for order to show cause
DENTON, H.R. Office of Nuclear Reactor Regulation 79/03/29 3pp

--7905020416 Forwards request for order to show cause why CP should not be suspended or revoked
O'Neil, Backus, Spielman 79/03/12 1p

--7905020422 Request for order to show cause why CP for proposed nuclear power plants should not be suspended or revoked.
BACKUS, R.A. O'Neil, Backus, Spielman 79/03/12 5pp

--7905020430 Request for order to show cause, filed by Seacoast Anti pollution League
DENTON, H.R. Office of Nuclear Reactor Regulation 79/03/12 1p.

7905300336 Requests NRC immediately stop const until design changes are made
WEINHOLD, E.H. Affiliation Unknown. 79/04/01 3pp

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record. Certificate of Bvc encl
BCINTQ, J.F. Hearings Division 79/04/11 45pp

7905140519 Response to 790404 brief of Philadelphia Electric Co, PREB & Atlantic City (NJ) Electric Co re de minimus theory. Certificate of Bvc encl
KEPFORD, C.R. Citizens for Safe Environment 79/04/11. 8pp

7905240251 Urges swift conclusion to seismic issue for facilities in light of closing of five nuclear plants
LEWIS, R. Seacoast Anti-Pollution League. 79/04/18. 1p

7905290353 Opposes EH Weinhold 790401 request for seismic design changes & for halt in const until implementation of such changes. EH Weinhold should be permitted to file brief amicus curiae.
BRENNER, L. Branch 3 79/04/23. 9pp.

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue. Parties have until 790525 in which to file for summary disposition
DUFLO, M.E. Atomic Safety and Licensing Appeal Panel. 79/04/23 13pp

I. Financial information

7905010477 Responds to NRC 790319 request for addl info re design, analysis, & fabrication for proposed mod of storing reactor cavity annular seal plate during operation Info will be provided by 790731.
WALBRIDGE, H.C. Sacramento Municipal Utility District. 79/04/26 1pp.

7905210129 Forwards 790513 final prospectus re sinking fund stock, 11.24% dividend series
RITTSHER, J.A. Ropes & Gray. 79/05/16 53pp

G Inspection reports, IE Bulletins & correspondence

7905010143 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
ORIER, B.H. Region 1, Philadelphia, Office of the Director.
79/03/23 1p.

7905020103 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B.H. Region 1, Philadelphia, Office of the Director
79/04/11. 1p.

DOCKETED ITEMS

213

7905020364 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
GRIER, B H. Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040100 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
GRIER, B H. Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040284 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
GRIER, B H. Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905030105 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
GRIER, B H. Region 1, Philadelphia, Office of the Director
79/04/17 1p

7905020324 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
GRIER, B H. Region 1, Philadelphia, Office of the Director.
79/04/18 1p

7905290083 Responds to IE Bulletin 79-09 GE type AK-2 circuit breakers not planned for use
SHEPARD, A M. Public Service Co of New Hampshire 79/04/23 1p

DOCKET 80-445 COMANCHE PEAK STEAM ELECTRIC STA., UNIT 1

A Application/construction stage documents & correspondence

7905140040 Summary of 790320-0321 meeting w/TX Utils Generating Co, Brown & Root, Gibbs & Hill & TX Utils Svc, Inc in Olen Ross, TX re testing schedule, const progress & gathering of info to permit independent estimate of fuel loading date
BURWELL, S B. Light Water Reactors Branch 2 79/04/06 8pp

7905030365 Forwards environ qualification plans Six oversized encls available in Central Files
GARY, R J. Texas Utilities Generating Co 79/04/23 2pp

7905090313 Informs that response to 790406 request for addl second round info will be submitted by Jul 1979
Texas Utilities Generating Co 79/04/30 1p

7905140284 Forwards initial responses to QA Branch round one questions (0423, 7-0423 20) which will be retransmitted to NRC as FSAR Amend 4.
BACKO, B B. Texas Utilities Co 79/04/30 125pp

7905140222 Forwards "Chlorine Minimization Plan" submitted by util Requests comment by 790601
ELLIOTT, R B. Environmental Protection Agency. 79/03/08 1p

--7905140224 Forwards "Chlorine Minimization Plan." Requests comment within 60 days.
FIKAR, L F. Texas Utilities Generating Co. 79/04/12 1p

--7905140226 "Chlorine Minimization Plan"
RICE, J K. Texas Utilities Generating Co. 79/03/29 18pp.

Q Adjudicatory correspondence

7905100228 Answer to Citizens for Sound Energy 790228 petition to intervene re application for OL Seeks denial as matter of right & discretion. Notice of appearance of NS Reynolds on behalf of utils. Certificate of Svc encl
REYNOLDS, N B., KNOTT, J. B. Debevoise & Lieberman 79/03/15 12pp

7905150821 Answer to Citizens for Fair Utility Regulation 790323 petition to intervene re application for OL Seeks denial as matter of right & discretion Certificate of Svc encl
REYNOLDS, N B., KNOTT, J. B. Debevoise & Lieberman 79/03/19 11pp

7905250271 Answer to Citizens for Sound Energy 790228 petition to intervene re application for OL Recommends granting intervention if petitioner refines request. Certificate of Svc encl.
CHANDLER, L J. Branch 1. 79/03/19. 8pp.

7905090154 Request for hearing & first amended petition to intervene by TX Association for Community Organizations Affidavits of T Thompson, R Martin, M Bishop, C Bishop, WA Wood & O Wood & Certificate of Svc encl
GARRETT, W., HAWTHORNE, B., GAY, O M. West Texas Legal Services. 79/03/29. 17pp.

7905240115 Request by joint intervenors that time for filing of contentions & first prehearing conference be continued Notice of appearance of OM Gay on behalf of intervenors, request of svc of documents & Certificate of Svc encl
GAY, O M. West Texas Legal Services 79/04/06 11pp

7905250143 Confirms scheduled 790417 meeting & requests draft of proposed contentions
CHANDLER, L J. Branch 1 79/04/06 1p

7905230853 Orders conference on 790522 to consider petitions to intervene
BOWERS, E B. Atomic Safety and Licensing Board Panel 79/04/09 2pp

7905100193 Answer by applicant, in opposition to 790329 first amended petition to intervene & request for hearing filed by TX Association of Community Organizations for Reform Now & West TX Legal Svcs Certificate of Svc encl
REYNOLDS, N B. Debevoise & Lieberman 79/04/13 24pp

7905220053 Corrects ASLB 790409 order re location of 790522 prehearing conference
BOWERS, E B. Atomic Safety and Licensing Board Panel 79/04/17 1p

7905300362 Recommends granting joint petition to intervene from TX Association of Community Organizations for Reform Now & West TX Legal Svcs, subj to clarification of interest & authorization Certificate of Svc encl
CHANDLER, L J. Branch 1 J 79/04/19 12pp

7905230639 Applicant's response to 790406 motion for continuance filed by Association of Community Organizations for Reform Now & West TX Legal Svcs Certificate of Svc encl
REYNOLDS, N B. Debevoise & Lieberman 79/04/25 4pp

7905240929 Motion to suppl contentions Certificate of Svc encl
ELLIOT, J. Citizens Association for Sound Energy 79/03/07 3pp

I Financial information

7905030154 Forwards financial analysis supporting Amend 1 to CPPR-126 & CPPR-127
SALTZMAN, J. Antitrust & Indemnity Group 79/04/13 6pp

M Antitrust correspondence

7905150545 Forwards TX Utils Co & subsidiaries' answer to NRC initial interrogatories & requests for production of documents Reserves rights to file objections & protective order before 790305. Certificate of Svc encl
SLICKEY, F K. Worsham, Forsythe & Samps 79/03/01. 1p

7905020232 Grants 790317 motion by Public Utils Board of Brownsville, TX seeking extensions, until 790330 & 790405, in which to compel fuller responses to Board's interrogatories
MARSHALL, E M. Atomic Safety and Licensing Board Panel 79/03/22 1p.

7905240127 Notifies that location of deposition of LC Peeler of Monsanto Co has been changed from Holiday Inn, Alvin, TX to Butler, Binion, Rice, Cook & Knapp law ofcs in Houston, TX.
RYAN, T. Q. Isham, Lincoln & Beale. 79/03/22 5pp

7905020480 Order protecting confidentiality of info sought by Houston Lighting & Power from Central Power & Light, West TX Utils, Public Svc of OK & Southeastern Electric Power Co
MILLER, M E. Atomic Safety and Licensing Board Panel. 79/03/23 5pp

7905310020 Response by util to second set of interrogatories & request for production of documents, submitted to Central Power & Light. Also moves for protective order Certificate of Svc encl
BARNETT, E W. Baker & Botts 79/03/28 25pp

7905070040 Advises that deposition of Edward Sherry, Air Products & Chemicals Co, Allentown, PA, originally scheduled for 790406, has been changed to 790419 at ofc of Air Products & Chemicals Co
RYAN, T. Q. Isham, Lincoln & Beale. 79/03/30 1p

--7905070043 RL Wright, AD Cyphers & L Peeler were deposed during Mar Central Power & Light filed answers & objections to Houston Lighting & Power Co first set of written interrogatories.
RYAN, T. Q. Isham, Lincoln & Beale. 79/03/30. 2pp

DOCKETED ITEMS

- 7905300058 Rept on progress made in Mar 1979 in completing discovery, submitted per ASLB 780621 order Certificate of Svc encl
HARRIS, J. L., BERGER, M. Q., CLARK, R. H. Justice, Dept of 79/03/31 7pp.
- 79053030175 Describes discovery activities of Public Utils Board of Brownsville, TX for Mar 1979 Certificate of Svc encl
POIRIER, M. R. Spiegel & McDiarmid, 79/04/03 6pp
- 79053090036 Request by TX Utils Generating Co for NRC to dismiss Central Power & Light South West Corp as intervenors in alternative, seeks summary disposition or invoking of collateral estoppel. Certificate of Svc encl
KNOTT, J. B. Debevoise & Lieberman 79/04/03 5pp.
- 79053090042 Request by TX Util Generating Co for order barring Central Power & Light from seeking relief inconsistent w/ District Court decision for favorable decision re summary disposition
KNOTT, J. B. Debevoise & Lieberman 79/04/03 2pp
- 79053090050 Memo by TX Utils Generating Co re points & authorities supporting motion to dismiss Central Power & Light South West Corp as intervenors or for summary disposition
KNOTT, J. B. Debevoise & Lieberman, 79/04/03 42pp
- 7905100288 Response to second set of interrogatories & requests for production of documents directed to DOJ by Houston Lighting & Power Qualifications of expert witnesses WE Scott & OTC Taylor & Certificate of Svc encl
HARRIS, J. L., BERGER, M. Q., CLARK, R. H. Justice, Dept of 79/04/03 23pp
- 7905100288 Response to second set of interrogatories & requests for production of documents directed to Dept of Justice by Houston Lighting & Power Qualifications of expert witnesses WE Scott & OTC Taylor & Certificate of Svc encl
HARRIS, J. L., BERGER, M. Q., CLARK, R. H. Justice, Dept of 79/04/03, 23pp
- 7905140070 Response to first set of interrogatories & request for production of documents submitted by TX Util Generating Co Certificate of Svc encl.
HARRIS, J. L. Justice, Dept of 79/04/03 11pp
- 7905250341 Request by Central Power & Light that ASLB issue protective order re interrogatories & request for production of documents from Houston Lighting & Power. Certificate of Svc encl
STAHL, D. M. Isham, Lincoln & Beale, 79/04/03 7pp.
- 7905100273 Response to TX Utils Generating Co's objections to & motion for protective orders & motion to compel further answers to interrogatories & request for production of documents Certificate of Svc encl
BLUME, M. B. Anti-Trust Division, 79/04/04 34pp
- 7905140115 Motion by Public Utils Board of Brownsville, TX to compel further production of documents from South TX Electric Cooperative & Medina Electric Cooperative Supporting documentation & Certificate of Svc encl.
POIRIER, M. R. Spiegel & McDiarmid, 79/04/03, 17pp.
- 7905140138 Request by Central Power & Light for extension of time to respond to 790328 responses by Houston Lighting & Power & TX Utils Generating Co to former's interrogatories & document requests. Certificate of Svc encl.
STAHL, D. Isham, Lincoln & Beale, 79/04/03, 6pp
- 7905100386 Moves that responses to motions for summary disposition filed by Houston Lighting & Power & TX Utils Generating Co be governed by 10CFR2.790(a). Certificate of Svc encl
LEBBY, R. P. Anti-Trust Division 79/04/06, 5pp.
- 7905150190 Motion by Houston Lighting & Power for protective order re public disclosure of info requested by Public Utils Board of Brownsville, TX. Certificate of Svc encl.
BARNETT, E. W. Baker & Botts, BOUKNIGHT, J. A., Lowenstein, Newman, Reis, Axelrad & Toll, 79/04/06, 9pp.
- 7905230793 Status of discovery & production during Mar 1979. Certificate of Svc encl.
BALOUGH, R. C. Austin, TX 79/04/06, 3pp.
- 7905100412 Applies restrictions on confidential documents to be produced by Houston Lighting & Power Co in response to request for production of documents by Public Utils Board of Brownsville, TX.
MILLER, M. E. Atomic Safety and Licensing Board Panel, 79/04/09, 5pp.
- 7905250488 Status rept on discovery for Mar 1979 Discovery requests were neither initiated nor received Certificate of Svc encl
JOHN, D. F. Akin, Oump, Hauer & Feld 79/04/09 5pp.
- 7905230651 Answer by Houston Power & Lighting to NRC 790323 response to util motion for protective order, NRC motion to compel further answers to interrogatories & NRC request for production of documents Certificate of Svc encl
BARNETT, E. W. Baker & Botts, BOUKNIGHT, J. A., Lowenstein, Newman, Reis, Axelrad & Toll 79/04/11 12pp
- 79053030260 Forwards revised page 28-1 attached to Central Power & Light Co's answers & objections to Houston Lighting & Power Co's first set of written interrogatories to Central Power & Light Co Certificate of Svc encl
STAHL, D. M. Isham, Lincoln & Beale 79/04/12 6pp
- 7905240332 Advises no discovery requests have been initiated or received by Tex-La Electric Cooperative, Inc Certificate of Svc encl
BURCHETTE, W. H. Northcutt Ely, 79/04/12 4pp
- 7905150663 Grants motions for extension of time for parties to respond to discovery requests
MILLER, M. E. Atomic Safety and Licensing Board Panel 79/04/13 3pp
- 7905230448 South TX Electric Cooperative, Inc & Medina Electric Cooperative, Inc's opposition to Public Utils Board of Brownsville, TX 790405 motion for fuller responses to interrogatories. Certificate of Svc encl.
MUNTEZ, M. McGinnis, Lochridge & Kilgore, JOHN, D. F. Akin, Oump, Hauer & Feld 79/04/13, 11pp
- 7905240967 Advises that during Mar 1979 NRC filed motions to compel against Houston Lighting & Power & TX Utils Generating Co NRC is preparing responses to TX Util's first & Houston's second set of interrogatories.
LEBBY, R. P. Anti-Trust Division 79/04/13 1p.
- 7905250129 Ack receipt of response to Mar 1979 motion to compel & evaluation in progress
LEBBY, R. P. Anti-Trust Division 79/04/13, 1p.
- 7905140126 Request by Public Utils Board of Brownsville, TX for extension of time to answer first set of interrogatories & requests for production of documents from Central Power & Light & Houston Lighting & Power. Certificate of Svc encl
MCDIARMID, R. C. Spiegel & McDiarmid 79/04/16, 7pp
- 7905240241 Corrects revised page 28-1 of Central Power & Light Co answers & objections in 790412 proceeding from "expenditure other than expenditure" to "expenditure other than advertising." Certificate of Svc encl
STAHL, D. M. Isham, Lincoln & Beale, 79/04/17 4pp
- 7905150780 Directs TX Utils Generating Co (TUOCO) to produce documents or make full responses to 790115 interrogatories Denies TUOCO's order for protective order.
MILLER, M. E. Atomic Safety and Licensing Board Panel, 79/04/18, 2pp.
- 7905230624 Response by util to Central Power & Light's 790326 objections & 790403 motion for protective order re util's first set of interrogatories. Includes motion to compel answers, w/ notice of appearance & Certificate of Svc encl
BARNETT, E. W. Baker & Botts, BOUKNIGHT, J. A., FRANKLIN, W. J., Lowenstein, Newman, Reis, Axelrad & Toll, 79/04/19, 18pp.
- 7905230677 Grants extension of time to answer interrogatories by Public Utils Board of Brownsville, TX, in response to 790416 motion.
MILLER, M. E. Atomic Safety and Licensing Board Panel 79/04/19, 1p
- 7905100118 Motion by Central Power & Light to compel Houston Lighting & Power to answer second set of interrogatories submitted 790223. Supporting documentation & Certificate of Svc encl.
STAHL, D. Isham, Lincoln & Beale, 79/04/20 20pp.
- 7905100123 Motion by Central Power & Light to compel TX Utils Generating Co to answer first set of interrogatories submitted 790223.
STAHL, D. Isham, Lincoln & Beale, 79/04/20, 12pp.
- 7905100271 Answer by Central Power & Light & Central & South West Corp seeking continuance of NRC antitrust reviews, w/ no party banned on grounds of res judicata of collateral estoppel. Supporting documentation & Certificate of Svc encl.
POWELL, R. E., MILLER, M. I., STAHL, D. M. Isham, Lincoln & Beale, 79/04/20, 115pp.

DOCKETED ITEMS

215

7905100106 Opposes City of Austin's 790329 brief & 790403 motions for full or partial summary judgment filed by Houston Lighting & Power & TX Utils Generating Co. Seeks denial of certification & interlocutory appeals w/Certificate of Svc LEBBY, R.P., BLUME, M.B. Anti-Trust Division 79/04/23 24pp.

7905140151 Response of Public Utils Board of Brownsville, TX opposing Houston Lighting & Power motion for summary decision & City of Austin brief in support of res Judicata Supporting documentation & Certificate of Svc encl
MCDIARMID, R.C., JABLON, R.A., POIRIER, M.R. Spiegel & McDiarmid. 79/04/23 84pp

7905230466 NRC answer to motions of Gulf States Util for protective order & order setting conditions for compliance w/790226 subpoena. Util should produce documents as requested Certificate of Svc encl.
BLUME, M.B. Anti-Trust Division 79/05/04 14pp

D. Inspection reports, IE Bulletins & correspondence

7905240196 Responds to IE Bulletin 79-01. No action to be taken at this time
GARY, R.J. Texas Utilities Generating Co 79/02/19 2pp

7905300761 Details actions taken in response to IE Bulletin 78-067 Survey prepared by Westinghouse indicates none of Cutler-Hammer Type M relays w/coil are in use in safety-related equipment
GARY, R.J. Texas Utilities Generating Co 79/02/19 2pp

7905070191 Forwards info meeting rept re 790213 meeting w/IE & local public officials in Granbury, TX to discuss assignment of resident inspector
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/02 2pp.

--7905070209 Summary of 790213 info meeting w/local officials of Granbury, TX re assignment of resident inspector, lines of communication, facility status & community concerns
TAYLOR, R.O., WISNER, C.E., CROSBY, W.A. Region 4, Dallas, Office of the Director 79/03/02 3pp

7905010365 Forwards IE Insp Repts 50-445/79-03 & 50-446/79-03 on 790202-28 Notice of violation already forwarded w/NRC 790220 ltr.
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/03/14 2pp

--7905010370 IE Insp Repts 50-445/79-03 & 50-446/79-03 on 790202-28 Noncompliance noted: failure to follow concrete placement procedures.
TAYLOR, R.O. Region 4, Dallas, Office of the Director 79/03/13 8pp

7905010281 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
BEYFRIT, K.V. Region 4, Dallas, Office of the Director 79/03/23 1p.

7905150556 Forwards IE Insp Repts 50-445/79-07 & 50-446/79-07 on 790308, 12 & 13. No noncompliance noted.
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/03/23 2pp

--7905150561 IE Insp Repts 50-445/79-07 & 50-446/79-07 on 790308, 12 & 13. No noncompliance noted. Major area inspected const activities
ROSENBERG, A.B. Region 4, Dallas, Reactor Construction & Engineering Support Branch. BARNES, I., ELLERBACH, L.E. Region 4, Dallas, Office of the Director 79/03/23 5pp.

7905010464 Forwards IE Bulletin 79-05A, "Nuclear Incident at TMI - Suppl."
BEYFRIT, K.V. Region 4, Dallas, Office of the Director. 79/04/05 1p.

7905040501 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bus Misalignments Identified During TMI Incident."
BEYFRIT, K.V. Region 4, Dallas, Office of the Director 79/04/14 1p.

7905040629 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
BEYFRIT, K.V. Region 4, Dallas, Office of the Director 79/04/14 1p

7905070080 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
BEYFRIT, K.V. Region 4, Dallas, Office of the Director. 79/04/14 1p.

7905010440 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
BEYFRIT, K.V. Region 4, Dallas, Office of the Director 79/04/16 1p

7905090108 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at TMI"
BEYFRIT, K.V. Region 4, Dallas, Office of the Director 79/04/16 1p

7905030283 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
BEYFRIT, K.V. Region 4, Dallas, Office of the Director 79/04/17 1p

7905290631 Ack receipt of 790320 & 0412 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept
50-445/79-04 & 50-446/79-04
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/26 1p

--7905290648 Responds to NRC 790320 ltr re violations noted in IE Insp Repts 50-445/79-04 & 50-446/79-04 Corrective actions equipment maint record for ventilation fan motor revised
GARY, R.J. Texas Utilities Generating Co 79/04/12 3pp

B Reportable occurrences, LERs & related correspondence

7905030140 Forwards PNO-79-67H, I, J & K
BEYFRIT, K.V. Region 4, Dallas, Office of the Director 79/04/06 1p

7905030085 Forwards PNO-79-67L, M, N & P
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/09 1p

7905030107 Forwards PNO-79-67G
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/10 1p

7905030151 Forwards PNO-79-67R & 79-77
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/11 1p

7905030124 Forwards PNO-79-67S.
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/12 1p

7905030201 Forwards PNO-79-67T
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/13 1p

7905030076 Forwards PNO-79-67U & V.
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/16 1p.

7905030254 Forwards PNO-79-67W
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/17 1p

7905020514 Forwards PNO-79-67AA
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/20 1p

7905020508 Forwards PNO-79-67AB, AC & AD.
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/23 1p.

7905040580 Forwards PNO-79-67AE.
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/26 1p

7905070193 Forwards PNO-79-67AF & AG
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/27 1p.

7905030230 Forwards PNO-79-67AH, AI & AJ
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/30 1p

7905240399 Forwards PNO-79-67AK & AL
SEIDLE, W.C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/05/04 1p.

DOCKETED ITEMS

7905210192 Confirms potentially RD re reactor vessel nozzle weld metal defects, originally reported in 790126 telcon. Investigation continuing
QARY, R J Texas Utilities Generating Co 79/05/14. 1p

DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA. UNIT 2

A Application/construction stage documents & correspondence

7905140040 Summary of 790320-0321 meeting w/TX Utils Generating Co, Brown & Root, Dicks & Hill & TX Utils Svc, Inc in Glen Rose, TX re testing schedule, const progress & gathering of info to permit independent estimate of fuel loading date
BURNELL, B B Light Water Reactors Branch 2 79/04/06. 8pp

7905030345 Forwards environ qualification plans Six oversized encls available in Central Files
QARY, R J Texas Utilities Generating Co 79/04/23 2pp.

7905070313 Informs that response to 790406 request for addl second round info will be submitted by Jul 1979
* Texas Utilities Generating Co 79/04/30 1p

7905140284 Forwards initial responses to GA Branch round one questions (G423 7-G423 20) which will be retransmitted to NRC as FSAR Amend 6
DACKO, B B Texas Utilities Co 79/04/30 125pp

7905140222 Forwards "Chlorine Minimization Plan" submitted by util Requests comment by 790601.
ELLIOTT, R B Environmental Protection Agency 79/05/08 1p

--7905140224 Forwards "Chlorine Minimization Plan" Requests comment within 60 days
FIKAR, L F Texas Utilities Generating Co 79/04/12 1p

--7905140226 "Chlorine Minimization Plan"
RICE, J K Texas Utilities Generating Co 79/03/29 18pp

D Adjudicatory correspondence

7905100228 Answer to Citizens for Sound Energy 790228 petition to Intervene re application for DL Seeks denial as matter of right & discretion Notice of appearance of NS Reynolds on behalf of utils Certificate of Bvc encl
REYNOLDS, N.B., KNOTTS, J B Debevoise & Lieberman 79/03/13 12pp

7905100821 Answer to Citizens for Fair Utility Regulation 790323 petition to intervene re application for DL Seeks denial as matter of right & discretion. Certificate of Bvc encl
REYNOLDS, N.B., KNOTTS, J B Debevoise & Lieberman 79/03/19 11pp.

7905250271 Answer to Citizens for Sound Energy 790228 petition to Intervene re application for DL Recommends granting intervention if petitioner refines request Certificate of Bvc encl.
CHANDLER, L J Branch 1 79/03/19 8pp

7905090194 Request for hearing & first amended petition to Intervene by TX Association for Community Organizations. Affidavits of T Thompson, R Martin, B Bishop, C Bishop, WA Wood & Q Wood & Certificate of Bvc encl.
GARRETT, M., HAWTHORNE, B., QAY, O M West Texas Legal Services. 79/03/29. 17pp.

7905240115 Request by joint intervenors that time for filing of contentions & first prehearing conference be continued. Notice of appearance of OM Qay on behalf of intervenors. Request of svc of documents & Certificate of Bvc encl.
QAY, O.M. West Texas Legal Services. 79/04/06 11pp.

7905230143 Confirms scheduled 790417 meeting & requests draft of proposed contentions.
CHANDLER, L J Branch 1 79/04/06 1p

7905230853 Orders conference on 790522 to consider petitions to Intervene
BOWERS, E.B. Atomic Safety and Licensing Board Panel 79/04/09. 2pp

7905100193 Answer by applicant, in opposition to 790329 first amended petition to Intervene & request for hearing filed by TX Association of Community Organizations for Reform Now & West TX Legal Svcs. Certificate of Bvc encl.
REYNOLDS, N.B. Debevoise & Lieberman. 79/04/13 24pp

7905220053 Corrects ASLB 790409 order re location of 790522 prehearing conference.
BOWERS, E B Atomic Safety and Licensing Board Panel. 79/04/17 1p

7905300362 Recommends granting joint petition to Intervene from TX Association of Community Organizations for Reform Now & West TX Legal Svcs; subj to clarification of interest & authorization Certificate of Bvc encl
CHANDLER, L J Branch 1 J 79/04/19 12pp

7905230637 Applicant's response to 790406 motion for continuance filed by Association of Community Organizations for Reform Now & West TX Legal Svcs Certificate of Bvc encl.
REYNOLDS, N.B. Debevoise & Lieberman 79/04/25 4pp

7905240927 Motion to suppl contentions Certificate of Bvc encl
ELLIS, J Citizens Association for Sound Energy 79/05/07 3pp

I Financial information

7905030314 Forwards financial analysis supporting Amend 1 to CPPR-126 & CPPR-127
BALTZMAN, J Antitrust & Indemnity Group 79/04/13 6pp

M Antitrust correspondence

7905150845 Forwards TX Utils Co & subsidiaries' answer to NRC initial interrogatories & requests for production of documents Reserves rights to file objections & protective order before 790303. Certificate of Bvc encl
SLICKEY, F K Worsham, Forsythe & Samps 79/03/01. 1p

7905020232 Grants 790317 motion by Public Utilis Board of Brownsville, TX seeking extensions, until 790330 & 790405, in which to compel fuller responses to Board's interrogatories
MARSHALL, E M Atomic Safety and Licensing Board Panel. 79/03/22 1p

7905240127 Notifies that location of deposition of LC Peeler of Monsanto Co has been changed from Holiday Inn, Alvin, TX to Butler, Binion, Rice, Cook & Knapp law ofcs in Houston, TX
RYAN, T.O. Isham, Lincoln & Beale 79/03/22 5pp.

7905020480 Order protecting confidentiality of info sought by Houston r Lighting & Power from Central Power & Light, West TX Utils, Public Svc of OK & Southeastern Electric Power Co
HILLER, M.E. Atomic Safety and Licensing Board Panel. 79/03/20 5pp

7905310020 Response by util to second set of interrogatories & request for production of documents, submitted to Central Power & Light Also moves for protective order. Certificate of Bvc encl.
BARNETT, E W Baker & Botts. 79/03/28. 25pp.

7905070040 Advises that deposition of Edward Sherry, Air Products & Chemicals Co, Allentown, PA, originally scheduled for 790406, has been changed to 790419 at ofc of Air Products & Chemicals Co
RYAN, T O. Isham, Lincoln & Beale. 79/03/30. 1p

--7905070045 RL Wright, AD Cyphers & L Peeler were deposed during Mar. Central Power & Light filed answers & objections to Houston Lighting & Power Co first set of written interrogatories.
RYAN, T O Isham, Lincoln & Beale. 79/03/30 2pp

7905300058 Rept on progress made in Mar 1979 in completing discovery, submitted per ASLB 780621 order. Certificate of Bvc encl.
HARRIS, J.L., BERGER, M.O., CLARK, R.H. Justice, Dept. of 79/03/31 7pp

7905030175 Describes discovery activities of Public Utilis Board of Brownsville, TX for Mar 1979. Certificate of Bvc encl.
POIRER, M R Spiegel & McDiarmid 79/04/03 6pp

7905090036 Request by TX Utils Generating Co for NRC to dismiss Central Power & Light South West Corp as intervenors, in alternative, seeks summary disposition or invoking of collateral estoppel Certificate of Bvc encl
KNOTTS, J B. Debevoise & Lieberman. 79/04/03 8pp.

--7905090042 Request by TX Util Generating Co for order barring Central Power & Light from seeking relief inconsistent w/District Court decision for favorable decision re summary disposition.
KNOTTS, J B Debevoise & Lieberman 79/04/03. 2pp

--7905090050 Memo by TX Util Generating Co re points & authorities supporting motion to dismiss Central Power & Light South West Corp as intervenors or for summary disposition.
KNOTTS, J.B. Debevoise & Lieberman 79/04/03 42pp

- 7905100288 Response to second set of interrogatories & requests for production of documents directed to DOJ by Houston Lighting & Power Qualifications of expert witnesses WE Scott & QTC Taylor & Certificate of Bvc encl.
HARRIS, J L, BERGER, M O, CLARK, R. H. Justice, Dept. of 79/04/03 23pp
- 7905100288 Response to second set of interrogatories & requests for production of documents directed to Dept of Justice by Houston Lighting & Power Qualifications of expert witnesses WE Scott & QTC Taylor & Certificate of Bvc encl.
HARRIS, J L, BERGER, M O, CLARK, R H Justice, Dept. of 79/04/03. 23pp
- 7905250361 Request by Central Power & Light that ABLB issue protective order re interrogatories & request for production of documents from Houston Lighting & Power Certificate of Bvc encl.
STAHL, D M Isham, Lincoln & Beale. 79/04/03 7pp.
- 7905100273 Response to TX Utils Generating Co's objections to & motion for protective orders & motion to compel further answers to interrogatories & request for production of documents Certificate of Bvc encl.
BLUME, M B Anti-Trust Division 79/04/04 34pp.
- 7905140115 Motion by Public Utils Board of Brownsville, TX to compel further production of documents from South TX Electric Cooperative & Medina Electric Cooperative. Supporting documentation & Certificate of Bvc encl
POIRIER, M R Spiegel & McDiarmid 79/04/05 17pp
- 7905140138 Request by Central Power & Light for extension of time to respond to 790328 responses by Houston Lighting & Power & TX Utils Generating Co to former's interrogatories & document requests Certificate of Bvc encl.
STAHL, D Isham, Lincoln & Beale 79/04/05 6pp
- 7905100386 Moves that responses to motions for summary disposition filed by Houston Lighting & Power & TX Utils Generating Co be governed by 10CFR2 790(a) Certificate of Bvc encl.
LEBBY, R. P. Anti-Trust Division. 79/04/06. 5pp
- 7905150190 Motion by Houston Lighting & Power for protective order re public disclosure of info requested by Public Utils Board of Brownsville, TX Certificate of Bvc encl.
BARNETT, E. W. Baker & Botts BOUKNIGHT, J A Lowenstein, Neuman, Reis, Axelrad & Toll 79/04/06. 9pp
- 7905230793 Status of discovery & production during Mar 1979 Certificate of Bvc encl.
BALOUGH, R C Austin, TX. 79/04/06 3pp.
- 7905100412 Applies restrictions on confidential documents to be produced by Houston Lighting & Power Co in response to request for production of documents by Public Utils Board of Brownsville, TX
MILLER, M E. Atomic Safety and Licensing Board Panel 79/04/09 3pp.
- 7905230488 Status rept on discovery for Mar 1979. Discovery requests were neither initiated nor received. Certificate of Bvc encl.
JOHN, D F Akin, Gump, Hauer & Feld 79/04/09. 5pp
- 7905230651 Answer by Houston Power & Lighting to NRC 790323 response to util motion for protective order. NRC motion to compel further answers to interrogatories & NRC request for production of documents. Certificate of Bvc encl.
BARNETT, E. W. Baker & Botts BOUKNIGHT, J A Lowenstein, Neuman, Reis, Axelrad & Toll 79/04/11. 12pp.
- 7905030260 Forwards revised page 28-1 attached to Central Power & Light Co's answers & objections to Houston Lighting & Power Co's first set of written interrogatories to Central Power & Light Co. Certificate of Bvc encl.
STAHL, D. M Isham, Lincoln & Beale. 79/04/12 6pp
- 7905240332 Advises no discovery requests have been initiated or, received by Tex-La Electric Cooperative, Inc Certificate of Bvc encl.
BURCHETTE, H. H. Northcutt Ely. 79/04/12. 4pp
- 7905150663 Grants motions for extension of time for parties to respond to discovery requests.
MILLER, M E. Atomic Safety and Licensing Board Panel. 79/04/13 3pp.
- 7905230448 South TX Electric Cooperative, Inc & Medina Electric Cooperative, Inc's opposition to Public Utils Board of Brownsville, TX 790405 motion for fuller responses to interrogatories. Certificate of Bvc encl
HUNTER, M. McInnis, Lochridge & Kilgore. JOHN, D F. Akin, Gump, Hauer & Feld 79/04/13. 11pp
- 7905240967 Advises that during Mar 1979 NRC filed motions to compel against Houston Lighting & Power & TX Utils Generating Co. NRC is preparing responses to TX Util's first & Houston's second set of interrogatories
LEBBY, R P Anti-Trust Division 79/04/13 1p.
- 7905230129 Ack receipt of response to Mar 1979 motion to compel & evaluation in progress
LEBBY, R P. Anti-Trust Division 79/04/13. 1p
- 7905140126 Request by Public Utils Board of Brownsville, TX for extension of time to answer first set of interrogatories & requests for production of documents from Central Power & Light & Houston Lighting & Power Certificate of Bvc encl
MCDIARMID, R C Spiegel & McDiarmid 79/04/16 7pp.
- 7905240241 Corrects revised page 28-1 of Central Power & Light Co answers & objections in 790412 proceeding from "expenditure other than expenditure" to "expenditure other than advertising" Certificate of Bvc encl
STAHL, D M Isham, Lincoln & Beale. 79/04/17. 4pp
- 7905130780 Directs TX Utils Generating Co (TUQCO) to produce documents or make full responses to 790113 interrogatories. Denies TUQCO's order for protective order
MILLER, M E Atomic Safety and Licensing Board Panel 79/04/18. 2pp
- 7905230624 Responses by util to Central Power & Light's 790326 objections & 790403 motion for protective order re util's first set of interrogatories Includes motion to compel answers w/notice of appearance & Certificate of Bvc
BARNETT, E. W Baker & Botts BOUKNIGHT, J A, FRANKLIN, W J Lowenstein, Neuman, Reis, Axelrad & Toll 79/04/19 18pp
- 7905230677 Grants extension of time to answer interrogatories by Public Utils Board of Brownsville, TX, in response to 790416 motion
MILLER, M E Atomic Safety and Licensing Board Panel. 79/04/19 1p
- 7905100118 Motion by Central Power & Light to compel Houston Lighting & Power to answer second set of interrogatories submitted 790223. Supporting documentation & Certificate of Bvc encl
STAHL, D Isham, Lincoln & Beale 79/04/20 20pp
- 7905100123 Motion by Central Power & Light to compel TX Utils Generating Co to answer first set of interrogatories submitted 790223.
STAHL, D Isham, Lincoln & Beale 79/04/20. 12pp
- 7905100271 Answer by Central Power & Light & Central & South West Corp seeking continuance of NRC antitrust reviews, w/no party banned on grounds of res judicata of collateral estoppel Supporting documentation & Certificate of Bvc encl.
POWELL, R. E, MILLER, M I., STAHL, D M Isham, Lincoln & Beale 79/04/20 115pp.
- 7905100106 Opposes City of Austin's 790329 brief & 790403 motions for full or partial summary judgment filed by Houston Lighting & Power & TX Utils Generating Co Seeks denial of certification & interlocutory appeals. W/Certificate of Bvc.
LEBBY, R P., BLUME, M. B. Anti-Trust Division. 79/04/23 24pp.
- 7905140151 Responses of Public Utils Board of Brownsville, TX opposing Houston Lighting & Power motion for summary decision & City of Austin brief in support of res judicata. Supporting documentation & Certificate of Bvc encl
MCDIARMID, R C, JABLON, R A, POIRIER, M R Spiegel & McDiarmid 79/04/23. 84pp.
- 7905230466 NRC answer to motions of Gulf States Util for protective order & order setting conditions for compliance w/790226 subpoena Util should produce documents as requested. Certificate of Bvc encl.
BLUME, M B. Anti-Trust Division. 79/05/04. 14pp.
- 0 Inspection reports, IE Bulletins & correspondence
- 7905240196 Responds to IE Bulletin 79-01 No action to be taken at this time.
GARY, R. J Texas Utilities Generating Co 79/02/19. 2pp
- 7905300761 Details actions taken in response to IE Bulletin 78-067. Survey prepared by Westinghouse indicates none of Cutler-Hammer Type M relays w/coil are in use in safety-related equipment.
GARY, R J. Texas Utilities Generating Co. 79/02/19. 2pp.
- 7905070191 Forwards info meeting rept re 790213 meeting w/IE & local public officials in Granbury, TX to discuss assignment of resident inspector.
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/02 2pp.

DOCKETED ITEMS

--7905070209 Summary of 790213 info meeting w/local officials of Granbury, TX re assignment of resident inspector, lines of communication, facility status & community concerns
TAYLOR, R O ; WIGNER, C E ; CROSSMAN, W A. Region 4, Dallas, Office of the Director 79/03/02 3pp

7905010365 Forwards IE Insp Repts 50-445/79-03 & 50-446/79-03 on 790202-28. Notice of violation already forwarded w/NRC 790220 ltr.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/14 2pp

--7905010370 IE Insp Repts 50-445/79-03 & 50-446/79-03 on 790202-28 Noncompliance noted failure to follow concrete placement procedures
TAYLOR, R O Region 4, Dallas, Office of the Director 79/03/13 6pp

7905010281 Forwards IE Info Notice 79-04, "Stress Analysis of Safety-Related Piping"
BEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/23. 1p.

7905150556 Forwards IE Insp Repts 50-445/79-07 & 50-446/79-07 on 790308, 12 & 13. No noncompliance noted
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/03/23 2pp

--7905150561 IE Insp Repts 50-445/79-07 & 50-446/79-07 on 790308, 12 & 13. No noncompliance noted Major area inspected: const activities
ROSENBERG, A B Region 4, Dallas, Reactor Construction & Engineering Support Branch BARNES, I ; ELLERSHAW, L E Region 4, Dallas, Office of the Director 79/03/23 3pp

7905010464 Forwards IE Bulletin 79-05A, "Nuclear Incident at TMI - Suppl"
BEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/05 1p.

7905040501 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
BEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 1p.

7905040629 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
BEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 1p

7905070080 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
BEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 1p

7905010440 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
BEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/16 1p

7905090108 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at TMI"
BEYFRIT, K V Region 4, Dallas, Office of the Director. 79/04/16 1p

7905030283 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
BEYFRIT, K V Region 4, Dallas, Office of the Director. 79/04/17 1p

7905290631 Ack receipt of 790320 & 0412 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-445/79-04 & 50-446/79-04.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/26. 1p

--7905290648 Responds to NRC 790320 ltr re violations noted in IE Insp Repts 50-445/79-04 & 50-446/79-04. Corrective actions: equipment maint record for ventilation fan motor revised.
GARY, R J. Texas Utilities Generating Co 79/04/12 3pp

B. Reportable occurrences, LERs & related correspondence

7905030140 Forwards PNO-79-67H, I, J & K.
BEYFRIT, K V Region 4, Dallas, Office of the Director. 79/04/06. 1p

7905030085 Forwards PNO-79-67L, M, N & P.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/09 1p.

7905030107 Forwards PNO-79-67O
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/10 1p

7905030151 Forwards PNO-79-67R & 79-77
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/11. 1p

7905030124 Forwards PNO-79-67S
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/12. 1p

7905030201 Forwards PNO-79-67T
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/13 1p

7905030076 Forwards PNO-79-67U & V.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/16 1p.

7905030254 Forwards PNO-79-67W
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/17 1p

7905020514 Forwards PNO-79-67AA
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/20 1p

7905020508 Forwards PNO-79-67AB, AC & AD.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/23 1p.

7905040580 Forwards PNO-79-67AE
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/26 1p

7905070193 Forwards PNO-79-67AF & AG.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/27 1p

7905030230 Forwards PNO-79-67AH, AI & AJ.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/30. 1p

7905240399 Forwards PNO-79-67AK & AL.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/05/04 1p

7905210192 Confirms potentially RD re reactor vessel nozzle weld metal defects, originally reported in 790126 telcon. Investigation continuing.
GARY, R J. Texas Utilities Generating Co. 79/05/14 1p

DOCKET STN-50-447 QESSAR-238

A. Application/construction stage documents & correspondence

7905220045 Responds to 790321 ltr requesting June 1979 deadline for detailed review of QESSAR-238 NI preliminary design approval extension. Due to manpower shortages, extension review will not be conducted on schedule
BENTON, H. R. Office of Nuclear Reactor Regulation 79/04/16. 7pp

J. Insurance & indemnity information

7905070582 Confirms increase in liability limit to \$36,000,000 for policies HF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters 79/05/01. 1p

DOCKET 50-448 DOUGLAS POINT NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905090374 Forwards "Site Selection Study for Two 1,100 Megawatt Nuclear Power Plants," prepared by Dams & Moore
COX, E. T. Potomac Electric Power Co. 79/05/07. 2pp

--7905090376 "Site Selection Study for Two 1,100 Megawatt Nuclear Power Plants."
* Potomac Electric Power Co. 79/05/01. 70pp.

DOCKETED ITEMS

219

Q. Adjudicatory correspondence

7905020147 States NRC has recently discovered document possibly relevant to sabotage of spent fuel it is classified & may never be published in final form Forwards related 790122 TF Carter memo NRC assessment of info to follow
BARTH, C. A Branch 3 79/04/05 2pp

7905030079 Forwards NRC survey of its use of WASH-1400 omitted from 790404 ltr
BARTH, C. A Branch 3 79/04/10 40pp

M. Antitrust correspondence

7905150643 Grants motions for extension of time for parties to respond to discovery requests
MILLER, M. E Atomic Safety and Licensing Board Panel 79/04/13 3pp.

DOCKET 50-449 DOUGLAS POINT NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905090374 Forwards "Site Selection Study for Two 1,100 Megawatt Nuclear Power Plants," prepared by Dames & Moore.
COX, E. T Potomac Electric Power Co 79/05/07 2pp

--7905090376 "Site Selection Study for Two 1,100 Megawatt Nuclear Power Plants"
Potomac Electric Power Co 79/05/01 70pp

Q. Adjudicatory correspondence

7905020147 States NRC has recently discovered document possibly relevant to sabotage of spent fuel it is classified & may never be published in final form Forwards related 790122 TF Carter memo NRC assessment of info to follow
BARTH, C. A Branch 3 79/04/05 2pp

7905030079 Forwards NRC survey of its use of WASH-1400 omitted from 790404 ltr
BARTH, C. A Branch 3 79/04/10 40pp.

M. Antitrust correspondence

7905100118 Motion by Central Power & Light to compel Houston Lighting & Power to answer second set of interrogatories submitted 790223 Supporting documentation & Certificate of Evc encl.
STAHL, D Isham, Lincoln & Beale, 79/04/20 20pp

DOCKET 50-450 SUMMIT NUCLEAR POWER STATION, UNIT 1

7905240508 Responds to 790410 ltr Util has no immediate plans to submit CP application
GOSSICK, L. V. Office of the Executive Director for Operations, 79/05/08, 1p

--7905240512 Requests to be informed when Delmarva Power & Light submits CP application for nuclear plant at Summit, DE.
BIDEN, J. R. Senate 79/04/10 1p

DOCKET 50-451 SUMMIT NUCLEAR POWER STATION, UNIT 2

7905240508 Responds to 790410 ltr Util has no immediate plans to submit CP application.
GOSSICK, L. V. Office of the Executive Director for Operations, 79/05/08, 1p.

--7905240512 Requests to be informed when Delmarva Power & Light submits CP application for nuclear plant at Summit, DE.
BIDEN, J. R. Senate, 79/04/10, 1p.

DOCKET 50-452 GREENWOOD ENERGY CENTER, UNIT 2

A. Application/construction stage documents & correspondence

7905150285 States procedures followed in filing of Amend 14 to PSAR & Suppl 5 to environ rept. Same procedure will be followed in future if no objections are made within ten days
HARGUARDT, P. A Detroit Edison Co 79/03/07, 1p.

7905240249 Finds PSAR sufficiently complete to begin technical review. Requests info re foundations for intake & discharge structures to complete review
HELLER, L. W. Geosciences Branch 79/04/19, 7pp

7905230473 Requests waiver of 10CFR50 App Q-III B.4 & B.5 requirements re fracture toughness tests as not applicable to reactor vessel, steam generators & pressurizers.
HARRIS, P. B Detroit Edison Co 79/05/01 2pp

Q. Adjudicatory correspondence

7905150737 Forwards NRC rept "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Grid Serving St Lucie"
SCHINKI, B. M Branch 3 79/04/11, 1p

DOCKET 50-453 GREENWOOD ENERGY CENTER, UNIT 3

A. Application/construction stage documents & correspondence

7905150285 States procedures followed in filing of Amend 14 to PSAR & Suppl 5 to environ rept. Same procedure will be followed in future if no objections are made within ten days
HARGUARDT, P. A Detroit Edison Co, 79/03/07 1p

7905240249 Finds PSAR sufficiently complete to begin technical review. Requests info re foundations for intake & discharge structures to complete review
HELLER, L. W. Geosciences Branch 79/04/19, 7pp

7905230473 Requests waiver of 10CFR50 App Q-III B.4 & B.5 requirements re fracture toughness tests as not applicable to reactor vessel, steam generators & pressurizers
HARRIS, P. B Detroit Edison Co 79/05/01 2pp

Q. Adjudicatory correspondence

7905150737 Forwards NRC rept "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Grid Serving St Lucie."
SCHINKI, B. M Branch 3, 79/04/11 1p.

DOCKET 50-454 BYRON STATION, UNIT 1

A. Application/construction stage documents & correspondence

7809050087 Forwards NUREG-0219, "Nuclear Security Personnel for Power Plants, Content & Review Procedures for Security Training & Qualification Program" W/o encl.
VASSALLO, D. B Assistant Director for Light Water Reactors, NUREG-0219, 78/08/23 4pp.

7905040482 Notifies of intention to develop safety analysis using existing computer codes. Requests addl info
BOLBRIG, C. W. Commonwealth Edison Co, 79/04/26 1p.

Q. Adjudicatory correspondence

7905090187 Grants petition to intervene by DeKalb Area Alliance for Responsible Energy, Siniissippi Alliance for Environ & League of Women Voters of Rockford, IL. Rejects M. Westerman's petition does not satisfy "interest" requirements
LUTON, E. Atomic Safety and Licensing Board Panel 79/03/23, 3pp.

7905250284 Request by util that ASLB schedule special prehearing conference per 10CFR2.751(a). Certificate of Evc encl
MURPHY, P. M. Isham, Lincoln & Beale 79/04/18 3pp.

7905240334 Responds to 790411 ltr re constituent petition to intervene in facility OL proceeding. ASLB issued order on 790323 holding that B. Weiner Farms had sufficiently demonstrated standing in proceeding
GOSSICK, L. V. Office of the Executive Director for Operations, 79/05/08, 2pp.

H. General correspondence

7905150655 Forwards 790329 ltr from constituent B. Weiner re petition to intervene in OL proceedings. Requests assistance in preparation for intervention
O'BRIEN, G. M. House of Rep. 79/04/11, 3pp.

DOCKETED ITEMS

J. Insurance & indemnity information

7905100163 Endorsement 99 to MAELU Policy MF-22
QERAS, T Nuclear Energy Liability Insurance Association 79/03/27
1p

7905070497 Confirms increased liability limit to \$124,000,000 for
policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
GUATTROCHHI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters. 79/05/01
1p.

7905070567 Forwards amend to application for CP & DL, submitted as
Amend 20 to FSAR
REED, C Commonwealth Edison Co 79/05/02 2pp

--7905070574 Amend 20 to FSAR
* Commonwealth Edison Co 79/05/02 430pp

7905130351 Forwards affidavit of distribution for FSAR Amend 20
NAUGHTON, W F Commonwealth Edison Co 79/05/11 2pp

Q. Inspection reports, IE Bulletins & correspondence

7905020421 Forwards response to IE Bulletins 78-12 & 78-12A, "Atypical
Weld Matl in Reactor Pressure Vessel Welds."
REED, C Commonwealth Edison Co 79/03/22 10pp

7905010236 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23
1p

7905030370 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26
1p.

7905030013 Forwards IE Bulletin 79-06, "Review of Operational Errors &
Bys Misalignments Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/11
1p.

7905010569 Forwards IE Bulletin 79-06A, "Review of Operational Errors &
Bys Misalignments Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/14,
1p.

7905040334 Forwards IE Bulletin 79-06B, "Review of Operational Errors &
Bys Misalignments Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14,
1p.

7905040529 Forwards IE Bulletin 79-08, "Events Relevant to Boiling
Water Reactors Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14
1p.

7905010380 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support
Struts."
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/16,
1p.

7905030206 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2
Circuit Breaker in Safety-Related Bys " Licenses action
required.
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/17
1p.

7905040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at
TMI-Suppl."
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/21
1p.

--7905040158 IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."
Supporting documentation encl.
* Region 3, Chicago, Office of the Director. 79/04/21. 12pp.

--7905040170 ACRS recommendations re 790328 incident at TMI. Suggests high
priority be placed on development of safety research on
behavior of LWRs during anomalous transients.
* ACRS - Advisory Committee on Reactor Safeguards. 79/04/17
2pp

--7905040201 Forwards ACRS recommendations re TMI incident, presented as
790417
FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards
79/04/18 1p.

--7905040221 In response to NRC 790418 ltr, states all 790417 ACRS
recommendations apply to all PWRs, but were not intended to
require immediate changes. Plant mods should be made after
study of effects on overall safety. TMI excluded
CARBON, M X ACRS - Advisory Committee on Reactor Safeguards,
79/04/20 2pp

7905240633 Forwards responses to IE Bulletin 79-07 requesting info re
seismic analysis of safety-related piping. Reanalysis
indicates method of intramodal combination has little effect
on pipe stresses & equipment support loads
REED, C Commonwealth Edison Co 79/04/24 4pp

DOCKET 50-455 BYRON STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905040482 Notices of intention to develop safety analysis using
existing computer codes. Requests addl info.
SOLBRIG, C H Commonwealth Edison Co. 79/04/26. 1p

O. Adjudicatory correspondence

7905090187 Grants petition to intervene by DeKalb Area Alliance for
Responsible Energy, Mississippi Alliance for Environ & League
of Women Voters of Rockford, IL. Rejects H Westerman's
petition does not satisfy "interest" requirements
LUTON, E. Atomic Safety and Licensing Board Panel 79/03/23 3pp

7905230284 Request by util that ASLS schedule special prehearing
conference per 10CFR2 751(a) Certificate of Evc encl
MURPHY, P. M. Isham, Lincoln & Beale. 79/04/18 5pp

7905240334 Responds to 790411 ltr re constituent petition to intervene
in facility DL proceeding ASLS issued order on 790323
holding that B Weiner Farms had sufficiently demonstrated
standing in proceeding
GOSBICK, L V Office of the Executive Director for Operations
79/05/08 2pp

J. Insurance & indemnity information

7905100163 Endorsement 99 to MAELU Policy MF-22
QERAS, T Nuclear Energy Liability Insurance Association 79/03/27
1p.

7905070497 Confirms increased liability limit to \$124,000,000 for
policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
GUATTROCHHI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters 79/05/01
1p

K. Utility Final Safety Analysis Report (FSAR) & amends

7905070567 Forwards amend to application for CP & DL, submitted as
Amend 20 to FSAR
REED, C. Commonwealth Edison Co 79/05/02 2pp.

--7905070574 Amend 20 to FSAR.
* Commonwealth Edison Co 79/05/02 430pp

7905130351 Forwards affidavit of distribution for FSAR Amend 20
NAUGHTON, W. F. Commonwealth Edison Co. 79/05/11. 2pp.

Q. Inspection reports, IE Bulletins & correspondence

7905020421 Forwards response to IE Bulletins 78-12 & 78-12A, "Atypical
Weld Matl in Reactor Pressure Vessel Welds."
REED, C. Commonwealth Edison Co. 79/03/22. 10pp.

7905010236 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23
1p.

DOCKETED ITEMS

221

7905030370 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/03/26
1p

7905030013 Forwards IE Bulletin 79-06, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident "
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/04/11
1p

7905010369 Forwards IE Bulletin 79-06A, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident "
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/04/14
1p

7905040334 Forwards IE Bulletin 79-06B, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident "
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/14
1p

7905040529 Forwards IE Bulletin 79-08, "Events Relevant to Boiling
Water Power Reactors Identified During TMI Incident "
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/14
1p

7905010380 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support
Struts "
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/18
1p.

7905030206 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2
Circuit Breaker in Safety-Related Sys " Licensee action
required
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/17
1p

7905040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at
TMI-Suppl
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/04/21
1p.

--7905040158 IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl "
Supporting documentation encl.
* Region 3, Chicago, Office of the Director 79/04/21 12pp

--7905040170 ACRS recommendations re 790328 incident at TMI Suggests high
priority be placed on development of safety research on
behavior of LWRs during anomalous transients
* ACRS - Advisory Committee on Reactor Safeguards. 79/04/17.
2pp

--7905040201 Forwards ACRS recommendations re TMI incident, presented on
790417.
FRALEY, R F. ACRS - Advisory Committee on Reactor Safeguards.
79/04/18 1p

--7905040221 In response to NRC 790418 ltr, states all 790417 ACRS
recommendations apply to all PWRs, but were not intended to
require immediate changes. Plant mods should be made after
study of effects on overall safety. TMI excluded.
CARSON, M X. ACRS - Advisory Committee on Reactor Safeguards.
79/04/20. 2pp.

7905240633 Forwards responses to IE Bulletin 79-07 requesting info re
seismic analysis of safety-related piping Reanalysis
/ indicates method of intramodal combination has little effect
on pipe stresses & equipment support loads.
REED, C. Commonwealth Edison Co. 79/04/24 4pp

DOCKET 50-456 BRAIDWOOD STATION, UNIT 1

A Application/construction stage documents & correspondence

7905040482 Notifies of intention to develop safety analysis using
existing computer codes Requests addl info
BOLBRIO, C.W. Commonwealth Edison Co. 79/04/26. 1p.

7905220337 Discusses fossil hunting program at facility. Number of
passes will be reduced as const progresses to minimize
possibility of injury & prevent interference w/const. Special
passes are available
REED, C. Commonwealth Edison Co. 79/03/14. 2pp

G. Adjudicatory correspondence

7905300032 Grants petitions to intervene filed by BL Rorem on behalf of
Bailly Alliance & B Weiner Farms, Inc. Rejects M Westerman's
petition to intervene for failure to demonstrate standing.
LUTON, E. Atomic Safety and Licensing Board Panel 79/03/22. 4pp.

7905230284 Request by util that ASLB schedule special prehearing
conference per 10CFR2 751(a). Certificate of Svc encl
MURPHY, P M. Isham, Lincoln & Seale 79/04/18 5pp

7905240334 Responds to 790411 ltr re constituent petition to intervene
in facility OL proceeding ASLB issued order on 790323
holding that B Weiner Farms had sufficiently demonstrated
standing in proceeding
OOSBICK, L.V. Office of the Executive Director for Operations
79/03/08 2pp

J Insurance & indemnity information

7905100163 Endorsement 99 to MAELU Policy MF-22.
GERAS, T. Nuclear Energy Liability Insurance Association 79/03/27
1p

7905070497 Confirms increased liability limit to \$124,000,000 for
policies MF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHINI, J. American Nuclear Insurers 79/03/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M. Mutual Atomic Energy Liability Underwriters 79/03/01
1p

K. Utility Final Safety Analysis Report (FSAR) & amends

7905070567 Forwards amend to application for CP & OL, submitted as
Amend 20 to FSAR
REED, C. Commonwealth Edison Co. 79/03/02 2pp

--7905070574 Amend 20 to FSAR.
* Commonwealth Edison Co 79/03/02. 430pp

7905180351 Forwards affidavit of distribution for FSAR Amend 20
NAUGHTON, W F. Commonwealth Edison Co 79/03/11. 2pp

Q Inspection reports, IE Bulletins & correspondence

7905020421 Forwards response to IE Bulletins 78-12 & 78-12A, "Atypical
Weld Matl in Reactor Pressure Vessel Welds."
REED, C. Commonwealth Edison Co 79/03/22 10pp

7905010236 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping."
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/03/23
1p.

7905030370 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/03/26.
1p.

7905240740 Forwards IE Insp Rpts 50-456/79-04 & 50-457/79-04 on
790320-21 & 23 No noncompliance.
FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/04/10. 2pp

--7903:
No
cor
CI:
ERI
DI:

790503
Sys
KEPP
1p.

790501
Sys
KEPP
1p.

790504
Sys
KEPP
1p.

DOCKETED ITEMS

7905040329 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident" KEPLER, J O Region 3, Chicago, Office of the Director. 79/04/14 1p

7905010380 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts" KEPLER, J O Region 3, Chicago, Office of the Director 79/04/18 1p

7905030206 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required. KEPLER, J O Region 3, Chicago, Office of the Director. 79/04/17. 1p.

7905040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl" KEPLER, J O Region 3, Chicago, Office of the Director 79/04/21 1p

--7905040158 IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl" Supporting documentation encl * Region 3, Chicago, Office of the Director 79/04/21 12pp

--7905040170 ACRS recommendations re 790328 incident at TMI Suggests high priority be placed on development of safety research on behavior of LWRs during anomalous transients * ACRS - Advisory Committee on Reactor Safeguards. 79/04/17. 2pp

--7905040201 Forwards ACRS recommendations re TMI incident, presented on 790417 FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards 79/04/18 1p

--7905040221 In response to NRC 790418 ltr, states all 790417 ACRS recommendations apply to all PWRs, but were not intended to require immediate changes. Plant mods should be made after study of effects on overall safety. TMI excluded. CARBON, M X ACRS - Advisory Committee on Reactor Safeguards 79/04/20 2pp

7905240633 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping Reanalysis indicates method of intramodal combination has little effect on pipe stresses & equipment support loads. REED, C Commonwealth Edison Co 79/04/24 4pp

DOCKET 50-457 BRAIDWOOD STATION, UNIT 2

A. Application/construction stage documents & correspondence

7809050087 Forwards NUREG-0219, "Nuclear Security Personnel for Power Plants, Content & Review Procedures for Security Training & Qualification Program." w/o encl. VASSALLO, D.B. Assistant Director for Light Water Reactors NUREG-0219 78/08/23 4pp

7905040482 Notifies of intention to develop safety analysis using existing computer codes. Requests addl info. BOLBRIO, C W Commonwealth Edison Co 79/04/26 1p

7905220337 Discusses fossil hunting program at facility Number of passes will be reduced as const progresses to minimize possibility of injury & prevent interference w/const Special passes are available REED, C Commonwealth Edison Co 79/05/14 2pp.

Q. Adjudicatory correspondence

7905300032 Grants petitions to intervene filed by BL Rorem on behalf of Bailly Alliance & B Weiner Farms, Inc. Rejects M Westerman's petition to intervene for failure to demonstrate standing. LUTON, E. Atomic Safety and Licensing Board Panel. 79/03/22. 4pp.

7905250284 Request by util that ABLB schedule special prehearing conference per 10CFR2.781(a). Certificate of Svc encl. MURPHY, P.M. Isham, Lincoln & Beale. 79/04/18. 5pp.

7905240334 Responds to 790411 ltr re constituent petition to intervene in facility DL proceeding ABLB issued order on 790323 holding that B Weiner Farms had sufficiently demonstrated standing in proceeding. GOBBICK, L V. Office of the Executive Director for Operations. 79/05/08. 2pp.

H General correspondence

7905150655 Forwards 790329 ltr from constituent B Weiner re petition to intervene in DL proceedings Requests assistance in preparation for intervention O'BRIEN, G M House of Rep 79/04/11 3pp

7905100163 Endorsement 99 to MAELU Policy MF-22 GERAS, T Nuclear Energy Liability Insurance Association 79/03/27 1p.

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others. GUATTROCHI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96 ROBERTS, D M Mutual Atomic-Energy Liability Underwriters. 79/05/01 1p.

K Utility Final Safety Analysis Report (FSAR) & amendments

7905070567 Forwards amend to application for CP & DL, submitted as Amend 20 to FSAR. REED, C. Commonwealth Edison Co. 79/05/02. 2pp

--7905070574 Amend 20 to FSAR * Commonwealth Edison Co 79/05/02 430pp.

7905150351 Forwards affidavit of distribution for FSAR Amend 20 NAUGHTON, W F. Commonwealth Edison Co 79/05/11 2pp

Q. Inspection reports, IE Bulletins & correspondence

7905020421 Forwards response to IE Bulletin 78-12 & 78-12A, "Atypical Weld Metl in Reactor Pressure Vessel Welds" REED, C Commonwealth Edison Co 79/03/22 10pp

7905010236 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping" KEPLER, J.O. Region 3, Chicago, Office of the Director 79/03/23 1p.

7905030370 Forwards IE Info Notice 79-07, "Rupture of Radwaste Units" KEPLER, J.O. Region 3, Chicago, Office of the Director 79/03/24 1p.

7905240740 Forwards IE Insp Repts 50-456/79-04 & 50-457/79-04 on 790320-21 & 23. No noncompliance FIGIELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/10. 2pp

--7905240748 IE Insp Repts 50-456/79-04 & 50-457/79-04 on 790320-21 & 23 No noncompliance noted Major areas inspected: storage of N888 components & safety-related equipment; quality records for Class 2 & 3 equipment & automatic pipe welder operation. ERB, C.M., DANIELSON, D.H. Region 3, Chicago, Office of the Director 79/04/04 4pp.

7905030013 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." KEPLER, J.O. Region 3, Chicago, Office of the Director 79/04/11 1p.

7905010569 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" KEPLER, J.O. Region 3, Chicago, Office of the Director. 79/04/14 1p.

7905040334 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." KEPLER, J.O. Region 3, Chicago, Office of the Director. 79/04/14 1p

7905040329 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident" KEPLER, J.O. Region 3, Chicago, Office of the Director. 79/04/14 1p

DOCKETED ITEMS

223

7905010380 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/18 1p.

7905030206 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
KEPPLER, J. O. Region 3, Chicago, Office of the Director. 79/04/17 1p.

7905040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."
KEPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/21 1p.

--7905040138 IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl." Supporting documentation encl
* Region 3, Chicago, Office of the Director 79/04/21. 12pp.

--7905040170 ACRS recommendations re 790328 incident at TMI. Suggests high priority be placed on development of safety research on behavior of LWRs during anomalous transients.
* ACRS - Advisory Committee on Reactor Safeguards 79/04/17. 2pp

--7905040201 Forwards ACRS recommendations re TMI incident, presented on 790417
FRALEY, R. F. ACRS - Advisory Committee on Reactor Safeguards. 79/04/18. 1p

--7905040221 In response to NRC 790418 ltr, states all 790417 ACRS recommendations apply to all PHRs, but were not intended to require immediate changes. Plant mods should be made after study of effects on overall safety. TMI excluded.
CARBON, M. X. ACRS - Advisory Committee on Reactor Safeguards 79/04/20. 2pp.

7905240633 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping Reanalysis indicates method of intramodal combination has little effect on pipe stresses & equipment support loads.
REED, C. Commonwealth Edison Co 79/04/24 4pp.

DOCKET 50-458 RIVER BEND STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905020437 Forwards NUREG-0531, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/03/23. 2pp.

7905130453 Notifies of reorganization of util's Engineering & Const Dept. JQ Weigand has overall responsibility for River Bend project.
HUMPHREYS, L. L. Gulf States Utilities Co. 79/05/08 1p.

7905310429 Advises of delay from 790601 to 791231 in providing response to NRC concerns re use of austenitic stainless steel in BWR facilities. Presently examining recommendations of pipe crack study in NUREG-0531.
WEIGAND, J. O. Gulf States Utilities Co. 79/05/22. 1p.

7905010277 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/23 1p.

7905010455 Forwards IE Bulletin 79-05A, "Nuclear Incident at TMI - Suppl."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/05. 1p.

7905040489 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/14. 1p.

7905040610 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/14. 1p.

7905070050 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/04/14. 1p.

7905010443 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/04/16 1p.

7905090098 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at TMI"
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/04/16 1p.

7905030267 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/04/17 1p.

B. Reportable occurrences, LERs & related correspondence

7905230808 Confirms 790329 telcon concerning potential deficiency re suspect cadweld sleeve welds mfg by Graver Energy Sys. Will submit interim rpt within 30 days.
HUMPHREYS, L. L. Gulf States Utilities Co. 79/03/30 1p

7905030131 Forwards PNO-79-67H, I, J & K
SEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/04/06 1p.

7905030089 Forwards PNO-79-67L, M, N & P.
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/09. 1p.

7905030091 Forwards PNO-79-67G.
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/10 1p.

7905030139 Forwards PNO-79-67R & 79-77.
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/11. 1p

7905030117 Forwards PNO-79-67S.
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/12 1p.

7905030186 Forwards PNO-79-67T.
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/13. 1p

7905030073 Forwards PNO-79-67U & V.
ENGELKEN, R. H. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/16. 1P.

7905030238 Forwards PNO-79-67W.
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/17. 1p

7905020528 Forwards PNO-79-67AA.
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/20. 1p.

7905020498 Forwards PNO-79-67AB, AC & AD
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/23. 1p.

7905040584 Forwards PNO-79-67AE
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/26. 1p.

7905070180 Forwards PNO-79-67AF & AG.
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/27. 1p.

7905310226 Forwards PNO-79-67AH, AI & AJ.
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/30. 1p.

7905240394 Forwards PNO-79-67AK & AL.
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/05/04. 1p.

DOCKETED ITEMS

DOCKET 50-459 RIVER BEND STATION, UNIT 2

A Application/construction stage documents & correspondence

7905020437 Forwards NUREG-0531, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability
VASSALLO, D B Assistant Director for Light Water Reactors
79/03/23 2pp

7905150453 Notices of reorganization of util's Engineering & Const Dept JO Waigand has overall responsibility for River Bend project
HUMPHREYS, L L Gulf States Utilities Co 79/05/08 1p

7905310429 Advises of delay from 790601 to 791231 in providing responses to NRC concerns re use of austenitic stainless steel in BWR facilities. Presently examining recommendations of pipe crack study in NUREG-0531
WEIGAND, J G Gulf States Utilities Co 79/05/22 1p

G Inspection reports, IE Bulletins & correspondence

7905010277 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
BEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/23 1p

7905010455 Forwards IE Bulletin 79-05A, "Nuclear Incident at TMI - Suppl."
BEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/05 1p

7905040489 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
BEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 1p

7905040610 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
BEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 1p

7905070050 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required.
BEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 1p

7905010443 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
BEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/16 1p

7905090098 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at TMI"
BEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/16 1p

7905030267 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
BEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/17 1p.

B Reportable occurrences, LERs & related correspondence

7905030131 Forwards PNO-79-67H, I, J & K
BEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/06 1p

7905030089 Forwards PNO-79-67L, M, N & P
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/09 1p.

7905030091 Forwards PNO-79-67Q
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/10 1p

7905030139 Forwards PNO-79-67R & 79-77.
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/11 1p.

7905030117 Forwards PNO-79-67S
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/12 1p.

7905030186 Forwards PNO-79-67T
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/13 1p.

7905030073 Forwards PNO-79-67U & V
ENGELKEN, R H Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/16 1p

7905030238 Forwards PNO-79-67W
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/17 1p

7905020528 Forwards PNO-79-67AA
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/20 1p

7905020498 Forwards PNO-79-67AB, AC & AD
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/23 1p

7905040584 Forwards PNO-79-67AE
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/26 1p

7905070180 Forwards PNO-79-67AF & AG.
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/27 1p

7905310226 Forwards PNO-79-67AH, AI & AJ
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/30 1p

7905040394 Forwards PNO-79-67AK & AL
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/04 1p

DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

A Application/construction stage documents & correspondence

7905010486 Repts on geological studies' status. Generic rept expected in Fall 1979. Requests meeting to discuss plans for submitting repts of studies, as well as mechanism for identification & review of studies in Hanford area.
RENNBERGER, D L Washington Public Power Supply System 79/04/27 2pp.

7905240411 Forwards NRC positions on WPPSS-DA-004, "Operational QA Program Description." Response to positions should be submitted by 790601 as amend to original rept.
HAASB, W P Quality Assurance Branch 79/05/01 2pp

7905230534 Requests NRC ltr stating acceptability of scale model tests in lieu of implant tests, to satisfy commitment in WNP-1/4 PSAR Question 6 77 re recirculation sump testing.
RENNBERGER, D L Washington Public Power Supply System 79/05/13 1p

7905010294 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
ENGELKEN, R H Region 4, Dallas, Office of the Director 79/03/23 1p

7905010015 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/04/14 1p

7905040516 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/04/14 1p.

7905040625 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/04/14 1p

7905070110 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required.
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/14 1p.

7905030305 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/17 1p.

7905080378 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/21 1p.

DOCKETED ITEMS

225

7905150069 Forwards PNO-79-67L
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/06 1p

7905150173 Forwards PNO-79-67R
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/11 1p

7905040134 Forwards PNO-79-67S
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/12 1p

7905150150 Forwards PNO-79-67T
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/13 1p

7905030018 Forwards PNO-79-67U
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p

7905020536 Forwards PNO-79-67AA
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/20 1p

7905010439 Forwards PNO-79-67AB
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/21 1p

7905010452 Forwards PNO-79-67AC & AD
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/23 1p

7905010463 Forwards PNO-79-67AE
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director,
79/04/24 1p.

7905090047 Forwards PNO-79-67AF,
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/25 1p

7905090059 Forwards PNO-79-67AG
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/26 1p

7905090121 Forwards PNO-79-67AH
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/27 1p

7905070034 Forwards PNO-79-67AI, AJ & AK per NRC 790401 ltr transmitting
IE Bulletin 79-05
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/30 1p.

7905070018 Forwards PNO-79-67AL per NRC 790401 ltr transmitting IE
Bulletin 79-05,
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director,
79/05/01 1p.

7905190067 Forwards final deficiency rept re letdown cooler supports,
per 790416 telcon
RENNBERGER, D. L. Washington Public Power Supply System. 79/05/07
1p.

--7905190069 Final deficiency rept. letdown cooler supports inadequate to
support specified loads. Caused by inadequate design by
component manufacturer. Wall mounted brackets redesigned.
* Washington Public Power Supply System. 79/05/07 2pp.

7905310037 Forwards PNO-79-67AM.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/05/07 1p.

7905240657 Ack receipt of 790507 final deficiency rept on letdown
cooler support design inadequacy.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director,
79/05/16 1p

DOCKET 50-461 CLINTON POWER STATION, UNIT 1

A Application/construction stage documents & correspondence

7905290563 Notification of proposed reactor pressure vessel mod QE
authorized to act as agent for performance of work which
will be subcontracted to Reactor Controls, Inc. Work to begin
790319,
KOCH, L. J. Illinois Power Co. 79/03/15 1p

7905040330 Requests addl info re 790426 telcon concerning emission
stds for operating nuclear power plants. Seeks info re
gaseous release of U daughters & stds for emission of
radioactive products into cooling water
PENNER, P. Prairie Alliance. 79/04/26 2pp

G. Inspection reports, IE Bulletins & correspondence

7905040347 Forwards IE Insp Rept 50-461/79-02 on 790306-08 Na
noncompliance noted
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/03/22 2pp

--7905040349 IE Insp Rept 50-461/79-02 on 790306-08 Na noncompliance
noted. Major areas inspected reactor coolant pressure
boundary, safety-related piping & welding, QA manuals &
procedures & work activities
LEE, E. W. Region 3, Chicago, Office of the Director
DANIELSON, D. H. Region 3, Chicago, Reactor Construction &
Engineering Support Branch 79/03/19 5pp

7905010257 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping."
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/03/23
1p

7905040035 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/03/26
1p

7905030033 Forwards IE Bulletin 79-06, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident."
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/11
1p

7905010390 Forwards IE Bulletin 79-06A, "Review of Operational Errors &
Sys Misalignments Identified during TMI Incident."
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14
1p.

7905040094 Forwards IE Bulletin 79-06B, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident."
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14
1p.

7905040459 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of
Safety-Related Piping." Licensee action required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14
1p

7905040566 Forwards IE Bulletin 79-08, "Events Relevant to Boiling
Water Power Reactors Identified During TMI Incident."
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14,
1p

7905010426 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support
Struts."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/16
1p

7905030228 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2
Circuit Breaker in Safety-Related Sys." Licensee action
required
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/17.
1p

7905080498 Forwards IE Bulletin 79-09B, "Nuclear Incident at
TMI-Bupl."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/21
1p

7905240906 Forwards IE Circular 79-07, "Unexpected Speed Increase of
Reactor Recirculation Motor Generator Set Resulted in
Reactor Power Increase."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/05/02
1p.

H. Reportable occurrences, LERs & related correspondence

7905290048 Ack receipt of 790307 final rept re drywell wall platework
defects. Review will be completed during future insp.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/03/23 1p.

DOCKETED ITEMS

DOCKET 30-462 CLINTON POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

7905040330 Requests addl info re 790426 telcon concerning emission stds for operating nuclear power plants Seeks info re gaseous release of U daughters & stds for emission of radioactive products into cooling water
PENNER, P Prairie Alliance 79/04/26 2pp

G Inspection reports, IE Bulletins & correspondence

7905010257 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23 1p

7905040035 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26 1p

7905030033 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/11 1p

7905010390 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040394 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040459 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040566 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905010426 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/16 1p

7905030228 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/17 1p

7905080498 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Buppl 1"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/21 1p

7905240906 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/02 1p

DOCKET 30-463 FULTON GENERATING STATION, UNIT 1

G. Adjudicatory correspondence

7905230153 Updates 790302 ltr, advising 10CFR is available in Pottstown, PA Public Library
GRAY, J R Branch 1 79/04/09 1p

7905150114 Discusses notifications not previously supplied in hearings re nuclear power reactors, specifically Lewis Committee Rept & transportation of radionuclides in urban environs.
GRAY, J R Branch 1 79/04/10 3pp

--7905150119 Ack receipt of GW Zimmer memo re neutron exposure at commercial power reactors Data does not imply lack of control by any licensee re neutron exposure, nor does it indicate personnel neutron dosimetry problem exists at LWRS.
EISENHUT, D O Division of Operating Reactors, VOLLMER, R H Assistant Director for Site Analysis 79/03/06 2pp

--7905150139 States that encl 780508 article by J Anderson, "Neutron Radiation at Nuclear Plants" contains factual errors. No calculations have been made of neutron radiation inside nuclear plants. Forwards EO Case 780403 memo
KREGER, W E Commission 78/05/08 3pp

7905230246 Forwards info re behavior of iodine during postulated steam generator tube rupture accidents & aspects of accumulator delivery
GRAY, J R Branch 1 79/04/10 7pp

7905230391 Ack receipt of 790402 ltr & resolution opposing NRC early site suitability review. NRC will consider issues raised.
DEYOUNG, R C Division of Site Safety & Environmental Analysis 79/04/19 1p

--7905230395 Forwards resolution opposing early site suitability review
GALBREATH, P Fulton Orange #66 79/04/02 2pp

H General correspondence

7905150124 Responds to comments re opposition to facility location. NRC is required to conduct an early site review on site suitability issues selected by applicant & does not have initiative in this matter.
BALLARD, R L Environmental Projects Branch 1 79/04/30 1p

J Insurance & indemnity information

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

DOCKET 30-464 FULTON GENERATING STATION, UNIT 2

G Adjudicatory correspondence

7905250153 Updates 790302 ltr, advising 10CFR is available in Pottstown, PA Public Library.
GRAY, J R Branch 1 79/04/09 1p

7905150114 Discusses notifications not previously supplied in hearings re nuclear power reactors, specifically Lewis Committee Rept & transportation of radionuclides in urban environs
GRAY, J R Branch 1 79/04/10 3pp

--7905150119 Ack receipt of GW Zimmer memo re neutron exposure at commercial power reactors Data does not imply lack of control by any licensee re neutron exposure, nor does it indicate personnel neutron dosimetry problem exists at LWRS.
EISENHUT, D O Division of Operating Reactors, VOLLMER, R H Assistant Director for Site Analysis 79/03/06 2pp

--7905150139 States that encl 780508 article by J Anderson, "Neutron Radiation at Nuclear Plants" contains factual errors. No calculations have been made of neutron radiation inside nuclear plants. Forwards EO Case 780403 memo.
KREGER, W E Commission 78/05/08 3pp

7905230246 Forwards info re behavior of iodine during postulated steam generator tube rupture accidents & aspects of accumulator delivery
GRAY, J R Branch 1 79/04/10 7pp

7905230391 Ack receipt of 790402 ltr & resolution opposing NRC early site suitability review. NRC will consider issues raised.
DEYOUNG, R C Division of Site Safety & Environmental Analysis 79/04/19 1p

--7905230395 Forwards resolution opposing early site suitability review
GALBREATH, P Fulton Orange #66 79/04/02 2pp

H. General correspondence

7905150124 Responds to comments re opposition to facility location. NRC is required to conduct an early site review on site suitability issues selected by applicant & does not have initiative in this matter.
BALLARD, R L Environmental Projects Branch 1 79/04/30 1p

DOCKETED ITEMS.

221

J Insurance & indemnity information

7903070497 Confirms increased liability limit to \$124,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
QUATTROCHIHI, J American Nuclear Insurers. 79/03/01 1p.

7903070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/03/01 1p.

DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7903250398 Forwards addl info re reactor pressure vessel off-loading facility, in response to 790328 request.
MCQUIRE, W F Houston Lighting & Power Co. 79/03/17 Bpp

7903310453 Responds to 790426 ltr & updates 771019 list of proposed & listed endangered species. Bald eagles now listed as endangered in TX. Requests biological assessment within 180 days of listed species in plant const area.
WOLSTENHULME, J Interior, Dept. of, Fish & Wildlife Service 79/03/22, 2pp

E. NRC Safety Evaluation Report (SER), supp's & correspondence

7903090299 Forwards Suppl 2 to SER re application for CR.W/o encl.
VAROA, B A Light Water Reactors Branch 4 79/04/09 3pp.

0 Adjudicatory correspondence

7903210381 Urges ABLB to modify 790212 order, grant JH Doherty's intervention petition & admit Contention 2 Certificate of Bvc encl.
BOHINKI, B M. Branch 3 79/03/06. 9pp.

7903080387 Request by Houston Lighting & Power that ABLB deny 790214 motion by JF Doherty & Armadillo Coalition for admission of previously abandoned contentions Certificate of Bvc encl.
CULP, R.H., NEWMAN, J.R., Lowenstein, Newman, Reis, Axelrad & Toll, COPELAND, J.O Baker & Botts 79/03/06. 7pp

7903310013 Response in opposition to TX PIRQ 790202 motion for admission of two contentions previously abandoned due to Class 9 accident prohibition based on Rasmussen Rept. Certificate of Bvc encl.
BOHINKI, B.M. Branch 2 79/03/08. 9pp

7903080331 Houston Lighting & Power's first set of interrogatories & request for production of documents for TX PIRQ. Certificate of Bvc encl.
COPELAND, J.O. Baker & Botts, NEWMAN, J.R., CULP, R.H., Lowenstein, Newman, Reis, Axelrad & Toll. 79/03/13. 28pp

7903080311 Request by Houston Lighting & Power that ABLB deny appeals of eight petitions for intervention filed in response to ALBB 790209 order. Certificate of Bvc encl.
NEWMAN, J.R., REIS, H.F., CULP, R.H., Lowenstein, Newman, Reis, Axelrad & Toll. 79/03/13. 46pp.

7903080320 Request by Houston Lighting & Power that ABLB deny 790223 petition for directed certification filed by TX PIRQ. Petition does not meet criteria of 10CFR2.718(i). Certificate of Bvc encl.
NEWMAN, J.R., REIS, H.F., CULP, R.H., Lowenstein, Newman, Reis, Axelrad & Toll. 79/03/13. 35pp.

7903080392 Requests ABLB deny 790223 petition of TX PIRQ for directed certification. Interlocutory review of question is not needed or proper. Certificate of Bvc encl.
WOODHEAD, C.P. Branch 3. 79/03/19. 14pp.

7903240178 Request to file brief amicus curiae. Certificate of Bvc encl.
ROISHAN, A. Z. Natural Resources Defense Council. PARKER, D.L., ISCOE, D. Georgetown Univ. Law School. 79/03/19. 4pp.

---7903240190 Brief amicus curiae in support of appeal of Natl Lawyers Guild re intervention petition. ABLB denial of petition was contrary to federal standing requirements.
PARKER, D.L., ISCOE, D. Georgetown Univ. Law School. ROISHAN, A. Z. Natural Resources Defense Council. 79/03/19. 21pp.

7903150087 Answers first set of interrogatories & request for production of documents from Houston Lighting & Power Certificate of Bvc encl.
HINDERSTEIN, C. Affiliation Unknown 79/03/26 2pp.

7903250130 Motion for admission of C Hinderstein's Contention 3 Certificate of Bvc encl.
HINDERSTEIN, C Affiliation Unknown 79/03/26 3pp

7903250230 Houston Lighting & Power's response to TX PIRQs first set of interrogatories. Certificate of Bvc encl.
COPELAND, J.O., THRASH, C O Baker & Botts NEWMAN, J.R., Lowenstein, Newman, Reis, Axelrad & Toll 79/03/26 23pp

7903300172 Response to first set of interrogatories submitted by Houston Lighting & Power Certificate of Bvc encl.
DOHERTY, J.F Texas Public Interest Research Group 79/03/27 4pp

---7903300177 First request for production of documents from Houston Lighting & Power Certificate of Bvc encl.
SCOTT, J.M Texas Public Interest Research Group 79/03/27 2pp

7903250135 Answers to interrogatories submitted to B McCorkle by Houston Lighting & Power Co. Certificate of Bvc encl.
MCCORKLE, B A Affiliation Unknown. 79/03/28. 2pp

7903250225 Request by Houston Lighting & Power Co for denial of 790324 motion by C Hinderstein & B McCorkle for 1-month extension of time for discovery Certificate of Bvc encl.
NEWMAN, J.R., REIS, H.F., CULP, R.H Lowenstein, Newman, Reis, Axelrad & Toll 79/03/28 5pp.

7903240360 Second set of interrogatories & requests for production of documents submitted to Houston Lighting & Power. Certificate of Bvc encl.
HINDERSTEIN, C Affiliation Unknown 79/03/29 6pp.

7903240120 Requests to make statement at 790418 hearing. Requests proponents of Wallis Trade Territory be allowed to speak
HAYER, B M Affiliation Unknown 79/03/30 1p.

---7903240124 Requests to make statement at 790418 hearing
MILLS, B Affiliation Unknown 79/04/10 2pp

---7903240132 Requests to make statement at 790418 hearing.
MUELLER, E E Affiliation Unknown 79/04/03 1p

---7903240141 Requests to make statement at 790418 hearing
FUNDERBURKE, W H Affiliation Unknown 79/04/08 1p

7903310409 Consolidates TX PIRQ & RC Hinderstein as intervenors. B McCorkle has until 790417 to complete discovery re contentions of TX PIRQ & C Hinderstein. C Hinderstein must complete discovery by 790502
WOLFE, B.J Atomic Safety and Licensing Board Panel. 79/03/30 3pp

7903250242 First round of interrogatories submitted to State of TX. Certificate of Bvc encl.
SCOTT, J M Texas Public Interest Research Group. 79/03/31 3pp.

7903310042 First set of interrogatories & requests for production of documents submitted to State of TX Certificate of Bvc encl.
HINDERSTEIN, C. Affiliation Unknown. 79/03/31. 5pp.

---7903310077 Third set of interrogatories & requests for production of documents submitted to Util.
HINDERSTEIN, C. Affiliation Unknown. 79/03/31. 4pp.

---7903310080 First set of interrogatories & requests for production of documents submitted to NRC.
HINDERSTEIN, C. Affiliation Unknown. 79/03/31. 3pp

7903310116 Request for production of documents & first set of interrogatories submitted to Houston Lighting & Power. Certificate of Bvc encl.
MCCORKLE, B. Affiliation Unknown. 79/04/01 4pp.

---7903310123 Request for production of documents & first set of interrogatories submitted to State of TX
MCCORKLE, B. Affiliation Unknown. 79/04/01. 2pp.

7903100276 Response to first set of interrogatories propounded by TX PIRQ. Supporting documentation & Certificate of Bvc encl.
BOHINKI, B.M. Branch 3. 79/04/02. 22pp.

DOCKETED ITEMS

- 7903110339 Motion to assume Contentions 2 & 3 re const hearing license raised by intervenor JR Schreffler
SCOTT, J M Texas Public Interest Research Group 79/04/02 2pp.
- 7903300066 Response of util to first interrogatories submitted by C Hinderstein Certificate of Svc encl
COPELAND, J O, THRASH, C O Baker & Botts NEWMAN, J R Lowenstein, Newman, Reis, Axelrad & Toll. 79/04/02 9pp
- 7903300072 Propounds interrogatories to TX PIRO Certificate of Svc encl.
BOHINKI, S M Branch 3 79/04/02 3pp
- 7903310111 First set of interrogatories & request for production of documents submitted to Houston Lighting & Power Certificate of Svc encl
WHITE, M, FAINTER, J W, LOWERRE, R W Texas, State of 79/04/02 9pp
- 7903310407 Response by util to second set of interrogatories from TX PIRO Certificate of Svc encl
COPELAND, J O, THRASH, C O Baker & Botts NEWMAN, J R Lowenstein, Newman, Reis, Axelrad & Toll 79/04/02 11pp
- 7903310382 Motion to postpone 790419 prehearing conference until completion of inquiry re accident at TMI
DOHERTY, J F Affiliation Unknown 79/04/04 4pp
- 7903110336 Supplemental contention re lack of strength of steel containment shell
DOHERTY, J F Affiliation Unknown 79/04/05 2pp
- 7903230161 Motion for admission of supplemental contention re strength of steel containment shell Intervenor asserts that petition is timely Certificate of Svc encl.
DOHERTY, J F Affiliation Unknown 79/04/05. 2pp
- 7903290068 Applicant's response to TX PIRO's undated motion to postpone further pretrial steps except for discovery Urges denial of motion; TX PIRO does not offer justification for delay Certificate of Svc encl
COPELAND, J O, THRASH, C O Baker & Botts NEWMAN, J R Lowenstein, Newman, Reis, Axelrad & Toll 79/04/05 6pp
- 7903310381 First request for production of documents to Houston Lighting & Power Co
DOHERTY, J F Affiliation Unknown 79/04/05 1p.
- 7903220057 Notifies of intention to make oral statement before ASLB on 790418.
BREMAECKER, D E Affiliation Unknown 79/04/06. 1p
- 7903130185 First set of interrogatories & second set of requests for documents, submitted to Houston Lighting & Power Certificate of Svc encl.
DOHERTY, J F Affiliation Unknown. 79/04/09 3pp
- 7903140060 Response to first set of interrogatories from TX PIRO. Certificate of Svc & supporting documentation encl
WHITE, M, FAINTER, J W, LOWERRE, R W Texas, State of 79/04/10 26pp.
- 7903230729 Requests appearance at 790418 prehearing conference in Houston, TX.
BERGREN, J Affiliation Unknown. 79/04/10 1p.
- 7903230736 Requests appearance at 790418 prehearing conference in Houston, TX.
LEWIS, E A Affiliation Unknown. 79/04/11. 2pp
- 7903230744 Requests const of facility.
BILLINGTON, O, PICKINGTON, C Affiliation Unknown
- ility, Expresses concern for public
wn. 79/04/19. 2pp.
- quiry into Allegation of Employee
rtigation to Determine
ing St Lucie " W/o encl.
04/11. 1p.
- tions as issues in controversy, as
Parties have 30 days to
Rescinds due dates for
tomic Safety and Licensing Board Panel).
- 7903100125 Informs of opposition to applicant's request for reconsideration of ASLB order canceling prehearing conference Order is reasonable, in light of issuance of ALAB-535
BOHINKI, S M Branch 3 79/04/12 2pp
- 7903140057 Motion by util for reconsideration of 790404 ALAB-535, as reversed & remanded to ASLB for further consideration Decision creates significant uncertainty re ASLB procedures Certificate of Svc encl
NEWMAN, J R, REIS, H F, CULP, R H Lowenstein, Newman, Reis, Axelrad & Toll 79/04/12. 10pp
- 7903100146 Forwards info re procedures involved in making limited appearance statements, in response to 790402 request
BOHINKI, S M Branch 3. 79/04/13 2pp.
- 7903230477 Submits contentions re reactor safety. Believes FEG is totally inadequate
FRAMSDON, R B, FRAMSDON, M B Affiliation Unknown 79/04/13 3pp.
- 7903240201 Forwards denial of suspension of facility CP Supporting documentation encl
DENTON, H R Office of Nuclear Reactor Regulation 79/04/13 1pp
- 7903240211 Director's denial of 10CFR2 206 request.
BOYD, R S Office of Nuclear Reactor Regulation 79/04/13 8pp.
- 7903240219 Analysis of need for facility.
* Division of Site Safety & Environmental Analysis 79/04/13 3pp
- 7903240227 Responds to RH Froelich 781207 request Forwards mail on Georgians Against Nuclear Energy request to suspend facility CP.
WHITMER, C F Georgia Power Co. 78/12/19 13pp
- 7903240232 TX PIRO's motion for admission of 781101 addl Contention 1
SCOTT, J M Texas Public Interest Research Group. 79/03/22. 3pp
- 7903230735 Expresses opposition to facility const Requests development of alternate sources of energy.
ANDRUS, M, MICHAELS, N, LOTZ, J B Affiliation Unknown. 79/04/16 8pp
- 7903240296 Response to TX PIRO brief supporting admission of renumbered Contention 12 re fire in wiring. Concurs that cable fires should be admitted as issue in controversy. Certificate of Svc encl
BOHINKI, S M Branch 3 79/04/17. 7pp
- 7903240149 Ack receipt of mailgram requesting copy of ALAB-335 which was submitted when ASLB issued ruling on 790404.
BOHINKI, S M Branch 3 79/04/18. 1p.
- 7903220071 Admits TX PIRO Contention 12 as issue in controversy. Discovery procedures shall begin immediately.
WOLFE, B J Atomic Safety and Licensing Board Panel. 79/04/19. 3pp
- 7903240310 Answers by Houston Power & Lighting to third set of interrogatories & requests for production of documents from intervenor C Hinderstein. Certificate of Svc encl
COPELAND, J O, THRASH, C O Baker & Botts NEWMAN, J R Lowenstein, Newman, Reis, Axelrad & Toll 79/04/19. 7pp.
- 7903100391 Requests by Houston Power & Lighting for denial of NRC 790418 motion for clarification of ALAB-535. Also requests that those matters be treated in ruling on util's motion for reconsideration. Certificate of Svc encl.
NEWMAN, J R, REIS, H F, CULP, R H Lowenstein, Newman, Reis, Axelrad & Toll. 79/04/20. 3pp
- 7903240043 Answers by Houston Lighting & Power Co to first set of interrogatories & request for production of documents from intervenor B McCormick. Affidavit & Certificate of Svc encl.
COPELAND, J O, THRASH, C O, NEWMAN, J R Baker & Botts 79/04/20 10pp.
- 7903240363 Notifies that ASLB orders of 790326, 790412 & 790416 have not yet been received, causing delay in response to ASLB order to perfect contentions to 30 days from date of receipt. Requests placement on svc list.
DOHERTY, J F Affiliation Unknown 79/04/23. 1p
- 7903240528 Supports admission of JF Doherty 790405 supplemental contention re strength of steel containment shells. Certificate of Svc encl.
BOHINKI, S M Branch 3. 79/04/23. 4pp

DOCKETED ITEMS

229

7905250239 Answers by Houston Lighting & Power to first set of interrogatories & request for production of documents submitted by State of TX Affidavit & Certificate of Svc encl
COPELAND, J G Baker & Botte, NEWMAN, J R, CULP, R H
Lowenstein, Newman, Reis, Axelrad & Toll 79/04/27 10pp

7905040473 Comments on draft suppl to FES recognition should be given to cumulative impacts of siting two plants adjacent to each other
HEIEROTTO, L E Interior, Dept of, Fish & Wildlife Service
79/04/26 2pp

7905250247 Moves for extension of time in which to submit contentions
Supporting info encl
PDITHOFF, F H Affiliation Unknown 79/05/07 4pp

7905220021 Forwards responses to comments submitted by Commonwealth of MA re draft suppl to FES Certificate of Svc encl
BUTLER, R M Boston Edison Co 79/05/18 45pp

DOCKET 50-467 ALLENS CREEK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7905250398 Forwards addl info re reactor pressure vessel off-loading facility, in response to 790328 request
MCQUIRE, W F Houston Lighting & Power Co 79/05/17 8pp

G Adjudicatory correspondence

7905290654 Forwards rept, "Parameters Bearing on Decision to Limit Siting Efforts to Given Geographical Area," & "Siting Study for Long-Term Power Generating Capacity Expansion," in response to NRC 780407 ltr re alternate sites
BUTLER, R M Boston Edison Co 78/04/13 2pp

7905310453 Responds to 790426 ltr & updates 771019 list of proposed & listed endangered species Bald eagles now listed as endangered in TX Requests biological assessment within 180 days of listed species in plant const area
MOULSTENHULME, J Interior, Dept of, Fish & Wildlife Service
79/05/22 2pp

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients
SCINTO, J F Hearings Division 79/04/02 31pp

G Adjudicatory correspondence

7905140060 Response to first set of interrogatories from TX PIRQ Certificate of Svc & supporting documentation encl
WHITE, M, FAINTER, J W, LOHERRE, R W, Texas, State of 79/04/10 26pp

--7905010136 Board notification staff assessment re nonsafety-grade equipment to mitigate transients
VASSALLO, D B Assistant Director for Light Water Reactors
79/03/29 2pp

7905230729 Requests appearance at 790418 prehearing conference in Houston, TX
BERGREN, J Affiliation Unknown, 79/04/10 1p

--7905010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients More info is required
TEDESCO, R L Assistant Director for Reactor Safety 79/03/16 3pp

--7905230736 Requests appearance at 790418 prehearing conference in Houston, TX.
LEWIS, E A Affiliation Unknown 79/04/11 2pp.

7905070131 Forwards notification of NRC evaluation of new info re flow blockage model for ECCS to determine design conformance
SMITH, B H Branch 2 79/04/02 1p

--7905230744 Protests const of facility
TROCHEBSET, K P, BILLINGTON, O, PICKINOTON, C Affiliation Unknown
79/04/13, 1p

7905240943 Opposes 790507 resumption of evidentiary hearings on alternative site Seeks postponement until 790521
BURT, L Massachusetts, State of 79/04/02 3pp

--7905230751 Opposes const of facility Expresses concern for public safety in event of mishap
MARTIN, A Affiliation Unknown 79/04/19, 2pp

7905100326 Second motion to supplemental hearing record re need for power issue & to defer current hearing schedule w/notice of appearance of MB Meyer on behalf of Commonwealth of MA & Certificate of Svc
BELLOTTI, F X, MEYER, M B, Massachusetts, State of 79/04/04 7pp

DOCKET 50-471 PILGRIM NUCLEAR POWER STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905240794 Forwards info requested in 790420 discussion re evacuation of Cape Cod summer population
BURT, L Massachusetts, State of 79/04/25 6pp

7905290055 Files memo on applicability & effect of 780714 Perkins partial initial decision re environ consequences of U cycle Certificate of Svc encl
SMITH, B H Branch 2 79/04/05 6pp.

7905140435 Forwards response to NRC inquiries re need for power & cost of 3-year delay in operation Response based on NRC load forecast. Starting point not conceded to be appropriate by util Facility will be needed in 1985
BUTLER, R M Boston Edison Co 79/05/08, 6pp

7905070129 Act receipt of motion to resume evidentiary hearings
Hearing should commence on 790507
SMITH, B H Branch 2 79/04/06 1p

7905180397 Forwards responses to question re comparison of projected population densities in PSAR & 1978 update to 1974 site selection study.
BUTLER, R M Boston Edison Co. 79/05/10 14pp.

7905100327 Evidentiary hearings shall resume 790524 in Plymouth, MA & continue on 790525 & 29-0601
LUTON, E Atomic Safety and Licensing Board Panel 79/04/06 2pp

7905300011 Forwards info re NRC load growth cases pertaining to savings associated w/installing facility in 1985 vs 1988 & comparison of annual carrying charges.
BUTLER, R M Boston Edison Co 79/05/23 4pp

7905100336 Memo by util re applicability & effect of Perkins partial initial decision on proceedings. Requests adoption of Perkins findings.
LEWALD, O H Ropes & Gray STODDLEY, D O Boston Edison Co
79/04/10 3pp

D. NRC Draft/Final Environmental Statements, suppl & correspondence

7905240131 Forwards comments received to date on draft suppl to FES. Requests review & response by 790418. W/o encl
REGAN, W H Environmental Projects Branch 2 79/04/10, 2pp.

79052402
supple
has no
is of
LEWALD
79/04/

79052905
EB Chr
CLEET

--79052
CLEI

7905090411 Comments by Commonwealth of MA on draft suppl to FES.
BELLOTTI, F X, BURT, L, WRIGHT, F B Massachusetts, State of
79/04/13 47pp.

79050200
Edison
Comm
encl.
MAZDA

DOCKETED ITEMS

7905290626 Forwards most recent long-range energy & demand forecasts of
util & New England Power Pool in response to Board's 790309
order. Certificate of Svc encl
STOODLEY, D. O. Boston Edison Co 79/03/15. 4pp

--7905290633 "Long-Range Forecast of Electric Power Needs & Requirements.
Annual Suppl 1-C." 1979-1988. Vols 1 & 2.
LYDON, J. H.; DESHOND, J. J. Boston Edison Co 79/04/01 300pp

--7905290637 "New England Load & Capacity Rept." 1978-1989
SMITH, J. R. Boston Edison Co 79/04/01. 55pp

--7905290641 "New England Long-Range Forecast of Electric Power Needs &
Requirements." 1979-1989
SMITH, J. R. Boston Edison Co. 79/03/01. 31pp

--7905290645 "Rept of New England Power Pool Load Forecasting Task Force
on Model-Based Forecast of New England Electric Energy &
Peak Load." 1979-1989
* Boston Edison Co 79/03/01 52pp

--7905290660 "Parameters Bearing on Decision to Limit Siting Efforts to
Given Geographic Area"
* Boston Edison Co 78/04/13 300pp.

--7905290671 "Siting Study For Long-Term Power Generating Capacity
Expansion, 1975-2008." Vols A, B & C
PRALL, T. F. Boston Edison Co 74/02/11 600pp.

I Financial information

7905300013 Forwards response to NRC request for info to complete
financial qualification review
BUTLER, R. M. Boston Edison Co. 79/03/23. 4pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHINI, J. American Nuclear Insurers 79/03/01. 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters 79/03/01.
1p

8 Reportable occurrences, LERs & related correspondence

7905110203 Board notification Seabrook refueling water storage tank
design deficiency
SCINTO, J. Hearings Division. 79/03/29. 30pp

DOCKET 30-472 PILGRIM NUCLEAR POWER STATION, UNIT 3

A. Application/construction stage documents & correspondence

7905130397 Forwards responses to question re comparison of projected
population densities in PSAR & 1978 update to 1974 site
selection study.
BUTLER, R. M. Boston Edison Co 79/03/10. 14pp.

DOCKET 30-477 ATLANTIC GENERATING STATION, UNIT 1

A Application/construction stage documents & correspondence

7905150043 Forwards FR notice re withdrawal of application to construct
& operate generating station.
BALLARD, R. L. Environmental Projects Branch 1. 79/04/23 1p.

DOCKET 30-478 ATLANTIC GENERATING STATION, Unit 2

A. Application/construction stage documents & correspondence

7905150043 Forwards FR notice re withdrawal of application to construct
& operate generating station
BALLARD, R. L. Environmental Projects Branch 1. 79/04/23. 1p.

DOCKET 30-482 WOLF CREEK GENERATING STATION

A. Application/construction stage documents & correspondence

7905020432 Forwards NUREG-0531, "Investigation & Evaluation of Stress
Corrosion Cracking in Piping of LWR Plants" & notice of
issuance & availability. W/o encl.
VABBALLO, D. B. Assistant Director for Light Water Reactors.
79/03/23. 2pp.

7905230731 Notification of 790513 meeting w/KS Gas & Electric Co &
Archel in Burlington, KS to discuss concrete strength of
facility base mat.
LICITRA, E. A. Light Water Reactors Branch 3 79/04/24. 1p.

7905250089 Forwards summary of concrete problems, in response to 790212
request.
OBERICK, L. V. Office of the Executive Director for Operations.
79/03/01. 4pp

7905080514 Forwards test rept of 28-day base mat cylinder Reactor bldg
base mat concrete is uniform & of high quality w/strength
exceeding specified design value of 5,000 psi.
KDESTER, O. L. Kansas Gas & Electric Co. 79/03/03 1p.

--7905080516 "Reactor Base mat Concrete Testing of 28-Day Cylinder
Remnants"
SHIDELER, J. J. Portland Cement Association. 79/04/27 20pp.

7905110311 Forwards "Reanalysis of Wolf Creek Reactor Bldg Base Mat."
per NRC 790208 request
KDESTER, O. L. Kansas Gas & Electric Co 79/03/10 2pp

--7905110314 "Reanalysis of Wolf Creek Reactor Bldg Base Mat"
* Kansas Gas & Electric Co. 79/03/09. 43pp.

O. Adjudicatory correspondence

7905080401 Forwards SAND77-1927, "Transport of Radionuclides in Urban
Environments Working Draft Assessment." BECY-78-311, dtd 780614
& BECY-78-311A, dtd 781109 re impact of working draft
assessment on regulatory policy W/o encl
LEWIS, B. H. Branch 2. 79/03/30 2pp

7905040131 Discusses ltr re sabotage of spent nuclear fuel, being
separately forwarded to ASLAB.
LEWIS, B. H. Branch 2. 79/04/02. 2pp

7905110418 Response to ALAB-509 re radon emissions & de minimus theory
from Perkins record Certificate of Svc encl
SCINTO, J. F. Hearings Division 79/04/11. 45pp.

7905140319 Response to 790404 brief of Philadelphia Electric Co, PSE&Q &
Atlantic City (NJ) Electric Co re de minimus theory
Certificate of Svc encl.
KEPFORD, C. R. Citizens for Safe Environment. 79/04/11 5pp

7905150321 Responds to 790324 ltr requesting hearing for possible sale
of 17% interest to certain rural electric cooperatives.
ENGELHARDT, T. F. Deputy Executive Legal Director 79/04/16 2pp

7905140332 Notices of consolidation of five intervenor groups re radon
emissions issue. Parties have until 790525 in which to file
for summary disposition.
DUFLO, M. E. Atomic Safety and Licensing Appeal Panel. 79/04/25
13pp

7905150639 Responds to encl 781229 mailgram re problems encountered
w/reactor base mat in const of facility. NRC staff action is
being taken to resolve these problems. Response by DOE is
unnecessary.
PREBBESKY, A. J. Energy, Dept. of. 79/01/25. 1p.

--7905150645 Comments on shoddy work being done on reactor base mat.
GROTEWIEL, K. Affiliation Unknown. 79/01/25. 2pp.

--7905150656 Responds to 781229 mailgram re "shoddy work being done on
reactor base mat" at facility. Although concrete apparently
does not meet original design, ultimate suitability yet to
be determined. W/summary of concrete problems.
DAVIS, J. O. Office of Inspection & Enforcement. 79/04/27 5pp

7905240998 Responds to 790125 ltr to JM Hendrie re faulty const.
Revocation of license is being considered. Forwards summary
of concrete problems, petition & FR notice
DAVIS, J. O. Office of Inspection & Enforcement. 79/04/27. 5pp

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHINI, J. American Nuclear Insurers. 79/03/01. 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/03/01.
1p.

DOCKETED ITEMS

831

0 Inspection reports, IE Bulletins & correspondence

7905010302 Forwards IE Insp Rept 50-482/79-03 on 790220-23, notice of violation & notice of deviation
BEIDLE, W C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/14. 2pp.

--7905010306 Notice of violation from insp on 790220-23
* Region 4, Dallas, Office of the Director 79/03/12 1p

--7905010308 Notice of deviation from insp on 790220-23.
* Region 4, Dallas, Office of the Director. 79/03/12 1p

--7905010312 IE Insp Rept 50-482/79-03 on 790220-23. Noncompliance noted failure to follow procedure to conform to Reg Guide 1.55.
OSERO, C. R., TAPIA, J. I. Region 4, Dallas, Office of the Director
HALL, R. E. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/12 12pp

7905010280 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
BEYFRIT, K V. Region 4, Dallas, Office of the Director 79/03/23. 1p.

7905010459 Forwards IE-Bulletin 79-08A, "Nuclear Incident at TMI - Suppl"
BEYFRIT, K V. Region 4, Dallas, Office of the Director 79/04/05. 1p.

7905040494 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
BEYFRIT, K V. Region 4, Dallas, Office of the Director 79/04/14 1p.

7905040617 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
BEYFRIT, K V. Region 4, Dallas, Office of the Director. 79/04/14 1p

7905070062 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
BEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/14 1p.

7905010446 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
BEYFRIT, K V. Region 4, Dallas, Office of the Director. 79/04/18. 1p

7905090100 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at TMI."
BEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/04/16 1p.

7905030273 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
BEYFRIT, K. V. Region 4, Dallas, Office of the Director 79/04/17 1p.

7905300621 Denies 790323 request for extension of time to respond to IE Bulletins 78-12, 78-12A & 78-12B. Generic repts from reactor vessel manufacturer are due by 790501; licensee responses by 790529.
BEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/25 1p.

--7905300626 Requests time extension to 791001 for responding to IE Bulletins 78-12, 78-12A & 78-12B.
KOEESTER, O L. Kansas Gas & Electric Co. 79/03/23 2pp.

7905320857 Clarifies current status of low concrete strength investigation at facility. Relevant documents are available at LPDR in Burlington, KB.
THORNBERG, H. D. Division of Reactor Construction Inspection 79/03/02. 6pp.

--7905320858 Notification of 790515 public meeting w/ util & Bechtel in Burlington, KB to discuss concrete strength of base mat.
LICITRA, E A. Light Water Reactors Branch 3. 79/04/24 2pp.

8. Reportable occurrences, LERs & related correspondence

7905030104 Forwards PNO-79-67H, I, J & K.
BEYFRIT, K V. Region 4, Dallas, Office of the Director 79/04/06 1p.

7905030097 Forwards PNO-79-67L, M, N & P
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/09 1p

7905030099 Forwards PNO-79-67Q
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/10 1p

7905030146 Forwards PNO-79-67R & 79-77
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/11 1p

7905030119 Forwards PNO-79-67S
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/12 1p

7905030193 Forwards PNO-79-67T
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/13 1p

7905030037 Forwards PNO-79-67U & V
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/16 1p

7905030248 Forwards PNO-79-67W
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/17 1p

7905020534 Forwards PNO-79-67AA
BEIDLE, W C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/20 1p

7905020503 Forwards PNO-79-67AB, AC & AD
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/23 1p

7905040575 Forwards PNO-79-67AE
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/26 1p.

7905310411 Withdraws initial notification of reportable deficiency in safety analysis methodology for certain single dropped control rod events Vendor 790410 ltr of notification encl
PETRICK, N A Snupps-Standardized Nuclear Unit Power Plant System 79/04/26 3pp

--7905310418 Confirms 790328 telcon to H Thornburg re reportable deficiency in safety analysis methodology for certain single dropped control rod events
ANDERSON, T M Westinghouse Electric Corp 79/03/30 2pp

7905070046 Forwards PNO-79-67AF & AG
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/27 1p

7905310206 Forwards PNO-79-67AH, AI & AJ.
BEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/30 1p

7905070649 Forwards deficiency rept "Final Rept on Pressurizer Support Anchor Bolts" for SNUPPS units
PETRICK, N A. Snupps-Standardized Nuclear Unit Power Plant System. 79/03/01. 2pp.

--7905070650 "Final Rept on Pressurizer Support Anchor Bolts" for SNUPPS units. Anchor bolts did not have adequate length to get full thread grip for two heavy hex nuts Design drawings revised
MILLER, C L. Snupps-Standardized Nuclear Unit Power Plant System. 79/04/30. 4pp.

7905240418 Forwards PNO-79-67AK & AL.
BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/04. 1p

7905240326 Provides interim significant deficiency rept re essential svc water pump anchor bolts. Preliminary indications show that anchor bolts as originally released for const may be adequate. Significant deficiency rept may be withdrawn.
KOEESTER, O L. Kansas Gas & Electric Co. 79/03/18. 1p.

DOCKETED ITEMS

DOCKET STN-50-483 CALLOWAY PLANT, UNIT 1

O Adjudicatory correspondence

7905160410 Requests consideration of forthcoming motion to show cause seeking order for review of portion of EIS which omitted ref to impact of transmission lines on migrating patterns
OCHSTEIN, D S Missouri, State of 79/05/10 1p

H General correspondence

7905020210 Responds to 790307 request re ltr from R Lauf Forwards "Summary of Progress of Callaway Plant" & "Reactor Licensing Process." Latter not encl
OGBSICK, L V. Office of the Executive Director for Operations 79/04/10 3pp

--7905020212 Requests response to R Lauf ltr if inquiry re NRC involvement w/plant
EAGLETON, T F Senate 79/03/07 1p

G Inspection reports, IE Bulletins & correspondence

7905010268 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23 1p

7905040058 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26 1p

7905030058 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/11 1p.

7905010610 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/14 1p

7905040428 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p.

7905040461 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040595 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905010405 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/16 1p

7905030249 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/17, 1p.

7905080512 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/21, 1p.

B. Reportable occurrences, LERs & related correspondence

7905010411 Withdraws initial notification of reportable deficiency in safety analysis methodology for certain single dropped control rod events. Vendor 790410 ltr of notification encl.
PETRICK, N A Snupps-Standardized Nuclear Unit Power Plant System. 79/04/26. 3pp.

--7905010418 Confirms 790328 telcon to H Thornburg re reportable deficiency in safety analysis methodology for certain single dropped control rod events.
ANDERSON, T M Westinghouse Electric Corp 79/03/30. 2pp

7905070649 Forwards deficiency rept "Final Rept on Pressurizer Support Anchor Bolts" for SNUPPS units
PETRICK, N A Snupps-Standardized Nuclear Unit Power Plant System. 79/05/01. 2pp

--7905070650 "Final Rept on Pressurizer Support Anchor Bolts" for SNUPPS units Anchor bolts did not have adequate length to get full thread grip for two heavy hex nuts Design drawings revised
MILLER, C L Snupps-Standardized Nuclear Unit Power Plant System. 79/04/30 4pp

DOCKET STN-50-484 TYRONE ENERGY PARK, UNIT 1

O Adjudicatory correspondence

7905100133 Memo by util submitting that radon release data & concentration levels contained in Perkins decision are complete & accurate Supports de minimus approach of Perkins board
BLAKE, E L, TRAVIESO-DIAZ, M Shaw, Pittman, Potts, & Trowbridge 79/04/09 9pp

7905240999 Notice of appearance on behalf of Northern States Power Certificate of Evc encl
TRAVIESO-DIAZ, M Shaw, Pittman, Potts, & Trowbridge 79/04/09 3pp

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Evc encl
BCINTO, J F Hearings Division 79/04/11 45pp.

7905140519 Response to 790404 brief of Philadelphia Electric Co. PSE&G & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Evc encl
KEPFORD, C R Citizens for Safe Environment 79/04/11 8pp

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition
DUFLO, M E Atomic Safety and Licensing Appeal Panel 79/04/23 13pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHINI, J American Nuclear Insurers. 79/05/01 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters. 79/05/01 1p.

O. Inspection reports, IE Bulletins & correspondence

7905010261 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/03/23 1p

7905040045 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/03/26 1p

7905030047 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/11 1p

7905010597 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040418 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/14. 1p

7905040443 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/14. 1p.

DOCKETED ITEMS

233

7905040387 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident,"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
1p

7905010419 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/16
1p

7905030235 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/17
1p.

7905080503 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"
KEPPLER, J G Region 3, Chicago, Office of the Director. 79/04/21
1p

G Reportable occurrences, LERs & related correspondence

7905110203 Board notification Seabrook refueling water storage tank design deficiency
SCINTO, J Hearings Division 79/03/29 30pp

79050310411 Withdraws initial notification of reportable deficiency in safety analysis methodology for certain single dropped control rod events. Vendor 790410 ltr of notification encl
PETRICK, N A Snupps-Standardized Nuclear Unit Power Plant System 79/04/26 3pp

--7905310418 Confirms 790328 telcon to H Thornburg re reportable deficiency in safety analysis methodology for certain single dropped control rod events.
ANDERSON, T M Westinghouse Electric Corp 79/03/30 2pp

7905070649 Forwards deficiency rept "Final Rept on Pressurizer Support Anchor Bolts" for SNUPPS units
PETRICK, N A Snupps-Standardized Nuclear Unit Power Plant System 79/03/01 2pp

--7905070650 "Final Rept on Pressurizer Support Anchor Bolts" for SNUPPS units. Anchor bolts did not have adequate length to get full thread grip for two heavy hex nuts. Design drawings revised
MILLER, C L Snupps-Standardized Nuclear Unit Power Plant System 79/04/30 4pp

DOCKET BYN-90-485 BTERLING POWER PROJECT NUCLEAR, UNIT 1

A Application/construction stage documents & correspondence

7905150393 Submits revised Attachment A, B & C to 780728 submittal amending Tech Specs for charcoal filter testing & iodine removal equipment operability
WILKENS, P C Rochester Gas & Electric Corp. 79/09/08 24pp

D Adjudicatory correspondence

7905230497 Licensee's response to ALAB-509. Urges ASLAB to conclude that intervenors have not demonstrated any deficiencies of significance in Perkins record & that health effects re Rn-222 are de minimis & do not require further analysis
LATSON, L K LeBoeuf, Lamb, Leiby & MacRae 79/04/09 80pp

7905290473 Urges withdrawal of CP or remanding of alternative sites issue to ASLB. Contacts ASLB interpretation of "obviously superior" std. Certificate of Svc encl.
REINERT, B Ecology Action of Oswego. 79/04/09. 10pp.

7905230678 Orders extension, until 790411, for NRC to file memo, per 790308 order
CHILK, B. J. Office of the Secretary of the Commission. 79/04/10. 1p.

7905110418 Response to ALAB-509 re radon emissions & de minimis theory from Perkins record Certificate of Svc encl.
SCINTO, J F Hearings Division. 79/04/11 45pp.

7905140519 Response to 790404 brief of Philadelphia Electric Co. PSE&O & Atlantic City (NJ) Electric Co re de minimis theory.
Certificate of Svc encl.
KEPPLER, C. R. Citizens for Safe Environment. 79/04/11 8pp

7905150745 Forwards NRC rept "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Grid Serving St Lucie" W/o encl.
SCHINKS, B. M. Branch 3. 79/04/11. 1p

7905290028 NRC memo in response to NRC 790308 order Supports approval of both 781019 ASLAB decision & formulation of obviously superior test as clear & substantial
BRENNER, L Branch 3 79/04/11 11pp

7905240195 Notice of appearance of MH Voigt & MF McBride on behalf of Rochester Gas & Electric Corp Certificate of Svc encl
VOIGHT, H H, MCBRIDE, M F LeBoeuf, Lamb, Leiby & MacRae 79/04/23 4pp

7905150074 Licensee's reply brief to Ecology Action of Oswego's 790409 opening brief NRC should dismiss Action's petition for review as having been improvidently granted Certificate of Svc encl
VOIGHT, H H, MCBRIDE, M F, LARSON, L K LeBoeuf, Lamb, Leiby & MacRae 79/04/24 14pp

7905310203 Reply to initial briefs re appeal of ALAB-502 Neither applicant nor NRC has made convincing argument for accepting ASLAB interpretation of "obviously superior" Certificate of Svc encl
REINERT, B Ecology Action of Oswego 79/04/24 6pp

7905140332 Notices of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition
DUPLD, M E Atomic Safety and Licensing Appeal Panel 79/04/25 13pp

I Financial information

7905040085 Forwards "Annual Financial Rept 1978" for Rochester Gas & Electric Co. Central Hudson Gas & Electric Co. Niagara Mohawk Power Corp. & Orange & Rockland Utils Repts available in Central Files only
THOMAS, E B LeBoeuf, Lamb, Leiby & MacRae 79/05/02 1p

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHHI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p.

G. Inspection reports, IE Bulletins & correspondence

7905010145 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/23 1p

7905020111 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/11. 1p

7905020360 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14. 1p

7905040104 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14. 1p

7905040295 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905030110 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director. 79/04/17 1p

7905020331 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B H Region 1, Philadelphia, Office of the Director. 79/04/18 1p

DOCKETED ITEMS

S Reportable occurrences, LERs & related correspondence

7905310411 Withdraws initial notification of reportable deficiency in safety analysis methodology for certain single dropped control rod events Vendor ltr of notification on 790410 encl
PETRICK, N A Snupps-Standardized Nuclear Unit Power Plant System 79/04/26 3pp

--7905310418 Confirms 790328 telcon to H Thornburg re reportable deficiency in safety analysis methodology for certain single dropped control rod events
ANDERSON, T M Westinghouse Electric Corp 79/03/30 2pp

7905070649 Forwards deficiency rept "Final Rept on Pressurizer Support Anchor Bolts" for SNUPPS units
PETRICK, N A Snupps-Standardized Nuclear Unit Power Plant System 79/05/01 2pp

--7905070650 "Final Rept on Pressurizer Support Anchor Bolts" for SNUPPS units Anchor bolts did not have adequate length to get full thread grip for two heavy hex nuts Design drawings revised
MILLER, C L Snupps-Standardized Nuclear Unit Power Plant System 79/04/30 4pp

DOCKET STN-30-486 Calloway Plant, Unit 2

A Application/construction stage

O Adjudicatory correspondence

7905160410 Requests consideration of forthcoming motion to show cause seeking order for review of portion of EIS which omitted ref to impact of transmission lines on migrating patterns
OCHSTEIN, D S Missouri, State of 79/05/10 1p

H General correspondence

7905020210 Responds to 790307 request re ltr from R Lauf Forwards "Summary of Progress of Calloway Plant" & "Reactor Licensing Process" Letter not encl
GOSSICK, L Y Office of the Executive Director for Operations 79/04/10 3pp

--7905020212 Requests response to R Lauf ltr if inquiry re NRC involvement w/plant
EAGLETON, T F Senate 79/03/07 1p

Q Inspection reports, IE Bulletins & correspondence

7905010268 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23 1p

7905040058 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26 1p

7905030058 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/11 1p

7905010610 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040428 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040461 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required.
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040595 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905010405 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Bruts"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/16 1p.

7905030249 Forwards IE Bulletin 79-09, "Failures of OE Type AX-2 Circuit Breaker in Safety-Related Sys" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/17 1p

7905080512 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl 1"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/21 1p

7905310411 Withdraws initial notification of reportable deficiency in safety analysis methodology for certain single dropped control rod events Vendor ltr of notification on 790410 encl
PETRICK, N A Snupps-Standardized Nuclear Unit Power Plant System 79/04/26 3pp

--7905310418 Confirms 790328 telcon to H Thornburg re reportable deficiency in safety analysis methodology for certain single dropped control rod events
ANDERSON, T M Westinghouse Electric Corp 79/03/30 2pp

7905070649 Forwards deficiency rept "Final Rept on Pressurizer Support Anchor Bolts" for SNUPPS units
PETRICK, N A Snupps-Standardized Nuclear Unit Power Plant System 79/05/01 2pp

--7905070650 "Final Rept on Pressurizer Support Anchor Bolts" for SNUPPS units Anchor bolts did not have adequate length to get full thread grip for two heavy hex nuts Design drawings revised.
MILLER, C L Snupps-Standardized Nuclear Unit Power Plant System 79/04/30 4pp

DOCKET STN-30-488 PERKINS NUCLEAR STATION, UNIT 1

O Adjudicatory correspondence

7905300079 Applicant's reply to intervenors' further supplemental proposed finding of fact & conclusions of law Certificate of Svc encl.
MCGARRY, J M Duke Power Co 79/03/21 22pp.

7905300056 NRC opposes intervenors' 790121 motion to reopen record to consider reactor safety study, geology, seismology, foundation & hydrology. Recommends motion be denied as lacking basis in law & fact. Certificate of Svc encl
BARTH, C A Branch 3 79/03/26 9pp

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients
SCINTO, J F Hearings Division 79/04/02 31pp

--7905010156 Board notification staff assessment re nonsafety-grade equipment to mitigate transients
VASSALLO, D B Assistant Director for Light Water Reactors 79/03/29 2pp

--7905010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients. More info is required.
TEDESCO, R L Assistant Director for Reactor Safety 79/03/16 3pp

7905240635 Forwards Vollmer 780222 memo re behavior of iodine during postulated steam generator tube rupture accidents.
BARTH, C A Branch 3 79/04/05 1p

7905250099 Forwards memo discussing info re behavior of iodine during postulated steam generator tube rupture accidents.
BARTH, C A Branch 3 79/04/10 1p.

7905020105 Responds to 790402 telegram re proposed facilities Results of NRC analysis of TMI incident will be forwarded when available.
YORE, F R Atomic Safety and Licensing Board Panel 79/04/17 1p

--7905020149 Requests proposed licensing of facility be held up, pending NRC assessment of TMI
NEAL, S. L. House of Rep. 79/04/02 1p

7905290475 Opposes intervenors' 790305 motion to reopen record & defer indefinitely issuance of initial decision on generic safety issue considerations Certificate of Svc encl.
MCGARRY, J M Duke Power Co 79/04/18 8pp

7905240667 Requests temporary moratorium on licensing of nuclear plants, in light of TMI incident
PERKINS, L HARRIS, P BERECHER, J Affiliation Unknown 79/04/30 4pp.

DOCKETED ITEMS

235

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHILI, J. American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters 79/05/01 1p

G. Inspection reports, IE Bulletins & correspondence

7905010183 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/03/23. 2pp.

7905030301 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/03/26 2pp

7905040185 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/14 2pp.

7905040266 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/14 2pp

7905040346 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/14. 1p

7905010356 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/16 1p

7905030153 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/17 1p

7905020453 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/18. 2pp

B Reportable occurrences, LERs & related correspondence

7905110203 Board notification: Seabrook refueling water storage tank design deficiency.
BCINTO, J. Hearings Division 79/03/29. 30pp

DOCKEY BTH-50-489 PERKINS NUCLEAR STATION, UNIT 2

C. Adjudicatory correspondence

7905300099 Applicant's reply to intervenors' further supplemental proposed finding of fact & conclusions of law. Certificate of Bvc encl.
HOGARRY, J.M. Duke Power Co 79/03/21 22pp.

7905300056 NRC opposes intervenors' 790121 motion to reopen record to consider reactor safety study, geology, seismology, foundation & hydrology. Recommends motion be denied as lacking basis in law & fact. Certificate of Bvc encl.
BARTH, C.A. Branch 3. 79/03/26. 9pp.

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients.
BCINTO, J.F. Hearings Division. 79/04/02 31pp.

--7905010156 Board notification: staff assessment re nonsafety-grade equipment to mitigate transients.
VASSALLO, D.B. Assistant Director for Light Water Reactors. 79/03/29. 2pp.

--7905010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients. More info is required
TEDESCO, R.L. Assistant Director for Reactor Safety 79/03/16 3pp

7905240635 Forwards Vollmer 780222 memo re behavior of iodine during postulated steam generator tube rupture accidents
BARTH, C.A. Branch 3 79/04/05 1p

7905250099 Forwards memo discussing info re behavior of iodine during postulated steam generator tube rupture accidents
BARTH, C.A. Branch 3 79/04/10 1p

7905020105 Responds to 790402 telegram re proposed facilities Results of NRC analysis of TMI incident will be forwarded when available.
YOBE, T.R. Atomic Safety and Licensing Board Panel 79/04/17 1p

--7905020149 Requests proposed licensing of facility be held up, pending NRC assessment of TMI
NEAL, B.L. House of Rep 79/04/02 1p

7905290475 Opposes intervenors' 790305 motion to reopen record & defer indefinitely issuance of initial decision on generic safety issue considerations Certificate of Bvc encl
MCQUARRY, J.M. Duke Power Co 79/04/18 8pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHILI, J. American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters 79/05/01 1p

G. Inspection reports, IE Bulletins & correspondence

7905010183 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905030301 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/03/26 2pp

7905040185 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/14 2pp

7905040266 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/14. 2pp.

7905040346 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/14. 1p.

7905010356 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/18. 1p

7905030153 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/17. 1p.

7905020453 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/18 2pp

DOCKETED ITEMS

B Reportable occurrences, LERs & related correspondence

7905110203 Board notification Seabrook refueling water storage tank design deficiency
SCINTO, J Hearings Division 79/03/29 30pp

DOCKET STN-50-490 PERKINS NUCLEAR STATION, UNIT 3

C Adjudicatory correspondence

7905300099 Applicant's reply to intervenors' further supplemental proposed finding of fact & conclusions of law Certificate of Bvc encl
MCARRY, J M Duke Power Co. 79/03/21. 22pp.

7905300056 NRC opposes intervenors' 790121 motion to reopen record to consider reactor safety study, geology, seismology, foundation & hydrology. Recommends motion be denied as lacking basis in law & fact Certificate of Bvc encl
BARTH, C A Branch 3. 79/03/26 9pp

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients
SCINTO, J F Hearings Division 79/04/02 31pp

--7905010156 Board notification staff assessment re nonsafety-grade equipment to mitigate transients
VASSALLO, D B Assistant Director for Light Water Reactors 79/03/29 2pp

--7905010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients. More info is required
TEDESCO, R L Assistant Director for Reactor Safety 79/03/16 3pp

7905240635 Forwards Vollmer 790222 memo re behavior of iodine during postulated steam generator tube rupture accidents.
BARTH, C A Branch 3 79/04/05 1p

7905250099 Forwards memo discussing info re behavior of iodine during postulated steam generator tube rupture accidents
BARTH, C A Branch 3 79/04/10 1p

7905020105 Responds to 790402 telegram re proposed facilities. Results of NRC analysis of TMI incident will be forwarded when available
YORE, T R Atomic Safety and Licensing Board Panel 79/04/17. 1p

--7905020149 Requests proposed licensing of facility be held up, pending NRC assessment of TMI.
NEAL, S L House of Rep 79/04/02 1p

7905240667 Requests temporary moratorium on licensing of nuclear plants, in light of TMI incident
PERKINS, L; HARRIS, P; BERECHER, J Affiliation Unknown 79/04/30. 4pp.

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATROCHCHI, J American Nuclear Insurers 79/05/01 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D M Mutual Atomic Energy Liability Underwriters. 79/03/01 1p

G. Inspection reports, IE Bulletins & correspondence

7905010183 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23. 2pp.

7905030301 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/26 2pp.

7905040185 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14. 2pp.

7905040266 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/14 2pp

7905040346 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident."
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905010356 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Brackets"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 1p

7905030153 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Bys" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 1p

7905020453 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp.

B Reportable occurrences, LERs & related correspondence

7905110203 Board notification Seabrook refueling water storage tank design deficiency
SCINTO, J Hearings Division 79/03/29 30pp

DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1

C Adjudicatory correspondence

7905080359 Forwards DF Ross memo re accumulator characteristics identified during study of ECCS performance
BARTH, C A Branch 3. 79/04/05 2pp

--7905080361 Discusses aspects of LOFT tests re accumulator delivery & effect on ECCS performance. Participants having approved licensing models should provide addl relevant info
ROSS, D F Assistant Director for Reactor Safety 79/04/03 3pp.

7905090147 Forwards memos discussing problems experienced in connection w/pipes support base plate design.
BARTH, C A Branch 3 79/04/05 2pp

--7905090150 Forwards 780928 Board notification pipe support base plate design. Requests notification of decision as to whether licensing boards will be notified.
SCINTO, J F Office of the Executive Legal Director 78/10/11 1p.

7905240738 Forwards memo re behavior of iodine during postulated steam generator tube rupture accidents
BARTH, C A Branch 3 79/04/05. 1p

7905290195 Forwards memo re sabotage of spent fuel NRC assessment of significance of info will be forwarded to Board when available
BARTH, C A Branch 3. 79/04/05 2pp

7905230061 Response filed per ALAB-509 Perkins Licensing Board's use of de minimus theory was appropriate & in compliance w/applicable law Certificate of Bvc encl.
MCARRY, J M Duke Power Co. 79/04/09 11pp

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Bvc encl
SCINTO, J F Hearings Division 79/04/11. 45pp

7905140519 Response to 790404 brief of Philadelphia Electric Co. PSEL & Atlantic City (NJ) Electric Co re de minimus theory. Certificate of Bvc encl
KEPFORD, C R Citizens for Safe Environment 79/04/11. 8pp

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue. Parties have until 790525 in which to file for summary disposition.
DUFLON, M E Atomic Safety and Licensing Appeal Panel 79/04/25 13pp.

DOCKETED ITEMS

237

Insurance & indemnity information

22 Confirms increase in liability limit to \$36,000,000 for
MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
92, 93, 94, 95 & 96
D M Mutual Atomic Energy Liability Underwriters 79/05/01

Inspection reports, IE Bulletins & correspondence

33 Forwards IE Info Notice 79-06, "Stress Analysis of
Related Piping"
Y, J P Region 2, Atlanta, Office of the Director
23. 2pp

31 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks,"
Y, J P Region 2, Atlanta, Office of the Director
26. 2pp

29 Ack receipt of IE Insp Repts 50-491/79-05, 50-492/79-05 &
79-05 on 790227-0302 No proprietary info
C. Duke Power Co 79/04/06 1p

2726 Forwards IE Insp Repts 50-491/79-05, 50-492/79-05, &
79-05 on 790227-0302 No noncompliance noted
Y, C E Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 79/03/30 2pp

2752 IE Insp Repts 50-491/79-05, 50-492/79-05 & 50-493/79-05 on
79-0302, No noncompliance noted. Major areas inspected:
plant, rebar storage, concrete procedures, specs, records
blasting controls
B, J R, BRYANT, J C Region 2, Atlanta, Reactor
Construction & Engineering Support Branch 79/03/27 5pp

35 Forwards IE Bulletin 79-06B, "Review of Operational Errors &
Misalignments Identified During TMI Incident"
Y, J P Region 2, Atlanta, Office of the Director
14 2pp

53 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of
Related Piping" Licensee action required
Y, J P Region 2, Atlanta, Office of the Director
14 2pp

66 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of
Related Piping" Licensee action required
Y, J P Region 2, Atlanta, Office of the Director
14 2pp

46 Forwards IE Bulletin 79-08, "Events Relevant to Boiling
Power Reactors Identified During TMI Incident"
Y, J P Region 2, Atlanta, Office of the Director
14 1p

56 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support
Struts"
Y, J P Region 2, Atlanta, Office of the Director.
18 1p

53 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2
Breaker in Safety-Related Sys" Licensee action
ed.
Y, J P Region 2, Atlanta, Office of the Director
17. 2pp.

53 Forwards IE Bulletin 79-06A, Revision 1, "Review of
Operational Errors & Sys Misalignments Identified During TMI
Incident"
Y, J P Region 2, Atlanta, Office of the Director
18. 2pp

20 Ack receipt of IE Insp Repts 50-491/79-07, 50-492/79-07 &
79-07 on 790320 & 23 No proprietary info
C. Duke Power Co. 79/04/25, 1p.

2525 Forwards IE Insp Repts 50-491/79-07, 50-492/79-07 &
79-07 on 790320 & 23. No noncompliance noted
Y, C E Region 2, Atlanta, Reactor Construction &
Engineering Support Branch 79/04/09. 2pp

2537 IE Insp Repts 50-491/79-07, 50-492/79-07 & 50-493/79-07 on
79-0302 & 23. No noncompliance noted. Major areas inspected:
batch plant, rebar storage, concrete procedures, specs, records
blasting controls
B, J R Region 2, Atlanta, Office of the Director
Y, J C Region 2, Atlanta, Reactor Construction &
Engineering Support Branch. 79/04/06 6pp

DOCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

O. Adjudicatory correspondence

7905080359 Forwards DF Ross memo re accumulator characteristics
identified during study of ECCS performance
BARTH, C A Branch 3 79/04/05 2pp

7905090147 Forwards memos discussing problems experienced in connection
w/pipe support base plate design.
BARTH, C A Branch 3 79/04/05 2pp

7905090150 Forwards 780928 Board notification pipe support base plate
design Requests notification of decision as to whether
licensing boards will be notified
SCINTO, J F Office of the Executive Legal Director 78/10/11
1p

7905240738 Forwards memo re behavior of iodine during postulated steam
generator tube rupture accidents
BARTH, C A Branch 3 79/04/05 1p

7905290195 Forwards memo re sabotage of spent fuel NRC assessment of
significance of info will be forwarded to Board when
available
BARTH, C A Branch 3 79/04/05 2pp

7905250061 Response filed per ALAB-509, Perkins Licensing Board's use of
de minimus theory was appropriate & in compliance
w/applicable law Certificate of Svc encl
MCGARRY, J M Duke Power Co 79/04/09 11pp

7905110418 Response to ALAB-509 re radon emissions & de minimus theory
from Perkins record Certificate of Svc encl
SCINTO, J F Hearings Division 79/04/11 49pp.

7905140319 Response to 790404 brief of Philadelphia Electric Co, PSE&O &
Atlantic City (NJ) Electric Co re de minimus theory.
Certificate of Svc encl
KEPFORD, C R. Citizens for Safe Environment 79/04/11 8pp

7905140332 Notifies of consolidation of five intervenor groups re radon
emissions issue. Parties have until 790525 in which to file
for summary disposition.
DUFLO, M E. Atomic Safety and Licensing Appeal Panel. 79/04/25
13pp

J Insurance & indemnity information

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01
1p

G. Inspection reports, IE Bulletins & correspondence

7905010356 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support
Struts"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/18 1p

7905010183 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/03/23 2pp

7905030301 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks,"
O'REILLY, J P Region 2, Atlanta, Office of the Director.
79/03/26. 2pp.

7905230699 Ack receipt of IE Insp Repts 50-491/79-05, 50-492/79-05 &
50-493/79-05 on 790227-0302. No proprietary info.
DAIL, L. C. Duke Power Co 79/04/06 1p

7905230726 Forwards IE Insp Repts 50-491/79-05, 50-492/79-05, &
50-493/79-05 on 790227-0302. No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction &
Engineering Support Branch. 79/03/30. 2pp.

7905230752 IE Insp Repts 50-491/79-05, 50-492/79-05 & 50-493/79-05 on
790227-0302 No noncompliance noted. Major areas inspected:
batch plant, rebar storage, concrete procedures, specs, records
blasting controls
HARRIS, J R, BRYANT, J C Region 2, Atlanta, Reactor
Construction & Engineering Support Branch. 79/03/27 5pp.

DOCKETED ITEMS

7905040185 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/04/14 2pp.

7905040263 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/04/14 2pp

7905040266 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/04/14 2pp

7905040346 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/04/14 1p

7905030153 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/04/17 1p

7905020453 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/04/18 2pp

7905240320 Ack receipt of IE Insp Repts 50-491/79-07, 50-492/79-07 & 50-493/79-07 on 790320 & 23 No proprietary info
DALL, L.C. Duke Power Co 79/04/25 1p

--7905240525 Forwards IE Insp Repts 50-491/79-07, 50-492/79-07 & 50-493/79-07 on 790320 & 23 No noncompliance noted
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/09 2pp.

--7905240537 IE Insp Repts 50-491/79-07, 50-492/79-07 & 50-493/79-07 on 790320 & 23 No noncompliance noted Major areas inspected: procedures for erection of containment, steel structures & supports, erection work & quality records
SHAN, M.B. Region 2, Atlanta, Office of the Director
BRYANT, J.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/06 6pp.

DOCKET BTN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3

Q. Adjudicatory correspondence

7905080359 Forwards DF Ross memo re accumulator characteristics identified during study of ECCB performance.
BARTH, C.A. Branch 3 79/04/05 2pp

7905090147 Forwards memo discussing problems experienced in connection w/pipe support base plate design.
BARTH, C.A. Branch 3 79/04/05, 2pp

--7905090150 Forwards 780928 Board notification pipe support base plate design. Requests notification of decision as to whether licensing boards will be notified.
SCINTO, J.F. Office of the Executive Legal Director 78/10/11 1p

7905240738 Forwards memo re behavior of iodine during postulated steam generator tube rupture accidents
BARTH, C.A. Branch 3, 79/04/05 1p

7905290195 Forwards memo re sabotage of spent fuel NRC assessment of significance of info will be forwarded to Board when available.
BARTH, C.A. Branch 3 79/04/05, 2pp.

7905250061 Response filed per ALAB-509 Perkins Licensing Board's use of de minimus theory was appropriate & in compliance w/applicable law Certificate of BVC encl.
MCQARRY, J.M. Duke Power Co. 79/04/09 11pp.

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record. Certificate of BVC encl.
SCINTO, J.F. Hearings Division, 79/04/11, 45pp.

7905140519 Response to 790404 brief of Philadelphia Electric Co, PSE&G & Atlantic City (NJ) Electric Co re de minimus theory. Certificate of BVC encl.
KEPPFORD, C.R. Citizens for Safe Environment, 79/04/11, 8pp.

7905140332 Notices of consolidation of five intervenor groups re radon emissions issue Parties have until 790523 in which to file for summary disposition
DUFFLO, M.E. Atomic Safety and Licensing Appeal Panel, 79/04/25 13pp.

J. Insurance & indemnity information

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905010183 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/03/23 2pp

7905030301 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tank"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/03/26 2pp

7905230699 Ack receipt of IE Insp Repts 50-491/79-05, 50-492/79-05 & 50-493/79-05 on 790227-0302 No proprietary info
DALL, L.C. Duke Power Co 79/04/06 1p

--7905230726 Forwards IE Insp Repts 50-491/79-05, 50-492/79-05 & 50-493/79-05 on 790227-0302 No noncompliance noted
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/30 2pp

--7905230752 IE Insp Repts 50-491/79-05, 50-492/79-05 & 50-493/79-05 on 790227-0302 No noncompliance noted Major areas inspected: batch plant, rebar storage, concrete procedures, specs, records & blasting controls
HARRIS, J.R. & BRYANT, J.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/27 5pp

7905040185 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/04/14 2pp.

7905040263 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/04/14, 2pp

7905040266 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/04/14, 2pp

7905040346 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/04/14, 1p

7905010356 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/04/18 1p.

7905030153 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director
79/04/17 1p.

7905020453 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director.
79/04/18, 2pp.

7905240320 Ack receipt of IE Insp Repts 50-491/79-07, 50-492/79-07 & 50-493/79-07 on 790320 & 23 No proprietary info.
DALL, L.C. Duke Power Co 79/04/25, 1p.

--7905240525 Forwards IE Insp Repts 50-491/79-07, 50-492/79-07 & 50-493/79-07 on 790320 & 23 No noncompliance noted.
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 79/04/09 2pp.

DOCKETED ITEMS

239

--7903240337 IE Insp Repts 30-491/79-07, 30-492/79-07 & 30-493/79-07 on 790320 & 23 No noncompliance noted Major areas inspected procedures for erection of containments, steel structures & supports, erection work & quality records
SHAN, H. B Region 2, Atlanta, Office of the Director
BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/06 6pp

DOCKET BTN-50-495 SWEBSAR-P1

A Application/construction stage documents & correspondence

7903070446 Responds to NRC 790124 ltr requesting addl info re preliminary design approval Forwards list of cross-referenced categories as aid in review
KENNEDY, W. J Stone & Webster Engineering Corp 79/05/03 2pp

--7903070452 Discusses extension review re preliminary design approvals: Requests assessment of SWEBSAR/REBAR-41 design compared to Category I-IV items.
BOYD, R. B. Division of Project Management 79/01/24 28pp

7903220232 Forwards set of SWEBSAR-P1 through Amend 23 for preliminary design assessment per T Cox request & index committed to in until 790303 ltr to RB Boyd
CULP, W. O Stone & Webster Engineering Corp 79/05/14 4pp

DOCKET BTN-50-498 SOUTH TEXAS PROJECT, UNIT 1

A Application/construction stage documents & correspondence

7903100049 Requests addl info in areas of mechanical engineering, structural engineering & sys analysis, for review of FSAR.
PARR, O. D. Light Water Reactors Branch 3 79/04/13 16pp.

7903300372 Requests addl info re metallurgy to complete review of FSAR
PARR, O. D. Light Water Reactors Branch 3 79/04/30 7pp

7903240867 Notification of 790310 meeting w/util in Bethesda, MD to discuss first round questions dealing w/soil structure interaction analysis
LITITRA, E Light Water Reactors Branch 3 79/05/04 3pp

F Security, medical, emergency & fire protection plans

7903030336 Forwards Amend 1 to physical security plan Plan withheld (ref 10CFR2 790)
TURNER, E. A. Houston Lighting & Power Co. 79/05/01 1p.

G. Adjudicatory correspondence

7903250386 Responds to Citizens for Equitable Utils 790223 petition to Intervene Petition should be granted because standing is shown Certificate of Bvc encl.
MCQUURREN, H. J. Branch 1. 79/03/12. 17pp

7903250170 Request by applicant that ASLB issue addl procedures prior to ruling on 780830 petition to intervene from Citizens Concerned About Nuclear Power, Certificate of Bvc encl.
NEWMAN, J. R., REIS, H. F., CULP, R. H. Lowenstein, Newman, Reis, Axelrad & Toll. 79/03/14. 8pp.

7903300081 NRC response to Houston Lighting & Power 790314 motion for addl procedures requested from Citizens Concerned About Nuclear Power, Request violates limitations stated in NRC Rules of Practice Certificate of Bvc encl.
MCQUURREN, H. J. Branch 1. 79/03/29. 8pp.

7903300064 Response to applicant's motion to provide ASLB w/790319 decision in Health Research Group vs Kennedy Reproduced from "Legal Times of Washington." Certificate of Bvc encl.
MCQUURREN, H. J. Branch 1 79/04/02. 3pp.

7903250318 Assignment of RB Balzman, JH Buck & MC Farrar to ASLB for proceeding.
DUFLO, H. E. Atomic Safety and Licensing Appeal Panel. 79/04/17. 1p

7903250328 Notice of appeal by Houston Lighting & Power of 790403 order granting intervention to Citizens Concerned About Nuclear Power, Citizens for Equitable Utils & Austin Citizens for Economical Energy, Certificate of Bvc encl.
NEWMAN, J. R., REIS, H. F., CULP, R. H. Lowenstein, Newman, Reis, Axelrad & Toll. 79/04/17. 5pp.

7903290002 Reply by applicants to NRC 790420 motion for extension of time & to Citizens for Equitable Utils 790422 motion for continuance Both motions are unnecessary & unreasonable Certificate of Bvc encl.
SCHWARZ, M. D. Baker & Botts NEWMAN, J. R., CULP, R. H. Lowenstein, Newman, Reis, Axelrad & Toll 79/04/27 5pp

H General correspondence

7903090007 FOIA request for "Prehearing Conference Order Ruling Upon Intervention Petitions" & "Part 2 Rules of Practice for Domestic Licensing Proceedings"
RYAN, C. R. Citizens Concerned About Nuclear Power, Inc 79/04/10 1p

7903010024 Response to FOIA request for "Prehearing Conference Order Ruling Upon Intervention Petitions," & "Part 2 Rules of Practice for Domestic Licensing Proceedings" Forwards requested info H/o encl
FELTON, J. M. Division of Rules and Records 79/04/24 1p

7903080408 Forwards Amend 3 to FSAR
TURNER, E. A. Houston Lighting & Power Co 79/05/04 3pp

--7903080409 Amend 3 to FSAR
* Houston Lighting & Power Co 79/05/04 500pp

7903130236 Forwards supplemental info to Amend 3 to FSAR covering Const Procedure AD40KPCCP-14 & GA vibrofloatation insp rept dtd 760503
TURNER, E. A. Houston Lighting & Power Co 79/05/09 70pp

M Antitrust correspondence

7903130345 Forwards TX Utils Co & subsidiaries' answer to NRC initial interrogatories & requests for production of documents Reserves rights to file objections & protective order before
790305 Certificate of Bvc encl
SLICKEY, F. K. Worsham, Forsythe & Sampsels 79/03/01 1p

7903020232 Grants 790317 motion by Public Utils Board of Brownsville, TX seeking extensions, until 790330 & 790405, in which to compel fuller responses to Board's interrogatories
MARSHALL, E. M. Atomic Safety and Licensing Board Panel 79/03/22 1p

7903240127 Notifies that location of deposition of LC Peeler of Monsanto Co has been changed from Holiday Inn, Alvin, TX to Butler, Binion, Rice, Cook & Knapp law ofcs in Houston, TX
RYAN, T. O. Isham, Lincoln & Beale. 79/03/22 5pp

7903020480 Order protecting confidentiality of info sought by Houston Lighting & Power from Central Power & Light, West TX Utils, Public Bvc of OK & Southeastern Electric Power Co
MILLER, M. E. Atomic Safety and Licensing Board Panel 79/03/23 5pp.

7903310020 Response by util to second set of interrogatories & request for production of documents, submitted to Central Power & Light Also moves for protective order Certificate of Bvc encl
BARNETT, E. W. Baker & Botts 79/03/28 25pp

7903070040 Advises that deposition of Edward Sherry, Air Products & Chemicals Co, Allentown, PA, originally scheduled for 790406, has been changed to 790419 at ofc of Air Products & Chemicals Co
RYAN, T. O. Isham, Lincoln & Beale 79/03/30 1p.

--7903070045 RL Wright, AD Cyphers & L Peeler were deposed during Mar Central Power & Light filed answers & objections to Houston Lighting & Power Co first set of written interrogatories.
RYAN, T. O. Isham, Lincoln & Beale. 79/03/30 2pp

7903300038 Rept on progress made in Mar 1979 in completing discovery, submitted per ASLB 780421 order Certificate of Bvc encl
HARRIS, J. L., BERGER, M. O., CLARK, R. H. Justice, Dept of. 79/03/31. 7pp.

7903030175 Describes discovery activities of Public Utils Board of Brownsville, TX for Mar 1979 Certificate of Bvc encl
POIRER, M. R. Spiegel & McDiarmid. 79/04/03 6pp.

DOCKETED ITEMS

- 7905090036 Request by TX Utils Generating Co for NRC to dismiss Central Power & Light South West Corp as intervenors in alternative, seeks summary disposition or invoking of collateral estoppel Certificate of Svc encl
KNOTTS, J B Debevoise & Lieberman 79/04/03 5pp
- 7905090042 Request by TX Util Generating Co for order barring Central Power & Light from seeking relief inconsistent w/District Court decision for favorable decision re summary disposition
KNOTTS, J B Debevoise & Lieberman 79/04/03 2pp
- 7905090050 Memo by TX Utils Generating Co re points & authorities supporting motion to dismiss Central Power & Light South West Corp as intervenors or for summary disposition
KNOTTS, J B Debevoise & Lieberman 79/04/03 42pp
- 7905100288 Response to second set of interrogatories & requests for production of documents directed to DDJ by Houston Lighting & Power Qualifications of expert witnesses WE Scott & OTC Taylor & Certificate of Svc encl.
HARRIS, J L, BERGER, M O, CLARK, R H Justice, Dept of 79/04/03 23pp
- 7905100288 Response to second set of interrogatories & requests for production of documents directed to Dept of Justice by Houston Lighting & Power Qualifications of expert witnesses WE Scott & OTC Taylor & Certificate of Svc encl
HARRIS, J L, BERGER, M O, CLARK, R H Justice, Dept of 79/04/03 23pp
- 7905250361 Request by Central Power & Light that ASLO issue protective order re interrogatories & request for production of documents from Houston Lighting & Power Certificate of Svc encl
STAHL, D M Isham, Lincoln & Beale 79/04/03 7pp
- 7905100273 Response to TX Utils Generating Co's objections to & motion for protective orders & motion to compel further answers to interrogatories & request for production of documents Certificate of Svc encl
BLUME, M B Anti-Trust Division 79/04/04 34pp
- 7905070251 Mar 1979 discovery progress rpt of City of San Antonio During week of 790323; documents made available by City were inspected by Public Utils Board of Brownville, TX Certificate of Svc encl
WOOD, J C Matthews, Nowlin, MacFarlane & Barrett 79/04/05 4pp
- 7905140115 Motion by Public Utils Board of Brownville, TX to compel further production of documents from South TX Electric Cooperative & Medina Electric Cooperative. Supporting documentation & Certificate of Svc encl
POIRIER, M R Spiegel & McDiarmid 79/04/05 17pp
- 7905140138 Request by Central Power & Light for extension of time to respond to 790328 responses by Houston Lighting & Power & TX Utils Generating Co to former's interrogatories & document requests Certificate of Svc encl
STAHL, D Isham, Lincoln & Beale 79/04/05 6pp.
- 7905100386 Moves that responses to motions for summary disposition filed by Houston Lighting & Power & TX Utils Generating Co be governed by 10CFR2 7904(a) Certificate of Svc encl
LESSY, R P Anti-Trust Division 79/04/06 5pp
- 7905150190 Motion by Houston Lighting & Power for protective order re public disclosure of info requested by Public Utils Board of Brownville, TX Certificate of Svc encl
BARNETT, E W Baker & Botts, BOUKNIGHT, J A Lowenstein, Newman, Reis, Axelrad & Toll 79/04/06 9pp
- 7905230793 Status of discovery & production during Mar 1979 Certificate of Svc encl
HALOUGH, R C Austin, TX, 79/04/06 3pp
- 7905100412 Applies restrictions on confidential documents to be produced by Houston Lighting & Power Co in response to request for production of documents by Public Utils Board of Brownville, TX
MILLER, M E Atomic Safety and Licensing Board Panel 79/04/09, 5pp
- 7905250488 Status rpt on discovery for Mar 1979 Discovery requests were neither initiated nor received. Certificate of Svc encl
JOHN, D F, Akin, Gump, Hauer & Feld 79/04/09, 5pp
- 7905290077 Motion by Gulf States Utils for further extension of time, until 790429, in which to complete response to City of Brownville's subpoena for production of documents. Certificate of Svc encl.
RADER, R M, Conner, Moore & Corber, 79/04/09, 6pp.
- 7905230651 Answer by Houston Power & Lighting to NRC 790323 response to util motion for protective order. NRC motion to compel further answers to interrogatories & NRC request for production of documents Certificate of Svc encl
BARNETT, E W Baker & Botts, BOUKNIGHT, J A Lowenstein, Newman, Reis, Axelrad & Toll 79/04/11 12pp
- 7905030260 Forwards revised page 28-1 attached to Central Power & Light Co's answers & objections to Houston Lighting & Power Co's first set of written interrogatories to Central Power & Light Co Certificate of Svc encl
STAHL, D M Isham, Lincoln & Beale 79/04/12 6pp
- 7905240332 Advises no discovery requests have been initiated or received by Tex-La Electric Cooperative, Inc Certificate of Svc encl
BURCHETTE, W H Northcutt Ely 79/04/12 4pp
- 7905230448 South TX Electric Cooperative, Inc & Medina Electric Cooperative, Inc's opposition to Public Utils Board of Brownville, TX 790405 motion for fuller responses to interrogatories Certificate of Svc encl
HUNTEZ, M McInnis, Lochridge & Kilgore JOHN, D F Akin, Gump, Hauer & Feld 79/04/13 11pp
- 7905240967 Advises that during Mar 1979 NRC filed motions to compel against Houston Lighting & Power & TX Utils Generating Co NRC is preparing responses to TX Util's first & Houston's second set of interrogatories
LESSY, R P Anti-Trust Division 79/04/13 1p
- 7905250129 Ack receipt of response to Mar 1979 motion to compel & evaluation in progress
LESSY, R P Anti-Trust Division 79/04/13 1p
- 7905140126 Request by Public Utils Board of Brownville, TX for extension of time to answer first set of interrogatories & requests for production of documents from Central Power & Light & Houston Lighting & Power Certificate of Svc encl
MCDIARMID, R C Spiegel & McDiarmid 79/04/16 7pp
- 7905240241 Corrects revised page 28-1 of Central Power & Light Co answers & objections in 790412 proceeding from "expenditure other than expenditure" to "expenditure other than advertising" Certificate of Svc encl
STAHL, D M Isham, Lincoln & Beale 79/04/17 4pp
- 7905150780 Directs TX Utils Generating Co (TUGCO) to produce documents or make full responses to 790115 interrogatories Denies TUGCO's order for protective order
MILLER, M E Atomic Safety and Licensing Board Panel 79/04/18 2pp
- 7905230624 Response by util to Central Power & Light's 790326 objections & 790403 motion for protective order re util's first set of interrogatories Includes motion to compel answers W/notice of appearance & Certificate of Svc
BARNETT, E W Baker & Botts, BOUKNIGHT, J A, FRANKLIN, W J Lowenstein, Newman, Reis, Axelrad & Toll 79/04/19, 18pp
- 7905230677 Grants extension of time to answer interrogatories by Public Utils Board of Brownville, TX, in response to 790416 motion
MILLER, M E Atomic Safety and Licensing Board Panel 79/04/19 1p.
- 7905100118 Motion by Central Power & Light to compel Houston Lighting & Power to answer second set of interrogatories submitted 790223 Supporting documentation & Certificate of Svc encl.
STAHL, D, Isham, Lincoln & Beale, 79/04/20 20pp
- 7905100123 Motion by Central Power & Light to compel TX Utils Generating Co to answer first set of interrogatories submitted 790223
STAHL, D, Isham, Lincoln & Beale, 79/04/20 12pp.
- 7905100271 Answer by Central Power & Light & Central & South West Corp seeking continuance of NRC antitrust reviews, w/no party banned on grounds of res judicata of collateral estoppel. Supporting documentation & Certificate of Svc encl
FOWELL, R E, MILLER, M E, STAHL, D M Isham, Lincoln & Beale 79/04/20, 115pp.
- 7905100106 Opposes City of Austin's 790329 brief & 790403 motions for full or partial summary judgment filed by Houston Lighting & Power & TX Utils Generating Co. Seeks denial of certification & interlocutory appeals W/Certificates of Svc
LESSY, R P, BLUME, M B Anti-Trust Division, 79/04/23 24pp.
- 7905140151 Response of Public Utils Board of Brownville, TX opposing Houston Lighting & Power motion for summary decision & City of Austin brief in support of res judicata. Supporting documentation & Certificate of Svc encl.
MCDIARMID, R C, JABLON, R A, POIRIER, M R, Spiegel & McDiarmid, 79/04/23, 84pp.

DOCKETED ITEMS

241

7905240248 Conforms 790424 telcon that util plans to file response to 790419 Motion By NRC for reconsideration of board order of 790416 compelling further answer by util Certificate of Svc encl
FRANKLIN, W J Lowenstein, Newman, Reis, Axelrad & Toll 79/04/24 5pp

7905240924 Util's discovery progress rept for Apr, 1979 Certificate of Svc encl
FRANKLIN, W J Lowenstein, Newman, Reis, Axelrad & Toll 79/05/02 7pp

7905290191 Requests util suppl & update list of privileged documents
LESSBY, R F Anti-Trust Division 79/05/02 1p.

7905230466 NRC answer to motions of Gulf States Util for protective order & order setting conditions for compliance w/790226 subpoena Util should produce documents as requested Certificate of Svc encl.
BLUME, M B Anti-Trust Division 79/05/04 14pp

0 Inspection reports, IE Bulletins & correspondence

7905010376 Forwards IE Insp Repts 50-498/79-03 & 50-499/79-03 on 790221-23 & notice of violation.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/14, 2pp

--7905010379 Notice of violation from insp on 790221-23
" Region 4, Dallas, Office of the Director 79/03/13 1p

--7905010383 IE Insp Repts 50-498/79-03 & 50-499/79-03 on 790221-23 Noncompliance noted failure to follow procedures for storage of matl
HUBACEK, W O, MARTIN, L E Region 4, Dallas, Office of the Director HALL, R E Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/13 9pp

7905010279 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/23 1p.

7905010457 Forwards IE Bulletin 79-05A, "Nuclear Incident at TMI - Suppl."
SEYFRIT, K V Region 4, Dallas, Office of the Director. 79/04/05 1p

7905040492 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 1p

7905040613 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14, 1p.

7905070055 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 1p

7905010441 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
SEYFRIT, K V. Region 4, Dallas, Office of the Director. 79/04/16 1p.

7905090099 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at TMI."
SEYFRIT, K V Region 4, Dallas, Office of the Director. 79/04/16 1p.

7905030271 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/17 1p

7905240686 Ack receipt of 790403 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/79-03 & 50-499/79-03
SEIDLE, W C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/26 1p.

--7905240693 Responds to NRC 790314 ltr re violations noted in IE Insp Repts 50-498/79-03 & 50-499/79-03 Corrective actions.
storage areas on site surveyed for stainless steel matl in contact w/carbon steel
TURNER, E A Houston Lighting & Power Co. 79/04/03, 2pp.

B Reportable occurrences, LERs & related correspondence

7905030138 Forwards PNO-79-67H, I, J & K
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/06 1p

7905030094 Forwards PNO-79-67L, M, N & P
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/09 1p

7905030095 Forwards PNO-79-67Q
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/10 1p

7905030143 Forwards PNO-79-67R & 79-77
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/11 1p

7905030118 Forwards PNO-79-67S
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/12 1p

7905030189 Forwards PNO-79-67T
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/13, 1p

7905030071 Forwards PNO-79-67U & V
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/16 1p.

7905030240 Forwards PNO-79-67W
SEIDLE, W C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/17 1p

7905020516 Forwards PNO-79-67AA
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/20 1p

7905020503 Forwards PNO-79-67AB, AC & AD
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/23 1p

7905040391 Forwards PNO-79-67AE
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/26 1p

--7905040406 PNO-79-67AE summary of info re nuclear incident as of 790424 Describes plant & environ status
" Office of Inspection & Enforcement 79/04/24 3pp.

7905070185 Forwards PNO-79-67AF & AO.
SEIDLE, W C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/27 1p.

7905010216 Forwards PNO-79-67AH, AI & AJ
SEIDLE, W C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/30 1p.

7905240385 Forwards PNO-79-67AK & AL
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/04 1p.

DOCKET 89N-50-499 SOUTH TEXAS PROJECT, UNIT "

A. Applicati

7905100064
structur
PARR, O. I

7905300371
PARR, O. I

7905240864
discuss
structur
LICITRA,

F. Securi

7905030333
(ref 10
TURNER,

DOCKETED ITEMS

U. Adjudicatory correspondence

79052503086 Responds to Citizens for Equitable Utils 790223 petition to intervene Petition should be granted because standing is shown Certificate of Svc encl
MCOURREN, H J Branch 1 79/03/12. 17pp.

7905250170 Request by applicant that ASLB issue addl procedures prior to ruling on 780830 petition to intervene from Citizens Concerned About Nuclear Power Certificate of Svc encl
NEWMAN, J R, REIS, H F, CULP, R H Lowenstein, Newman, Reis, Axelrad & Toll 79/03/14 8pp

7905300081 NRC response to Houston Lighting & Power 790314 motion for addl procedures requested from Citizens Concerned About Nuclear Power. Request violates limitations stated in NRC Rules of Practice Certificate of Svc encl
MCOURREN, H J Branch 1 79/03/29 8pp

7905300064 Response to applicant's motion to provide ASLB w/790319 decision in Health Research Group vs Kennedy. Reproduced from "Legal Times of Washington" Certificate of Svc encl
MCOURREN, H J Branch 1 79/04/02 3pp.

7905250318 Assignment of RS Salsman, JH Buck & MC Farrar to ASLB for proceeding
DUPLON, M E Atomic Safety and Licensing Appeal Panel 79/04/17. 1p

7905250328 Notice of appeal by Houston Lighting & Power of 790403 order granting intervention to Citizens Concerned About Nuclear Power. Citizens for Equitable Utils & Austin Citizens for Economical Energy Certificate of Svc encl
NEWMAN, J R, REIS, H F, CULP, R H Lowenstein, Newman, Reis, Axelrad & Toll 79/04/17 5pp

7905290002 Reply by applicants to NRC 790420 motion for extension of time & to Citizens for Equitable Utils 790422 motion for continuance Both motions are unnecessary & unreasonable Certificate of Svc encl
SCHWARZ, M D Baker & Batts NEWMAN, J R, CULP, R H Lowenstein, Newman, Reis, Axelrad & Toll 79/04/27 5pp

H General correspondence

7905090007 FOIA request for "Prehearing Conference Order Ruling Upon Intervention Petitions" & "Part 2 Rules of Practice for Domestic Licensing Proceedings."
RYAN, C R. Citizens Concerned About Nuclear Power, Inc 79/04/10 1p

7905010024 Response to FOIA request for "Prehearing Conference Order Ruling Upon Intervention Petitions," & "Part 2 Rules of Practice for Domestic Licensing Proceedings" Forwards requested info. w/o encl
FELTON, J M Division of Rules and Records 79/04/24 1p.

K. Utility Final Safety Analysis Report (FSAR) & amendments

7905080408 Forwards Amend 5 to FSAR.
TURNER, E A Houston Lighting & Power Co. 79/05/04 3pp

--7905080409 Amend 5 to FSAR
* Houston Lighting & Power Co 79/05/04 500pp.

7905150236 Forwards supplemental info to Amend 5 to FSAR covering Const Procedure A040KPCCP-14 & QA vibroflotation insp rept dtd 760503
TURNER, E A Houston Lighting & Power Co 79/05/09. 70pp

M Antitrust correspondence

7905150345 Forwards TX Utils Co & subsidiaries' answer to NRC initial interrogatories & requests for production of documents. Reserves rights to file objections & protective order before 790305 Certificate of Svc encl
SLICKEY, F K Worsham, Forsythe & Bampels. 79/03/01 1p

7905020232 Grants 790317 motion by Public Utils Board of Brownsville, TX seeking extensions until 790330 & 790405 in which to compel fuller responses to Board's interrogatories
MARSHALL, E M Atomic Safety and Licensing Board Panel 79/03/22 1p

7905240127 Notifies that location of deposition of LC Peeler of Monsanto Co has been changed from Holiday Inn, Alvin, TX to Butler, Binion, Rice, Cook & Knapp law offices in Houston, TX
RYAN, T G. Isham, Lincoln & Beale. 79/03/22 5pp

7905020480 Order protecting confidentiality of info sought by Houston Lighting & Power from Central Power & Light, West TX Utils, Public Svc of OK & Southwestern Electric Power Co
MILLER, M E Atomic Safety and Licensing Board Panel. 79/03/23 3pp

7905310020 Response by util to second set of interrogatories & request for production of documents, submitted to Central Power & Light Also moves for protective order Certificate of Svc encl
BARNETT, E W Baker & Batts 79/03/28 28pp

7905070040 Advises that deposition of Edward Sherry, Air Products & Chemicals Co, Allentown, PA, originally scheduled for 790406, has been changed to 790419 at ofc of Air Products & Chemicals Co
RYAN, T G Isham, Lincoln & Beale 79/03/30 1p

--7905070045 RL Wright, AD Cyphers & L Peeler were deposed during Mar Central Power & Light filed answers & objections to Houston Lighting & Power Co first set of written interrogatories
RYAN, T G Isham, Lincoln & Beale 79/03/30 2pp

7905300058 Rept on progress made in Mar 1979 in completing discovery, submitted per ASLB 780621 order Certificate of Svc encl
HARRIS, J L Justice, Dept of 79/03/31 7pp

7905030175 Describes discovery activities of Public Util Board of Brownsville, TX for Mar 1979. Certificate of Svc encl
POIRIER, M R Spiegel & McDiarmid 79/04/03 6pp

7905090036 Request by TX Utils Generating Co for NRC to dismiss Central Power & Light South West Corp as intervenors in alternative, seeks summary disposition or invoking of collateral estoppel Certificate of Svc encl.
KNOTT, J B Debevoise & Lieberman. 79/04/03 5pp

--7905090042 Request by TX Util Generating Co for order barring Central Power & Light from seeking relief inconsistent w/District Court decision for favorable decision re summary disposition
KNOTT, J B Debevoise & Lieberman 79/04/03 2pp.

--7905090050 Memo by TX Utils Generating Co re points & authorities supporting motion to dismiss Central Power & Light South West Corp as intervenors or for summary disposition
KNOTT, J B Debevoise & Lieberman 79/04/03 42pp

7905100288 Response to second set of interrogatories & requests for production of documents directed to Dept of Justice by Houston Lighting & Power Qualifications of expert witnesses HE Scott & QC Taylor & Certificate of Svc encl.
HARRIS, J L Justice, Dept of 79/04/03. 23pp

7905140070 Responses to first set of interrogatories & request for production of documents submitted by TX Util Generating Co Certificate of Svc encl
HARRIS, J L Justice, Dept of. 79/04/03 11pp.

7905250361 Request by Central Power & Light that ASLB issue protective order re interrogatories & request for production of documents from Houston Lighting & Power. Certificate of Svc encl
STAHL, D M. Isham, Lincoln & Beale 79/04/03 7pp

7905100273 Response to TX Utils Generating Co's objections to & motion for protective orders & motion to compel further answers to interrogatories & request for production of documents Certificate of Svc encl.
BLUME, M B. Anti-Trust Division. 79/04/04 34pp

7905070251 Mar 1979 discovery progress rept of City of San Antonio During week of 790323, documents made available by City were inspected by Public Utils Board of Brownsville, TX Certificate of Svc encl.
WOOD, J C Matthews, Nowlin, MacFarlane & Barrett. 79/04/05 4pp

7905140115 Motion by Public Utils Board of Brownsville, TX to compel further production of documents from South TX Electric Cooperative & Medina Electric Cooperative Supporting documentation & Certificate of Svc encl.
POIRIER, M R Spiegel & McDiarmid 79/04/05 17pp.

7905140138 Request by Central Power & Light for extension of time to respond to 790328 responses by Houston Lighting & Power & TX Utils Generating Co to former's interrogatories. Document requests. Certificate of Svc encl
STAHL, D Isham, Lincoln & Beale 79/04/05 6pp.

DOCKETED ITEMS

243

- 7905100384 Moves that responses to motions for summary disposition filed by Houston Lighting & Power & TX Utils Generating Co be governed by 10CFR2 790(a) Certificate of Svc encl
LESSY, R P Anti-Trust Division 79/04/06 5pp
- 7905150190 Motion by Houston Lighting & Power for protective order re public disclosure of info requested by Public Utils Board of Brownsville, TX Certificate of Svc encl
BARNETT, E W Baker & Botts 79/04/06 9pp
- 7905230793 Status of discovery & production during Mar 1979 Certificate of Svc encl
BALGUGH, R C Austin, TX 79/04/06 3pp
- 7905100412 Applies restrictions on confidential documents to be produced by Houston Lighting & Power Co in response to request for production of documents by Public Utils Board of Brownsville, TX
MILLER, M E Atomic Safety and Licensing Board Panel 79/04/09 3pp
- 7905230488 Status rept on discovery for Mar 1979 Discovery requests were neither initiated nor received Certificate of Svc encl
JOHN, D F Akin, Gump, Hauer & Feld 79/04/09 5pp
- 7905290077 Motion by Gulf States Util for further extension of time, until 790425, in which to complete response to City of Brownsville's subpoena for production of documents Certificate of Svc encl
RADER, R M Conner, Moore & Corber 79/04/09 6pp
- 7905230651 Answer by Houston Power & Lighting to NRC 790323 response to util motion for protective order, NRC motion to compel further answers to interrogatories & NRC request for production of documents Certificate of Svc encl
BARNETT, E W Baker & Botts 79/04/11 12pp
- 7905030260 Forwards revised p 28-1 attached to "Central Power & Light Co's Answers & Objections to Houston Lighting & Power Co's First Set of Written Interrogatories to Central Power & Light Co." w/Certificate of Svc
STAHL, D M Isham, Lincoln & Beale 79/04/12 6pp.
- 7905240332 Advises no discovery requests have been initiated or received by Tex-La Electric Cooperative, Inc Certificate of Svc encl
BURCHETTE, W H Norcutt Elq 79/04/12 App.
- 7905150663 Grants motions for extension of time for parties to respond to discovery requests
MILLER, M E Atomic Safety and Licensing Board Panel 79/04/13 3pp.
- 7905230448 South TX Electric Cooperative, Inc & Medina Electric Cooperative, Inc's opposition to Public Utils Board Brownsville, TX 790405 motion for fuller responses to interrogatories Certificate of Svc encl
HUNTEZ, M McGinnis, Lochridge & Kilgore 79/04/13 11pp
- 7905240967 Advises that during Mar 1979 NRC filed motions to compel against Houston Lighting & Power & TX Utils Generating Co NRC is preparing responses to TX Util's first & Houston's second set of interrogatories
LESSY, R P Anti-Trust Division 79/04/13 1p.
- 7905250129 Ack receipt of response to Mar 1979 motion to compel & evaluation in progress
LESSY, R P Anti-Trust Division 79/04/13 1p.
- 7905140126 Request by Public Utils Board of Brownsville, TX for extension of time to answer first set of interrogatories & requests for production of documents from Central Power & Light & Houston Lighting & Power, Certificate of Svc encl
MCDIARMID, R C Spiegel & McDiarmid. 79/04/16 7pp
- 7905240241 Corrects revised page 28-1 of Central Power & Light Co Answers & Objections in 790412 proceeding from "expenditure other than expenditures" to "expenditure other than advertising" Certificate of Svc encl
STAHL, D M Isham, Lincoln & Beale. 79/04/17 4pp
- 7905150780 Directs TX Utils Generating Co (TUOGCO) to produce documents or make full responses to 790115 interrogatories, Denies TUOGCO's order for protective order.
MILLER, M E Atomic Safety and Licensing Board Panel. 79/04/18 2pp
- 7905230624 Response by util to Central Power & Light's 790326 objections & 790403 motion for protective order re util's first set of interrogatories. Includes motion to compel answers, w/notice of appearance & Certificate of Svc.
BARNETT, E W Baker & Botts. 79/04/19 18pp.
- 7905230677 Grants extension of time to answer interrogatories by Public Utils Board of Brownsville, TX, in response to 790416 motion
MILLER, M E Atomic Safety and Licensing Board Panel. 79/04/19 1p.
- 7905100123 Motion by Central Power & Light to compel TX Utils Generating Co to answer first set of interrogatories submitted 790223
STAHL, D M Isham, Lincoln & Beale 79/04/20 12pp
- 7905100271 Answer by Central Power & Light & Central & South West Corp seeking continuance of NRC untrust reviews, w/no party banned on grounds of res judicata of collateral estoppel Supporting documentation & Certificate of Svc encl
POWELL, R E Isham, Lincoln & Beale. 79/04/20 115pp
- 7905100106 Opposes City of Austin's 790329 brief & 790403 motions for full or partial summary judgment filed by Houston Lighting & Power & TX Utils Generating Co Seeks denial of certification & interlocutory appeals w/Certificate of Svc.
LESSY, R P Anti-Trust Division. 79/04/23 24pp
- 7905140151 Response of Public Utils Board of Brownsville, TX opposing Houston Lighting & Power motion for summary decision & City of Austin brief in support of res judicata Supporting documentation & Certificate of Svc encl
MCDIARMID, R C Spiegel & McDiarmid 79/04/23 84pp.
- 7905240248 Confirms 790424 telcon that util plans to file response to 790419 Motion By NRC for reconsideration of board order of 790416 compelling further answer by util Certificate of Svc encl
FRANKLIN, W J Lowenstein, Newman, Reis, Axelrad & Toll. 79/04/24 6pp
- 7905240824 Util's discovery progress rept for Apr. 1979. Certificate of Svc encl
FRANKLIN, W J Lowenstein, Newman, Reis, Axelrad & Toll 79/05/02 7pp.
- 7905250191 Requests util suppl & update list of privileged documents
LESSY, R P Anti-Trust Division 79/05/02 1p
- 7905230466 NRC answer to motions of Gulf States Util for protective order & order setting conditions for compliance w/790226 subpoena Util should produce documents as requested Certificate of Svc encl
BLUME, M B Anti-Trust Division 79/05/04 14pp
- G. Inspection reports, IE Bulletins & correspondence

- 7905010376 Forwards IE Insp Repts 50-498/79-03 & 50-499/79-03 on 790221-23 & notice of violation.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/14 2pp.
- 7905010379 Notice of violation from insp on 790221-23.
" " Region 4, Dallas, Office of the Director 79/03/13 1p.
- 7905010383 IE Insp Repts 50-498/79-03 & 50-499/79-03 on 790221-23. Noncompliance noted, failure to follow procedures for storage of mat.
HUBACEK, W O, MARTIN, L E. Region 4, Dallas, Office of the Director HALL, R E Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/03/13 9pp
- 7905010279 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
SEYFRIT, K V Region 4, Dallas, Office of the Director. 79/03/23. 1p.
- 7905010457 Forwards IE Bulletin 79-05A, "Nuclear Incident at TMI - Suppl."
SEYFRIT, K V Region 4, Dallas, Office of the Director. 79/04/05. 1p.
- 7905040492 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
SEYFRIT, K V. Region 4, Dallas, Office of the Director. 79/04/14 1p.
- 7905040613 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident."
SEYFRIT, K V. Region 4, Dallas, Office of the Director. 79/04/14. 1p.
- 7905070055 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required.
SEYFRIT, K V. Region 4, Dallas, Office of the Director. 79/04/14. 1p.

DOCKETED ITEMS

7903010441 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/16
1p

7903090099 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at TMI."
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/16
1p

7903030271 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/17
1p

7903240686 Ack receipt of 790403 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/79-03 & 50-499/79-03
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/26 1p

--7903240693 Responds to NRC 790314 ltr re violations noted in IE Insp Repts 50-498/79-03 & 50-499/79-03 Corrective actions storage areas on site surveyed for stainless steel matl in contact w/carbon steel
TURNER, E A Houston Lighting & Power Co 79/04/03 2pp

B Reportable occurrences, LERs & related correspondence

7903030138 Forwards PNO-79-67H, I, J & K
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/06
1p

7903030094 Forwards PNO-79-67L, H, N & P
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/09 1p

7903030095 Forwards PNO-79-67Q
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/10 1p

7903030143 Forwards PNO-79-67R & 79-77
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/11 1p

7903030118 Forwards PNO-79-67S
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/12 1p

7903030189 Forwards PNO-79-67T
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/13 1p

7903030071 Forwards PNO-79-67U & V
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/16 1p

7903030240 Forwards PNO-79-67W
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/17 1p

7903020316 Forwards PNO-79-67AA
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/20 1p

7903020305 Forwards PNO-79-67AB, AC & AD.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/23 1p

7903040391 Forwards PNO-79-67AE
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/26 1p

--7903040406 PNO-79-67AE, summary of info re nuclear incident as of 790424. Describes plant & environ status.
* Office of Inspection & Enforcement. 79/04/24. 3pp.

7903070185 Forwards PNO-79-67AF & AG.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/27 1p

7903310216 Forwards PNO-79-67AH, AI & AJ.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/30 1p

7903240385 Forwards PNO-79-67AK & AL.
SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/04 1p

DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2

G Adjudicatory correspondence

7903160216 Forwards final evaluation of items discussed in 790228 memo re B&W designed nuclear plants Requests addl info be forwarded to licensing boards
MOSELEY, N C Division of Reactor Operations Inspections 79/03/28 10pp

7903160163 Forwards Board Notification 79-10 on reactor inspector concerns re B&W plants Certificate of Svc encl
SCINTO, J F Hearings Division 79/03/29 14pp

--7903160185 Board notification reactor inspector concerns re B&W plants
VASSALLO, D B Assistant Director for Light Water Reactors 79/03/06 2pp

--7903160201 Forwards two Moseley-to-Thompson memos for Board notification info
THOMPSON, D Office of I & E Executive Officer for Operations Support 79/03/29 1p

--7903160209 Preliminary evaluation of Item 3 contained in 790328 memo will be reviewed in light of TMI transient Addl info may cause change in previous assessment
MOSELEY, N C Division of Reactor Operations Inspections 79/03/29 1p

7903160112 Board notification nuclear incident at TMI Recommend boards on cases involving B&W reactors be provided w/IE Bulletin 79-05 & PNO-67 & 67A, B, C, D, E, F, G & H
VASSALLO, D B Assistant Director for Light Water Reactors 79/04/03 2pp

7903110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl.
SCINTO, J F Hearings Division 79/04/11 45pp

7903140319 Response to 790404 brief of Philadelphia Electric Co, PSE&Q & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Svc encl
KEPFORD, C R Citizens for Safe Environment 79/04/11 8pp

7903140332 Notices of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition
DUFLO, M E Atomic Safety and Licensing Appeal Panel 79/04/25 13pp

J Insurance & indemnity information

7903070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHI, J American Nuclear Insurers. 79/05/01 1p.

7903070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters. 79/03/01 1p.

7903140361 Forwards Endorsements 28 & 29 to NELIA Policy NF-236
LLOYD, R D Marsh & McLennan; M & M Nuclear Consultants, Inc. Div 79/05/07 3pp

G Inspection reports, IE Bulletins & correspondence

7903020461 Forwards IE Insp Rept 50-500/79-01 & 50-501/79-01 on 790222 No noncompliance noted.
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/22 2pp

--7903020470 IE Insp Rept 50-500/79-01 & 50-501/79-01 on 790222. No noncompliance noted. Major areas inspected: QA/QC program in applicable areas, drilling & grouting in progress & manpower requirements.
JONES, C E, HAYES, D W, KNOP, R C Region 3, Chicago, Office of the Director. 79/03/19 6pp.

B Reportable occurrences, LERs & related correspondence

7903020266 Notices of reportable event on 790413, certain starters for essential motors had overload heaters installed which were smaller than capacity specified on relay data sheets, causing possible overload heater burnout. Heater being replaced
MURRAY, T D Toledo Edison Co. 79/04/16 1p.

DOCKETED ITEMS

245

DOCKET 50-501 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 3

0 Adjudicatory correspondence

7903160216 Forwards final evaluation of items discussed in 790228 memo re B&W designed nuclear plants Requests addl info be forwarded to licensing boards
MOSELEY, N C Division of Reactor Operations Inspections 79/03/28 10pp

7903160163 Forwards Board Notification 79-10 on reactor inspector concerns re B&W plants Certificate of Bvc encl
SCINTO, J F Hearings Division 79/03/29 14pp

--7903160185 Board notification reactor inspector concerns re B&W plants VASSALLO, D B Assistant Director for Light Water Reactors 79/03/06 2pp

--7903160201 Forwards two Moseley-to-Thompson memos for Board notification info THOMPSON, D, Office of I & E Executive Officer for Operations Support 79/03/29 1p

--7903160209 Preliminary evaluation of Item 3 contained in 790328 memo will be reviewed in light of TMI transient Addl info may cause change in previous assessment
MOSELEY, N C Division of Reactor Operations Inspections 79/03/29 1p

7903160112 Board notification nuclear incident at TMI Recommends boards on cases involving B&W reactors be provided w/IE Bulletin 79-05 & PNO-67 & 67A, B, C, D, E, F, Q & H
VASSALLO, D B Assistant Director for Light Water Reactors 79/04/03 2pp

7903110418 Response to ALAR-509 re radon emissions & de minimus theory from Perkins record Certificate of Bvc encl.
SCINTO, J F Hearings Division, 79/04/11 45pp

7903140519 Response to 790404 brief of Philadelphia Electric Co, PBE&O & Atlantic City (NJ) Electric Co re de minimus theory, Certificate of Bvc encl
KEPFORD, C R Citizens for Safe Environment 79/04/11 8pp

7903140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790325 in which to file for summary disposition
DUFLO, M.E. Atomic Safety and Licensing Appeal Panel 79/04/25 13pp

J. Insurance & indemnity information

7903070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHINI, J. American Nuclear Insurers 79/05/01 1p

7903070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01 1p.

7903140361 Forwards Endorsements 28 & 29 to NELIA Policy NF-236.
LLOYD, R D. Marsh & McLennan, M & M Nuclear Consultants, Inc. Div. 79/05/07 3pp.

G. Inspection reports, IE Bulletins & correspondence

7903020461 Forwards IE Insp Rept 50-500/79-01 & 50-501/79-01 on 790222 No noncompliance noted
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/03/22 2pp.

--7903020470 IE Insp Rept 50-500/79-01 & 50-501/79-01 on 790222 No noncompliance noted Major areas inspected: GA/GG program in applicable areas; drilling & grouting in progress & manpower requirements.
JONES, C.E., HAYES, D.W., KNOP, R.C. Region 3, Chicago, Office of the Director 79/03/19 6pp

B. Reportable occurrences, LERs & related correspondence

7903020266 Notifies of reportable event on 790413, certain starters for essential motors had overload heaters installed which were smaller than capacity specified on relay data sheets, causing possible overload heater burnout. Heater being replaced
MURRAY, T.D. Toledo Edison Co 79/04/16 1p.

DOCKET STN-50-502 HAVEN NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

7905100322 Requests info re State of WI Public Bvc Commission views on limiting const of facility & effect of WI Electric Power Co application for single nuclear unit near Haven in Sheboygan County, WI
DENTON, H R Commission 79/04/05 2pp

7905090141 Forwards request for addl info re outstanding alternate sites issues
BALLARD, R L Environmental Projects Branch 1 79/04/19 3pp

7905030337 Forwards addl copies of results of geological investigations re possible faulting under Lake Michigan, presented by utility & B&W at 790307 meeting w/NRC No evidence of faulting indicated. 62 oversized drawings in Central Files
BURSTEIN, B Wisconsin Electric Power Co 79/04/20 86pp

7905150381 Submits addl info re PSAR & site addendum in response to 790320 request Identifies items requiring addl time for completion
BURSTEIN, B Wisconsin Electric Power Co 79/05/10 33pp

B Utility Preliminary Safety Analysis Report, amends

7905010313 Forwards Amend 22, to be inserted into PSAR site addendum Affidavit encl
BURSTEIN, B Wisconsin Electric Power Co. 79/04/20 2pp

--7905010315 Amend 22 to PSAR site addendum Insertion instructions encl
* Wisconsin Electric Power Co 79/04/20 138pp

C. Utility Environmental Report (ER), amends & correspondence

7905010489 Forwards "Amend 14 to Environ Rept," CP stage
BURSTEIN, B Wisconsin Electric Power Co. 79/04/18 3pp

--7905010490 "Amend 14 to Environ Rept," CP stage w/oversized drawings
* Wisconsin Electric Power Co 79/04/18 161pp

G. Adjudicatory correspondence

7905070230 Requests explanation for dismissal of 781009 motion Certificate of Bvc encl.
HANLEY, W C Safe Energy for New Haven 79/03/30 3pp.

7905010267 Motion & brief in support of Verification & analysis of data supplied by B&W Certificate of Bvc encl
HANLEY, W C. Safe Energy for New Haven. 79/03/30 2pp

7905250339 Seeks denial of 790330 motion by intervenor Safe Haven for verification & analysis of computations & computer codes. Intervenor is making inappropriate request beyond scope of ABLB.
CHURCHILL, B W Shaw, Pittman, Potts, & Troubridge 79/04/13 6pp.

7905240286 Response in opposition to intervenor Safe Haven 790330 motion for verification & analysis of all B&W computer codes Intervenor does not cite sufficient facts or legal authority. Certificate of Bvc encl.
GOLDBERG, B.G. Branch 2 79/04/17 6pp.

H. General correspondence

7905080470 Forwards affidavits of FP Libertowicz, attesting svc of environ rept Amends 13 & 14 & PSAR Amend 22.
BURSTEIN, B Wisconsin Electric Power Co. 79/05/02 10pp.

J. Insurance & indemnity information

7903070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHINI, J. American Nuclear Insurers. 79/05/01 1p.

7903070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01 1p.

DOCKETED ITEMS

P. Operating license stage documents & correspondence

7905240395 Forwards chronology of FSAR amend re GA program in response to NRC 790320 request
BASKIN, K P Southern California Edison Co 79/04/27 3pp

DOCKET STN-50-503 HAVEN NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

7905100322 Requests info re State of HI Public Svc Commission views on limiting const of facility & effect of HI Electric Power Co application for single nuclear unit near Haven in Sheboygan County, HI
DENTON, H R Commission 79/04/03 2pp

O Adjudicatory correspondence

7905070230 Requests explanation for dismissal of 781007 motion Certificate of Svc encl
HANLEY, W C Safe Energy for New Haven 79/03/30 3pp

7905310267 Motion & brief in support of verification & analysis of data supplied by S&W Certificate of Svc encl
HANLEY, W C Safe Energy for New Haven 79/03/30 2pp

DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

7905040379 Forwards Suppl 4 to "Groundwater Drainage Sys. Analysis of Sys Performance & Data to Date"
RENNBERGER, D L Washington Public Power Supply System 79/04/26. 3pp.

--7905040388 Suppl 4 to "Groundwater Drawings Sys. Analysis of Sys Performance & Data to Date" Oversized drawings encl
* Washington Public Power Supply System 79/03/31. 10pp.

7905240411 Forwards NRC positions on WPPSS-GA-004, "Operational GA Program Description" Response to positions should be submitted by 790401 as amend to original rept
HAASS, W P Quality Assurance Branch 79/05/01 2pp

7905160337 Notifies that environ evaluation has been performed on West Laydown Area; no adverse impacts associated w/development activity Development of area to begin in June 1979. Forwards internal memo & rept re potential environ impacts
RENNBERGER, D L Washington Public Power Supply System 79/05/07. 6pp

I Financial information

7905090284 Forwards "Annual Financial Rept 1978" for Puget Sound Power & Light Co. Portland GE, Pacific Power & WPPSS
RENNBERGER, D L Washington Public Power Supply System 79/05/01 2pp.

--7905090283 "Annual Financial Rept 1978."
* Puget Sound Power & Light Co. 78/12/31. 44pp.

--7905090288 "Annual Financial Rept 1978"
* Portland General Electric Co 79/03/31 40pp

--7905090293 "Annual Financial Rept 1978."
* Pacific Power Co. 78/12/31 32pp

--7905090295 "Annual Financial Rept 1978."
* Washington Public Power Supply System. 78/12/31 45pp.

--7905090303 "Annual Financial Rept 1978."
* Washington Water Power Co. 78/12/31 32pp.

Q Inspection reports, IE Bulletins & correspondence

7905010294 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
ENGELKEN, R H Region 4, Dallas, Office of the Director. 79/03/23 1p.

7905010015 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/14 1p.

7905040516 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/14 1p

7905040625 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/14 1p

7905070110 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/14 1p

7905030305 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/17 1p

7905080378 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/21 1p.

B Reportable occurrences, LERs & related correspondence

7905150069 Forwards PNO-79-67L
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/06 1p

7905150173 Forwards PNO-79-67R
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/11 1p

7905040134 Forwards PNO-79-67S.
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/12 1p

7905150150 Forwards PNO-79-67T.
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/13. 1p.

7905030018 Forwards PNO-79-67U.
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905020336 Forwards PNO-79-67AA
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/20 1p

7905010439 Forwards PNO-79-67AB
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/21 1p.

7905010452 Forwards PNO-79-67AC & AD.
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/23. 1p

7905010463 Forwards PNO-79-67AE
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/24 1p.

7905090047 Forwards PNO-79-67AF.
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/25 1p

7905090059 Forwards PNO-79-67AG.
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/26. 1p.

7905090121 Forwards PNO-79-67AH.
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/27. 1p

7905070034 Forwards PNO-79-67AI, AJ & AK per NRC 790401 ltr transmitting IE Bulletin 79-05.
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/04/30. 1p.

7905070018 Forwards PNO-79-67AL per NRC 790401 ltr transmitting IE Bulletin 79-05.
ENGELKEN, R H Region 5, San Francisco, Office of the Director. 79/05/01. 1p.

DOCKETED ITEMS

247

7905310037 Forwards PNO-79-67AM.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/05/07 1p

DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

7905040379 Forwards Suppl 4 to "Groundwater Drainage Sys. Analysis of
Sys Performance & Data to Date "
RENBARGER, D. L. Washington Public Power Supply System 79/04/26
3pp

--7905040388 Suppl 4 to "Groundwater Drawings Sys. Analysis of Sys
Performance & Data to Date " Oversized drawings encl
* Washington Public Power Supply System 79/03/31. 10pp

7905240411 Forwards NRC positions on WPPSS-0A-004, "Operational OA
Program Description " Response to positions should be
submitted as amend to original rept by 790601.
HAASB, W. P. Quality Assurance Branch 79/05/01 2pp

7905160337 Notifies that environ evaluation has been performed on West
Laydown Area: no adverse impacts associated w/development
activity Development of area to begin in June 1979 Forwards
Internal memo & rept re potential environ impacts
RENBARGER, D. L. Washington Public Power Supply System 79/05/07.
6pp

I Financial information

7905090284 Forwards "Annual Financial Rept 1978" for Puget Sound Power
& Light Co. Portland OE, Pacific Power & WPPSS
RENBARGER, D. L. Washington Public Power Supply System 79/05/01
2pp

--7905090285 "Annual Financial Rept 1978 "
* Puget Sound Power & Light Co 78/12/31 44pp

--7905090288 "Annual Financial Rept 1978 "
* Portland General Electric Co 79/03/31. 40pp

--7905090293 "Annual Financial Rept 1978. "
* Pacific Power Co 78/12/31. 32pp

--7905090295 "Annual Financial Rept 1978. "
* Washington Public Power Supply System 78/12/31 45pp.

--7905090303 "Annual Financial Rept 1978 "
* Washington Water Power Co 78/12/31 32pp

7905010294 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping "
ENGELKEN, R. H. Region 4, Dallas, Office of the Director 79/03/23
1p

7905010015 Forwards IE Bulletin 79-06A, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident "
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/14. 1p

7905040516 Forwards IE Bulletin 79-06B, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident. "
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/14 1p.

7905040625 Forwards IE Bulletin 79-08, "Events Relevant to Boiling
Water Power Reactors Identified During TMI Incident "
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director.
79/04/14. 1p

7905070110 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of
Safety-Related Piping " Licensee action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/14 1p.

7905030305 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 -
Circuit Breaker in Safety-Related Sys " Licensee action
required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director.
79/04/17. 1p.

7905080378 Forwards IE Bulletin 79-05B, "Nuclear Incident at
TMI-Suppl. "
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director.
79/04/21. 1p

B Reportable occurrences, LERs & related correspondence

7905180069 Forwards PNO-79-67L
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/06 1p

7905130173 Forwards PNO-79-67R
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/11. 1p

7905040134 Forwards PNO-79-67S
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director.
79/04/12 1p

7905130150 Forwards PNO-79-67T
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/13 1p

7905030018 Forwards PNO-79-67U
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director.
79/04/14 1p

7905020536 Forwards PNO-79-67AA
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director.
79/04/20 1p

7905010439 Forwards PNO-79-67AB
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/21 1p.

7905010452 Forwards PNO-79-67AC & AD
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/23 1p

7905010463 Forwards PNO-79-67AE
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/24. 1p.

7905090047 Forwards PNO-79-67AF
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director.
79/04/25 1p

7905090059 Forwards PNO-79-67AG
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/26. 1p

7905090121 Forwards PNO-79-67AH.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director.
79/04/27. 1p

7905070034 Forwards PNO-79-67AI, AJ & AK per NRC 790401 ltr transmitt.
IE Bulletin 79-05.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director.
79/04/30. 1p

7905070018 Forwards PNO-79-67AL per NRC 790401 ltr transmitting IE
Bulletin 79-05
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director.
79/05/01. 1p.

7905310037 Forwards PNO-79-67AM.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director.
79/05/07 1p

DOCKET 50-310 BLUE HILLS STATION, UNIT 1

Q. Adjudicatory correspondence

7905130143 Forwards 780929 memo discussing results of recently
conducted fire protection research test performed by UL as
part of NRC fire protection research program
WOODHEAD, C. P. Branch 3. 79/04/03. 1p

7905240212 Evidentiary hearing re applicati- / .to review
will begin 790508.
MILLER, M. E. Atomic Safety and Licensing Board Panel. 79/04/06.
6pp

7905300213 Requests permission to address site hearings.
EVANS, R. Sierra Club. 79/04/26. 1p.

DOCKETED ITEMS

T. Hearing transcripts on non-antitrust matters

7905230563 Transcript of 790508 hearing in Jasper, TX Pp 1-122
MILLER, M E, LITTLE, L W, KORNBLITH, L Atomic Safety and Licensing
Board Panel 79/03/08 123pp

7905250070 Transcript of 790509 hearing in Jasper, TX Pp 123-289
MILLER, M E, LITTLE, L W, KORNBLITH, L Atomic Safety and Licensing
Board Panel 79/03/09 167pp

DOCKET 90-511 BLUE HILLS STATION, UNIT 2

Q. Adjudicatory correspondence

7905150143 Forwards 780929 memo discussing results of recently
conducted fire protection research test, performed by UL as
part of NRC fire protection research program
WOODHEAD, C P Branch 3 79/04/05 1p

7905240212 Evidentiary hearing re application for early site review
will begin 790508
MILLER, M E Atomic Safety and Licensing Board Panel 79/04/06
6pp

7905300219 Requests permission to address site hearings
EVANS, R Sierra Club 79/04/26 1p

T. Hearing transcripts on non-antitrust matters

7905230563 Transcript of 790508 hearing in Jasper, TX Pp 1-122
MILLER, M E, LITTLE, L W, KORNBLITH, L Atomic Safety and Licensing
Board Panel 79/03/08 123pp

7905250070 Transcript of 790509 hearing in Jasper, TX Pp 123-289
MILLER, M E, LITTLE, L W, KORNBLITH, L Atomic Safety and Licensing
Board Panel 79/03/09 167pp

DOCKET 90-513 WPPSS NUCLEAR PROJECT, UNIT 4

A. Application/construction stage documents & correspondence

7905010486 Repts on geological studies' status Generic rept expected in
Fall 1979. Requests meeting to discuss plans for submitting
repts of studies, as well as mechanism for identification &
review of studies in Hanford area
RENSBERGER, D L Washington Public Power Supply System 79/04/27
2pp.

7905240411 Forwards NRC positions on WPPSS-GA-004, "Operational QA
Program Description." Responses to position should be
submitted as amend to original rept by 790601.
HAAESS, W P Quality Assurance Branch 79/05/01 2pp.

7905230534 Requests NRC ltr stating acceptability of scale model tests
in lieu of implant tests, to satisfy commitment in WNP-1/4
PSAR Question 6.77 re recirculation pump testing.
RENSBERGER, D L Washington Public Power Supply System, 79/03/15.
1p.

ion of review on
ASLB
ng record.
stem 79/04/09.

& de minimus theory

P.

a Electric Co, PSE&O &
ory.

/04/11 8pp.

venor groups re radon
ch to file

encl. 79/04/23.

Q. Inspection reports, IE Bulletins & correspondence

7905010274 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping"
ENGELKEN, R H Region 4, Dallas, Office of the Director 79/03/23
1p

7905010015 Forwards IE Bulletin 79-06A, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident"
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/14 1p

7905040516 Forwards IE Bulletin 79-06B, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident"
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/14 1p

7905040625 Forwards IE Bulletin 79-08, "Events Relevant to Boiling
Water Reactors Identified During TMI Incident."
ENGELKEN, R H Region 5, San Francisco, Office of the Director,
79/04/14 1p

7905070110 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of
Safety-Related Piping" Licensee action required
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/14 1p

7905030305 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2
Circuit Breaker in Safety-Related Sys" Licensee action
required
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/17 1p

7905080378 Forwards IE Bulletin 79-09B, "Nuclear Incident at
TMI-Suppl 1"
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/21 1p

B Reportable occurrences, LERS & related correspondence

7905150069 Forwards PNO-79-67L
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/06 1p

7905150173 Forwards PNO-79-67R,
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/11 1p

7905040134 Forwards PNO-79-67S
ENGELKEN, R H Region 5, San Francisco, Office of the Director,
79/04/12 1p

7905150150 Forwards PNO-79-67T
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/13 1p

7905030018 Forwards PNO-79-67U,
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/14 1p

7905020536 Forwards PNO-79-67AA,
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/20 1p

7905010439 Forwards PNO-79-67AB
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/21 1p.

7905010452 Forwards PNO-79-67AC & AD,
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/23 1p

7905010463 Forwards PNO-79-67AE,
ENGELKEN, R H Region 5, San Francisco, Office of the Director,
79/04/24 1p.

7905090047 Forwards PNO-79-67AF
ENGELKEN, R H Region 5, San Francisco, Office of the Director,
79/04/25 1p.

7905090059 Forwards PNO-79-67AO,
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/26 1p.

DOCKETED ITEMS

249

7905090121 Forwards PNO-79-67AH
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/27 1p

7905070034 Forwards PNO-79-67AI, AJ & AK per NRC 790401 ltr transmitting
IE Bulletin 79-05
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/30 1p

7905070010 Forwards PNO-79-67AL per NRC 790401 ltr transmitting IE
Bulletin 79-05
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/05/01 1p.

7905190067 Forwards final deficiency rept re letdown cooler supports,
per 790416 telcon.
REMBERGER, D. L. Washington Public Power Supply System 79/05/07
1p.

--7905190067 Final deficiency rept letdown cooler supports inadequate to
support specified loads Caused by inadequate design by
component manufacturer Wall mounted brackets redesigned
* Washington Public Power Supply System 79/05/07 2pp

7905310037 Forwards PNO-79-67AM
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/05/07 1p.

7905240657 Ack receipt of 790507 final deficiency rept on letdown
cooler support design inadequacy.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/05/16 1p

DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

0 Adjudicatory correspondence

7905160163 Forwards Board Notification 79-10 on reactor inspector
concerns re B&W plants Certificate of Svc encl
SCINTO, J. F. Hearings Division 79/03/29 14pp

7905010115 Forwards request for Board notification re nonsafety-grade
equipment to mitigate transients
SCINTO, J. F. Hearings Division 79/04/02 31pp

--7905010156 Board notification staff assessment re nonsafety-grade
equipment to mitigate transients.
VASSALLO, D. B. Assistant Director for Light Water Reactors
79/03/29 2pp

--7905010198 Board notification recent issue on nonsafety-grade
equipment to mitigate transients More info is required
TEDESCO, R. L. Assistant Director for Reactor Safety 79/03/16
3pp.

7905160112 Board notification nuclear incident at TMI. Recommends boards
on cases involving B&W reactors be provided w/IE Bulletin
79-05 & PNO-67 & 67A, B, C, D, E, F, G & H.
VASSALLO, D. B. Assistant Director for Light Water Reactors
79/04/03 2pp.

7905240762 Memo & order re 790620 conference to discuss schedules,
status of state of OR proceeding & status of open items
YORE, J. R. Atomic Safety and Licensing Board Panel 79/03/11 2pp

I Financial Information

7905250475 "Annual Financial Rept 1978" from SEC
* Portland General Electric Co. 78/12/31 55pp

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHHI, J. American Nuclear Insurers. 79/03/01 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters 79/05/01.
1p.

0 Advisory Committee on Reactor Safeguards reports & correspondence

7905110014 Forwards responses to 26 ACRS questions re plant
application, in response to NRC 771121 ltr.
WILLIAMS, J. L. Portland General Electric Co 77/11/30 11pp

P Operating license stage documents & correspondence

7905030361 Responds to DOE 790411 ltr Unable to provide supplemental
info by 790430 Response dependent upon preparation &
approval of Offsite Dose Calculation Manual Response will be
ready by 790531
GOODWIN, C. Portland General Electric Co 79/04/27 1p

S Reportable occurrences, LERs & related correspondence

7905110203 Board notification Seabrook refueling water storage tank
design deficiency
SCINTO, J. Hearings Division 79/03/29 30pp

DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

0 Adjudicatory correspondence

7905160163 Forwards Board Notification 79-10 on reactor inspector
concerns re B&W plants Certificate of Svc encl
SCINTO, J. F. Hearings Division 79/03/29 14pp

7905010115 Forwards request for Board notification re nonsafety-grade
equipment to mitigate transients
SCINTO, J. F. Hearings Division 79/04/02 31pp

--7905010156 Board notification staff assessment re nonsafety-grade
equipment to mitigate transients
VASSALLO, D. B. Assistant Director for Light Water Reactors
79/03/29 2pp

--7905010198 Board notification recent issue on nonsafety-grade
equipment to mitigate transients More info is required
TEDESCO, R. L. Assistant Director for Reactor Safety 79/03/16
3pp

7905160112 Board notification nuclear incident at TMI Recommends boards
on cases involving B&W reactors be provided w/IE Bulletin
79-05 & PNO-67 & 67A, B, C, D, E, F, G & H
VASSALLO, D. B. Assistant Director for Light Water Reactors
79/04/03 2pp

7905240762 Memo & order re 790620 conference to discuss schedules,
status of state of OR proceeding & status of open items
YORE, J. R. Atomic Safety and Licensing Board Panel 79/03/11 2pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for
policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHHI, J. American Nuclear Insurers 79/03/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters 79/05/01
1p.

0 Advisory Committee on Reactor Safeguards reports & correspondence

7905110014 Forwards responses to 26 ACRS questions re plant
application, in response to NRC 771121 ltr.
WILLIAMS, J. L. Portland General Electric Co 77/11/30 11pp

P. Operating license stage documents & correspondence

7905030361 Responds to DOE 790411 ltr Unable to provide supplemental
info by 790430 Response dependent upon preparation &
approval of Offsite Dose Calculation Manual Response will be
ready by 790531
GOODWIN, C. Portland General Electric Co 79/04/27 1p

DOCKETED ITEMS

B Reportable occurrences, LERs & related correspondence

7905110203 Board notification Seabrook refueling water storage tank design deficiency
SCINTO, J. Hearings Division 79/03/29 30pp.

DOCKET STN-30-516 JAMESPORT NUCLEAR STATION, UNIT 1

O Adjudicatory correspondence

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients
SCINTO, J F Hearings Division 79/04/02 31pp

--7905010156 Board notification staff assessment re nonsafety-grade equipment to mitigate transients
VASSALLO, D B Assistant Director for Light Water Reactors 79/03/29 2pp

--7905010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients More info is required
TEDESCO, R L Assistant Director for Reactor Safety 79/03/16 3pp

7905100152 Applicants' brief opposing Suffolk County 790115 exceptions & 790226 supporting brief. Supporting documentation & Certificate of Svc encl
REVELEY, W T, WHITTEMORE Hunton & Williams 79/04/02 53pp

7905080053 Responds to request for info re possible shutdown of facilities due to possible design deficiencies caused by computer model design Computer model in question not used for facilities
HOEFLING, R K Branch 4 79/04/03 2pp

7905240278 Opposes intervenor County of Suffolk brief in support of exceptions to ASLB 781226 initial decision Certificate of Svc encl
BORDENICK, B M Branch 4 79/04/12 29pp

7905290106 Requests inclusion of NY Dept of Public Svc on svc list for NY siting proceeding
BLAU, J New York, State of 79/04/13 1p.

G Inspection reports, IE Bulletins & correspondence

7905010116 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/23 1p

7905020051 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director. 79/04/11 1p.

7905020395 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required.
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905040038 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director. 79/04/14 1p

7905040208 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905030070 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director. 79/04/17 1p.

7905020263 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/18 1p

B Reportable occurrences, LERs & related correspondence

7905110203 Board notification Seabrook refueling water storage tank design deficiency.
SCINTO, J. Hearings Division. 79/03/29. 30pp

DOCKET STN-30-517 JAMESPORT NUCLEAR STATION, UNIT 2

O Adjudicatory correspondence

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients
SCINTO, J F Hearings Division 79/04/02 31pp

--7905010156 Board notification staff assessment re nonsafety-grade equipment to mitigate transients.
VASSALLO, D B Assistant Director for Light Water Reactors 79/03/29 2pp

--7905010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients More info is required
TEDESCO, R L Assistant Director for Reactor Safety 79/03/16 3pp

7905100152 Applicants' brief opposing Suffolk County 790115 exceptions & 790226 supporting brief. Supporting documentation & Certificate of Svc encl
REVELEY, W T, WHITTEMORE Hunton & Williams 79/04/02 53pp

7905080053 Responds to request for info re possible shutdown of facility due to possible design deficiencies caused by computer model design Computer model in question not used for facilities
HOEFLING, R K Branch 4 79/04/03 2pp

7905240278 Opposes intervenor County of Suffolk brief in support of exceptions to ASLB 781226 initial decision Certificate of Svc encl
BORDENICK, B M Branch 4 79/04/12 29pp

7905290106 Requests inclusion of NY Dept of Public Svc on svc list for NY siting proceeding
BLAU, J New York, State of 79/04/13 1p

G Inspection reports, IE Bulletins & correspondence

7905010116 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/23 1p.

7905020051 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/11 1p

7905020395 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director. 79/04/14 1p

7905040038 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B H Region 1, Philadelphia, Office of the Director. 79/04/14 1p.

7905040208 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director. 79/04/14 1p.

7905030070 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/17 1p.

7905020263 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/18 1p.

B Reportable occurrences, LERs & related correspondence

7905110203 Board notification Seabrook refueling water storage tank design deficiency.
SCINTO, J. Hearings Division. 79/03/29. 30pp.

DOCKETED ITEMS

251

DOCKET STN-50-51B HARTSVILLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

7903080541 Discusses util position on leak testing, pressure & temp requirements of ACI Stds 318 & 349 for piping to be embedded in concrete. Revisions to PSAR re embedded piping will be implemented immediately.
GILLELAND, J. E. Tennessee Valley Authority 79/03/03 3pp

F. Security, medical, emergency & fire protection plans

7903300462 Forwards addl response to 780926 meeting minutes re STRIDE fire hazards analysis. Includes proposed design changes to fire protection sys. Requests early meeting to discuss responses.
GILLELAND, J. E. Tennessee Valley Authority 79/03/20 9pp

O. Adjudicatory correspondence

7903240874 Requests adoption of de minimus theory of Perkins ASLR Certificate of Bvc encl.
BANDER, H. B., WALLACE, L. E., GUTTERMAN, A. H. Tennessee Valley Authority 79/04/06 11pp

790311041B Response to ALAB-507 re radon emissions & de minimus theory from Perkins record Certificate of Bvc encl.
SCINTO, J. F. Hearings Division 79/04/11 45pp.

7903140519 Response to 790404 brief of Philadelphia Electric Co. PBE&O & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Bvc encl.
KEPFORD, C. R. Citizens for Safe Environment 79/04/11 8pp

7903140332 Notifies of consolidation of five intervenor groups re radon emissions issue. Parties have until 790525 in which to file for summary disposition.
DUFLO, M. E. Atomic Safety and Licensing Appeal Panel. 79/04/25 13pp

J Insurance & indemnity information

7903070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 17D, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTRONE, J. American Nuclear Insurers. 79/03/01 1p.

7903070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters 79/03/01 1p

Q Inspection reports, IE Bulletins & correspondence

7903010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/23 2pp

7903150072 Forwards IE Insp Repts 50-51B/79-06, 50-519/79-06, 50-520/79-06 & 50-521/79-06 on 790226-28 No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/23 2pp

--7903150081 IE Insp Repts 50-51B/79-06, 50-519/79-06, 50-520/79-06 & 50-521/79-06 on 790226-28. No noncompliance noted. Major areas inspected: const activities, IE circulars & GA program as implemented by Const Engineering Manual.
BURDETTE, T. E. Region 2, Atlanta, Office of the Director.
HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/22 4pp.

7903250422 Forwards IE Insp Repts 50-51B/79-07, 50-519/79-07, 50-520/79-07 & 50-521/79-07 on 790307-09 No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/02 2pp.

--7903280431 IE Insp Repts 50-51B/79-07, 50-519/79-07, 50-520/79-07 & 50-521/79-07 on 790307-09 No noncompliance noted. Major areas inspected: concrete foundation of spray pond areas, safety-related steel structures, & GA audits & schedule.
BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/02 6pp

7903240498 Forwards IE Insp Repts 50-51B/79-08, 50-519/79-08, 50-520/79-08 & 50-521/79-08 on 790326-0328 No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Office of the Director 79/04/06 2pp

--7903240507 IE Insp Repts 50-51B/79-08, 50-519/79-08, 50-520/79-08 & 50-521/79-08 on 790326-0328 No noncompliance noted. Major areas inspected: const activities, previously identified items, 10CFR50 55(e) items, 10CFR21 posting & QA.
BURDETTE, T. E. Region 2, Atlanta, Office of the Director.
HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/06 3pp

7903030368 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 3pp

7903040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 3pp

7903110368 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 1p

7903010341 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/18 1p

7903030172 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/17 2pp

7903020479 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/18 2pp

7903030253 Submits supplemental response to IE Bulletin 77-07 Original response submitted 78120. Provides addl info received from manufacturer & describes plans in area of electrical penetrations.
GILLELAND, J. E. Tennessee Valley Authority 79/04/27 5pp

R Periodic operating reports & related correspondence

7903150286 Forwards "Socioeconomic Monitoring & Mitigation Rept" Apr 1979. Future repts will be prepared semiannually.
GILLELAND, J. E. Tennessee Valley Authority 79/03/09 1p

--7903150294 "Socioeconomic Monitoring & Mitigation Rept" Apr 1979 * Tennessee Valley Authority 79/04/30 46pp

S. Reportable occurrences, LERs & related correspondence

7903140478 Forwards final rept of reportable condition re BWR/6 HPCS local control panels. (NRC OE-79-01)
GILLELAND, J. E. Tennessee Valley Authority 79/04/03 1p

--7903140482 Reportable condition on 790306 OE determined that defect existed in HPCS panel H22-P028. Caused by installation of nonqualified type relay. Procedures revised & QA program modified.
* Tennessee Valley Authority 79/04/03 2pp

DOCKET STN-50-51B HARTSVILLE NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7903080541 Discusses util position on leak testing, pressure & temp requirements of ACI Stds 318 & 349 for piping to be embedded in concrete. Revisions to PSAR re embedded piping will be implemented immediately.
GILLELAND, J. E. Tennessee Valley Authority 79/03/03 3pp

DOCKETED ITEMS

F Security, medical, emergency & fire protection plans

7905300462 Forwards addl response to 780926 meeting minutes re STREDE fire hazards analysis Includes proposed design changes to fire protection sys Requests early meeting to discuss responses
GILLELAND, J E Tennessee Valley Authority 79/05/20 9pp

G Adjudicatory correspondence

7905240874 Requests adoption of de minimus theory of Perkins ABL3 Certificate of Svc encl
BANGER, H B, WALLACE, L E, GUTTERMAN, A H Tennessee Valley Authority 79/04/06 11pp

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl.
SCINTO, J F. Hearings Division 79/04/11 45pp

7905140519 Response to 790404 brief of Philadelphia Electric Co, PSE&O & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Svc encl
KEPFORD, C R Citizens for Safe Environment 79/04/11 8pp

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition
DUFLO, M E. Atomic Safety and Licensing Appeal Panel. 79/04/25 13pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATTROCHINI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

K Inspection reports, IE Bulletins & correspondence

7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905150072 Forwards IE Insp Repts 50-518/79-06, 50-519/79-06, 50-520/79-06 & 50-521/79-06 on 790226-28 No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/23 2pp

--7905150081 IE Insp Repts 50-518/79-06, 50-519/79-06, 50-520/79-06 & 50-521/79-06 on 790226-28. No noncompliance noted. Major areas inspected: const activities, IE circulars & QA program as implemented by Const Engineering Manual
BURDETTE, T E Region 2, Atlanta, Office of the Director.
HERDT, A R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/22. 4pp

7905250422 Forwards IE Insp Repts 50-518/79-07, 50-519/79-07, 50-520/79-07 & 50-521/79-07 on 790307-09 No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 2pp

--7905250431 IE Insp Repts 50-518/79-07, 50-519/79-07, 50-520/79-07 & 50-521/79-07 on 790307-09 No noncompliance noted. Major areas inspected: concrete foundation of spray pond areas; safety-related steel structures; & QA audits & schedule
SWAN, W B. Region 2, Atlanta, Office of the Director.
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/02 6pp

7905240498 Forwards IE Insp Repts 50-518/79-08, 50-519/79-08, 50-520/79-08 & 50-521/79-08 on 790326-0328. No noncompliance noted.
MURPHY, C E. Region 2, Atlanta, Office of the Director. 79/04/06 2pp

--7905240507 IE Insp Repts 50-518/79-08, 50-519/79-08, 50-520/79-08 & 50-521/79-08 on 790326-0328. No noncompliance noted. Major areas inspected: const activities; previously identified items; 10CFR50.55(e) items; 10CFR21 posting & QA
BURDETTE, T E Region 2, Atlanta, Office of the Director
HERDT, A R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/06 5pp

7905030368 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 3pp

7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 3pp

7905110365 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/14 1p

7905010341 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/18 1p

7905030172 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/17 2pp

7905020479 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp

7905300253 Submits supplemental response to IE Bulletin 77-07 Original response submitted 78120. Provides addl info received from manufacturer & describes plans in area of electrical penetrations
GILLELAND, J E Tennessee Valley Authority 79/04/27 5pp

R. Periodic operating reports & related correspondence

7905150286 Forwards "Socioeconomic Monitoring & Mitigation Rept" Apr 1979 Future repts will be prepared semiannually
GILLELAND, J E Tennessee Valley Authority 79/05/09 1p

--7905150294 "Socioeconomic Monitoring & Mitigation Rept" Apr 1979.
* Tennessee Valley Authority 79/04/30. 46pp

B Reportable occurrences, LERs & related correspondence

7905140478 Forwards final rept of reportable condition re BWR/6 WPCB local control panels. (NRC OE-79-01)
GILLELAND, J E Tennessee Valley Authority 79/04/03. 1p

--7905140482 Reportable condition on 790306 OE determined that defect existed in WPCB panel H22-P028. Caused by installation of nonqualified type relay Procedures revised & QA program modified
* Tennessee Valley Authority. 79/04/03 2pp

DOCKET BTN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3A. Application/construction stage documents & correspondence

7905080541 Discusses util position on leak testing, pressure & temp requirements of ACI Stds 318 & 349 for piping to be embedded in concrete Revisions to PSAR re embedded piping will be implemented immediately.
GILLELAND, J E Tennessee Valley Authority. 79/05/03 3pp

DOCKETED ITEMS

263

F. Security, medical, emergency & fire protection plans

7905300462 Forwards addl response to 780926 meeting minutes re STRIDE fire hazards analysis. Includes proposed design changes to fire protection sys. Requests early meeting to discuss responses.
GILLELAND, J E Tennessee Valley Authority 79/05/20 9pp

G. Adjudicatory correspondence

7905240874 Requests adoption of de minimus theory of Perkins ABLB Certificate of Svc encl
SANGER, H B., WALLACE, L E., GUTTERMAN, A H Tennessee Valley Authority 79/04/06 11pp

7905110418 Response to ALAB-309 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl
SCINTO, J F Hearings Division 79/04/11 45pp

7905140519 Response to 790404 brief of Philadelphia Electric Co, PSE&O & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Svc encl
KEPFORD, C R Citizens for Safe Environment 79/04/11 8pp

7905140332 Notices of consolidation of five intervenor groups re radon emissions issue. Parties have until 790525 in which to file for summary disposition.
DUFLO, M E. Atomic Safety and Licensing Appeal Panel 79/04/25 13pp

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHI, J American Nuclear Insurers 79/05/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D M Mutual Atomic Energy Liability Underwriters, 79/05/01, 1p

G. Inspection reports, IE Bulletins & correspondence

7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23, 2pp

7905150072 Forwards IE Insp Repts 50-518/79-06, 50-519/79-06, 50-520/79-06 & 50-521/79-06 on 790226-28 No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/23, 2pp

--7905150081 IE Insp Repts 50-518/79-06, 50-519/79-06, 50-520/79-06 & 50-521/79-06 on 790226-28 No noncompliance noted. Major areas inspected const activities, IE circulars & QA program as implemented by Const Engineering Manual.
BURDETTE, T E Region 2, Atlanta, Office of the Director.
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/22 4pp.

7905250422 Forwards IE Insp Repts 50-518/79-07, 50-519/79-07, 50-520/79-07 & 50-521/79-07 on 790307-09. No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02, 2pp

--7905250431 IE Insp Repts 50-518/79-07, 50-519/79-07, 50-520/79-07 & 50-521/79-07 on 790307-09. No noncompliance noted. Major areas inspected concrete foundation of spray pond areas, safety-related steel structures, & QA audits & schedule.
SHAM, W B Region 2, Atlanta, Office of the Director.
BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 6pp

7905240498 Forwards IE Insp Repts 50-518/79-08, 50-519/79-08, 50-520/79-08 & 50-521/79-08 on 790326-0328 No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Office of the Director 79/04/06, 2pp

--7905240507 IE Insp Repts 50-518/79-08, 50-519/79-08, 50-520/79-08 & 50-521/79-08 on 790326-0328 No noncompliance noted. Major areas inspected const activities, previously identified items, 10CFR50.55(a) items, 10CFR21, posting & QA.
BURDETTE, T E Region 2, Atlanta, Office of the Director.
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 79/04/06 5pp

7905030368 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 3pp

7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/04/14 3pp

7905110365 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident."
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/04/14 1p

7905010341 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 1p

7905030172 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp

7905020479 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp

7905300253 Submits supplemental response to IE Bulletin 77-07. Original response submitted 78120 Provides addl info received from manufacturer & describes plans in area of electrical penetrations.
GILLELAND, J E Tennessee Valley Authority 79/04/27 5pp.

R. Periodic operating reports & related correspondence

7905150286 Forwards "Socioeconomic Monitoring & Mitigation Rept" Apr 1979. Future repts will be prepared semiannually.
GILLELAND, J E Tennessee Valley Authority 79/05/09, 1p.

--7905150294 "Socioeconomic Monitoring & Mitigation Rept" Apr 1979
* Tennessee Valley Authority, 79/04/30 46pp.

B. Reportable occurrences, LERs & related correspondence

7905140478 Forwards final rept of reportable condition re BWR/6 HPCB local control panels (NRC OE-79-Q11)
GILLELAND, J E Tennessee Valley Authority, 79/04/05, 1p.

--7905140482 Reportable condition on 790306. OE determined that defect existed in HPCB panel H22-P028. Caused by installation of nonqualified type relay. Procedures revised & QA program modified.
* Tennessee Valley Authority, 79/04/05, 2pp

DOCKET SIN-30-321 HARTSVILLE NUCLEAR PLANT, UNIT 4

A. Application/construction stage documents & correspondence

7905080541 Discusses util position on leak testing, pressure & temp requirements of ACI Stds 318 & 349 for piping to be embedded in concrete. Revisions to PSAR re embedded piping will be implemented immediately.
GILLELAND, J E Tennessee Valley Authority 79/05/03, 3pp.

DOCKETED ITEMS

F Security, medical, emergency & fire protection plans

7905300462 Forwards addl response to 780926 meeting minutes re STRIDE fire hazards analysis Includes proposed design changes to fire protection sys Requests early meeting to discuss responses
OILLELAND, J E Tennessee Valley Authority 79/03/20 9pp

G Adjudicatory correspondence

7905240874 Requests adoption of de minimus theory of Perkins ASLB. Certificate of Bvc encl.
SANDER, H. B Tennessee Valley Authority. 79/04/06 11pp

7905110418 Response to ALAB-309 re radon emissions & de minimus theory from Perkins record Certificate of Bvc encl
SCINTO, J F Hearings Division 79/04/11 45pp

7905140319 Response to 790404 brief of Philadelphia Electric Co, PSE&O & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Bvc encl.
KEPFORD, C R Citizens for Safe Environment 79/04/11 8pp.

7905140332 Notices of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition
DUFLO, M E Atomic Safety and Licensing Appeal Panel 79/04/23 13pp.

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 29, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 183, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
QUATROCHINI, J American Nuclear Insurers 79/03/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/03/01 1p.

Q. Inspection reports, IE Bulletins & correspondence

7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23. 2pp.

7905130072 Forwards IE Insp Repts 50-518/79-06, 50-519/79-06, 50-520/79-06 & 50-521/79-06 on 790226-28 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/23. 2pp.

--7905130081 IE Insp Repts 50-518/79-06, 50-519/79-06, 50-520/79-06 & 50-521/79-06 on 790226-28 No noncompliance noted Major areas inspected, const activities, IE circulars & QA program as implemented by Const Engineering Manual.
BURDETTE, T E Region 2, Atlanta, Office of the Director. 79/03/22. 4pp

7905250422 Forwards IE Insp Repts 50-518/79-07, 50-519/79-07, 50-520/79-07 & 50-521/79-07 on 790307-09 No noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/02 2pp

--7905250431 IE Insp Repts 50-518/79-07, 50-519/79-07, 50-520/79-07 & 50-521/79-07 on 790307-09. No noncompliance noted. Major areas inspected: concrete foundation of spray pond areas, safety-related steel structures, & QA audits & schedule.
SWAN, W B Region 2, Atlanta, Office of the Director. 79/04/02. 6pp

7905240498 Forwards IE Insp Repts 50-518/79-08, 50-519/79-08, 50-520/79-08 & 50-521/79-08 on 790326-0328. No noncompliance noted.
MURPHY, C E Region 2, Atlanta, Office of the Director 79/04/06. 2pp

--7905240507 IE Insp Repts 50-518/79-08, 50-519/79-08, 50-520/79-08 & 50-521/79-08 on 790326-0328. No noncompliance noted Major areas inspected: const activities, previously identified items, 10CFR50.55(e) items, 10CFR21 posting & QA
BURDETTE, T E Region 2, Atlanta, Office of the Director. 79/04/06. 5pp

7905030364 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/14. 3pp

7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 3pp

7905110303 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p.

7905010341 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 1p

7905030172 Forwards IE Bulletin 79-09, "Failures of OE Type AX-2 Circuit Breaker in Safety-Related Bys" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp

7905020479 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18. 2pp

7905030253 Submits supplemental response to IE Bulletin 77-07 Original response submitted 780120 Provides addl info received from manufacturer & describes plans in area of electrical penetrations
OILLELAND, J E Tennessee Valley Authority 79/04/27 3pp

R Periodic operating reports & related correspondence

7905130296 Forwards "Socioeconomic Monitoring & Mitigation Rept" Apr 1979. Future repts will be prepared semiannually
OILLELAND, J E Tennessee Valley Authority 79/03/09 1p

--7905130294 "Socioeconomic Monitoring & Mitigation Rept" Apr 1979
* Tennessee Valley Authority 79/04/30 46pp.

B. Reportable occurrences, LERs & related correspondence

7905140478 Forwards final rept of reportable condition re BHR/6 I#CB local control panels (NRC OE-79-01)
OILLELAND, J E Tennessee Valley Authority 79/04/05. 1p

--7905140482 Reportable condition on 790306 OE determined that defect existed in HPCB panel H22-P028. Caused by installation of nonqualified type relay Procedures revised & QA program modified
* Tennessee Valley Authority. 79/04/05. 2pp

DOCKET STN-50-522 SKA01T NUCLEAR POWER PROJECT, UNIT 1A Application/construction stage documents & correspondence

7905090211 Forwards summary of 790227 meeting of Skagit River Indian's representatives w/House Committee on Interior & Insular Affairs.
LEECH, P H Environmental Projects Branch 2 79/04/10 1p

--7905090264 Summary of 790227 meeting w/representatives of Indian tribes in Washington, DC re study, funded by Bureau of Indian Affairs, of potential impact of facility on local hydrology, socioeconomic conditions & Indian fisheries.
KAMMERER, G. Office of Congressional Affairs 79/03/03 2pp

7905230826 Discusses delays in issuance of CP in response to 790212 telegram to President Carter
STOLZ, J F Light Water Reactors Branch 1. 79/04/16. 3pp

7905240857 Approves request to withhold from public disclosure 790223 & 790416 ltrs re aeromagnetic data.
STOLZ, J F. Light Water Reactors Branch 1. 79/04/30. 4pp

7905090090 Forwards "Environ Assessment, DOA Plant Assessment," in response to NRC 780605 request Recommends mods re mgt requirements in applicant's mitigation plan, Encl available in Central Files.
BERGLAND, B Agriculture, Dept of. 79/03/02. 2pp.

DOCKETED ITEMS

265

7905160347 Forwards "Rept of Geological Investigations in 1978-1979," Vols 2 & 3. Discusses deferred & supplemental sections.
MECCA, J E Puget Sound Power & Light Co. 79/05/10 7pp

--7905160356 "Rept of Geological Investigations in 1978-1979" Vols 2 & 3
Four oversized drawings encl
* Puget Sound Power & Light Co 79/05/10. 281pp

7905310383 Responds to 780630 request for addl geological info Forwards
addl supportive matl to "Rept of Geologic Investigations in
1978-1979" Extensive geologic investigations confirm site
suitability. Rept encl
MECCA, J E Puget Sound Power & Light Co 79/05/25 100pp

0 Adjudicatory correspondence

7905140159 Motion for leave to file interim statement of issues three
days out of time, on 790312
BUSCH, R W Evergreen Legal Services MEANS, D S. Means, Donald S
79/03/12. 2pp.

--7905140161 Intervenor Tribes interim statement of issues in response to
790208 order.
BUSCH, R W Evergreen Legal Services. MEANS, D S. Means, Donald S
79/03/12 23pp.

7905230818 Forelaws on Board/Coalition for Safe Power's statement of
issues, submitted per 790208 order Follows applicant 790222
revised statement. Discusses environ issues. Certificate of
Svc encl
STACHOM, E O Coalition for Safe Power 79/03/16 4pp.

7905010115 Forwards request for Board notification re nonsafety-grade
equipment to mitigate transients
SCINTO, J F Hearings Division 79/04/02 31pp

--7905010156 Board notification staff assessment re nonsafety-grade
equipment to mitigate transients
VABBALLO, D B Assistant Director for Light Water Reactors
79/03/29 2pp.

--7905010198 Board notification, recent issue on nonsafety-grade
equipment to mitigate transients More info is required
TEDESCO, R. L. Assistant Director for Reactor Safety 79/03/16
3pp.

7905250128 Forwards policy statement re NUREG/CR-0400, reactor safety
study & survey of uses made of WASH-1400 W/o encl.
BLACK, R L. Branch 1. 79/04/04 1p.

7905140030 Order for agenda of conference scheduled for 790424-26.
DEALE, V. B Atomic Safety and Licensing Board Panel. 79/04/10 7pp

7905250180 Advises that recommended order of OR Energy Facility Siting
Council hearing examiner will be issued in Aug 1979 rather
than Apr 1979.
BANDVIK, R. M Oregon, State of 79/04/17. 1p

1. Financial information

7905250459 Forwards addl financial info, as requested by NRC 790405 ltr.
Info includes matl re testimony & exhibits in most recent
rate relief actions; BEC prospectus & annual financial repts.
MECCA, J. E. Puget Sound Power & Light Co 79/05/17 350pp

--7905250465 "Annual Financial Rept 1978."
* Puget Sound Power & Light Co 78/12/31. 43pp.

--7905250472 "Annual Financial Rept 1978"
* Pacific Power Co. 78/12/31. 32pp

7905310372 Responds to 790405 ltr. Forwards financial info. form
BEC 10-K, prospectus, testimony, exhibits & "Portland OE
Pro Forma Sources of Funds for Sys Wide Const. Expenditures
& Capital Structure." Encl in Central Files.
MECCA, J. E Puget Sound Power & Light Co. 79/05/25. 400pp.

T. Hearing transcripts on non-antitrust matters

7905140016 Transcript of 790424 meeting in Seattle, WA. Pp 11, 776-11, 953.
DEALE, V. B., LINENBERGER, G., HOOVER, F. F. Atomic Safety and Licensing
Board Panel. 79/04/24. 178pp.

DOCKET STN-50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2

A. Application/construction stage documents & correspondence

7905090211 Forwards summary of 790227 meeting of Skagit River Indian's
representatives w/House Committee on Interior & Insular
Affairs
LEECH, P M Environmental Projects Branch 2 79/04/10 1p

--7905090264 Summary of 790227 meeting w/representatives of Indian tribes
in Washington, DC re study, funded by Bureau of Indian
Affairs, of potential impact of facility on local hydrology,
socioeconomic conditions & Indian fisheries
KAMMERER, C Office of Congressional Affairs 79/03/05 2pp

7905230826 Discusses delays in issuance of CP in response to 790212
telegram to President Carter
STOLZ, J F Light Water Reactors Branch 1 79/04/16 3pp

7905240857 Approves request to withhold from public disclosure 790223
& 790416 ltrs re aeromagnetic data
STOLZ, J F Light Water Reactors Branch 1 79/04/30 4pp

7905090090 Forwards "Environ Assessment, DOA Plant Assessment," in
response to NRC 780605 request Recommends mods re mgt
requirements in applicant's mitigation plan Encl
available in Central Files
BERGLAND, S Agriculture, Dept of 79/05/02 2pp

7905160347 Forwards "Rept of Geological Investigations in 1978-1979,"
Vols 2 & 3 Discusses deferred & supplemental sections
MECCA, J E Puget Sound Power & Light Co 79/05/10 7pp

--7905160356 "Rept of Geological Investigations in 1978-1979" Vols 2 & 3
Four oversized drawings encl
* Puget Sound Power & Light Co 79/05/10 281pp

7905310383 Responds to 780630 request for addl geological info Forwards
addl supportive matl to "Rept of Geologic Investigations in
1978-1979." Extensive geologic investigations confirm site
suitability Rept encl
MECCA, J E Puget Sound Power & Light Co 79/05/25 100pp

0 Adjudicatory correspondence

7905140159 Motion for leave to file interim statement of issues three
days out of time, on 790312
BUSCH, R W Evergreen Legal Services MEANS, D S Means, Donald S
79/03/12 2pp

--7905140161 Intervenor Tribes interim statement of issues in response to
790208 order.
BUSCH, R W Evergreen Legal Services MEANS, D B Means, Donald S
79/03/12. 23pp

7905230818 Forelaws on Board/Coalition for Safe Power's statement of
issues, submitted per 790208 order Follows applicant 790222
revised statement Discusses environ issues Certificate of
Svc encl.
STACHOM, E. O Coalition for Safe Power 79/03/16 4pp

7905010115 Forwards request for Board notification re nonsafety-grade
equipment to mitigate transients.
SCINTO, J. F Hearings Division 79/04/02 31pp

--790501
equi
VAB
79/

--79050
equ
TED
3pp

7905250
study
BLACK

7905140
DEALE

DOCKETED ITEMS

I. Financial information

7905250439 Forwards addl financial info. as requested by NRC 790405 ltr
Info includes matl re testimony & exhibits in most recent
rate relief actions, SEC prospectus & annual financial repts
MECCA, J E Puget Sound Power & Light Co 79/05/17 350pp

--7905250465 "Annual Financial Rept 1978"
* Puget Sound Power & Light Co 78/12/31 43pp

--7905250472 "Annual Financial Rept 1978"
* Pacific Power Co 78/12/31 32pp

7905310372 Responds to 790405 ltr Forwards financial info form
SEC 10-K, prospectus, testimony, exhibits & "Portland GE
Pro Forma Sources of Funds for Sys Wide Const Expenditures
& Capital Structure" Encl in Central Files
MECCA, J E Puget Sound Power & Light Co 79/05/25 400pp

T. Hearing transcripts on non-antitrust matters

7905140016 Transcript of 790424 meeting in Seattle, WA Pp 11, 776-11, 953
DEALE, V B, LINENBERGER, O, HOOPER, F F Atomic Safety and Licensing
Board Panel. 79/04/24 178pp.

DOCKET 50-524 BARTON, UNIT 1

O Adjudicatory correspondence

7905140280 Describes NRC notification to ASLAB during past year re
nuclear power reactors, for info of Board & parties in
proceeding
GRAY, J R Branch 1 79/04/12 3pp

--7905140287 Discusses issue of neutron exposure at commercial power
reactors No problem exists Questions data on which concerns
were based
EISENHUT, D O Division of Operating Reactors VOLLHER, R H,
Assistant Director for Site Analysis 79/03/05 2pp

--7905140292 Follows up 790306 memo & 790301 & 08 meetings re GE's
BWR-N888 equipment adequacy evaluation Describes action plan
which parallels program & proposed decision process plan
MATTSON, R J Division of Systems Safety 78/03/16 4pp

--7905140299 Summary of 780301 meeting w/GE re GE's BWR-N888 equipment
adequacy evaluation for Mark II & III plants, w/supporting
documentation
MATTSON, R J Division of Systems Safety. 78/03/06 21pp

DOCKET 50-525 BARTON, UNIT 2

O Adjudicatory correspondence

7905140280 Describes NRC notification to ASLAB during past year re
nuclear power reactors, for info of Board & parties in
proceeding
GRAY, J R Branch 1 79/04/12 3pp

--7905140287 Discusses issue of neutron exposure at commercial power
reactors No problem exists. Questions data on which concerns
were based
EISENHUT, D O Division of Operating Reactors. VOLLHER, R H,
Assistant Director for Site Analysis. 79/03/05. 2pp

--7905140292 Follows up 790306 memo & 790301 & 08 meetings re GE's
BWR-N888 equipment adequacy evaluation Describes action plan
which parallels program & proposed decision process plan.
MATTSON, R J Division of Systems Safety. 78/03/16. 4pp.

--7905140299 Summary of 780301 meeting w/GE re GE's BWR-N888 equipment
adequacy evaluation for Mark II & III plants W/supporting
documentation.
MATTSON, R. J. Division of Systems Safety. 78/03/06 21pp

DOCKET 50-526 PALO VERDE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

7905220386 Requests authorization to use encl ASME code cases in plant
const.
VAN BRUNT, E E Arizona Public Service Co. 79/05/07. 2pp.

--7905220392 Ack receipt of 741004 ltr requesting approval of ASME Code
14B1 for use in design of hydrogen recombiner for post-LOCA
use. Approval is granted
SCHROEDER, F Atomic Energy Commission, Directorate of Licensing
(Pre-1975) 74/10/22 1p.

--7905220397 Requests authorization to use ASME Code Case 1592 in design
of hydrogen recombiners for post-LOCA use w/list of LWR
projects incorporating subj. criteria
STONE, L R Rockwell International Corp 78/04/14 2pp.

G Inspection reports, IE Bulletins & correspondence

7905150609 Forwards IE Insp Repts 50-528/78-09 & 50-529/78-07 on
781218-21 No noncompliance noted.
VAN BRUNT, E E Region 5, San Francisco, Reactor Construction &
Engineering Support Branch 79/03/16 2pp.

--7905150620 IE Insp Repts 50-528/78-09 & 50-529/78-07 on 781218-21 No
noncompliance noted Major areas inspected: containment
structural concrete, containment post tensioning sys, reactor
vessel final alignment & electrical cable & components.
HAYNES, R C Region 5, San Francisco, Office of the Director
ECKHARDT, J H, NARBUT, P P Region 5, San Francisco, Reactor
Construction & Engineering Support Branch 79/03/16 11pp.

7905010283 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping"
ENGELKEN, R H Region 4, Dallas, Office of the Director 79/03/23
1p

7905040074 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tank"
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/03/26 1p

7905290054 Responds to IE Bulletin 79-03 Forwards 781117 ltr
VANBRUNT, E E Arizona Public Service Co. 79/04/03. 1p

7905010016 Forwards IE Bulletin 79-06A, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident"
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/14. 1p

7905040307 Forwards IE Bulletin 79-06B, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident"
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/14. 1p

7905040614 Forwards IE Bulletin 79-08, "Events Relevant to Boiling
Water Power Reactors Identified During TMI Incident."
ENGELKEN, R H Region 5, San Francisco, Office of the Director.
79/04/14. 1p

7905070098 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of
Safety-Related Piping" Licensee action required.
ENGELKEN, R H Region 5, San Francisco, Office of the Director.
79/04/14 1p

7905030286 Forwards IE Bulletin 79-09, "Failures of GE Type AX-2
Circuit Breaker in Safety-Related Sys." Licensee action
required
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/17. 1p

7905080365 Forwards IE Bulletin 79-05B, "Nuclear Incident at
TMI-Suppl"
ENGELKEN, R H Region 5, San Francisco, Office of the Director.
79/04/21. 1p.

7905290072 Response to IE Bulletins 78-12 & 78-12A will be submitted by
790713. Awaiting generic rept from C-E.
VANBRUNT, E E. Arizona Public Service Co. 79/05/25. 1p.

B Reportable occurrences, LERs & related correspondence

7905150057 Forwards PNO-79-67L.
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/06 1p

7905130165 Forwards PNO-79-67R
ENGELKEN, R H Region 5, San Francisco, Office of the Director.
79/04/11. 1p.

7905040121 Forwards PNO-79-67B.
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/04/12. 1p

DOCKETED ITEMS

257

7905150136 Forwards PNO-79-67T
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/13 1p

7905030030 Forwards PNO-79-67U
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p.

7905020525 Forwards PNO-79-67AA
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/20 1p

7905010420 Forwards PNO-79-67AB.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/21 1p

7905010442 Forwards PNO-79-67AC & AD.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/23 1p

7905010456 Forwards PNO-79-67AE
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/04/24 1p

7905090038 Forwards PNO-79-67AF
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/25 1p

7905090053 Forwards PNO-79-67AG
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/26 1p

7905090115 Forwards PNO-79-67AH
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/04/27 1p

7905070025 Forwards PNO-79-67AI, AJ & AK per NRC 790401 ltr transmitting
IE Bulletin 79-05
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/04/30 1p

7905040355 Forwards PNO-79-67AL per NRC 790401 ltr transmitting IE
Bulletin 79-05
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/05/01 1p.

--7905040358 PNO-79-67AL summary of info re nuclear incident as of
790501. Describes plant & environ status
* Office of Inspection & Enforcement 79/05/01 3pp.

7905310059 Forwards PNO-79-67AM
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/05/07 1p

DOCKET SYN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

7905220386 Requests authorization to use encl ASME code cases in plant
const.
VAN BRUNT, E. E. Arizona Public Service Co. 79/03/07 2pp

--7905220392 Ack receipt of 741004 ltr requesting approval of ASME Code
1481 for use in design of hydrogen recombiner for post-LOCA
use. Approval is granted
SCHROEDER, F. Atomic Energy Commission, Directorate of Licensing
(Pre-1979). 74/10/22. 1p

--7905220397 Requests authorization to use ASME Code Case 1592 in design
of hydrogen recombiners for post-LOCA use w/list of LWR
projects incorporating sub criteria
STONE, L. R. Rockwell International Corp 78/04/14. 2pp.

B Inspection reports, IE Bulletins & correspondence

7905150609 Forwards IE Insp Repts 50-528/78-09 & 50-529/78-07 on
781218-21. No noncompliance noted.
VAN BRUNT, E. E. Region 3, San Francisco, Reactor Construction &
Engineering Support Branch. 79/03/16 2pp.

--7905150620 IE Insp Repts 50-528/78-09 & 50-529/78-07 on 781218-21. No
noncompliance noted. Major areas inspected: containment
structural concrete, containment post tensioning sys, reactor
vessel final alignment & electrical cable & components
MAYNES, R. C. Region 3, San Francisco, Office of the Director.
ECKHARDT, J. H., VANBRUNT, P. P. Region 3, San Francisco, Reactor
Construction & Engineering Support Branch 79/03/16. 11pp.

7905010283 Forwards IE Info Notice 79-06: "Stress Analysis of
Safety-Related Piping"
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director 79/03/23
1p

7905040076 Forwards IE Info Notice 79-07: "Rupture of Radwaste Tanks."
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/03/26 1p

7905290056 Responds to IE Bulletin 79-03 Forwards 781117 ltr
VANBRUNT, E. E. Arizona Public Service Co 79/04/03 1p

7905010016 Forwards IE Bulletin 79-06A: "Review of Operational Errors &
Bus Misalignments Identified During TMI Incident."
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/04/14. 1p

7905040507 Forwards IE Bulletin 79-06B: "Review of Operational Errors &
Bus Misalignments Identified During TMI Incident"
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p

7905040614 Forwards IE Bulletin 79-08: "Events Relevant to Boiling
Water Power Reactors Identified During TMI Incident"
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p

7905070098 Forwards IE Bulletin 79-07: "Seismic Stress Analysis of
Safety-Related Piping" Licensee action required
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p

7905030286 Forwards IE Bulletin 79-09: "Failures of GE Type AK-2
Circuit Breaker in Safety-Related Bus" Licensee action
required
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/17 1p

7905080365 Forwards IE Bulletin 79-05B: "Nuclear Incident at
TMI-Suppl"
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/21 1p

7905290072 Response to IE Bulletins 78-12 & 78-12A will be submitted by
790913. Awaiting generic rept from C-E
VANBRUNT, E. E. Arizona Public Service Co. 79/03/25 1p

B Reportable occurrences, LERs & related correspondence

7905150057 Forwards PNO-79-67L
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/06 1p

7905150165 Forwards PNO-79-67R
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/11 1p

7905040121 Forwards PNO-79-67B.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/12. 1p.

7905150136 Forwards PNO-79-67T.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/04/13. 1p.

7905030050 Forwards PNO-79-67U
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p

7905020525 Forwards PNO-79-67AA.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/04/20 1p.

7905010420 Forwards PNO-79-67AB.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/04/21 1p.

7905010442 Forwards PNO-79-67AC & AD.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director
79/04/23. 1p

7905010456 Forwards PNO-79-67AE
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/04/24. 1p.

7905090038 Forwards PNO-79-67AF
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/04/25 1p.

DOCKETED ITEMS

7905090053 Forwards PNO-79-67A0
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director.
79/04/26 1p

7905090113 Forwards PNO-79-67AH
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/27 1p

7905070025 Forwards PNO-79-67AI, AJ & AK per NRC 790401 ltr transmitting
IE Bulletin 79-05
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/30 1p

7905040355 Forwards PNO-79-67AL per NRC 790401 ltr transmitting IE
Bulletin 79-05
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/05/01 1p

7905310059 Forwards PNO-79-67AM
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/05/07 1p

DOCKET STN-50-330 PALO VERDE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

7905100029 Suggests NRC command & control ctr w/communications link
that automatically receives data from operating reactors &
shippers of SNH
PODOLAK, E. M. Radiological Health Standards Branch 79/04/17
1p

7905220386 Requests authorization to use encl ASME code cases in plant
const
VAN BRUNT, E. E. Arizona Public Service Co 79/05/07. 2pp

--7905220392 Ack receipt of 741004 ltr requesting approval of ASME Code
1481 for use in design of hydrogen recombiner for post-LOCA
use Approval is granted.
SCHROEDER, F. Atomic Energy Commission, Directorate of Licensing
(Pre-1975) 74/10/22 1p

--7905220397 Requests authorization to use ASME Code Case 1592 in design
of hydrogen recombiners for post-LOCA use. W/1ist of LWR
projects incorporating subj criteria
STONE, L. R. Rockwell International Corp. 78/04/14 2pp.

G Inspection reports, IE Bulletins & correspondence

7905010283 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping."
ENGELKEN, R. H. Region 4, Dallas, Office of the Director. 79/03/23.
1p

Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
Region 5, San Francisco, Office of the Director
2.

IE Bulletin 79-03 Forwards 781117 ltr.
na Public Service Co. 79/04/03. 1p.

tin 79-06A, "Review of Operational Errors &
ed During TMI Incident."
San Francisco, Office of the Director.

tin 79-06B, "Review of Operational Errors &
ed During TMI Incident."
San Francisco, Office of the Director.

tin 79-08, "Events Relevant to Boiling
ified During TMI Incident."
San Francisco, Office of the Director.

tin 79-07, "Seismic Stress Analysis of
consequence action required
San Francisco, Office of the Director

tin 79-09, "Failures of OE Type AK-2
Related Sys." Licensee action

San Francisco, Office of the Director.

7905080365 Forwards IE Bulletin 79-05B, "Nuclear Incident at
TMI-Suppl."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/21 1p

7905290072 Response to IE Bulletins 78-12 & 78-12A will be submitted by
790713. Awaiting generic rept from C-E
VANBRUNT, E. E. Arizona Public Service Co 79/05/25 1p

S. Reportable occurrences, LERs & related correspondence

7905150037 Forwards PNO-79-67L
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/06 1p

7905150165 Forwards PNO-79-67R
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/11 1p.

7905040121 Forwards PNO-79-67S
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/12 1p

7905150136 Forwards PNO-79-67T
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/13 1p

7905030050 Forwards PNO-79-67U
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/14 1p

7905020525 Forwards PNO-79-67AA
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/20. 1p

7905010420 Forwards PNO-79-67AB
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/21 1p

7905010442 Forwards PNO-79-67AC & AD
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/23. 1p.

7905010436 Forwards PNO-79-67AE
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/24. 1p.

7905090038 Forwards PNO-79-67AF
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/25 1p

7905090053 Forwards PNO-79-67A0
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/26 1p

7905090115 Forwards PNO-79-67AH
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/27. 1p

7905070025 Forwards PNO-79-67AI, AJ & AK per NRC 790401 ltr transmitting
IE Bulletin 79-05
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/04/30 1p

7905040355 Forwards PNO-79-67AL per NRC 790401 ltr transmitting IE
Bulletin 79-05.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director.
79/05/01. 1p.

7905310059 Forwards PNO-79-67AM
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director
79/05/07. 1p

DOCKET STN-50-531 OEBBAR-251

J. Insurance & indemnity information

7905070582 Confirms increase in liability limit to \$36,000,000 for
policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters 79/05/01
1p.

DOCKETED ITEMS

259

DOCKET STN-50-532 BOP BAR

A. Application/construction stage documents & correspondence

7905240676 Notifies that expiration date for Preliminary Design Approval 5 is extended to 810807, based on review of Amend 9 to application
BOYD, R B Division of Project Management 79/05/03 2pp

DOCKET 50-537 Clinch River Breeder Reactor

A Application/construction stage

7905020293 Forwards affidavit confirming distribution of PSAR Amend 49 to designated local public officials & EPA representatives
COPELAND, R L Energy, Dept of, Clinch River Breeder Reactor Plant 79/04/25 2pp

DOCKET 50-538 MEMPHIS STATE UNIV RESEARCH REACTOR

J Insurance & indemnity information

7905160232 Forwards Amend 2 to Indemnity Agreement E-59, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

Q Inspection reports, IE Bulletins & correspondence

7905070153 Forwards IE Bulletins 79-05, 79-05A & 79-06 re nuclear incident at TMI
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/13 1p

DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

7905070292 Responds to comments re application for const of pumphouse intake & discharge structure W/781016 ltr from Attorney General of KY to Corps of Engineers, Louisville re dredge & fill application of Public Svc Co of IN
WHITLOCK, W N Army, Dept of, Corps of Engineers 78/11/06 7pp

--7905090296 Notifies of licensee's mitigation plan to recover archeological resources disturbed by const of intake & discharge structures W/IN Dept of Natural Resources ltr discussing plan
BALLARD, R L Environmental Projects Branch 2 78/09/22 2pp.

7905020445 Forwards NUREG-0531, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability W/o encl
VASSALLO, D B Assistant Director for Light Water Reactors 79/03/23 3pp.

7905020521 Responds to 790403 ltr re cubicle coolers w/improperly installed gaskets. Matter will be reviewed in future insp
FIORELLI, O Region 3, Chicago, Office of the Director, 79/04/17 1p

7905100171 Notification of 790503 meeting w/util in Bethesda, MD to discuss Caseload Forecast Panel's estimate for fuel load date & submittal date for FBAR.
VARQA, S A Light Water Reactors Branch 4, 79/04/23 4pp.

7905150296 Notification that lack of expected prehistoric resources justifies termination of mitigation effort
BALLARD, R L, Environmental Projects Branch 1, 79/04/30 2pp

7905080415 Discusses NRC intention to delay FBAR review until end of year. Delay is unacceptable, as based on average const schedule Util is better than average & unit is committed for 1982 operation FBAR will be filed in June 1979.
COUCHLIN, J, Public Service Co. of Indiana, Inc 79/05/04 4pp.

Q Adjudicatory correspondence

7905150220 Motion to reopen safety hearings to discuss WASH-1400 & herbicide "2,4,5-T"
DATTILO, T M Dattilo, T.M. 79/03/22 2pp.

7905020448 Forwards NRC memo discussing problems experienced w/pipes support base plate design Piping design analysis on case-by-case basis being reviewed under BRP Section 3.9.2.
BRENNER, L. Branch 3 79/04/05 2pp

7905020456 Forwards 780929 memo from Director of Ofc of Nuclear Reactor Regulation to Commissioners, discussing fire protection research test results conducted by UL.
BRENNER, L. Branch 3 79/04/05 2pp.

7905160208 Forwards latest motion to reopen safety hearings by T Dattilo on behalf of Save the Valley - Save Marble Hill
Forwards revisions to draft motions attached to 790402 memo
MURRAY, J P Rulemaking & Enforcement Division 79/04/05 2pp.

--7905160212 Motion to suspend & revoke CP for proposed facility because of TMI incident
DATTILO, T.M Matford & Dattilo 79/04/04 2pp

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl.
SCINTO, J F Hearings Division 79/04/11 45pp

7905140519 Response to 790404 brief of Philadelphia Electric Co, PSE&O & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Svc encl
KEPFORD, C R Citizens for Safe Environment 79/04/11 8pp

7905240791 Ack receipt of 790404 petition to institute const suspension proceedings Decision under consideration Forwards 790412 FR notice
DENTON, H R Office of Nuclear Reactor Regulation 79/04/12 1p.

--7905240813 FR notice of request to reopen safety hearing
BOYD, R B Office of Nuclear Reactor Regulation 79/04/12 2pp.

--7905240850 Forwards motion of intervenor to reopen safety hearing, petition to revoke CP & FR notice.
DENTON, D R Office of Nuclear Reactor Regulation 79/04/12 5pp

--7905240872 Motion for ASLAB to reopen safety hearings
DATTILO, T.M Save the Valley - Save Marble Hill, 79/04/12 2pp

--7905240964 Motion to reopen safety hearings due to EPA ban on herbicide & invalidity of WASH-1400
DATTILO, T M Save the Valley - Save Marble Hill 79/04/12 3pp.

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition
DUFFLO, M E. Atomic Safety and Licensing Appeal Panel 79/04/25 13pp

H General correspondence

7905240725 Discusses ability of Commissioners to reach objective decisions re nuclear power, in light of svc in promotional capacity w/NRC Suggests addl govt funding for researching civilian energy needs
WATSON, S. Kentucky, State of 79/04/20 2pp.

Q. Inspection reports, IE Bulletins & correspondence

7905090386 Forwards IE Insp Repts 50-546/79-02 & 50-547/79-02 on 790227-0301 & notice of violation.
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/14 2pp

--7905090390 Notice of violation from insp on 790227-0301.
* Region 3, Chicago, Office of the Director. 79/03/13 1p.

--7905090393 IE Insp Noncompliance n instruction for
SCHWEIBINZ, E.R. Office of th

79050102
Safety
KEPPLER
1p.

79050400
KEPPLER
1p.

79050300
Sys M
KEPPLER
1p

79050101
Sys M
KEPPLER
1p.

DOCKETED ITEMS

7905040425 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bus Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14
1p

7905040589 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14
1p

7905070167 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14
1p

7905010411 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/16
1p

7905030241 Forwards IE Bulletin 79-09, "Failure of GE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/17
1p

7905080507 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/21
1p

7905140091 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/79-02 & 50-547/79-02
FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/25 1p

--7905140097 Responds to NRC 790314 ltr re violations noted in IE Insp Repts 50-546/79-02 & 50-547/79-02 Corrective actions space heaters energized & shafts rotated.
COUGHLIN, J Public Service Co of Indiana, Inc 79/04/10 2pp

7905230433 Responds to IE Bulletin 79-03 re piping mfg by Youngstown Welding & Engineering Co Piping not in use at facility
COUGHLIN, J Public Service Co of Indiana, Inc 79/03/03 1p.

B Reportable occurrences, LERs & related correspondence

7905230529 Forwards K Scheid 791121 ltr & ME Jamison 790315 ltr re cubicle cooler defects & repairs
HARRIS, R Trans Co 79/04/03 1p.

7905160400 Potential RO on 790409 two const cranes collided & fell, striking containment liner Vertical angle stiffener, horizontal reinforcing bars & circular CB ring stiffener were damaged Evaluation rept to follow
COUGHLIN, J Public Service Co. of Indiana, Inc 79/05/09. 1p.

7905310420 Provides interim rept of RO on 790416 possible damage to two post-tensioning trumplates & surrounding concrete Caused by overheating from propane fired torches used to repair tendon duct Repair procedures studied
COUGHLIN, J Public Service Co of Indiana, Inc. 79/05/16 1p.

DOCKET BTN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905090292 Responds to comments re application for const of pumphouse intake & discharge structure. W/781016 ltr from Attorney General of KY to Corps of Engineers, Louisville re dredge & fill application of Public Svc Co of IN.
WHITLOCK, W N Army, Dept. of, Corps of Engineers. 78/11/06 7pp.

--7905090296 Notifies of licensee's mitigation plan to recover archeological resources disturbed by const of intake & discharge structures. W/IN Dept of Natural Resources ltr discussing plan.
BALLARD, R L Environmental Projects Branch 2. 78/09/22. 2pp

7905020445 Forwards NUREG-0531, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability. W/a encl.
VASSALLO, D B Assistant Director for Light Water Reactors 79/03/23. 3pp.

7905020521 Responds to 790403 ltr re cubicle coolers w/improperly installed gaskets. Matter will be reviewed in future insp.
FIORELLI, O. Region 3, Chicago, Office of the Director. 79/04/17 1p.

7905100171 Notification of 790503 meeting w/util in Bethesda, MD to discuss Caseload Forecast Panel's estimate for fuel load data & submittal date for FSAR
VARDA, S A Light Water Reactors Branch 4 79/04/23 4pp

7905150296 Notification that lack of expected prehistoric resources justifies termination of mitigation effort
BALLARD, R L Environmental Projects Branch 1 79/04/30 2pp.

7905080415 Discusses NRC intention to delay FSAR review until end of year Delay is unacceptable, as based on average const schedule Util is better than average & unit is committed for 1982 operation FSAR will be filed in June 1979
COUGHLIN, J Public Service Co of Indiana, Inc 79/05/04 4pp

Q Adjudicatory correspondence

7905150220 Motion to reopen safety hearings to discuss WASH-1400 & herbicide "2,4,5-T"
DATILO, T M Dattilo, T M 79/03/22 2pp

7905020448 Forwards NRC memo discussing problems experienced w/piping support base plate design Piping design analysis on case-by-case basis being reviewed under SRP Section 3 9 2.
BRENNER, L Branch 3 79/04/05 2pp

7905020456 Forwards 780929 memo from Director of Ofc of Nuclear Reactor Regulation to Commissioners, discussing fire protection research test results conducted by UL
BRENNER, L Branch 3. 79/04/05 2pp

7905160208 Forwards latest motion to reopen safety hearings by T Dattilo on behalf of Save the Valley - Save Marble Hill
Forwards revisions to draft motions attached to 790402 memo
MURRAY, J P Rulemaking & Enforcement Division 79/04/05 2pp

--7905160212 Motion to suspend & revoke CP for proposed facility because of TMI incident
DATILO, T M Metford & Dattilo 79/04/04 2pp

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl.
BCINTO, J F Hearings Division 79/04/11. 45pp

7905140519 Response to 790404 brief of Philadelphia Electric Co, PSE&O & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Svc encl
KEPFORD, C R Citizens for Safe Environment. 79/04/11 8pp

7905240791 Ack receipt of 790404 petition to institute const suspension proceedings Decision under consideration. Forwards 790412 FR notice.
DENTON, H R Office of Nuclear Reactor Regulation 79/04/12. 1p

--7905240813 FR notice of request to reopen safety hearing
BOYD, R B Office of Nuclear Reactor Regulation. 79/04/12 2pp

--7905240850 Forwards motion of intervenor to reopen safety hearing. petition to revoke CP & FR notice
DENTON, D R Office of Nuclear Reactor Regulation. 79/04/12 5pp

--7905240872 Motion for ABLAB to reopen safety hearings
DATILO, T M Save the Valley - Save Marble Hill. 79/04/12 2pp

--7905240964 Motion to reopen safety hearings due to EPA ban on herbicide & invalidity of WASH-1400
DATILO, T M Save the Valley - Save Marble Hill 79/04/12 3pp

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition
DUFLO, M. E. Atomic Safety and Licensing Appeal Panel 79/04/25 13pp.

H. General correspondence

7905240725 Discusses ability of Commissioners to reach objective decisions re nuclear power, in light of svc in promotional capacity w/NRC Suggests add govt funding for researching civilian energy needs.
WATSON, S. Kentucky, State of. 79/04/20. 2pp.

DOCKETED ITEMS

281

G Inspection reports, IE Bulletins & correspondence

7905090386 Forwards IE Insp Repts 50-546/79-02 & 50-547/79-02 on 790227-0301 & notice of violation
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/14. 2pp

--7905090390 Notice of violation from insp on 790227-0301.
* Region 3, Chicago, Office of the Director 79/03/13 1p

--7905090393 IE Insp Repts 50-546/79-02 & 50-547/79-02 on 790227-0301
Noncompliance noted failure to have special storage instruction for safety-related pump & motor
SCHWEIBINZ, E R, MAXWELL, O F, KNOP, R C Region 3, Chicago, Office of the Director 79/03/13 10pp

7905010265 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/23 1p

7905040051 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/26 1p

7905030049 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/11 1p.

7905010602 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040425 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905040589 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/14 1p

7905070167 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14 1p

7905010411 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/16. 1p

7905030241 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Bys" Licensee action required.
KEPPLER, J O. Region 3, Chicago, Office of the Director 79/04/17. 1p

7905080307 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."
KEPPLER, J O Region 3, Chicago, Office of the Director. 79/04/21 1p

7905140091 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/79-02 & 50-547/79-02.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/25 1p.

--7905140097 Responds to NRC 790314 ltr re violations noted in IE Insp Repts 50-546/79-02 & 50-547/79-02, Corrective actions: space heaters energized & shafts rotated.
COUGHLIN, J Public Service Co of Indiana, Inc. 79/04/10. 2pp

7905250433 Responds to IE Bulletin 79-03 re piping mfg by Youngstown Welding & Engineering Co, Piping not in use at Facility.
COUGHLIN, J. Public Service Co. of Indiana, Inc. 79/05/03. 1p.

B Reportable occurrences, LERs & related correspondence

7905230529 Forwards K Scheid 791121 ltr & ME Jamison 790315 ltr re cubicle cooler defects & repairs.
HARRIS, R. Trans Co. 79/04/03. 1p.

7905160400 Potential RO on 790409 two const cranes collided & fell, striking containment liner Vertical angle stiffener, horizontal reinforcing bars & circular CR ring stiffener were damaged Evaluation rept to follow
COUGHLIN, J Public Service Co of Indiana, Inc 79/05/09 1p

7905310420 Provides interim rept of RO on 790416 possible damage to two post-tensioning trumplates & surrounding concrete Caused by overheating from propane fired torches used to repair tendon duct Repair procedures studied
COUGHLIN, J Public Service Co of Indiana, Inc 79/05/16 1p

DOCKET 50-548 FORT CALHOUN STATION, UNIT 2

G Adjudicatory correspondence

7905240989 Forwards info on iodine behavior during postulated generator tube rupture accidents & ECCS performance characteristics
GRAY, J R. Branch 1 79/04/10 5pp

--7905241001 Discusses accumulator delivery comparisons for LOFT tests L1-3a & L1-4, & effect on ECCS performance
ROSS, D F Assistant Director for Reactor Safety 78/02/03 2pp

7905100110 Forwards notifications re UL fire protection test; Lewis Committee Rept, "Transportation of Radionuclides in Urban Environ" & neutron dosimetry
GRAY, J R Branch 1 79/04/12 4pp.

7905240801 Submits semiannual rept on behalf of util. Lawsuit brought by NE Public Power District against util has been settled Requests further licensing procedures be held in abeyance due to parallel suit
VOIGT, H H. LeBoeuf, Lamb, Leiby & MacRae 79/04/30 1p

DOCKET 50-549 GREENE COUNTY NUCLEAR POWER PLANT

A. Application/construction stage documents & correspondence

7905030350 Comments on "Federal-State Authorities & Cooperation in Nuclear Power Plant Licensing" outlines changes to NY siting law & attempts to eliminate duplication of regulatory processes between federal & state agencies
SMOLINSKY, J New York, State of. 79/04/24 2pp

G Adjudicatory correspondence

7905030239 Forwards interrogatories by NY Dept of Environ Conservation to NY Dept of Public Bvc
ENGEL, D A New York, State of 79/03/09. 1p

--7905030247 Interrogatories of NY Dept of Environ Conservation to NY Dept of Public Bvc.
BISHOP, M O, SMOLINSKY, J H New York, State of. 79/03/09 3pp

7905160163 Forwards Board Notification 79-10 on reactor inspector concerns re B&W plants, Certificate of Bvc encl
SCINTO, J F. Hearings Division. 79/03/29. 14pp

7905230841 NRC motion for mod of 790323 Joint Board ruling extending scheduled dates in proceeding. Moves for stay of filing dates pending util's rept to be filed on 790320, Certificate of Bvc encl
LEWIS, S. H. 79/03/29 8pp

7905010115
equipmen
SCINTO, J

--79050101
equip
VASSAL
79/03/

--79050101
equip
TEDES
3pp

790507013
potenti
fuel, W/
LEWIS, S

DOCKETED ITEMS

7905040423 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14
1p

7905040589 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14
1p

7905070167 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/14
1p

7905010411 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/16
1p

7905030241 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Bys" Licensee action required
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/17
1p

7905080507 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl 1"
KEPPLER, J O Region 3, Chicago, Office of the Director 79/04/21
1p

7905140091 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-546/79-02 & 90-547/79-02
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/25 1p

--7905140097 Responds to NRC 790314 ltr re violations noted in IE Insp Repts 90-546/79-02 & 90-547/79-02 Corrective actions space heaters energized & shafts rotated
COUGHLIN, J Public Service Co of Indiana, Inc. 79/04/10 2pp

7905250433 Responds to IE Bulletin 79-03 re piping mfg by Youngstown Welding & Engineering Co Piping not in use at facility
COUGHLIN, J Public Service Co of Indiana, Inc 79/05/03 1p.

8 Reportable occurrences, LERs & related correspondence

7905230529 Forwards K Scheid 791121 ltr & ME Jamison 790315 ltr re cubicle cooler defects & repairs
HARRIS, R Trans Co 79/04/03, 1p

7905160400 Potential RO on 790409, two const cranes collided & fell, striking containment liner Vertical angle stiffener, horizontal reinforcing bars & circular CB ring stiffener were damaged Evaluation rept to follow
COUGHLIN, J Public Service Co. of Indiana, Inc 79/05/09, 1p

7905310420 Provides interim rept of RO on 790416 possible damage to two post-tensioning trumplates & surrounding concrete Caused by overheating from propane fired torches used to repair tendon duct Repair procedures studied
COUGHLIN, J Public Service Co of Indiana, Inc 79/05/16, 1p

DOCKET SYN-30-547 MARBLE HILL NUCLEAR STATION, UNIT 2

on/construction stage documents & correspondence

is re application for const of pumphouse
W/781016 ltr from Attorney
gineers, Louisville re dredge &
vc Co of IN.
Cores of Engineers. 78/11/06 7pp.

plan to recover
of intake &
Resources ltr
Branch 2 78/09/22 2pp

on & Evaluation of Stress
& notice of
ght Water Reactors.

coolers w/improperly
in future insp.
f the Director 79/04/17

7905100171 Notification of 790503 meeting w/util in Bethesda, MD to discuss Caseload Forecast Panel's estimate for fuel load data & submittal date for FSAR
VAROA, B A Light Water Reactors Branch 4 79/04/23 4pp

7905150294 Notification that lack of expected prehistoric resources justifies termination of mitigation effort
BALLARD, R L Environmental Projects Branch 1 79/04/30 2pp

7905080415 Discusses NRC intention to delay FSAR review until end of year Delay is unacceptable, as based on average const schedule Util is better than average & unit is committed for 1982 operation FSAR will be filed in June 1979
COUGHLIN, J Public Service Co of Indiana, Inc 79/03/04, 4pp

O Adjudicatory correspondence

7905150220 Motion to reopen safety hearings to discuss WASH-1400 & herbicide "2,4,5-T"
DATTILO, T M Dattilo, T M 79/03/22 2pp

790502044B Forwards NRC memo discussing problems experienced w/pipeline support base plate design Piping design analysis on case-by-case basis being reviewed under SRP Section 3.9.2
BRENNER, L Branch 3 79/04/05 2pp.

7905020456 Forwards 780929 memo from Director of Ofc of Nuclear Reactor Regulation to Commissioners, discussing fire protection research test results conducted by UL
BRENNER, L Branch 3 79/04/05 2pp

7905160208 Forwards latest motion to reopen safety hearings by T Dattilo on behalf of Save the Valley - Save Marble Hill
Forwards revisions to draft motions attached to 790402 memo
MURRAY, J P Rulemaking & Enforcement Division 79/04/05 2pp

--7905160212 Motion to suspend & revoke CP for proposed facility because of TMI incident
DATTILO, T M Matford & Dattilo 79/04/04 2pp

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record, Certificate of Svc encl
SCINTO, J F Hearings Division 79/04/11 45pp

7905140519 Response to 790404 brief of Philadelphia Electric Co, PSE&G & Atlantic City (NJ) Electric Co re de minimus theory, Certificate of Svc encl
KEPFORD, C R Citizens for Safe Environment 79/04/11 8pp

7905240791 Ack receipt of 790404 petition to institute const suspension proceedings Decision under consideration Forwards 790412 FR notice.
DENTON, H R Office of Nuclear Reactor Regulation 79/04/12 1p

--7905240813 FR notice of request to reopen safety hearing.
BOYD, R B. Office of Nuclear Reactor Regulation. 79/04/12 2pp

--7905240850 Forwards motion of intervenor to reopen safety hearing, petition to revoke CP & FR notice.
DENTON, D.R Office of Nuclear Reactor Regulation 79/04/12 3pp

--7905240872 Motion for ABLAB to reopen safety hearings
DATTILO, T M. Save the Valley - Save Marble Hill 79/04/12 2pp

--7905240964 Motion to reopen safety hearings due to EPA ban on herbicide & invalidity of WASH-1400
DATTILO, T.M Save the Valley - Save Marble Hill 79/04/12 3pp

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue Parties have until 790525, in which to file for summary disposition
DUPLD, M.E. Atomic Safety and Licensing Appeal Panel 79/04/23 13pp.

H. General correspondence

7905240725 Discusses ability of Commissioners to reach objective decisions re nuclear power, in light of svc in promotional capacity w/NRC. Suggests addl govt funding for researching civilian energy needs
WATSON, S Kentucky, State of. 79/04/20, 2pp.

DOCKETED ITEMS

261

Q Inspection reports, IE Bulletins & correspondence

7905090386 Forwards IE Insp Repts 50-546/79-02 & 50-547/79-02 on 790227-0301 & notice of violation
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/14 2pp

--7905090390 Notice of violation from insp on 790227-0301
* Region 3, Chicago, Office of the Director 79/03/13 1p

--7905090393 IE Insp Repts 50-546/79-02 & 50-547/79-02 on 790227-0301
Noncompliance noted failure to have special storage instruction for safety-related pump & motor
SCHWEIBINZ, E R, MAXWELL, O F, KNOP, R C Region 3, Chicago, Office of the Director 79/03/13 10pp

7905010263 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/03/23 1p

7905040051 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/03/26 1p

7905030049 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/11 1p

7905010602 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/14 1p

7905040425 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/14 1p

7905040589 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/14 1p

7905070167 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/14 1p

7905010411 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/16 1p

7905030241 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/17 1p

7905080507 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Buppl"
KEPPLER, J Q Region 3, Chicago, Office of the Director 79/04/21 1p

7905140091 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/79-02 & 50-547/79-02
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/25 1p

--7905140097 Responds to NRC 790314 ltr re violations noted in IE Insp Repts 50-546/79-02 & 50-547/79-02, corrective actions, space heaters energized & shafts rotated
COUGHLIN, J Public Service Co. of Indiana, Inc. 79/04/10 2pp.

7905290433 Responds to IE Bulletin 79-03 re piping mfg by Youngstown Welding & Engineering Co. Piping not in use at facility
COUGHLIN, J Public Service Co. of Indiana, Inc. 79/03/03 1p.

S Reportable occurrences, LERs & related correspondence

7905230329 Forwards K Scheid 791121 ltr & ME Jamison 790315 ltr re cubicle cooler defects & repairs.
HARRIS, R Trane Co 79/04/03 1p.

7905160400 Potential RO on 790409 two const cranes collided & fell, striking containment liner Vertical angle stiffener, horizontal reinforcing bars & circular CB ring stiffener were damaged Evaluation rept to follow
COUGHLIN, J Public Service Co. of Indiana, Inc 79/03/09 1p.

7905310420 Provides interim rept of RO on 790416 possible damage to two post-tensioning trumplates & surrounding concrete Caused by overheating from propane fired torches used to repair tendon duct Repair procedures studied
COUGHLIN, J Public Service Co. of Indiana, Inc 79/03/16 1p

DOCKET 50-548 FORT CALHOUN STATION, UNIT 2

Q Adjudicatory correspondence

7905240989 Forwards info on iodine behavior during postulated generator tube rupture accidents & ECCS performance characteristics
GRAY, J R Branch 1 79/04/10 3pp

--7905241001 Discusses accumulator delivery comparisons for LOFT tests L1-3a & L1-4, & effect on ECCS performance
ROSS, D F Assistant Director for Reactor Safety 78/02/03 2pp

7905100110 Forwards notifications re UL fire protection test, Lewis Committee Rept, "Transportation of Radionuclides in Urban Environ" & neutron dosimetry
GRAY, J R Branch 1 79/04/12 4pp

7905240801 Submits semiannual rept on behalf of util Lawsuit brought by NE Public Power District against util has been settled Requests further licensing procedures be held in abeyance due to parallel suit
VOIOT, H H LeBoeuf, Lamb, Leiby & MacRae 79/04/30 1p

DOCKET 50-549 GREENE COUNTY NUCLEAR POWER PLANT

A Application/construction stage documents & correspondence

7905030350 Comments on "Federal-State Authorities & Cooperation in Nuclear Power Plant Licensing", outlines changes to NY siting law & attempts to eliminate duplication of regulatory processes between federal & state agencies
SMOLINSKY, J New York, State of 79/04/24 2pp.

Q Adjudicatory correspondence

7905030239 Forwards interrogatories by NY Dept of Environ Conservation to NY Dept of Public Svc
ENGEL, D A New York, State of 79/03/09 1p

--7905030247 Interrogatories of NY Dept of Environ Conservation to NY Dept of Public Svc.
BISHOP, M O, SMOLINSKY, J H New York, State of 79/03/09 3pp

7905160163 Forwards Board Notification 79-10 on reactor inspector concerns re B&W plants Certificate of Svc encl.
SCINTO, J F Hearings Division 79/03/29 14pp

7905230841 NRC motion for mod of 790323 Joint Board ruling extending scheduled dates in proceeding. Moves for stay of filing dates pending util's rept to be filed on 790320. Certificate of Svc encl.
LEWIS, S H Branch 2 79/03/29 9pp

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients.
SCINTO, J F Hearings Division 79/04/02 31pp.

--7905010136 Board notification: staff assessment re nonsafety-grade equipment to mitigate transients.
VASSALLO, D B Assistant Director for Light Water Reactors 79/03/29 2pp.

--7905010198 Board notification: recent issue on nonsafety-grade equipment to mitigate transients. More info is required.
TEDEBECQ, R L Assistant Director for Reactor Safety 79/03/16 3pp.

7905070134 Forwards transmittal memo for document which contains info potentially relevant to issue of sabotage of spent nuclear fuel. W/o encl.
LEWIS, S H Branch 2 79/04/02 2pp

DOCKETED ITEMS

--7903070141 Forwards draft rept on sabotage attacks on spent fuel transportation sys Rept is first one available re high level explosive attack on spent fuel shipping casts w/o encl CARTER, T F Division of Safeguards 79/01/22 2pp.

7903160112 Board notification nuclear incident at TMI Recommends boards on cases involving B&W reactors be provided w/IE Bulletin 79-05 & PNO-67 & 67A,B,C,D,E,F,G & H VASSALLO, D B Assistant Director for Light Water Reactors 79/04/03 2pp

7903250080 Suspends further hearings re util's application for certificate for authority to construct & operate plant Grants 790329 interlocutory appeal of State of NY Dept of Public Svc Certificate of Svc encl MADISON, S R New York, State of 79/04/05 1pp

7903100150 Forwards requested summary of 790410 telcon w/util re permission to construct nuclear facility MOORE, J E Branch 2 79/04/12 2pp

7903240983 Motion by Greene County & towns of Athens & Catkill in support of NRC & NY Dept of Public Svc 790403 motion to dismiss application & terminate proceeding & in opposition to applicant's 790416 alternative request BUTZEL, A K Butzel & Kass 79/04/22 2pp

7903300367 Forwards draft "Historical & Cultural Context of Proposed Greene County Nuclear Power Plant." Requests certain matl not be reproduced due to copyrights LEWIS, S H Branch 2 79/04/23 1p

J Insurance & indemnity information

7903070497 Confirms increased liability limit to \$124,000,000 for policies MF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others QUATTROCHI, J American Nuclear Insurers. 79/05/01 1p

7903070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96. ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

B Reportable occurrences, LERs & related correspondence

7903110203 Board notification Seabrook refueling water storage tank design deficiency SCINTO, J Hearings Division 79/03/29 30pp

DOCKET SYN-50-550 GESSAR-238-80P INTERFACE

J. Insurance & indemnity information

7903070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96. ROBERTS, D M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

DOCKET SYN-50-553 PHIPPS BEND NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

7903100093 Discusses 790329 site visit re addl fault found in core cooling water trench Util to provide description of trench fault; discussion of fault's relationship to regional geology & fault area mapping HELLER, L W Geosciences Branch 79/04/17 2pp

7903040345 Forwards description of addl fault discovered beneath component cooling water pumping station. Fault not considered to be capable One oversized drawing encl GILLELAND, J E Tennessee Valley Authority. 79/04/30 2pp.

7903080541 Discusses util position on leak testing, pressure & temp requirements of ACI Stds 318 & 349 for piping to be embedded in concrete Revisions to PBAR re embedded piping will be implemented immediately. GILLELAND, J E Tennessee Valley Authority. 79/05/03 3pp.

7903140270 Describes adjusted route for transporting reactor pressure vessels. Util finds environ impact to be within scope of original analysis GILLELAND, J E Tennessee Valley Authority. 79/05/07 1p.

F Security, medical, emergency & fire protection plans

7903300462 Forwards addl response to 780926 meeting minutes re STRIDE fire hazards analysis Includes proposed design changes to fire protection sys Requests early meeting to discuss responses GILLELAND, J E Tennessee Valley Authority 79/05/20 9pp

O Adjudicatory correspondence

7903240874 Requests adoption of de minimus theory of Perkins ABLB Certificate of Svc encl SANGER, H B Tennessee Valley Authority 79/04/06 11pp

7903110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl SCINTO, J F Hearings Division 79/04/11 43pp

7903140519 Response to 790404 brief of Philadelphia Electric Co, PSE&G Atlantic City (NJ) Electric Co re de minimus theory Certificate of Svc encl KEPPORD, C R Citizens for Safe Environment. 79/04/11 8pp

7903140332 Notices of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition DUFFO, M E Atomic Safety and Licensing Appeal Panel. 79/04/25 13pp

G Inspection reports, IE Bulletins & correspondence

7903010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7903030368 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 3pp

7903040233 Forwards IE Bulletin 79-08B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/14 3pp

7903110365 Forwards IE Bulletin 79-08, "Events Relevant to Rolling Water Power Reactors Identified During TMI Incident." O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7903010341 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts." O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 1p

7903030172 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required. O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp

7903020479 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " O'REILLY, J P Region 2, Atlanta, Office of the Director. 79/04/18 2pp

7903030253 Submits supplemental response to IE Bulletin 79-07. Original response submitted 780120. Provides addl info received from manufacturer & describes plans in area of electrical penetrations. GILLELAND, J E Tennessee Valley Authority 79/04/27 5pp.

S. Reportable occurrences, LERs & related correspondence

7903140478 Forwards final rept of reportable condition re BHR/6 HPCB local control panels. (NRC OE-79-01) GILLELAND, J E Tennessee Valley Authority. 79/04/05 1p.

--7903140482 Reportable condition on 790304. OE determined that defect existed in HPCB panel H22-P02B. Caused by installation of nonqualified type relay Procedures revised & QA program modified * Tennessee Valley Authority 79/04/05 2pp.

DOCKETED ITEMS

263

DOCKET STN-50-554 PHIPPS BEND NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7905100093 Discusses 790329 site visit re addl fault found in core cooling water trench Util to provide description of trench fault; discussion of fault's relationship to regional geology & fault area mapping
HELLER, L. H. Geosciences Branch 79/04/17 2pp

7905040345 Forwards description of addl fault discovered beneath component cooling water pumping station Fault not considered to be capable One oversized drawing encl
GILLELAND, J. E. Tennessee Valley Authority 79/04/30. 2pp

7905080541 Discusses util position on leak testing, pressure & temp requirements of ACI Stds 31B & 349 for piping to be embedded in concrete. Revision to PSAR re embedded piping will be implemented immediately
GILLELAND, J. E. Tennessee Valley Authority 79/05/03 3pp

7905140270 Describes adjusted route for transporting reactor pressure vessels. Util finds environ impact to be within scope of original analysis
GILLELAND, J. E. Tennessee Valley Authority 79/05/07 1p

F. Security, medical, emergency & fire protection plans

7905300462 Forwards addl response to 780926 meeting minutes re STRIDE fire hazards analysis Includes proposed design changes to fire protection sys Requests early meeting to discuss responses
GILLELAND, J. E. Tennessee Valley Authority 79/05/20 9pp

D. Adjudicatory correspondence

790511041B Response to ALAB-509 re radon emissions & de minimus theory from Perkins record Certificate of Svc encl
SCINTO, J. F. Hearings Division 79/04/11 45pp.

7905140519 Response to 790404 brief of Philadelphia Electric Co. PSE&O & Atlantic City (NJ) Electric Co re de minimus theory Certificate of Svc encl
KEPFORD, C. R. Citizens for Safe Environment. 79/04/11 8pp.

7905140332 Notices of consolidation of five intervenor groups re radon emissions issue Parties have until 790525 in which to file for summary disposition.
DUFFLO, H. E. Atomic Safety and Licensing Appeal Panel 79/04/25 12pp.

G. Inspection reports, IE Bulletins & correspondence

7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/23 2pp.

7905030368 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14 3pp

7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14. 3pp

7905110365 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.

7905010341 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/18. 1p

7905030172 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/17. 2pp

7905020479 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/18 2pp.

7905300253 Submits supplemental response to IE Bulletin 77-07. Original response submitted 780120. Provides addl info received from manufacturer & describes plans in area of electrical penetrations.
GILLELAND, J. E. Tennessee Valley Authority 79/04/27 5pp

B. Reportable occurrences, LERs & related correspondence

790514047B Forwards final rept of reportable condition re BWR/6 HPCS local control panels (NRC GE-79-01)
GILLELAND, J. E. Tennessee Valley Authority 79/04/05. 1p

--7905140482 Reportable condition on 790303 GE determined that defect existed in HPCS panel H22-P028 Caused by installation of nonqualified type relay Procedures revised & QA program modified
* Tennessee Valley Authority 79/04/05 2pp

DOCKET STN-50-556 BLACK FOX STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905020452 Forwards NUREG-0531, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability H/o encl
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/03/23 2pp

7905150641 Notification of 790303-04 geologic site visit w/util in Indla. OK to observe site excavation & geologic mapping activities
THOMAS, C. D. Light Water Reactors Branch 1 79/04/06 4pp.

E. NRC Safety Evaluation Report (SER), suppl & correspondence

7905070665 Forwards Suppl 2 to SER
VARDA, S. A. Light Water Reactors Branch 4 79/04/05 3pp.

G. Adjudicatory correspondence

7905160304 Response by util in opposition to intervenors' 790301 motion to suppl record w/"Tulsa Metropolitan Area, Tulsa Urban Study, Draft, Summary Rept, Stage 2 Study" prepared by Tulsa Army Corps of Engineers W/Certificate of Svc
MURPHY, P. M., BIELAWSKI, A. P. Isham, Lincoln & Beale 79/03/14. 6pp

7905090185 Applicant's response to intervenors' 790307 motion to file supplemental brief & to intervenors' supplemental brief itself Brief concerns failure to consider Class 9 accidents in environ review Certificate of Svc encl
MURPHY, P. M., BIELAWSKI, A. P. Isham, Lincoln & Beale 79/03/16. 7pp.

7905070021 NRC response in opposition to intervenors' 790301 motion to suppl record w/"Tulsa Metropolitan Area Urban Study, Draft, Summary Rept, Stage 2 Study" prepared by Tulsa Army Corps of Engineers Certificate of Svc encl
DAVIS, L. D. Branch 4 79/03/19. 8pp

7905090182 NRC response to intervenors' 790304 motion to file supplemental brief re letter's Exceptions 112 & 113 Certificate of Svc encl.
DAVIS, D. L. Branch 4. 79/03/23 6pp

7905010113 Forwards request equipment to mitigate tr/
SCINTO, J. F. Hear

--7905010
equip
VASSA
79/03

--7905010
equip
TEDES
3pp

790529027
facts &
FARRIS,

790524027
law on
THOMAS,

79051500'
DAVIS, I

DOCKETED ITEMS

7905220062 Forwards errata sheet correcting errors in findings of fact & conclusions of law submitted 790326 & 28
GALLLO, J. Isham, Lincoln & Beale 79/04/09 2pp

7905230259 Discusses regulations re interconnection of sys of both reactors, in event of accident at one reactor affecting safe operation at other reactor.
DAVIS, L. D. Branch 4 79/04/11 2pp

7905140547 Notice of filing of intervenors Citizens for Safe Energy, L. Burrell & I. Younghein proposed findings of fact, conclusions of law & proposed order in form of partial initial decision Certificate of Bvc encl
FARRIS, J. R. Green, Feldman, Hall & Woodard 79/04/12 4pp

--7905140550 Intervenor Citizens Action for Safe Energy, L. Burrell & I. Younghein proposed findings of fact, conclusions of law & proposed order in form of partial initial decision re radiological health & safety matters
FARRIS, J. R., WOODARD, J. R. Green, Feldman, Hall & Woodard 79/04/12 77pp

7905100226 Proposed findings of fact & conclusions of law, in form of initial decision re radiological health & safety matters w/supporting documentation
DAVIS, D. L., PATON, W. D. Branch 4 WOODHEAD, C. P. Branch 3 79/04/13 161pp

7905220064 Requests Reed rept & subtask repts be returned to GE Repts will be made available for NRC review, if needed Certificate of Bvc encl
EDGAR, O. L. Morgan, Lewis & Bockius 79/04/13 4pp

7905100215 Requests extension until 790426 to file ECCB portion of proposed findings of fact & conclusions of law Certificate of Bvc encl
DAVIS, L. D. Branch 4 79/04/16 3pp

--7905100219 Proposed findings of fact & conclusions of law in form of initial decision re radiological health & safety matters. W/o ECCB section Certificate of Bvc encl
DAVIS, L. D. Branch 4 79/04/16 2pp.

7905240879 Requests Reed Rept be maintained in confidence pending ASLB ruling on whether Rept should be returned to GE
EDGAR, O. L. Morgan, Lewis & Bockius 79/04/18 2pp

7905130063 Moves for indefinite stay of proceeding concerning issuance of initial decision, pending investigation of TMI-2 & hearings re facility financing Certificate of Bvc encl.
THOMAS, C. O., ROGERB, C. S., CARTWRIGHT, J. E. Oklahoma, State of 79/04/19 11pp

7905130491 Ack receipt of 790418 ltr Request basis is hypothetical; no NRC personnel have requested ASLB for access to Reed Rept NRC technical & legal staff will not have access to report until 790430
WOLFE, B. J. Atomic Safety and Licensing Board Panel 79/04/19. 1p

7905230759 Advises that motion has been filed to stay issuance of initial decision.
ROGERB, C. Oklahoma, State of 79/04/19 1p

7905230179 Errata sheet & table of contents to applicants 790426 reply to proposed findings of fact & conclusions of law filed by NRC & intervenors
Isham, Lincoln & Beale 79/04/26. 2pp.

7905240924 Responses by intervenors Citizens Action for Safe Power, L. Burrell & I. Younghein supporting adoption of motion by State of OK for indefinite stay in issuance of initial decision Certificate of Bvc encl.
FARRIS, J. R. Green, Feldman, Hall & Woodard 79/04/27. 10pp.

7905230174 Forwards info re schedule & cost analysis, Commercial operation for Unit 1 shall begin on 880701 & for Unit 2 on 880901 Applicants filed reply to NRC & intervenors' proposed findings of fact & conclusions of law on 790426
GALLLO, J. Isham, Lincoln & Beale. 79/04/30 12pp.

7905230560 Grants extension until 790509 to file proposed findings of fact re ECCB, per NRC 790426 request
WOLFE, B. J. Atomic Safety and Licensing Board Panel 79/05/01. 1p

7905230570 Grants extension until 790511 for util & NRC to file answers to motion by State of OK for indefinite stay of issuance of initial decision.
WOLFE, B. J. Atomic Safety and Licensing Board Panel. 79/05/01. 1p

H General correspondence

7905130279 Requests info re June 1979 hearing in Phoenix, AZ Group wants to send delegation to hearing
* Nuclear Free State 79/03/28 1p.

7905100353 Believes GE should publish Reed Rept re Unresolvable safety issues Opposes nuclear plant const Supports solar & wind power research
BELCHER, T. Affiliation Unknown 79/04/16 1p

7905100397 Urges NRC to release all portions of transcripts of safety hearings, including portions dealing w/Reed Rept
GARNETT, H., GARNETT, G. Affiliation Unknown 79/04/17 1p

I Financial information

7905230029 Requests addl financial info on updated cost estimates, in order to complete review of revised financial info.
EWING, T. N. Public Service Co of Oklahoma 79/05/07 3pp

7905090357 "Annual Financial Rept 1978 "
* Central & Southwest Services, Inc. 79/05/09 40pp

7905090359 "Annual Financial Rept 1978 "
* Public Service Co of Oklahoma 79/05/09 39pp

7905230424 Submits addl financial info in response to NRC 790507 request Previous info was solely to advise of cost & schedule study & not in response to motions to intervene
Bvc list encl
EWING, T. N. Public Service Co of Oklahoma 79/05/14. 2pp

7905240393 Responds to NRC 790501 request for addl info Util 790430 ltr included all available financial info
EWING, T. N. Public Service Co of Oklahoma 79/05/14 2pp

Q Inspection reports, IE Bulletins & correspondence

7905130564 Forwards IE Insp Repts 50-556/79-02 & 50-557/79-02 on 790306-09, No noncompliance noted
BEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/23 2pp

--7905130370 IE Insp Repts 50-556/79-02 & 50-557/79-02 on 790306-09 No noncompliance noted Major areas inspected, const status, development of concrete mix design, training & indoctrination & QA
HUBACEK, W. Q., CROSSMAN, W. A., HALL, R. E. Region 4, Dallas, Office of the Director 79/03/23 7pp

DOCKET 97N-50-557 BLACK FOX STATION, UNIT 2

A Application/construction stage documents & correspondence

7905020452 Forwards NUREG-0531, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability W/o encl.
VASSALLO, D. B. Assistant Director for Light Water Reactors 79/03/23 2pp

7905130641 Notification of 790503-04 geologic site visit w/util in Indla, OK to observe site excavation & geologic mapping activities.
THOMAS, C. O. Light Water Reactors Branch 1 79/04/06. 4pp

E. NRC Safety Evaluation Report (SER), suppl & correspondence

7905070665 Forwards Suppl 2 to SER.
VARDA, S. A. Light Water Reactors Branch 4 79/04/05 3pp.

G. Adjudicatory correspondence

7905160304 Response by util in opposition to intervenors' 790301 motion to suppl record w/"Tulsa Metropolitan Area, Tulsa Urban Study, Draft, Summary Rept, Stage 2 Study" prepared by Tulsa Army Corps of Engineers, W/Certificate of Bvc.
MURPHY, P. M., BIELANSKI, A. P. Isham, Lincoln & Beale. 79/03/14. 6pp.

7905090185 Applicant's response to intervenors' 790307 motion to file supplemental brief & to intervenors' supplemental brief itself. Brief concerns failure to consider Class 9 accidents in environ review, Certificate of Bvc encl.
MURPHY, P. M., BIELANSKI, A. P. Isham, Lincoln & Beale. 79/03/16. 7pp.

DOCKETED ITEMS

285

7905070021 NRC response in opposition to intervenors 790301 motion to suppl record w/"Tulsa Metropolitan Area Urban Study, Draft, Summary Rept, Stage 2 Study" prepared by Tulsa Army Corps of Engineers Certificate of Svc encl
DAVIS, L. D. Branch 4 79/03/19 8pp

7905090182 NRC response to intervenors 790304 motion to file supplemental brief re latter's Exceptions 112 & 113 Certificate of Svc encl
DAVIS, D. L. Branch 4 79/03/23 6pp

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients
SCINTO, J. F. Hearings Division 79/04/02 31pp

--7905010136 Board notification staff assessment re nonsafety-grade equipment to mitigate transients
VABEALLO, D. B. Assistant Director for Light Water Reactors, 79/03/29 2pp

--7905010198 Board notification recent issue on nonsafety-grade equipment to mitigate transients More info is required
TEDESCO, R. L. Assistant Director for Reactor Safety 79/03/16 3pp.

7905290273 Requests extension until 790412 to file proposed findings of fact & conclusions of law Certificate of Svc encl
FARRIS, J. R. Citizens Action For Safe Energy 79/04/03 5pp

7905240275 Declines to file proposed findings of fact & conclusions of law on limited record Certificate of Svc encl
THOMAS, O., ROGERB, C. B. Oklahoma, State of 79/04/05. 5pp.

7905130059 Forwards NUREG-0190, Mar 1979, Suppl 2 to BER
DAVIS, L. D. Branch 4. 79/04/09 1p

7905220062 Forwards errata sheet correcting errors in findings of fact & conclusions of law submitted 790326 & 28
GALLQ, J. Isham, Lincoln & Beale 79/04/09 2pp

7905230259 Discusses regulations re interconnection of sys of both reactors, in event of accident at one reactor affecting safe operation at other reactor
DAVIS, L. D. Branch 4 79/04/11. 2pp

7905140547 Notice of filing of intervenors Citizens for Safe Energy, L Burrell & I Younghein proposed findings of fact, conclusions of law & proposed order in form of partial initial decision Certificate of Svc encl
FARRIS, J. R. Green, Feldman, Hall & Woodard 79/04/12 4pp

--7905140550 Intervenor Citizens Action for Safe Energy, L Burrell & I Younghein proposed findings of fact, conclusions of law & proposed order in form of partial initial decision re radiological health & safety matters
FARRIS, J. R., WOODARD, J. R. Green, Feldman, Hall & Woodard. 79/04/12 77pp

7905100226 Proposed findings of fact & conclusions of law, in form of initial decision re radiological health & safety matters w/supporting documentation
DAVIS, D. L., PATON, W. D. Branch 4. WOODHEAD, C. P. Branch 3. 79/04/13 161pp.

7905220064 Requests Read rept & subtask repts be returned to OE. Repts will be made available for NRC review, if needed Certificate of Svc encl.
EDGAR, O. L. Morgan, Lewis & Bockius 79/04/13. 4pp

7905100215 Requests extension until 790426 to file ECCB portion of proposed findings of fact & conclusions of law Certificate of Svc encl
DAVIS, L. D. Branch 4. 79/04/16 3pp

--7905100219 Proposed findings of fact & conclusions of law in form of initial decision re radiological health & safety matters w/o ECCB section Certificate of Svc encl
DAVIS, L. D. Branch 4. 79/04/16. 2pp.

7905240879 Requests Read Rept be maintained in confidence pending ASLB ruling on whether rept should be returned to OE.
EDGAR, O. L. Morgan, Lewis & Bockius. 79/04/18. 2pp

7905130063 Moves for indefinite stay of proceeding concerning issuance of initial decision, pending investigation of TMI-2 & hearings re facility financing Certificate of Svc encl.
THOMAS, O., ROGERB, C. B., CARTWRIGHT, J. E. Oklahoma, State of. 79/04/19. 11pp

7905130491 Ack receipt of 790418 ltr Request basis is hypothetical, no NRC personnel have requested ASLB for access to Read Rept NRC technical & legal staff will not have access to report until 790430
WOLFE, B. J. Atomic Safety and Licensing Board Panel 79/04/19 1p

7905230759 Advises that motion has been filed to stay issuance of initial decision
ROGERS, C. Oklahoma, State of. 79/04/19 1p

7905250179 Errata sheet & table of contents to applicants 790426 reply to proposed findings of fact & conclusions of law filed by NRC & intervenors
* Isham, Lincoln & Beale. 79/04/26 2pp

7905240924 Response by intervenors Citizens Action for Safe Power, L Burrell & I Younghein supporting adoption of motion by State of OK for indefinite stay in issuance of initial decision Certificate of Svc encl
FARRIS, J. R. Green, Feldman, Hall & Woodard 79/04/27 10pp

7905250174 Forwards info re schedule & cost analysis Commercial operation for Unit 1 shall begin on 880701 & for Unit 2 on 880501 Applicants filed reply to NRC & intervenors' proposed findings of fact & conclusions of law on 790426
GALLQ, J. Isham, Lincoln & Beale 79/04/30 12pp

7905230360 Grants extension until 790509 to file proposed findings of fact re ECCB, per NRC 790426 request.
WOLFE, B. J. Atomic Safety and Licensing Board Panel 79/03/01. 1p

7905230570 Grants extension until 790511 for util & NRC to file answers to motion by State of OK for indefinite stay of issuance of initial decision
WOLFE, B. J. Atomic Safety and Licensing Board Panel 79/03/01 1p

H General correspondence

7905150279 Requests info re June 1979 hearing in Phoenix, AZ Group wants to send delegation to hearing.
* Nuclear Free State 79/03/28. 1p

7905100353 Believes OE should publish Read Rept re unresolvable safety issues Opposes nuclear plant const Supports solar & wind power research
BELCHER, T. Affiliation Unknown. 79/04/16 1p.

7905130397 Urges NRC to release all portions of transcripts of safety hearings, including portions dealing w/Read Rept
GARNETT, H., GARNETT, O. Affiliation Unknown 79/04/17 1p

I. Financial information

7905250029 Requests addl financial info on updated cost estimates, in order to complete review of revised financial info
EWING, T. N. Public Service Co. of Oklahoma 79/03/07. 3pp

7905090357 "Annual Financial Rept 1978."
* Central & Southwest Services, Inc 79/05/09. 40pp

7905090359 "Annual Financial Rept 1978"
* Public Service Co. of Oklahoma 79/05/09. 39pp.

7905230424 Submits addl financial info in response to NRC 790307 request Previous info was solely to advise of cost & schedule study & not in response to motions to intervene. Svc list encl
EWING, T. N. Public Service Co. of Oklahoma. 79/05/14. 2pp.

7905240393 Responds to NRC 790301 request for addl info. Util 790430 ltr included all available financial info
EWING, T. N. Public Service Co. of Oklahoma 79/05/14. 2pp.

O Inspection reports; IE Bulletins & correspondence

7905130564 Forwards IE Insp Repts 50-356/79-02 & 50-357/79-02 on 790306-09. No noncompliance noted.
SEIDLE, W. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/03/23. 2pp.

--7905150570 IE Insp Repts 50-356/79-02 & 50-357/79-02 on 790306-09 No noncompliance noted Major areas inspected, const status, development of concrete mix design, training & indoctrination & QA.
HUBACEK, W. O., CROSSMAN, W. A., HALL, R. E. Region 4, Dallas, Office of the Director. 79/03/23. 7pp

DOCKET 50-364 NUCLEAR FUELS RECOVERY & RECYCLE CENTER

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1,23,43,76,83,100,111,140,146,151,161,164,170,173,174,178,179,180,182,185,186,187,188,189,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215, & others
GUATTROCHI, J American Nuclear Insurers 79/03/01 1p

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22,26,29,38,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95 & 96
ROBERTS, D H Mutual Atomic Energy Liability Underwriters 79/03/01 1p

DOCKET STN-50-366 YELLOW CREEK NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

7905080541 Discusses util position on leak testing, pressure & temp requirements of ACI Stds 318 & 349 for piping to be embedded in concrete. Revision to PSAR re embedded piping will be implemented immediately
GILLELAND, J E Tennessee Valley Authority 79/03/03 3pp

G. Inspection reports, IE Bulletins & correspondence

7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905030368 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 3pp

7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 3pp.

7905110365 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905010341 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 1p

7905030172 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp

7905020479 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp

7905230698 Ack receipt of 790409 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-366/79-04 & 50-367/79-04.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/19 1p

--7905230733 Responds to NRC 790315 ltr re violations noted in IE Insp Repts 50-366/79-04 & 50-367/79-04. Corrective actions: concrete cylinder curing tank temp was readjusted & immersion heaters were installed
GILLELAND, J E Tennessee Valley Authority 79/04/09 3pp.

--7905230740 Forwards IE Insp Repts 50-366/79-04 & 50-367/79-04 on 790220-22 & notice of violation.
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/15 2pp.

--7905230747 Notice of violation from insp on 790220-22.
* Region 2, Atlanta, Office of the Director. 79/03/14 1p.

--7905230753 IE Insp Repts 50-366/79-04 & 50-367/79-04 on 790220-22. Noncompliance noted GA audit deficiencies
OUGUE, M J Region 2, Atlanta, Office of the Director
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/14 6pp

DOCKET STN-50-367 YELLOW CREEK NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

7905080541 Discusses util position on leak testing, pressure & temp requirements of ACI Stds 318 & 349 for piping to be embedded in concrete. Revisions to PSAR re embedded piping will be implemented immediately
GILLELAND, J E Tennessee Valley Authority 79/03/03 3pp

G Inspection reports, IE Bulletins & correspondence

7905010211 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905030368 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 3pp

7905040233 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 3pp

7905110365 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7905010341 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 1p

7905030172 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys" Licensee action required.
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/17 2pp

7905020479 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/18 2pp

7905230698 Ack receipt of 790409 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-366/79-04 & 50-367/79-04
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/19 1p

--7905230733 Responds to NRC 790315 ltr re violations noted in IE Insp Repts 50-366/79-04 & 50-367/79-04. Corrective actions: concrete cylinder curing tank temp was readjusted & immersion heaters were installed
GILLELAND, J E Tennessee Valley Authority. 79/04/09 3pp

--7905230740 Forwards IE Insp Repts 50-366/79-04 & 50-367/79-04 on 790220-22 & notice of violation
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/15 2pp

--7905230747 Notice of violation from insp on 790220-22.
* Region 2, Atlanta, Office of the Director. 79/03/14 1p.

--7905230753 IE Insp Repts 50-366/79-04 & 50-367/79-04 on 790220-22. Noncompliance noted GA audit deficiencies
OUGUE, M J Region 2, Atlanta, Office of the Director
HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/14 6pp

DOCKETED ITEMS

267

DOCKET STN-30-548 NEP NUCLEAR, UNIT 1

Q Adjudicatory correspondence

7905240641 Changes issuance date for DEB to early May 1979
CUTCHIN, J M Branch 3 79/04/12 1p

7905240940 Withdraws appearance on behalf of intervenor Concerned
Citizens of RI, effective 790402 Certificate of Evc encl
COLLINS, C O Affiliation Unknown 79/04/13 4pp.

I Financial information

7905250240 Notifies of denial of request to withhold from public
disclosure, Revision 3 to general & financial info section of
license application Forwards SEC ltr
FARR, O D Light Water Reactors Branch 3 79/03/12 4pp

--7905250245 Responds to NRC 780809 ltr re public availability of
financial info submitted for license application Submission
of financial info for public disclosure does not contravene
SEC requirements
COOK, J R Securities & Exchange Commission 78/12/14 3pp

DOCKET STN-30-549 NEP Nuclear, Unit 2

A Application/construction stage

7905240641 Changes issuance date for DEB to early May 1979
CUTCHIN, J M Branch 3 79/04/12 1p.

7905240940 Withdraws appearance on behalf of intervenor Concerned
Citizens of RI, effective 790402 Certificate of Evc encl
COLLINS, C O Affiliation Unknown 79/04/13 4pp

7905250240 Notifies of denial of request to withhold from public
disclosure, Revision 3 to general & financial info section of
license application Forwards SEC ltr
FARR, O D Light Water Reactors Branch 3 79/03/12 4pp

--7905250245 Responds to NRC 780809 ltr re public availability of
financial info submitted for license application Submission
of financial info for public disclosure does not contravene
SEC requirements
COOK, J R Securities & Exchange Commission. 78/12/14 3pp

DOCKET STN-30-574 BAOAC NUCLEAR POWER PROJECT

Q Adjudicatory correspondence

7905240168 Opposes licensing of proposed Westinghouse nuclear power
plant in Philippines
AIN, F P. Another Mother for Peace. 78/10/31 1p

7905150235 Requests denial of nuclear reactor export license to
Philippines Reactor design is unsafe, sited on earthquake
fault, near four active volcanoes & in tidal wave zone, thus
jeopardizing US soldier nearby
HURLEY, J Nautilus Alliance 78/11/26 1p

DOCKET STN-30-580 ERIE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

7905150783 Forwards request for addl info to continue review of CP
application
REGAN, W H Environmental Projects Branch 2. 79/04/06 17pp.

7905240936 Requests addl info re new mgt organization to be
incorporated into PSAR Amend 21.
BAER, R. L. Light Water Reactors Branch 2. 79/04/30 3pp.

Q. Adjudicatory correspondence

7905160163 Forwards Board Notification 79-10 on reactor inspector
concerns re B&W plants Certificate of Evc encl
SCINTO, J. F. Hearings Division. 79/03/29 14pp.

7905010115 Forwards request for Board notification re nonsafety-grade
equipment to mitigate transients.
SCINTO, J. F. Hearings Division 79/04/02 31pp.

--7905010156 Board notification staff assessment re nonsafety-grade
equipment to mitigate transients
VASSALLO, D. B. Assistant Director for Light Water Reactors.
79/03/29 2pp.

--7905010198 Board notification recent issue on nonsafety-grade
equipment to mitigate transients. More info is required
TEDESCO, R. L. Assistant Director for Reactor Safety 79/03/16.
3pp

7905160112 Board notification nuclear incident at TMI. Recommends boards
on cases involving B&W reactors be provided w/IE Bulletin
79-05 & PNO-67 & 67A, B, C, D, E, F, G & H
VASSALLO, D. B. Assistant Director for Light Water Reactors.
79/04/03 2pp

7905070225 Forwards memos re problems of pipe support base plate
design.
BARTH, C. A. Branch 3 79/04/05 21pp

7905080377 Informs that NRC has recently discovered document possibly
relevant to sabotage of spent fuel info is classified & may
never be published in final form Forwards TF Carter 790122
memo info assessment will follow when available
BARTH, C. A. Branch 3 79/04/05 2pp

7905150685 Forwards aspects of PWR accumulator delivery re ECCB
performance characteristics
BARTH, C. A. Branch 3 79/04/05 5pp.

B Reportable occurrences, LERs & related correspondence

7905110203 Board notification Seabrook refueling water storage tank
design deficiency
SCINTO, J. Hearings Division 79/03/29 30pp

DOCKET STN-30-581 ERIE NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7905150783 Forwards request for addl info to continue review of CP
application
REGAN, W H Environmental Projects Branch 2. 79/04/06 17pp

7905240936 Requests addl info re new mgt organization to be
incorporated into PSAR Amend 21.
BAER, R. L. Light Water Reactors Branch 2 79/04/30 3pp.

7905160163 Forwards Board Notification 79-10 on reactor inspector
concerns re B&W plants Certificate of Evc encl
SCINTO, J. F. Hearings Division 79/03/29 14pp

7905010115 Forwards request for Board notification re nonsafety-grade
equipment to mitigate transients
SCINTO, J. F. Hearings Division. 79/04/02 31pp.

--7905010156 Board notification staff assessment re nonsafety-grade
equipment to mitigate transients
VASSALLO, D. B. Assistant Director for Light Water Reactors.
79/03/29 2pp.

--7905010198 Board notification: recent issue on nonsafety-grade
equipment to mitigate transients. More info is required
TEDESCO, R. L. Assistant Director for Reactor Safety 79/03/16
3pp.

7905160112 Board notification: nuclear incident at TMI. Recommends boards
on cases involving B&W reactors be provided w/IE Bulletin
79-05 & PNO-67 & 67A, B, C, D, E, F, G & H.
VASSALLO, D. B. Assistant Director for Light Water Reactors.
79/04/03 2pp

7905070225 Forwards memos re problems of pipe support base plate
design.
BARTH, C. A. Branch 3. 79/04/05 21pp.

7905080377 Informs that NRC has recently discovered document possibly
relevant to sabotage of spent fuel info is classified & may
never be published in final form Forwards TF Carter 790122
memo. Info assessment will follow when available.
BARTH, C. A. Branch 3. 79/04/05 2pp

7905150685 Forwards aspects of PWR accumulator delivery re ECCB
performance characteristics.
BARTH, C. A. Branch 3 79/04/05 5pp.

B Reportable occurrences, LERs & related correspondence

7905110203 Board notification. Seabrook refueling water storage tank
design deficiency.
SCINTO, J. Hearings Division. 79/03/29 30pp.

DOCKETED ITEMS

DOCKET STN-50-584 QIBBSAR, QIBBS & HILL

A. Application/construction stage documents & correspondence

7905100117 Forwards first round requests for addl info to complete review of QIBBSAR Also forwards Q-1's & Q-2's for purpose of completing formal record of review
HELTENEG, C J Standardization Branch 79/04/27 53pp

K Utility Final Safety Analysis Report (FSAR) & amends

7905090272 Forwards Amend 13 to QIBBSAR BOPSSAR, referencing REBAR-414
Includes responses to NRC Questions 032 B-032 32, except 032 15 & 032 27 Affidavit encl
PRIETO, R Gibbs & Hill, Inc (subs of Dravo Corp) 79/05/04 2pp

--7905090274 Amend 13 to QIBBSAR BOPSSAR referencing REBAR-414
* Gibbs & Hill, Inc (subs of Dravo Corp) 79/05/04 175pp.

7905230432 Forwards Amend 14 to BOPSSAR, including responses to NRC questions Table 6 219 reissued in amend, due to preproduction error in Amend 13
PRIETO, R Gibbs & Hill, Inc (subs of Dravo Corp) 79/05/18 2pp

--7905230435 Amend 14 to BOPSSAR
* Gibbs & Hill, Inc (subs of Dravo Corp.) 79/05/18 134pp

DOCKET STN-50-592 PALO VERDE NUCLEAR STATION, UNIT 4

A Application/construction stage documents & correspondence

7905020316 Ack 790405 telcon & confirms 790426 meeting in Los Angeles, CA
GOLDBERG, J R Anti-Trust Division 79/04/05 1p

7905240218 Details chronology for period from BAR docketing through issuance of SER
STRIGHT, R L Light Water Reactors Branch 3 79/04/09 4pp

7905090180 Summary of 790329 & 0406 meetings w/util, consultants & ACRS in Phoenix, AZ & Washington, DC, respectively, re replication of CP for addl units
LICITRA, E A Light Water Reactors Branch 3 79/04/13 3pp

7905310378 Forwards info re plant seepage analysis, consisting of listing of "Simulation Conditions & Assumptions for Predictive Model Presented in PSAR Section 2.4.13.1.2" & matrix table on sensitivity of seepage model
VAN BRUNT, E E Arizona Public Service Co 79/05/17 5pp

D. NRC Draft/Final Environmental Statements, supp & correspondence

7905220058 Forwards DES for review w/o encl.
REGAN, W H Environmental Projects Branch 2 79/04/12 2pp.

7905090345 Submits no comments on DES.
BARRONS, H L Agriculture, Dept of, 79/05/03 1p Available at NRC pr

7905240598 Requests 30-day extension of comment period for DES
URBAN, M California, State of, 79/05/14 1p

7905310349 Comments on DES, discusses soil surveys drainage areas & pH organic matter content & texture of soils.
ROCKENBAUGH, T Agriculture, Dept. of, 79/05/23 1p

7905310422 No comments on DES
DILLABOUGH, N Transportation, Dept of 79/05/24 1p.

G. Adjudicatory correspondence

7905150127 NRC response to amended contention of L Bard, Opposes admission of contentions re transportation of spent fuel, as issue in controversy, Certificate of Evc encl.
SOHINKI, S M Branch 3 79/03/21 7pp.

7905090178 Palo Verde Nuclear Intervenor's petition to intervene is defective for untimeliness & lack of standing Denies petition but grants intervenors opportunity to cure defects by filing amended petition within ten days.
LAZO, R M Atomic Safety and Licensing Board Panel 79/03/22 7pp.

7905100332 Amended petition for co-intervention filed in response to NRC 790306 response to first petition for co-intervention if granted co-intervenor status, will consolidate w/L Bard
RHODES, L., DANIELSON, T, FULLINWIDER, S P Palo Verde Nuclear Intervenor 79/03/27 3pp

7905100002 Joint applicants' response to undated third amended contention of L Bard Submits that Bard failed to file an admissible contention on transportation of hazardous waste Suggests that contentions be limited to 790211 order.
GEHR, A C, BISCHOFF, C A Snell & Wilmer 79/03/30 8pp

7905220061 Requests development of nuclear power in US be stopped for sake of safety
JOSEPH, P Affiliation Unknown 79/04/05 1p

7905150748 Forwards NRC rept. "Inquiry inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Grid Serving St Lucie"
SOHINKI, S M Branch 3 79/04/11 1p

7905300337 Discusses evaluation of new info re C-E flow blockage model for ECCB in order to determine sys design conformance to requirements of App K, 10CFR50.46
SOHINKI, S M Branch 3 79/04/11 2pp

7905240133 Forwards DES for facility w/o encl
SOHINKI, S M Branch 3 79/04/17 2pp

H General correspondence

7905240502 Confirms agreement to meet w/recipient & E Rose in Anaheim, CA on 790425
GOLDBERG, J R Anti-Trust Division 79/04/10 1p.

I Financial information

7905300616 Requests addl info re ownership, sources of funds & annual repts to complete financial review Previous responses, dtd 79011 & 790408, have not been adequate
PARR, D D Light Water Reactors Branch 3 79/04/23 5pp

7905150282 Forwards addl financial info Info withheld (ref 10CFR2 790)
JOHNSON, W J El Paso Electric Co, 79/04/26 2pp

7905090085 Forwards "Sources of Funds for Sys Wide Const Expenditures During Period of Const of Subj Nuclear Plant," w/application to withhold document & affidavit of R Korpan Proprietary info withheld (ref 10CFR2 790)
MASTER, V P San Diego Gas & Electric Co 79/03/03 3pp

7905300287 Forwards "Addendum 2 to General Financial Info"
VAN BRUNT, E E Arizona Public Service Co 79/05/23 3pp.

--7905300292 "Addendum 2 to General Financial Info."
* Arizona Public Service Co 79/05/23, 600pp

DOCKET STN-50-593 PALO VERDE NUCLEAR STATION, UNIT 5

A. Application/construction stage documents & correspondence

7905020316 Ack 790405 telcon & confirms 790426 meeting in Los Angeles, CA
GOLDBERG, J R. Anti-Trust Division 79/04/05 1p

7905240218 Details chronology for period from BAR docketing through issuance of SER.
STRIGHT, R L Light Water Reactors Branch 3 79/04/09 4pp

7905090180 Summary of 790329 & 0406 meetings w/util, consultants & ACRS in Phoenix, AZ & Washington, DC, respectively, re replication of CP for addl units
LICITRA, E A Light Water Reactors Branch 3 79/04/13 3pp

7905310378 Forwards info re plant seepage analysis, consisting of listing of "Simulation Conditions & Assumptions for Predictive Model Presented in PSAR Section 2.4.13.1.2" & matrix table on sensitivity of seepage model.
VAN BRUNT, E E Arizona Public Service Co, 79/05/17 5pp

DOCKETED ITEMS

269

D NRC Draft/Final Environmental Statements, suppl's & correspondence

7903220058 Forwards DES for review W/o encl
REGAN, W.H. Environmental Projects Branch 2. 79/04/12 2pp

7903090345 Submits no comments on DES
BARROWS, H.L. Agriculture, Dept of 79/05/03 1p Available at NRC
pdr

7903240598 Requests 30-day extension of comment period for DES
URBAN, M. California, State of 79/05/14 1p

7903310349 Comments on DES discusses soil surveys drainage areas & pH
organic matter content & texture of soils
ROCKENBAUGH, T. Agriculture, Dept of. 79/05/23, 1p

7903310422 No comments on DES
DILLABOUGH, N. Transportation, Dept of 79/05/24 1p.

O Adjudicatory correspondence

7903150127 NRC response to amended contention of L. Bard Opposes
admission of contentions re transportation of spent fuel, as
issue in controversy Certificate of Svc encl
SCHINKL, S.M. Branch 3 79/03/21 7pp

7903090178 Palo Verde Nuclear Intervenor's petition to intervene is
defective for untimeliness & lack of standing Denies
petition but grants intervenors opportunity to cure defects
by filing amended petition within ten days
LAZO, R.H. Atomic Safety and Licensing Board Panel. 79/03/22 7pp

7903100332 Amended petition for co-intervention filed in response to
NRC 790306 response to first petition for co-intervention if
granted co-intervenor status, will consolidate w/L. Bard
RHODES, L., DANIELSON, T., FULLINWIDER, B.P. Palo Verde Nuclear
Intervenor's. 79/03/27. 3pp

7903100002 Joint applicants' response to undated third amended
contention of L. Bard Submits that Bard failed to file an
admissible contention on transportation of hazardous
materials Suggests that contentions be limited to 790211 order
DEHR, A.C., BISCHOFF, C.A. Snell & Wilmer 79/03/30 3pp.

7903220061 Requests development of nuclear power in US be stopped for
sake of safety
JDBEPH, P. Affiliation Unknown 79/04/05. 1p.

7903150748 Forwards NRC rept, "Inquiry into Allegation of
Employee Misconduct by Restricting Investigation to
Determine Reliability of Power Grid Serving St. Lucie"
SCHINKL, S.M. Branch 3 79/04/11 1p

7903300537 Discusses evaluation of new info re C-E flow blockage
model for ECCB in order to determine sys design conformance
to requirements of App K, 10CFR50.46
SCHINKL, S.M. Branch 3. 79/04/11 2pp

7903240133 Forwards DES for facility W/o encl
SCHINKL, S.M. Branch 3. 79/04/17. 2pp

H. General correspondence

7903240502 Confirms agreement to meet w/recipient & E. Ross in Anaheim,
CA on 790425
GOLDBERG, J.R. Anti-Trust Division. 79/04/10. 1p.

I. Financial information

7903300416 Requests addl info re ownership, sources of funds & annual
repts to complete financial review Previous responses, dtd
790111 & 790405, have not been adequate.
FARR, O.D. Light Water Reactors Branch 3. 79/04/23 3pp

7903150282 Forwards addl financial info. Info withheld (ref 10CFR2.790).
JOHNSON, M.J. El Paso Electric Co. 79/04/26. 2pp.

7903090085 Forwards "Sources of Funds for Bys Wide Const Expenditures
During Period of Const of Buby Nuclear Plant,"
w/application to withhold document & affidavit of R. Korpan.
Proprietary info withheld (ref 10CFR2.790).
MASTER, V.P. San Diego Gas & Electric Co. 79/05/03. 3pp.

7903300287 Forwards "Addendum 2 to General Financial Info."
VAN BRUNT, E.E. Arizona Public Service Co. 79/03/23. 3pp.

--7903300292 "Addendum 2 to General Financial Info."
* Arizona Public Service Co 79/03/23 300pp.

DOCKET BTN-50-576 NEW HAVEN, UNIT 1

A. Application/construction stage documents & correspondence

7903290053 Forwards requested RB Boyd 790119 ltr to A. Kintigh re
alternate site analysis W/o encl.
SWANSON, D.T. Branch 1 79/03/28 1p

7903010664 Forwards proposed schedule for radiological safety review
BOYD, R.B. Division of Project Management 79/04/13 3pp

7903020390 In response to 790327 ltr, forwards signed Agreements for
technical support in review of facility
DEYOUNG, R.C. Division of Site Safety & Environmental Analysis
79/04/13 2pp

7903070070 Requests addl info for completion of PSAR review Matl
concerns discrepancy in participation of operator license
candidates in simulator training course
COLLINS, P.F. Operator Licensing Branch 79/04/13 2pp

7903030350 Comments on "Federal-State Authorities & Cooperation in
Nuclear Power Plant Licensing", outlines changes to NY siting
law & attempts to eliminate duplication of regulatory
processes between federal & state agencies
SMOLINSKY, J. New York, State of 79/04/24. 2pp

7903230837 Informs of establishment of schedule for radiological safety
review of application for CP Estimates prospective decision
date to be 810708
BOYD, R.S. Division of Project Management 79/04/24 4pp

7903250107 Notification of 790308 meeting w/util. NY state
representatives & ANL in Mexico, NY to acquaint local
residents w/status on environ review
SELLS, D.E. Environmental Projects Branch 2. 79/04/24 2pp

7903010494 Forwards "1978 Hudson River Shortnose Sturgeon Study, Scope
of Work."
RAY, M.J. New York State Electric & Gas Corp. 79/04/25 22pp.

7903290066 Requests addl info in order to continue evaluation of PSAR
Specific info requested concerns areas of containment sys,
effluent treatment sys, radiological assessment, geology &
seismology & operator training.
FARR, O.D. Light Water Reactors Branch 3. 79/04/27 13pp.

7903310464 Forwards previously omitted page from 790427 ltr re
Questions 361.24 & 361.25.
FARR, O.D. Light Water Reactors Branch 3. 79/05/03. 3pp.

7903220120 Responds to 790427 ltr requesting addl info Info will be
submitted as PSAR amend by mid-July.
KINTIGH, A.E. New York State Electric & Gas Corp 79/05/14 1p

B. Utility Preliminary Safety Analysis Report, amends

7903310342 Forwards affidavit of svc for Amend 3 to PSAR & CP
application
KINTIGH, A.E. New York State Electric & Gas Corp 79/05/16. 4pp.

C. Utility Environmental Report (ER), amends & correspondence

7903070316 Requests addl info re analysis of cooling tower & thermal
discharge. Amend to environ rept containing responses to
encl questions should be submitted by 790615 in order to
continue environ review.
REGAN, W.H. Environmental Projects Branch 2. 79/04/23 4pp.

7903070467 Requests extension to file preliminary draft of first
chapters of environ statement.
SMOLINSKY, J. New York, State of. 79/04/26 2pp.

7903300477 Amend 2 to environ rept.
KINTIGH, A.E. New York State Electric & Gas Corp 79/05/24. 303pp.

O. Adjudicatory correspondence

7903250353 Petitions to intervene in proceeding. Asserts health &
safety will be adversely affected by plant.
WEBER, S., DALY, M. Ecology Action of Oswego. 79/03/08. 3pp.

DOCKETED ITEMS

7905240098 Petition to intervene, submitted by Columbia County, NY, Town of Stuyvesant, NY & Concerned Citizens for Safe Energy, Inc
KAFIN, R J KAFIN, R J 79/03/12 2pp

--7905240106 Supports petition to intervene submitted by Columbia County, NY, Town of Stuyvesant, NY & Concerned Citizens for Safe Energy, Inc Notice of appearance & Certificate of Svc encl
KAFIN, R J KAFIN, R J 79/03/12. 10pp

7905230350 Petitions to intervene in proceeding Asserts health & safety will be adversely affected by plant
CLARK, L Safe Energy for New Haven 79/03/16 3pp

7905230409 Mid-Hudson Nuclear Opponents' petition to intervene as full party re alternate site considerations, need for facility, financial qualifications of applicants & cost of proposed plant
BROWN, P D Mid-Hudson Nuclear Opponents, Inc 79/03/19 3pp.

7905230365 Notice of appearance on behalf of util
SCHUTT, R, ZEBRAK, I L Huber, Magill, Lawrence & Farrell 79/03/20 1p

--7905230370 Answer to intervention petitions of various groups, including NY State Energy Ofc, Oswego County Farm Bureau, Ecology Action & Safe Energy for New Haven, Certificate of Svc encl
SCHUTT, R, ZEBRAK, I L Huber, Magill, Lawrence & Farrell 79/03/20 8pp

7905100178 Response to petitions to intervene filed in Columbia/Ulster County area during Mar 1979 Intervenor failed to establish standing; petitions should be denied.
Certificate of Svc encl
SWANSON, D T Branch 1 79/04/02. 12PP

7905240160 Answer seeking denial of 790319 petition to intervene filed by Mid-Hudson Nuclear Opponents, Inc Certificate of Svc encl
SCHUTT, R, ZEBRAK, I E New York State Electric & Gas 79/04/03 6pp

7905130266 Forwards first set of interrogatories to util from NY St Dept of Environ Conservation
ENGEL, D A New York, State of 79/04/04 1p

--7905130271 First set of interrogatories for util from NY St Dept of Environ Conservation
* New York, State of 79/04/04 8pp

7905130164 Requests copy of 790402 "NRC Answer to Petitions to Intervene Filed in Columbia/Ulster County Area"
ZEBRAK, I L Huber, Magill, Lawrence & Farrell 79/04/06 2pp.

7905240148 Requests leave to intervene in proceedings re selection of alternate sites. Protests previous denial of intervenor status.
KEEPING, W. Gardiner, NY. 79/04/12 1p

H. General correspondence

7905230347 Notice to all parties & interested persons to send documents for W Jordan to 881 West Outer Drive, Oak Ridge, TN
WEHNER, B Atomic Safety and Licensing Board Panel. 79/04/20. 1p

7905130115 Forwards info requested in 790131 ltr re nuclear reactor const for utils & schools
REGAN, W. H. Environmental Projects Branch 2 79/04/30 5pp

DOCKET STN-30-597 NEW HAVEN, UNIT 2

A. Application/construction stage documents & correspondence

7905290053 Forwards requested RB Boyd 790119 ltr to A Kintigh re alternate site analysis w/o encl.
SWANSON, D T Branch 1 79/03/28. 1p

7905010664 Forwards proposed schedule for radiological safety review
BOYD, R. B. Division of Project Management. 79/04/13. 3pp.

7905020390 In response to 790327 ltr, forwards signed agreements for technical support in review of facility.
DEYOUNG, R C. Division of Site Safety & Environmental Analysis 79/04/13. 2pp.

7905070070 Requests addl info for completion of PSAR review. Matl concerns discrepancy in participation of operator license candidates in simulator training course.
COLLINS, P. F. Operator Licensing Branch. 79/04/13. 2pp.

7905030350 Comments on "Federal-State Authorities & Cooperation in Nuclear Power Plant Licensing" outlines changes to NY siting law & attempts to eliminate duplication of regulatory processes between federal & state agencies
SMOLINSKY, J New York, State of. 79/04/24. 2pp

7905230837 Informs of establishment of schedule for radiological safety review of application for CP Estimates prospective decision date to be 810708
BOYD, R B Division of Project Management 79/04/24 4pp

7905230107 Notification of 790508 meeting w/util, NY state representatives & ANL in Mexico, NY to acquaint local residents w/status on environ review
SELLS, D E Environmental Projects Branch 2 79/04/24. 2pp

7905010494 Forwards "1978 Hudson River Shortnose Sturgeon Study, Scope of Work"
RAY, M J New York State Electric & Gas Corp 79/04/25 22pp

7905290066 Requests addl info in order to continue evaluation of PSAR Specific info requested concerns areas of containment sys, effluent treatment sys, radiological assessment, geology & seismology & operator training
PARR, D D Light Water Reactors Branch 3 79/04/27 15pp.

7905310464 Forwards previously omitted page from 790427 ltr re Questions 361 24 & 361 25
PARR, D D Light Water Reactors Branch 3 79/05/03 3pp

7905220120 Responds to 790427 ltr requesting addl info Info will be submitted as PSAR amend by mid-July
KINTIGH, A E New York State Electric & Gas Corp 79/05/14 1p

B Utility Preliminary Safety Analysis Report, amends

7905310342 Forwards affidavit of svc for Amend 3 to PSAR & CP application
KINTIGH, A E. New York State Electric & Gas Corp 79/05/16. 4pp

C Utility Environmental Report (ER), amends & correspondence

7905070316 Requests addl info re analysis of cooling tower & thermal discharge Amend to environ rept containing responses to encl questions should be submitted by 790613 in order to continue environ review
REGAN, W. H. Environmental Projects Branch 2 79/04/23. 4pp

7905070467 Requests extension to file preliminary draft of first chapters of environ statement.
SMOLINSKY, J New York, State of 79/04/26. 2pp.

7905300477 Amend 2 to environ rept.
KINTIGH, A E New York State Electric & Gas Corp 79/05/24. 303pp

D Adjudicatory correspondence

7905230333 Petitions to intervene in proceeding. Asserts health & safety will be adversely affected by plant.
WEBER, B., DALY, H. Ecology Action of Oswego. 79/03/08 3pp

7905240098 Petition to intervene, submitted by Columbia County, NY, Town of Stuyvesant, NY & Concerned Citizens for Safe Energy, Inc.
KAFIN, R. J. KAFIN, R J 79/03/12. 2pp.

--7905240106 Supports petition to intervene submitted by Columbia County, NY, Town of Stuyvesant, NY & Concerned Citizens for Safe Energy, Inc. Notice of appearance & Certificate of Svc encl.
KAFIN, R. J. KAFIN, R J. 79/03/12 10pp.

7905230350 Petitions to intervene in proceeding Asserts health & safety will be adversely affected by plant.
CLARK, L. Safe Energy for New Haven. 79/03/16 3pp.

7905230409 Mid-Hudson Nuclear Opponents' petition to intervene as full party re alternate site considerations, need for facility, financial qualifications of applicants & cost of proposed plant.
BROWN, P. D. Mid-Hudson Nuclear Opponents, Inc. 79/03/19 3pp

7905230365 Notice of appearance on behalf of util.
SCHUTT, R., ZEBRAK, I. L. Huber, Magill, Lawrence & Farrell. 79/03/20 1p

DOCKETED ITEMS

271

--7905250370 Answer to intervention petitions of various groups, including NY State Energy Ofc, Oswego County Farm Bureau, Ecology Action & Safe Energy for New Haven Certificate of Svc encl SCHUTT, R., ZEBRAK, I L Huber, Magill, Lawrence & Farrell 79/03/20 8pp

7905100178 Response to petitions to intervene filed in Columbia/Ulster County area during Mar 1979. Intervenor failed to establish standing; petitions should be denied Certificate of Svc encl. SWANSON, D T Branch 1. 79/04/02 12pp

7905240160 Answer seeking denial of 790319 petition to intervene filed by Mid-Hudson Nuclear Opponents, Inc Certificate of Svc encl SCHUTT, R., ZEBRAK, I E New York State Electric & Gas 79/04/03 6pp.

7905130266 Forwards first set of interrogatories to util from NY St Dept of Environ Conservation ENGEL, D A New York, State of 79/04/04 1p

--7905130271 First set of interrogatories for util from NY St Dept of Environ Conservation. * New York, State of 79/04/04 8pp

7905130164 Requests copy of 790402 "NRC Answer to Petitions to Intervene Filed in Columbia/Ulster County Area " ZEBRAK, I L Huber, Magill, Lawrence & Farrell 79/04/06. 2pp.

7905240148 Requests leave to intervene in proceedings re selection of alternate sites. Protests previous denial of intervenor status. KEEPING, W Gardiner, NY. 79/04/12 1p

H General correspondence

7905250347 Notice to all parties & interested persons to send documents for W Jordan to BBI West Outer Drive, Oak Ridge, TN HENNER, B. Atomic Safety and Licensing Board Panel 79/04/20. 1p.

7905130113 Forwards info requested in 790131 ltr re nuclear reactor const for utils & schools REGAN, W H Environmental Projects Branch 2 79/04/30 5pp

DOCKET 50-0598 NORTHWESTERN UNIV

A Application/construction stage documents & correspondence

7905170243 Requests that application for CP & DL for Model AON-201, Serial 114, nuclear reactor be withdrawn BTROTZ, R H Northwestern Univ 79/03/15 1p.

DOCKET 50-599 CARROLL FACILITY I

A Application/construction stage documents & correspondence

7905130759 Notification of 790509 meeting w/util in Bethesda, MD for pretending discussions involving certain NRC branches: Instrumentation & Control, Reactor Sys Core Performance & Analysis & Containment Sys BIRKEL, R A Light Water Reactors Branch 2. 79/04/26 2pp

7905250091 Notification of 790502 meeting w/util, ANL, EPA, DOI & Corps of Engineers in Savannah, IL to discuss environ issues related to NRC licensing review HAUTP, C A Environmental Projects Branch 1. 79/04/26 1p

7905090360 Forwards "Site Investigations of Areas Along MS & Lower IL Rivers," Aug 1974, "Erie Site Geotechnical Evaluation," May 1975, "Preliminary Site Evaluation, La Salle & Putnam Counties, IL," 771201 W/o encl. NAUGHTON, W F Commonwealth Edison Co 79/05/07. 2pp.

7905170246 Forwards repts in response to NRC 790404 ltr re site investigations & evaluations for areas along MS & lower IL rivers, Erie Site, Oldstone North & Rosetta West site, Quad-Cities, LaSalle & Putnam Counties, IL sites W/o encl. NAUGHTON, W F Commonwealth Edison Co. 79/05/07. 2pp

7905240914 Forwards FR notice re CP application for info. due to proximity of proposed site to WI state border. W/o encl. BALLARD, R L. Environmental Projects Branch 1. 79/05/07 1p.

7905240919 Forwards FR notice re CP application for info W/o encl. BALLARD, R L. Environmental Projects Branch 1. 79/05/07 1p.

7905240926 Forwards FR notice re CP application for info. due to proximity of site to IA state border. W/o encl. BALLARD, R L. Environmental Projects Branch 1 79/05/07. 1p.

7905240966 Requests comments on site suitability environ rept by 790903. BALLARD, R L. Environmental Projects Branch 1. 79/05/08. 4pp.

7905240664 Forwards magnetic tape containing hourly meteorological observation data for 760801-770731, in response to RC DeYoung 790404 request NAUGHTON, W F Commonwealth Edison Co. 79/05/09. 7pp

7905170264 Notification that USGS quadrangle maps have been forwarded under separate cover, in response to first part of Question 361.4 NAUGHTON, W F Commonwealth Edison Co 79/05/11 4pp

7905220102 Forwards Amend 1 to application for CP & early site review. REED, C Commonwealth Edison Co 79/05/18 1p.

--7905220107 Amend 1 to application for CP & early site review. Amend comprises util responses to NRC questions re site suitability generated during early site review acceptance. * Commonwealth Edison Co 79/05/18 650pp

7905310393 Forwards affidavit certifying 790523 distribution of site suitability/site safety rept; Amend 1 NAUGHTON, W F Commonwealth Edison Co 79/05/25 2pp

O Adjudicatory correspondence

7905130260 Notice of hearing re request for early site review & CP CHILK, B J Office of the Secretary of the Commission 79/05/01 7pp

DOCKET 50-600 CARROLL FACILITY II

A Application/construction stage documents & correspondence

7905130759 Notification of 790509 meeting w/util in Bethesda, MD for pretending discussions involving certain NRC branches: Instrumentation & Control, Reactor Sys Core Performance & Analysis & Containment Sys BIRKEL, R A Light Water Reactors Branch 2. 79/04/26. 2pp

7905250091 Notification of 790502 meeting w/util, ANL, EPA, DOI & Corps of Engineers in Savannah, IL to discuss environ issues related to NRC licensing review HAUTP, C A Environmental Projects Branch 1 79/04/26. 1p.

7905090360 Forwards "Site Investigations of Areas Along MS & Lower IL Rivers," Aug 1974, "Erie Site Geotechnical Evaluation," May 1975, "Preliminary Site Evaluation, La Salle & Putnam Counties, IL," 771201 W/o encl. NAUGHTON, W F. Commonwealth Edison Co. 79/05/07. 2pp.

7905170246 Forwards repts in response to NRC 790404 ltr re site investigations & evaluations for areas along MS & lower IL rivers, Erie Site, Oldstone North & Rosetta West site, Quad-Cities, LaSalle & Putnam Counties, IL sites W/o encl. NAUGHTON, W F Commonwealth Edison Co 79/05/07. 2pp.

7905240914 Forwards FR notice re CP application for info. due to proximity of proposed site to WI state border W/o encl. BALLARD, R L. Environmental Projects Branch 1. 79/05/07. 1p.

7905240919 Forwards FR notice re CP application for info. W/o encl. BALLARD, R L. Environmental Projects Branch 1 79/05/07. 1p.

7905240926 Forwards FR notice re CP application for info. due to proximity of site to IA state border. W/o encl. BALLARD, R L. Environmental Projects Branch 1 79/05/07. 1p

7905240966 Requests comments on site suitability environ rept by 790903. BALLARD, R L. Environmental Projects Branch 1. 79/05/08 4pp.

7905240664 Forwards magnetic tape containing hourly meteorological observation data for 760801-770731, in response to RC DeYoung, 790404 request NAUGHTON, W F Commonwealth Edison Co 79/05/09. 7pp.

7905170264 Notification that USGS quadrangle maps have been forwarded under separate cover, in response to first part of Question 361.4 NAUGHTON, W F Commonwealth Edison Co. 79/05/11. 4pp.

7905220102 Forwards Amend 1 to application for CP & early site review REED, C. Commonwealth Edison Co. 79/05/18 1p

--7905220107 Amend 1 to application for CP & early site review. Amend comprises util responses to NRC questions re site suitability generated during early site review acceptance. * Commonwealth Edison Co 79/05/18. 650pp.

DOCKETED ITEMS

7905310393 Forwards affidavit certifying 790523 distribution of site suitability/site safety rept. Amend 1
NAUGHTON, W F Commonwealth Edison Co 79/05/25 2pp

G Adjudicatory correspondence

7905150260 Notice of hearing re request for early site review & CP
CHILK, S J Office of the Secretary of the Commission 79/05/01
7pp.

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0008 Battelle Columbus Laboratories

7905150814 Forwards "Site Security Personnel Training Plan for
Facility " Encl withheld (ref 10CFR2 790)
TOY, M L Battelle Memorial Institute, Columbus Laboratories
79/02/20 2pp

7905010191 Forwards IE Info Notice 79-08, "Interconnection of
Contaminated Sys w/Svc Air Sys Used as Source of Breathing
Air"
KEPLER, J Q Region 3, Chicago, Office of the Director 79/03/28
1p

7905150790 Forwards 790308 ltr requesting fee for review of security
training & qualification plan Requests fee be forwarded
within 15 days W/o encl
HEISS, D License Fee Management Branch 79/04/24 1p

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP

7905010239 Forwards IE Info Notice 79-08, "Interconnection of
Contaminated Sys w/Svc Air Sys Used as Source of Breathing
Air"
ENGELKEN, R H Region 5, San Francisco, Office of the Director
79/03/28 1p

DOCKET 70-0027 BABCOCK & WILCOX CO

7905040105 Ack receipt of 790323 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 70-0027/79-02
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/04/03 1p

--7905040114 Responds to NRC 790309 ltr re violations noted in IE Insp
Rept 70-0027/79-02 Corrective actions withheld
(ref 10CFR2 790).
EWING, J F Babcock & Wilcox Co 79/03/23 1p

--7905040118 Forwards IE Insp Rept 70-0027/79-02 on 790213-16 Notice of
violation withheld (ref 10CFR2 790)
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/03/09
2pp

IE Insp Rept 70-0027/79-02 on 790213-16. Noncompliance noted
to include weight measurements of fabrication
residues in limit of error calculations. Details
(ref 10CFR2 790)
Region 2, Atlanta, Office of the Director
H. Region 2, Atlanta, Safeguards Branch 79/03/09

status of efforts to develop new LEHUF model
7901 including addl time required to
or validation Procedural mods will
0101
Wilcox Co 79/04/23 1p.

DOCKET 70-0033 TEXAS INSTRUMENTS, INC.

7905230277 Forwards IE Insp Rept 70-0033/79-02 on 790220-22 No
noncompliance noted
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 79/03/14
2pp.

--7905230288 IE Insp Rept 70-0033/79-02 on 790220-22 No noncompliance
noted. Major areas inspected: physical inventory verification,
& measurement & statistical control of nuclear matl. Details
withheld (ref 10CFR2 790).
ZIBULSKY, H., COHEN, I. Region 1, Philadelphia, Office of the
Director JOYNER, J H Region 1, Philadelphia, Safeguards
Branch. 79/03/14 1p

7905240078 Forwards revision to HFIR project safeguards contingency
plan for final acceptance review Plan withheld (ref Atomic
Energy Act of 1954 & Energy Reorganization Act of 1974)
SHERMAN, F L, GONZALES, B Texas Instruments, Inc 79/04/12 2pp

DOCKET 70-0102 AMHERST COLLEGE

7905100422 Discusses IE Insp of Licenses 20-03570-02, 20-03570-03,
20-03570-06 & BNM-94 on 790308 No noncompliance noted
Major areas inspected: examinations of procedures &
representative records & interviews w/personnel.
MCCLINTOCK, R O Region 1, Philadelphia, Office of the Director,
79/03/20 1p

DOCKET 70-0135 Babcock & Wilcox Co

7905090060 Forwards revised organization chart for PA operations &
updated position description for nuclear matl control &
accountability personnel, excluding BNM custodian &
technician positions, which were not changed
AUSTIN, M A Babcock & Wilcox Co, Nuclear Material Div 79/02/26
16pp.

7905080027 Responds to 790130 ltr to LC Rouse Agrees to assignment of
Ort: as compliance section manager & deletion of regulatory
projects coordinator position Assignment of Congedo as
licensing & nuclear safety specialist is conditional
CROW, W T Division of Fuel Cycle & Material Safety 79/03/16
2pp

7905240594 Forwards Table & 1, "Comprehensive Listing of Storage Area
Codes" enumerating current matl balance areas & item control
areas Table was omitted from B&W 781213 ltr
AUSTIN, M A Babcock & Wilcox Co 79/04/06 2pp

7905220072 Ack receipt of 790220 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 70-0135/78-30 &
70-0364/78-32
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 79/04/10
1p

--7905220077 Responds to NRC 790130 ltr re violations noted in IE Insp
Repts 70-0135/78-30 & 70-0364/78-32 Corrective action
withheld (ref 10CFR2 790)
AUSTIN, M A Babcock & Wilcox Co, Nuclear Material Div. 79/02/20
1p

--7905220087 Forwards IE Insp Repts 70-0135/78-30 & 70-0364/78-32 on
781106-1201 Notice of violation withheld (ref 10CFR2 790).
MARTIN, W O Region 1, Philadelphia, Safeguards Branch
79/01/30 2pp

--7905220092 IE Insp Repts 70-0135/78-30 & 70-0364/78-32 on 781106-1201.
Noncompliance noted: failure to maintain stds program for
crane scale & failure to assure gross weights and
measurements of element Details withheld (ref 10CFR2 790)
KUSHNER, W L, JOYNER, J H Region 1, Philadelphia, Safeguards
Branch. 79/01/22 1p

7905230048 Responds to 790221 ltr requesting assessment of potential
magnitude of MUF bias due to degree of verification
currently performed No addl measurements required for
verification Forwards measurements control plan, W/o encl.
AUSTIN, M A Babcock & Wilcox Co. 79/04/20 2pp

7905240756 Ack receipt of 790416 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 70-0135/79-01 &
70-0364/79-02.
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 79/04/26
1p

--7905240763 Responds to NRC 790320 ltr re violations noted in IE Insp
Repts 70-0135/79-01 & 70-0364/79-02. Corrective actions
shop talk will be scheduled to review BNM custodian
responsibilities.
AUSTIN, M A Babcock & Wilcox Co. 79/04/16. 2pp.

--7905240775 Forwards IE Insp Rept 70-0135/79-01 & 70-0364/79-02 on
790103-0202. Notice of violation withheld (ref 10CFR2 790).
MARTIN, W O Region 1, Philadelphia, Safeguards Branch
79/03/20 3pp

--7905240784 IE Insp Rept 70-0135/79-01 & 70-0364/79-02 on 790103-0202.
Noncompliance noted: failure to advise NRC of changes to
internal control sys & failure to adhere to control
procedures for BNM. Details withheld (ref 10CFR2 790).
KUSHNER, W L. Region 1, Philadelphia, Office of the Director
JOYNER, J H Region 1, Philadelphia, Safeguards Branch.
79/03/19. 3pp

DOCKETED ITEMS

273

7905300583 Accepts encl proposed contingency plan to provide acceptable level of physical protection in event of strike, as discussed & agreed upon during MJ Defillippi 790423 visit Plan withheld (ref 10CFR2, 790).
MCCORKLE, O W Physical Security Licensing Branch 79/04/26, 2pp

DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC

7905090265 Responds to NFB 781009 ltr transmitting decommissioning program for U-235 facilities & requesting that Part 2 be withheld (ref 10CFR2 790) Request denied; considerations are not specific enough
CROW, W T Fuel Process & Fab. Branch 79/03/09 3pp.

7905230684 Forwards IE Insp Rept 70-0143/79-08 on 790226-0302 No noncompliance noted.
KENNA, H B Region 2, Atlanta, Safeguards Branch, 79/03/19 2pp

--7905230689 IE Insp Rept 70-0143/79-08 on 790226-0302 No noncompliance noted. Major areas inspected; records & repts.
HODGEM, J W Region 2, Atlanta, Office of the Director
GILLESPIE, F P Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/19 3pp

7905150664 Informs that info requested re amend to Certificate of Compliance 6400 will be submitted by 790430.
MICHEL, C J Nuclear Fuel Services, Inc (subs of Getty Oil Co.) 79/03/23, 1p.

7905100423 Requests Amend MMP-1 to License SNM-124 Details withheld (ref 10CFR2 790).
HENSLEY, K D Nuclear Fuel Services, Inc. (subs of Getty Oil Co.). 79/03/27, 2pp

7905230535 Forwards project rept on sys analysis study Study withheld (ref 10CFR2, 790).
MANBER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 79/04/03, 1p.

7905130024 Submits proposed new Section 7.7 of fundamental nuclear matl control plan for approval, in response to 790112 ltr Details withheld (ref 10CFR2 790).
MANBER, W C Nuclear Fuel Services, Inc (subs. of Getty Oil Co) 79/04/06, 2pp

7905020417 Ack receipt of 790403 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/79-07
KENNA, H B Region 2, Atlanta, Safeguards Branch 79/04/12 1p.

--7905020425 Responds to NRC 790312 ltr re violations noted in IE Insp Rept 70-0143/79-07. Corrective actions re safeguard measures withheld (ref 10CFR2 790).
MANBER, W C Nuclear Fuel Services, Inc. (subs of Getty Oil Co) 79/04/03 1p

--7905020433 Forwards IE Insp Rept 70-0143/79-07 Notice of violation withheld (ref 10CFR2 790).
KENNA, H B Region 2, Atlanta, Safeguards Branch, 79/03/12 2pp.

--7905020439 IE Insp Rept 70-0143/79-07 on 790110-0209 Noncompliance noted: failure to calculate bias associated w/measurement of process holdup & stack & laundry discharges
LEE, T D Region 2, Atlanta, Office of the Director
WILLIAMS, O H Region 2, Atlanta, Safeguards Branch, 79/03/07, 1p.

7905240344 Ack receipt of IE Insp Rept 70-0143/79-13 on 790414-15. No proprietary info
MANBER, W C Nuclear Fuel Services, Inc (subs. of Getty Oil Co.) 79/04/20, 1p

--7905240382 Forwards IE Insp Rept 70-0143/79-13 on 790414-15. No noncompliance noted.
KENNA, H B Region 2, Atlanta, Office of the Director, 79/04/20, 1p.

--7905240361 IE Insp Rept 70-0143/79-13 on 790414-15. No noncompliance noted. Major areas inspected: shutdown preparations & plant operations
KENNA, H B Region 2, Atlanta, Office of the Director, 79/04/19, 2pp.

7905140141 Notifies that Section 7.7 of fundamental nuclear matl control plan submitted in 790406 ltr is satisfactory. License condition 2.1 of Amend MMP-1 to License SNM-125 is revised accordingly.
PARTLOW, J O Material Control Licensing Branch, 79/04/24, 2pp

7905130135 Responds to 790423 ltr requesting time extension for conducting low enriched U inventory Request is granted
PARTLOW, J C Material Control Licensing Branch 79/04/26 1p

7905230844 Determines that revised & corrected safeguards contingency plan is acceptable License Conditions 7.1 & 9.2 are being amended Physical protection requirements encl
MCCORKLE, O W Physical Security Licensing Branch 79/03/02 2pp

7905010137 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/28 1p

DOCKET 70-0130 PURDUE UNIV

7905110041 Forwards IE Insp Repts 50-182/79-01 & 70-0130/79-02 on 790213-19 Notice of violation withheld (ref 10CFR2 790)
* Region 3, Chicago, Safeguards Branch 79/03/26 2pp

--7905110047 IE Insp Repts 50-182/79-01 & 70-0130/79-02 on 790213-19 Noncompliance noted keys, locks & hardware deficiencies for fast breeder blanket facility Details withheld (ref 10CFR2, 790).
CHRISTOFFER, O M, MADEDA, T J Region 3, Chicago, Office of the Director
HIND, J A Region 3, Chicago, Safeguards Branch 79/03/21 1p

DOCKET 70-0364 PARKS TOWNSHIP SITE, BABCOCK & WILCOX CO

7905090060 Forwards revised organization chart for PA operations & updated position description for nuclear matl control & accountability personnel, excluding SNM custodian & technician positions, which were not changed
AUSTIN, M A Babcock & Wilcox Co., Nuclear Material Div 79/02/26 16pp

7905150137 Requests administrative change to License SNM-414, changing levels of U enrichment in matl limitations portion of Tech Specs
AUSTIN, M A Babcock & Wilcox Co 79/03/01 3pp

7905080027 Responds to 790130 ltr to LC Rouse Agrees to assignment of Onr as compliance section manager & deletion of regulatory projects coordinator position Assignment of Congedo as licensing & nuclear safety specialist is conditional.
CROW, W T Division of Fuel Cycle & Material Safety 79/03/16 2pp

7905220072 Ack receipt of 790220 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/78-30 & 70-0364/78-32
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 79/04/10 1p

--7905220077 Responds to NRC 790130 ltr re violations noted in IE Insp Repts 70-0135/78-30 & 70-0364/78-32 Corrective action withheld (ref 10CFR2, 790).
AUSTIN, M A Babcock & Wilcox Co., Nuclear Material Div 79/02/20 1p

--7905220087 Forwards IE Insp Repts 70-0135/78-30 & 70-0364/78-32 on 781106-1201 Notice of violation withheld (ref 10CFR2 790).
MARTIN, W O Region 1, Philadelphia, Safeguards Branch 79/01/30 2pp

--7905220092 IE Insp Repts 70-0135/78-30 & 70-0364/78-32 on 781106-1201 Noncompliance noted failure to maintain stds program for crane scale & failure to assure gross weights and measurements of element Details withheld (ref 10CFR2, 790).
KUSHNER, W L, JOYNER, J H Region 1, Philadelphia, Safeguards Branch, 79/01/22 1p.

7905240089 Forwards revisions to proposed Parks Township site safeguards contingency plan in response to 790228 ltr. Plan withheld (ref Atomic Energy Act of 1954 & Energy Reorganization Act of 1974)
AUSTIN, M A Babcock & Wilcox Co., Nuclear Material Div 79/04/18 7pp.

7905250048 Responds to 790221 ltr requesting assessment of potential magnitude of WUF bias due to degree of verification currently performed. No addl measurements required for verification. Forwards measurements control plan w/o encl
AUSTIN, M A Babcock & Wilcox Co 79/04/20, 2pp

DOCKETED ITEMS

7909020530 Responds to 790623 ltr Data generated in Pu glovebox line must be treated individually
PARTLOW, J O Material Control Licensing Branch 79/04/24 1p

7909110092 Forwards 790323 ltr requesting \$150 fee for amend to delay Pu physical inventory Requests payment, within 15 days of receipt of ltr
WEISS, D License Fee Management Branch 79/04/24 1p

7909230706 Summary of 790420 meeting w/B&W re revisions to Section II of License SNM-414 re improvement of Pu facility fire protection & ventilation sys
BURKHARDT, W Fuel Reprocess & Recycle Branch 79/04/26 1p

7909240756 Ack receipt of 790416 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/79-01 & 70-0364/79-02
MARTIN, H O Region 1, Philadelphia, Safeguards Branch 79/04/26 1p

--7909240763 Responds to NRC 790320 ltr re violations noted in IE Insp Repts 70-0135/79-01 & 70-0364/79-02 Corrective actions shop talk will be scheduled to review SNM custodian responsibilities
AUSTIN, M A Babcock & Wilcox Co 79/04/16 2pp

--7909240775 Forwards IE Insp Rept 70-0135/79-01 & 70-0364/79-02 on 790103-0202 Notice of violation withheld (ref 10CFR2 790)
MARTIN, H O Region 1, Philadelphia, Safeguards Branch 79/03/20 3pp

--7909240784 IE Insp Rept 70-0135/79-01 & 70-0364/79-02 on 790103-0202 Noncompliance noted failure to advise NRC of changes to internal control sys & failure to adhere to control procedures for SNM Details withheld (ref 10CFR2 790)
KUSHNER, W L Region 1, Philadelphia, Office of the Director.
JOYNER, J H Region 1, Philadelphia, Safeguards Branch 79/03/19 3pp

7909300583 Accepts encl proposed contingency plan to provide acceptable level of physical protection in event of strike, as discussed & agreed upon during MJ Defillippi 790423 visit Plan withheld (ref 10CFR2 790)
MCCORKLE, G W Physical Security Licensing Branch 79/04/26, 2pp

7909160116 Forwards Amend 1 to Indemnity Agreement G-1, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl.
BALTMAN, J Antitrust & Indemnity Group 79/05/01 5pp.

7909110205 Confirms 790501 telcon increasing liability limit to \$36 million for MAELU Policies MF-5, MF-B4 & MF-B5
ROBERTS, D Mutual Atomic Energy Liability Underwriters 79/05/02 1p.

7909290410 Forwards executed Amend 1 to Indemnity Agreement G-1.
LEWIS, J R Babcock & Wilcox Co, Nuclear Material Div 79/05/21 2pp

7909010080 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air"
ORIER, B. H. Region 1, Philadelphia, Office of the Director 79/03/28 1p.

DOCKET 70-0371 UNITED NUCLEAR CORP

7909290059 Forwards Naval Products Div training & qualification plan. Plan withheld (ref 10CFR2 790)
KIRK, W. F. United Nuclear Corp 79/02/13 2pp.

7909230798 Responds to 790303 request to use bolt type seal on drums for burial. Request referred to Ofc of Bids Development
PARTLOW, J O Material Control Licensing Branch. 79/04/09. 1p

7909240784 Responds to 790410 ltr requesting exemption from License Condition 3.1 & 10CFR70.58E. Administrative amend fee is required
WEISS, D. License Fee Management Branch. 79/04/17. 1p.

7909230850 Responds to 790330 ltr re fee for guard training & qualification plan. Purpose of review & approval of plan is to determine whether licensee meets requirements of regulations. Amend fee of \$8,300 is required.
MILLER, W O License Fee Management Branch. 79/05/08. 2pp.

DOCKET 70-0734 GENERAL ATOMIC CO

7909010234 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air"
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/03/28. 1p

7909100048 Ack receipt of 790330 ltr in response to 790308 notice of violation Corrective actions will be reviewed during next physical protection insp.
NORDERHAUD, L R Region 3, San Francisco, Safeguards Branch 79/04/03 1p

DOCKET 70-0754 VALLECITOS NUCLEAR CENTER, GENERAL ELECTRIC CO

7909230730 Forwards details of proposal to eliminate need for granting of exemptions re excess SNM holdings at facility Proposal withheld (ref 10CFR2 790)
MOSCHNER, R A General Electric Co., Nuclear Energy Products Div. 79/01/11. 2pp.

7909290062 Forwards security training & qualification plan. Plan withheld (ref 10CFR2 790)
CUNNINGHAM, G E General Electric Co., Nuclear Energy Products Div 79/02/16 2pp

7909010230 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air"
ENGELKEN, R H Region 3, San Francisco, Office of the Director 79/03/28 1p

7909250218 Forwards safeguards contingency plan, w/comments on revisions suggested in NRC 790207 ltr Plan & comments withheld (ref 10CFR2 790)
CUNNINGHAM, G E General Electric Co., Nuclear Energy Products Div 79/04/05. 2pp

7909300680 Responds to 790111 ltr Agrees w/concept of tailored fundamental nuclear matl control & accounting program for Advanced Fuel Lab Any request for mod to plants plan should include description of process equipment & flows
PARTLOW, J. O. Material Control Licensing Branch 79/04/23 1p

7909160181 Forwards Amend 1 to Indemnity Agreement G-4, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl
BALTMAN, J. Antitrust & Indemnity Group 79/05/01. 5pp

7909240230 Determines request for amend to License SNM-960 contains administrative changes requiring \$150 administrative fee.
WEISS, D License Fee Management Branch. 79/05/02. 1p.

7909150382 Amend 1 to Indemnity Agreement G-4.
BALTMAN, J Antitrust & Indemnity Group. DARMITZEL, R W General Electric Co 79/05/08 1p.

DOCKET 70-0820 United Nuclear Corp

7909150628 Forwards fuel recovery operation training & qualifications plan. Plan withheld (ref 10CFR2 790).
OIGLIGIT, R United Nuclear Corp. 79/01/13 2pp.

7909110029 Forwards IE Insp Repts 70-0820/79-05 & 70-2760/79-01 on 790205 No noncompliance noted.
MARTIN, W. O. Region 1, Philadelphia, Safeguards Branch 79/03/07 2pp

--7909110036 IE Insp Repts 70-0820/79-05 & 70-2760/79-01 on 790205 No noncompliance noted. Major areas inspected: export shipment of SNM.
SMITH, G. C., MCKEOWN, L. Region 1, Philadelphia, Office of the Director
JOYNER, J. H. Region 1, Philadelphia, Safeguards Branch. 79/03/02. 1p.

7909220032 Notifies that response to 790308 ltr re proposed vault mods is not expected until further advice from licensee.
MCCORKLE, G H Physical Security Licensing Branch. 79/03/14 1p.

7909250236 Forwards addl info in form of revised pages re const of recovery bay authorized by Amend 4 to License SNM-777. Info does not involve changes in process, bldg location or safety & environ controls. W/encl drawings.
BOWERS, C E United Nuclear Corp. 79/03/26. 7pp.

7909220047 Forwards fee for safeguards insp conducted on 790522-24 Payment is submitted under protest. Requests refund if decision is reversed.
SCHUTZ, D M. United Nuclear Corp. 79/04/06. 2pp.

DOCKETED ITEMS

276

7905280532 Requests exception to License Condition 9.3.20 for contractor vehicles to be used to transport excavated matl within protected area. Each vehicle to be escorted by armed guard outside area.
01010711, R J United Nuclear Corp. 79/04/09 1p

7905240084 Forwards revised pages of "United Nuclear Corp Recovery Sys. Fundamental Nuclear Matl Control Plan," in response to 790322 ltr Plan withheld (ref Atomic Energy Act of 1954 & Energy Reorganization Act of 1974)
BOWEN, C E. United Nuclear Corp 79/04/20 2pp

7905241008 Notifies that rept on safeguard contingency plan changes is withheld (ref Atomic Energy Act of 1954).
United Nuclear Corp 79/04/24 1p.

DOCKET 70-0824 BABCOCK & WILCOX CO.

7905160148 Forwards Amend 1 to Indemnity Agreement O-2, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7905110203 Confirms 790501 telcon increasing liability limit to \$36 million for MAELU Policies MF-3, MF-84 & MF-85.
ROBERTS, D. Mutual Atomic Energy Liability Underwriters 79/05/02 1p

7905240944 Notifies B&W of overpayment of license amend fee Refund will be sent
WEISS, D License Fee Management Branch. 79/05/03 1p

DOCKET 70-0984 PACIFIC NORTHWEST LAB

7905010225 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air."
ENOLKERN, R H Region 5, San Francisco, Office of the Director 79/03/28 1p

DOCKET 70-1007 GENERAL ELECTRIC CO

7905010230 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used as Source of Breathing Air."
ENOLKERN, R H Region 5, San Francisco, Office of the Director 79/03/28 1p

7905240588 Forwards "Annual Financial Rept 1978"
CUNNINGHAM, O C General Electric Co, Nuclear Energy Products Div 79/03/30 1p.

DOCKET 70-1086 WESTINGHOUSE ELECTRIC CORP

7905250307 Forwards "Semiannual Effluent Monitoring Rept," Jul-Dec 1978.
NARDI, A J Westinghouse Electric Corp. 79/03/02 1pp.

--7905250314 "Semiannual Effluent Monitoring Rept," Jul-Dec 1978
NARDI, A J Westinghouse Electric Corp. 79/03/02. 1p

DOCKET 70-1100 COMBUSTION ENGINEERING, INC

7905240269 Forwards emergency plan for low enriched U oxide fuel fabrication plant in Windsor, CT, in response to 790215 ltr.
LICHTENBERGER Combustion Engineering, Inc 79/04/10. 1p

--7905240276 Emergency plan for low enriched U oxide fuel fabrication plant in Windsor, CT w/780612 & 780614 ltrs.
Combustion Engineering, Inc 79/04/01. 35pp.

DOCKET 70-1113 GENERAL ELECTRIC CO.

7905140309 Forwards requested revisions to Wilmington Mfg Dept's emergency plan. Changes reflect use of protective equipment & supplies, notification of offsite agencies & restoration of plant to safe status
KAPLAN, A L. General Electric Co., Nuclear Energy Products Div. 79/04/04. 9pp

7905240600 Extends appreciation for guidance re reporting of proposed changes to fundamental nuclear matl control plans. Agrees w/NRC position re prompt submittal of plan changes
KAPLAN, A L. General Electric Co., Nuclear Energy Products Div. 79/04/04 1p

7905150791 Ack receipt of ltr reporting results of 790312-15 insp conducted by DH Jones at fuel fabrication plant
KAPLAN, A L General Electric Co 79/04/09 1p

7905070091 Ack receipt of IE Insp Rept 70-1113/79-10 on 790320 Nonproprietary info.
KAPLAN, A L General Electric Co, Nuclear Energy Products Div 79/04/18 1p

--7905070095 Forwards IE Insp Rept 70-1113/79-10 on 790320 Noncompliance noted
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/06 2pp

--7905070101 IE Insp Rept 70-1113/79-10 on 790320 Noncompliance noted
Major areas inspected determination of site boundary concentration due to unplanned release on 781203
TROUP, G L Region 2, Atlanta, Office of the Director
QIBSON, A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/06 3pp

7905240811 Ack receipt of results of 790326-30 insp conducted at fuel fabrication plant.
KAPLAN, A L General Electric Co, Nuclear Energy Products Div 79/04/18 1p

7905220025 Forwards revised version of App D to emergency plan re dose distance plots
KAPLAN, A L General Electric Co, Nuclear Energy Products Div 79/04/19 10pp

7905290082 Ack receipt of 790406 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1113/79-07
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/30 1p

--7905290087 Responds to NRC 790329 ltr re violations noted in IE Insp Rept 70-1113/79-07 Corrective actions new procedure implemented re posting of documents required by NRC
KAPLAN, A L. General Electric Co 79/04/06 2pp

J-7905290092 Forwards IE Insp Rept 70-1113/79-07 on 790226-0302 & notice of violation
SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 2pp

--7905290094 Notice of violation from insp on 790226-0302
Region 2, Atlanta, Office of the Director 79/03/29 1p

--7905290099 IE Insp Rept 79-1113/79-07 on 790226-0302 Noncompliance noted: failure to post responses to notice of violations
KAHLE, J B Region 2, Atlanta, Office of the Director
POTTER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 6pp

7905240222 Reviews 790321 ltr to OAO re record-keeping requirements found in 10CFR40.61. Records retained for five years unless part of investigation
PARTLOW, J O Material Control Licensing Branch 79/03/02 1p

DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP

7905240826 Forwards amend fee re safeguards contingency plan review
Submits fee under protest
DIPIAZZA, R P Westinghouse Electric Corp 79/01/30. 2pp

7905250286 Forwards Revision 6 to "Plan for Providing Physical Security at Cheswick Site" Revision withheld (ref 10CFR2 7901).
DIPIAZZA, R P Westinghouse Electric Corp 79/02/19 1p

7905010086 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Bvc Air Sys Used, as Source of Breathing Air."
ORIER, B H Region 1, Philadelphia, Office of the Director. 79/03/28 1p.

7905110072 Ack receipt of 790316 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-1143/79-01 & 30-6134/79-01.
SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 79/04/04 1p

--7905110077 Responds to NRC 790226 ltr re violations noted in IE Insp Repts 70-1143/79-02 & 30-6134/79-01 Corrective actions: more detailed sys of control has been instituted
MODRE, J S. Westinghouse Electric Corp 79/03/16 2pp.

DOCKETED ITEMS

--7905110102 Forwards IE Insp Repts 70-1143/79-02 & 30-6134/79-01 on 790123,24,31 & 0201 & notice of violation
SHITTH, Q H Region 1, Philadelphia, Fuel Facility & Materials
Safety Branch 79/02/26 2pp

--7905110105 Notice of violation from Insp on 790123,24,31 & 0201
SHITTH, Q H Region 1, Philadelphia, Fuel Facility & Materials
Safety Branch 79/02/26 1p

--7905110113 IE Insp Repts 70-1143/79-02 & 30-6134/79-01 on 790123,24,31
& 0201 Noncompliance noted failure to perform bioassay
analysis
CLEMONS, P, NIMITZ, R. L. Region 1, Philadelphia, Office of the
Director CROCKER, H. W. Region 1, Philadelphia, Fuel Facility &
Materials Safety Branch 79/02/21 11pp

7905160108 Forwards Amend 1 to Indemnity Agreement O-S, per 10CFR140
changes, re liability insurance increase from \$140 million to
\$160 million, effective 790501 Supporting documentation encl
BALTZMAN, J Antitrust & Indemnity Group. 79/03/01 3pp

7905110205 Confirms 790501 telcon increasing liability limit to
\$26 million for MAELU Policies MF-S, MF-B4 & MF-B5.
ROBERTS, D Mutual Atomic Energy Liability Underwriters 79/03/02
1p

DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP

7905230621 Requests license amend to accumulate contaminated low
enriched scrap w/uncertainty of greater than 10% for period
not to exceed Jul 1980. Contaminated scrap will be purified
through solvent extraction. Details withheld (ref 10CFR2 790)
DIPIAZZA, R. P Westinghouse Electric Corp 79/02/13 2pp

7905300712 Requests forwarded matl WRD-LS&S-66B be withheld from public
disclosure (ref 10CFR2 790)
DIPIAZZA, R. P Westinghouse Electric Corp 79/03/22 1p

7905140321 Clarifies issues discussed in recent telcon re request for
License SNM-1107 exemption from regulations, including
accumulation of scrap containers
FOSTER, H Westinghouse Electric Corp 79/03/23 1p

7905250474 Forwards revised Page 3 of 790322 submittal of proposed
solid waste fixation, transportation & burial info, in
response to 790323 telcon.
REITER, E. K Westinghouse Electric Corp 79/03/23 2pp

--7905250477 Forwards proposed solid waste fixation, transportation &
burial info describing operations at Columbia site
REITER, E. K Westinghouse Electric Corp. 79/03/22. 3pp

7905100419 Confirms 790327 telcon request for extension of next BNM
physical inventory from 790428 to 790519 Details reasons
for request
FOSTER, H. Westinghouse Electric Corp. 79/03/27 1p

7905240323 Forwards IE Insp Rept 70-1151/79-04 on 790226-28 No
noncompliance noted.
KENNA, W. B Region 2, Atlanta, Safeguards Branch. 79/03/27. 2pp.

--7905240336 IE Insp Rept 70-1151/79-04 on 790226-28 No noncompliance
noted Major areas inspected: export license, container
identification & documentation & radiation & contamination
monitoring
CLAY, E. L., GILLESPIE, F. P. Region 2, Atlanta, Office of the
Director. 79/03/27 4pp.

7905140313 Clarifies issues discussed in recent telcon re request for
License SNM-1107 exemption from regulations, including amount
of incinerated ash & contaminated scrap w/U content.
FOSTER, H. Westinghouse Electric Corp. 79/03/27, 1p.

7905240295 Forwards IE Insp Rept 70-1151/79-05 on 790319-21
No noncompliance noted.
KENNA, W. B Region 2, Atlanta, Safeguards Branch. 79/03/30. 2pp.

--7905240312 IE Insp Rept 70-1151/79-05 on 790319-21 No noncompliance
noted Major areas inspected: export license, shipping
procedures & techniques & radiation & contamination
monitoring.
CLAY, E. L., GILLESPIE, F. P. Region 2, Atlanta, Office of the
Director 79/03/30 4pp.

7905090190 Requests amend to License SNM-1107 authorizing operations
w/BNM in expansion of Columbia facility, per encl
application. Proprietary portion to be transmitted under
separate cover. Forwards fee, w/supporting documentation
DIPIAZZA, R. P. Westinghouse Electric Corp. 79/04/03. 33pp.

7905020187 Forwards application for amend to License SNM-1107 to
authorize operations w/BNM in expanded Columbia Facility
Replaces earlier submittal of 790305 Application withheld
(ref 10CFR2 790)
DIPIAZZA, R. P. Westinghouse Electric Corp. 79/04/04. 2pp

7905020146 Ack receipt of 790405 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 70-1151/79-03
KENNA, W. B Region 2, Atlanta, Safeguards Branch. 79/04/12 1p

--7905020150 Responds to NRC 790313 ltr re violations noted in IE Insp
Rept 70-1151/79-03 Corrective actions withheld
(ref 10CFR2 790)
GOODWIN, W. L. Westinghouse Electric Corp. 79/04/05 1p

--7905020156 Forwards IE Insp Rept 70-1151/79-03 on 790206-09 Notice
of violation withheld (ref 10CFR2 790)
KENNA, W. B Region 2, Atlanta, Safeguards Branch 79/03/13
2pp

7905020161 IE Insp Rept 70-1171/79-03 on 790206-09 Noncompliance
noted failure to follow approved plan for sampling U oxide
pellets Details withheld (ref 10CFR2 790)
BATES, J. W., ROBERTSON, J. B., WILLIAMS, O. H. Region 2, Atlanta,
Office of the Director 79/03/13 1p

7905070269 Forwards IE Insp Rept 70-1151/79-07 on 790409-12 No
noncompliance noted.
KENNA, W. B Region 2, Atlanta, Safeguards Branch. 79/04/23 1p

--7905070283 IE Insp Rept 70-1151/79-07 on 790409-12 No noncompliance
noted Major areas inspected onsite records & repts. Details
withheld (ref 10CFR2 790)
GILLESPIE, F. P. Region 2, Atlanta, Safeguards Branch
HODGES, J. W. Region 2, Atlanta, Office of the Director
79/04/18 1p

7905230852 Formalizes 790417 discussion re current LEID model
Westinghouse-Columbia model needs to be modified to ensure
proper treatment of systematic errors
PARTLOW, J. O Material Control Licensing Branch. 79/03/08 1p

DOCKET 70-1173 MERCYHURST COLLEGE

7905300051 Ack receipt of 790427 ltr identifying inaccurate amend
numbers in NRC 790409 ltr Forwards corrected pages. Encl
withheld (ref 10CFR2 790).
MCCORMACK, O. W. Physical Security Licensing Branch. 79/05/07.
2pp

DOCKET 70-1193 CIMARRON FACILITY, KERR-MCGEE CORP.

7905010197 Forwards IE Info Notice 79-08, "Interconnection of
Contaminated Sys w/Bvc Air Sys Used as Source of Breathing
Air"
KEPPLER, J. O Region 3, Chicago, Office of the Director. 79/03/26.
1p.

7905230736 Cancels Amend MPP-2 & issues encl safeguards Amend MPP-3 for
License SNM-1174
BURNETT, R. F. Division of Safeguards. 79/04/09. 2pp.

--7905230771 Amend MPP-3 to License SNM-1174 re requirements for control,
accounting & physical security of BNM.
* Division of Safeguards. 79/03/31. 11pp

7905240139 Responds to 781129 ltr re dismantling & removal of solvent
extraction sys. Forwards license Amend 3. Comments on
deletions & revisions to license which were rendered
obsolete by change in operation.
BURNETT, R. F. Division of Safeguards. 79/04/09 2pp.

--7905240146 Amend 3 to License SNM-1174, requiring measurement of U, Pu &
U-235 content of BNM receipt, shipments & matl inventoried,
except where specified in Condition 2.1.
* Division of Safeguards. 79/03/31. 11pp.

DOCKET 70-1201 UF & CONVERSION FACILITY, BABCOCK & WILCOX CO

7905130112 Forwards IE Insp Rept 70-1201/79-09 on 790327-30 No
noncompliance noted.
KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 79/04/13. 2pp

DOCKETED ITEMS

277

--7905150116 IE Insp Rept 70-1201/79-09 on 790327-30 No noncompliance noted Major areas inspected licenses action on previously identified items & measurements & statistical control Details withheld (ref 10CFR2 790)
JONES, D W, WILKINS, T. D. Region 2, Atlanta, Office of the Director
GILLESPIE, F P Region 2, Atlanta, Safeguards Branch
79/04/09 1p

7905070240 Ack receipt of 790412 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1201/79-06.
KENNA, W B Region 2, Atlanta, Safeguards Branch. 79/04/20 1p

--7905070243 Responds to NRC 790326 ltr re violations noted in IE Insp Rept 70-1201/79-06 Corrective actions withheld (ref 10CFR2 790).
SILK, E J Babcock & Wilcox Co 79/04/12 1p

--7905070252 Forwards IE Insp Rept 70-1201/79-06 on 790226-0301 Notice of violation withheld (ref 10CFR2 790)
KENNA, W B Region 2, Atlanta, Safeguards Branch. 79/03/26 2pp

--7905070259 IE Insp Rept 70-1201/79-06 on 790226-0301 Noncompliance noted. Failure to determine measurement bias from stds program Details withheld (ref 10CFR2 790)
WILLIAMS, O H, ROBERTSON, J S C Region 2, Atlanta, Safeguards Branch 79/03/22 1p

7905300016 Forwards IE Insp Rept 70-1201/79-11 on 790419-20 No noncompliance noted
KENNA, W B Region 2, Atlanta, Safeguards Branch 79/03/02 2pp

--7905300021 IE Insp Rept 70-1201/79-11 on 790419-20 No noncompliance noted. Major areas inspected storage & internal control & followup on previous enforcement matters Details withheld (ref 10CFR2 790)
YODD, G. A Region 2, Atlanta, Office of the Director
GILLESPIE, F P Region 2, Atlanta, Safeguards Branch 79/03/01 1p.

7905230184 Proposes adding new license conditions to Amend MPP-2 to allow for procedures in fundamental nuclear matl control plan contrary to ltr of regulation. Requests response as to acceptability of amend
PARTLOW, J O Material Control Licensing Branch 79/03/08 3pp.

DOCKET 70-1257 MIXED OXIDE FABRICATION PLANT, EXXON NUCLEAR CO, INC

7905150686 Forwards IE Insp Rept 70-1257/79-01 on 790212-16 No noncompliance noted
BOOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/03/16 2pp

--7905150701 IE Insp Rept 70-1257/79-01 on 790212-16 No noncompliance noted. Major areas inspected safety committee activities, training, calibr, criticality safety, emergency planning & fire & radiation protection
COOLEY, W J, ZURAKAWSKI, P. R. Region 5, San Francisco, Office of the Director
BOOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/03/16 11pp.

7905010228 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air."
ENGELKEN, R. H Region 5, San Francisco, Office of the Director
79/03/28, 1p.

7905150289 Forwards IE Insp Rept 70-1237/79-02 on 790326-31 Rept withheld (ref 10CFR2 790).
NORDERHAUG, L. R. Region 5, San Francisco, Safeguards Branch.
79/04/24 2pp

7905160123 Forwards Amend 1 to Indemnity Agreement O-3, per 10CFR140 changes, re liability insurance from increase from \$140 million to \$160 million, effective 790301. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group 79/03/01, 5pp

DOCKET 70-1308 MORRIS OPERATIONS, GENERAL ELECTRIC CO.

7905140305 Forwards table indicating no status change for fuel stored in Jan & Feb 1979
DAWSON, D M General Electric Co, Nuclear Energy Products Div.
79/03/08, 2pp.

7905230437 Forwards IE Insp Rept 70-1308/79-02 on 790228, 0301-02 & 07. No noncompliance noted.
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/03/26, 2pp.

--7905230442 IE Insp Rept 70-1308/79-02 on 790228, 0301-02 & 07. No noncompliance noted Major areas inspected emergency planning & fire protection
AXELSON, W L, EBBIG, T. H Region 3, Chicago, Office of the Director 79/03/21, 9pp

7905100426 Forwards responses to NRC 790301 ltr re decommissioning plan for Morris Operation
DAWSON, D M General Electric Co, Nuclear Energy Products Div.
79/04/04 4pp

7905240370 Forwards Amend 7 to License BNM-1265 BNM-1281 is terminated
ROUSE, L C Fuel Reprocess & Recycle Branch 79/04/10, 2pp

--7905240383 Amend 7 to License BNM-1265, terminating License BNM-1281 & incorporating operation specs of consolidated SAR Chapter 10
ROUSE, L. C. Fuel Reprocess & Recycle Branch. 79/04/10 2pp.

7905130297 Ack receipt of 790404 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 79-1308/79-01 Details withheld (ref 10CFR2 790)
HIND, J. A Region 3, Chicago, Safeguards Branch 79/04/20 2pp

--7905150301 Responds to NRC 790316 ltr re violations noted in IE Insp Rept 70-1308/79-01 Corrective actions withheld (ref 10CFR2 790)
ZAHN, L. L General Electric Co, Nuclear Energy Products Div.
79/04/04 1p

7905150744 Forwards IE Insp Repts 70-1308/79-04 & 70-1309/79-01 on 790410-12 No noncompliance noted
HIND, J. A Region 3, Chicago, Safeguards Branch 79/04/26 2pp

--7905150754 IE Insp Repts 70-1308/79-04 & 70-1309/79-01 on 790410-12 No noncompliance noted Major areas inspected review of BNM records, Pu-241 decay calculations & nuclear matl transaction Details withheld (ref 10CFR2 790)
FINLEY, A O, PATTERSON, J P Region 3, Chicago, Office of the Director
HIND, J. A Region 3, Chicago, Safeguards Branch 79/04/26 1p

DOCKET 70-1309 MORRIS OPERATIONS, SOURCES & STANDARDS, GENERAL

7905240370 Forwards Amend 7 to License BNM-1265 BNM-1281 is terminated
ROUSE, L C Fuel Reprocess & Recycle Branch. 79/04/10, 2pp

--7905240383 Amend 7 to License BNM-1265, terminating License BNM-1281 & incorporating operation specs of consolidated SAR Chapter 10
ROUSE, L C Fuel Reprocess & Recycle Branch 79/04/10, 2pp

7905150744 Forwards IE Insp Repts 70-1308/79-04 & 70-1309/79-01 on 790410-12 No noncompliance noted.
HIND, J. A, Region 3, Chicago, Safeguards Branch 79/04/26, 2pp

--7905150754 IE Insp Repts 70-1308/79-04 & 70-1309/79-01 on 790410-12 No noncompliance noted Major areas inspected: review of BNM records, Pu-241 decay calculations & nuclear matl transaction Details withheld (ref 10CFR2 790)
FINLEY, A O, PATTERSON, J P Region 3, Chicago, Office of the Director
HIND, J. A Region 3, Chicago, Safeguards Branch. 79/04/26 1p

DOCKET 70 ---

790511002
STUKENE

790522005
ML Nucl
radiat
license
CUNNING
79/04/

DOCKET 7

79052400
survey
decont
CROW, W

DOCKETED ITEMS

DOCKET 70-1355 ARMY, DEPT OF

7905100374 IE Insp Findings & Licenses Act, dtd 790306, of Licenses 29-01022-08, 29-01022-11, 29-01022-12, SUB-1150, 6MB-1327 & SNM-1327 Insp findings no noncompliance noted
FRIEDMAN, L F Region 1, Philadelphia, Office of the Director
79/03/06 1p

DOCKET 70-1379 PARKHILL LABORATORIES, INC

7905290183 Forwards guidelines & info re decontamination of facilities & radiation surveys, per 790312 telcon Requests
implementation schedule within two weeks
KEPLER, J O Region 3, Chicago, Office of the Director 79/03/14
9pp

7905150635 Forwards IE Insp Rept 70-1379/79-01 on 790301 & notice of violation
DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/03/27 2pp

--7905150640 Notice of violation from insp on 790301
& Region 3, Chicago, Fuel Facility & Materials Safety Branch
79/03/19 1p.

--7905150646 IE Insp Rept 79-1379/79-01 on 790301 Noncompliance noted
possession of licensed matl w/o license
FINN, J A, JANUSKA, A O, PAGLIARD, J A Region 3, Chicago, Office
of the Director. 79/03/19. 7pp.

DOCKET 70-1821 PLUT. PROD FACIL., ALLIED GENERAL NUCLEAR SERVICES CORP

7905150660 Responds to 790206 ltr requesting refund of application
fee paid by Allied-General Nuclear Svcs in Jan 1975 for
proposed Pu product facility Will notify re refund request
upon collection of complete cost data
DONOHUE, D J. Office of Administration. 79/04/11 1p

--7905150663 Requests refund to Allied-General Nuclear Svcs for
application fee paid to NRC on 750124 for Pu product
facility Application withdrawn due to suspension of design
work
BOSKEY, B. Volpe, Boskey & Lyons 79/04/11. 4pp.

--7905150669 Forwards questions re initial review of 740703 application
to construct Pu product facility
ROUSE, L C Atomic Energy Commission (Pre 1975) 74/12/10. 2pp.

--7905150674 Forwards Category 1 B fee for Pu processing & fabrication
plants
NEWMAN, R I Allied General Nuclear Services 75/01/24 3pp

--7905150679 Ack receipt of 750115 ltr re status of const at Pu
processing & fabrication plant Discusses problems of license
review, design & const resulting from GESMO & safeguards
studies, Requests meeting
GOBBICK, L V. Office of the Executive Director for Operations.
75/02/03 2pp.

--7905150683 Notifies of suspension of design work for Pu product
facility.
PRICE, W J. Allied General Nuclear Services. 75/01/15 4pp.

DOCKET 70-2428 ST FRANCIS GENERAL HOSP. PI, PENNSYLVANIA

7905150727 Discusses IE Insp of License SNM-1689 on 790205 No
noncompliance noted, License is inactive & licensed matl has
never been used under authorization of license
MCCLINTOCK, R O Region 1, Philadelphia, Office of the Director.
79/02/26. 1p.

DOCKET 70-2623 MCQUIRE SPENT FUEL POOL, DUKE POWER CO.

7905110040 Applicant serves interrogatories & requests to produce
documents on Carolina Action, per 790223 order, Certificate
of Svc encl.
MCQUARRY, J M Duke Power Co. 79/03/16. 33pp

7905090438 NRC second set of interrogatories served on Safe Energy
Alliance, Certificate of Svc encl
HOEFLING, R K. Branch 4 79/03/23. 9pp.

7905090440 Requests that Safe Energy Alliance permit insp &
copying of documents identified in responses to NRC second
set of interrogatories Certificate of Svc encl.
HOEFLING, R K. Branch 4. 79/03/23. 3pp.

7905230766 First set of interrogatories submitted to NRDC Certificate
of Svc encl
HOEFLING, R K Branch 4 79/03/23 13pp.

--7905230775 Requests production of all documents identified by NRDC in
response to NRC first of interrogatories
HOEFLING, R K Branch 4 79/03/23 1p

7905110037 Applicant's response to NRDC interrogatories to applicant
Supporting documentation & Certificate of Svc encl
MCQUARRY, J M Duke Power Co 79/03/27 22pp

7905090164 Requests ltr either withdrawing 790213 original security
plan submittal or ack it for record as original plan
ROUSE, L C Fuel Reprocess. & Recycle Branch. 79/03/29 2pp

7905240317 Forwards statements of qualifications of DH Storratt, SB
Hager, HT Sneed & RW Bostian as experts intending to testify
for applicant in answer to NRDC interrogatories
MCQUARRY, J M Debevoise & Lieberman 79/03/30 7pp

7905150440 Motion to dismiss Safe Energy Alliance as active participant
in proceeding, due to Alliance's failure to comply w/ASLB
790223 order Certificate of Svc encl.
MCQUARRY, J M Duke Power Co. 79/04/02 5pp.

7905240482 Serves NRC request for admission of matters & facts upon
applicant, Certificate of Svc encl.
ROISMAN, A Z Natural Resources Defense Council. 79/04/02 7pp.

7905030103 NRC motion to compel Carolina Environ Study Group to respond
to 790306 interrogatories Supporting brief, proposed form,
original interrogatories & Certificate of Svc encl
KETCHEN, E O Branch 3 79/04/05 14pp

--7905030116 NRC motion to compel Carolina Action to respond to 790306
interrogatories, Supporting brief, proposed form of order,
original interrogatories & Certificate of Svc encl.
KETCHEN, E O Branch 3 79/04/05 14pp.

--7905030120 NRC motion to compel Davidson College chapter of NC Public
Interest Group to respond to 790306 interrogatories
Supporting brief, proposed form of order, original
interrogatories & Certificate of Svc encl.
KETCHEN, E O Branch 3 79/04/05 16pp

7905030132 Describes event re packaging to be used by Util for shipment
of spent fuel, Defect may substantially decrease
effectiveness of packaging Certificate of Svc encl.
CUNNINGHAM, R E. Division of Fuel Cycle & Material Safety
79/04/11. 4pp

--7905030152 Forwards NMSS 790406 order re use of Model NFB-4 packaging
DIRCKS, W J. Office of Nuclear Material Safety & Safeguards.
79/04/06 2pp

7905090138 Forwards request for addl info re proposed amend of License
SNM-1773 to ship spent fuel from Oconee to McQuire, Requests
response by 790423
ROUSE, L C. Fuel Reprocess. & Recycle Branch. 79/04/12 3pp.

7905220048 Dismisses Safe Energy Alliance as party intervenor.
MILLER, M E Atomic Safety and Licensing Board Panel 79/04/12
2pp.

7905230666 Orders intervenors Carolina Environ Study Group, NC PIRG
chapter & Carolina Action to interrogatories within five
days, Adopts schedule to govern summary disposition,
discovery, direct testimony & evidentiary hearing
MILLER, M E Atomic Safety and Licensing Board Panel. 79/04/12
3pp.

7905220463 Forwards modified interim security plan for fuel storage
bldg & interim safeguards contingency plan, Plans withheld
(ref 10CFR2.790).
PARKER, W O Duke Power Co 79/04/12. 3pp.

7905140079 Responds to util's interrogatories, Affidavits of TB Cochran
HR Tamplin & AZ Roisman & Certificate of Svc encl.
COCHRAN, T B, TAMPLIN, A R., ROISMAN, A Z. Natural Resources Defense
Council 79/04/16. 32pp.

7905240921 Requests notification of any addl witnesses to be included
in proceedings.
PORTER, W L. Duke Power Co. 79/04/19. 1p.

7905240938 Confirms 790312 telcon re vital areas during storage of
spent fuel, Irradiated fuel must be protected as vital
equipment.
MCCORKLE, O W. Physical Security Licensing Branch. 79/04/20. 1p.

DOCKETED ITEMS

271

7905290679 Second set of interrogatories submitted to applicant
ROBMAN, A. Z. Natural Resources Defense Council 79/04/23 9pp

7905240470 Motion for order to dismiss Carolina Action as active
participant in proceeding due to failure to provide answers
to applicant's interrogatories of 790316 Certificate of Svc
encl
MCARRY, J M Duke Power Co 79/05/03 5pp.

DOCKET 70-2753 HOLYOKE HOSP HQ, MASSACHUSETTS

7905290106 Ack receipt of 790323 ltr informing NRC of steps taken to
correct deviation noted in IE Insp Repts 30-1873/79-01 &
70-2753/79-01
MCCLINTOCK, R O Region 1, Philadelphia, Office of the Director
79/04/03 1p

--7905290161 Responds to NRC 790305 ltr re deviation noted in IE Insp
Rept 30-1873/79-01 & 70-2753/79-01 Corrective actions no
food or drinks allowed in areas where radioactive mats are
used or stored.
HAYWARD, J Holyoke Hosp HQ, Massachusetts 79/03/23 1p

--7905290163 Discusses IE Insp Rept 30-1873/79-01 & 70-2753/79-01 on
790216 Noncompliance noted drink permitted to be stored in
same area where radioactive matl stored.
MCCLINTOCK, R O Region 1, Philadelphia, Office of the Director
79/03/03 2pp.

DOCKET 70-2760 UNITED NUCLEAR CORP.

7905110029 Forwards IE Insp Repts 70-0820/79-05 & 70-2760/79-01 on
790205. No noncompliance noted
MARTIN, H O Region 1, Philadelphia, Safeguards Branch 79/03/07
2pp.

--7905110036 IE Insp Repts 70-0820/79-05 & 70-2760/79-01 on 790205 No
noncompliance noted. Major areas inspected. export shipment
of BNH
BHETH, O G, MCKEON, L Region 1, Philadelphia, Office of the
Director JOYNER, J H Region 1, Philadelphia, Safeguards
Branch. 79/03/02 1p

DOCKET 70-2838 CINCINNATI GAS & ELECTRIC CO.

7905240100 Amends License BNH-1023 Items 4 & 9 re expiration date &
add Items 6c, 8c & 14.
CROW, H. T. Division of Safeguards 79/03/06 2pp.

--7905240108 Recommends approval of 790202 amend request re license
expiration date change to allow use of nominal 5 Ci
Pu-Beryllium neutron source.
DELAHEY, J. C Division of Safeguards 79/03/06 2pp

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0001 ANEFCO, INC

7905170270 Forwards request for addl info to complete review of QA
program
MACDONALD, C. E. Transportation Branch. 79/03/29 1p.

7905290146 Forwards revised QA program for shipping packages for
radioactive matl
MURPHY, J. D Anefco, Inc. 79/03/03 1p

--7905290148 QA program for shipping packages for radioactive matl.
MURPHY, J. D Anefco, Inc. 79/03/01 2pp.

DOCKET 71-0002 CHEM-NUCLEAR SYSTEMS, INC.

7905240041 Forwards request for addl info to complete review of QA
program.
MACDONALD, C. E. Transportation Branch. 79/04/27 13pp

DOCKET 71-0006 UNITED NUCLEAR CORP.

7905020185 Forwards request for addl info to complete review of QA
program.
MACDONALD, C. E. Transportation Branch. 79/04/11 12pp.

DOCKET 71-0008 COMMONWEALTH EDISON CO

7905150076 Responds to NRC 790319 request by revising application for
approval of program to meet requirements of 10CFR71.31
"QA Program for Nuclear Generating Stations." CE-1-A
Revision 6, fulfills QA requirements
REED, C Commonwealth Edison Co 79/04/16 2pp

7905240847 Forwards QA program approval for radioactive matl package
MACDONALD, C E Transportation Branch 79/05/01 1p

--7905240854 QA program approval for radioactive matl package 00008
Revision 0
MACDONALD, C E Transportation Branch 79/03/01 1p

DOCKET 71-0024 HITTMAN NUCLEAR & DEVELOPMENT CORP

7905240046 Forwards request for addl info to complete review of QA
program
MACDONALD, C E Transportation Branch 79/04/27 13pp

DOCKET 71-0031 MARYLAND SHIPBUILDING & DRY DOCK CO

7905150149 Proposed QA program does not meet requirements of App E to
10CFR71 Forwards sample QA program for industrial
radiography licenses, dtd 790402, to assist in application
revision. Requests revision by 790527
MACDONALD, C E Transportation Branch 79/04/27 3pp

DOCKET 71-0033 IND TEST LAB SERVICES CORP

7905150268 Forwards "QA Program for Use, Maint & Repair of Shipping
Packages for Special Form Radioactive Matl." Revision 1
HANDRAHAN, E Industrial Testing Laboratory Services Corp 79/04/16
1p

--7905150274 "QA Program for Use Maint & Repair of Shipping Packages for
Special Form Radioactive Matl." Revision 1
HANDRAHAN, E Industrial Testing Laboratory Services Corp
79/04/16 5pp

DOCKET 71-0034 BABCOCK & WILCOX CO

7905020198 Forwards request for addl info to complete review of QA
program
MACDONALD, C E Transportation Branch 79/04/13 2pp

DOCKET 71-0036 ITT GRINNELL CORP

7905080128 Forwards QA program, in response to 790321 request for addl
info.
THIELSCH, H International Telephone & Telegraph Corp 79/04/04
2pp.

--7905080134 "QA Program Radioactive Matl Shipping Packages"
* International Telephone & Telegraph Corp 79/04/02 6pp

DOCKET 71-0038 CRANE CO

7905150329 Forwards QA program approval for radioactive matl package
MACDONALD, C E Transportation Branch 79/03/22 1p

--7905150333 QA program approval for radioactive matl package 0008,
Revision 0
MACDONALD, C E Transportation Branch 79/03/22 1p

DOCKET 71-0039 WALWORTH CO.

7905240140 Proposed QA program does not meet requirements of App E to
10CFR71 Forwards sample QA program for industrial
radiography licenses, dtd 790402, to assist in application
revision. Requests revision by 790502
MACDONALD, C E Transportation Branch 79/04/27 3pp

DOCKETED ITEMS

DOCKET 71-0047 CAPITOL INTERNATIONAL AIRWAYS, INC

7905190739 Forwards request for addl info to complete review of GA program
MACDONALD, C E Transportation Branch 79/04/13 2pp

7905190692 Forwards GA requirements for transportation packaging, in response to 790426 telcon
SPARKS, E Capitol International Airways, Inc. 79/04/27 1p

--7905190699 "GA Requirements for Transportation Packaging (10CFR71) As Applicable to Industrial Radiography Licenses"
* Capitol International Airways, Inc 79/04/27. 6pp

DOCKET 71-0048 INTERMOUNTAIN PIPE & WELDING

7905190176 Proposed GA program does not meet requirements of App E to 10CFR71. Forwards sample GA program for industrial radiography licenses, dtd 790402, to assist in application revision. Requests revision by 790527
MACDONALD, C E Transportation Branch 79/04/27. 3pp

DOCKET 71-0050 MIDLAND-ROSS CORP

7905190318 Forwards GA program approval for radioactive matl package
MACDONALD, C E Transportation Branch 79/03/22 1p

--7905190323 GA program approval for radioactive matl package 0050, Revision 0
MACDONALD, C E Transportation Branch 79/03/22 1p.

DOCKET 71-0055 H R INSPECTION SERVICE

7905240904 Forwards addl info for approval of GA program
ROGERS, H W H R Inspection Service 79/03/02. 2pp

DOCKET 71-0056 PHILADELPHIA ELECTRIC CO

7905240184 Informs that Amend 35 to FSAR contains existing GA program, in response to NRC 790321 request.
DALTROFF, S L Philadelphia Electric Co 79/04/10 1p

DOCKET 71-0057 EXXON CO USA, EXXON CORP.

7905300658 Forwards Radiation Safety Committee organizational chart, in response to NRC 790413 ltr.
WEILAND, R W Exxon Corp 79/04/20 2pp

DOCKET 71-0063 OZARK AIRLINES, INC.

7905190682 Forwards request for addl info to complete review of GA program. Requests statement that scope of audit program will include annual audit re personnel training, personnel qualifications & record keeping.
MACDONALD, C E Transportation Branch 79/04/13 2pp

7905190084 Forwards GA Program for License 24-13591-01.
YOUNG, R E Ozark Airlines 79/04/23 1p

--7905190094 GA Program for License 24-13591-01.
* Ozark Airlines. 79/04/23. 4pp.

DOCKET 71-0065 H.F. & ASSOCIATES, INC

7905240382 Proposed GA program does not meet requirements of App E to 10CFR71. Forwards sample GA program for industrial radiography licenses, dtd 790402, to assist in application revision. Requests revision by 790502.
MACDONALD, C E Transportation Branch. 79/04/27. 3pp.

DOCKET 71-0066 CERTIFIED TESTING LABS, INC.

7905190160 Proposed GA program does not meet requirements of App E to 10CFR71. Forwards sample GA program for industrial radiography licenses, dtd 790402, to assist in application revision. Requests revision by 790427
MACDONALD, C E Transportation Branch. 79/04/27. 3pp.

DOCKET 71-0068 YANKEE ATOMIC ELECTRIC CO

7905240311 Forwards GA program approval for radioactive matl package
MACDONALD, C E Transportation Branch 79/03/04 1p

--7905240318 GA program approval for radioactive matl package 0068, Revision 0
MACDONALD, C E Transportation Branch 79/03/04 1p

DOCKET 71-0070 GENERAL MOTORS CORP

7905240365 Informs that proposed GA program does not meet requirements of App E to 10CFR71. Forwards sample GA program for industrial radiography licenses, dtd 790402, to assist in application revision. Requests revision by 790520
MACDONALD, C E Transportation Branch 79/04/20 1p.

--7905240369 "GA Program for Industrial Radiography Licenses"
* Transportation Branch 79/04/02 2pp

DOCKET 71-0072 BABCOCK & WILCOX CO

7905110069 Proposed GA program does not meet requirements of App E to 10CFR71. Forwards sample GA program for industrial radiography licenses, dtd 790402, to assist in application revision. Requests revision by 790502
MACDONALD, C E Transportation Branch. 79/04/27 3pp

DOCKET 71-0074 NUCLEAR WELDING, INC

7905110071 Proposed GA program does not meet requirements of App E to 10CFR71. Forwards sample GA program for industrial radiography licenses, dtd 790402, to assist in application revision. Requests revision by 790502
MACDONALD, C E Transportation Branch 79/04/27. 3pp

DOCKET 71-0077 MIDSTATE TESTING LAB

7905020255 Forwards GA Program for License 13-11822-01
KEILMAN, T J Midstate Testing Laboratory, Inc. 79/04/03 1p.

--7905020259 GA Program for License 13-11822-01
KEILMAN, T J Midstate Testing Laboratory, Inc. 79/04/03 4pp.

7905240165 Forwards request for addl info to complete review of GA program
MACDONALD, C E Transportation Branch 79/04/27 2pp

DOCKET 71-0087 NAVY, DEPT. OF

7905110204 Proposed GA program does not meet requirements of App E to 10CFR71. Forwards sample GA program for industrial radiography licenses, dtd 790402, to assist in application revision. Requests revision by 790520.
MACDONALD, C E Transportation Branch. 79/04/20 3pp.

DOCKET 71-0088 BABCOCK & WILCOX CO

7905020407 Forwards request for addl info to complete review of GA program.
MACDONALD, C E Transportation Branch. 79/04/11 12pp

DOCKET 71-0089 NAVY, DEPT. OF

7905070267 Forwards request for addl info to complete review of GA program
MACDONALD, C E Transportation Branch 79/04/13 2pp.

DOCKET 71-0090 COMBUSTION ENGINEERING CO., INC

7905250013 Responds to request for addl info re GA program. Will continue to use existing GA program until approval of GA Program CENFH-WH is obtained. Supporting documentation encl
LICHTENBERGER, H Combustion Engineering, Inc. 79/04/11. 4pp.

DOCKETED ITEMS

281

DOCKET 71-0099 FOSTER WHEELER ENERGY CORP

7903070272 Forwards request for addl info to complete review of GA program
MACDONALD, C E Transportation Branch 79/04/13 2pp

DOCKET 71-0103 TWIN CITY TESTING & ENGR LAB

7903070279 Forwards request for addl info to complete review of GA program
MACDONALD, C E Transportation Branch 79/04/13 2pp

DOCKET 71-0104 CHICAGO BRIDGE & IRON CO

7903070292 Forwards request for addl info to complete review of GA program
MACDONALD, C E Transportation Branch 79/04/13 2pp

7903290311 Forwards GA program for License 12-05639-01
HEHRLE, R R Chicago Bridge & Iron Co 79/04/18 2pp

--7903290314 GA program for License 12-05639-01.
* Chicago Bridge & Iron Co 79/04/18 4pp

DOCKET 71-0109 UNION CARBIDE CORP

7903241000 Forwards request for addl info to complete review of GA program
MACDONALD, C E Transportation Branch 79/04/20 12pp.

DOCKET 71-0110 BUCKEYE STEEL CASTINGS

7904200311 Forwards request for addl info to complete review of GA program
MACDONALD, C E Transportation Branch 79/04/06 2pp.

7903240616 Forwards GA program for industrial radiography re handling & shipping of isotopes
KRAMER, J F Buckeye International, Inc., Steel Castings Div.
79/04/27 3pp

--7903240713 GA program for industrial radiography
* Buckeye International, Inc., Steel Castings Div. 79/04/27.
4pp

DOCKET 71-0111 MATERIAL TESTING LAB. OF VIRGINIA, INC.

7903110075 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790302
MACDONALD, C E Transportation Branch. 79/04/27. 4pp

DOCKET 71-0116 NAVY, DEPT. OF

7903110210 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790302
MACDONALD Transportation Branch 79/04/20 3pp

DOCKET 71-0119 INGERSOLL-RAND CO.

7903070237 Forwards request for addl info to complete review of GA program
MACDONALD, C E Transportation Branch. 79/04/13. 2pp

DOCKET 71-0120 DANIEL INTERNATIONAL CORP.

7903110078 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees, dtd 790402, to assist in application revision Request revision by 790302.
MACDONALD, C E. Transportation Branch. 79/04/27 3pp.

DOCKET 71-0121 NEUTRON PRODUCTS, INC

7903240156 Forwards request for addl info to complete review of GA program
MACDONALD, C E Transportation Branch 79/04/27 12pp

DOCKET 71-0126 STANWICK CORP

7903150742 Forwards request for addl info to complete review of GA program
MACDONALD, C E Transportation Branch 79/04/13 2pp

DOCKET 71-0127 NATIONAL ANNEALING BOX CO

7903070282 Forwards request for addl info to complete review of GA program
MACDONALD, C E Transportation Branch 79/04/13 2pp.

7903100104 Forwards organizational chart requested by NRC 790413 ltr.
FRANTZ, J.R National Annealing Box Co 79/04/16 2pp

DOCKET 71-0128 AMSCO OIL CO

7903110081 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790302
MACDONALD, C E Transportation Branch 79/04/27 3pp

DOCKET 71-0130 CHICAGO BRIDGE & IRON CO

7903070287 Forwards request for addl info to complete review of GA program
MACDONALD, C E Transportation Branch 79/04/13 2pp

DOCKET 71-0131 WELDING INSTITUTE OF ALASKA

7903140119 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790302
MACDONALD, C E Transportation Branch 79/04/27 3pp.

DOCKET 71-0137 METALS TESTING CO, INC.

7903150078 Forwards "Shipping Container GA Requirements."
DELIBLE, R. Metals Testing Co., Inc 79/04/16. 1p.

--7903150088 "Shipping Container GA Requirements"
* Metals Testing Co., Inc 79/04/16 6pp.

DOCKET 71-0141 ROCKWELL INTERNATIONAL

7903110084 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790302.
MACDONALD, C E Transportation Branch 79/04/27 3pp.

DOCKET 71-0143 RANCHERS EXPLORATION & DEV. CO

7903240161 Forwards request for addl info to complete review of GA program
MACDONALD, C E. Transportation Branch. 79/04/27. 3pp.

DOCKETED ITEMS

DOCKET 71-0151 HESS OIL VIRGIN ISLANDS CORP

7905150265 Responds to request for addl info re GA program Discusses organization, document control, handling, storage & shipping, insp. records & audits
 PHELAN, M K Hess Oil Virgin Islands Corp 79/04/16 6pp

DOCKET 71-0154 GENERAL DYNAMICS

7905290916 Informs that term "radiation safety officer" has been replaced w/ "radiation protection officer" for License 20-11915-01
 ROBERTS, V M General Dynamics Corp, Quincy Shipbuilding Div 79/04/16 1p

DOCKET 71-0156 INDUSTRIAL FABRICATING CO

7905110063 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licenses, dtd 790402, to assist in application revision Requests revision by 790502
 MACDONALD, C E Transportation Branch 79/04/27 3pp

DOCKET 71-0158 X-RAY INDUSTRIES, INC

7905240285 Forwards info to clarify GA program for License 21-03472-01, in response to 790413 ltr
 THAMM, R W X-Ray, Inc 79/04/24 2pp

DOCKET 71-0161 CURTISS-WRIGHT CORP

7905230354 Responds to NRC 790406 ltr re radioactive sealed source shipping procedure Forwards revised GA program
 JACKSON, C Curtiss-Wright Corp 79/05/01 1p

--7905230366 Revised GA program
 JACKSON, C Curtiss-Wright Corp. 79/05/01. 4pp.

DOCKET 71-0162 EBABCO SERVICES, INC

7905010185 Forwards request for addl info to complete review of GA program
 MACDONALD, C E Transportation Branch 79/04/13 2pp

DOCKET 71-0166 NEW YORK TESTING LABS, INC

7905150178 Forwards request for addl info to complete review of GA program
 MACDONALD, C E Transportation Branch 79/04/13 2pp

DOCKET 71-0167 FINLAY TESTING LABORATORIES

7905010169 Forwards request for addl info to complete review of GA program
 MACDONALD, C E Transportation Branch 79/04/13 2pp

DOCKET 71-0168 QUALITY ASSURANCE LABS

7905150205 Forwards request for addl info to complete review of GA program
 MACDONALD, C E Transportation Branch 79/04/13 2pp

DOCKET 71-0169 FLORIDA POWER & LIGHT CO.

7905240834 Forwards GA program approval for radioactive matl packages
 MACDONALD, C E Transportation Branch 79/05/04 1p.

--7905240839 GA program approval for radioactive matl packages
 MACDONALD, C E Transportation Branch 79/05/04. 1p

DOCKET 71-0174 SOUTHERN CALIFORNIA EDISON CO.

7905240395 Forwards chronology of FSAR amend re GA program, in response to NRC 790320 request
 BASKIN, K P Southern California Edison Co. 79/04/27 3pp.

DOCKET 71-0175 GC SERVICES, INC

7905020394 Forwards request for addl info to complete review of GA program
 MACDONALD, C E Transportation Branch 79/04/13 2pp.

DOCKET 71-0178 ENERGY PRODUCTS GROUP

7905020399 Forwards request for addl info to complete review of GA program
 MACDONALD, C E Transportation Branch 79/04/13 2pp

DOCKET 71-0180 HARTFORD STEAM BOILER CO

7905020392 Forwards request for addl info to complete review of GA program
 MACDONALD, C E Transportation Branch 79/04/13 2pp

DOCKET 71-0181 CONSOLIDATED X-RAY SERVICE CORP

7905110095 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licenses, dtd 790402, to assist in application revision Requests revision by 790502
 MACDONALD, C E Transportation Branch 79/04/27 3pp.

DOCKET 71-0188 MAYNARD STEEL CASTING CO

7905150157 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licenses, dtd 790402, to assist in application revision Requests revision by 790527
 MACDONALD, C E Transportation Branch 79/04/27 3pp

DOCKET 71-0189 TODD SHIPYARDS CORP

7905150169 Proposed GA program does not meet requirements of App E to 10CFR71. Forwards sample GA program for industrial radiography licenses, dtd 790402, to assist in application revision Requests revision by 790527
 MACDONALD, C E Transportation Branch 79/04/27. 3pp

DOCKET 71-0202 PACIFIC GAS & ELECTRIC CO

7905290011 Responds to 790313 ltr Lists references to specific docketed info describing operational GA program
 CRANE, P A. Pacific Gas & Electric Co 79/04/20 1p.

DOCKET 71-0205 QUALITY TESTING, INC.

7905250016 Forwards GA program for use of approved packages in shipment of sealed sources
 MASTERSON, D J. Quality Testing, Inc 79/05/01. 1p.

--7905250019 GA program for use of approved packages in shipment of sealed sources.
 MASTERSON, D J Quality Testing, Inc 79/05/01 5pp.

DOCKET 71-0207 CONNECTICUT YANKEE ATOMIC POWER CO

7905240503 Informs that latest revision to operational GA program is described in Revision 3A to GA rept NU-GA-1, forwarded to NRC on 790426
 COUNCIL, W G. Connecticut Yankee Atomic Power Co. 79/04/26 1p

DOCKET 71-0209 JACKSONVILLE SHIPYARDS, INC

7905110065 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licenses, dtd 790402, to assist in application revision Requests revision by 790502
 MACDONALD, C E Transportation Branch 79/04/27. 3pp.

DOCKETED ITEMS

283

DOCKET 71-0213 INTERMOUNTAIN TESTING CO

7905020386 Forwards request for addl info to complete review of QA program
MACDONALD, C E Transportation Branch 79/04/13 2pp.

DOCKET 71-0214 GAS RENTALS, INC

7905110067 Proposed QA program does not meet requirements of App E to 10CFR71. Forwards sample QA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790502
MACDONALD, C E Transportation Branch 79/04/27 3pp

DOCKET 71-0215 SPACE SCIENCE SERVICES

7905100340 Proposed QA program does not meet requirements of App E to 10CFR71. Forwards sample QA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790502
MACDONALD, C E Transportation Branch 79/02/19 3pp

DOCKET 71-0216 NUCLEAR ENERGY SERVICES, INC

7905020384 Forwards request for addl info to complete review of QA program
MACDONALD, C E Transportation Branch 79/04/13 2pp

7905240632 Forwards QA Program 99-0P-002
GAMBLE, O C obsolete code 79/04/27 1p

--7905240638 Responds to Dec 1978 application requesting approval of QA program Requests addl info re operating logs & results of insp
MACDONALD, C E Transportation Branch 79/04/13 2pp

--7905240643 QA Program 99-0P-002
GAMBLE, O C obsolete code 78/11/01 9pp

DOCKET 71-0217 PULLMAN KELLOGG, INC.

7905250227 Forwards request for addl info to complete review of QA program
MACDONALD, C E Transportation Branch 79/04/06 2pp

7905150647 Responds to 790406 ltr requesting addl info re QA program for license 42-16573-01 Lists changes which will be incorporated into program
TURNER, J E Pullman, Inc 79/04/17 1p

DOCKET 71-0220 GENERAL DYNAMICS CORP

7905020376 Forwards request for addl info to complete review of QA program
MACDONALD, C E Transportation Branch 79/04/13 2pp

DOCKET 71-0222 ST LOUIS TESTING LABS, INC

7905240293 Responds to 790406 request for info re QA program sections concerning radioactive matl shipping package design & responsibility for performing critical handling & storage
TROWBRIDGE, C D St Louis Testing Labs, Inc 79/04/24 1p

DOCKET 71-0223 B F SHAW, INC

7905240291 Forwards request for addl info to complete review of QA program
MACDONALD, C E Transportation Branch 79/04/13 2pp.

DOCKET 71-0225 NAVY, DEPT OF

7905020196 Forwards request for addl info to complete review of QA program
MACDONALD, C E Transportation Branch 79/04/13 2pp.

DOCKET 71-0226 NEW YORK STATE UNIV. OF

7905020193 Forwards request for addl info to complete review of QA program
MACDONALD, C E Transportation Branch 79/04/13 2pp

DOCKET 71-0234 X-RAY, INC

7905250066 Proposed QA program does not meet requirements of App E to 10CFR71. Forwards sample QA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790527
MACDONALD, C E Transportation Branch 79/04/27 3pp

DOCKET 71-0235 ARMY, DEPT OF

7905100342 Proposed QA program does not meet requirements of App E to 10CFR71. Forwards sample QA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790502
MACDONALD, C E Transportation Branch 79/04/27 3pp

DOCKET 71-0238 AGRICULTURE, DEPT OF

7905100167 Proposed QA program does not meet requirements of App E to 10CFR71. Forwards sample QA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790502
MACDONALD, C E Transportation Branch 79/04/27 3pp

DOCKET 71-0239 NAVY, DEPT OF

7905020191 Forwards request for addl info to complete review of QA program
MACDONALD, C E Transportation Branch 79/04/13 2pp

DOCKET 71-0241 UNITED NUCLEAR CORP

7905240774 Forwards request for addl info to complete review of QA program
MACDONALD, C E Transportation Branch 79/04/20 1pp

DOCKET 71-0251 WESTINGHOUSE ELECTRIC CORP

7905290096 Responds to 790328 ltr Confirms that package suppliers need not have QA program approved per App E of 10CFR71. User is responsible to ensure that all transportation activities meet specified criteria
MACDONALD, C E Transportation Branch 79/04/26 1p

DOCKET 71-0255 WALWORTH CO

7905100347 Proposed QA program does not meet requirements of App E to 10CFR71. Forwards sample QA program for industrial radiography licensees, dtd 790402, to assist in application revision. Requests revision by 790502
MACDONALD, C E Transportation Branch 79/04/27 3pp

DOCKET 71-0257 INDUSTRIAL LABS, INC

7905100352 Proposed QA program does not meet requirements of App E to 10CFR71. Forwards sample QA program for industrial radiography licensees, dtd 790402, to assist in application revision. Requests revision by 790502
MACDONALD, C E Transportation Branch 79/04/27 3pp

DOCKET 71-0260 ABSTOTEC, INC

7905110199 Proposed QA program does not meet requirements of App E to 10CFR71. Forwards sample QA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790520
MACDONALD, C E Transportation Branch 79/04/20 3pp.

DOCKET 71-0261 NAVY, DEPT OF

7905290235 Proposed QA program does not meet requirements of App E to 10CFR71. Forwards sample QA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790502
MACDONALD, C E Transportation Branch 79/04/20 3pp.

DOCKETED ITEMS

DOCKET 71-0266 DUKE POWER CO

7905240214 Commits to applying Revision 4 to GA topical rept, Duke-1-A, to comply w/10CFR71 IS requirements, in response to 790402 ltr
PARKER, H G Duke Power Co 79/04/11 1p

7905240835 Forwards GA program approval for radioactive matl package
MACDONALD, C E Transportation Branch, 79/05/01 1p

--7905240845 GA program approval for radioactive matl packages issued to Duke Power Co
MACDONALD, C E Transportation Branch 79/05/01 1p

DOCKET 71-0268 NAVY, DEPT OF

7905100339 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790502
MACDONALD, C E Transportation Branch 79/04/20 3pp

DOCKET 71-0273 NAVY, DEPT OF

7905100448 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licensees, dtd 790402, to assist in application revision Requests revision by 790502
MACDONALD, C E Transportation Branch 79/04/20 3pp

DOCKET 71-0277 ALLIED CHEMICAL CORP

7905070228 Forwards request for addl info to complete review of GA program
MACDONALD, C E Transportation Branch 79/04/11 12pp.

7905240867 Responds to 790411 ltr Will discuss GA program during 790502 meeting Will rewrite program to meet NRC requirements
NEWMAN, R I Allied Chemical Corp 79/04/27 1p

DOCKET 71-0280 ABCO PERFORATORS, INC

7905150214 Forwards GA program for License 4-1723, authorizing shipment of radioisotopes
COOK, C L Abco Perforators, Inc 79/03/12 2pp

--7905150474 GA program for License 4-1723, authorizing shipment of radioisotopes
COOK, C L Abco Perforators, Inc 79/03/12 3pp

DOCKET 71-0282 WKM WELLHEAD SYSTEMS, INC.

7905290251 Forwards GA program for License LA-2365-LO1
CANNON, E WKM Wellhead Systems, Inc 79/03/14 3pp.

DOCKET 71-0286 BFB INSTRUMENTS, INC

7905150026 Forwards GA program for License 13-17342-01
GRACE, J. O BFB Instruments, Inc 79/03/19 1p.

--7905150027 GA program for License 13-17342-01, for compliance w/10CFR71, App E.
GRACE, J. O BFB Instruments, Inc 79/03/19 4pp

DOCKET 71-0287 CARBON NON-DESTRUCTIVE TESTING

7905290318 Forwards request for addl info to complete review of GA program
MACDONALD, C E Transportation Branch, 79/04/13 2pp.

DOCKET 71-0288 NORTH DAKOTA STATE WATER COMMISSION

7905100393 Forwards GA program for License 33-06501-01
BURKE, P A North Dakota, State of, 79/03/16 1p.

--7905100398 "GA program of ND State Water Commission" for compliance w/10CFR71, App E.
BURKE, P A North Dakota, State of 79/03/15 3pp

DOCKET 71-0290 UNITED TESTING SERVICES, INC

7905280281 Forwards GA program of United Testing Svc implemented for LA-2717-LO1 per 10CFR71, App E requirements w/two oversized pages
United Testing Services, Inc 79/03/20 4pp

DOCKET 71-0296 IOWA ELECTRIC LIGHT & POWER CO

7905100400 Plans to modify GA program in order to implement shipping activities No further shipments of Type B radwaste will be made until approval is received from NRC
LIU, L Iowa Electric Light & Power Co 79/03/16 1p

7905150723 Forwards GA program approval for radioactive matl package
MACDONALD, C E Transportation Branch 79/04/10 2pp

DOCKET 71-0297 E LEWIS COOK & ASSOCIATES

7905290463 Forwards GA program for License R-3333-L5
HUCKABEE, K W E Lewis Cook & Associates 79/03/21 1p

--7905290469 GA program for License R-3333-L5
HUCKABEE, K W E Lewis Cook & Associates 79/03/21 4pp

DOCKET 71-0299 QUALITY CONTROL SERVICES, INC

7905240175 Forwards GA program for License 13-14856-01
SACHSE, J Quality Control Services, Inc 79/03/30 1p

--7905240183 GA program for License 13-14856-01
SACHSE, J Quality Control Services, Inc, 79/03/30 24pp

DOCKET 71-0300 INDEPENDENT TESTING LABORATORIES

7905170296 Forwards GA program for License 03-15981-02
SWAIN, W E Independent Testing Laboratories 79/03/26 1p

--7905170299 GA program for License 03-15981-02
SWAIN, W E Independent Testing Laboratories 79/03/26 5pp

DOCKET 71-0304 TELEDYNE BROWN ENGINEERING CO.

7905290305 Forwards GA program for State of AL License 599
MEYER, W A Teledyne Brown Engineering Co 79/03/27 1p

--7905290309 GA program for State of AL License 599
MEYER, W A Teledyne Brown Engineering Co 79/03/27 3pp

DOCKET 71-0305 AMERICAN X-RAY & INSPECTION, INC

7905100361 Forwards GA program for License 21-15455-01
GRASHAW, T D American X-Ray & Inspection 79/03/30 1p.

--7905100365 GA program for License 21-15455-01.
GRASHAW, T D. American X-Ray & Inspection 79/03/01 5pp

DOCKET 71-0307 TEXAS PIPE BENDING CO OF PUERTO RICO

7905100368 Forwards GA program for License 32-13632-01
WARREN, M C. Texas Pipe Bending Co (subs of Bendix Corp). 79/03/30 1p.

--7905100369 GA program for License 32-13632-01
WARREN, M C. Texas Pipe Bending Co. (subs of Bendix Corp), 79/03/29 5pp

DOCKET 71-0309 WORTHINGTON PUMP CORP. (UBA)

7905150763 Forwards GA program for License 29-02210-02
HOLYNEUX, E L Worthington Pump, Inc. (subs of Studebaker-Worthington, Inc.). 79/03/30 1p

DOCKETED ITEMS

285

--7905180766 GA program for License 29-02210-02
MOLYNEUX, E. L. Worthington Pump, Inc (subs of
Studebaker-Worthington, Inc) 79/01/01 7pp

DOCKET 71-0311 LOGWELL, INC

7905150689 Forwards GA program for License 35-13565-01
BAILEY, F O Logwell 79/03/30 1p

--7905150693 GA program for License 35-13565-01
BAILEY, F O Logwell 79/03/30 4pp

DOCKET 71-0312 METALFORMS, INC

7905150626 Forwards GA program for License 8-2261.
BENNETT, C Metalforms, Inc 79/03/29 1p

--7905150632 GA Program for License 8-2261
BENNETT, C Metalforms, Inc 79/03/29 43pp

DOCKET 71-0317 HUDSON PRODUCTS CORP

7905240206 Forwards GA program for License 8-2370
BENEFIELD, W E Hudson Products Corp 79/04/16 1p

--7905240210 GA program for License 8-2370
BENEFIELD, W E Hudson Products Corp 79/04/16 4pp

DOCKET 71-0322 CONTROL COMPONENTS INTERNATIONAL

7905290081 Forwards GA program of Control Components Intl. implemented
for License 3265-30, State of CA
LAWRENCE, M Babcock & Wilcox Co 79/04/11 1p

--7905290084 GA program implemented for License 3265-30 State of CA
LAWRENCE, M. Babcock & Wilcox Co 79/04/11 3pp

DOCKET 71-4986 MODEL RA-2, EXXON NUCLEAR CO, INC

7905240017 Forwards Revision 4 of Certificate of Compliance 4986 for
shipping package Models RA-1, 2, 3 & J
MACDONALD, C E Transportation Branch 79/04/26 2pp

--7905240020 Certificate of Compliance 4986, Revision 4, for radioactive
matl shipping package Models RA-1, 2, 3 & J
MACDONALD, C E Transportation Branch 79/04/26 6pp

DOCKET 71-5026 MODEL BC-4B-220, ATCOR, INC

7905240608 Informs that operations & assets of Protective Packaging, Inc
were transferred from Nuclear Engineering Co to Teledyne
Energy Sys in Jan 1979. Requests applicable certificates of
compliance be changed to this effect.
HALL, W C. Teledyne, Inc 79/04/06 1p

DOCKET 71-5450 MODEL RCC-1, -2, -3, WESTINGHOUSE ELECTRIC CORP.

79052020307 Withdraws proprietary portion of application for revision of
Certificate of Compliance 5450, to include authorization of
RCC-4 type shipping package Matl being reclassified as
nonproprietary
DIPIAZZA, R P. Westinghouse Electric Corp 79/04/06 1p.

7905240209 Requests registration as user of Model 5450
DUNN, C N Duquesne Light Co 79/04/10 1p.

DOCKET 71-5790 MODEL A1-M3, ENERGY, DEPT OF

7905230691 Informs that Albuquerque Operations Ofc 790130 ltr
responding to NRC 781101 request for addl info for Models
AL-M3 & AL-M6 packages did not fully answer questions
Requests advisement of further info within 30 days.
MACDONALD, C E Transportation Branch 79/03/30 1p

DOCKET 71-5791 MODEL A1-M6, ENERGY, DEPT OF

7905230691 Informs that Albuquerque Operations Ofc 790130 ltr
responding to NRC 781101 request for addl info for Models
AL-M3 & AL-M6 packages did not fully answer questions
Requests advisement of further info within 30 days
MACDONALD, C E Transportation Branch 79/03/30 1p

DOCKET 71-5795 MODEL NONE, ENERGY, DEPT OF

7905160053 Forwards 790226 ltr requesting registration as user of ORNL
foamglass shipping container Since this is DOE-approved
package, DOE field ofc should be contacted
MACDONALD, C E Transportation Branch 79/04/13 1p

--7905160058 Requests authorization as shipper of ORNL foamglass shipping
container under same terms & conditions listed in
Certificate of Compliance 5795
KEENEY, W P Argonne National Laboratory 79/02/26 1p

DOCKET 71-5805 MODEL ATCOR V4DB CASK, ATCOR, INC

7905230847 Requests addl info to complete review of 790124 application
for amend to Model Vandenberg packaging Requests
delineation of changes made to Drawing 0999-D-07, Revision F
MACDONALD, C E Transportation Branch 79/03/10 1p

DOCKET 71-5908 MODEL DOT-QM TYPE B, BABCOCK & WILCOX CO

7905300490 Requests revised Certificate 5908 for 4M packaging
MOTT, W E Energy, Dept of 79/04/20 1p

DOCKET 71-5926 MODEL 100, GENERAL ELECTRIC CO

7905150627 Forwards updated version of drawings of GE Model 100
shipping container due to incremental editorial changes
W/12 drawings
CUNNINGHAM, G E General Electric Co 79/04/09 5pp

DOCKET 71-5957 MODEL BMI-1, ENERGY, DEPT OF

7905080180 Notification of registration as user of Model BMI-1 in
response to 790223 request
MACDONALD, C E Transportation Branch 79/04/20 1p

DOCKET 71-6058 MODEL B3-1, NUCLEAR ENGINEERING CO

7905070047 Notifies that Model B3-1 packaging may not conform to design
approval in Certificate of Compliance 6058, Revision 3 Users
should confirm that packages were properly fabricated before
use.
MACDONALD, C E Transportation Branch 79/04/02 2pp

--7905070058 Follows up 790312 ltr re review which disclosed that
shipping cask Model B3-1 lifting lugs have been fabricated
out of stainless steel rather than Cor-ten as specified in
Certificate of Compliance 6058
VOTH, M H Union Carbide Corp 79/03/22 1p

7905240608
were tran
Energy Sy
compliance
HALL, W C

7905150281
Heat shie
& found c
VOTH, M H

7905100126
Radioacti
Inc Ship
of cask
BURIAM, R
79/04/21

7905230219
shipping
MACDONALD

DOCKETED ITEMS

--7905250226 Certificate of Compliance 405B, Revision 4, for radioactive matl shipping package Model 83-1
MACDONALD, C E Transportation Branch 79/04/27 3pp

DOCKET 71-6144 MODEL 6144, NUCLEAR ENGINEERING CO

7905240608 Informs that operations & assets of Protective Packaging, Inc were transferred from Nuclear Engineering Co to Teledyne Energy Sys in Jan 1979 Requests applicable certificates of compliance be changed to this effect
HALL, W C Teledyne, Inc 79/04/06 1p

7905070075 Forwards Revision 3 of Certificate of Compliance 6144 for shipping package Model 6144
MACDONALD, C E Transportation Branch 79/04/23 3pp

--7905070081 Certificate of Compliance 6144, Revision 3, for radioactive matl shipping package Model 6144.
MACDONALD, C E Transportation Branch 79/04/23 3pp

DOCKET 71-6244 MODEL 6244, CHEM-NUCLEAR SYSTEMS, INC

7905240187 Notifies that info requested in 790316 ltr will be forwarded by 790330
REYNOLDS, L E Chem-Nuclear Systems, Inc 79/04/11, 1p

7905240112 Notifies that Certificate of Compliance 6244 for shipping package Model 6244 expires 790531 Renewal must be requested
MACDONALD, C E Transportation Branch 79/04/12 1p

7905300636 Responds to 790412 notice of 790531 expiration of Certificate of Compliance 6244 Expects to submit application for license renewal & amend by 790530
REYNOLDS, L E Chem-Nuclear Systems, Inc 79/04/20 1p

DOCKET 71-6272 MODEL POLY PANTHER, NUCLEAR ENGINEERING CO

7905240608 Informs that operations & assets of Protective Packaging, Inc were transferred from Nuclear Engineering Co to Teledyne Energy Sys in Jan 1979 Requests applicable certificates of compliance be changed to this effect
HALL, W C Teledyne, Inc 79/04/06 1p

7905070302 Forwards Revision 2 of Certificate of Compliance 6272 for shipping package Model Poly Panther
MACDONALD, C E Transportation Branch 79/04/23 2pp

--7905070307 Certificate of Compliance 6272, Revision 2, for radioactive matl shipping package Model Poly Panther
MACDONALD, C E Transportation Branch 79/04/23 2pp.

DOCKET 71-6273 MODEL 48X, F. A. Y. ALLIED-GENERAL NUCLEAR SERVICES

7905240128 Responds to 781108 ltr requesting review of "U Hexafluoride Handling Procedures & Container Criteria," ORQ-651, Revision 4, dtd Apr 1977 Unacceptable replacement for Revision 3; general notes deleted
MACDONALD, C E Transportation Branch 79/04/26, 1p.

DOCKET 71-6346 MODEL FBV-1, GENERAL ATOMIC CO.

7905020387 Forwards addl info supporting application for shipping cask design using alternate closure configuration Derived analyses show impact limiter protects cask closure, assuring radioactive matls will not be released to environ.
MCKAY, W R General Atomic Co (subs. of Gulf Oil Corp) 79/04/06 53pp.

DOCKET 71-6386 MODEL 235R001, ENERGY, DEPT. OF

7905250341 Forwards Revision 4 of Certificate of Compliance 6386 for shipping package Model 235R001.
MACDONALD, C E Transportation Branch, 79/05/01 1p.

--7905250346 Certificate of Compliance 6386, Revision 4, for radioactive matl shipping package Model 235R001.
MACDONALD, C E Transportation Branch, 79/05/01, 3pp

DOCKET 71-6387 MODEL 60, BATTELLE MEMORIAL INSTITUTE

7905020270 Forwards 790319 ltr from HEDL requesting mode of NRC certificate of compliance to reflect new types & sizes of fuel pins
FITZBINKINS, T R Energy, Dept of 79/04/03 8pp

DOCKET 71-6400 MODEL-SUPER TIGER, WESTINGHOUSE ELECTRIC CORP

7905150664 Informs that info requested re amend to Certificate of Compliance 6400 will be submitted by 790430
MICHEL, C J Nuclear Fuel Services, Inc (subs of Getty Oil Co) 79/03/23 1p

7905300136 Forwards request for exemption from 10CFR71.42(b) re shipment of waste matl in Model Super Tiger shipping container.
DIPIAZZA, R P Westinghouse Electric Corp 79/04/03 1p

--7905300142 "Info for Pu Waste Drum Shipments"
* Westinghouse Electric Corp 79/04/03 7pp

7905240608 Informs that operations & assets of Protective Packaging, Inc were transferred from Nuclear Engineering Co to Teledyne Energy Sys in Jan 1979 Requests applicable certificates of compliance be changed to this effect
HALL, W C Teledyne, Inc 79/04/06 1p

7905240036 Forwards Revision 3 of Certificate of Compliance 6400 for shipping package Model Super Tiger
MACDONALD, C E Transportation Branch 79/04/26 3pp

--7905240039 Certificate of Compliance 6400, Revision 3, for radioactive matl shipping package Model Super Tiger
MACDONALD, C E Transportation Branch 79/04/26 6pp

DOCKET 71-6553 MODEL PADUCAH TIGER, ENERGY, DEPT. OF

7905240128 Responds to 781108 ltr requesting review of "U Hexafluoride Handling Procedures & Container Criteria," ORQ-651, Revision 4, dtd Apr 1977 Unacceptable replacement for Revision 3; general notes deleted
MACDONALD, C E Transportation Branch 79/04/26 1p

DOCKET 71-6679 MODEL 1/2 SUPER TIGER, NUCLEAR ENGINEERING CO

7905240608 Informs that operations & assets of Protective Packaging, Inc were transferred from Nuclear Engineering Co to Teledyne Energy Sys in Jan 1979 Requests applicable certificates of compliance be changed to this effect
HALL, W C Teledyne, Inc 79/04/06 1p

7905230305 Forwards Revision 2 of Certificate of Compliance 6679 for shipping package Model Half Super Tiger
MACDONALD, C E Transportation Branch, 79/04/26, 2pp

--7905230316 Certificate of Compliance 6679, Revision 2, for radioactive matl shipping package Model Half Super Tiger
MACDONALD, C E Transportation Branch 79/04/26, 5pp.

DOCKET 71-6697 MODEL 8500 PKO, GENERAL ELECTRIC CO.

7905240327 Forwards Revision 4 of Certificate of Compliance 6697 for shipping package Model GE-8500
MACDONALD, C E Transportation Branch 79/05/08, 2pp

--7905240331 Certificate of Compliance 6697, Revision 4, for radioactive matl shipping package Model GE-8500.
MACDONALD, C E Transportation Branch 79/05/08, 2pp

DOCKET 71-6698 MODEL NFB-4, NUCLEAR FUEL SERVICES, INC

7905020252 Reports deviation of NAC-1 cask from specs in certificate of compliance Corrective action being taken
ROLLINS, J D. Nuclear Assurance Corp, 79/04/02 2pp

DOCKETED ITEMS

287

7905020176 Forwards order to show cause, effective immediately, which prohibits further use of Model NFB-4 package, requires evaluation of deviations from design approval & requires further order of NRC to return packaging to svc
DIRCKS, W J Office of Nuclear Material Safety & Safeguards
79/04/06 2pp

--7905020180 Order to show cause, effective immediately, prohibiting further use of Model NFB-4 package, requiring evaluation of deviations from design approval & requiring further order of NRC to return packaging to svc
DIRCKS, W J Office of Nuclear Material Safety & Safeguards
79/04/06 3pp

7905300668 Responds to NRC 790406 ltr Util has no plans to use NFB-4 packaging to ship nuclear fuel in near future.
BAYNARD, P Y Florida Power Corp 79/04/16 1p

7905240414 Requests extension until 790515 to respond to 790406 order to show cause re Nuclear Assurance Corp cast Model NFB-4.
MCGARRY, J M Debevoise & Lieberman 79/04/30 1p.

DOCKET 71-6744 MODEL POLY TIGER, NUCLEAR ENGINEERING CO

7905240408 Informs that operations & assets of Protective Packaging, Inc were transferred from Nuclear Engineering Co to Teledyne Energy Sys in Jan 1979 Requests applicable certificates of compliance be changed to this effect
HALL, W C Teledyne, Inc 79/04/06 1p

7905090089 Forwards Revision 2 of Certificate of Compliance 6744 for shipping package Model Poly Tiger
MACDONALD, C E Transportation Branch 79/04/24 3pp

DOCKET 71-6771 MODEL BN-1, NUCLEAR ENGINEERING CO

7905240608 Informs that operations & assets of Protective Packaging, Inc were transferred from Nuclear Engineering Co to Teledyne Energy Sys in Jan 1979 Requests applicable certificates of compliance be changed to this effect
HALL, W C Teledyne, Inc 79/04/06 1p

7905070290 Forwards Revision 2 of Certificate of Compliance 6771 for shipping package Model BN-1
MACDONALD, C E Transportation Branch 79/04/24 2pp

--7905070295 Certificate of Compliance 6771, Revision 2, for radioactive matl shipping package Model BN-1
MACDONALD, C E Transportation Branch 79/04/24 2pp.

DOCKET 71-9009 MODEL FL 10-1, GENERAL ELECTRIC CO

7905240910 Requests amend to Certificate of Compliance 9009, Revision 2 re Model FL 10-1 shipping package Diagram of container arrangement encl
CUNNINGHAM, G E General Electric Co, Nuclear Energy Products Div
79/04/16 4pp

7905290041 Forwards Revision 3 of Certificate of Compliance 9009 for shipping package Model FL 10-1
MACDONALD, C E Transportation Branch. 79/05/04. 2pp

--7905290046 Certificate of Compliance 9009, Revision 3, for radioactive matl shipping package Model FL 10-1
MACDONALD, C E Transportation Branch. 79/05/04 4pp.

DOCKET 71-9010 MODEL NLI-1/2, NL INDUSTRIES, INC.

7905290071 Requests registration of listed parties as users of Model NLI-1/2 cast. Users have Revision 4 of certificate of compliance Requests forwarding of future revisions
RQSB, D M Energy, Dept of. 79/05/01 1p

7905130576 Notification of registration as user of Model NLI-1/2 package 9010, in response to licensee 790501 request
MACDONALD, C E Transportation Branch. 79/05/02 1p.

DOCKET 71-9023 MODEL NLI-10/24, NL INDUSTRIES, INC

7905250211 Informs that licensee will provide requested info by 790615
WILLIAMS, C E NL Industries, NL Nuclear Div 79/03/28 1p

DOCKET 71-9033 MODEL 660 & 660E, TECHNICAL OPERATIONS, INC

7905240348 Requests revision to Certificate of Compliance 9033, Revision 2, to include correct address for American Airlines
ANDERSON, C R American Airlines, Inc 79/04/06 1p

DOCKET 71-9044 MODEL GE-1600, GENERAL ELECTRIC CO

7905290076 Requests registration as user of Model GE-1600 radioactive matl shipping package
OPEKA, J F Northeast Utilities 79/04/27 1p

DOCKET 71-9070 MODEL N-35, ENERGY, DEPT. OF

7905240244 Notification of registration as user of Model N-35, in response to licensee 790222 request.
MACDONALD, C E Transportation Branch 79/05/04 1p

DOCKET 71-9079 MODEL HN-100 SERIES 2, HITTMAN NUCLEAR & DEVELOPMENT

7905100079 Responds to 790312 ltr re driver checklists submitted w/ SARs for various radwaste packages Unless checklists are specifically required by certificate of compliance, users may develop their own procedures
MACDONALD, C E Transportation Branch 79/04/13 1p

DOCKET 71-9080 MODEL HN-600, HITTMAN NUCLEAR & DEVELOPMENT CORP

7905100079 Responds to 790312 ltr re driver checklists submitted w/ SARs for various radwaste packages Unless checklists are specifically required by certificate of compliance, users may develop their own procedures
MACDONALD, C E Transportation Branch 79/04/13 1p

DOCKET 71-9086 MODEL HN-100 SERIES 1, HITTMAN NUCLEAR & DEVELOPMENT

7905100079 Responds to 790312 ltr re driver checklists submitted w/ SARs for various radwaste packages Unless checklists are specifically required by certificate of compliance, users may develop their own procedures
MACDONALD, C E Transportation Branch 79/04/13 1p

DOCKET 71-9089 MODEL NH-100 S, HITTMAN NUCLEAR & DEVELOPMENT CORP.

7905100079 Responds to 790312 ltr re driver checklists submitted w/ SARs for various radwaste packages Unless checklists are specifically required by certificate of compliance, users may develop their own procedures.
MACDONALD, C E Transportation Branch 79/04/13 1p.

DOCKET 71-9090 MODEL 480M, ALLIED CHEMICAL CORP.

7905240128 Responds to 781108 ltr requesting review of "U Hexafluoride: Handling Procedures & Container Criteria," ORD-631, Revision 4, dtd Apr 1977. Unacceptable replacement for Revision 3; general notes deleted.
MACDONALD, C E Transportation Branch. 79/04/26 1p.

DOCKET 71-9091 MODEL 30 A, GENERAL ELECTRIC CO.

7905240128 Responds to 781108 ltr requesting review of "U Hexafluoride: Handling Procedures & Container Criteria," ORD-631, Revision 4, dtd Apr 1977. Unacceptable replacement for Revision 3; general notes deleted
MACDONALD, C E Transportation Branch 79/04/26. 1p.

DOCKETED ITEMS

DOCKET 71-9092 MODEL HN-300, HITTMAN NUCLEAR & DEVELOPMENT CORP

7905100079 Responds to 790312 ltr re driver checklists submitted w/ SARs for various radwaste packages. Unless checklists are specifically required by certificate of compliance, users may develop their own procedures
MACDONALD, C E Transportation Branch 79/04/13 1p

DOCKET 71-9093 MODEL HN-400, HITTMAN NUCLEAR & DEVELOPMENT CORP

7905100079 Responds to 790312 ltr re driver checklists submitted w/ SARs for various radwaste packages. Unless checklists are specifically required by certificate of compliance, users may develop their own procedures
MACDONALD, C E Transportation Branch 79/04/13 1p

DOCKET 71-9116 MODEL CN6-B0B, NUCLEAR PACKAGING, INC

7905240497 Requests info re status of application for certificate of compliance authorizing shipment of nuclear matl in NuPac CN6-B0B shielded cask
HANSEN, L J Nuclear Packaging, Inc 79/04/26 1p

DOCKET 71-9120 MODEL TN-12, TRANSNUCLEAR CORP

7905150788 Withdraws method proposed in 790131 ltr to demonstrate fracture toughness of Tn-12 containment vessel steels. Outlines new approach
GOLDMAN, K Transnuclear, Inc 79/04/06 3pp

7905230066 Forwards Revision 1 to SAR of TN-12 packaging, in response to 780907 request for addl info
HACKLIN, L Transnuclear, Inc 79/04/30 500pp

DOCKET 71-9132 MODEL T-3, NUCLEAR PACKAGING, INC

7905150786 Notifies that licensee will respond to 790305 request for addl info re T-3 shipping cask by 790601
SINGHUR, J D Nuclear Packaging, Inc 79/04/05 1p

DOCKET 71-9506 MODEL MS27684-2, ENERGY, DEPT OF

7905220105 Forwards drawings for shipping container Model 9506, as requested in 790302 memo
BLAUVELT, R K Monsanto Co 79/03/27 18pp

7905240099 Requests addl info re Model MS 27684-2 package Albuquerque Operations. Dfc 790302 response not sufficient. Requests 30-day notification if info will be provided
MACDONALD, C E Transportation Branch 79/04/27 1p

DOCKET 71-9785 MODEL SZW/SZWA, ENERGY, DEPT OF

7905020264 Forwards response to NRC 781221 comments re SAR for shipment of SZW/SZWA spent core cartridge shipping container.
BRODSKY, R S Energy, Dept of 79/04/05 12pp

DOCKET 71-9852 MODEL DT-14, ENERGY, DEPT. OF

7905020170 In ref to 780802 ltr, requests addl info for review of Model DT-14 shipping package
MACDONALD, C E Transportation Branch 79/04/06 2pp

NONDOCKETED ITEMS

- 7904130020 Informs of review of all category A, B, C & D generic technical activities & categorization according to risk. Requests comments on Ofc of Nuclear Regulatory Research rept & draft Commission paper by 781101. DEYOUNG, R. C. Division of Site Safety & Environmental Analysis. 78/10/27 2pp
- 7904160268 Forwards Rept 7 on status of generic items re LWRs in effort to simplify referencing, numbering sys for generic items has been revised. CARBON, M. W. ACRS - Advisory Committee on Reactor Safeguards 79/03/21 33pp.
- 7904170091 Research Info Ltr 46 discusses effectiveness of cable tray coating mats & barriers in retarding combustion of cable trays subjected to exposure fires & in preventing propagation between cable trays. LEVINE, B. Division of Reactor Safety Research 79/02/04 11pp.
- 7904170363 Responds to 780906 memo re NMSS/NRC interface on input from different branches. Environ Projects, Geosciences, Meteorology/Hydrology & Accident Analysis. DEYOUNG, R. C. Division of Site Safety & Environmental Analysis. 78/10/26 6pp
- 7904170321 Responds to request for comments on U Mill Tailings Radiation Act of 1978 NRC has regulatory jurisdiction over mill tailings until 81109 & should conduct specific mill tailings licensing proceedings. SCHIFTER, R. O. Fried, Frank, Harris, Shriver & Kampelman. 79/03/30 2pp
- 7904180171 Forwards rept of Review Group for EPA: "Risk Assessment of Radioactive Waste Isolation in Deep Geologic Formations." ROBERTS, I. C. Assistant Director for Siting Standards. DALLINGFORD, M. Probabilistic Analysis Branch 79/03/16 3pp.
- 7904180175 "Risk Assessment of Radioactive Waste" Isolation in Deep Geologic Formations," from 781204-08 meeting of Review Group for EPA. Assistant Director for Siting Standards. 78/12/08 33pp
- 7904180179 Responds to 781129 memo re status of AD Little repts & EPA planned use in developing radioactive waste stds. Repts are in draft stages & will be used as partial support for waste stds. MARTIN, J. E. Environmental Protection Agency. 78/11/30 1p
- 7904190311 Summary of 781111 meeting w/NRC GA Review Team re plans to review GA practices. BENNETT, G. L. Research Support Branch. 79/04/12. 80pp.
- 7904210061 Summary of 790406 meeting w/Research Review Group re future course of project "Post-Licensing Studies of Socioeconomic Impacts of Nuclear Power Plant Siting." FRICHARD, C. Environmental Effects Research Branch. 79/04/06 3pp.
- 7904210768 Responds to 790224 ltr re perimeter fence requirements. Forwards portion of "Barrier Technology Handbook" which discusses perimeter fences. PRELL, J. A. Safeguards Standards Branch. 79/03/19. 21pp.
- 7904210770 Responds to 790224 ltr re perimeter fence requirements. Inquiry has been forwarded to NRC headquarters. ABRAMMAN, K. Region I, Philadelphia, Office of the Director. 79/02/28. 1p.
- 7904210774 Requests info re regulations & stds re fence design for nuclear plants. SCOTT, R. Bartlett Consolidated, Inc. 79/02/24. 1p.
- 7904240389 Forwards product promotional info for iron oxide mortar to be used as fail-safe passive heat sink for reactors. If each plant can contain worst possible accident, antinuclear forces will be rendered ineffective. HALL, M. C. Chemtree Corp. 79/04/12. 2pp.
- 7904240392 Ack receipt of 760805 ltr concerning reduction of probability of extended reactor outages by using high thermal reactivity concrete. NRC cannot mandate use of product, urges continued scales effort. HEINEMAN, R. E. Division of Systems Safety. 76/08/31. 1p.
- 7904240395 "Assured Above & Below Ground Containment of a Class 9 Accident to a Nuclear Power Reactor." HALL, M. C. Chemtree Corp. 79/03/30. 21pp.
- 7904300173 Certificate of disposition of waste under License 20-05838-01. Waste transferred to Tracerlab, Inc. WEISS, N. M. Metals & Controls Corp. 70740. 65/08/13. 1p.
- 7904300258 Waste under License 20-05838-2 have been transferred to Curtiss-Wright Co. DUFF, P. A. Metals & Controls Corp. 63/05/20 1p
- 7904300319 Application for amend of Matl/Byproduct License 20-05838-1 authorizing Br-90 to be used in beta gauge SANDERS, H. E. Metals & Controls Corp. 34251. 61/04/27. 2pp.
- 7904300328 Certificate of disposition of waste under License 20-05838-03 disposing of Br-90 by burial at Nuclear Engineering site in Morehead, KY on 770628. JOLAN, D. B. Texas Instruments, Inc. 3101. 77/08/22. 1p
- 7904300341 Certificate of disposition of waste under License 20-05838-03 transferring Co-60 to Tracerlab, Inc. WEISS, N. M. Metals & Controls Corp. 76494 67/08/18. 1p
- 7904300342 Matl/Byproduct License 20-05838-3 for Metals & Controls, Inc is amended per 650820 application authorizing any byproduct matl, Co-60 & Br-90 to be used for repair & mod of non-fuel reactor components & film calibr. BRINKMAN, R. E. Atomic Energy Commission (Pre 1975). 65/09/16. 3pp
- 7904300354 Certificate of disposition of waste under License 20-05838-03 by transfer of Co-60 to Tracerlab, Inc. WEISS, N. M. Texas Instruments, Inc. 30165. 72/08/29 1p
- 7904300253 Emphasizes importance of need for free & open communications between all organizational levels in course of managing NRC confirmatory safety research program. KOUTS, H. J. Office of Nuclear Regulatory Research. 76/03/04 1p
- 7904300260 Notifies of personnel change in Power Reactor Licensing Div. as of 790315. MINZINGA, W. J. General Atomic Co. (subs. of Gulf Oil Corp.). 79/04/20. 1p
- 7905010032 Appeal of initial FOIA decision to deny request for Section 4 C of contract between Dow Chemical Co & Consumers Power Co. FREEDKIN, B. Public Interest Research Group. 79/03/15. 2pp.
- 7905010041 Response to appeal of denial of FOIA request for Section 4 C of 780621 general agreement contract between Dow Chemical Co & Consumers Power Co Requested info remains exempt from public disclosure. OGBICK, L. V. Office of the Executive Director for Operations. 79/04/23. 2pp.
- 7905010473 Forwards responses to NRC 790227 request for addl info re topical rept ATC-132-A dtd 790227. BROWNSTEIN, M. ATCOR. EO 2495. 79/04/24. 65pp.
- 7905010556 Requests Executive Branch position re Edlow Intl Co application for license to export special nuclear matl to Argentina. OGBICK, L. V. Office of the Executive Director for Operations. 79/04/13. 1p.
- 7905010540 In response to request for addl info re OE core spray distribution program, forwards "Pretest Prediction for Sector Steam Test Facility Core Spray Tests." LEVINE, A. J. General Electric Co., Nuclear Energy Products Div. MFN-106-79. 79/04/17. 1pp.
- 7905010561 "Pretest Prediction for Sector Steam Test Facility Core Spray Tests." RHOE, S. K., SANDOZ, B. A. General Electric Co., Nuclear Energy Products Div. 79/04/13 26pp.
- 7905010648 FOIA request for info re govt contracts on low level radioactive waste mgmt, name of contractor, contract number, beginning & completion dates & brief description of purpose. LOOKABILL, T. NUS Corp. OMBED 79-087. 79/03/23. 1p.
- 7905010652 Response to FOIA request for info re govt contracts on low level radioactive waste mgmt, name of contractor, contract number & start & completion dates. Forwards lists of contracts. W/o encl. FELTON, J. M. Division of Rules and Records. 79/04/25. 1p.
- 7905010654 FOIA request for info justifying previous failure to use boron to flood facility, preventing release of radioactivity into atmosphere. SCOUTEN, J. W. Affiliation Unknown. 78/03/31. 1p.

NONDOCKETED ITEMS

7905010657 Response to FOIA request for records re non-use of boron to flood reactor core. Forwards IE Bulletin 79-05A & discusses reactor scram incident. W/o encl
FELTON, J M Division of Rules and Records 79/04/24 1p.

7905010660 Response to FOIA request for transcripts of closed NRC meetings re TH-1 from 790328-790405 Transcripts for 790330-0405 meetings are available in PDR
FELTON, J M Division of Rules and Records 79/04/23 1p

7905020004 "Heavy-Section Steel Technology Program", quarterly progress rept for Oct-Dec 1978
WHITMAN, Q D, BRYAN, R M Oak Ridge National Laboratory FIN 8-0119 ORNL/NUREG/TH-2 79/04/30 72pp.

7905020022 NUREG/CR-0283
"Behavior of Defective PWR Fuel Rods During Power Ramp & Film Boiling Operation"
CROUCHER, D W Idaho National Engineering Laboratory, FIN A-6046 TREE-1267, 79/02/28 37pp

7905020037 FOIA request for info re test scores for licensing C Faust & E Frederick as reactor operators & K Bryon & BO Smith as senior operators.
SCHAKNE, R CBS News, CBS, Inc. 79/04/04. 1p.

7905020038 Forwards per Public Law 95-601, "Means for Improving State Participation in Siting, Licensing & Development of Federal Nuclear Waste Facilities," NUREG-0339
HENDRIE, J M. Commission 79/04/19 1p.

--7905020063 NUREG-0339
"Means for Improving State Participation in Siting, Licensing & Development of Federal Nuclear Waste Facilities"
* Office of State Programs. 79/03/31. 82pp

7905020052 Response to FOIA request for info re test scores for licensing C Faust & E Frederick as reactor operators & K Bryon & BO Smith as senior operators.
FELTON, J M Division of Rules and Records. 79/04/24. 1p

7905020056 FOIA request for winning proposal re evaluation of reactor radiation streaming to be provided at requested 790329 debriefing
HERIGOLD, O Science Applications, Inc K-1903 79/03/27. 1p

7905020059 Response to FOIA request for winning proposal for RFP R8-REG-78-193 Forwards relevant correspondence considered acceptable for public disclosure W/o encl
FELTON, J M Division of Rules and Records. 79/04/19. 2pp

7905020080 FOIA request for outline of NRC structural organization, nature of administration's existence, basic health & safeguard stds & important cases of past & present.
CONLEY, M E Bentley College 79/03/18. 1p.

7905020084 Response to FOIA request for various info re NRC organization & activities Forwards appropriate documents, including organization charts, 1978 Annual Rept & other NRC issuances. Discusses two types of NRC stds W/o encl.
FELTON, J M. Division of Rules and Records 79/04/23. 2pp.

7905020088 FOIA request for final rept on Jan 1961 SL-1 prototype reactor accident resulting in death of three naval personnel at Natl Reactor Testing Station, Idaho Falls, ID
HUNTER, R. Affiliation Unknown. 79/04/04 1p.

7905020094 Response to FOIA request for final rept on 1961 SL-1 reactor accident at Natl Reactor Testing Station Forwards press announcement & final investigation rept.
FELTON, J M. Division of Rules and Records 79/04/23. 9pp

--7905020101 Forwards final rept on SL-1 accident occurring at Natl Reactor Testing Station on 8/01/03. Concludes main cause was manual withdrawal of control control rod blade from core beyond specified limits.
NELSON, C. A. Atomic Energy Commission (Pre 1975). 62/09/03 10pp

7905020136 License for Mitsui & Co Inc to export 25,463 pounds of Zircaloy-4 tube shells to Japan
OPLINGER, O. O Assistant Director for Export/Import & International Safeguards 79/04/13. 1p.

7905020142 Proposed Revision 4 to Reg Guide 8.8, "Info Relevant to Ensuring that Occupational Radiation Exposures at Nuclear Power Stations Will Be As Low As Is Reasonably Achievable."
* Office of Standards Development. 79/03/31. 42pp.

7905020151 "Investigation of Post-Critical Heat Flux Transfer for Water-Cooled Reactor Application & Development of Two Phase Flow Instrumentation," progress rept Oct-Dec 1978
CHEN, J C, SUNDARAM, R. K., LONDON, E J. Lehigh Univ. NRC-04-74-180 79/01/01 13pp

7905020154 "Creare Refill Effects Program," Creare Project 345-10 progress rept Mar 1979
ROTHE, P H, CROWLEY, C J Creare, Inc. NRC-04-75-162 79/04/03. 3pp

7905020162 Agenda of ACRB 781005 meeting to discuss FFTF project
* ACRB - Advisory Committee on Reactor Safeguards 78/10/03. 1p

7905020169 Application for extension of time to respond to intervenors' & NRC comments on Stanislaus commitments Certificate of Bvc encl
WATTS, M J McCutchen, Doyle, Brown & Emerson 79/03/07. 5pp

7905020177 Notification of contract execution, "Sys Maint Programming," awarded to Small Business Administration.
HAGAN, T F Administrative Contracts Branch. NRC-10-79-372 883-4-0-8(A)79-. 79/04/10 1p.

--7905020182 Contract for "Sys Maint Programming" awarded to Small Business Administration
WATSON, C Administrative Contracts Branch NRC-10-79-372 NRC-10-79-372 79/04/02 16pp

7905020290 Requests Amend 1 to License XT-B429 to extend expiration from 791201 to 801201
HATSON, V Transnuclear, Inc 79/04/05 1p

7905020297 Requests Amend to License XM-B430 to modify intermediate consignee W/o encl.
GROSS, W T. Fansteel, Inc 79/03/28 1p.

7905020328 Discusses LOCA evaluation model. Leibnitz rule approximation justification is appropriate & effect of high heat transfer on calculated peak clad temp will result in reduction by several hundred degrees
STROUPE, E P General Electric Co., Nuclear Energy Products Div MFH 10B-79. 79/04/19 11pp

7905020348 In response to NRC 790424 meeting w/B&W & 177 fuel assembly plant owners, B&W agreed to describe scope & status of addl analytical work Requested info should be provided by 790504
TAYLOR, J H Babcock & Wilcox Co. 79/04/25. 6pp.

7905020349 License for Westinghouse to export 92 Zr tubes & miscellaneous specially designed or prepared parts & components for use in reactors to Italy.
OPLINGER, O. O. Assistant Director for Export/Import & International Safeguards. 79/04/13. 1p.

7905020355 License for Mitsui & Co Inc to export 77,600 lb of Zircaloy-2 tube shells to Japan
OPLINGER, O. O Assistant Director for Export/Import & International Safeguards 79/04/13 1p

7905020361 License for Mitsubiline Travel Bvc of America, Inc to export miscellaneous specially designed parts for use in reactors to Japan.
OPLINGER, O O Assistant Director for Export/Import & International Safeguards. 79/04/13. 1p

7905020366 License for Mitsui & Co Inc to export 25,463 lb of Zircaloy-2 tube shells to Japan
OPLINGER, O. O. Assistant Director for Export/Import & International Safeguards. 79/04/13 1p.

7905020381 License for Marshaw Chemical Co to export two mCi Br-90 beta ray sources incorporated in Br-90 calibrators to People's Republic of China.
OPLINGER, O O Assistant Director for Export/Import & International Safeguards. 79/04/13. 2pp.

7905020385 License for Kawachi Beryllco Industries, Inc to export 417 35 lb of Zircaloy-2 seamless tubing to Canada.
OPLINGER, O O Assistant Director for Export/Import & International Safeguards. 79/04/17. 1p

7905020409 License for Westinghouse Electric Corp to export fuel tubes, fuel rod springs, & end plugs (top & bottom) to Sweden.
OPLINGER, O. O. Assistant Director for Export/Import & International Safeguards 79/04/17. 1p.

NONDOCKETED ITEMS

291

7905020434 Amend 1 to license for Exxon Nuclear Co. Inc to import U from West Germany, increasing amount licensed from 43,340 kg to 86,480 kg
OPLINGER, Q. O. Assistant Director for Export/Import & International Safeguards 79/04/20 1p

7905020464 Forwards matl describing process for modeling procedures for distribution to licensees
MATHIAS, A. Lawrence Livermore Laboratory S 79-245-D 79/04/23 6pp.

7905020469 Notification of contract execution, Mod 1 to "Economic Assistance Related to Antitrust Hearings for South TX Proceedings." Contractor, Transcomm, Inc
OLAGOLA, A. F. Technical Assistance Contracts Branch FIN B-6393, NRC-03-79-131 79/04/12 1p

--7905020477 Mod 1, extending period of performance until 790531 to "Economic Assistance Related to Antitrust Hearings for South TX Proceedings."
DOUGHERTY, D. J. Technical Assistance Contracts Branch FIN B-6393 79/04/12, 1p.

7905020482 Forwards acceptance of Revision 3 to QA topical rept NU-QA-1 submitted 790307.
HARRIS, W. P. Assistant Director for Quality Assurance & Operations 79/04/13 1p

--7905020493 Evaluation of NU-QA-1 Revision 3A, "Northeast Utils QA Program Topical Rept." Rept is acceptable
Assistant Director for Quality Assurance & Operations 79/03/09, 2pp.

7905020483 License for Westinghouse to import 92.281 kg U from Sweden
OPLINGER, Q. O. Assistant Director for Export/Import & International Safeguards. 79/04/20 3pp.

7905020484 License for Exxon Nuclear Co. Inc to import 40,000 kg U-235 from USSR.
OPLINGER, Q. O. Assistant Director for Export/Import & International Safeguards. 79/04/20, 2pp

7905020499 License for Westinghouse to export one compensated ionization chamber to West Germany.
OPLINGER, Q. O. Assistant Director for Export/Import & International Safeguards. ZE-10227 79/04/18, 1p.

7905020506 License for Transnuclear, Inc to export 2,059 75 mCi Cf-252 as cement wire to France.
OPLINGER, Q. O. Assistant Director for Export/Import & International Safeguards. 79-108/01 (TNP2). 79/04/18 2pp

7905020510 License for Melco USA, Inc to export 1 BF-3 counter type radiation detector to Japan.
OPLINGER, Q. O. Assistant Director for Export/Import & International Safeguards. 79/04/18, 1p.

7905020518 License for Transnuclear, Inc to export 20,526 kg U-235 to West Germany.
OPLINGER, Q. O. Assistant Director for Export/Import & International Safeguards. 79/04/17, 2pp.

7905020522 License for Sigma Chemical Co to export 1 kg heavy water to France
OPLINGER, Q. O. Assistant Director for Export/Import & International Safeguards. 79/04/18 1p.

7905020538 Comments on proposed Reg Guide 1.44: issuance of proposed guide will result in increase in number of internal & external audits conducted by utility
BOYER, V. B. Philadelphia Electric Co. 79/03/20, 6pp.

7905030015 NUREG/CR-0426 V1
"Radiation Dose to Const Workers at Operating Nuclear Power Plant Sites, Vol 1," final rept for Sept 1978-Sept 1978.
ENDRES, O. W., BHIPLER, D. B. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2073, PNW-2773 VOL 1. 78/12/31, 120pp. Available at NTIS 6b, 50.

7905030068 License for Mitsubishi Intl Corp to export pressure tubes, 2r tubes, reactor intervals, control rod drive mechanisms & other specially designed reactor parts, except pressure vessels, control rods, primary coolant pumps & fuel machines.
OPLINGER, Q. O. Assistant Director for Export/Import & International Safeguards. 79/04/16, 2pp.

7905030082 License for TX Nuclear Div to export 1.415 mg Pu-238 to the Netherlands
OPLINGER, Q. O. Assistant Director for Export/Import & International Safeguards. T-1481. 79/04/20, 2pp.

7905030087 Amend 3 to license for QAC, extending expiration date for export of matl to Japan
OPLINGER, Q. O. Assistant Director for Export/Import & International Safeguards IEL-740 79/04/20 1p

7905030090 Dept of Water Resources reply to brief of Southern CA Edison Co which appeals denial of motion to quash subpoena duces tecum Certificate of Subpoena
STRUMHASSER, M. J., DEUMHEJIAN, O., GRUSHIN, S. N. California, State of 79/03/30 46pp

7905030092 Forwards application by Edlow Intl Co for license to export 48,000 kg U-308 to Brazil
HARMON, D. W. Edlow International Co UNQ 2 79/04/17 1p

--7905030100 Application by Edlow Intl Co for license to export 48,000 kg U-308 to Brazil
HARMON, D. W. Edlow International Co 79/04/16 1p

7905030106 Application by GE for license to export specially designed pipe whip restraints to Belgium
WILSON, B. D. General Electric Co BDW-79095 79/04/13 1p

7905030109 Application by Sigma Chemical Co for license to export equivalent of 2 kg D2O liquid in compounds containing deuterium to Argentina
Sigma Chemical Co (subs of Sigma Aldrich Corp) D-10 79/04/16 1p

7905030123 Application by GE for license to export 18,452 kg UO2 powder to Japan.
WILSON, B. D. General Electric Co BDW-79097 79/04/13 1p

7905030127 License for Westinghouse to export pressure tubes, 2r tubes, control rod drive mechanisms & other miscellaneous specially designed parts to Japan.
OPLINGER, Q. O. Assistant Director for Export/Import & International Safeguards 79/04/13 1p

7905030142 NUREG/CR-0494
"Dose-Rate Conversion Factors for External Exposure to Photon & Electron Radiation from Radionuclides Occurring in Routine Releases from Nuclear Fuel Cycle Facilities"
KOECHER, D. C. Oak Ridge National Laboratory FIN B-0188 ORNL/NUREG/TK-2 79/04/30 168pp

7905030144 Forwards QA Program Insp Rept 99900522/79-02 on 790205-08 No noncompliance noted
POTAPOV, U. Region 4, Dallas, Vendor Inspection Branch 79/02/22 2pp

--7905030150 QA Program Insp Rept 99900522/79-02 on 790205-08 No noncompliance noted Major areas inspected previous insp findings, pipe support fillet welds, control of drawings & calculations, & design insp
BRICKLEY, R. H., HALE, C. J. Region 4, Dallas, Vendor Inspection Branch 79/02/20 8pp

7905030157 Ack receipt of 781128 ltr discussing Reactor Safeguards Licensing Branch Review Guideline 23 re security at nuclear plants Bellaves Guideline 23 should not be withdrawn as requested KMC 781128 ltr encl
DENTON, H. R. Office of Nuclear Reactor Regulation 79/04/17 5pp

--7905030176 "Study to Assess Radiological Sabotage Potential of Operating Nuclear Power Plants"
KMC, Inc 78/11/28 25pp

7905030161 Transcript of 790418 Subcommittee on Waste Mgt meeting in Richland, WA to discuss update of waste mgt, sealed disposal, disruptive phenomena in various media & acid digestion Pp 1-148
MOELLER, D. W., LANROSKI, S., MATHIS, W. ACRS - Advisory Committee on Reactor Safeguards. 79/04/18 261pp

7905030180 Notification of contract execution, Mod 1 to "Seismicity Study of Northwestern IL & Southeastern WI." Contractor Univ of WI, Milwaukee
HAGEY, H. Research Contracts Branch. FIN B-6314 NRC-04-7B-232, 79/04/24 1p.

--7905030184 Mod 1, changing performance date from 790228 to 790630, to "Seismicity Study of Northwestern IL & Southeastern WI."
MORTON, K. V. Research Contracts Branch. FIN B-6314 NRC-04-7B-232 79/03/01, 2pp

7905030194 Forwards nonproprietary topical rept BAW-10085, Revision 3
TAYLOR, J. H. Babcock & Wilcox Co. 79/04/12 1p

NONDOCKETED ITEMS

- 7905030205 BAN-10085 R3
"Reactor Protection Sys." Revision 3, nonproprietary version.
ORGERA, E. G., GILBERTSON, L. A., FAIRBROTHER, D. Babcock & Wilcox Co.
79/03/31 200pp
- 7905030194 Notification of contract execution, Mod 1 to "Liquefaction in Lake Amatitlan Area During Feb 1976 Guatemalan Earthquake." Contractor Univ of CA, Bartley.
HAGEY, H. Research Contracts Branch FIN B-6279 NRC-04-78-219.
79/04/24 1p
- 7905030203 Mod 1, changing performance data from 790531 to 790930 to "Liquefaction in Lake Amatitlan Area During Feb 1976 Guatemalan Earthquake."
MORTON, K. V. Research Contracts Branch, FIN B-6279
NRC-04-78-219. 79/04/02 2pp.
- 7905030199 Notice of taking of deposition of RH Oerdes on 790502 Certificate of Bvc encl
MATT, P. K. Spiegel & McDiarmid 79/03/26. 5pp.
- 7905030221 NUREG/CR-0597
"Analysis of Superheated Wall Effects During Refill at Small Scale."
CROWLEY, C. J., ROTHE, P. H. Crears, Inc. FIN A-4070 CREARE TN-287
79/04/30 174pp Available at NTIS. \$8.00
- 7905030226 Notification of contract execution, Mod 1 to "Confirmatory Research Related to Dating of Ground Water." Contractor Univ of Az.
MYNATT, A. Research Contracts Branch FIN B-6736 NRC-04-78-272
79/04/19. 1p.
- 7905030234 Mod 1, increasing funding from \$133,835.00 to \$185,148.46 & allowing for purchase of gas chromatograph-mass spectrometer to "Confirmatory Research Related to Dating of Ground Water."
MORTON, K. V. Research Contracts Branch FIN B-6736
NRC-04-78-272 79/04/01 4pp
- 7905030231 NUREG/CR-0446
"Determining Effectiveness of ALARA Design & Operational Features."
HALL, T. M., DODD, A. M., HAIGHT, R. F. United Nuclear Corp. FIN B-2069.
UNI-TR-3. 79/04/30 532pp. Available at NTIS. \$15.50
- 7905030233 Supplemental answers by P&E to third set of interrogatories submitted by CA Dept of Water Resources Verifications & Certificate of Bvc encl.
DOYLE, M. H., HOUJIHAN, T. J., ARMSTRONG, W. H. McCutchen, Doyle, Brown & Emerson. 79/03/14. 18pp.
- 7905030246 NUREG/CR-0523
"MEGODIF-II, Variable Trajectory Plume Segment Model to Assess Ground-Level Air Concentrations & Deposition of Effluent Releases from Nuclear Power Facilities."
FOWELL, D. C., MEGLEY, H. L., FOX, T. D. Battelle Memorial Institute, Pacific Northwest Laboratory. NRC-03-77-181. PNK-2419. 79/03/31. 320pp Available at NTIS \$11.75.
- 7905030257 Notification of 790425 meeting w/Exxon Nuclear Co in Bethesda, MD to discuss Exxon neutronics calculations for reloads.
WEISS, S. H. Reactor Safety Branch 79/04/20 1p.
- 7905030340 Describes Mark III tests of pressure suppression test facility, Series 6002 & 6003
BOBON, L. J. General Electric Co., Nuclear Energy Products Div
MFN-118-79 79/04/27. 17pp.
- 7905030356 Forwards schedule & scope for reliability analysis of integrated control sys & schedule for developing auxiliary feedwater control independent of integrated control sys
TAYLOR, J. H. Babcock & Wilcox Co. 79/04/28 4pp
- 7905040003 Ack receipt of 790305 ltr requesting NRC to issue 6-month extension of comment period re NUREG-0499, "Policy Statement on Generic Rulemaking to Improve Nuclear Power Plant Licensing." W/790403 Congressional correspondence
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/04/04 3pp.
- 7905040015 Request for extension of initial comment period to permit adequate public consideration of NUREG-0499, "Policy Statement on Generic Rulemaking to Improve Power Plant Licensing."
BROWN, J. W. Affiliation Unknown. 79/03/05. 1p.
- 7905040024 Notification of contract execution, Mod 5 to "Study of Pattern & Ages of Post-Metamorphism Faults in Part of Northern Piedmont of VA & NC." Contractor VA Polytechnic Institute & State Univ
HAGEY, H. Research Contracts Branch FIN A-9027 NRC-04-75-237.
79/04/24. 1p.
- 7905040034 Mod 5, changing period of performance from 790114 to 790315 to "Study of Pattern & Ages of Post-Metamorphism Faults in Part of Northern Piedmont of VA & NC."
MORTON, K. V. Research Contracts Branch FIN A-9027
NRC-04-75-237 79/01/15 2pp
- 7905040028 Forwards response to NRC questions re Mark II improved chugging load definition
BOBON, L. J. General Electric Co MFN-120-79 79/04/30 31pp
- 7905040042 Notification of contract execution, Mod 1 to "Axial Photography for Droplet Size Distribution of Two-Phase Dispersed Flow Through Reactor Grid." Contractor Wichita State Univ
HAGEY, H. Research Contracts Branch FIN B-6250 NRC-04-77-133
79/04/24 1p
- 7905040052 Mod 1, changing period of performance from 790630 to 800630 to "Axial Photography for Droplet Size Distribution of Two-Phase Dispersed Flow Through Reactor Grid."
MORTON, K. V. Research Contracts Branch FIN B-6250
NRC-04-77-133. 79/04/09. 2pp
- 7905040064 Notification of contract execution, Mod 2 to "Meteorological Conditions Unique to Tornado Development Through Proximity Analysis." Contractor Univ of MO
HAGEY, H. Research Contracts Branch. FIN B-6196. NRC-04-77-035.
79/04/24 1p
- 7905040069 Mod 2, changing performance data from 790331 to 790630 to "Meteorological Conditions Unique to Tornado Development Through Proximity Analysis."
MORTON, K. V. Research Contracts Branch FIN B-6196
NRC-04-77-035 79/04/01 2pp
- 7905040079 Notification of contract execution, Mod 5 to "Steady & Transient Natural Convection in Enclosed Fluid Layers w/ Volumetric Energy Sources." Contractor OH State Univ
HAGEY, H. Research Contracts Branch. FIN A-4061. NRC-04-74-149
79/04/24 1p
- 7905040090 Mod 5, changing period of performance from 790331 to 800331 to "Steady & Transient Natural Convection in Enclosed Fluid Layers w/ Volumetric Sources."
MORTON, K. V. Research Contracts Branch FIN A-4061
NRC-04-74-149 79/04/01 2pp
- 7905040098 Application by Kawecki Berylo Industries for license to export Zircaloy tubing to Canada
GILBERT, Y. K. Kawecki Berylo Industries, Inc. 79/04/16 2pp
- 7905040137 License for Transnuclear, Inc to import 22 071 kg U from France.
DPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/04/20 2pp
- 7905040150 Summary of 780712 meeting w/Mark I owners in Bethesda, MD re methodology for defining safety relief valve discharge loads for quencher discharge device & steam condensation observed in full scale test facility (R9-9A Mark I)
GRIMES, G. Plant Systems Branch. 79/04/26 3pp
- 7905040171 Requests Executive Branch position re OE application for license to export components to Belgium, W/o encl.
DPLINGER, G. O. Assistant Director for Export/Import & International Safeguards. 79/04/18. 1p.
- 7905040177 Requests Executive Branch position re Mitsui & Co (USA) application for license to export Zircaloy-4 tube shells to Japan, W/o encl.
DPLINGER, G. O. Assistant Director for Export/Import & International Safeguards. 79/04/18. 1p.
- 7905040186 Requests Executive Branch position re Mitsui & Co (USA) application for license to export Zircaloy-2 tube shells to Japan, W/o encl.
DPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/04/18. 1p.
- 7905040189 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl.
DPLINGER, G. O. Assistant Director for Export/Import & International Safeguards. 79/04/18. 1p
- 7905040207 Comments on proposed rule 10CFR20, Ford, Bacon & Davis approach to intrusion scenario underestimates dose commitments by several orders of magnitude W/encl handwritten notes & article from "Health Physics."
BARD, S. T. Environmental Protection Agency. 79/01/22 10pp.

NONDOCKETED ITEMS

293

7905040247 Comments on proposed rule 10CFR19 & 20: adequate basis does not exist for calling hearing on occupational dose limiting stds. Studies referred to have all been repudiated & proposed exposure limits too low
LEHNER, C. Edison Electric Institute. 79/04/16 2pp

7905040250 Comments on proposed rule 10CFR50: opposes any proposed regulations which permit greater flexibility in meeting public health & safety stds. THM-2 proves need for more regulation
DAVIS, H. A. Affiliation Unknown. 79/04/09. 1p

7905040261 Comments on proposed rule 10CFR50: urges Commission not adopt proposed rule. Reexamination of any relaxation of requirements re nuclear power safety mechanisms should be conducted. THM-2 indicates need for more study
JUSTICE, R. L. Affiliation Unknown. 79/04/03. 1p.

7905040265 Comments on proposed rule 10CFR20 supports revocation of 10CFR20.304
AARDE, H. H. West Virginia, State of. 79/01/15. 1p.

7905040274 Comments on proposed rule 10CFR50. 790328 notice was untimely: opposes streamlining of licensing procedure. Proposal to amend App. II is good as it will protect vessel integrity. Opposes change to App. Q.
ANDREWS, J. C. Affiliation Unknown. 79/04/16. 1p.

7905040283 Comments on proposed rule 10CFR20: encourages proposed changes. Any disposal of radionuclides should be licensed
Affiliation Unknown. 79/04/19. 1p

7905040294 Comments on proposed rule 10CFR20: calendar quarter should be defined as std quarter to avoid use of different dose info reporting periods
RENDERGER, D. L. Washington Public Power Supply System. 79/04/06. 1p

7905040305 Comments on proposed rule 10CFR19 & 20: suggests wording be clarified & replacement of word "dose" w/ "occupational dose" wherever it occurs.
STALLINGS, C. H. Virginia Electric & Power Co. 79/04/06. 5pp

7905040313 Comments on proposed rules 10CFR19 & 20: some airlines use radiotelephones for insp of aircrafts & engines: most ATA member airlines support proposal. Comments from American Airlines & Air Canada encl.
TINKER, E. L. Air Transport Association. 79/04/17. 4pp

7905070016 Comments on proposed rule re new sys of recordkeeping using magnetic tape along w/ transcription of individual interviews w/ NRC employees. believes program may contradict President Carter's wish to reduce govt costs
COONEY, M. J. Affiliation Unknown. 79/03/24. 1p.

7905070042 Ltr of assurance certifying matl mentioned in application for license to export 143.2 mg U containing 133.1 mg U-235, & transfer of this matl is subj to all terms & conditions of 603725 addl agreement for cooperation.
OOPPEL, H. Euratom Supply Agency (Belgium). 79/03/28. 1p.

7905070086 Notification of 790426 meeting w/ OE in Bethesda, MD to discuss two loop test apparatus & model development.
KODGEB, H. W. Analysis Branch. 79/04/20. 1p

7905070094 Responses to NRC 781228 Questions re "Mount Taylor U Mill Project. W/oversized drawings."
Gulf Oil Corp., Gulf Mineral Resources Co. 79/04/13. 46pp

7905070105 Urges issuance of license for GE to export neutron detectors containing U to India to replace failed detectors which might endanger Tarapur reactor safety
WILSON, B. D. General Electric Co. 79/04/23. 1p.

7905070111 Comments on proposed Reg Guide 3.8: reg guide should conform to procedural provisions established by CEQ for NEPA. Portion of environ rept should contain description of mining activities.
HERSLOFF, L. W. Rocky Mountain Energy Co. 79/03/14. 4pp

7905070171 Comments on proposed rulemaking 10CFR20-13: certification by American Board of Health Physics is preferable to NRC certification plan.
DULEY, J. W. Affiliation Unknown. 79/04/12. 2pp.

7905070181 Comments on proposed rulemaking 10CFR20-13: endorses proposition & notes address of Natl Registry of Radiation Protection Technologists.
SMITH, H. P. Affiliation Unknown. 79/04/09. 2pp

7905070201 Forwards "Probable Max Flood from Canon de Marquez watershed for Designing U Tailings Impoundment Drainage Diversion Sys. Marquez, NM." w/ supplemental agreement
TOPP, A. New Mexico, State of. 79/03/30. 6pp

--7905070213 "Probable Max Flood from Canon de Marquez watershed for Designing U Tailings Impoundment Drainage Diversion Sys. Marquez, NM. Bokum Resources Corp."
BIMONS, D. B.; L. R. M. Colorado State Univ. 79/03/30. 34pp

7905070222 Requests P&E supply Northern CA Power Authority w/ names of all persons util deems to have been members of "control group" for periods from which documents claimed as privileged have arisen
ADRAGONA, J. M. Spiegel & McDiarmid. 2. 79/04/04. 2pp

7905070382 Comments on proposed rulemaking 10CFR20-13 opposes petition & believes public certification programs sufficient
KASPERSKI, D. C. Affiliation Unknown. 79/04/10. 1p

7905070406 Comments on proposed rulemaking 10CFR20-13 formal certification of health physicists unnecessary
SCHAFER, K. H. Iowa-Illinois Gas & Electric. 79/04/02. 2pp

7905070417 Comments on proposed rulemaking 10CFR2-6 strongly supports recognition that licensing proceedings should be conducted in timely manner
CASSAN, V. J. Power Authority State of New York. 79/04/06. 3pp

7905070424 Comments on proposed rulemaking 10CFR2-7 opposes petition due to potential for abuse & delays in licensing process
Isham, Lincoln & Beale. 79/04/05. 3pp

7905070432 Comments on proposed rulemaking 10CFR2-7 rejects proposal & suggests more rigid rules & requirements to prevent unnecessary intervention
Affiliation Unknown. 79/04/05. 3pp

7905070442 Comments on proposed rulemaking 10CFR20-13 opposes petition because objectives are currently being achieved under existing regulations. No evidence of need for further regulation
JENSEN, W. H. Detroit Edison Co. 79/04/05. 2pp

7905070495 Forwards initial evaluation of Div of Operating Reactors' fire protection needs for 1980
HALL, R. E. Brookhaven National Laboratory. 79/04/30. 4pp

7905070555 Forwards proprietary rept BAW-10085P, Revision 6, "Reactor Protection Sys."
TAYLOR, J. H. Babcock & Wilcox Co. 79/04/12. 2pp

7905070564 Informs that addl info re ATHS mitigating capability of plants which use C-E NBSS will be submitted approx 790601, rather than 790301
SCHERER, A. E. C-E Power Systems. LD-79-026. 79/05/01. 1p

7905070658 Forwards Revision 3A to QA program rept NU-QA-1
COUNCIL, W. O. Northeast Utilities. QA-3187. 79/04/23. 1p

--7905070660 Accepts Revision 3A to QA Topical Rept NU-QA-1
HAASB, W. P. Quality Assurance Branch. 79/03/13. 2pp

--7905070663 Topical rept evaluation of QA program Rept NU-QA-1 Rept commits util to comply w/ requirements of App. B to 10CFR50
Quality Assurance Branch. 79/03/09. 1p

--7905070666 NU-QA-1
QA program rept, Revision 3A
Northeast Utilities. 79/03/09. 91pp

7905080028 FOIA request for NRC rept & recommendations on petition for rulemaking filed by PIRO
DICKSON, K. B. California, State of. 79/03/28. 1p

7905080031 Response to FOIA request for NRC rept & recommendations on petition for rulemaking filed by PIRO. Forwards relevant info.
FELTON, J. M. Division of Rules and Records. 79/03/01. 1p

--7905080035 SECY-78-13G
Attempts to obtain NRC approval of response to PIRO petition for rulemaking
MINOQUE, R. B. Office of Standards Development. 78/12/19. 9pp

NONDOCKETED ITEMS

- 7905080036 Petition for rulemaking to promulgate regulations for nuclear power plant decommissioning
SCHULTZ, W.B., ABBOTT, J. Public Interest Research Group
77/07/03 11pp
- 7905080040 Forwards comments supporting of petition in response to 770808 NRC notice 42FR40063 Five addl groups have requested inclusion as co-petitioners Forwards amended petition Corrects erroneous listing of J Abbotts as esquire
ABBOTT, J., Public Interest Research Group 77/10/07 7pp
- 7905080047 Forwards comments in support of petition responding to NRC notice of 42FR59374 on 771114 Natl Consumer Law Ctr Energy Project requests participation as co-petitioner
ABBOTT, J., BANCROFT, M.H., SCHULTZ, W.B. Public Interest Research Group 78/01/03 42pp.
- 7905080055 "Water Reactor Research Directorate Monthly Rept." Feb 1979
YBARRONDO, L.J. Idaho National Engineering Laboratory 79/02/28, 200pp
- 7905080070 Transcript of 790418 meeting in Washington, DC Pp 1-33 Initial discussion of upgrade rule & supporting guidance. Supporting documentation encl.
GILINSKY, V., KENNEDY, R.T., BRADFORD, P.A. Commission 79/04/18, 34pp
- 7905080082 BECY-79-187
Discusses strengthened physical protection requirements for fuel cycle facilities & transportation involving formula quantities of strategic SNM Supporting documentation encl
MINOUE, R.B. Office of Standards Development DIRCKB, W.J. Office of Nuclear Material Safety & Safeguards 79/03/16 172pp
- 7905080081 Responds to 790322 ltr re processing site designation for Canonsburg, PA, supporting draft engineering evaluation & environ analysis repts Forwards relevant NRC comments Will arrange meeting as requested
DIRCKB, W.J. Office of Nuclear Material Safety & Safeguards 79/04/18 1p.
- 7905080087 Comments on draft engineering assessment by Ford, Bacon & Davis Utah of former Vitro Rare Metals plant at Canonsburg, PA discusses radioactive contamination & costs of remedial actions
MARTIN, J.B. Assistant Director for Fuel Cycle Safety & Licensing 78/08/21 2pp
- 7905080101 Reviews summary evaluation of radiation exposures for workers at former Vitro Rare Metals plant in response to 781023 request Proposed EPA criteria should be considered in corrective action selection
MARTIN, J.B. Assistant Director for Fuel Cycle Safety & Licensing 78/11/24 1p
- 7905080108 Requests review of encl proposed designation of processing site at Canonsburg, PA. Requests meeting between NRC & DOE to discuss site & other relevant info.
CLUBEN, R.C. Energy, Dept. of. 79/03/22 4pp
- 7905080109 YFBP-TR-209
"PBF-LOCA Test Series, Test LDC-11"
LARSON, J.R., ALLISON, C.M. EO & O, Inc. FIN A-6041. YFBP-TR-209 79/03/19, 87pp.
- 7905080114 Forwards request for addl info to complete review of OE rept, MEDO-21039, "BWR Radioactive Waste Treatment Sys."
PARR, D.D. Light Water Reactors Branch 3. 79/04/19, 2pp.
- 7905080137 Responds to 781226, 790112 & 790202 ltrs noting instances of lack of timeliness & suggestion that policy be implemented for prompt board notification. Forwards sys procedures & case analysis of these failures.
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/04/12, 2pp
- 7905080144 Office Ltr 19 establishing procedures for board notification of relevant & new info Forwards notification procedure, J Yors 780207 memo & A Rosenthal 780208 memo.
CASE, E.O. Office of Nuclear Reactor Regulation. 78/07/06 26pp
- 7905080154 Submits ASLB comments & suggestions re NRC board notification of relevant & new info re licensing cases. Suggests different procedures before & after publication of referenced NRC documents.
YORE, J.R. Atomic Safety and Licensing Board Panel. 78/02/07, 5pp
- 7905080163 ASLAB comments re NRC notification to boards of relevant new info re licensing cases Endorses ASLB suggestion of different procedures before & after publication of NRC documentation
ROSENTHAL, A.B. Atomic Safety and Licensing Appeal Panel 78/02/08 2pp
- 7905080171 Forwards package of info re criteria for buckling of steel containment shells Info judged too preliminary for board notification at this time W/o encl
VASSALLO, D.B. Assistant Director for Light Water Reactors 78/03/29 1p
- 7905080178 Informs that Sihwell memo contains expert opinions which are relevant info for plants w/design concern of steel containment shell buckling Requests identification of cases in hearing process w/similar design criteria
ORDSMAN, M.J. Hearings Division 78/04/10 1p
- 7905080217 Board notification, buckling of steel containment shells Info is still preliminary & NRC position not yet clear Encl question is representative of info supplied to applicants Recommends consideration of free standing steel shells
VASSALLO, D.B. Assistant Director for Light Water Reactors. 78/04/18 2pp
- 7905080230 Board notification buckling of steel containment shells Recommends waiting for results from technical assistance program before making further determination
VASSALLO, D.B. Assistant Director for Light Water Reactors. 78/09/28, 1p
- 7905080249 Expresses puzzlement over reasons for not informing boards re buckling of steel containment shells If info indicates inadequate or nonconservative techniques, boards should be informed
SCINTO, J.F. Hearings Division 78/10/11, 1p
- 7905080259 Board notification, containment buckling. Forwards backup info from original memo & list of boards to be notified. Backup info consists of Allens Creek PSAR questions & answers
VASSALLO, D.B. Assistant Director for Light Water Reactors 78/10/31 7pp
- 7905080263 Notes draft rept on containment buckling is preliminary & will be greatly revised before issuance in Feb 1979. Suggests NRC wait until final rept is issued before notifying board. Supporting info encl
SCHAUER, F. Structural Engineering Branch 79/01/11 10pp
- 7905080278 Board notification EDO, Inc analysts on asymmetric loads Suggests forwarding encl R Stiger 771104 memo to boards for PWR plants. Sample forwarding ltr encl.
VASSALLO, D.B. Assistant Director for Light Water Reactors. 78/02/24 6pp
- 7905080286 Notes delay of almost one year for release of rept questioning steel containment buckling criteria NRC should promptly transmit such data to licensing boards & public.
ROISMAN, A.Z. Natural Resources Defense Council. 78/12/26 2pp
- 7905080296 Forwards I Sihwell 780130 memo re need to notify ACRS & licensing boards on containment buckling criteria. Memo underscores problems outlined previously.
ROISMAN, A.Z. Natural Resources Defense Council. 79/01/12 1p
- 7905080139 Forwards MI House of Representatives resolution demanding investigation re allegations of safety problems at plants in state.
BRYANT, W.R. Michigan, State of. 79/04/12, 3pp
- 7905080165 Requests Executive Branch position re GE application for license to export 18,432 kg U to Spain
OPLINGER, O.O. Assistant Director for Export/Import & International Safeguards. 79/04/23 1p.
- 7905080174 Forwards application by Transnuclear, Inc for license for minor nuclear export Ltr of assurance required.
OPLINGER, O.O. Assistant Director for Export/Import & International Safeguards 79/04/24 1p
- 7905080190 Forwards 790409 export license amend request W/o encl.
OGBICK, L.V. Office of the Executive Director for Operations. 79/04/24, 1p.

NONDOCKETED ITEMS

295

- 7905080219 Comments on proposed Reg Guide 1.144 frequency of audits should be established based upon type of activity, experience & other relevant factors ANSI N43.2 12-1977 provides such latitude
LINO, J. American Society of Mechanical Engineers 79/03/23. 2pp
- 7905080242 Forwards "Operating Procedure Guidelines for Small Breaks" w/background info that will be used as training aid for operators.
TAYLOR, J.H. Babcock & Wilcox Co. 79/03/05 28pp
- 7905080364 Forwards 790426 documents re B&W transient & accident analysis methods
MATTSON, R.J. Division of Systems Safety. 79/04/26. 1p
- 7905080372 Forwards background info re B&W operating plant response to transients w/postulated equipment malfunctions. B&W will submit detailed analyses per schedule to be decided at 790426 meeting w/NRC
RDY, D.H. Babcock & Wilcox Co. 79/04/26. 64pp
- 7905080393 Forwards results of LOFT Test L2-3 in response to NRC 790117 ltr
OWSLEY, O.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 79/04/30 81pp
- 7905080405 Forwards handouts from 790208 midyear review & subsequent program review meetings on ORNL safety-related operator action study handouts include preliminary results re operator time margin
FARMER, W.B. Research Support Branch 79/04/13 11pp
- 7905080440 Forwards "Test Results For Solenoid Valve Performance Test," final rept, NEDE-23887, per F. Clementson request.
SHERWOOD, D.Q. General Electric Co. MFN 110-79. 79/05/01 1p
- 7905080442 NEDE-23887
"Test Results For Solenoid Valve Performance Test," final rept.
General Electric Co. 78/04/30 19pp
- 7905090004 Lists all NRC contracts & repts of 1978-79 re low level radioactive waste
Commission 79/04/23 3pp
- 7905090011 FOIA request for 1978 diary, calendar & telephone log of Commissioner Olinisky
MANN, J.R. Affiliation Unknown. 79/04/02 1p
- 7905090013 Response to FOIA request for 1978 diary, calendar & telephone log of Commissioner Olinisky. Commissioner does not maintain telephone log or diary. Calendar is being placed in PDR
FELTON, J.M. Division of Rules and Records 79/05/01 1p
- 7905090014 Notice of 790315 meeting w/ACRB Subcommittee on Fort St Vrain Nuclear Power Station, util & NRC staff on Longmont, CO to review operating experience, refueling operations & proposed mode for facility.
HOYLE, J.C. ACRB - Advisory Committee on Reactor Safeguards. 79/02/22. 2pp
- 7905090018 Notice of proposed meetings from 790223-790512 of ACRB subcommittees & working groups.
HOYLE, J.C. ACRB - Advisory Committee on Reactor Safeguards. 79/02/22. 3pp.
- 7905090023 Notice of proposed meetings from 790323-790719 of ACRB subcommittees & working groups meetings from 790323-0719.
HOYLE, J.C. ACRB - Advisory Committee on Reactor Safeguards. 79/03/20 3pp.
- 7905090025 FOIA request for info re const of proposed nuclear power plants before year 2000, specific locations, svc areas & MW output of each plant.
DOWNES, L.T. Affiliation Unknown. 79/04/16 2pp.
- 7905090028 Revised notice of 790405-07 meeting of ACRB & NRC in Washington, DC to discuss basis for shutting down five nuclear plants to resolve piping questions. Revision cites changes in meeting schedule.
HOYLE, J.C. ACRB - Advisory Committee on Reactor Safeguards. 79/03/26. 3pp.
- 7905090030 Response to FOIA request for info re proposed const of nuclear power plants to be built by year 2000 & info concerning presently operating plants. Forwards site map
FELTON, J.M. Division of Rules and Records. 79/04/27. 1p
- 7905090031 "PA 37 Pipe Rupture Study".
CLARKE, W.L. General Electric Co. NRC-04-75-202. 79/03/09. 4pp.
- 7905090032 FOIA request for outline of NRC structural organization, nature of administration's existence, basic health & safeguards stds & "important post" & present cases
CONLEY, M.E. Affiliation Unknown 79/03/18 1p
- 7905090034 Response to FOIA request for records re NRC organization health & safeguards stds & "important" cases. Lists documents available from OPO
FELTON, J.M. Division of Rules and Records. 79/04/25 2pp
- 7905090048 NUREG-0553
"Cost & Funding of State & Local Govt Radiological Emergency Response Plans & Preparedness in Support of Commercial Nuclear Power Stations"
BALDWIN, B. Office of State Programs. 79/03/30. 131pp
- 7905090111 Transcript of 790329 public meeting in Washington, DC re continuation of discussion of SECY-79-34A, final rept "Regulation of Federal Radioactive Waste Activities." Pp 1-51. SECY-79-34C encl.
HENDRIE, J.M., OILINSKY, V., KENNEDY, R.T. Commission. 79/03/29 52pp.
- 7905090117 SECY-79-034C
Provides followup to NRC requirements re initial briefing on SECY-79-34A, draft rept, "Regulation of Federal Radioactive Waste Activities"
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/03/26 2pp
- 7905090158 Responds to request for info re W Peoples 790221 ltr protesting 10CFR71, App E because its packaging requirements are unjustified. Requirements apply generally to shippers of fissile matl & Type B quantities
CORNELL, E.K. Office of the Executive Director for Operations. 79/04/02 6pp
- 7905090161 Minutes & apps of 781207-09 224th ACRB meeting in Washington, DC re NRC safety research program (NUREG-0496), ATM resolution & combination of dynamic loads in nuclear facilities design. FR notice of meeting encl.
ACRB - Advisory Committee on Reactor Safeguards 78/12/09 150pp.
- 7905090163 "Application of Internal Friction Nondestructive Evaluation Technique for Detecting Incipient Cracking of Bypass Lines & Pipes in BWR Piping" Progress Rept 9.
YEAGER, L.L. Daedalus Associates, Inc. NRC-04-78-242 79/04/09. 11pp.
- 7905090168 Forwards generic letter to all BWR licensees re relief & safety relief valves which are installed in reactor coolant sys &/or automatic depressurization sys
CLEMENSON, F. Plant Systems Branch 79/04/05 1p.
- 7905090171 Concludes that implementation of requirement for increased surveillance testing is not most effective way of assuring safety relief valve reliability. Requests answers to questions re target rock safety relief valves.
ORFIER, B.K. Assistant Director for Engineers & Projects. 79/04/05. 4pp.
- 7905090176 Comments on proposed Reg Guide 3.8, Revision 1: recent CEG rule for EIS should be reviewed. Changes in EIS process could be used in guide.
WOLFF, T. New Mexico, State of. 79/03/16 3pp.
- 7905090192 Notification of ACRB Subcommittee on Waste Mgt 790418-19 meeting w/NRC to discuss re vitrification
CHILK, B.J. 2pp
- 7905090194
790426-28
review 19
CHILK, B.J.
2pp.
- 7905090197
instrumt
BLOTCY,
2pp
- 7905090203
for Nucl
arrestor
alternat
THORPE, J
- 7905090205
Plant:
GFI

NONDOCKETED ITEMS

- 7905090354 Preliminary value/impact assessment supporting draft reg guide, "Lightning Protection for Nuclear Power Plants" "Proposed Alternate Regulatory Position" encl
* Office of Standards Development. 78/12/12 1p.
- 7905090261 Comments on proposed Reg Guide 8.8, Revision 4: notes editorial mistakes re certain footnotes
WEBER, M D American Nuclear Society. 79/04/12 1p.
- 7905090262 Comments on proposed Reg Guide 3.5 believes NRC should address only radiation safety & not general safety
No need for detailed corporate organization repts in application if general competence is described
YELDERMAN, J C US Steel Corp. 79/03/19 3pp.
- 7905090266 Notice of 790329 meeting of ACRS Subcommittee on Palo Verde Nuclear Generating Station: Units 4 & 5, its consultants & NRC staff in Washington, DC to review const application
HOYLE, J. C. ACRS - Advisory Committee on Reactor Safeguards 79/03/08 2pp
- 7905090267 Notice of date change of meeting of ACRS Subcommittee on Evaluation of LERs in Washington, DC from 790323-24 to 790322-24.
HOYLE, J. C. ACRS - Advisory Committee on Reactor Safeguards. 79/03/09 1p
- 7905090268 Forwards Revision 1 to MPL-TOP-1A, "Operational QA Manual," per NRC 781211 instructions
REAVES, T E Mississippi Power & Light Co. AECH/79-36. 79/03/01 1p
- 7905090271 "Operational QA Manual"
STAMPLEY, N L Mississippi Power & Light Co 79/05/03 18pp.
- 7905090270 Notice of 790403 meeting of ACRS Subcommittee on Combination of Dynamic Loads, its consultants & NRC in Washington, DC to review technical basis of order to shut down five plants w/safety-related piping nonconformities
HOYLE, J. C. ACRS - Advisory Committee on Reactor Safeguards. 79/03/15 2pp.
- 7905090276 Notice of 790323-24 meeting of ACRS Subcommittee on Evaluation of LERs, its consultants & NRC staff in Washington, DC to review LERs of 1976-78
HOYLE, J. C. ACRS - Advisory Committee on Reactor Safeguards 79/03/01 2pp
- 7905090290 Forwards review of updated WCAP-B691, "Fuel Rod Bowing." Acceptable basis has been provided for calculating critical heat flux on bowed rods
STOLZ, J F Light Water Reactors Branch 1 79/04/05 1p.
- 7905090294 Topical rept evaluation of WCAP-B691, "Fuel Rod Bowing" Rept provides acceptable data base for critical heat flux bowed to 85% of bow necessary for contact
* Light Water Reactors Branch 1 79/04/05, 9pp.
- 7905090306 Details changes to Tech Specs re use of reflector elements & fuel element positions
BALDWIN, M. M. Babcock & Wilcox Co 79/03/02, 2pp
- 7905090327 Summary of 790426 meeting w/Westinghouse to discuss capabilities of natural circulation for Westinghouse plants. Forwards responses to questions raised re power operated pressuriser relief valve opening
ANDERSON, T. M. Westinghouse Electric Corp NS-TMA-2078. 79/03/01. 8pp
- 7905090366 Due to increased workload from TH1, ATWS data per NRC 790215 request will be submitted 790501.
ANDERSON, T. M. Westinghouse Electric Corp. NS-TMA-2077. 79/03/01. 1p.
- 7905090396 Notification of contract execution: "Design of NRC Supply & Maint Modules of Property & Supply Sys." Awarded to Small Business Administration & subcontract awarded to Rehab Group, Inc.
HAGAN, T. F. Administrative Contracts Branch. NRC-10-79-378. 883-44-8A79C44. 79/04/03. 1p.
- 7905090399 Contract for "Design of NRC Supply & Maint Modules of Property & Supply Sys." awarded to Small Business Administration & subcontract awarded to Rehab Group, Inc.
MATTIA, M. J. Administrative Contracts Branch. NRC-10-79-378. 79/03/19. 12pp.
- 7905090401 NUREG/CR-0253
"CONTENT-PT-LT/028: Computer Program for Predicting Containment Pressure-Temp Responses to LOCA."
HARROVES, D. W., METCALFE, L. J. EG & O, Inc. FIN A-6009. 79/03/31. 24pp. Available at NTIS
- 7905090406 NUREG/CR-0728
"Test Plan Large Scale Molten Salt-Water Vapor Explosion Studies to be Conducted at Ispra, Italy"
HENRY, R. E. Argonne National Laboratory FIN A-2026 79/02/28 27pp Available at NTIS
- 7905090408 NUREG/CR-0390
"An Evaluation of Fuel Rod Behavior During Test LOC-11."
COOK, T. F. EG & O, Inc. FIN A-6041 79/03/31 105pp Available at NTIS.
- 7905090413 Forwards NRC computer security program/responses to GAO recommendations & NRC Manual Chapter 2101 "NRC Security Program"
HENDRIE, J. M. Commission 79/04/12 87pp
- 7905090416 Comments on proposed Reg Guide 1.2B, Revision 2 language of ANSI N45 2-1977 should be maintained. Requirements for specific procedures eliminate desirable flexibility.
SULLIVAN, T. J. Consumers Power Co 79/04/03 1p
- 7905090417 NUREG/CR-0754
"An Exploratory Study of Inhibition of Intergranular Stress Corrosion Cracking in Sensitized Type 304 Stainless Steel."
BROWN, B. F., O'DELL, C. B., FOLEY, R. T. American Univ. FIN B-5607 79/04/30. 125pp Available at NTIS
- 7905090422 NUREG/CR-0642
"Ref Critical Experiments," progress rept Oct-Dec 1978
GOSBEL, O. R., OH, I., PECORA, D. Rockwell International Corp. FIN A-1036 RFP-2888 79/04/30 39pp
- 7905090428 NUREG/CR-0454
"Effects of Nuclear Power Plants on Community Growth & Residential Property Values," final rept, 770930-781115
GAMBLE, H. B., DOWNING, R. H., BAUERLENDER, O. H. Pennsylvania State Univ. FIN B-6173 79/04/30 85pp Available at NTIS #6 00.
- 7905090430 Comments on proposed rule 10CFR50 re acceptable criteria for ECRS for LWRs, supports relevant research & forwards list of research repts
LEVENSON, M. Electric Power Research Institute 79/03/19 11pp.
- 7905090431 Comments on proposed rule re generic rulemaking to improve nuclear power plant licensing/agrees w/NRC proposed change & forwards suggestions
HEDEMAN, N. N. Environmental Protection Agency. 79/03/15 4pp.
- 7905090433 Comments on proposed rule re generic rulemaking to improve nuclear power plant licensing, endorses concept if it does not delay or cause expensive & complicated backfits on plants already in licensing process.
LINBLAD, W. J. Portland General Electric Co. 79/03/09 3pp.
- 7905090435 Comments on proposed rulemaking 10CFR2-7: proposed change has potential for addl costs & delays w/o corresponding benefits to public. Should not be adopted
BAUM, E. A. Virginia Electric & Power Co. 154 79/03/20. 2pp.
- 7905100004 Forwards corrected motion to reschedule RH Qerdes deposition on 790326. Certificate of Evc encl.
STREBEL, B. J. Spiegel & McDiarmid. 79/04/12 1p.
- 7905100007 Corrected motion for rescheduling of RH Qerdes deposition served on 790326. Certificate of Evc encl.
MATT, P. K., STREBEL, B. J. Spiegel & McDiarmid. 79/04/12 7pp.
- 7905100020 Transcript of 790419 briefing in Washington, DC on operational safety data-gathering & analysis. Pp 1-99.
GILINSKY, V., BRADFORD, P. A., KENNEDY, R. T. Commission. 79/04/19. 100pp.
- 7905100026 Requests briefing on operational safety data-gathering & analysis. Outline & relevant LER encl
CHILK, S. J. Office of the Secretary of the Commission. 79/02/22 13pp.
- 7905100030 SECY-79-207
Proposes ltr be prepared from Secretary denying Kranish FOIA Appeal 79-A-3. Ltr should state that deleted portions are properly classified.
BICKMIT, L. Office of the General Counsel 79/03/23 3pp.
- 7905100045 Responds to FOIA 781107 request for transcript of 781106 Commission meeting re Qossick testimony. Portions of transcript withheld. Appeal possible.
FELTON, J. M. Division of Rules and Records. FOIA-78-318 79/03/01. 1p.

NONDOCKETED ITEMS

297

- 7903100047 Commission determination re public disclosure of 781106 transcript of Gossick testimony Portions of record withheld.
CHILK, S J Office of the Secretary of the Commission 79/02/26, 1p
- 7903100050 Appeals deletions from 781106 Commission meeting transcript supplied in response to FOIA 78-310.
KRANISH, A Trends Publishing, Inc 79/03/09 1p
- 7903100408 Responds to 790309 appeal of initial determination in FOIA 78-318 requesting transcript of Commission meeting on 781106 Govt in Sunshine Act precludes making deleted portions available
CHILK, S J Office of the Secretary of the Commission 79/03/09 1p
- 7903100021 "Steamline Rupture Analysis for Generic C-E Plant (Including Concurrent Steam Generator Tube Rupture) Phase 1."
CONNELL, H R., LEVINE, M M., BHIER, W O Brookhaven National Laboratory. FIN A-3005 BNL-NUREG 25855 79/03/31. 72pp.
- 7903100023 Informs of circuit breaker failure indicating defects affecting safety of nuclear power plants Shaft mounting ratcheting driving pawl broke at weld & cotter pin securing latching pawl shaft broke
CONNORS, J E Golden Gate Switchboard Co 79/03/30 3pp.
- 7903100028 Responds to 790316 ltr re Lewis rept. Would welcome opportunity to meet & discuss issue in future
Testimony of HR Denton on 790321 before Congress encl.
HENDRIE, J M Commission 79/04/23 1p.
- 7903100032 Believes NRC press release of 790119 was major source of confusion since positive findings of Lewis rept were not mentioned & release put entire WASH-1400 on same level as executive summary.
HJDBSON, O R Illinois, State of 79/03/16. 3pp
- 7903100035 Transcript of 790321 statement before Subcommittee on Energy & Water Development re computer code readings on seismic design of pipe stress analysis Supporting documentation encl
DENTON, H R. Office of Nuclear Reactor Regulation 79/03/21. 52pp.
- 7903100036 Forwards notice of denial of petition for rulemaking re amending 10CFR20, "Btde for Protection Against Radiation."
Reg guide will be issued to clarify meaning of regulation
HINOQUE, R B Office of Standards Development. 79/04/05 1p
- 7903100043 Forwards relevant press releases & preliminary notifications issued to date in response to 790330 telex re TMI incident
KAMMERER, C. Office of Congressional Affairs. 79/04/10 4pp.
- 7903100049 Ack receipt of 790406 ltr re info on nuclear safety & emergency evacuation plans.
KAMMERER, C. Office of Congressional Affairs. 79/04/10. 4pp
- 7903100051 Ack receipt of 790402 ltr requesting security status rept on security at Oconee 1, 2 & 3 in light of TMI incident
KAMMERER, C. Office of Congressional Affairs. 79/04/10. 4pp.
- 7903100053 BECV-79-270
Forwards for Commission consideration application from Edlow Intl Co for license to export U hexafluoride to Argentina
BHEA, J R Office of International Programs. 79/04/16. 1p
- 7903100056 Recommends license be granted to Westinghouse to import 92.281 kg U from Sweden Requests notification of licensee.
CHILK, S J. Office of the Secretary of the Commission. 79/04/20. 1p.
- 7903100059 Draft evaluation of Bokum Resources proposal will not include radiological assessment section due to insufficient info.
SCARANO, R. A. Assistant Director for Waste Management (Pra 790301). 79/04/09. 1p.
- 7903100082 Forwards JR Cavanaugh 790403 ltr expressing support for federal central status ctr for US nuclear plants Requests info necessary for reply.
PRICE, M. House of Rep. 79/04/09. 5pp.
- 7903100090 Minutes of ACRB A/E Balance of Plant Subcommittee 790126 meeting in Washington, DC to review Fluor Power Svcs, Inc BOPBAR & relationship to B&W Std Ref Bys BBAR-205 for preliminary design approval
ACRB - Advisory Committee on Reactor Safeguards. 79/01/26. 16pp.
- 7903100091 Ack receipt of 790330 ltr re TMI incident Complete response will be forwarded as soon as possible Forwards NRC press releases & preliminary notifications re incident
KAMMERER, C. Office of Congressional Affairs. 79/04/10 3pp.
- 7903100101 Responds to 790319 ltr Northern CA Power Authority (NCPA) does not agree that it is time to move ahead w/previously authorized discovery directed toward individual NCPA member NCPA will not permit until to search member city files
MCDIARMID, R C Spiegel & McDiarmid 79/03/30 2pp
- 7903100136 Ack receipt of 790405 ltr re TMI incident Complete response will be forwarded as soon as possible Forwards NRC press releases & preliminary notifications re incident
KAMMERER, C. Office of Congressional Affairs. 79/04/10 3pp
- 7903100138 Supports AGLB 7900125 order denying Southern CA Edison Co's 790305 motion to quash subpoena duces tecum. Supporting documentation & Certificate of Svc encl
OCLDBERG, J, VOLGER, B H Anti-Trust Division 79/04/18 49pp
- 7903100142 Response by util to NRC & intervenors' preliminary comments re commitments. Discusses specific suggested changes to commitments Supporting documentation & Certificate of Svc encl.
DOYLE, M H, ARMSTRONG, W H, HATTIS, M J McCutchen, Doyle, Brown & Emerson 79/04/16 130pp
- 7903100153 Forwards revision to HPI operator instructions per IE Bulletin 79-05a
TAYLOR, J H Babcock & Wilcox Co. 79/04/17. 3pp.
- 7903100159 Ack receipt of 790402 ltr re TMI incident. Complete response will be forwarded as soon as possible Forwards relevant releases & preliminary notifications.
KAMMERER, C. Office of Congressional Affairs. 79/04/09 3pp
- 7903100166 Requests info re design or operational problems generic to B&W facilities & relationship to similar problems experienced at TMI.
FAZIO, V House of Rep. 79/04/02. 3pp
- 7903100165 NUREG/CR-0643
"Matl Compatibility Tests for LOFT Nuclear Reactor Fuel Centerline Thermocouples"
CHAN, A I., MEYERS, S C, BEUTLER, P B Hanford Engineering Development Laboratory. FIN B-6228. HEDL-TME-78-75 79/03/31. 63pp
Available at NTIS. \$5.25.
- 7903100176 Ack receipt of 790403 ltr re safety of South TX project in light of TMI
KAMMERER, C. Office of Congressional Affairs. 79/04/10. 3pp
- 7903100185 Forwards third submittal to App D of NEDE-24011-P-A: "Generic Reload Fuel Application" Encl withheld (ref 10CFR2.790).
QUIRK, J F. General Electric Co., Nuclear Energy Products Div. MC 682. 79/02/08 2pp
- 7903100190 NUREG/CR-0736
"Transportation of Radioactive Matl in IL." 770606-780606
* Illinois, State of. 79/04/30 30pp. Available at NTIS \$4.50.
- 7903100194 Forwards second submittal to App D of NEDE-24011-P-A: "Generic Reload Fuel Application" Encl withheld (ref 10CFR2.790).
QUIRK, J F. General Electric Co., Nuclear Energy Products Div. MC 682. 79/02/28. 4pp.
- 7903100198 In response to 790401 ltr re TMI incident, forwards press release & preliminary notifications issued to date & NRC response to Governor Brown's request to close Rancho Seco.
KAMMERER, C. Office of Congressional Affairs. 79/04/10. 3pp.
- 7903100213 NUREG/CR-0573
"Radiation Dose Estimates & Hazard Evaluations for Inhaled Radionuclides," annual progress rept, July 1977-June 1978.
MEWHINNEY, J A Lovelace Biomed & Environmental Research Institute. LF-63. 79/03/31. 84pp. Available at NRC. \$7.00.
- 7903100218 Ack receipt of 790402 ltr re TMI incident. Complete response will be forwarded as soon as possible. Forwards NRC press releases & preliminary notifications re incident.
KAMMERER, C. Office of Congressional Affairs. 79/04/09. 3pp.
- 7903100229 NUREG/CR-0724
"Study of Reverse Osmosis Applicability to LWR Radwaste Processing."
MARKIND, J., VAN TRAN, T. Abcor, Inc. 79/04/30. 132pp. Available at NTIS. \$7.25.

NONDOCKETED ITEMS

- 7905100230 Supplements 790117 ltr Licensing action on application for export of components to the Philippines not yet completed
Case presently under consideration
SHEA, J.R. Office of International Programs 79/04/27. 1p
- 7905100240 NUREG/CP-0005
"Proceedings of Conference on High Level Radioactive Solid Waste Forms Dec 19-21, 1978 at Denver, CO"
CASEY, L.A. Office of Nuclear Material Safety & Safeguards 78/12/19 800pp. Available at NTIS. \$21.50
- 7905100243 "Biocide Byproducts in Aquatic Environ," quarterly progress rept for Oct-Dec 1978
ANDERSON, D.R., BEAN, R.M., QIBSON, C.I. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-209B-9. PNL-2931. 79/03/31 41pp
- 7905100253 NUREG-0380 V3 N4
"Program Summary Rept." Vol 3, No 4
* Office of Management and Program Analysis 79/04/20 103pp
Available at NTIS \$12.50.
- 7905100264 On behalf of Marubeni Canada, Ltd. requests extension of expiration date of License XU-B395 to 800401 To date, 50,000 kg U-308 exported against license
HARMON, D.W. Edlow International Co 79/03/13 7pp
- 7905100268 Comments on proposed draft reg guide "Qualification of QA Program Audit Personnel for Nuclear Power Plants" ASME code activities would be excluded in ANSI/ASME N45 2.23 unless otherwise indicated.
TRIMBLE, D.C. Arkansas Power & Light Co 019-4 79/03/23 1p
- 7905100277 Summary of 790226-27 meeting w/QA Co in San Diego, CA re QC/FBR & HTROR program descriptions, licensing overview, R&D programs & inservice insp requirements.
WILLIAMS, P.M., MEYER, J.F. Advanced Reactors Branch. 79/04/17 14pp.
- 7905100278 Weekly info rept for week ending 790420
REHM, T.A. Office of the Executive Director for Operations 79/04/27 27pp
- 7905100287 Requests info re application for license to export to IAEA .22 microgram Pu-239 & whether or not it is subj to terms of US-IAEA agreement for cooperation
PETERSON, M. Office of International Programs 79/03/01. 1p
- 7905100323 Ltr of assurance in response to NRC 790322 ltr re Reuter-Stokes application for license to export U-235 to Norway. Transfer will be subj to all terms & conditions of 670608 agreement for cooperation.
RINDAL, A. Norway. 79/03/30. 2pp
- 7905100330 Summary of 780620 meeting w/Sacramento Municipal Util District & B&W re cooldown transient of 780320
ZMETZLO, G.B. Operating Reactors Branch 4. 78/07/13. 6pp
- 7905100343 Ack receipt of 790330 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900400/79-01.
POTAPOV, V. Region 4, Dallas, Vendor Inspection Branch. 79/04/11 1p.
- 7905100351 Responds to NRC 790301 ltr re deviation noted in QA Program Insp Rept 99900400/79-01. Corrective actions: change inquiry/ authorization is being processed to correct design inconsistencies & review of contracts will be conducted
MACMILLAN, J.H. Babcock & Wilcox Co 79/03/30. 4pp.
- 7905100356 Forwards QA Program Insp Rept 9900400/79-01 on 790212-16 & notice of deviation.
POTAPOV, V. Region 4, Dallas, Vendor Inspection Branch. 79/03/01. 2pp
- 7905100360 Notice of deviation from insp on 790212-16
* Region 4, Dallas, Vendor Inspection Branch. 79/02/26. 1p
- 7905100366 QA Program Insp Rept 99900400/79-01 on 790212-16. Noncompliance noted, equipment spec & sys description valves for safety-related sys did not agree w/sys requirements spec.
ANDERSON, D.O., HALE, C.J. Region 4, Dallas, Vendor Inspection Branch. 79/02/26. 10pp.
- 7905100358 Requests extension of expiration date for export license XBNM-1270 from 790801 to 800801.
MATSON, V. Transnuclear, Inc. 79/04/04. 1p.
- 7905100410 Forwards QA Program Insp Rept 99900521/79-01 on 790226-0301 & notice of deviation
POTAPOV, V. Region 4, Dallas, Vendor Inspection Branch 79/03/09 2pp
- 7905100413 Notice of deviation from insp on 790226-0301
* Region 4, Dallas, Vendor Inspection Branch 79/03/08 1p
- 7905100418 QA Program Insp Rept 99900521/79-01 on 790226-0301
Noncompliance noted Section 11 of project internal procedures manual not revised by 790129 as committed.
BRICKLEY, R.H., HALE, C.J. Region 4, Dallas, Vendor Inspection Branch. 79/03/08 6pp
- 7905100415 SECY-79-269
Forwards, for Commission consideration, application from Transnuclear, Inc for license to export U-235 to the Netherlands.
SHEA, J.R. Office of International Programs 79/04/16 1p
- 7905100417 Forwards application for license to export U-235 to the Netherlands
MATSON, V. Transnuclear, Inc 79-121/01. 79/04/11 1p
- 7905100424 Forwards Abnormal Occurrence 50-312-75-3 for Rancho Seco 1.
* Sacramento Municipal Utility District 75/03/11. 1p.
- 7905100430 Abnormal Occurrence 50-312-75-3 on 750212, turbine/generator tripped when overspeed trip relay became falsely de-energized due to caliber drift Faulty transmitter replaced
* Sacramento Municipal Utility District 75/03/11 1p
- 7905100436 Informs of review completion of util data re 780320 reactor trip & resultant cooldown transient Concurs w/util's intent to return plant to power operation at level below 75% full power, w/certain recommendations
JANIS, J.T. Babcock & Wilcox Co 78/03/23 2pp
- 7905100445 Confirms transfer of lead responsibility made verbally 781223 re steam generator level control during auxiliary feedwater operation
JORDAN, E.L. Division of Reactor Operations Inspections. IE, ROI, TP-79-01. 79/01/16 2pp
- 7905100447 License for Hoke, Inc to export bellows sealed instrument isolating valves to Canada.
OFLINGER, O.O. Assistant Director for Export/Import & International Safeguards 79/04/27. 1p
- 7905100453 Requests extension of License XBNM-909 from 790501 to 781231.
KEENAN, R.P. Westinghouse Electric Corp. 79/03/19. 1p.
- 7905100456 Comments on proposed rulemaking 10CFR20-13: petition should be denied. Supports certification of health physics personnel, although NRC should not have function of certification.
SHOOP, P.R. International Brotherhood of Electrical Workers. 79/04/09. 2pp.
- 7905100453 Project on structural integrity of water reactor pressure boundary components, monthly progress rept for Mar 1979.
LOSS, F.J. Navy, Dept of, Naval Research Laboratory. 79/04/10 6pp
- 7905100455 Comments on potential effect of loop seals in a pressurizer surge line, greater emphasis must be placed on this matter in light of TMI-2
NOVAK, T. Reactor Systems Branch. 78/01/10. 1p.
- 7905100460 Comments on potential effects of loop seals in a pressurizer surge line, recommends bases for design requirement be studied for all CP reviews to determine if loop seal can be eliminated.
NOVAK, T. Reactor Systems Branch. 78/01/10. 2pp.
- 7905100461 Presents Analysis Branch contribution to task group evaluation of protection of operating B&W plants against feedwater transients. Info typically provided is not sufficient.
ROBZTOGZY, Z.R. Analysis Branch 79/04/10. 9pp.
- 7905100464 Assigns R Tedesco as group leader of Task Group on Generic Review of Feedwater Transient in B&W-Designed Reactors.
CASE, E. Office of Nuclear Reactor Regulation. 79/04/09 1p

NONDOCKETED ITEMS

299

7905110094 Forwards WCAP-9402, "Verification Testing & Analyses of 17x17 Optimized Fuel Assembly," nonproprietary
ANDERSON, T.M. Westinghouse Electric Corp NS-YNA-2074. 79/04/27 1p.

--7905110098 WCAP-9402 (NF)
"Verification Testing & Analysis of 17x17 Optimized Fuel Assembly," nonproprietary
KRAMER, F.W., CADEX, F.F., ANDERSON, T.M. Westinghouse Electric Corp 79/03/31 70pp

7905110116 Clarifies uncertainties re ODYN evaluation & proposed licensing basis Evaluation completed re neutron effective void correlation uncertainty Evaluation withheld (ref 10CFR2.790) Affidavit encl
COOK, K.W. General Electric Co MFN 123-79 79/04/30 6pp

7905110137 Comments on proposed rulemaking 10CFR2-6, endorses petition.
STEVENS, J.R. New England Power Co. 79/04/06 2pp

7905110141 Comments on proposed rulemaking 10CFR2-7, it would only serve to complicate already rigorous licensing process
Streamlining of nuclear plant licensing procedures is needed
SZALINSKI, P.A. Affiliation Unknown 79/03/28. 1p

7905110143 Board notification BN-79-10, reactor inspector concerns re B&W plants Recommends Boards be notified Supporting documentation encl.
VASSALLO, D.B. Assistant Director for Light Water Reactors 79/03/06. 5pp.

7905110145 Comments on proposed rulemaking 10CFR2-7, present rules re intervention are adequate.
PRINCE, R.J. Affiliation Unknown. 79/03/26 1p

7905110146 Comments on proposed rulemaking 10CFR2-7 opposes amend; wording of "good cause" is vague.
FINK, J.K. Affiliation Unknown. 79/04/02. 1p.

7905110150 Comments on proposed rulemaking 10CFR20-13, would place unjustified & potentially unsafe requirements on operation emergency planning.
MANDTH, L.K. Arizona Public Service Co. 79/04/06. 2pp.

7905110154 Forwards charter & member list of Task Group on Generic Review of Feedwater Transients in B&W Designed Reactors
DAVIS, D.K. Systematic Evaluation Programs Branch. 79/04/02 2pp

7905110179 Forwards info on possible nuclear incidents in USSR. Proposes briefing by DRNL.
QILINSKY, V. Commission. 79/04/23. 7pp.

7905110180 Discusses Tech Specs for reactor coolant sys heatup & cooldown rates & pressure/temp limits.
STELLO, V. Division of Operating Reactors. 78/04/17. 2pp.

7905110182 Ack receipt of 790414 memo defining matl subj to FOIA request Requests clarification re personal diaries & tapes.
QILINSKY, V. Commission 79/04/16 1p.

7905110208 Summarizes status of HEW briefing, evacuation plan & talks w/Governor Brown re B&W reactor problem
QILINSKY, V. Commission 79/04/03. 1p.

7905110224 Requests views on Rositocz 790410 memo re feedwater transients.
QILINSKY, V. Commission. 79/04/12. 1p

--7905110226 Presents Analysis Branch contribution to task group evaluation of generic feedwater transients in B&W reactors
ROBITOCZY, Z.R. Analysis Branch. 79/04/10. 9pp

7905110239 Determines that little benefit would result from reducing all B&W plants to 50% power should event similar to TMI occur.
TEDESCO, R.L. Assistant Director for Plant Systems 79/04/04. 2pp.

7905110283 Tabulates reactor safety research supplemental funding.
MURLEY, T.E. Division of Reactor Safety Research. 79/04/24. 3pp.

7905110288 Forwards "C-E Best Estimate Pre-Test Analysis of LOFT Test L2-3,"
BCHNER, A.E. C-E Power Systems, LD-79-029. 79/03/08. 1p.

--7905110294 LD-79-029
"C-E Best Estimate Pre-Test Analysis of LOFT Test L2-3,"
May 1979
* C-E Power Systems 79/03/08 56pp

7905110341 Moves for postponement of 790402 deadline for discovery & 790418 prehearing conference due to TMI incident.
SCOTT, B.H. Texas Public Interest Research Group 79/04/05. 3pp

7905110342 Motion for postponement of 790418 prehearing conference pending full investigation of TMI
DOHERTY, J.F. Affiliation Unknown. 79/04/04. 4pp.

7905110347 Motion by intervenors to reopen record indefinitely & postpone decision on generic safety issue considerations pending full investigation of TMI.
PFEFFERKORN, W.G., PISHKO, D.C. Pfefferkorn & Conley, P.A. 79/04/03. 3pp

7905110349 Discusses & clarifies actions for Emergency Procedure 5, loss of testdown w/radiological control program.
TEDESCO, R.L. Assistant Director for Plant Systems 79/04/09. 3pp

7905110353 Motion to reopen safety hearings to consider suspension & revocation of CP.
BATTILO, T.M. Affiliation Unknown. 79/04/04. 2pp

7905110355 Requests comments re environ qualification & instrumentation to follow course of an accident
MANAUER, B.H. Assistant Director for Plant Systems 79/04/06 2pp

7905110379 Notification of ACRB Subcommittee on Power & Electrical Sys 790330 meeting w/its consultants & NRC staff in Washington. DC to review interconnection of protection & safety sys w/reactor control sys on REBAR-414 design
MOYLE, J.C. ACRB - Advisory Committee on Reactor Safeguards. 79/03/14 2pp

7905110398 Forwards QA Program Insp Rept 99900104/79-01 on 790205-08
No noncompliance noted.
POTAPOV, S.U. Region 4, Dallas, Vendor Inspection Branch 79/03/05. 2pp.

--7905110404 QA Program Insp Rept 99900104/79-01 on 790205-08. No noncompliance noted. Major areas inspected: implementation of 10CFR30, App B, criteria & applicable codes & stds including action on previous findings, insp & tests.
HUNTER, V.H., WHITEBELL, D.E. Region 4, Dallas, Vendor Inspection Branch. 79/02/28. 3pp.

7905110412 Notification of contract execution: "Development of Improved Techniques for Analyzing Matl Control & Accounting Data," awarded to Science Applications, Inc.
ROHNER, J. Technical Assistance Contracts Branch FIN B-6399-9. NRC-02-79-028. 79/04/20 1p.

--7905110413 Contract: "Development of Improved Techniques for Analyzing Matl Control & Accounting Data," awarded to Science Applications, Inc.
DOUGHERTY, D.J. Technical Assistance Contracts Branch. FIN B-6399-9. NRC-02-79-028. 79/04/20 20pp.

7905110414 Board notification. IE reactor inspector concerns re B&W plants.
VASSALLO, D.B. Assistant Director for Light Water Reactors 79/04/02. 1p.

--7905110420
790328 m
MOBELEY,
79/03/29

--7905110421
MOBELEY,
79/03/26

7905140019
in Richia,
MOELLER, D
Reactor B.

7905140043
of Protec
Disaster
* Enviro

NONDOCKETED ITEMS

- 7905140056 Summary of 790320 meeting w/BNL personnel to discuss mid-year review of progress on FY79 reactor physics technical assistance program
DUMENFELD, M Core Performance Branch 79/04/17. 3pp
- 7905140059 Notification of contract execution: "Consultation & Review of Nuclear Power Plant Sites," awarded to US Dept of Interior
GLAGOLA, A F Technical Assistance Contracts Branch FIN 8-6548
NRC-03-79-145 79/04/13 1p.
- 7905140069 Contract "Consultation & Review of Nuclear Power Plant Sites," awarded to US Dept of Interior
DOUGHERTY, D. J Division of Contracts, FIN 8-6548
NRC-03-79-145 79/04/13 3pp
- 7905140089 Motion by Cities of Anaheim & Riverside, CA to reschedule deposition of RH Gerdes for 790502 Urges ASLB vacate 790405 order deferring deposition & reinstate 790326 notice of deposition Certificate of Svc encl.
HATT, P K Spiegel & McDiarmid 79/04/11. 7pp.
- 7905140093 Application by Sigma Chemical Co for license to export 5 kg deuterium liquid to Canada
* Sigma Chemical Co. (subs of Sigma Aldrich Corp) 79/04/25 1p
- 7905140096 Application by Mitsubishi Intl Corp for license to export 250 mCi encapsulated cement wire, CF-232 to Japan
TANAKA, N Mitsubishi International Corp. (subs of Mitsubishi Corp.) 79/04/27 1p
- 7905140099 Notification of contract execution, Mod 4 to "Various Task Agreements." Contractor Battelle Columbus Labs
MYNATT, A Research Contracts Branch, NRC-04-76-293 79/04/01 1p.
- 7905140103 Mod 4, updating contract by adding new clause to "Various Task Agreements"
MORTON, K. V Division of Contracts, NRC-04-76-293 79/04/01 3pp.
- 7905140102 Act receipt of 790404 request for all NRC documents & communications re TH1. Lists records already in PDR. Others to be placed there upon disclosure.
FELTON, J M Division of Rules and Records, 79/05/03. 1p.
- 7905140128 Application by Nuclear Valve Div of Borg-Warner Corp for license to export 3/4-inch & 1-inch 600 lb carbon steel globe valves, manual & air actuated.
HAN, S. Borg-Warner Corp. 79/04/18 1p.
- 7905140149 NUREG/CR-0649
"Spent Fuel Heatup Following Loss of Water During Storage"
BENJAMIN, A B, McCLOSKEY, D. J, POWERS, D. A. Sandia Laboratories FIN A-2050. SAND77-1371 79/03/31. 171pp. Available at NTIS
- 7905140158 FOIA request for ACRS 690331 rept, AEC 690630 internal staff study re safety of large nuclear reactors AEC 691112 rept on reactor safeguards & ltr to Seaborg concerning safety questions
KENDALL, M. C. Indiana State of. 79/04/12. 2pp.
- 7905140160 Response to FOIA request for ACRS 690331 rept on reactor safeguards, AEC 690630 internal staff study re safety of large nuclear reactors, ACRS 691112 rept on reactor safeguards, & ltr to Seaborg concerning safety questions
FELTON, J. M Division of Rules and Records, 79/05/09. 2pp.
- 7905140164 "ACRS, Its Role in Nuclear Safety"
LAWRDSKI, B. Argonne National Laboratory. MOELLER, D. M. Harvard Univ. 78/09/26. 39pp
- 7905140165 Forwards comments on water reactor safety research program. Emphasizes importance of public health & safety
HENDRIE, J. M. ACRS - Advisory Committee on Reactor Safeguards. 69/03/20 1p.
- 7905140169 Comments on water reactor safety program plan. Coverage needed on proposed large water reactors. Understanding of fuel failures needed. Urges support be given to capable personnel. Analysis of accident prevention needed.
HENDRIE, J. M. ACRS - Advisory Committee on Reactor Safeguards. 69/03/20. 9pp.
- 7905140174 Reemphasizes previous recommendations re need for safety research. Urges addl R&D re seismic effects on sodium-cooled fast reactors & environ effects. More effort needed in examining fuel failure.
HENDRIE, J. M. ACRS - Advisory Committee on Reactor Safeguards. 69/11/12. 3pp
- 7905140170 Notification of contract execution: "Implementation of Mod to NRC Contract Info Sys," awarded to Small Business Administration
MEDROW, L A Administrative Contracts Branch NRC-10-79-381. 79/04/27 1p
- 7905140179 Contract for "Implementation of Mod to NRC contract Info Sys," awarded to Small Business Administration w/Social Research Application Corp as subcontractor
MATTIA, M J. Contract Policy Branch NRC-10-79-381 79/04/30 70pp
- 7905140177 FOIA request for winning technical proposal for NRC-02-79-035. "Safeguards for High Level Waste Repositories."
RAQAN, K M Kinetic Research, Inc. NRC-02-79-035. 79/02/19 1p
- 7905140180 Forwards RFP & winning technical proposal for NRC-02-79-035. "Safeguards for High Level Waste," in response to FOIA request
FELTON, J M Division of Rules and Records NRC-02-79-035 79/05/08 2pp
- 7905140183 FOIA request for internal NRC memo alleging that Idaho Falls, ID low power plant accident involved lovers' triangle.
WILLIAM, W. A Affiliation Unknown. 79/04/06 1p
- 7905140187 Addresses potentiality of Idaho Falls, ID stationary low power plant incident, involving lovers' triangle. Cautions against shortcomings in technological development & screening, supervision & surveillance of personnel
HANAUER, S H Atomic Energy Commission (Pre 1975) 71/09/10. 1p.
- 7905140184 Forwards 710910 memo in response to FOIA request for internal NRC memo alleging that stationary Idaho Falls, ID low power plant accident involved lovers' triangle.
FELTON, J. M Division of Rules and Records. 79/04/26. 1p
- 7905140191 FOIA request for documents prepared or received re environ impacts & health effects possibly resulting from nuclear tests conducted for Project Plowshare Program during 1960s & early 1970s
STRAIN, P. The Denver Post 79/04/02 1p.
- 7905140197 Forwards documents in response to FOIA request for info re impacts of nuclear tests for Project Plowshare Program. Addl info available from CD Public Health Dept & DOE.
FELTON, J M Division of Rules and Records. 79/05/01. 2pp.
- 7905140200 Informs of completion of reorganization of Div of Peaceful Nuclear Explosives Plowshare activities & personnel positions of Special Projects Div transferred to headquarters on 690518. Lists personnel assignments.
KELLY, J B Atomic Energy Commission (Pre 1975). 69/07/31. 3pp
- 7905140203 "Development of Regulatory Criteria for Control of Radiation Exposures to Population from Consumer Products Produced by Plowshare Applications." (R&D-3 Plowshare)
ROGERS, L R, WESTERN, F. Atomic Energy Commission (Pre 1975) 69/04/11. 26pp.
- 7905140213 Forwards IE Circular 79-06 "Failure to Use Byringe & Bottle Shields in Nuclear Medicine" & list of addressees
PAPPAS, M. Region 3, Chicago, Office of the Director 79/04/25 49pp.
- 7905140237 Notice of 790404 meeting of ACRS Subcommittee on Regulatory Activities, NRC & consultants in Washington, DC to discuss various proposed reg guides.
HOYLE, J C. ACRS - Advisory Committee on Reactor Safeguards. 79/03/14. 3pp.
- 7905140248 Notice of 790312 meeting of ACRS Subcommittee on Sequoyah Nuclear Power Station in Washington, DC to review TVA application for DL.
HOYLE, J C ACRS - Advisory Committee on Reactor Safeguards. 79/02/22. 2pp.
- 7905140252 Forwards matl provided 790404 & relevant B&W & NRC memos re feedwater events at B&W plants.
ORNSTEIN, H Office of the Executive Director for Operations 79/04/06. 19pp
- 7905140274 Addl info requested in 790209 ltr re two loop test apparatus test results being reviewed to determine schedule for response. Review results expected by 790417. Meeting suggested for week of 790423 for addl test data evaluation.
SHERWOOD, G O General Electric Co., Nuclear Energy Products Div MFN-099-79. 79/04/06. 2pp.

NONDOCKETED ITEMS

301

7903140297 Clarifies application of Leibnitz rule in integration of conservation of mass equations in SAFE code
STROUPE, E. P. General Electric Co., Nuclear Energy Products Div
MFN078-79. 79/03/20. 2pp.

7903140313 Forwards draft NUREG-0553, "Beyond Defense-in-Depth Cost & Funding... In Support of Commercial Nuclear Power Stations."
Requests comments by 790309 W/o encl.
RYAN, R. O. Office of State Programs. 79/04/10 1p

--7903140320 Forwards NUREG-0553, "Beyond Defense-in-Depth Cost & Funding... In Support of Commercial Nuclear Power Stations."
Requests comments by 790309 W/o encl.
RYAN, R. O. Office of State Programs. 79/04/10 1p

--7903140325 Forwards draft NUREG-0553, "Beyond Defense-in-Depth Cost & Funding... In Support of Commercial Nuclear Power Stations."
& requests comments before 790309. Final rept will be issued shortly after 790309. W/o encl.
RYAN, R. O. Office of State Programs. 79/04/10 1p

--7903140329 Forwards draft NUREG-0553, "Beyond Defense-in-Depth Cost & Funding... In Support of Commercial Nuclear Power Stations."
Requests comments by 790309 W/o encl.
RYAN, R. O. Office of State Programs. 79/04/10 1p

--7903140331 Forwards draft NUREG-0553, "Beyond Defense-in-Depth Cost & Funding... In Support of Commercial Nuclear Power Stations."
Requests comments by 790309 W/o encl.
RYAN, R. O. Office of State Programs. 79/04/10. 1p.

7903140314 Comments on DF Ross to EQ Case memo summarizing meeting re natural circulation considerations. Davis-Besse 1 771029 transient resulted in subcooling of 80 F or more. Erroneous implications made re Michelson Rept.
TAYLOR, J. H. Babcock & Wilcox Co. 79/03/04. 1p.

7903140326 Forwards new application for export license w/requested corrections.
MARTINEZ, F. P. Spain. 79/04/09. 1p.

--7903140328 Corrected Application by German Dominguez for license to export 51 kg U as U hexafluoride to Spain
" Spain. 79/02/28. 1p.

7903140392 Forwards proprietary rept NEDE-21983-P, "Submerged Structures Model: Main Vent Air Discharges Evaluation Rept." Affidavit encl. Rept available in Central Files.
BOBROW, L. J. General Electric Co., Nuclear Energy Products Div.
MFN-121-79. 79/04/30. 5pp.

7903140426 Submits requested info re 2-loop test apparatus & evaluation model reactor calculations, vaporization correlation data, & response to NRC question re vaporization in 2-loop test apparatus. W/encl 790129 ltr.
STROUPE, E. P. General Electric Co MFN-022-79. 79/01/30 74pp

--7903140428 Discusses NRC concern re heat transfer coefficient of 4-inch SAFE code & OE clarification.
STROUPE, E. P. General Electric Co. MFN-021-79. 79/01/29. 3pp

7903140469 Forwards slides presented at 790313 meeting w/NRC re ECCS evaluation model. Submittal contains proprietary info (ref 10CFR2.790).
ANDERSON, T. M. Westinghouse Electric Corp. NS-TMA-2068. 79/04/18. 1p.

7903140309 Forwards map furnishing info & list of burial sites in response to FOIA request for info re all nuclear plants, either completed under const & all nuclear waste burial sites W/o encl.
FELTON, J. M. Division of Rules and Records. 79/03/10. 1p.

7903140311 FOIA request for map & current geographical listing of all nuclear plants either completed or under const & all nuclear waste burial sites.
COMBER, R. B. Affiliation Unknown. 79/03/01. 1p.

7903140321 Comments on draft reg guide & value/impact statement re "Nuclear Analysis & Design of Concrete Radiation Shielding."
Specific criteria for design of concrete radiation shielding structures should be provided.
GAVIN, F. X. Energy Dept of. 79/04/02. 1p.

7903140323 Response to FOIA request for info re drawings & specs of model Theratron 80, Co-60 teletherapy unit. Forwards various documents, drawing & list of drawings withheld as proprietary. Documents & drawings not encl.
FELTON, J. M. Division of Rules and Records. 79/03/09. 2pp.

7903140327 FOIA request for internal files of facilities.
GLOUM, J. J. Milwaukee Sentinel. 79/04/12. 1p.

--7903140334 Forwards FOIA request for access to documents in regional office
KEPPLER, J. G. Region 3. Chicago. Office of the Director
79/04/20 1p

7903140330 Response to FOIA request for records not in NRC PDR re facilities
FELTON, J. M. Division of Rules and Records 79/03/08 1p

7903140372 NUREG/CR-0339
"PMR Blowdown Heat Transfer Separate-Effects Program Data Evaluation Rept. THF Test Series II"
MALLING, C. B., HYMAN, C. R., CRADDICK, W. O. Oak Ridge National Laboratory FIN B-0125 ORNL/NUREG-53 79/04/30 189pp
Available at NTIS

7903140373 NUREG-0344
"Handbook of Acronyms & Initialisms"
" Office of Administration 79/03/31 121pp

7903140375 NUREG/CR-0645
"Multidimensional Analysis of Fluid Flow in LOFT Cold Leg Blowdown Pipe During Loss-of-Coolant Experiment"
DEWHIE, P. N., HOFMANN, K. R. Idaho National Engineering Laboratory FIN A-6048 TREE-1323 79/03/31 77pp Available at NTIS #3 00

7903140376 NUREG/CR-0646
"Computer Program K-FIX/MDI Mod of Computer Program K-FIX for Application to Fluid Flow Simulation in LOFT Sys Piping"
DEWHIE, P. N., HOFMANN, K. R. Idaho National Engineering Laboratory FIN A-6048 TREE-1324. 79/03/31 84pp Available at NTIS #3 00

7903150003 Transcript of 79046 open meeting for NRC briefing on five shutdown plants (seismic design) Ps 1-67.
HENDRIE, J. M., OILINSKY, V., KENNEDY, R. T. Commission 79/04/26 68pp

7903150005 Ack receipt of 790313 ltr w/statement on "Probabilistic Risk Assessment & Its Application in Reactor Safety & Licensing"
Forwards NRC policy statement re Lewis Rept & instructions to NRC & testimony before Udall subcommittee
HENDRIE, J. M. Commission 79/04/23 1p

--7903150008 Forwards copy of "Probabilistic Risk Assessment & Its Application in Reactor Safety & Licensing" submitted to Committee on Interior & Insular Affairs
RICKARD, C. L. General Atomic Co (subs of Gulf Oil Corp.) 79/03/13 6pp.

--7903150009 Testimony of PA Bradford before Subcommittee on Energy & Environ of House Committee on Interior & Insular Affairs
BRADFORD, P. A. Commission 79/02/26 4pp

--7903150010 Testimony of JM Hendrie before Subcommittee on Energy & Environ of House Committee on Interior & Insular Affairs
HENDRIE, J. M. Commission 79/02/26 26pp.

7903150014 NUREG-0540 VI N3
"Title List of Documents Made Publicly Available for Mar 1979"
" Office of Administration 79/03/31. 381pp. Available at NTIS. #3.00.

7903150029 License for Transnuclear, Inc to export 413 kg U-235 & 0.0325 kg U-235 to West Germany
OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/04/27 2pp

7903150030 License for Hoke, Inc to export bellows sealed valves, valve manifold, sealed globe valves, sealed instrument isolating valves & manifolds to Canada.
OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/04/23. 1p

7903150031 License for Transnuclear, Inc to export 635 kg U-235 & 0.0335 kg U-235 to West Germany
OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/04/27 2pp.

7903150032 License for Exxon Nuclear Co, Inc to export 1940 4 kg U-235 to Belgium
OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards. 79/04/27. 2pp.

7903150033 License for Hoke, Inc to export bellows sealed globe valves, needle & globe valves to Canada.
OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/04/27. 1p.

NONDOCKETED ITEMS

- 7905130035 License for Hoke, Inc to export bellows sealed instrument isolating valves, sealed valves & valve manifolds to Canada.
OPLINGER, O O Assistant Director for Export/Import & International Safeguards 79/04/27 1p
- 7905130037 License for Hoke, Inc to export bellows sealed instrument isolating valves & spares, valve manifolds & sealed instrument valves to Canada
OPLINGER, O O Assistant Director for Export/Import & International Safeguards 79/04/27 1p
- 7905130038 License for Hoke, Inc to export bellows sealed instrument isolating valves to Canada
OPLINGER, O O Assistant Director for Export/Import & International Safeguards 79/04/27 1p.
- 7905130040 License amendment for GE to export 2.48 kg Pu & 61 kg natural U to France.
OPLINGER, O O Assistant Director for Export/Import & International Safeguards 79/04/26 1p
- 7905130047 Ltr of assurance certifying fuel elements mentioned in General Atomic 790222 application will be subg to conditions of 600725 addl agreement for cooperation
GOPPEL, K. European Communities, Commission of. 79/03/27 1p
- 7905130066 Notice of 790319-20 ACRS Subcommittee on ECCB meeting. w/its consultants & NRC in Los Angeles, CA to discuss status of physical code inputs, current licensing actions & asymmetric blowdown forces.
HOYLE, J.C. ACRS - Advisory Committee on Reactor Safeguards. 79/02/26 2pp
- 7905130093 Responds to 790312 ltr requesting NRC extend comment period for NUREG-0499, "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Plant Licensing." No extensions planned
DENTON, H R Office of Nuclear Reactor Regulation 79/03/16 2pp
- 7905130098 Comments on NUREG-0499, "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Plant Licensing." Alternative energy sources should be considered & believes there is no need for adding baseload capacity
HITTE, R.E. Appalachian Research & Defense Fund, Inc. 79/03/12 2pp
- 7905130095 Executive Branch position re Mitsubine Travel Bvc of America, Inc application for license to export reactor components & parts to Japan. License should be issued
NOSENZO, L.V. State, Dept. of, Bureau of Oceans & Internatl. Environ & Scientific Affairs XCOM-152 79/04/23 1p
- 7905130099 "Water Reactor Safety Research, Heat Transfer Highlights" Jan 1979.
LOTTEB, P.A. Argonne National Laboratory. DOE 40-550-75 78/11/30, 6pp.
- 7905130101 Notification of contract execution, Mod 6 to "A/E Consulting Svcs." Contractor, Burns & Roe, Inc.
MYNATT, A. Research Contracts Branch. FIN B-6220 NRC-04-77-097, 79/03/31 1p.
- 7905130109 Mod 6, no-cost time extension through 800331 to "A/E Consulting Svcs"
MORTON, K.V. Research Contracts Branch. FIN B-6220, NRC-04-77-097 79/03/31 2pp.
- 7905130105 Application by Hoke, Inc for license to export motorized & isolating valves & spare parts to Korea.
LINDNER, T P Hoke, Inc. 79/04/16 1p.
- 7905130106 Application by Hoke, Inc for license to export bellows sealed instrument isolating valves & valve manifolds to Korea.
* Hoke, Inc. 79/04/19 2pp.
- 7905130123 Executive Branch position re Mitsubishi Intl Corp application for license to export 342 kg U-235 to Japan. License should be granted.
NOSENZO, L.V. State, Dept. of, Bureau of Oceans & Internatl. Environ & Scientific Affairs. 79/04/16 3pp.
- 7905130140 Monthly ltr rept for Feb 1979 re technical project status of "Aerosol Measurements & Modeling for Fast Reactor Safety."
QIESEKE, J.A. Battelle Memorial Institute, Columbus Laboratories. 79/03/28 3pp.
- 7905130154 Summary of 790330 meeting w/GE re Target Rock safety relief valves & review of progress toward reducing number of BWR blowdowns.
NOWICKI, B.J. Operating Reactors Branch 2. 79/04/12 16pp.
- 7905130155 Forwards petition to intervene & request for hearing on behalf of Ctr for Development Policy & two other intervenors re application for export license w/o encl.
ASHER, T R Asher, T R. PC XBNMD 1471. 79/04/20 1p
- 7905130158 License for Mitsubine Travel Bvc of America, Inc to export miscellaneous reactor parts to Japan
OPLINGER, O O Assistant Director for Export/Import & International Safeguards 79/04/13 1p
- 7905130161 Application by Sigma Chemical Co for license to export compounds containing equivalent of 4 kg deuterium liquid over 2-year period to Australia
* Sigma Chemical Co (subs of Sigma Aldrich Corp.). 79/04/11 1p
- 7905130162 License for Mitsubine Travel Bvc of America, Inc to export miscellaneous specially designed or prepared parts for use in reactors to Japan
OPLINGER, O O Assistant Director for Export/Import & International Safeguards 79/04/13 1p
- 7905130179 Requests approval of proposal to expand scope of DDR generic issue B-23, "Degraded Grid Voltage," to accommodate causes of degraded voltage identified by Arkansas Nuclear One abnormal occurrence
VOLLMER, R. Assistant Director for Systems & Projects. 79/04/03 3pp
- 7905130183 Executive Branch position re Edlow Intl Co application for license to export 800,000 Ci of tritium to Switzerland. License should be granted
NOSENZO, L.V. State, Dept. of, Bureau of Oceans & Internatl. Environ & Scientific Affairs 79/04/18 2pp
- 7905130186 Executive Branch position re Westinghouse application for license to export fuel rod tubes, springs & end plugs to Sweden. License should be granted
NOSENZO, L.V. State, Dept. of, Bureau of Oceans & Internatl. Environ & Scientific Affairs 79/04/12 2pp
- 7905130188 Responds to 790307 ltr. Since GA program description does not meet NUREG-0390, it will not be introduced to NRC topical rept program w/encl topical rept program description
HAASB, W P L K Constock Engineering Co. 79/03/28 9pp.
- 7905130191 Executive Branch position re Mitsubine Travel Bvc of America, Inc application for license to export 18,000 poison tubes to Japan. License should be granted.
NOSENZO, L.V. State, Dept. of, Bureau of Oceans & Internatl. Environ & Scientific Affairs. 79/04/19 2pp.
- 7905130195 Application by Transnuclear, Inc to amend export license to include addl quantity of 0.2 g of U-235.
MATSON, V. Transnuclear, Inc 79/04/18 1p.
- 7905130198 Application by Edlow Intl Co to amend export license to show ABEA ATOM as only intermediate consignee.
HARMON, D.W. Edlow International Co. 79/04/10 1p.
- 7905130199 Responds to BECY-79-88 "Timing of Certain Requirements of U Mill Tailings Radiation Control Act of 1978." Details position re federal-state authority to license mills w/regard to requirements of AEC Act, Section 274.
KIND, B. New Mexico, State of. 79/03/07 3pp.
- 7905130203 Application by GE to amend license to export matl to Japan. Requests rescheduling of first shipment to 790831.
WILSON, B.D. General Electric Co., Nuclear Energy Products Div BOW-79058. 79/04/13 1p.
- 7905130208 Application by General Atomic Co to amend license to export fuel elements containing U to Japan. Requests extension of expiration date to 800701.
MOWRY, W.R. General Atomic Co. (subs. of Gulf Oil Corp.). IEL-104B. 79/04/13 1p.
- 7905130213 NUREG/CR-0595
"Assessment of Intergranular Fracture Within Unrestricted UO2 Fuel Due to Film Boiling Operation."
CROWENBERG, A.W. YACKLE, T.R. EO & O, Inc. FIN A-6046. TREE-1330. 79/03/31 93pp. Available at NTIS.
- 7905130219 NUREG/CR-0513
"Reactor Safety Research Programs." quarterly progress rept Jul-Sept 1978
KOUTS, H.J.; KATO, W.V.; ROMANO, A.J. Brookhaven National Laboratory. EY-74-C-02-0016 BNL-NUREG-80931. 78/11/30 215pp. Available at NTIS.

NONDOCKETED ITEMS

303

7903130229 Comments on proposed rules 10CFR19 & 20 endorse proposed limit for mandating monitoring of minors 18 years of age or under who are exposed to radiation above natural background levels
LAMPKA, J V Bunker Hill Community College 79/03/15 2pp

7903130238 Petition to separate NRC into two entities one covering power reactors, U mining, nuclear weapons mfg, nuclear fuel processors & other dealing w/byproduct matl
PEEPLEB, W P Non-Destructive Testing Management Association 79/04/12 2pp

7903130311 Responds to 790212 ltr re application for license to export monazite ore to India. Application was forwarded to Executive Branch on 780421 for review
BHEA, J. R. Assistant Director for Export/Import & International Safeguards 79/04/13, 1p.

7903130314 Application by Borg-Warner Corp, Nuclear Valve Div for license to export globe & check valves, carbon steel & stainless steel to Belgium.
ANDERSON, B. Borg-Warner Corp 79/04/16 1p.

7903130327 Ack receipt of 790321 ltr providing views on NRC interpretation & implementation of U Mill Tailings Radiation Control Act of 1978.
SHAPAR, H K. Office of the Executive Legal Director 79/03/07 1p

7903130332 Weekly info rept for week ending 790427.
REHMT, T A Office of the Executive Director for Operations 79/04/01 29pp

7903130342 NRC review of application need not be completed by 780331 due to probable change of ownership & mgt for MV Mineral Corp Keweenaw project. Forwards Resources Corp 790313 ltr to CO Dept of Health
HAILE, A J Colorado, State of 79/03/16 4pp

7903130349 Comments on NUREG-0523, "Summary of Operating Experience w/ Recirculating Steam Generators" Considers this one of the best repts on subj.
BURSTEIN, B Wisconsin Electric Power Co. 79/05/10 2pp

7903130348 Moves for protective order to prevent deposition of RH Gerdas Certificate of Evc encl.
WATTS, M. J., DOYLE, M. M McCutchen, Doyle, Brown & Emerson.
FURBUSH, M. H. Pacific Gas & Electric Co 79/03/31, 12pp

7903130369 Requests that OE rept NEDE-21944-P "Quarter Scale Pressure Suppression Pool Bwell Test Program: Plant Unique Tests" be included in docket.
FILANT, J. H. Nebraska Public Power District. 79/03/08 1p

7903130494 Comments on proposed rule 10CFR19 & 20: adequacy of present occupational dose limiting stds is essential.
STRELOW, R. Commonwealth Edison Co. 79/04/19 1p.

--7903130498 Comments on proposed rule 10CFR19 & 20: preferable to address dose accumulation & occupational exposure at separate hearings. Current proposal has not been thoroughly evaluated & potential consequences ignored.
STRELOW, R. Commonwealth Edison Co 79/03/13, 3pp.

7903130524 FOIA request for info re all records of LERs & NRC insp repts on NL Industries, Inc Nuclear Div plant in Wilmington, DE.
BIVENB, T. News-Journal Co WI, Delaware 79/03/19, 1p

7903130528 Response to FOIA request for info re all records of LERs & NRC insp repts on NL Industries, Inc Nuclear Div plant in Wilmington, DE. No LERs for NL Industries, Inc Forwards four facility licenses & insp records. W/o encl.
FELTON, J. M. Division of Rules and Records. 79/03/10 1p

7903130573 Certifies matl mentioned in QA Co license application to export fission chamber to Italy will be subj to all terms & conditions of amended 600725 addl agreement for cooperation.
BPAAR, F. European Communities, Commission of. 79/03/26, 1p.

7903130581 Forwards QA Program Insp Rept 99900060/79-01 on 790206-09. No noncompliance noted.
POYAPOV, U. Region 4, Dallas, Office of the Director 79/03/06, 2pp.

--7903130585 QA Program Insp Rept 99900060/79-01 on 790206-09. No noncompliance noted. Major areas inspected: implementation of 10CFR50, App B & other applicable regulations.
KELLY, W. D., JOHNSON, J. M., WHITEBELL, D. E. Region 4, Dallas, Vendor Inspection Branch. 79/03/02, 18pp.

7903130582 Inform that FR notice of denial of petition for rulemaking has been modified to indicate that five rather than four people have submitted comments on petition for rulemaking PRM 20-9 Revised page of notice encl
BARKER, R F Transportation & Product Standards Branch 79/04/09 2pp

--7903130588 Comments on PRM 20-9 re allowable radiation levels for radiographer safety & radioactive transport suggests 50 is better level than 100 (at 5 cm), but 75 may be suitable compromise
WHITE, M C, JACK, O C Atomic Energy Control Board, Canada 77/07/18 1p

--7903130592 Comments on PRM 20-9 & PRM 34-1 present limits are pragmatic, providing necessary protection Recommends petition be denied, as compliance would be too difficult to document & enforce
SCHEDEL, K R Westinghouse Electric Corp WRD-LS4S-273 77/07/18 1p

--7903130597 Comments on PRM 20-9 & PRM 34-1 new regulations not needed to overcome impracticality & inconsistency of results in determining radiation intensities at surfaces Changes will be too restrictive
RHODE, O K Niagara Mohawk Power Corp 77/07/18 1p

--7903130605 Comments on PRM 20-9 change restricts operations at nuclear power plants & does not follow ALARA philosophy Present rule is adequate
UHRIQ, R E Florida Power & Light Co L-77-229 77/07/25 2pp

--7903130611 Comments on PRM 20-9 confirms opposition expressed in 770718 telegram Finds first proposal reasonable, but second & third proposals are unacceptable
JACK, O C, WHITE, M C Atomic Energy Control Board, Canada 77/08/03 5pp

--7903130619 Comments on PRM 20-9 change does not improve quality of survey, nor does it provide better control of external dose rates Proposed mods would be more impractical than existing regulations
DEHERITT, E L Rochester Gas & Electric Corp 77/08/10 1p

7903130614 Comments on proposed rules 10CFR19 & 20 endorse retention of quarterly dose limit & approves of proposed dose per CY
BAIETTI, A L Affiliation Unknown 79/03/26 2pp

7903130652 Comments on proposed Reg Guide 8.23 acceptable contamination limits are too restrictive
STRAUSS, K J Michael Reese Hosp & Medical Center 79/03/21 1p

7903130702 Responds to 790305 ltr commenting on proposed deletion of dose averaging formula 5(N-18) Forwards draft rept of Interagency Task Force on Ionizing Radiation W/o encl
ALEXANDER, R E Occupational Health Standards Branch 79/03/15 1p

--7903130706 Requests citations re epidemiological data & associated recommendations for noncumulative lower stds
FRDQGE, J L Affiliation Unknown 79/03/05 1p

7903130705 Forwards application amend request from OE to change date of first scheduled shipment from 791201 to 790831 W/o encl
OPLINGER, O O Assistant Director for Export/Import & International Safeguards 79/04/23 1p

7903130710 Oral argument
ASLB 790125 order will
DUFLD, M E Atomic Sa 2pp

7903130716 Denies CI
790502 as date for
MILLER, M E. 2pp

79031307
valuab
in doc
their
GABRIE

79031307
users
w/expe
profes
EYRAET

NONDOCKETED ITEMS

7905150731 Notification of 790510 meeting w/uttl & NY State in
Stuyvesant, NY to provide NRC review team opportunity to
visit alternate site in order to discharge NEPA obligation
BELL, D E Environmental Projects Branch 2 79/04/27 2pp

7905150734 Comments on proposed Reg Guide 10 B "thin window" survey
meter not necessary to detect low radiation. Sensitivity
requirement for area wipe tests too low
GORMAN, H C Lakeview Medical Center DA, Illinois 79/04/03. 1p.

7905150738 Comments on proposed rulemaking 10CFR2 714 recommends denial
of petition as destructive of present balance between
citizen interest & administrative needs. Proceedings could be
indiscriminately re-opened & continued
TROWBRIDGE, O F Shaw, Pittman, Potts, & Trowbridge 79/04/18 4pp

7905150741 Comments on proposed Reg Guide 1.8, Revision 2, believes
staffing requirements for technical competence are much too
low
WILLIS, C A Philippines. 79/04/02 1p

7905150752 Comments on proposed Reg Guide 3 B opposes provisions
requesting info on ore body location & openings of related
mines because mill operator should only be responsible.
WALPOLE, J R. American Mining Congress 79/03/14 13pp

7905150777 "Study of Plutonium Oxide Leak Rates from Shipping
Containers," quarterly progress report Oct-Dec 1978
SCHWENDIMAN, L. C. MADIA, M. J. ; MISHIMA, J Battelle Memorial Institute,
Pacific Northwest Laboratory FIN 8-2093, PNL-2260-9, 79/02/01.
43pp Available at NTIS.

7905150784 Requests quantity of matl be raised to 75 kilos of ThF4 &
extension of expiration date to 791231 for license to export
thorium to Scotland.
COLTON, E Cerac, Inc 79/04/27 2pp

7905150788 Comments on proposed rulemaking 20-13 amend may be
appropriate for nuclear power plants, but should not cover
airline employees
ANDERSON, C R American Airlines, Inc 79/04/12. 1p.

7905150787 License for GE to export four NA 200 local power range
monitors to India.
OPLINGER, O O Assistant Director for Export/Import & International
Safeguards 79/04/30 1p

7905150792 Forwards GA Program Insp Rept 99900677/79-01 on 790226-0301
No noncompliance noted.
POTAPOV, U Region 4, Dallas, Vendor Inspection Branch.
79/03/15 2pp.

--7905150797 GA Program Insp Rept 99900677/79-01 on 790226-0301 No
noncompliance noted. Major areas inspected: implementation of
10CFR30, App B criteria, applicable codes & stds & actions on
previous insp finding
ROBERTS, H W. ; HANNICUTT, D M. Region 4, Dallas, Vendor
Inspection Branch. 79/03/14 3pp.

7905150803 Supplemental answer by uttl to first set of interrogatories.
Affidavit & Certificate of Svc encl.
DOYLE, M M. ; HOULIHAN, T. J. ; McCutchen, Doyle, Brown & Emerson
HEISS, R L Pacific Gas & Electric Co. 79/04/16 6pp.

7905150804 License for Air Products & Chemicals, Inc to export 100 g
deuterium to United Kingdom
OPLINGER, O O Assistant Director for Export/Import & International
Safeguards. 79/04/27. 2pp.

7905150807 Executive Branch position re Edlow Intl Co application for
license to export 393 kg U-235 to United Kingdom for
fabrication into fuel assemblies for reload in Italy
License should be granted Ltr of assurance encl.
NOSENZO, L V. State, Dept of, Bureau of Oceans & Internatl. Environ.
& Scientific Affairs. 79/04/24. 2pp.

7905150808 Responds to 790323 request. Provides comments &
recommendations re proposed revision of Reg Guide 1.89.
Statements conflict re length of time that equipment must
function safely
VOLLMER, R Assistant Director for Systems & Projects. 79/04/19.
4pp

7905150810 License for Tetadyne Wah Chang Albany to export 16,000 lb
Zircaloy to Canada
OPLINGER, O O Assistant Director for Export/Import & International
Safeguards. 79/04/27. 1p.

7905150813 License for Sigma Chemical Co to export 2 kg heavy water
to Belgium.
OPLINGER, O O Assistant Director for Export/Import & International
Safeguards. 79/04/27. 2pp.

7905150815 License for Transnuclear, Inc to export 360 kg U-235 to
Belgium
OPLINGER, O O Assistant Director for Export/Import & International
Safeguards 79/04/27 2pp

7905160105 Comments on 790306 request for transmission of info to ASLB
re reactor inspector's concerns about B&W plants
SHAPAR, H K Office of the Executive Legal Director. 79/03/29 2pp

--7905160109 Forwards procedures for notifying ASLB, ASLAB & NRC of new
info
SHAPAR, H K Office of the Executive Legal Director 78/07/12
6pp

7905160228 Executive Branch position re Eberline Instrument Corp
application for license to export 81.6 micrograms Pu-239 to
Indonesia
NOSENZO, L V. State, Dept of, Bureau of Oceans & Internatl. Environ.
& Scientific Affairs 79/04/24 2pp

7905160234 Executive Branch position re Cordis Corp application for
license to export 45 g U-238 to Saudi Arabia & Jordan.
NOSENZO, L V. State, Dept of, Bureau of Oceans & Internatl. Environ.
& Scientific Affairs. 79/04/23 2pp

7905160250 Transcript of 790426 meeting of Subcommittee on Licensee
Evaluation Repts in Washington, DC Pp i-242
MOELLER, D W. ; ETHERINGTON, H. ; RAY, J J ACRS - Advisory Committee on
Reactor Safeguards. 79/04/26 244pp.

7905160370 Responds to 790307 request for addl info re "Evaluation of
Transient Behavior & Small RCS Breaks in 177 Fuel Assembly
Plant." Forwards ref matl & addl info re App 2.
TAYLOR, J H Babcock & Wilcox Co. 79/05/10. 26pp.

7905160373 Responds to NRC request for addl info re small break
analysis in "Evaluation of Transient Behavior & Small
RCS Breaks in 177 Fuel Assembly Plant." Forwards requested
analysis.
TAYLOR, J H Babcock & Wilcox Co 79/05/12 44pp.

7905160388 Responds to NRC request for info on B&W 790507 rept re
"Evaluation of Transient Behavior & Small RCS Breaks in 177
Fuel Assembly Plant." Discusses pump status, operating limits
& position on pump integrity
TAYLOR, J H. Babcock & Wilcox Co. 79/05/10 3pp.

7905160391 Submits schedule for completion of generic licensing topical
rept in response to NRC 790426 request.
CLARK, C W. Ederer, Inc (subs. of Formac International, Inc.)
79/05/11. 1p.

7905160441 Comments on NUREG-0531, "Investigation & Evaluation of
Stress Corrosion Cracking in Piping of LWR Plants:" more
detailed recommendations for inservice insp being prepared.
Requests addl info
GRIDLEY, R L General Electric Co, Nuclear Energy Products Div.
MFN-130-79. 79/05/04. 9pp

7905170277 Forwards "Upward Fire Propagation in Vertical Cable Tray
Fire Propagation Over Central, Thermally Thin Cables" &
"Fire Resistance of Cable Penetration Seals: Theory for
Radially Isothermal Cables."
FEIT, R. Division of Reactor Safety Research 79/04/12. 2pp

--7905170279 TR-39
"Upward Fire Propagation in Vertical Cable Tray Fire
Propagation Over Central, Thermally Thin Cables."
HUNTER, L W Johns Hopkins Univ. 79/03/12. 12pp

--7905170282 TR-40
"Fire Resistance of Cable Penetration Seals: Theory for
Radially Isothermal Cables."
HUNTER, L W Johns Hopkins Univ. 79/03/30. 9pp.

7905170280 Application by Hoke, Inc for license to export bellows-sealed
instrument isolating valves to Canada.
LINDNER, T. P. Hoke, Inc. 79/04/06. 4pp.

7905170283 Application by Hoke, Inc for license to export bellows-sealed
instrument isolating valves to Canada.
LINDNER, T. P. Hoke, Inc. 79/04/04. 4pp.

7905170285 Application by Hoke, Inc for license to export bellows-sealed
sealed globe pattern, nonrising stem valves to Canada.
LINDNER, T. P. Hoke, Inc. 79/04/05. 4pp.

7905170289 Application by Hoke, Inc for license to export bellows-sealed
valves, three valve manifolds & bellows-sealed instrument
isolating valves to Canada.
LINDNER, T. P. Hoke, Inc. 79/04/09. 4pp.

NONDOCKETED ITEMS

305

7903170293 Application by Hoke, Inc for license to export bellows-sealed valves, three valve manifolds, globe valves & instrument isolating valves to Canada.
LINDNER, T. F. Hoke, Inc 79/04/03 9pp.

7903190055 Lists contract codes/previous employee codes for previous radiation exposure.
* Office of Inspection & Enforcement. 79/02/12. 1pp

7903190063 Responds to 790115 ltr Forwards requested addl info re electrical equipment qualification
ANDERSON, T. M. Westinghouse Electric Corp NB-TMA-2059. 79/03/14 3pp

7903190064 Discusses exposure of TLDs to radiation under specified conditions in response to NRC requests
EISENHOWER, E. H. Commerce, Dept of, National Bureau of Standards 79/04/20 1p

7903190065 Forwards addl requested info re small break ECCB analysis
ANDERSON, T. M. Westinghouse Electric Corp. NB-TMA-2085. 79/03/16 3pp.

7903190161 Forwards "Evaluation of Transient Behavior & Small RCB Breaks in 177 Fuel Assembly Plant," Vols I & II, App
TAYLOR, J. H. Babcock & Wilcox Co. 79/03/07 2pp

--7903190164 "Evaluation of Transient Behavior & Small RCB Breaks in 177 Fuel Assembly Plant," Vols I & II, App.
* Babcock & Wilcox Co. 79/03/07. 500pp

7903190200 Discusses organizational changes in QA dept which will be implemented during next revision to B&W QA plan, BWHGAP 1-74A
KELLY, R. B. Stone & Webster Engineering Corp. 79/03/09 2pp

7903210094 Comments on IEEE 379 draft of May 1976; not accepted because of confusing language
HAWAUER, B. H. Office of the Executive Director for Operations 79/06/17 1p

7903210136 Forwards "Mark-III Demonstration Assemblies Licensing Rept." proprietary & nonproprietary versions Affidavit for withholding encl (ref 10CFR2.790)
TAYLOR, J. H. Babcock & Wilcox Co 79/03/03. 7pp

--7903210138 BAW-1533
"Mark-III Demonstration Assemblies Licensing Rept."
nonproprietary version
* Babcock & Wilcox Co. 79/04/30. 1pp.

7903210146 Responds to 780926 ltr Forwards addl info re reactor core response to excessive secondary steam releases Remaining questions will be answered by 790101.
ANDERSON, T. M. Westinghouse Electric Corp NB-TMA-2080. 79/03/07 22pp.

7903210152 Forwards "Mark I Containment Program Safety/Relief Valve Analytical Models for Use W/Ramshead Discharge Devices,"
Yant, T. L. I. W/affidavit for withholding (ref 10CFR2.790).
SOBON, L. J. General Electric Co, Nuclear Energy Products Div. WFN-L29-79 79/03/07. 190pp.

7903210166 FBAR Amend 35 incorporating changes to Section 13.3.
* Hanford Engineering Development Laboratory HEDL-TI-75002-3 79/04/30. 65pp.

7903210184 Forwards FBAR Amend 30; revision of Chapter 17 "FFTF Tech Specs." Does not constitute DOE technical approval for fuel load.
BAIRD, G. L. Hanford Engineering Development Laboratory 00285 79/03/14 1p.

--7903210187 Revision of chapter 17 "FFTF Tech Specs." submitted as Amend 30 to FBAR.
* Hanford Engineering Development Laboratory. HEDL-TI-75002-3 79/03/31. 275pp.

7903210232 Summary of "Decay Heat Removal During Small Break LOCA for B&W 205 Fuel Assembly PWR."
MICHELSON, C. Babcock & Wilcox Co. 78/01/31. 36pp

7903220023 Forwards BN-TOP-4 Revision 1, "Subcompartment Pressure & Temp Transient Analysis."
JUDG, J. C. Bechtel Power Corp. (subs. of Bechtel Corp.). 79/03/10. 1p.

--7903220026 BN-TOP-4
"Subcompartment Pressure & Temp Transient Analysis."
* Bechtel Power Corp. (subs. of Bechtel Corp.) 77/10/31. 88pp.

7903220034 Comments on proposed rule 10CFR19 & 20 concurs w/proposed radiation limit Recommends that NPC Form-4 be redesignated for use by individual in disclosing previous exposure records to licensee
BRONSON, F. Health Physics Society 79/03/16 4pp

7903220043 Research Info Ltr 49 in vitro dissolution of U product samples from four U mills
LEVINE, S. Office of Nuclear Regulatory Research LF-59 79/04/04 5pp

7903220051 BECY-79-256
Notifies of NRC review of proposed issuance of license to Exxon Nuclear Co, Inc to import 40,000kg U-235 from Russia
Recommends license be issued
SHEA, J. R. Office of International Programs 79/04/12 3pp

--7903220060 License for Exxon Nuclear Co, Inc to import 40,000 kg. enriched to max of 3 IX in U-235 isotope as U hexafluoride.
from Russia
OPLINGER, O. O. Assistant Director for Export/Import & International Safeguards 79/01/25 2pp

7903220096 Provides further response to DO Comey 781005 ltr requesting documents re MUREQ-75-067 & OE BWR pipe cracking problems occurring since 1975 Forwards bibliography of available documents
FELTON, J. M. Division of Rules and Records 79/04/18 3pp

7903220079 Transcript of 790302 briefing on steam generator denting & replacement, held in Washington, DC Pp 1-69
HENDRIE, J. H., OILINSKY, V., KENNEDY, R. T. Commission 79/03/02 70pp

7903220080 Forwards nonproprietary & proprietary versions of Amends 3-NP & 3P to CENPD-153, "Evaluation of Uncertainty in Nuclear Form Factor Measured by Self-Powered Fixed Incore Detector Sys" W/affidavit for withholding (ref 10CFR2.790)
SCHAEFER, A. E. Combustion Engineering, Inc LD-79-025 79/04/30 5pp

--7903220083 CENPD-153 3-NP
Nonproprietary version of Amend 3-NP to CENPD-153.
"Evaluation of Uncertainty in Nuclear Form Factor Measured by Self-Powered Fixed Incore Detector Sys." revised Chapter 4, rod power calculation error
* Combustion Engineering, Inc 79/04/30 33pp

7903220324 Forwards Suppl 1 to Section 6 of "Evaluation of Transient Behavior & Small RCB Breaks in 177 Fuel Assembly Plant." dtd 790307
TAYLOR, J. H. Babcock & Wilcox Co 79/03/12 1p

--7903220330 "Evaluation of Transient Behavior & Small RCB Breaks in 177 Fuel Assembly Plant," Vol 1, Section 6 O, Suppl 1
* Babcock & Wilcox Co 79/03/12 41pp

7903220348 Discusses Leibnitz rule simplification & high heat transfer in LOCA models. Provides verified results demonstrating that current LOCA evaluation model is conservative in calculation of peak clad temp
STROUPE, E. P. General Electric Co WFN-124-79 79/03/02 11pp.

7903220408 Forwards Suppl 1 to App 2: "Steam Generator Tube Thermal Stress Evaluation"
TAYLOR, J. H. Babcock & Wilcox Co 79/03/10 1p

--7903220410 "Steam Generator Tube Thermal Stress Evaluation," Suppl 1 to App 2
* Babcock & Wilcox Co 79/03/10 25pp

7903220422 Responds to IE Bulletin 79-06A re TMI incident Forwards addl matl to clarify position on Item 7 re operating procedures & training instructions
ANDERSON, T. M. Westinghouse Electric Corp. NB-TMA-2087. 79/03/17. 10pp.

7903220448 Requests Executive Branch position re Sigma Chemical Co application for license to export heavy water to Argentina
OPLINGER, O. O. Assistant Director for Export/Import & International Safeguards 79/04/23 1p.

7903220449 Requests Executive Branch position re Edlow Intl Co application for license to export source matl to Brazil
OPLINGER, O. O. Assistant Director for Export/Import & International Safeguards 79/04/23 1p

7903220468 Forwards distribution list for bundle test interim data repts.
PICKLEBIMER, M. L. Fuel Behavior Branch 79/04/17 2pp.

NONDOCKETED ITEMS

- 7905230098 Summary of 790501 meeting w/C-E in Bethesda, MD re natural circulation in C-E operating reactors
* Reactor Systems Branch 79/09/01. 88pp
- 7905230280 Submits info re renewal of License STB-67B Application to be filed 30 days before expiration date of existing license
LAYFIELD, R L Atomic Energy Commission (Pre 1975) 64/07/06 1p
- 7905230739 Submits addl recommendations re mfg procedure controls
Proposes radiation measures conducted to assure sufficient radiation control includes results of survey conducted re radioactivity in controlled & uncontrolled areas
CARRIQAN, R H Fellows Medical Mfg Co., Inc., Fellows-Testagar Div 64/12/17. 3pp.
- 7905230247 Requests extension from 641122 to 641222 of submission deadline for procedures of controlling spread of contamination.
CARRIQAN, R H Fellows Medical Mfg Co., Inc., Fellows-Testagar Div 64/11/04. 1p
- 7905230386 Ack receipt of 680126 ltr notifying of license expiration
Forwards application for renewal of License STB-67B
CARRIQAN, R H Fellows Medical Mfg Co., Inc., Fellows-Testagar Div. 596. 68/08/07 1p
- 7905230670 Notifies that License STB-67B expires 680331.
MUSSEBAUMER, D A. Atomic Energy Commission (Pre 1975) 68/01/24 1p
- 7905230124 FOIA request for info re Thorotrast, licensing, manufacturers & licensees.
FELDMAN, S M Feldman & Feldman 79/04/06. 1p
- 7905240176 Application by GE for license to export 29,526 kg low enriched U oxide powder, enriched to max of 3.65% U-235, to Japan.
WILSON, B D General Electric Co., Nuclear Energy Products Div 79093 79/04/03. 4pp.
- 7905230188 Agenda for ACRS 790416-17 meeting w/NRC & nuclear industry representatives in Washington, DC to discuss IE Bulletin 79-05A, "Nuclear Incident at TMI," & other related items.
* ACRS - Advisory Committee on Reactor Safeguards. 79/04/11. 3pp
- 7905230301 Executive Branch position re Mitsubishi Travel Svc application for license to export components & parts for test reactors to Japan License should be issued
NOSENZO, L V. State, Dept. of, Bureau of Oceans & Internatl. Environ. & Scientific Affairs. 79/04/19. 2pp.
- 7905230396 FOIA request for related documents on WASH-1400 & BECY-78-137, as identified in HR Denton 781211 memo to LV Gossick
BURT, L Massachusetts, State of 79/04/18 5pp.
- 7905230400 Response to FOIA request for related documents on WASH-1400 & BECY-78-137 Forwards 14 requested documents; others not yet reviewed by NRC
FELTON, J M Division of Rules and Records. 79/05/11 2pp.
- Discusses review of draft liquid pathway generic study I to subys re WASH-1400 Contamination risks should be realistically per recommended revisions.
Office of Nuclear Regulatory Research. 76/08/09 9pp
- Forwards draft responses for CA Energy Resources Development Commission in response to 760723 ltr
Probabilistic Analysis Branch 76/08/23. 12pp.
- Comments on EPA draft publication concerning technical projection methods to be used as basis for actions for nuclear accidents; report is of little value only hypothetical conditions evaluated.
Office of Nuclear Regulatory Research. 76/10/07. 3pp
- Issues technical errors noted in Judge JB McMillen Indiana Environ Study, Inc et al vs AEC, et al (restanding of Levine's testimony & error in site heat rejected by plants is significant).
Probabilistic Analysis Branch. 77/03/17. 4pp.
- Comments on draft NUREG-0396, "Modified Planning Basis for State & Local Govt Radiological Emergency in Support of LWRs;" use of 10-mile & 30-mile radii is excessive
Office of Nuclear Regulatory Research. 78/03/22. 3pp
- 7905230443 Comments on sections of OSA draft environ statement re disposal of Charlestown Naval Auxiliary Landing Field "hazards" should be referred to as "risks"
BUHL, A R Probabilistic Analysis Branch 78/06/06 2pp
- 7905230449 Discusses review of ATWS suppl (NUREG-0460) ATWS is not overwhelming safety problem in plant design ATWS risk estimates cannot be substantially improved
BUHL, A R Probabilistic Analysis Branch. 78/09/21 2pp.
- 7905230453 Forwards comments on "Investigation of Probability of Hypothetical Catastrophic Accidents in Oyster Creek Nuclear Power Plant," by PR Davis; upper bound estimate of protection vs failure probability is not justified
LEVINE, S Office of Nuclear Regulatory Research 76/11/09 10pp
- 7905230460 BECY-78-624
Requests approval of NRC response to PIRO et al petition for rulemaking to amend 10CFR100 re population density criteria around nuclear reactor sites
HINDQUE, R B Office of Standards Development 78/12/04. 157pp
- 7905230470 Comments on BECY-78-624, PIRO petition for rulemaking on population density around reactor sites; proposed response by NRC is deficient.
PEDERSEN, K B. Office of Policy Evaluations KELLEY, J L Office of the General Counsel 79/01/04. 11pp.
- 7905230701 Informs that NRC will seek recommendation of Siting Policy Task Force before taking action on BECY-78-624.
CHILK, S J Office of the Secretary of the Commission 79/01/04 1p.
- 7905230484 Requests progress briefing by Siting Policy Task Force re work status, problems, plans & principal issues receiving task force attention Comments on role of certain concepts in policy for site evaluation
CHILK, S J Office of the Secretary of the Commission. 79/01/05. 1p
- 7905230494 Comments on BECY-78-624, PIRO petition for rulemaking on population density around reactor sites; NRC should not respond to petition until further info is received Agrees w/request for task force briefing.
AHEARNE, J F. Commission 79/01/09 1p
- 7905230499 Comments on BECY-78-624, PIRO petition for rulemaking on population density around reactor sites; Commissioner Ahearne believes task force should be informed of specific questions re petition or proposed responses.
CHILK, S J Office of the Secretary of the Commission. 79/01/11 1p.
- 7905230713 Comments on BECY-78-624, PIRO petition for rulemaking on population density around reactor sites; RT Kennedy proposed response to petition is acceptable
SHAPE, H K Office of the Executive Legal Director. 79/01/11 2pp.
- 7905230508 Proposed Reg Guide 1.3, "Assumptions Used for Evaluating Light Water Power Reactor Siting Distances for Purposes of 10CFR100."
* Office of Standards Development 78/12/31. 13pp.
- 7905230511 Proposed Reg Guide 1.4 "Assumptions Used for Evaluating Potential Radiological Consequences to Public from Design Basis Accidents in LWRs for Purposes of 10CFR50 & 51."
Proposed revision to 10CFR100 encl.
* Office of Standards Development. 78/12/31. 41pp.
- 7905230524 Requests Executive Branch position re Hoke, Inc application for license to export components to Argentina.
OPLINGER, O O Assistant Director for Export/Import & International Safeguards 79/04/26 1p
- 7905230533 Requests Executive Branch position re Transnuclear, Inc application for license to export BNH to Denmark.
GOSSICK, L V Office of the Executive Director for Operations. 79/04/26. 1p.
- 7905230537 BECY-79-272
Informs Commissioners of receipt of withdrawal of 780608 license application by Samincorp, Inc to export matl to India
SHEA, J R. Assistant Director for Export/Import & International Safeguards. 79/04/17. 1p

--7905230835 Responds to 790212 ltr re application for license to export monazite ore to India. Application forwarded 790621 to Executive Branch for review. Review close to completion when application was cancelled in Dec 1978.
BHEA, J. R. Office of International Programs. 79/04/13. 1p

7905230541 Comments on proposed rulemaking 10CFR2-7 existing rules are adequate for protection of rights of parties & necessary to give finality to proceedings.
PORTER, H. L. Duke Power Co. 79/04/13 2pp

7905230553 BECY-79-271
Provides background info re proposed issuance of license for Edlow Intl Co to import enriched U from Japan. Recommends license be granted.
BHEA, J. R. Office of International Programs 79/04/16. 3pp.

7905230559 Executive Branch position re Byron Jackson Pump Div application for license to export components & parts to Switzerland. License should be granted.
NOBENZO, L. V. State, Dept. of, Bureau of Oceans & Internatl Environ. & Scientific Affairs 79/04/24 3pp

7905230567 Requests license to import fuel assemblies being returned to US from Japan for reprocessing, on behalf of British Nuclear Fuels, Ltd. Unsigned import license encl.
EDLOW, J. Edlow International Co 79/02/07. 3pp.

7905230572 Agenda of 790308-10 227th ACRS meeting in Washington, DC to discuss various ACRS repts re status of LHR generic items & dynamic loads as design basis for nuclear facilities
* ACRS - Advisory Committee on Reactor Safeguards 79/02/28 3pp

7905230575 Executive Branch position re Byron Jackson Pump Div application for license to export parts for use in reactor coolant pump to Italy. License should be granted.
NOBENZO, L. V. State, Dept. of, Bureau of Oceans & Internatl. Environ. & Scientific Affairs. 79/04/24 2pp.

7905230577 Comments on proposed Reg Guide 8.23 guide is too specific & leaves no leeway for health physicists to follow best course of action. Guide aimed at procedure & not protection.
EYRAETZ, J. C. Health Physics Society. 79/04/17. 2pp

7905230581 Forwards QA Program Insp Rept 9900510/79-01 on 790226-0302 & notice of violation
FOUADOVB, U. Region 4, Dallas, Vendor Inspection Branch 79/03/18. 2pp.

--7905230587 Notice of deviation from insp on 790226-0302
* Region 4, Dallas, Vendor Inspection Branch. 79/03/14 1p

--7905230593 QA Program Insp Rept 9900510/79-01 on 790226-0302. Noncompliance noted; released stress repts not revised by committed corrective action completion date
COBTELLO, J. R., BROWN, R. L., HALE, C. J. Region 4, Dallas, Vendor Inspection Branch. 79/03/14 15pp.

7905230597 Executive Branch position re DE application for license to export components & parts to Japan. License should be granted.
NOBENZO, L. V. State, Dept. of, Bureau of Oceans & Internatl. Environ. & Scientific Affairs. 79/04/24. 2pp.

7905230606 Notifies of current status of PRM-71-6 re emergency response for transportation accidents involving radioactive materials. Draft rept of NRC/DOE study of transportation hazards released for public comments, which NRC must consider.
MINDQUE, R. B. Office of Standards Development. 79/04/17. 1p.

--7905230611 Forwards PRM-71-6 & 40 public comments received for consideration in conjunction with rulemaking proceedings.
W/o encl.
BERNERD, R. M. Assistant Director for Materials Safety Branch 79/04/17. 1p.

7905230629 Amend 4 to License IBNM-1610 for Transnuclear, Inc. extending expiration date from 790630 to 800630.
OPLINGER, O. O. Assistant Director for Export/Import & International Safeguards. 79/04/13. 1p.

7905230634 Provides NRC conclusions re Exxon Nuclear Co, Inc Sept 1978 application to export 88,400 kg U to Belgium. License should be issued, based on Executive Branch position & end use statement.
MOORE, R. M. Office of International Programs 79/04/27. 1p.

7905230638 Notification of contract execution: "Two Phase Flow Aspects of Reactor Safety," awarded to Dartmouth College.
HANCZER, M. B. Technical Assistance Contracts Branch. FIN B-6525. NRC-03-79-102. 79/04/24 1p.

--7905230647 Contract "Two Phase Flow Aspects of Reactor Safety," awarded to Dartmouth College
DOUGHERTY, D. J. Division of Contracts FIN B-6525 NRC-03-79-102 79/04/24 16pp

7905230669 Executive Branch position re BW Shattuck Chemical Co application for license to export 10.3 lb depleted U to Mexico. License should be granted.
NOBENZO, L. V. State, Dept. of, Bureau of Oceans & Internatl Environ. & Scientific Affairs 79/04/30 2pp

7905230682 Notification of contract execution. Mod B to "Assessment of Nuclear Industrial Impact on Environ." Contractor Univ of WA.
HAGEY, H. Research Contracts Branch FIN B-5679 NRC-04-75-222 79/04/26 1p

--7905230690 Mod B, continuing funding & work on Task 4 to "Assessment of Nuclear Industrial Impact on Environ."
MORTON, K. V. Research Contracts Branch FIN B-5679 NRC-04-75-222 79/04/19 3pp

7905230696 Notification of change in 790328 telegram & 790331 ltr to read "Uranic" instead of "Uranios"
WILSON, B. D. General Electric Co. 79/03/30 1p

7905230697 Notification of contract execution. Mod C to "Improvement of Lister Techniques for Analyzing Atmospheric Dispersion of Nuclear Power Plant Effluents." Contractor Stanford Research Inst.
HAGEY, H. Research Contracts Branch FIN B-6222 NRC-04-77-147 79/04/25. 1p

--7905230702 Mod C, changing period of performance to 790430 at no cost, to "Improvement of Lister Techniques for Analyzing Atmospheric Dispersion of Nuclear Power Plant Effluents."
MORTON, K. V. Research Contracts Branch FIN B-6222 NRC-04-77-147 79/04/23 2pp

7905230708 Executive Branch position re Edlow Intl Corp application for license to export 2,190 kg U-235 to Sweden. License should be granted. Ltr of assurance encl.
NOBENZO, L. V. State, Dept. of, Bureau of Oceans & Internatl Environ. & Scientific Affairs 79/03/01 2pp.

7905230716 Submits NRC conclusions re Transnuclear, Inc application for license to export 18,951 kg U to West Germany. License should be issued.
MOORE, R. M. Office of International Programs 79/04/27 1p

7905230717 Notification of contract execution. Mod B to "NBS Control Room Infiltration Program." Contractor Dept of Commerce
HENCZER, M. B. Technical Assistance Contracts Branch FIN B-5329. 79/04/30. 1p.

--7905230720 Mod B, decreasing funding by \$80.47 to "NBS Control Room Infiltration Program."
DOUGHERTY, D. J. Division of Contracts FIN B-5329 79/04/30 3pp.

7905230741 Research Info Ltr 49, invitro dissolution of U product samples from four U mills. Forwards NUREG/CR-0414 W/o encl.
LEVINE, B. Office of Nuclear Regulatory Research 79/04/04 5pp

7905230749 Forwards UCS petition requesting that NRC order immediate reanalysis of operating plants to determine adequate earthquake protection.
WEISS, E. R. Sheldon, Harmon & Roisman. 79/03/28 2pp.

--7905230760 UCS emergency petition for reanalysis of capacity of operating US nuclear power plants to withstand earthquakes
WEISS, E. R. Sheldon, Harmon & Roisman. 79/03/28. 10pp

7905230761 Comments on proposed Reg Guide 1.144: Flexibility provided by ANSI N45.2 12-1977 is extremely beneficial to auditing operation while still ensuring that goals of program are achieved.
SULLIVAN, T. J. Consumers Power Co 79/03/20. 2pp.

7905230765 Agenda for 781207-09 224th ACRS meeting in Washington, DC to discuss ACRS annual rept to Congress on NRC safety research program.
* ACRS - Advisory Committee on Reactor Safeguards 78/11/21. 2pp

7905230778 Comments on proposed Reg Guide 1.1XX, "Functional Spec for Safety-Related Valve Assemblies in Nuclear Power Plants." Safety-Related Valve Assemblies of ANSI N278.1 & applicability. doubts industry acceptance of ANSI N278.1 & applicability.
OAVIGAN, F. X. Energy, Dept. of. 79/04/12 1p.

NONDOCKETED ITEMS

- 7905230781 Confirms understandings re 781013 application for license to export 110,230 lb Zircaloy-4 tube shells to West Germany. License action will be withheld pending retransfer assurances from Iranian govt.
DPLINGER, O O Assistant Director for Export/Import & International Safeguards 79/04/13 1p
- 7905230787 Agenda of 790104-03 225th ACRS meeting in Washington, DC to discuss ATSB & reg guides
* ACRS - Advisory Committee on Reactor Safeguards. 78/12/23 3pp
- 7905230788 "Dosimetry & Biotransport Models to Implement ALARA," quarterly progress rept, Oct-Dec 1978
KILLOUGH, O O, KOCHER, D C Oak Ridge National Laboratory FIN B-0188 ORNL/HASRD-21. 78/12/22 4pp
- 7905230801 Notifies that C Helt is Plant Sys Branch representative to follow matls aspects of qualification testing evaluation.
STELL, D V. Division of Operating Reactors 79/04/06 1p
- 7905230814 Requests plant shutdowns be scheduled to avoid blackouts. Firm's production is directly dependent upon availability of electric cooling sys
MAY, K N Affiliation Unknown 79/04/26 1p
- 7905230820 BECY-79-142A
Notifies of NRC review of proposed Westinghouse license to import low enriched U from Sweden. Recommends license be issued
SHEA, J.R Office of International Programs. 79/04/12. 3pp
- 7905230822 BECY 79-235
Informs of completion of NRC review of proposed amend to Exxon license to import partially completed fuel assemblies from West Germany. Amend should be issued.
SHEA, J.R Office of International Programs 79/04/12. 3pp
- 7905230828 Amend 1 to Exxon Nuclear Co, Inc license to export increased quantity of U-235 to West Germany
DPLINGER, O O Assistant Director for Export/Import & International Safeguards 79/01/02 1p.
- 7905230839 License for Exxon Nuclear Co, Inc to export 2,557 kg U-235 to West Germany
DPLINGER, O O Assistant Director for Export/Import & International Safeguards 77/08/23 2pp.
- 7905230846 Amend 1 to Exxon Nuclear Co, Inc license to import increased amount of U from West Germany.
DPLINGER, O O Assistant Director for Export/Import & International Safeguards 78/12/04 1pp.
- 7905230849 Forwards request for addl info re NEDO-21888, "Mark I Long-Term Program Load Definition Rept"
EISENHUT, D O Division of Operating Reactors. 79/05/03. 5pp
- 7905240001 BECY-79-102A
Provides NRC review of proposed issuance of license to Mitsubishi Intl Corp to export source matl to Canada.
Requests Commissioner comments by 790330.
SHEA, R. Office of International Programs. 79/03/30. 3pp
- 7905240005 Forwards application for license to export source matl to Eldorado Nuclear Ltd, Canada.
TSUJI, K Mitsubishi International Corp (subs. of Mitsubishi Corp.). NYC/HA-646. 78/09/14 1p.
- 7905240010 Application for Mitsubishi Intl Corp to export 538,511 kg U contained in 635,036 kg U-308 to Canada.
TSUJI, K. Mitsubishi International Corp. (subs. of Mitsubishi Corp.) HSA-5686-01. 78/09/14 2pp.
- 7905240021 NRC position re Transnuclear, Inc application for license amend to export low enriched U to Switzerland. License should be granted
MOORE, R.N. Office of International Programs. 79/04/09. 1p
- 7905240023 Forwards application for export license for minor nuclear export. Ltr of assurance required. W/o encl.
DPLINGER, O.O. Assistant Director for Export/Import & International Safeguards 79/04/26. 1p.
- 7905240025 NUREG/CR-0040 V1 N4
"Licensee, Contractor & Vendor Insp Status Rept," quarterly rept.
* Office of Inspection & Enforcement. 78/06/30. 308pp. Available at NTIS. \$12.50.
- 7905240028 NUREG-0040 V3 N1
"Licensee, Contractor & Vendor Insp Status Rept," quarterly rept.
* Office of Inspection & Enforcement 79/03/31 130pp Available at NTIS \$12.50
- 7905240031 NUREG-0040 V2 N6
"Licensee, Contractor & Vendor Insp Status Rept," quarterly rept.
* Office of Inspection & Enforcement 78/12/31. 237pp Available at NTIS \$12.50
- 7905240035 NUREG-0040 V1 N3
"Licensee, Contractor & Vendor Insp Status Rept," quarterly rept.
* Office of Inspection & Enforcement 78/03/31. 227pp. Available at NTIS \$7.50
- 7905240047 NUREG-0040 V1 N2
"Licensee, Contractor & Vendor Insp Status Rept," quarterly rept.
* Office of Inspection & Enforcement. 77/12/31 284pp. Available at NTIS \$7.50
- 7905240050 Requests Executive Branch position re Berg-Warner Corp application for license to export globe & check valves to Belgium
DPLINGER, O O Assistant Director for Export/Import & International Safeguards 79/04/26 1p
- 7905240051 NUREG-0040-77/2
"Licensee, Contractor & Vendor Insp Status Rept," quarterly rept.
* Office of Inspection & Enforcement. 77/06/30. 149pp. Available at NTIS \$7.50
- 7905240053 NUREG-0040-05
"Licensee, Contractor & Vendor Insp Status Rept," quarterly rept.
* Office of Inspection & Enforcement. 77/03/31 173pp. Available at NTIS \$12.50.
- 7905240058 NUREG-0040-02
"Licensee, Contractor & Vendor Insp Status Rept," quarterly rept.
* Office of Inspection & Enforcement. 76/06/30 158pp. Available at NTIS. \$6.75.
- 7905240059 BECY-79-120A
Forwards background info re proposed issuance of license to Exxon Nuclear Co, Inc to import low enriched U. License should be granted.
SHEA, J.R. Office of International Programs 79/04/02 2pp
- 7905240061 NUREG-0040-01
"Licensee, Contractor & Vendor Insp Status Rept," quarterly rept.
* Office of Inspection & Enforcement 76/03/31. 67pp. Available at NTIS \$4.50.
- 7905240063 NUREG-0040-03
"Licensee, Contractor & Vendor Insp Status Rept," quarterly rept.
* Office of Inspection & Enforcement. 76/09/30. 144pp. Available at NTIS \$6.00.
- 7905240068 Confirms 790420 telcon informing that Ofc of General Counsel will serve Executive Secretary of DOB & HK Shaper. NRC Executive Legal Director, re Westinghouse application to export BNW Westinghouse has been served.
ASHER, T R Asher, T. R. PC. 79/04/20. 1p.
- 7905240070 Agenda of 790405-07 228th ACRS meeting w/NRC & DOE in Washington, DC to discuss various ACRS repts re generic items & selected reactors
* ACRS - Advisory Committee on Reactor Safeguards. 79/02/28 6pp.
- 7905240102 Notification of 790501 meeting w/Exxon Nuclear Co to discuss Exxon rod bow model.
HANNON, J M. Operating Reactors Branch 3. 79/04/10. 2pp
- 7905240103 Comments on 790116 ACRS meeting in Washington, DC: specs of QA code applications should be provided as fully & clearly as possible
HU, T Y. Hu, T.Y. 79/02/16. 2pp.

7905240107 Notification of contract execution, Mod 4 to "Antitrust Consultants." Contractor Charles River Associates
LEBO, C D Technical Assistance Contracts Branch FIN B-5141
79/04/24. 1p

--7905240111 Mod 4, decreasing amount obligated by \$3,902.92 to "Antitrust Consultants" J
DOUGHERTY, D J Division of Contracts. FIN B-5141 79/04/30
1p.

7905240113 "Acoustic Emission/Flaw Relationships for Inservice Monitoring of Nuclear Pressure Vessels," Mar 1979 progress rept re flaw growth in A933B pressure vessel steel.
HUTTON, P. H., SCHWENK, E. B., KURTZ, R J Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-208B. 79/04/17 11p.

7905240116 Application by Isotope Products Labs for license to export 10 mCi Cm-244, contained in ceramic disc to Canada
AMLAUER, K Isotope Products Laboratories W/D 6835 79/04/23
2pp

7905240118 Notification of contract execution "Computer Package for Bayesian Analysis of Attribute Data w/Arbitrary Prior Distributions," awarded to KS State Univ
HAQEV, H. Research Contracts Branch FIN B-6705 NRC-04-79-182.
79/04/24. 1p

--7905240125 Contract "Computer Package for Bayesian Analysis of Attribute Data w/Arbitrary Prior Distributions," awarded to KS State Univ.
MORTON, K V. Research Contracts Branch. PERRY, R H Kansas State Univ. FIN B-6705 NRC-04-79-182. 79/04/17 4pp.

7905240119 Forwards application for license to export moveable incore detector to Belgium
KEENAN, R. P. Westinghouse Electric Corp ICB-8556 79/04/19. 1p

--7905240123 Application by Westinghouse for license to export one moveable incore detector containing 0.0041 g U-308 to Belgium
KEENAN, R P. Westinghouse Electric Corp. 79/04/20 1p.

7905240121 Requests expiration date of License IBNM-1610 be extended from 790630 to 800630.
HATSON, V. Transnuclear, Inc. 79/04/10. 1p.

7905240130 Summary of 790418 meeting w/B&W in Bethesda, MD re natural circulation in B&W reactors
ROBB, D F Division of Project Management 79/04/24 14pp

7905240147 BECY-79-248
Notifies NRC of receipt of British Embassy application for license to export source matl to United Kingdom.
SHEA, J.R. Office of International Programs 79/04/06 1p.

7905240153 Weekly info rept for week ending 790406.
REIM, T.A. Office of the Executive Director for Operations
79/04/11 26pp.

7905240155 Weekly info rept for week ending 790330
REIM, T.A. Office of the Executive Director for Operations.
79/04/05. 21pp

7905240164 Forwards RE Williams 790328 ltr re groundwater contamination at Cotter site. Shukle 790218 memo re tailings impoundment & WA Mahler response.
MCORATH, E. J. McOrath, E J. 79/04/11. 1p.

--7905240170 Suggests method for monitoring groundwater contamination at Cotter site. Notes wells which should be used. Suggests location of another which should be drilled w/article on embankment dam design
WILLIAMS, R. E Idaho Univ. of 79/03/28. 14pp

7905240173 BECY-79-249
Informs of receipt of license application from GE to export low enriched U oxide powder to Japan.
SHEA, J.R. Office of International Programs. 79/04/06. 1p

7905240202 Requests comments re Nissho-Iwai American Corp amend to export license application, changing address of intermediate consignee.
GOSBICK, L V. Office of the Executive Director for Operations.
79/04/30. 1p.

7905240208 Transcript of 790510-12 229th ACRB meeting in Washington, DC.
Pp 1-96B.
CARSON, M. W., PLESSET, M. B., BENDER, H. ACRB - Advisory Committee on Reactor Safeguards 79/05/10. 96Bpp

7905240264 Notification of 790531 presentation by Harry Diamond Lab to Qualification Testing Evaluation Research Review Group to discuss fluidic development re nuclear plants
FEIT, R Division of Reactor Safety Research 79/05/02 2pp

7905240281 BECY-79-258
Notifies NRC of receipt of Transnuclear, Inc application for license to export highly enriched U to Sweden
SHEA, J R Office of International Programs 79/04/12 1p

7905240315 Informs that Commissioners have reviewed License IBNM-78004 of Exxon Nuclear Co, Inc & accepted BECY-79-255 recommendation to amend license to increase quantity of low enriched U to be imported from West Germany
CHILK, S J Office of the Secretary of the Commission 79/04/20 1p

7905240316 Research Info Ltr 48 forwards NUREO-0382, "Tectonic Overview of Central Midcontinent"
LEVINE, S Office of Nuclear Regulatory Research 79/04/03 4pp

--7905240326 NUREO-0382
"A Tectonic Overview of the Central Midcontinent"
HINZE, W J., BRAILE, L W Purdue Univ KELLER, O R Texas Univ of 77/11/30 106pp Available at NTIS \$6 50

7905240320 "Fire Protection in Operating Nuclear Power Stations," Indian Point Unit 3 SER review
HALL, R E Brookhaven National Laboratory FIN A-3107 79/03/21 4pp

7905240325 Application by Hoke, Inc for license to export nuclear components to South Korea
LINDNER, T.P. Hoke, Inc 1132 79/04/16. 5pp

7905240337 Requests addl info to complete review of BVTR-1-0, "QA Program Description"
HAAS, W P Quality Assurance Branch BVTR-1-0. 79/04/30 14pp

7905240346 "Environ Statements Project, Cost/Benefit Analysis Group," progress rept for Feb 1979
TEPEL, R C Oak Ridge National Laboratory FIN B-0411 79/03/22 3pp

7905240353 "BWR Blowdown/Emergency Core Cooling Program" monthly rept for Mar 1979.
BURNETTE, O.W. General Electric Co, Nuclear Energy Products Div NRC-04-76-215. 79/04/05 6pp

7905240358 Notifies that Commission has reviewed & accepted Transnuclear, Inc license to export 4.23 kg U, enriched to 93.3% U-235, to Canada (BECY-79-157).
CHILK, S.J. Office of the Secretary of the Commission 79/05/07 1p.

7905240359 Summary of 790425 meeting w/util in TN re visit to facility to acquire info for further development of fault trees by Sandia Labs.
ANGELO, J Light Water Reactors Branch 1. 79/05/04 2pp.

7905240366 Informs that Commissioners have reviewed & accepted Transnuclear, Inc license to import 5,500 kg U, enriched to 2.3% U-235, from France (BECY-79-286).
CHILK, S J. Office of the Secretary of the Commission. 79/05/07 1p

7905240371 BECY-79-28814
Informs Commission of receipt of GE 790413 application for license to export low enriched U to Japan
SHEA, J.R. Office of International Programs. 79/04/24. 1p

7905240377 Forwards Bokum Resources 790418 reply to NRC 790323 request for info re tabulation of data & assumptions re airborne emissions for Bokum U mine.
TOPP, A.A. New Mexico, State of. 79/04/20 27pp.

7905240389 "LWR Thermal Hydraulic Development Program," monthly highlights for Mar 1979.
JONES, D C Brookhaven National Laboratory FIN A-3045. 79/03/31 5pp.

7905240398 Forwards NUREO-0511, Vols 1-2, "Draft OEIS on U Milling." Requests review & comment.
SCARANO, R.A. Uranium Recovery Licensing Branch. 79/04/18. 1p

--7905240406 NUREO-0511 V1
"Draft OEIS on U Milling," Vol 1, summary & text
Office of Nuclear Material Safety & Safeguards 79/04/30. 340pp.

- 7903240413 NUREG-0311 V2
"Draft OEIS on U Milling," Vol 2, Apps
* Office of Nuclear Material Safety & Safeguards 79/04/30
270pp.
- 7903240401 Forwards state agencies' comments on NUREG-0499, "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing"
YOUNGBLOOD, J. Arizona, State of 79/02/13 18pp
- 7903240404 "Physical Protection of Nuclear Facilities," progress rept for Feb 1979
CHAPMAN, L D Sandia Laboratories FIN A-1060 79/03/16 9pp
- 7903240409 Notification of contract execution, Mod 3 to "Investigation of Use of Cyclic, Torsional Screw Plate Test to Determine Insitu Liquefaction Potential of Cohesionless Soils,"
Contractor Univ of FL
HAGEY, H Research Contracts Branch, FIN B-6254 NRC-04-77-171
79/04/24 1p
- 7903240420 Mod 3, adding funds for second year of 3-yr contract, to "Investigation of Use of Cyclic, Torsional Screw Plate Test to Determine Insitu Liquefaction Potential of Cohesionless Soils,"
MORTON, K V Research Contracts Branch FIN B-6254, NRC-04-77-171, 79/04/24, 4pp
- 7903240410 Forwards state agencies' comments on NUREG-0499, Suppl 1, "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing"
YOUNGBLOOD, J. Arizona, State of, 79/02/07 3pp
- 7903240415 "Thermal Hydraulic LMFBR Safety Experiments," monthly highlights for Mar 1979
JONES, D C Brookhaven National Laboratory FIN A-3024 79/03/31, 4pp
- 7903240417 Offers no comments on NUREG-0499, Suppl 1, "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing"
WALLACE, A Iowa, State of, 79/01/26, 1p.
- 7903240424 Offers no comments on NUREG-0499, "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Plant Licensing"
TEMPEST, L Utah, State of, 79/01/03 1p.
- 7903240427 "Short Segmented Cask Code Development & Validation," project highlights for Mar 1979.
ACRAWAL, A K. Brookhaven National Laboratory FIN A-3015-B 79/03/31 7pp.
- 7903240431 Executive Branch position re Caban Precision Engineering & Mfg Corp application for license to export 20,000 diamond incoinal springs to India. License should be granted
NOSENZO, L V. State, Dept of, Bureau of Oceans & Internatl. Environ. & Scientific Affairs, 79/04/30, 2pp.
- 7903240433 Comments on proposed rule: outlines biographical statement emphasizing nuclear plant siting experience
MCQUORUM, W. B. Ohio, State of 79/03/02 2pp.
- 7903240435 Details discussion of extension of interim fuel cycle rule through 790315. Notes NRC request for meeting re "Statement of Consideration for U Fuel Cycle Rule" (RM 50-3), subsequently scheduled for 790302
CHILK, S. J. Office of the Secretary of the Commission, 79/03/01, 1p.
- 7903240438 Offers no comments on NUREG-0499, "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing"
YOUNGBLOOD, J. Arizona, State of, 79/03/06, 2pp.
- 7903240439 Notification of contract execution, Mod 3 to "Institutional Radioactive Wastes," Contractor: Univ of MD.
HAGEY, H Research Contracts Branch, FIN B-5959 NRC-04-76-344, 79/04/24, 1p.
- 7903240447 Mod 3, extending period of performance until 790630 to "Institutional Radioactive Wastes,"
MORTON, K V Research Contracts Branch FIN B-5454, NRC-04-76-344, 79/04/24, 2pp.
- 7903240446 Requests 781214 FR notice (Vol 430241, Pg 58379-81) be sent to parties listed.
LEWIS, M. Affiliation Unknown, 79/02/16, 2pp.
- 7903240476 Summary of 790425 meeting w/C-E re natural circulation capabilities
THADANI, A C Reactor Systems Branch, 79/03/02 40pp.
- 7903240494 Forwards "Rept on Analysis Methods for RCS Natural Circulation."
TAYLOR, J H Babcock & Wilcox Co 79/03/18 1p
- 7903240495 "Rept on Analysis Methods for RCS Natural Circulation"
* Babcock & Wilcox Co 79/03/16 33pp
- 7903240496 Notice of availability of NUREG-0311, "Draft OEIS on U Milling"
SCARANO, R. A. Uranium Recovery Licensing Branch 79/04/16, 4pp
- 7903240529 "Advanced Reactor Safety Analysis Technical Assistance, Reactor Projects," monthly highlights for Mar 1979
BARI, R A Brookhaven National Laboratory, FIN A-3000 79/04/10 5pp.
- 7903240540 "Safeguards Analysis for Byproduct Matis & Small Quantities of BNM," monthly progress rept for Mar 1979
CHESTER, R. O, KIRKCEY, K A., RANDOLPH, M L Oak Ridge National Laboratory FIN B-6108 ORNL/HASRD-34, 79/04/09 5pp
- 7903240542 Forwards list of documents on file in support of Gulf Taylor U mill license application
MACKIN, J. New Mexico, State of 79/04/25 6pp
- 7903240552 "First Quarter FY79 Progress Rept on Refill Effects Program"
CROMLEY, C J, ROTHE, P H, GARY, C N Creare, Inc NRC-04-75-162
CREARE TN-292, 79/04/30 26pp
- 7903240553 "Physical Protection of Nuclear Matl In Transit Project," monthly rept for Mar 1979
CHAPMAN, L D Sandia Laboratories FIN A-1173 79/04/17 4pp.
- 7903240556 "Rept on Foreign Travel of TB Kress to Karlsruhe, Germany & Cadarache, France."
KREBB, T. S Oak Ridge National Laboratory, FIN B-0121 ORNL/FIR-586, 79/04/19 37pp
- 7903240567 Application by Westinghouse for license to export reactor internals, reactor control drive mechanisms, components for reactor fuel charging & discharging machines to Switzerland
KEENAN, R. P Westinghouse Electric Corp ICS-8574 79/04/23 2pp
- 7903240576 "Environ Assessments of Fuel Cycle Facilities," monthly progress rept Feb 1979.
ZITTEL, H. E Oak Ridge National Laboratory, FIN B-0279, ORNL/ED/EIS-88 79/02/28, 6pp.
- 7903240577 Application by Westinghouse to amend license to export equipment, parts & components for nuclear reactors to Belgium & France
HERBCH, M M Westinghouse Electric Corp, ICS-8580, 79/04/24, 1p.
- 7903240587 "Evaluation of Docket Files of Terminated Licenses," monthly progress rept for Mar 1979.
HOLOWAY, C F, LANTZ, P. M, DICKSON, H. W. Oak Ridge National Laboratory FIN A-9085-7, ORNL/HASRD-33, 79/03/31, 6pp.
- 7903240663 Notification of contract execution, Mod 4 to "Radionuclide Retention & Land Form Mod in Surface Pathways," Contractor, Univ of State of NY
HAGEY, H, Research Contracts Branch FIN B-600B NRC-04-77-169 79/04/25, 1p.
- 7903240669 Mod 4, extending period of performance to 790331 at no cost, to "Radionuclide Retention & Land Form Mod in Surface Pathways,"
MORTON, K V, Research Contracts Branch FIN B-600B NRC-04-77-169 79/04/25, 2pp.
- 7903240776 Requests denial of UCS 771104 petition for emergency & remedial action & UCS 780903 petition for reconsideration of NRC 780413 memo & order.
EDWARDS, D. Yankee Atomic Electric Co, 79/03/16, 10pp.
- 7903240787 Notification of contract execution, Mod 3 to "Antitrust Hearings," Contractor: Charles River Associates.
LEBO, C D. Technical Assistance Contracts Branch, AT(49-24)-0083 79/04/24, 1p.
- 7903240808 Mod 3, decreasing amount obligated for "Antitrust Hearings,"
DAUGHERTY, D. J. Division of Contracts AT(49-24)-0083, 79/04/30, 1p.

7905240820 Accepts recommendation for Dept of Army to export 230 kg depleted U to United Kingdom Requests notification of issuance & delivery of license to Dept of Army by 790507 CHILK,B.J. Office of the Secretary of the Commission. 79/03/01 1p

7905240860 Requests Executive Branch position re TX Nuclear Div application for license to export SNM to Peru. OPLINGER, O O Assistant Director for Export/Import & International Safeguards 79/04/03 1p

7905240863 Confirms 790423 telcon approving agreement between NRC & PQ&E for extension of time to file motion to compel discovery to NRC first set of supplemental interrogatories EVANS, D.J. Anti-Trust Division 79/04/23 1p.

7905240875 Executive Branch position re Byron Jackson Pump Div application for license to export two rotating elements & two mechanical seal cartridges & accessories to Japan License should be granted. NOSENZO, L.V. State, Dept of 79/03/02 2pp

7905240883 Executive Branch position re Spax Industries, Inc application for license to export 0 09823 g U-235, contained in 5 g U for use in mass spectrographic analysis, to Japan License should be granted, Japanese ltr of assurance encl NOSENZO, L.V. State, Dept of 79/03/07. 3pp

7905240886 NUREG/CR-0785 "CDMHX-1: Three-Dimensional Transient Single-Phase Component Computer Program for Thermal Hydraulic Analysis " W/errata sheet correcting NUREG/CR-0415 to NUREG/CR-0785 SHAW, W.T., DOMANUS, H.M., BUCHHEIT, R.C. Argonne National Laboratory. FIN A-2045 78/09/30 120pp

7905240889 Executive Branch position re OE application for license to export 331 kg U-234, contained in 11,965 kg U enriched to max of 3 1%, to Japan. License should be granted, Japanese ltr of assurance encl NOSENZO, L.V. State, Dept of 79/03/07. 3pp

7905240897 Executive Branch position re OE application for license to export, over 10-yr period, specially designed or prepared reactor parts & components to Sweden. License should be granted. NOSENZO, L.V. State, Dept of 79/03/07. 2pp

7905240925 NUREG/CR-0486 "Survey of Postirradiation Heat Treatment as Means to Mitigate Radiation Embrittlement of Reactor Vessel Steels." HAWTHORNE, J.R. Navy, Dept of, Naval Research Laboratory NRC-REG-79-103. NRL REPT 8287. 79/02/14 34pp. Available at NTIS.

7905240977 Advises that addl matl to CENPD-149-P re method for determining overall uncertainty in DNB operating margin is acceptable. Forwards revised evaluation. BAER, R.L. Light Water Reactors Branch 2. 79/04/03. 7pp.

7905240979 Notifies of NRC position change re application of ANSI 45.2.13, referenced in Reg Guide 1.123. Discusses current position & requests acceptance or alternative proposal within 30 days. HAASB, W.P. Quality Assurance Branch. 79/03/02. 1p.

7905240990 Requests addl info to complete review of NEDE-21821 & NEDE-21821-01, "BWR Feedwater Nozzle/Sparger," final rept & Suppl I, respectively. EISENHUT, D.O. Division of Operating Reactors. 79/03/08 2pp.

7905240991 Forwards license application summary & safety review submitted by Cotter Corp to CD Dept of Health, W/o encl. MCCRATH, E.J. McCrath, E. J. 79/04/11. 1p.

7905240997 Lists licensees who received IE Bulletin 79-038, "Nuclear Incident at TMI-Suppl I" Bulletin encl. PAPPAS, H. Region 3, Chicago, Office of the Director. 79/04/23 2pp.

7905250033 BECY-79-183A Discusses NRC review of proposed issuance of export license to Mitsubishi Intl Corp. SHEA, J.R. Office of International Programs. 79/04/02. 4pp

--7905250037 Application by Mitsubishi Intl Corp for license to export 545 kg U-235, contained in 16,341 kg U, to Japan. TSUJI, K. Mitsubishi International Corp. (subs of Mitsubishi Corp.). XBNM-1386. 78/09/29. 3pp.

--7905250041 Forwards application for license to export enriched U hexafluoride to Japan to be used for fabrication of fuel assemblies WATANABE, N Mitsubishi International Corp (subs of Mitsubishi Corp.). HBA-5478-08 78/09/29 3pp

--7905250045 Forwards 780914 end use statement. WATANABE, N Mitsubishi International Corp (subs of Mitsubishi Corp.) XBNM-1386 78/10/19. 2pp.

--7905250054 Executive Branch position re Mitsubishi Intl Corp application for license to export 545 kg U-235 to Japan Japanese ltr of assurance encl NOSENZO, L.V. State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs XBNM-1386 79/03/03 4pp.

--7905250059 License for Mitsubishi Intl Corp to export 545 kg U-235, contained in 16,341 kg U, to Japan OPLINGER, O O Assistant Director for Export/Import & International Safeguards 79/04/02 3pp

7905250038 Responds to 790121 ltr re 10CFR20 304 & Watts Retreat Farm Farm is licensed by State of NC, not by NRC. Proposal to amend 10CFR20 304, presently under consideration, would allow burial of radioactive matl w/NRC approval. KERR, Q.W. Office of State Programs 79/04/17. 1p

7905250030 Requests addl info & clarifications to complete evaluation of generic licensing topical rept EDR-1. Requests schedule for responses so rept review schedule can be drawn up. BAER, R.L. Light Water Reactors Branch 2. 79/04/26 5pp.

7905250063 Advises that Commissioners have approved proposed license by Transnuclear, Inc to export 19.8 kg U, enriched to 93 3% U-235, to Netherlands Requests description of security measures CHILK, B.J. Office of the Secretary of the Commission. 79/04/11. 1p

7905250069 Comments on proposed rule 10CFR19-20: forwards talk presented at AIF 790402 conference re regulation of radiation. Proposal would be very costly to implement. LEE, B. Commonwealth Edison Co. 79/04/06. 24pp.

7905250086 Summary of ACRB Subcommittee on Procedures & Administration 790207 meeting in Washington, DC re work assignments of ACRB fellows & possible fellows appointments. Encl withheld (ref 10CFR2.790) * ACRB - Advisory Committee on Reactor Safeguards. 79/02/07 3pp

7905250102 Notification of 790501 meeting w/C-E in Bethesda, MD to discuss plant transient responses & Michelson rept. THADANI, A.C. Reactor Systems Branch 79/04/26. 1p

7905250106 Summarizes ACRB ECRB Subcommittee 790319-20 meeting in Los Angeles, CA re std problem program. ZUDANS, Z. Franklin Institute Research Laboratory. 79/03/30 2pp.

7905250111 Evaluates Sandia 790226 mid-year review re upper heat injection RELAP model development; statistical LOCA study, two-phase jets, steam explosion phenomena & molten core interactions. CATTON, I. California, Univ. of, Los Angeles. 79/03/22. 4pp

7905250113 Notification of 790502 meeting w/OE in Bethesda, MD to discuss two loop test apparatus & model development. HODGEB, W. Analysis Branch. 79/04/26. 1p.

7905250114 Notification of contract execution, Mod 3 to "Review of Proposed Pile Foundations for Bailey Nuclear Generating Station." Contractor: MT Davison. PERLMAN, J. Purchasing Section. NRC-03-78-166. NRC-03-78-166 79/03/07. 1p

--7905250120 Mod 3, extending period of performance to 790424, to "Review of Proposed Pile Foundations for Bailey Nuclear Generating Station." HARGETT, D.J. Division of Contracts. NRC-03-78-166. NRC-03-78-166. 79/04/11. 1p.

7905250115 Ltr of assurance confirming govt authorization for licensee to receive & possess nuclear matl identified in application. Transfer will be subj to all conditions of 660808 agreement for cooperation between Switzerland & US. MULLER, R.E. Switzerland. 681.513 SKW-MR/. 79/03/26. 1p.

NONDOCKETED ITEMS

7905250118 Review LERs. Better operator training is needed. Discusses several incidents indicating operator problems & requests narrative followup repts covering noted LERs. CATTON, I. California, Univ. of, Los Angeles 79/04/17 3pp.

7905250122 Summary of 790425 meeting w/Black & Veatch Consulting Engineers in Kansas City, MO re topical rept BVTR-1-0, "QA Program Description". SPAUL, J. Quality Assurance Branch 79/04/27 2pp

7905250124 Requests comments on NURE0-0660 re operating experience of emergency onsite diesel generators at LWRs. VASSALLO, D. B. Assistant Director for Light Water Reactors 79/04/18 3pp.

7905250133 Comments on ACRS EGCS Subcommittee 790319-20 meeting re code work on transient two-phase flow, LOFT L2-2 test, BWR core spray test program, CREARE downcomer program & std problem program. ZALOUDEK, F. R. Battelle Memorial Institute, Pacific Northwest Laboratory 79/03/28 2pp

7905250139 Comments on Mark I owners group 790215 meeting re vent clearing & pool swirl phase of suppression pool load definition study. CATTON, I. California, Univ. of, Los Angeles. 79/03/08 2pp.

7905250160 "Rept on Foreign Travel of BQ Eads, Manager for Advanced Instrumentation for Reflood Studies Program". EADS, B. O. Oak Ridge National Laboratory ORNL/FTR-581 79/04/20 5pp

7905250166 Informs that ltr of assurance has been sent re Eberline Instrument Corp license to export 0.22 micrograms Pu-239 to Austria. * Austria 79/04/13 1p

7905250167 Ack receipt of invitation to speak to Univ of VA Student Legal Forum; reluctant to give firm commitment at this time. HENDRIE, J. M. Commission 79/04/26 1p.

--7905250169 Extends invitation to speak at Student Legal Forum at Univ of VA School of Law. HENDRIE, J. M. Virginia, Univ of 79/04/12. 1p

7905250189 Summary of 790308-10 227th ACRS meeting in Washington, DC re review of request for DL for Zimmer Nuclear Power Station Unit 1, alternatives for resolution of ATWS & review of "Status of Generic Items Relating to LWRs." CARBON, M. W. ACRS - Advisory Committee on Reactor Safeguards. 79/03/22 3pp.

7905250195 Ack 790321 ltr requesting joint hearing re licensee application; concurs w/suggestion. Both organizations have already developed procedures to be proposed to any joint hearings. HENDRIE, J. M. Commission 79/04/24 1p.

--7905250209 Proposes joint hearing for consideration of issues over which NRC & NY State Public Svc Commission have concurrent jurisdiction. ZIELINSKI, C. A. New York, State of, 79/03/21. 2pp.

7905250207 Notifies that NRC has not completed licensing action on application to export low enriched U fuel to Japan. Favorable Executive Branch view received on 790307. Final matters under review. SHEA, J. R. Office of International Programs. 79/05/07. 1p.

7905250214 "Crack Arrest Technology" monthly progress rept for Mar 1979. ROSENFELD, A. R. Battelle Memorial Institute, Columbus Laboratories NRC-04-76-293-06. 79/04/11 3pp.

7905250224 Transcript corrections of 790119 hearing. LINKER, H. Natural Resources Defense Council. 79/02/27. 1p

7905250231 Notification of 790426 meeting w/EPRI & util re IE Bulletin 79-01. JORDAN, E. L. Division of Reactor Operations Inspections. 79/04/19. 2pp.

7905250232 License for Edlow Intl Co to import 115 kg U as irradiated MTR fuel elements. OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/05/09. 2pp

7905250235 License for Consolidated Controls Corp to export twenty 425 LDI resistance temp detectors to Italy. OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards. 79/05/09. 1pp

7905250237 License for Edlow Intl Co to export 2,190 kg U-235, contained in 61,750 kg U hexafluoride, to Sweden. OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/05/09 2pp

7905250264 BECY-79-268. Forwards application from Aerojet Ordnance Co to export source matl to Canada. SHEA, J. R. Office of International Programs 79/04/16 1p

--7905250270 Application for amend & renewal of license to export 100,000 kg U to Canada. SCHWARTZ, H. Aerojet Ordnance Co 79/04/06. 2pp.

7905250265 Application by Reuter-Stokes, Inc for license to export Reuter-Stokes Model RS-C1-1210-135 compensated ion chamber to France. SKARUPA, J. D. Reuter-Stokes, Inc. U-8129 79/04/27 1p

7905250272 License for Hoke, Inc to export needle valves, bellows-sealed instrument isolating valves, bellows-sealed manually & pneumatically operated valves, bleed & drain valves & three valve manifolds to South Korea. OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/05/09 1p

7905250276 License for Hoke, Inc to export bellows-sealed instrument isolating valves to Korea. OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/05/09 1p.

7905250282 License for Hoke, Inc to export bellows sealed manually & pneumatically operated valves, bleed & drain valves & three valve manifolds to Korea. OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/05/09 1p.

7905250287 Amend 2 to License XU-8342, increasing quantity of matl to 135,039 kg U, contained in 136,000 kg depleted U, for export to Canada. OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/05/09. 1p

7905250291 Amend 1 to License XBNM-0937, deleting Transnuclear as other party to export & substituting Nishio-Iwami Co. Ltd. for transport purposes only. SHEA, J. R. Assistant Director for Export/Import & International Safeguards. 79/05/09. 1p

7905250295 License for Hoke, Inc to export bellows-sealed instrument isolating valves & three valve manifolds to South Korea. OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/05/09 1p.

7905250299 Notification of contract execution: "Reactor Vessel Irradiation Damage," awarded to Naval Research Lab. OLAGOLA, A. F. Technical Assistance Contracts Branch FIN B-6809. 20-19-04-02-2. 79/04/03 1p.

--7905250309 Updates contract for "Reactor Vessel Irradiation Damage." Extends period of performance & increases cost estimate. DOUGHERTY, D. J. Technical Assistance Contracts Branch. FIN B-6809. NRC-03-79-148. 79/04/02 7pp.

7905250300 License for Hoke, Inc to export bellows-sealed instrument isolating valves & three valve manifolds to South Korea. OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards. 79/05/09. 1p.

7905250306 Application by Isotope Products Labs for license to export 0.01 micrograms Cf-252 neutron source welded in stainless steel capsule to Australia. AMLAUER, K. Isotope Products Laboratories. 79/05/01. 1p.

7905250312 Notifies of shipment of 1 g Th-232, 0.6 g U-238 & 0.05 g Np-237 to Russia between Jun & Oct 1979. Requests procedural instructions. CHETIRKIN, P. V. National Aeronautics & Space Admin. LB-236-5. 79/04/13. 1p.

7905250321 Comments on H. R. 344, H. R. 2 & H. R. 1059 per request. Forwards comments on B 2 which is similar to H. R. 2. Objects to duplicative budget review but supports objectives of bills to eliminate overlapping federal programs. HENDRIE, J. M. Commission. 79/03/16. 2pp.

--7905250326 Responds to request for review of B. 2 bill passed by Senate on 781011. Supports legislation to eliminate waste & duplication in federal govt. Questions effectiveness of citizens' commission due to statutory limitations. STOIBER, C. Office of the General Counsel. 78/12/19 2pp.

- 7903250329 Forwards H R 544 to require authorization of new budget authority for govt programs at least every five years & to establish procedure for zero-based budgeting. Requests review & comments
BROCKB, J House of Rep., Government Operations 79/01/29. 39pp
- 7903250336 Forwards H R 1059 to require authorization of new budget authority & review for govt programs at least every five years Requests review & comments.
BROCKB, J House of Rep., Government Operations. 79/02/07. 52pp
- 7903250337 Forwards H R.2 requiring new budget authority & program review at least every ten years
BROCKB, J House of Rep., Government Operations 79/01/24 66pp.
- 7903250322 Research Info Ltr 32 earthquake intensity scale. USGS should promulgate new intensity scale based on analysis described in ltr.
BENTON, H R Office of Nuclear Reactor Regulation MINOQUE, R B Office of Standards Development. 79/04/23 4pp.
- 7903250323 Authorizes issuance of license to Edlow Intl Co for export of 61,750 kg U, enriched to 3.55% U-235, to Sweden
MOORE, R W Office of International Programs. 79/05/09 1p
- 7903250327 Application by Unipax Intl for license to export 900 kg depleted U to Korea
YUN, J. W Unipax International 79/03/29 4pp.
- 7903250331 Advises that Commissioners have approved proposed license by Edlow Intl Co to import enriched U from Japan (SECY-79-271). Requests notification of issuance & delivery of license to Edlow by 790311
CHILK, B J Office of the Secretary of the Commission. 79/05/08 1p.
- 7903250333 Application by MELCO USA, Inc for license to export radiation detector to Japan
NAKATANI, T. Melco U.S.A., Inc. 79/03/23. 4pp.
- 7903250334 Summary of NRC 790503 discussion in Washington, DC re B-3 rulemaking.
CHILK, B. J Office of the Secretary of the Commission. 79/05/04 1p
- 7903250338 Summary of 790425-26 meeting w/ANL in Argonne, IL re preparation of final OEIS on handling & storage of spent LWR fuel.
ROBERTS, J. P Fuel Reprocess & Recycle Branch 79/03/02 1p.
- 7903250345 Requests Executive Branch position re Westinghouse application for license to export miscellaneous parts & components to Switzerland
DPLINGER, O. O. Assistant Director for Export/Import & International Safeguards. 79/05/09. 1p.
- 7903250374 Comments on proposed rule 10CFR19-20: rule does not allow flexibility provided by 5(N-18) dose averaging formula
BRENNSON, B. M Radiation Services, Inc. 79/03/14. 1p.
- 7903250379 Informs that conference w/counsel will be held on 790315-17 re brief & responses filed by parties & objections to util's fourth set of interrogatories & motions for protective order.
MILLER, H. E. Atomic Safety and Licensing Board Panel. 79/04/17. 1p
- 7903250442 Executive Branch position re Nishio-Iwai American Corp application for license to export 5 448 kg U-235 to Japan
License should be granted.
NOBENZO, L. V. State, Dept. of, Bureau of Oceans & Internatl. Environ. & Scientific Affairs. 79/04/30. 3pp.
- 7903250444 Forwards comments received as of 790330 re NUREQ-0396: "Planning Basis for Development of State & Local Govt Radiological Emergency Response Plans in Support of Light Water Nuclear Power Plants."
COLLINS, H. E. Assistant Director for Emergency Preparedness. 79/04/05. 1p
- 7903250447 Notice of availability of NUREQ-0396, rept of NRC/EPA Task Force on Emergency Planning.
RYAN, R. O Office of State Programs. 78/12/15 1p
- 7903250450 PCBE-79137
Comments on NUREQ-0396: emergency zone should be planned for small area around reactor. Once tested & perfected, zone could be expanded to appropriate size.
CLEARY, P. Citizens for a Better Environment. 79/03/29. 9pp.
- 7903250435 Comments on NUREQ-0396 NRC/EPA task force is not representative of public. Protective action & guides rely on subjective evaluations Reliance on Rasmussen rept calculations are questionable Rept should be recalled.
LEWIS, M. J Affiliation Unknown 79/01/31. 1p.
- 7903250438 Comments on NUREQ-0396 lack of NRC sanctions against inadequate plans shows fundamental flaw Reliance on WASH-1400 is misplaced
ROISMAN, A Z Natural Resources Defense Council 79/01/19. 3pp.
- 7903250460 Comments on NUREQ-0396, objects to absence of regulatory impact assessment & questions reliability of info used to support planning basis elements Placing parameters on emergency planning zone is premature.
REED, C Commonwealth Edison Co 79/03/26. 5pp
- 7903250462 Comments on NUREQ-0396 emergency planning zones unnecessary & inappropriate Rept is overly conservative & unrealistic Implementation of rept items will be very costly & lead to possible public misinformation.
WHITMER, C F Georgia Power Co 79/03/28. 2pp
- 7903250466 Comments on NUREQ-0396, 50-mile radius emergency plan is absurd, Rept not responsive to state program directors' needs Utils may be required to finance state emergency plans Calls for realistic planning
PARKER, W. D Duke Power Co 79/03/27. 2pp.
- 7903250467 Comments on NUREQ-0396 planning for Class 9 actions is not justified: questions validity of info supporting rept Establishment of emergency planning zones will be very costly.
RENNBERGER, D. L Washington Public Power Supply System. 79/03/28 5pp.
- 7903250469 Comments on NUREQ-0396, planning for Class 9 accident is illogical, rept lacks perspective on public risks & implementation costs & feasibility are misrepresented Requests value impact assessment & withdrawal of rept.
WARD, J E Atomic Industrial Forum 79/03/30. 6pp
- 7903250473 Comments on NUREQ-0396 rept is premature & based on incomplete info Issuing rept could complicate licensing process. Planning for Class 9 events should be reconsidered.
VANDENBURGH, D. Yankee Atomic Electric Co 79/03/28. 9pp
- 7903250476 Comments on NUREQ-0396 potential exists for confusion re licensees' emergency planning obligations Requests add clarification prior to NRC adoption of rept.
REIS, H F. Lowenstein, Newman, Reis, Axelrad & Toll 79/03/30 7pp.
- 7903250478 Comments on NUREQ-0396, adoption of rept could be very costly. Requests NRC provide adequate support in planning & implementation. Requests withdrawal & reconsideration of rept
BULLIVANT, T. J. Consumers Power Co. 79/03/23. 2pp.
- 7903250491 Comments on NUREQ-0396, present plans are adequate. Questions validity of emergency planning zones Implementation would be very costly.
ALLEN, O. J. Citrus County, FL 79/03/19. 4pp.
- 7903250493 Comments on NUREQ-0396: suggests rept be advisory only Expanded emergency planning zones are excessive & burdensome. Five & twenty-mile radii zones are more reasonable.
TEMPLE, J Grundy County, IL 79/03/23 2pp.
- 7903250494 Comments on NUREQ-0396: rept could be helpful if used early in planning process. Use of rept would lead to interjurisdictional planning & substantial costs.
HEUBNER, A. T Connecticut, State of 79/03/09. 1p.
- 7903250495 Comments on NUREQ-0396: local govts offer more meaningful planning participation than other govts Saluda Township, IN would like to participate in emergency planning discussions, but lacks funds. Inquires whether NRC can provide funds.
ORAY, R, CRAFTON, H Saluda Township, IN. 79/01/13. 1p.
- 7903250496 Comments on NUREQ-0396: current emergency plans are adequate. Questions standardized approach. Supports rept validity.
KOBS, R. R. Kewaunee County, WI. 79/03/06. 2pp.
- 7903250497 Comments on NUREQ-0396, planning for Class 9 event is unreasonable. Questions validity of dosimetry data.
KOHLE, R. Florida, State of. 79/03/23. 3pp.

NONDOCKETED ITEMS

- 7905230498 Forwards comments on NUREQ-0396 planning based on Class 9 accident is not realistic. Emergency plan criteria should be consistent with licensing criteria Ten & fifty-mile radii should be eliminated.
LEWIS, L. Affiliation Unknown. 79/03/22 3pp
- 7905230499 Civil Defense Ofc has no comments on NUREQ-0396
BOYD, H. K. Richland County, SC 79/02/08 1p
- 7905230500 Comments on NUREQ-0396 few county govts have expertise to prepare emergency plans. More guidance needed.
HAUNEY, B. R. Aiken County, SC 79/01/13 1p
- 7905230502 Comments on NUREQ-0396 local govts do not have expertise to understand or implement rept. Rept provides no objective means to measure emergency.
RIGOR, R. R. Contra Costa County, CA 79/03/28 3pp
- 7905230503 Ack receipt of NUREQ-0396. Requests addl info for preparing comments. Requests info on WASH-1400 reevaluation & its impact on NUREQ-0396 consideration schedule.
RADACK, E. D. Affiliation Unknown 79/01/29 1p
- 7905230504 Comments on NUREQ-0396 comprehensive emergency response plan already exists for CT. Rept does not address real health & safety needs of public. Suggest future inclusion of medical, meteorological & transportation expertise in repts.
MANCUSO, F. Connecticut, State of, 79/01/08 2pp
- 7905230505 Comments on NUREQ-0396 cost effectiveness is not adequately treated in rept. W/article from 790320 Charlottesville Daily Progress re Louisa County investigation of fallout facilities near North Anna plant.
WOOD, W. C. Virginia, Univ of 79/03/22 2pp
- 7905230506 Comments on NUREQ-0396 questions reliance of rept on WASH-1400. Rept should provide detailed description of worst case LOCA, avoid evaluation of event probability & suggest public evaluation drills.
IBSER, H. W. California State Univ, Sacramento, 79/03/26 2pp
- 7905230507 Forwards summary of 790214 public hearing. No one present supported extension of present 3-25 mile emergency planning zones to 10-30 mile radii proposed in NUREQ-0396. County Commissioners oppose zone extension.
GRANT, J. Citrus County, FL. 79/03/19 1p
- 7905230508 Comments on NUREQ-0396: agrees w/ views of SC Bureau of Radiological & Environ Control. County is outside plume exposure pathway for accidents discussed; no addl cost for emergency planning.
KINO, R. B. Anderson County, SC. 79/01/12 1p.
- 7905230510 Comments on NUREQ-0396: rept is vague re level of planning required for emergency planning zones. More consideration should be given to Class 1-B accidents.
MOORE, T. C. South Carolina, State of, 79/01/15 1p
- 7905230511 Comments on NUREQ-0396: establishment of emergency planning zones of std distances from all facilities is inappropriate. Suggests zones be established as required for each facility.
W/780811 ltr commenting on draft NUREQ-0396.
HENDERSON, O. K. Pennsylvania, State of 79/03/16 3pp
- 7905230512 Comments on NUREQ-0396: guidance useful, but expects considerable costs in implementing 30-mile emergency planning zones. Plant siting & emergency planning should be inseparable.
EPPERSON, L. M. Arkansas, State of 79/01/12 3pp.
- 7905230513 Comments on proposed amends to 10CFR30, App E: proposal is unnecessary. Questions rationale for imposing interim regulations. Amends would be very costly. Requests defeat of proposal.
COUNCIL, W. O. Northeast Utilities 78/10/10 2pp.
- 7905230514 Comments on NUREQ-0396: most local civil defense directors do not have expertise to understand rept.
BLACK, B. Oconee County, SC. 79/01/13 1p.
- 7905230515 Comments on NUREQ-0396: questions rept reliance on WASH-1400 & validity of emergency planning zone radii. Rept needs more work & would be costly to implement.
JONES, O. L. Virginia, State of, 79/03/21 2pp.
- 7905230518 States no comments should be made on NUREQ-0396 until after region & state civil defense preparedness agencies conduct briefings & conferences w/ local representatives.
PRICE, H. M. Florence County, SC 79/01/13 1p.
- 7905230519 Comments on NUREQ-0396 criticizes rept methodology for calculations of accident probabilities. Offers alternative. Funding not available for implementation of rept.
FARROT, M. H. Oregon, State of 79/02/08 2pp
- 7905230521 Comments on NUREQ-0396 expanded emergency planning zones not necessary & costly to implement. Suggests inclusion of guidance for local adjustments to zone radii.
SHANAHAN, W. R. Humboldt County, CA 79/01/16 2pp
- 7905230523 Comments on NUREQ-0396 rept implementation would be very costly. Questions feasibility & legal basis. Rept lacks historical perspective & technical basis in using Class 9 accident as planning basis.
COUNCIL, W. O. Northeast Utilities 78/11/13 4pp
- 7905230525 Comments on NUREQ-0396 unilateral adoption of rept methodology by NRC will probably not have desired results. Rept is good for bldg consensus in absence of significant mods to WASH-1400.
JASKE, R. T. Office of State Programs 78/09/25 4pp
- 7905230482 Comments on NUREQ-0396 revision is cosmetic in nature & previous comments still apply. Forwards 781129 comments on draft of same rept.
KASPERBKI, D. C. Gilbert Associates, Inc. 79/02/23 1p
- 7905230485 Forwards comments on Draft 2 of NUREQ-0396 planning for Class 9 accidents is unnecessary. Disputes NRC use of WASH-1400. Questions appropriateness of dose calculation methodology. Rept will increase public confusion.
KASPERBKI, D. C. Gilbert Associates, Inc 78/11/29 4pp.
- 7905230501 Forwards requested info: demographic statistics on reactor sites; rept on adequacy of composite population distribution & meteorological transport used in reactor safety study & maps showing nuclear plant locations.
COLLINS, H. E. Assistant Director for Emergency Preparedness 79/02/01 1p
- 7905230492 Requests demographic info for use in preparing comments on NUREQ-0396.
WOOD, W. C. Virginia, Univ of 79/01/24 1p.
- 7905230509 Comments on NUREQ-0396: requests info re relationship of rept to existing safety analyses & extensiveness of emergency plan. Suggests rept be used guide, not regulation.
MUMPER, H. J. Bechtel Power Corp (subs. of Bechtel Corp.). 79/01/16 1p
- 7905230516 Ack receipt of 790116 ltr re NUREQ-0396. Rept not intended as regulation. No relationship exists to past analysis performed on plant siting. Forwards NUREQ-0396 & NUREQ-78/111. W/o encl.
COLLINS, H. E. Assistant Director for Emergency Preparedness 79/01/16 1p.
- 7905230517 Ack receipt of 790223 ltr commenting on NUREQ-0396. Clarifies concept of 30-mile emergency planning zone. Rept implementation should not present substantial costs. Objects to suggestion that planning be based on historical events.
COLLINS, H. E. Assistant Director for Emergency Preparedness 79/03/26 2pp.
- 7905230520 Comments on NUREQ-0396: would be very costly to implement. NRC should bear the cost. St. Lucie County Commission voted to object to 30-mile concept at 790220 meeting.
RDDI, P. J. St. Lucie County, FL. 79/02/23 2pp.
- 7905230448 No comments on NUREQ-0499, Suppl 1: "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing."
WALLACE, A. T. Iowa, State of, 79/01/19 1p.
- 7905230451 No comments on NUREQ-0499, Suppl 1: "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing."
HAYWARD, N. Delaware, State of, 79/02/06 1p.
- 7905230453 Requests info re NUREQ-0499, "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing."
JOLMBRUD, J. H. Pennsylvania, State of, 79/02/01 1p
- 7905230454 Comments on proposed rule 10CFR17-20: questions justification of expense of changing regulation which is currently acceptable. Suggests continuation of present regulations to protect populace from radiation.
CASH, A. Yuba Heat Transfer Corp. 79/03/27 2pp.

NONDOCKETED ITEMS

315

7905250457 Comments on NUREG-0499, "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing;" new licensing for nuclear plants is futile since utilities are not requesting new plants
LEWIS, M. I. Affiliation Unknown. 79/01/31 1p.

7905250463 No comments on proposed rule "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing"
HILL, R. M. Nevada, State of 79/02/06 1p

7905250468 Comments on proposed rule "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing;" proposed project does not adversely affect state plans
DEGAETIA, P. V. Kansas, State of 79/02/12 7pp.

7905250470 Comments on NUREG-0449, Suppl 1, re nuclear plant licensing improvements as simple as possible.
YOUNGBLOOD, J. Arizona, State of. 79/02/06 18pp.

7905250483 Reg Guide 3.11 i, "Operational Insp & Surveillance of Embankment Retention Sys for U Mill Tailings."
* Office of Standards Development 79/04/30 8pp

7905250487 Comments on proposed Reg Guide 7.9, serious technical error. Fuel rods cannot contain anything within cladding
Guide should not be distributed.
LEWIS, M. I. Affiliation Unknown. 79/04/13 1p.

7905250522 Forwards comments on NUREG-0396, emergency planning should be done by licensee prior to OL Planning zones are adequate
Implementation of rpt would be very costly.
CLACK, B. J. Georgia, State of. 79/02/21. 3pp.

7905250531 Comments on proposed Reg Guide 1.2B, Revision 2, recommends clarification of term "safety-related," & believes Section C 1 is too restrictive.
WIDLEY, J. B. Bechtel Power Corp (subs of Bechtel Corp).
JBV-79-70. 79/03/30. 2pp

7905250539 Forwards NRC determination statement re public withholding of transcript of 790420 discussion of personnel matter
CHILKIS, B. J. Office of the Secretary of the Commission 79/05/08 2pp.

7905250540 Forwards 790316 ltr & end use statement from Radium-Chemie Ltd. as addl info to export license application.
HOK, H. M. Radium Chemical Co., Inc 79/04/18. 3pp

7905290008 Transcript of 790502 Affirmation Session 79-10 in Washington, DC. Pg 1-3.
MEMORIE, J. M., OILINSKY, V., KENNEDY, R. T. Commission. 79/05/02 4pp.

7905290015 Responds to 790409 ltr to JM Hendrie requesting info re operator license requirements Forwards Reg Guide 1.134, "Medical Evaluation of Nuclear Power Plant Personnel Requiring OL"
BOYD, R. B. Assistant Director for Light Water Reactors. 79/04/19. 1p.

--7905290018 Reg Guide 1.134, Revision 1, "Medical Evaluation of Nuclear Power Plant Personnel Requiring Operator Licenses."
* Office of Standards Development. 79/03/31 2pp

--7905290024 Requests info on nuclear power plant personnel regulations on alcohol before & during duty hours.
* United Christian Action, Inc. 79/04/09. 1p.

7905290038 Comments on proposed rule 10CFR19 & 20, approves elimination of accumulated dose averaging formula.
AAROE, W. H. West Virginia, State of. 79/04/06. 1p.

7905290043 Comments on proposed rule 10CFR19 & 20, failure of individual to disclose exposure rates could endanger fine.
MCCORMACK, J. B. Affiliation Unknown. 79/04/04. 1p.

7905290047 Comments on proposed rule 10CFR19 & 20, favors making 3 rem/yr dose limit for whole body exposure. Limit for calendar quarter should be abolished. Regulations should reflect most conservative annual limits
GALLAGHER, F. E. California, Univ. of, Santa Barbara. 79/04/04. 3pp

7905290067 Lists northern CA electric capacity margins in event of shutdown of plant Margins are insufficient to prevent customer load curtailment should addl forced outages occur.
W/790423 telegram to public util commission.
BROWN, H. P. Sacramento Municipal Utility District. 79/04/26. 2pp

7905290085 Ack receipt of 790327 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept
99900403/79-01
POTAF0VB, U. Region 4, Dallas, Vendor Inspection Branch
79/04/23 1p

--7905290091 Responds to NRC 790228 ltr re deviation noted in QA Program Insp Rept 99900403/79-01 Corrective actions audit rpt content will be added to checklist for internal audits prior to next scheduled internal audit
BARNARD, J. General Electric Co., Nuclear Energy Products Div
79/03/27 3pp

--7905290097 Forwards QA Program Insp Rept 99900403/79-01 on 790205-09 & notice of deviation
POTAF0VB, U. Region 4, Dallas, Vendor Inspection Branch
79/02/28 2pp

--7905290104 Notice of deviation from insp on 790205-09.
* Region 4, Dallas, Vendor Inspection Branch 79/02/26 3pp

--7905290113 QA Program Insp Rept 99900403/79-01 on 790205-09 Noncompliance noted audit summary rpt did not mention audit team meetings, did not identify checklists used & did not list persons contacted during audit
COSTELLO, J. R., BROWN, R. L., MALE, C. J. Region 4, Dallas, Vendor Inspection Branch. 79/02/26 22pp

7905290101 Forwards specific info re proposed end uses of tritium gas for export license submitted on 790213 W/o encl
OPLINGER, O. G. Assistant Director for Export/Import & International Safeguards 79/04/26 1p.

7905290107 Forwards Gulf Nuclear Inc comment on proposed rule 10CFR19 & 20.
PAUL, R. House of Rep. 79/04/18 1p.

--7905290110 Comments on proposed rule 10CFR19 & 20 opposes rule because no latitude allowed & wording indicates overexposures are deliberate
PEEPLES, W. P. Affiliation Unknown. 79/04/11 3pp.

7905290115 Comments on proposed Reg Guides 1.144.1 i25 Revision 1.1 72 Revision 2 & 1.9 Revision 1.
OILLELAND, J. E. Tennessee Valley Authority 79/04/05 8pp

7905290118 Forwards export license application for Transnuclear, Inc to export kg U to Denmark.
MATSON, V. Transnuclear, Inc 79/04/20 1p

--7905290121 Application by Transnuclear, Inc for license to export 15 03B kg U in form U-235 enriched to max 93.3% to Denmark
MATSON, V. Transnuclear, Inc 79/04/20 3pp.

7905290124 Comments on proposed Reg Guide 1.144 suggests deletion of paragraph 3iOA guidance is provided in Reg Guide 1.33
CANNILL, W. J. Consolidated Edison Co of New York. 79/03/20 3pp.

7905290127 License for Eberline Instrument Corp to export 0.22 kg P-239 to Austria.
OPLINGER, O. G. Assistant Director for Export/Import & International Safeguards. 79/04/23. 2pp

7905290128 License for Edlow Intl Co to export 800,000 Ci tritium to Switzerland
OPLINGER, O. G. Assistant Director for Export/Import & International Safeguards 79/04/23 1p

7905290131 Defers RH Oardes' deposition, served on 790326, until after 790318-17 prehearing conference.
MILLER, M. E. Atomic Safety and Licensing Board Panel 79/04/05 2pp

7905290133 License for Mitsubiline Travel Svc to export miscellaneous specially designed or prepared parts & components for use in nuclear reactors to Japan.
OPLINGER, O. G. Assistant Director for Export/Import & International Safeguards. 79/04/23 1p

7905290135 Applies for license to export reactor internals, reactor control drive mechanisms, components for reactor fuel charging & discharging machines to Spain
KEENAN, R. P. Westinghouse Electric Corp. 79/04/18. 2pp.

7905290136 Applies for license amend to increase enrichment in U-235 from 3.14 to 3.20 w/o max.
DAHLBYRD, C. O. Westinghouse Electric Corp. 79/04/17. 1p

NONDOCKETED ITEMS

- 7905290139 Application by Mitsui Lines Travel Svc of America, Inc for license to export 20 pieces of water tubing for S2B BWR fuel to Japan
YAMAZAKI, M Mitsui Lines Travel Service of America, Inc. 79/04/13. 2pp.
- 7905290141 Application by Edlow Intl Co for license to export 3 ampoules of BRM 4,333 Pu-242 to Sweden
HARMON, D.W Edlow International Co 79/04/19 2pp
- 790529016B Application by Air Products & Chemicals, Inc for license to export 1,886 liters of deuterium to England
NOVAKARD, D Air Products & Chemicals, Inc. 79/04/17 1p
- 7905290181 Requests participation in rulemaking re radioactive exposure of workers
LEWIS, M Environmental Coalition on Nuclear Power. 79/03/23 1p
- 7905290187 Requests that J Johnsrud & C Kepford be granted participation in rulemaking re radioactive exposure of workers.
LEWIS, M Environmental Coalition on Nuclear Power 79/03/23. 1p
- 7905290186 Advice of correction to Edlow Co application for license to export source matl to Brazil Matl is natural U & element weight should read 711X
OPLINGER, O O Assistant Director for Export/Import & International Safeguards 79/04/26 1p
- 7905290190 Submit application by Nissho-Iwai American Corp to amend license by changing intermediate consignee
TSUJIK, K Nissho-Iwai American Corp 79/04/20. 1p.
- 7905290231 Notification of contract execution; Mod 1B to "Geologic & Seismologic Review & Appraisal of Nuclear Facilities, Miscellaneous Investigations & Technical Support " Contractor: US Dept of Interior
OLAGOLA, A.F Technical Assistance Contracts Branch. NRC-03-75-113. 79/04/24 1p.
- 7905290242 Mod 1B, extending period of performance to 781030 w/no change in cost, to "Geologic & Seismologic Review & Appraisal of Nuclear Facilities, Miscellaneous Investigations & Technical Support " Contractor: US Dept of Interior
DOUGHERTY, D J Division of Contracts. NRC-03-75-113. 79/04/24 1p.
- 7905290238 Application by Aerojet Ordnance Co to amend & renew license to export 100,000 kg U to Canada
SCHWARTZ, H Aerojet Ordnance Co 79/04/06 2pp.
- 7905290239 Forwards NEDE-21944-P, "1/4 Scale Pressure Suppression Pool Swell Test Program: Plant Unique Tests," Vols 1-4 Affidavit for withholding encl. Rept withheld (ref 10CFR2 790).
BOBOL, L. J. General Electric Co., Nuclear Energy Products Div. MFN-113-79 79/04/24. 5pp.
- 7905290262 Transcript of 790508 meeting in Washington, DC Pp 1-220.
SHEPHERD, P O., MARK, J.C., ETHERINGTON, H ACRS - Advisory Committee on Reactor Safeguards 79/05/08 220pp.
- 790529026B Transcript of 790516 meeting in Bethesda, MD. Pp 2436-2662.
MILLER, M.E., LUTON, E., WENNER, B. Atomic Safety and Licensing Board Panel. 79/05/16. 226pp
- 7905290311 Comments on proposed Reg Guide 1.8 paragraph C.1 is contradictory; paragraph C.2 provides needed definition of equivalency & value/impact statement is unsatisfactory
DERMYER, M.D Affiliation Unknown 79/03/20. ap.
- 7905290424 Suggests subsurface explorations in bedrock & soils to reveal true stratigraphic & structural conditions prior to const. (Author's name & affiliation deleted).
* Affiliation Unknown. 89/05/07 2pp
- 7905290431 Notification of contract execution; Mod 2 to "Antitrust Hearings Consulting Svcs " Contractor: RM Beck.
MENCZER, M.B Technical Assistance Contracts Branch. FIN B-1119. AT(49-24)-026B. 79/04/30 1p.
- 7905290438 Mod 2, deobligating \$12,995.27 & closing out contract "Antitrust Hearings Consulting Svcs."
DOUGHERTY, D J Division of Contracts. FIN B-1119. AT(49-24)-026B. 79/04/30. 1p.
- 7905290435 Forwards memo of agreement between EPA Region II & NY State Siting Board on Electric Generation Siting & Environ. Memo delegates Siting Board authority to issue permits for major steam electric generating stations.
CIANCI, J.M. New York, State of, 79/05/22. 21pp.
- 7905290465 Responds to request for comments on Sunset bills, H R 2 & H R 65 Supports plan to promote govt efficiency by eliminating overlapping federal programs.
HENDRIE, J M Commission 79/03/16 5pp.
- 7905290478 Forwards H.R. 2 which would require budget authority & review of govt programs every 10 years, & H.R. 65 to improve Congressional oversight of federal programs Requests response by 790309
BULLINO, R House of Rep., Committee on Rules. 79/02/26 155pp
- 7905290491 "Dynamic Photoelastic Study of Crack Arrest," monthly progress rpt for Mar 1979
DALLY, J.W Maryland; Univ of NRC-04-76-172 79/04/02 3pp
- 7905290498 "Methods in Dosimetry for Nuclear Regulation," quarterly progress rpt for Oct-Dec 1978
BERNARD, B.R., CRIBBY, M., FORD, M.R. Oak Ridge National Laboratory FIN B-0410-8 ORNL/HABRD-22 79/01/04 4pp
- 7905290503 Requests proposed amend to regulations which would eliminate accumulated dose averaging formula mentioned in encl article, "Radiation Task Force Rept Feels Hazards May Be Greater than Previously Suspected"
ELLIDT, J C Tennessee Valley Authority. 79/04/03 3pp
- 7905290523 Requests info re cracking of BWR feedwater nozzle mockup & development of improved ultrasonic testing procedures Info will be used to resolve generic feedwater nozzle inservice issue
SNATDER, R P Systematic Evaluation Programs Branch 79/04/16. 1p
- 7905290573 Application by Air Products & Chemicals, Inc for license to export B 4 g of deuterium to England.
NOVAKOVICH, D Air Products & Chemicals, Inc. 79/04/24. 1pp.
- 7905290579 Application by Westinghouse for license to export compensated ionization chambers to France.
POUCHAL, W.F Westinghouse Electric Corp. 79/04/30. 1pp.
- 7905290589 Application by Air Products & Chemical, Inc for license to export 7 cu ft deuterium to United Kingdom
EBERT, R Air Products & Chemicals, Inc. 79/03/08. 1p.
- 7905290597 Notification of time change of 790501 meeting w/C-E in Bethesda, MD to discuss plant transient responses & Michelson rept
THADANI, A.C Reactor Systems Branch. 79/04/27. 1p.
- 7905290673 Progress rpt 18 for Mar 1979 on NRC-01-77-180 discussing irradiations, dosimeters, & finances
PLATO, P. Michigan; Univ. of. NRC-01-77-180. 79/03/30. 15pp.
- 7905300078 NUREG/CR-0682
"Quarterly Progress Rpt on Fission Product Behavior in LWRs from Oct to Dec 1978"
MALINAUSKAS, A.P Oak Ridge National Laboratory. FIN B-0127. ORNL/NUREG/TM-3 79/04/30. 20pp. Available at NTIS.
- 7905300082 Responds to 790424 ltr to HR Denton requesting that x-ray technician training at Passaic County NJ Community College be investigated.
YOUNG, F.W Assistant Director for Program Development. 79/05/11. 1p.
- 7905300088 Requests intervention in x-ray technician training at Passaic County NJ Community College. Forwards 760402 & 780117 ltrs from NJ EPA.
PICKETT, J.F. Affiliation Unknown. 79/04/24. 7pp.
- 7905300114 Comments on proposed Reg Guide "Guide for Preparation of Applications for Use of Gamma Irradiators;" severely harmful to small companies & too detailed Notes four new rules not in referenced documents.
STEIN, M.H. RBA Corp. 79/04/11 5pp.
- 7905300152 Notification of contract execution; "BDA to Develop Regulatory Framework for Nuclear Waste Mgt;" awarded to Kaman Sciences Corp.
LEBO, C.D. Technical Assistance Contracts Branch. NRC-02-77-201-43 79/04/24. 1p.
- 7905300161 Contract: "BDA to Develop Regulatory Framework for Nuclear Waste Mgt;" awarded to Kaman Sciences Corp.
DOUGHERTY, D.J. Division of Contracts. NRC-02-77-201-43. 79/04/24. 1p.

NONDOCKETED ITEMS

317

7905300178 Notification of contract execution. "Const of Nuclear & Fossil Fueled Power Plants," awarded to US Dept of Labor
CLAGOLA, A. F. Technical Assistance Contracts Branch FIN B-6540
NRC-03-79-125 79/04/20 1p.

--7905300186 Contract "Const of Nuclear & Fossil Fueled Power Plants" awarded to Dept of Labor
DOUGHERTY, D. J. Technical Assistance Contracts Branch FIN B-6540. NRC-03-79-125 79/04/18. 4pp

7905300180 "Reactor Operator Training Programs Utilizing Nuclear Power Plant Simulators"
COLLINS, P. F. Operator Licensing Branch. NB 16(4) VI B
79/03/23 20pp

7905300194 Notification of contract execution, Mod 2 to "Review of Proposed Pile Foundations for Bally Nuclear Generating Station." Contractor MT Davison
PERLMAN, J. Division of Contracts NRC-03-78-166 79/04/24 1p

--7905300200 Mod 2, adding miscellaneous expenses to contract to "Review of Proposed Pile Foundations for Bally Nuclear Generating Station"
HARRETT, D. J. Division of Contracts NRC-03-78-166 79/04/24 1p

7905300228 Notification of contract execution, Mod 2 to "Application of ILLAC IV TREB for Determining Seismic Environ at Nuclear Power Sites." Contractor NASA-Ames Research Ctr
CLAGOLA, A. F. Technical Assistance Contracts Branch FIN B-6494. NRC-03-78-162. 79/04/24 1p

--7905300237 Mod 2, deobligating \$49,961 00, to "Application of ILLAC IV TREB for Determining Seismic Environ at Nuclear Power Plant Sites"
DOUGHERTY, D. J. Division of Contracts FIN B-6494. NRC-03-78-162 79/04/24 2pp

7905300247 Notification of contract execution. "BGA to Develop Regulatory Framework for Nuclear Waste Mgt," awarded to FUORO, Inc
LEBO, C. D. Technical Assistance Contracts Branch. NRC-02-77-201-44 79/04/26. 1p

--7905300260 Contract: "BGA to Develop Regulatory Framework for Nuclear Waste Mgt," awarded to FUORO, Inc
DOUGHERTY, D. J. Division of Contracts. NRC-02-77-20-144 79/04/26 1p

7905300269 Notification of contract execution: "Economic Consulting Bvc in Connection w/FL Power & Light Co's Application for License to Const St Lucie, Unit 2, Nuclear Power Plant," awarded to J Kuhlman.
CLAGOLA, A. F. Technical Assistance Contracts Branch. FIN B-6503-9 NRC-03-79-147 79/04/24. 1p.

--7905300280 Contract. "Economic Consulting Bvc in Connection w/FL Power & Light Co's Application for License to Const St Lucie, Unit 2, Nuclear Power Plant," awarded to J Kuhlman.
DOUGHERTY, D. J. Division of Contracts. FIN B-6503-9. NRC-03-79-147 79/04/24. 4pp

7905300278 "Licensing & Certification of Personnel at Nuclear Power Plants"
* Office of Nuclear Reactor Regulation. 79/05/22 12pp

7905300282 "NRC Examination Results for Nuclear Power Plant Personnel" App A: 1971-74.
* Commission 74/12/31. 14pp.

7905300285 IAEA-BK-178/34
"Reactor Operator Training Programs Utilizing Nuclear Power Plant Simulators."
COLLINS, P. F. Atomic Energy Commission, Directorate of Licensing (Pre-1975). 74/12/31 26pp.

7905300289 "License Examination Results Update, 1975-1978."
MOLMAN, J. J. Operator Licensing Branch. 78/12/31. 27pp.

7905300290 Notification of contract execution, Mod 1 to "Electric Engineering Contractual Assistance for South TX Antitrust Proceeding." Contractor RW Beck & Associates.
CLAGOLA, A. F. Technical Assistance Contracts Branch. NRC-03-79-129. 79/04/24. 1p.

--7905300297 Mod 1, extending period of performance to 790630 and changing principal engineer to "Electric Engineering Contractual Assistance for South TX Antitrust Proceedings."
DOUGHERTY, D. J. Division of Contracts. NRC-03-79-129. 79/04/24 2pp.

7905300295 NUREG-0560
"Staff Rpt on Generic Assessment of Feedwater Transients in PHRs Designed by B&W"
* Office of Nuclear Reactor Regulation. 79/05/25 380pp. Available at NTIS

7905300303 Notification of contract execution, Mod 2 to "Safeguards for High Level Waste Repositories." Contractor Science Applications
MENCZER, W. B. Technical Assistance Contracts Branch FIN B-6376-9 NRC-02-79-035. 79/04/24 1p

--7905300308 Mod 2, changing key personnel to "Safeguard for High Level Waste Repositories"
DOUGHERTY, D. J. Division of Contracts FIN B-6376-9 NRC-02-74-035 79/04/24. 1p

7905300317 Responds to DO Eisenhut 781023 ltr. Submits info re axially varying R-factors in order to broaden scope of NRC approval of NEDE-24011-P-A. "Generic Reload Fuel Application." W/o encl.
ENDEL, R. E. General Electric Co, Nuclear Energy Products Div MC 682 79/05/15 5pp.

7905300321 Forwards application for export license
MOWRY, W. R. General Atomic Co (subs of Gulf Oil Corp.). IEL-1053 79/04/26 1p

--7905300326 Application by General Atomic Co for license to export: multirange picometer, linear power channel, wide range log power channel, flux controller & bistable trip module to Egypt
MOWRY, W. R. General Atomic Co. (subs of Gulf Oil Corp.). 79/04/26 1p

7905300332 Forwards application for export license.
HOADLEY, B. D. Monsanto Co. 79/04/25 1p

--7905300339 Application by Monsanto Research Corp for license to export 0.33 g Pu 80% enriched in Pu-238 sealed neutron source encapsulated to Turkey.
HOADLEY, B. D. Monsanto Co 79/04/25 1p.

7905300342 Forwards minutes of Risk Assessment Review Group 780829-31 meeting
AUSTIN, J. H. Office of Policy Evaluations. 79/02/27 1p.

--7905300350 Summary of 780829-31 Risk Assessment Review Group meeting in Washington, DC FR notice, attendance list & list of available documents encl
* Office of Policy Evaluations 79/02/27 5pp.

--7905300355 Responds to 780804 FR notice requesting comments re agenda for meeting of Risk Assessment Review Group. Sabotage & evacuation issues should be reexamined.
GARRETT, E. O. Affiliation Unknown 78/08/13. 1p.

7905300356 Submits preliminary info re natural circulation cooling at TMI-2
LAFLEUR, J. D. Office of International Programs 79/04/28 2pp

7905300359 Submits preliminary info which is subj to confirmation of regulatory action re B&W plants.
LAFLEUR, J. D. Office of International Programs 79/04/27. 2pp

7905300365 Forwards IE Bulletin 79-058 re procedures & training for establishing & maintaining natural circulation & reactor vessels integrity at B&W plants. W/o encl.
LAFLEUR, J. D. Office of International Programs. 79/04/23 1p.

7905300368 Forwards responses to NRC questions re heat transfer & flow distribution aspects of revised flow blockage model. Requests approval of model for future licensing submittals.
SCHERER, A. E. C-E Power Systems. LD-79-030. 79/05/23. 14pp.

7905300369 Forwards IE Bulletin 79-06, 79-06A, 79-06B & 79-08 addressing aspects of TMI incident which apply to Westinghouse or C-E reactors. W/o encl.
LAFLEUR, J. D. Office of International Programs. 79/04/18. 1p.

7905300370 Submits preliminary info on TMI incident. Further actions should be considered for all LWRs, since pressure level indication problem may be generic in nature
LAFLEUR, J. D. Office of International Programs. 79/04/11. 2pp.

7905300374 Comments on training, examination & licensing program for plant operators. Program has serious flaws & needs prompt attention
MEDEIROB, M. B. Reactor Systems Standards Branch. 79/04/20. 7pp.

NONDOCKETED ITEMS

7905300379 Responds to FOIA 790413 & 0426 requests for transcripts of closed NRC meetings re TMI incident Describes process involved in obtaining info List of closed Commission meetings re TMI incident encl
FELTON, J. M. Division of Rules and Records. 79/05/23 6pp.

7905300383 FOIA request for transcripts of NRC meetings, public statements & internal memos re TMI incident.
ETHEREDGE, L. Massachusetts Institute of Technology 79/04/15 1p

7905300385 FOIA request for tapes of NRC meetings re TMI incident
ETHEREDGE, L. Massachusetts Institute of Technology 79/04/26 1p

7905300389 Responds to FOIA 790428 request & forwards WASH-1400 & WASH-740, Lewis rept & NRC 790118 policy statement
FELTON, J. M. Division of Rules and Records. 79/05/15 1p

--7905300394 FOIA request for Rasmussen rept (WASH-1400)
MAY, H. Affiliation Unknown 79/04/28 1p

7905300400 Forwards charter of Task Group on Generic Review of Feedwater Transients in B&W Designed Reactors.
GABE, E. O. Office of Nuclear Reactor Regulation. 79/04/02 2pp

7905300414 Notification of contract execution, Mod 3 to "Mooring Bys for Floating Nuclear Power Plants." Contractor, US Naval Facilities Engineering Command.
HENGZER, W. B. Technical Assistance Contracts Branch FIN B-5304 AT(49-24)-0112. 79/04/24. 1p.

--7905300423 Mod 3, decreasing funds by \$10,209,48, to "Mooring Bys for Floating Nuclear Power Plants."
BOUQUERTY, D. J. Division of Contracts FIN B-5304 AT(49-24)-0112 79/04/24 1p

7905300449 Comments on NURE0-0531, insufficient justification for reclassifying recirculation-riser piping to nonconforming svc-sensitive category
UTLEY, E. E. Carolina Power & Light Co. OD-79-1338 79/05/21 1p

7905300460 Forwards signed executive personnel delegation performance agreement in response to 790410 memo.
HENDRIE, J. M. Commission. 79/04/20. 2pp.

7905300464 Extends gratitude for 790419 ltr re recommendations for improving regulatory process
HENDRIE, J. M. Commission 79/05/01 1p

--7905300467 Forwards copy of ltr to President Carter & 790417 ltr to New York Times re recommendations for improving regulatory process
SMITH, H. E. Meteorological Evaluation Services, Inc. 79/04/19 7pp.

7905300481 Responds to 790430 & 790504 request for meeting transcripts Explains status of classified & unclassified portions of transcripts, some of which will be made available following classification review
CHILK, S. J. Office of the Secretary of the Commission. 79/05/14. 1p

--7905300487 Requests disclosure of transcripts of listed NRC meetings re export of nuclear reactors & matls Cites applicable portions of Sunshine Act
JACOBBS, T. J. Project for Open Government. 79/04/30. 3pp.

ins NRC export licensing authority over zirconium which designed or prepared" for nuclear facility
obtained generic retransfer assurances
leading partners
79/05/11. 2pp

requirement for licensing export of Zr in concerns of constituent that

79/04/02 1p

oments on freedom of eply.

of comment on first amend
ns that comment
ing rise to

--7905300531 Requests explanation of meaning of statement made re opposition to first amend made at 790331 press conference on TMI
FREIDHEIM, J. W. American Newspaper Publishers Association 79/04/17 1p

7905300532 Forwards "Evaluation of Effects of Corrosion Particles on Control Rod Drive Operation" Rept will assist in evaluation of GE proposal to delete control rod drive return line
SHERWOOD, G. G. General Electric Co., Nuclear Energy Products Div. MFN-146-79 79/05/22 1p

--7905300538 "Evaluation of Effects of Corrosion Particles on Control Rod Drive Operation
* General Electric Co., Nuclear Energy Products Div 79/05/22 9pp

7905300558 Forwards rept, "Technical Description of Ring Vortex Model, Mar 1978"
SDEGN, L. J. General Electric Co., Nuclear Energy Products Div MFN-144-79 79/05/22 1p.

--7905300561 "Technical Description of Ring Vortex Model, Mar 1978"
CHU, C. M. General Electric Co., Nuclear Energy Products Div LEE, T. Y. General Electric Co. 78/03/31 32pp

7905300562 Discusses markup of Senate Bill B.562, NRC authorization for FY80, which omitted three of four NRC proposals Requests meeting to discuss how best to proceed
HENDRIE, J. M. Commission. 79/05/09 2pp

7905300563 Apologizes for use of term "blind men" in derogatory manner & describes it as "slip of tongue"
HENDRIE, J. M. Commission 79/04/26 1p.

--7905300571 Protests ref to "blind men stumbling around making decisions" & requests more care be taken w/comments in future.
SHED, J. P. Affiliation Unknown. 79/04/18. 1p.

7905300568 Forwards summary of info which led to order to shut down five nuclear plants on 790313. Reviews NRC actions taken to expedite return to operation
HENDRIE, J. M. Commission. 79/05/02. 7pp.

--7905300572 Forwards prompt examination of independent evaluation which concludes that piping supports comply w/NRC stds. Critical energy situation exists in ME. Urges immediate return of plant to full operation
BRENNAN, J. E. Maine, State of. 79/03/23 1p

7905300577 Extends gratitude for 790416 ltr & offer of assistance Requests to be informed of new developments re Energy Ctr concept. Will forward resume to other Commissioners
HENDRIE, J. M. Commission 79/05/01. 1p.

--7905300587 Offers personal svc to nuclear industry in areas of equipment design & design philosophy maint, operational control & organization Suggests US adopt Energy Generation Ctr programs
DICKEMAN, R. L. Affiliation Unknown. 79/04/16 6pp.

7905300596 Responds to President 790410 memo requiring 5X reduction in agency energy use. Supports reduction effort. NRC employee announcement encl.
HENDRIE, J. M. Commission. 79/04/27. 1p

--7905300606 Requests conservation efforts to decrease consumption by 5X & details specific actions to achieve goals. White House memo to agency & dept heads encl.
HENDRIE, J. M. Commission 79/04/27 3pp

7905300613 Ack receipt of 790321 ltr re fire protection. NRC will consider comments in its response to group 780502 petition.
CHILK, S. J. Office of the Secretary of the Commission 79/05/03 1p.

--7905300619 Asserts relative risk of serious reactor accidents from electrical cable fires is higher than risk from earthquakes. Cites AEC concerns re problem. Requests action be taken
FORD, D. F. Union of Concerned Scientists. 79/03/21. 2pp

--7905300632 Summary rept of 730119 meeting of ad-hoc working group in Washington, DC re fire protection
* ACRS - Advisory Committee on Reactor Safeguards. 73/01/19 5pp.

NONDOCKETED ITEMS

319

7905300648 Weekly info rept for week ending 790413
REIM, T. A. Office of the Executive Director for Operations
79/04/18 30pp

7905300652 Explains misunderstanding arising from lack of details in
790316 weekly info rept re PIPESTRESS code error. Responds to
790322 ltr. Related FR notice encl.
HENDRIE, J. M. Commission 79/05/11 3pp

--7905300657 Discusses differing impressions created by NRC testimony &
790316 weekly info rept re PIPESTRESS code error or
"unconservative" calculational technique.
UDALL, M. H. House of Rep 79/03/22. 2pp.

7905300672 Responds to 790215 ltr re proposed interim export of reactor
components to Philippines under License XCOM-0013 Case under
review Ruling on petition to consolidate application w/
XR-120 to be issued before final decision.
HENDRIE, J. M. Commission 79/05/02. 1p.

--7905300677 Advises final Executive Branch recommendation on reactor
export license application for Philippines plant is pending.
Urges issuance of XCOM-0013 to avoid reactor const delays
PICKERING, T. R. State, Dept. of, Bureau of Oceans & Internatl.
Environ & Scientific Affairs. 79/02/15 2pp.

7905300718 Discusses support needed to implement Reg Guide 1.97,
"Instrumentation of LWR Plants to Assess Plant Conditions
During & Following Accident"
LAINAB, O. Plant Systems Branch. 79/04/10. 2pp.

7905300723 Concurs w/RO 1 140, Revision 1, "Design, Testing & Maint
Criteria for Normal Ventilation Exhaust Sys Air Filtration &
Adsorption Units of Light-Water Cooled Nuclear Power
Plants"
CARBON, M. H. ACRS - Advisory Committee on Reactor Safeguards.
79/04/10. 1p

7905300727 Certifies that 0041 g U-235 will be subj to all terms &
conditions of 600725 addl agreement for cooperation & that
EHEB N. V. of Belgium is authorized consignee
GOPPEL, M. European Communities, Commission of. 79/05/07 1p.

7905310015 "Steam Generator Tube Integrity Program," progress rept for
Mar 1977.
CLARK, R. A. Battelle Memorial Institute, Pacific Northwest
Laboratory. FIN B-2077 79/04/11. 5pp

7905310067 Responds to 790404 ltr. Forwards list of documents placed in
PDR w/o encl.
FELTON, J. H. Division of Rules and Records 79/05/23 1p

7905310069 Forwards application by TX Nuclear Div for license to export
1.76 mg Pu-238 to Holland
HENDRICK, W. Q. Ramsey Engineering Co 79/04/25 1p

--7905310074 Application by TX Nuclear Div for license to export 1.76 mg
Pu-238 to Holland
HENDRICK, W. Q. Ramsey Engineering Co 79/04/25 1p

7905310321 Forwards magnetic tape of time histories used to generate
cumulative damage function curves for NMSB applications
presented in NEDE 24010-P Index of contents, info on
formatting & example printouts of time history encl
SOBON, L. J. General Electric Co., Nuclear Energy Products Div
MFN-150-79 79/05/29. 7pp

7905310339 Requests proprietary computer program PIBYS & NEDE-24077,
"PIBYS Users Manual" dtd Mar 1978, be withheld
(ref 10CFR2 790) Affidavit encl
SHERWOOD, G. O. General Electric Co., Nuclear Energy Products Div
MFN-143-79 79/05/22. 5pp

7905310343 Clarifies commitment contained in JH Taylor 790428 ltr re
schedule for developing auxiliary feedwater control sys
independent of integrated control sys
TAYLOR, J. H. Babcock & Wilcox Co 79/05/22 2pp

7905310377 Forwards Suppl 3 to Vol 1, Section 6 of "Evaluation of
Transient Behavior of Small RCS Breaks in 177 Fuel Assembly
Plant" dtd 790524.
TAYLOR, J. H. Babcock & Wilcox Co 79/05/24. 1p

--7905310386 Suppl 3 to Vol 1, Section 6 of "Evaluation of Transient
Behavior of Small RCS Breaks in 177 Fuel Assembly Plant"
* Babcock & Wilcox Co. 79/05/24 5pp

7905310406 Forwards affidavit supporting request for proprietary
classification of BAW-46B9, "Pressurizer Ref Leg
Effervescence Test," dtd 770301.
TAYLOR, J. H. Babcock & Wilcox Co 79/05/18 8pp

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
AAROE, W. H.	7905040265			ASHER, T. R.	7905240068		
AAROE, W. H.	7905290038			ASWELL, D. L.	7905110260	50-382	
ABBOTT, J.	7905080036			ASWELL, D. L.	7905150264	50-382	
ABBOTT, J.	7905080040	50-22		ASWELL, D. L.	7905150408	50-382	
ABBOTT, J.	7905080047			ASWELL, D. L.	7905170228	50-382	
ABRAHAM, K.	7904210770			ASWELL, D. L.	7905170231	50-382	
ABRAHAM, K.	7905150287	50-363		AUSTIN, H. A.	7905150137	70-364	
ABRAHAM, K.	7905150298	50-363		AUSTIN, H. A.	7905240594	70-135	
ABRAHAM, K.	7905070220	50-320		AUSTIN, H. A.	7905240763	70-135	
ADAMS, W. E.	7905150414	50-255		AUSTIN, H. A.	7905250048	70-135	
ADRAGNA, J. M.	7905070222			AUSTIN, H. A.	7905220077	70-135	
AGRAWAL, A. K.	7905240427		7905240427	AUSTIN, H. A.	7905070060	70-135	
AHEARNE, J. F.	7905230494			AUSTIN, H. A.	7905240089	70-364	
AHEARNE, J. F.	7905160097	50-320		AUSTIN, J. H.	7905300342		
AHEARNE, J. F.	7905160177	50-320		AUTIO, H. A.	7905110317	50-29	
AHEARNE, J. F.	7905160056	50-320		AUTIO, H. A.	7905150422	50-29	
AHEARNE, J. F.	7905160084	50-320		AUTIO, H. A.	7905150433	50-29	
AHEARNE, J. F.	7905160169	50-320		AUTIO, H. A.	7905170126	50-29	
AHEARNE, J. F.	7905020024			AXELRAD, M.	7905030158	50-344	
AHEARNE, J. F.	7905160073	50-320		AXELRAD, M.	7905150722	50-344	
AHEARNE, J. F.	7905160259	50-320		AXELRAD, M.	7905240939	50-376	
AHEARNE, J. F.	7905160137	50-320		AXELRAD, M.	7905240970	50-376	
AHEARNE, J. F.	7905160140	50-320		AXELRAD, J. A.	7905150267	50-348	
AHEARNE, J. F.	7905020046			AXELSON, M. L.	7905230442	70-1308	
AHEARNE, J. F.	7905160114	50-320		AYCOCK, H.	7905150338	50-320	
AHEARNE, J. F.	7905160119	50-320		BACKUS, R. A.	7905150323	50-443	
AHEARNE, J. F.	7905160088	50-320		BACKUS, R. A.	7905010329	50-443	
AHEARNE, J. F.	7905160147	50-320		BACKUS, R. A.	7905020422	50-443	
AHEARNE, J. F.	7905030055			BACKUS, R. A.	7905080398	50-443	
AHEARNE, J. F.	7905290003			BACON, J. L.	7905090307	50-329	
AIN, F. P.	7905240168	50-574		BAER, R. L.	7905240977		
ALDEN, W. H.	7905140344	50-277		BAER, R. L.	7905250050		
ALDEN, W. H.	7905170241	50-277		BAER, R. L.	7905240936	50-580	
ALEXANDER, R. E.	7905150702			BAER, R. L.	7905150112	50-382	
ALLAN, J. H.	7905210036	50-320		BAIETTI, A. L.	7905150614		
ALLAN, J. H.	7905210039	50-320		BAILEY, F. O.	7905150689	71-311	
ALLEN, O. J.	7905250491			BAILEY, F. O.	7905150693		
ALLEN, J.	7905300063	50-320		BAIR, O. O.	7905110169	50-344	
ALLISON, C. M.	7905080109		TFBP-TR-209	BAIRD, G. L.	7905210184		
ALVAREZ, B.	7905240199	50-280		BAIRD, J. B.	7905040366	50-344	
AMBLER, E.	7905240354	50-184		BAJRA, B. G.	7905240459	50-400	
AMLAUER, K.	7905240116			BAKER, J. R.	7905250304	40-8452	
AMLAUER, K.	7905250306			BAKER, C. E.	7905300132	40-8681	
ANDERSON, L.	7905140029	50-320		BAKER, C. E.	7905240544	40-8681	
ANDERSON, G. H.	7905240348	71-9033		BAKER, K. R.	7905020208	50-315	
ANDERSON, G. R.	7905130785			BALDWIN, H. A.	7905230032	50-275	
ANDERSON, B.	7905130314			BALDWIN, H. N.	7905070304		
ANDERSON, T. M.	7905310418	50-482		BALL, R.	7905220453	50-320	
ANDERSON, T. M.	7905110098		HCAP-9402 (NP)	BALLARD, R. L.	7905090141	50-302	
ANDERSON, T. M.	7905140449			BALLARD, R. L.	7905150043	50-477	
ANDERSON, T. M.	7905110096			BALLARD, R. L.	7905150128	50-376	
ANDERSON, T. H.	7905090327			BALLARD, R. L.	7905150132	50-376	
ANDERSON, T. H.	7905070366			BALLARD, R. L.	7905150124	50-463	
ANDERSON, T. H.	7905210146			BALLARD, R. L.	7905150296	50-546	
ANDERSON, T. H.	7905190063			BALLARD, R. L.	7905230855	50-382	
ANDERSON, T. H.	7905220422			BALLARD, R. L.	7905240914	50-599	
ANDERSON, T. H.	7905230393	50-320		BALLARD, R. L.	7905240919	50-599	
ANDERSON, T. H.	7905300905	40-8722		BALLARD, R. L.	7905240926	50-599	
ANDERSON, L. F.	7905100243		7905100243	BALLARD, R. L.	7905240966	50-599	
ANDERSON, D. R.	7905240330	50-255		BALLARD, R. L.	7905090296	50-546	
ANDERSON, D. C.	7905100366			BALOUGH, R. C.	7905230793	50-443	
ANDERSON, D. C.	7905040316	50-322		BALTZAR, R. Z.	7905080536	50-329	
ANDONINI, G. C.	7905010842	50-293		BANCROFT, H. H.	7905140072	50-320	
ANDONINI, G. C.	7905080501	50-293		BANKS, H. R.	7905230604	50-261	
ANDONINI, G. C.	7905170235	50-293		BANKS, H. R.	7905190010	50-261	
ANDONINI, G. C.	7905170230	50-293		BANKS, H. R.	7905190086	50-261	
ANDONINI, G. C.	7905310392	50-293		BANKS, H. R.	7905220106	50-261	
ANDREWS, J. C.	7905040274			BANKS, H. R.	7905230618	50-324	
ANDREWS, R. D.	7905100223	40-8452		BANKS, H. R.	7905220342	50-323	
ANDREWS, R. D.	7905100233	40-8452		BANKS, H. R.	7905220361	50-323	
ANDREWS, R. D.	7905240282	40-8452		BANKS, H. R.	7905220367	50-323	
ANDREWS, H.	7905240223	50-367		BANKS, H. R.	7905220406	50-324	
ANDREWS, H.	7905230492	50-275		BANKS, H. R.	7905230413	50-325	
ANDREWS, R. L.	7905070541	50-238		BANKS, H. R.	7905240219	50-261	
ANDREWS, R. L.	7905210236	50-285		BANKS, H. R.	7905300384	50-324	
ANDREWS, R. L.	7905210268	50-285		BANKS, H. R.	7905300425	50-325	
ANDREWS, R. L.	7905220300	50-285		BANKS, H. R.	7905300371	50-324	
ANDREWS, R. L.	7905300848	50-285		BANKS, H. R.	7905300375	50-324	
ANDRUS, H.	7905230733	50-466		BANKS, H. R.	7905300387	50-324	
ANG, H. P.	7905020117	50-391		BANKS, H. R.	7905300512	50-325	
ANG, H. P.	7905010243	50-389		BARD, S. T.	7905040207		
ANGELO, J.	7905240359	50-390		BARDEG, C. R.	7905110090	50-280	
ARLOTTO, G. A.	7905090228	50-320		BARHAM, C. D.	7905170233	50-261	
ARMSTRONG, W. H.	7905030233			BARI, R. A.	7905240529	7905240529	
ARMSTRONG, W. H.	7905100142			BARKER, R. F.	7905150582		
ARNOLD, R. C.	7905230117	50-320		BARNARD, J.	7905290091		
ARNOLD, R. C.	7905230110	50-320		BARNES, R. D.	7905080568	50-397	
ARNOLD, R. C.	7905230082	50-320		BARNETT, E. W.	7905310020	50-445	
ARNOLD, R. C.	7905190113	50-320		BARNETT, E. W.	7905310190	50-445	
ARNOLD, R. C.	7905190111	50-320		BARNETT, E. W.	7905230651	50-445	
ARNOLD, R. C.	7905190093	50-320		BARNETT, E. W.	7905230624	50-445	
ARNOLD, R. C.	7905190120	50-320		BARNES, J. D.	7905040506	50-387	
ARNOLD, R. C.	7905190187	50-320		BARNES, I.	7905150561	50-445	
ARNOLD, R. C.	7905190089	50-320		BARRETT, P. A.	7905030074	50-373	
ARNOLD, R. C.	7905230013	50-320		BARRETT, P. A.	7905150419	50-341	
ARNOLD, R. C.	7905140025	50-320		BARRETT, L.	7905300255	50-320	
ARNOLD, R. C.	7905230005	50-320		BARRETT, L. H.	7904260292	50-320	
ARNOLD, R. C.	7905230024	50-320		BARRONS, H. L.	7905090441	40-8498	
ARNOLD, R. C.	7905100420	50-289		BARRONS, H. L.	7905090345	50-592	
ARNOLD, R. C.	7905110333	50-320		BARTI, C. A.	7905250368	50-400	
ARNOLD, R. C.	7905110165	50-320		BARTI, C. A.	7905240144	50-255	
ARNOLD, R. C.	7905110170			BARTI, C. A.	7905080379	50-388	
ARNOLD, R. C.	7905110176	50-320		BARTI, C. A.	7905300036	50-488	
ARNOLD, R. C.	7905110178	50-289		BARTI, C. A.	7905300091	50-358	
ASHER, T. R.	7905150153			BARTI, C. A.	7905230829	50-400	

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
BARTH, C. A.	7905020334	50-358		BERNERO, R.	7905160220	50-320	
BARTH, C. A.	7905220075	50-358		BERNERO, R. M.	7905230411		
BARTH, C. A.	7905250093	50-400		BESAW, W. J.	7905300149	50-320	
BARTH, C. A.	7905020147	50-448		BESKID, N.	7905170292	40-1162	
BARTH, C. A.	7905070216	50-400		BESSETTE, D. E.	7905140011	50-320	
BARTH, C. A.	7905070225	50-580		BETH, R. M.	7905240387	50-141	
BARTH, C. A.	7905080341	50-358		BETTENHAUSEN, L.	7905300752	50-311	
BARTH, C. A.	7905080359	50-491		BEUTLER, P. S.	7905100165		NUREG/CR-0443
BARTH, C. A.	7905080377	50-580		BEVER, B.	7905100345	50-346	
BARTH, C. A.	7905070147	50-491		BICKEL, J. H.	7905140048	50-320	
BARTH, C. A.	7905150685	50-580		BICKWIT, L.	7905140178	50-320	
BARTH, C. A.	7905220443	50-400		BICKWIT, L.	7905100030	50-320	
BARTH, C. A.	7905240635	50-488		BICKWIT, L.	7905090256	50-320	
BARTH, C. A.	7905240703	50-400		BICKWIT, L.	7905140163	50-320	
BARTH, C. A.	7905240738	50-491		BICKWIT, L.	7905140166	50-320	
BARTH, C. A.	7905290195	50-491		BICKWIT, L.	7905140188	50-320	
BARTH, C. A.	7905030079	50-448		BICKWIT, L.	7905090250	50-320	
BARTH, C. A.	7905030132	50-400		BICKWIT, L.	7905300319	50-320	
BARTH, C. A.	7905250099	50-488		BIDEN, J. R.	7905240512	50-490	
BARTH, C. A.	7905110046	50-253		BIELAWSKI, A. P.	7905160504	50-556	
BARTH, C. A.	7905240506	50-358		BIELAWSKI, A. P.	7905090185	50-556	
BARTH, C. A.	7905300140	50-253		BIELAWSKI, A. P.	7905300022	50-295	
BARTON, A. R.	7905190357	50-348		BIEN, F. N.	7905250371	50-315	
BARTO, H. C.	7905160424	50-387		BILLIO, J.	7905220065	50-290	
BASKIN, K. P.	7905160319	50-206		BILLINGTON, G.	7905230744	50-466	
BASKIN, K. P.	7905240395	50-206		BIRD, P. E.	7905300518	50-320	
BASKIN, K. P.	7905210160	50-361		BIRKEL, R. A.	7905240108	50-437	
BASTO, S.	7905220065	50-250		BIRKEL, R. A.	7905150759	50-599	
BATES, A.	7905140031	50-320		BISCHOFF, C. A.	7905100002	50-592	
BATES, A.	7905140034	50-320		BISHOP, H. Q.	7905030247	50-549	
BATES, J. W.	7905020161	70-1151		BIVENS, T.	7905150524		
BATTIST, L.	7905160129	50-320		BIXBY, W. W.	7905110287	50-320	
BATTIST, L.	7905160202	50-320		BIXBY, W. W.	7905300054	50-320	
BATTIST, L.	7905190107	50-320		BIXEL, D. A.	7905040099	50-155	
BATTIST, L.	7905300300	50-320	NUREG-0358	BIXEL, D. A.	7905080480	50-155	
BAUER, E. Q.	7905030352	50-277		BIXEL, D. A.	7905290278	50-155	
BAUM, E. A.	7905090435			BIXEL, D. A.	7905150457	50-155	
BAUNACK, W. H.	7905070182	50-286		BIXEL, D. A.	7905250095	50-155	
BAUNACK, W. H.	7905290166	50-336		BIXEL, D. A.	7905310449	50-155	
BAUBER, M. A.	7905300035	50-230		BLACK, B.	7905250514		
BAUBER, M. A.	7905150793	50-230		BLACK, R. L.	7905250128	50-322	
BAUBER, M. A.	7905150799	50-230		BLAKE, E. L.	7905090247	50-320	
BAUBER, M. A.	7905240207	50-389		BLAKE, E. L.	7905100133	50-484	
BAXLEY, B. X.	7905080524	50-321		BLAKE, J. J.	7905240665	50-324	
BAXLEY, S. X.	7905070646	50-366		BLANSETT, V.	7905310401	50-123	
BAXLEY, S. X.	7905300660	50-321		BLAU, J.	7905290106	50-516	
BAXTER, R. C.	7905230782	50-332		BLAUVELT, R. K.	7905220105	71-9506	
BAYNARD, P. Y.	7905300668	71-6698		BLOND, R.	7905160131	50-320	
BAYNE, J. P.	7905070168	50-286		BLOTCKY, A. J.	7905140192	50-131	
BAYNE, J. P.	7905030181	50-286		BLOTCKY, A. J.	7905140198	50-131	
BAYNE, J. P.	7905250172	50-286		BLOTCKY, A. J.	7905090197		
BAYNE, J. P.	7905250241	50-286		BLUMBERG, N. J.	7905070182	50-286	
BAYNE, J. P.	7905010516	50-286		BLUMBERG, N.	7905070138	50-272	
BAYNE, J. P.	7905090301	50-286		BLUME, M. B.	7905100273	50-445	
BAYNE, J. P.	7905150302	50-286		BLUME, M. B.	7905100106	50-445	
BAYNE, J. P.	7905230351	50-286		BLUME, M. B.	7905230466	50-445	
BEAN, R. H.	7905100243		7905100243	BODTKE, P. J.	7905150416	50-255	
BEATON, R. H.	7905190154	50-73		BODENERT, P.	7905140154	50-320	
BECHHOEFER, C.	7905100381	50-255		BODDEN, O.	7905300147	40-1162	
BECHHOEFER, C.	7905300690	50-358		BODDEN, O.	7905240437	40-1162	
BECHHOEFER, C.	7905250208	50-385		BODDEN, O.	7905240442	40-1162	
BECHHOEFER, C.	7905290036	50-358		BOHANNON, J. R.	7905310432	50-8	
BECHHOEFER, C.	7905130284	50-358		BOHN, R. J.	7905010534	50-367	
BECHHOEFER, C.	7905240330	50-255		BOHN, R. J.	7905140308	50-367	
BECKMAN, D. A.	7905290173	50-244		BOHN, R. J.	7905110306	50-367	
BECKMAN, D. A.	7905290157	50-334		BOHN, R. J.	7905220207	50-367	
BECKNER, W. D.	7905110363	50-320		BOHN, R. J.	7905300329	50-367	
BECKNER, W. D.	7905110328	50-320		BOLLINO, R.	7905290478		
BECKURTS, K. H.	7905140260	50-320		BOND, O. R.	7905220368	50-219	
BEHLING, S.	7905230486	50-320		BOND, O. R.	7905210270	50-219	
BEILMAN, T. P.	7905070613	50-315		BONNER, J.	7905110412		
BEILMAN, T. P.	7905150441	50-315		BOOK, H. E.	7905020513	50-142	
BEILMAN, T. P.	7905220326	50-315		BOOK, H. E.	7905020520	50-142	
BEILMAN, T. P.	7905220333	50-315		BOOK, H. E.	7905150686	70-1257	
BEILMAN, T. P.	7905220339	50-315		BOOK, H. E.	7905150701	70-1257	
BELANGER, J. L.	7905150775	50-295		BOOK, H. E.	7905230656	50-323	
BEISCHER, T.	7905100353	50-386		BOOK, H. E.	7905230664	50-323	
BELEN, O. L.	7905010567	50-290		BOOK, H. E.	7905040362	50-344	
BELL, H.	7905250260	50-344		BOOK, H. E.	7905040366	50-344	
BELL, J. M.	7905110160	50-320		BORDENICK, B. M.	7905110418	50-320	
BELL, J. M.	7905110156	50-320		BORDENICK, B. M.	7905240278	50-516	
BELL, M. J.	7905140035	50-320		BORER, P. S.	7905150526	50-298	
BELL, M. J.	7905160036	50-320		BORIS, R.	7905190057	50-320	
BELLOTTI, F. X.	7905100326	50-471		BORGHANN, E. A.	7905100210	50-358	
BELLOTTI, F. X.	7905090411	50-471		BORGHANN, E. A.	7905100222	50-358	
BENARDYA, V.	7905190203	50-320		BORGHANN, E. A.	7905140083	50-358	
BENDER, M.	7905140021	50-320		BORGHANN, E. A.	7905140111	50-358	
BENDER, M.	7905240205			BORGHANN, E. A.	7905020451	50-358	
BENEFIELD, W. E.	7905240206	71-317		BORGHANN, E. A.	7905290149	50-358	
BENEFIELD, W. E.	7905240210	71-317		BORGHANN, E. A.	7905080439	50-358	
BENJAMIN, A. S.	7905140149		NUREG/CR-0419	BORGHANN, E. A.	7905110148	50-358	
BENNEDEN, M. B.	7905010618	40-8698		BORGHANN, E. A.	7905160424	50-358	
BENNETT, C.	7905150626	71-312		BORIS, H. R.	7905150484	50-155	
BENNETT, C.	7905150632	71-312		BORIS, H. R.	7905250303	50-155	
BENNETT, D. E.	7905140032	50-320		BORCHOFF, I. D.	7905070166	50-382	
BENNETT, G. L.	7904190311			BOBKEY, B.	7905100194	50-346	
BENNETT, G. L.	7905110330	50-320		BOBKEY, B.	7905150665	70-1821	
BERECHER, J.	7905240667	50-488		BOTT, T. F.	7905300438	50-320	ORNL/TH-6853
BERGER, D. W.	7905230019	50-320		BOUKNIGHT, J. A.	7905180190	50-445	
BERGER, M. G.	7905300058	50-445		BOUKNIGHT, J. A.	7905230651	50-445	
BERGER, M. G.	7905100288	50-445		BOUKNIGHT, J. A.	7905230664	50-445	
BERGGREN, J.	7905230729	50-466		BOUKNIGHT, J. A.	7905240853	50-389	
BERGLAND, S.	7905090090	50-522		BOURNIA, A.	7905290052	50-373	
BERICK, D.	7905240199	50-280		BOWDEN, T. J.	7905180391	50-548	
BERRY, J. A.	7905240968	50-313		BOWERS, C. E.	7905250236	70-820	
BERNARD, S. R.	7905290498		7905290498	BOWERS, C. E.	7905240066	70-820	

PERSONAL AUTHOR INDEX

323

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
SCHEER, E. S.	7905240479	50-250		BROWN, S. C.	7905110297	50-404	
SCHEER, E. S.	7905290114	50-275		BROWN, S. C.	7905160418	50-339	
SCHEER, E. S.	7905230893	50-443		BROWN, S. C.	7905220111	50-404	
SCHEER, E. S.	7905220053	50-443		BROWN, S. C.	7905220344	50-339	
SCHEER, E. S.	7905140567	50-250		BROWN, S. C.	7905230022	50-338	
SCHEER, E. S.	7905270489	50-250		BROWN, S. C.	7905290375	50-338	
SCHEER, H. K.	7905250499			BROWN, S. C.	7905290404	50-339	
SCHEER, D. C.	7905140087	50-295		BROWN, S. C.	7905300017	50-339	
SCHEER, R. S.	7905240813	50-546		BROWN, S. C.	7905230691		
SCHEER, R. S.	7905230439	50-331		BROWN, S. C.	7905230693		
SCHEER, R. S.	7905190080	50-424		BROWN, S. C.	7905100266	50-267	
SCHEER, R. S.	7905240211	50-424		BROWN, R. L.	7905290113		
SCHEER, R. S.	7905220030	50-263		BROWN, R. L.	7905230393		
SCHEER, R. S.	7905220033	50-263		BROWN, R. S.	7905160028	50-320	
SCHEER, R. S.	7905070452	50-495		BRUCE, N. L.	7905310261	50-271	
SCHEER, R. S.	7905010664	50-596		BRUCE, R. O.	7905170269	50-260	
SCHEER, R. S.	7905230582	50-275		BRUNNER, E. J.	7905300588	50-249	
SCHEER, R. S.	7905300392	50-424		BRUNNER, E. J.	7905140208	50-317	
SCHEER, R. S.	7905140516	50-382		BRUNNER, E. J.	7905220441	50-320	
SCHEER, R. S.	7905220837	50-596		BRUNNER, E. J.	7905290169	50-244	
SCHEER, R. S.	7905190118	50-275		BRUNNER, E. J.	7905210042	50-320	
SCHEER, R. S.	7905240662	50-346		BRUNNER, E. J.	7905290116	50-277	
SCHEER, R. S.	7905240676	50-532		BRUNNER, E. J.	7905070172	50-286	
SCHEER, R. S.	7905290015			BRUNNER, E. J.	7905070145	50-272	
SCHEER, R. S.	7905190315	50-331		BRUNNER, E. J.	7905090142	50-213	
SCHEER, R. L.	7905090383	50-404		BRUNNER, E. J.	7905070189	50-247	
SCHEER, V. S.	7905020538			BRUNNER, E. J.	7905080099	50-286	
SCHEER, V. S.	7905290345	50-277		BRUNNER, E. J.	7905110216	50-219	
SCHEER, H. C.	7905010395	50-313		BRUNNER, E. J.	7905110362	50-247	
BRADFORD, H. H.	7905230503			BRUNNER, E. J.	7905110368	50-271	
BRADFORD, H. H.	7905230503	50-269		BRUNNER, E. J.	7905240430	50-289	
BRADFORD, P. A.	7905300667	50-322		BRUNNER, E. J.	7905240692	50-245	
BRADFORD, P. A.	7905190009			BRUNNER, E. J.	7905300743	50-311	
BRADFORD, P. A.	7905160038	50-320		BRUNNER, E. J.	7905290123	50-334	
BRADFORD, P. A.	7905160072	50-320		BRUNNER, E. J.	7905290140	50-245	
BRADFORD, P. A.	7905020024			BRUNNER, E. J.	7905290154	50-334	
BRADFORD, P. A.	7905160134	50-320		BRUNNER, E. J.	7905290160	50-334	
BRADFORD, P. A.	7905160101	50-320		BRUNNER, E. J.	7905070133	50-272	
BRADFORD, P. A.	7905020046			BRUNNER, E. J.	7905070161	50-286	
BRADFORD, P. A.	7905080070			BRUNNER, E. J.	7905190507	50-277	
BRADFORD, P. A.	7905100020	50-320		BRUNNER, E. J.	7905150225	50-263	
BRADFORD, P. A.	7905080125	50-320		BRUNNER, E. J.	7905080139		
BRADFORD, P. A.	7905030055			BRYAN, R. H.	7905020004		
BRADFORD, P. A.	7905290003			BRYAN, S. E.	7905110200	50-286	
BRADLEY, E. J.	7905030348	50-277		BRYAN, S. E.	7905110009	50-312	
BRADLEY, E. J.	7905030352	50-277		BRYAN, S. E.	7905140067	50-320	
BRADLEY, E. J.	7905110073	50-277		BRYAN, S. E.	7905110218	50-320	
BRADLEY, E. J.	7905220347	50-277		BRYAN, S. E.	7905110413		
BRADLEY, R. D.	7905230020	50-400		BRYAN, J. C.	7905290117	50-395	
BRADY, R. J.	7905160006	50-320		BRYAN, J. C.	7905020332	50-369	
BRADY, R. J.	7905160005	50-320		BRYAN, J. C.	7905020442	50-327	
BRADY, R. J.	7905160161	50-320		BRYAN, J. C.	7905020117	50-391	
BRADY, R. A.	7905160179	50-320		BRYAN, J. C.	7905070358	50-389	
BRADY, R. A.	7905160171	50-320		BRYAN, J. C.	7905240307	50-327	
BRADY, L. W.	7905240326			BRYAN, J. C.	7905010243	50-389	
BRAND, W. E.	7905030268	50-395		BRYAN, J. C.	7905290398	50-281	
BREHMECKER, D. E.	7905220087	50-466		BRYAN, J. C.	7905090426	50-395	
BRENNAN, J. E.	7905300572	50-309		BRYAN, J. C.	7905230752	50-491	
BRENNER, L.	7905020448	50-546		BRYAN, J. C.	7905230431	50-508	
BRENNER, L.	7905030436	50-546		BRYAN, J. C.	7905240537	50-491	
BRENNER, L.	7905240343	50-443		BRYAN, J. C.	7905240509	50-424	
BRENNER, L.	7905290028	50-485		BUCHANAN, J.	7905160129	50-320	
BRENNER, L.	7905290353	50-443		BUCHANAN, J.	7905190107	50-320	
BREYTHAUER, E.	7905230175	50-320		BUCHANAN, J.	7905300300	50-320	
BRICKLEY, R. H.	7905030150			BUCK, P.	7905160427	50-409	
BRICKLEY, R. H.	7905100418			BUDENHOLZER, R.	7905300232	50-320	
BRIDGES, K.	7905190303	40-8698		BUDNITZ, R. J.	7905110291	50-320	
BRIDGES, L. E.	7905110217	50-219		BUDNITZ, R. J.	7905110293	50-320	
BRINDLEY, J. H.	7905080510	50-375		BUDNITZ, R. J.	7905110299	50-320	
BRINKER, W. F.	7905100201	50-320		BUDNITZ, R. J.	7905110301	50-320	
BRINKMAN, R. E.	7904300342			BUDNITZ, R. J.	7905110302	50-320	
BRODSKY, R. S.	7905020264	71-9785		BUDNITZ, R. J.	7905160452	50-320	
BROEHL, D. J.	7905040520	50-344		BUDNITZ, R. J.	7905110286	50-320	
BROEHL, D. J.	7905090291	50-344		BUDNITZ, R. J.	7905110289	50-320	
BROEHL, D. J.	7905190387	50-344		BUDNITZ, R. J.	7905110308	50-320	
BROWN, F.	7905220034			BUL, A. R.	7905230443		
BROOKS, J.	7905230337			BUL, A. R.	7905230449		
BROOKS, J.	7905290329			BUNTING, R. L.	7905100251	50-285	
BROOKS, J.	7905230336			BUNNANO, N. A.	7905230711	50-352	
BROWN, J. M.	7905040015			BURCHETTE, W. H.	7905240332	50-445	
BROWN, P. D.	7905230409	50-596		BURCH, C. L.	7905300347	50-320	
BROWN, F. F.	7905090417			BURDETTE, T. E.	7905190801	50-518	
BROWNSTEIN, M.	7905010473			BURDETTE, T. E.	7905240468	50-395	
BROWN, E. G.	7905100364	50-320		BURDETTE, T. E.	7905240507	50-518	
BROWN, E. G.	7905240713	50-275		BURGER, A.	7905230040	50-29	
BROWN, M. S.	7905040002	50-316		BURIAN, R. J.	7905100126	71-6058	
BROWN, M. S.	7905110124	50-315		BURKE, P. A.	7905100398	71-288	
BROWN, M. S.	7905180430	50-315		BURKE, P. A.	7905100393	71-288	
BROWN, M. S.	7905230330	50-316		BURKE, D. J.	7905020019	50-280	
BROWN, H. P.	7905290067	50-312		BURKHARDT, W.	7905230706	50-364	
BROWN, R. A.	7905040132	50-346		BURN, R. R.	7905090298	50-2	
BROWN, D. H.	7905090273	50-346		BURN, R. R.	7905090367	50-2	
BROWN, B. C.	7905100070	50-339		BURNETT, O.	7905160489	50-116	
BROWN, B. C.	7905100076	50-339		BURNETT, O. W.	7905240353		
BROWN, B. C.	7905100055	50-339		BURNETT, P. T.	7905240491	50-327	
BROWN, B. C.	7905290529	50-339		BURNETT, P. T.	7905240534	50-339	
BROWN, B. C.	7905040126	50-338		BURNETT, R. F.	7905230756	70-1193	
BROWN, B. C.	7905240407	50-338		BURNETT, R. F.	7905240139	70-1193	
BROWN, B. C.	7905070404	50-339		BURNETT, R. F.	7905020041	50-320	
BROWN, B. C.	7905080511	50-339		BURSTEIN, S.	7905020289	50-301	
BROWN, B. C.	7905100317	50-338		BURSTEIN, S.	7905020304	50-301	
BROWN, B. C.	7905080434	50-339		BURSTEIN, S.	7905010489	50-502	
BROWN, B. C.	7905080443	50-338		BURSTEIN, S.	7905020310	50-266	
BROWN, B. C.	7905080482	50-339		BURSTEIN, S.	7905020318	50-266	
BROWN, S. C.	7905090297	50-339		BURSTEIN, S.	7905290075	50-266	
BROWN, S. C.	7905110214	50-339		BURSTEIN, S.	7905010513	50-502	

NEDO-24169A

NUREG-0382

NUREG-0358

NUREG/CR-0755

NUREG/CR-0754

7905240353

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
BURSTEIN, B.	7905030337	50-502		CARRIER, W. C.	7905220352	50-320	
BURSTEIN, B.	7905240319	50-266		CARRIER, W. C.	7905290285	50-320	
BURSTEIN, B.	7905100236	50-301		CARRIGAN, R. H.	7905230390		
BURSTEIN, B.	7905100263	50-301		CARRIGAN, R. H.	7905230388		
BURSTEIN, B.	7905240303	50-266		CARRIGAN, R. H.	7905230380	40-2407	
BURSTEIN, B.	7905020271	50-266		CARRIGAN, R. H.	7905230370	40-2407	
BURSTEIN, B.	7905100314	50-301		CARRIGAN, R. H.	7905230357	40-2407	
BURSTEIN, B.	7905100315	50-301		CARRIGAN, R. H.	7905230352	40-2407	
BURSTEIN, B.	7905300316	50-266		CARRIGAN, R. H.	7905230351	40-2407	
BURSTEIN, B.	7905240831	50-266		CARRIGAN, R. H.	7905230345	40-2407	
BURSTEIN, B.	7905080470	50-502		CARRIGAN, R. H.	7905230338	40-2407	
BURSTEIN, B.	7905150202	50-266		CARRIGAN, R. H.	7905230332	40-2407	
BURSTEIN, B.	7905130448	50-266		CARRIGAN, R. H.	7905230328	40-2407	
BURSTEIN, B.	7905240611	50-266		CARRIGAN, R. H.	7905230320	40-2407	
BURSTEIN, B.	7905240627	50-266		CARRIGAN, R. H.	7905230315	40-2407	
BURSTEIN, B.	7905290284	50-266		CARRIGAN, R. H.	7905230306	40-2407	
BURSTEIN, B.	7905160362	50-266		CARRIGAN, R. H.	7905230299	40-2407	
BURSTEIN, B.	7905150349			CARRIGAN, R. H.	7905230284	40-2407	
BURSTEIN, B.	7905150378	50-301		CARRIGAN, R. H.	7905230276	40-2407	
BURSTEIN, B.	7905150381	50-302		CARRIGAN, R. H.	7905230261	40-2407	
BURSTEIN, B.	7905240397	50-301		CARRIGAN, R. H.	7905230247	40-2407	
BURSTEIN, B.	7905310399	50-266		CARRIGAN, R. H.	7905230758	40-2407	
BURT, L.	7905070026	50-443		CARRIGAN, R. H.	7905230233	40-2407	
BURT, L.	7905240943	50-471		CARRIGAN, R. H.	7905230226		
BURT, L.	7905090411	50-471		CARRIGAN, R. H.	7905230586		
BURT, L.	7905230396			CARRIGAN, R. H.	7905230214		
BURT, L.	7905240794	50-471		CARROLL, J. T.	7905010528	50-317	
BURWELL, B. B.	7905140040	50-443		CARROLL, J. T.	7905190083	50-317	
BUSCH, R. M.	7905140159	50-322		CARROLL, J. T.	7905290430	50-317	
BUSCH, R. M.	7905140161	50-322		CARROLL, J. T.	7905070557	50-219	
BUSKIN, K. P.	7905230314	50-266		CARROLL, J. T.	7905090329	50-219	
BUTLER, R. M.	7905290654	50-471		CARROLL, J. T.	7905140327	50-219	
BUTLER, R. M.	7905140435	50-471		CARSON, J. E.	7905040462	50-329	
BUTLER, R. M.	7905150297	50-293		CARTER, T. F.	7905070141		
BUTLER, R. M.	7905220021	50-471		CARTER, T.	7904270399	50-320	
BUTLER, R. M.	7905300011	50-471		CARTWRIGHT, K.	7905100089	40-2061	
BUTLER, R. M.	7905300013	50-471		CARTWRIGHT, J. E.	7905150063	50-356	
BUTZEL, A. K.	7905240983	50-549		CARTWRIGHT, W. R.	7905020396	50-338	
CABA, E. C.	7905140235	50-346		CARTWRIGHT, W. R.	7905020403	50-338	
CADEK, F. F.	7905110098			CARTWRIGHT, W. R.	7905020484	50-338	
CAHILL, W. J.	7905290124			CARTWRIGHT, W. R.	7905020248	50-338	
CAHILL, W. J.	7905290185	50-3		CARTWRIGHT, W. R.	7905070533	50-338	
CAHILL, W. J.	7905250248	50-3		CARTWRIGHT, W. R.	7905070659	50-338	
CAHILL, W. J.	7905040004	50-247		CARTWRIGHT, W. R.	7905070662	50-338	
CAHILL, W. J.	7905070549	50-3		CARTWRIGHT, W. R.	7905080447	50-338	
CAHILL, W. J.	7905090287	50-247		CARTWRIGHT, W. R.	7905080449	50-338	
CAHILL, W. J.	7905190015	50-3		CARTWRIGHT, W. R.	7905110147	50-338	
CAHILL, W. J.	7905190021	50-3		CARTWRIGHT, W. R.	7905110152	50-338	
CAHILL, W. J.	7905170244	50-247		CARTWRIGHT, W. R.	7905160437	50-338	
CAHILL, W. J.	7905230365	50-3		CARTWRIGHT, W. R.	7905160444	50-338	
CAHILL, W. J.	7905310396	50-247		CARTWRIGHT, W. R.	7905160454	50-338	
CAHILL, W. J.	7905300354	50-247		CARTWRIGHT, W. R.	7905160459	50-338	
CAHILL, W. J.	7905300358	50-247		CARTWRIGHT, W. R.	7905210260	50-338	
CALDWELL, R. A.	7905230268	50-285		CARTWRIGHT, W. R.	7905220296	50-338	
CALDWELL, R. A.	7905150584	50-112		CARTWRIGHT, W. R.	7905230071	50-338	
CALIFANO, J. A.	7904170110	50-320		CARTWRIGHT, W. R.	7905300404	50-338	
CALKINS, O. D.	7905160015	50-320		CARTWRIGHT, W. R.	7905300409	50-338	
CAMP, O. T.	7905160399	50-295		CARTWRIGHT, W. R.	7905300412	50-338	
CAMPBELL, J.	7905100310	50-304		CARY, C. N.	7905240552		7905240552
CAMPBELL, M.	7905160194	50-320		CASE, E. O.	7905080144		
CAMPBELL, M.	7905160077	50-320		CASE, E. O.	7905300400		
CAMPBELL, M.	7905160007	50-320		CASE, E.	7905110064		
CANNON, E.	7905290251	71-282		CASEY, L. A.	7905100240		
CANOVA, M. A.	7905090342	50-318		CASH, A.	7905250454		
CANOVA, M. A.	7905080561	50-317		CASHELL, B.	7905010488		
CANTER, H. L.	7905110086	50-312		CASHMAN, T. J.	7905230813	50-201	
CANTRELL, F. B.	7905290174	50-335		CASJENS, L.	7905250201	40-8681	
CANTRELL, F. B.	7905290717	50-369		CASSAN, V. J.	7905070417		
CANTRELL, F. B.	7905020049	50-280		CATALANO, G. R.	7905100078	40-2061	
CANTRELL, F. B.	7905020019	50-280		CATCHPOLE, G. J.	7905100172	40-8693	
CANTRELL, F. B.	7905020471	50-339		CATTON, I.	7905250139		
CANTRELL, F. B.	7905020423	50-369		CATTON, I.	7905250111		
CANTRELL, F. B.	7905010275	50-338		CATTON, I.	7905250118		
		50-230		CAVANAUGH, H.	7905070483	50-313	
		50-348		CAVANAUGH, H.	7905110082	50-313	
		50-320		CAVANAUGH, H.	7905140279	50-313	
		50-311		CAVANAUGH, H.	7905170265	50-368	
		50-320		CAVANAUGH, H.	7905190053	50-313	
		50-320		CAVANAUGH, H.	7905210264	50-313	
		50-320		CAVANAUGH, H.	7905300002	50-368	
		50-320		CERNE, A. C.	7905240684	50-363	
		50-320		CHADWELL, H. M.	7905070604	50-315	
		50-320		CHAN, J.	7905040561	50-237	
		50-320		CHAN, J.	7905300573	50-237	
		50-320		CHAN, A. I.	7905100165		
		50-320		CHANANIA, F. D.	7905230622	50-250	
		50-320		CHANANIA, F. D.	7905130216	50-395	
		50-320		CHANANIA, F. D.	7905230743	50-395	
		50-320		CHANDLER, L. J.	7905250271	50-445	
		50-320		CHANDLER, L. J.	7905250143	50-445	
		50-320		CHANDLER, L. J.	7905300362	50-445	
		50-320		CHAPPELL, D.	7905040262	50-320	
		50-320		CHAPMAN, L. D.	7905240404		
		50-320		CHAPMAN, L. D.	7905240553		
		50-320		CHEN, J. C.	7905020151		
		50-320		CHERN, J. C.	7905100290	50-305	
		50-320		CHESTER, R. O.	7905240540		
		50-320		CHESTER, R. O.	7905250312		
		50-320		CHESTER, R. O.	7905140419	50-400	
		50-320		CHILDS, M. V.	7905010503	50-333	
		50-320		CHILDS, M. V.	7905010508	50-333	
		50-320		CHILDS, M. V.	7905150477	50-333	
		50-320		CHILDS, M. V.	7905300416	50-333	
		50-320		CHILDS, M. V.	7905300314	50-333	
		50-320		CHILDS, M. V.	7905300527	50-333	
		50-320		CHILDS, B. J.	7905300613		

NCAP-9402 (NP)

7905240552

NUREG/CP-0005

NUREG/CR-0643

7905240404

7905240553

7905020151

KN-MF-79-27

7905240540

PERSONAL AUTHOR INDEX

325

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
CHILK, S. J.	7905230701			COLLINS, H. E.	7905250444		
CHILK, S. J.	7905230484			COLLINS, H. E.	7905090214	50-320	
CHILK, S. J.	7905230499			COLLINS, D. H.	7905230202	50-320	
CHILK, S. J.	7905100026	50-320		COLLINS, J. T.	7905230056	50-320	
CHILK, S. J.	7905090283	50-313		COLLINS, J. T.	7905230074	50-320	
CHILK, S. J.	7905100047	50-320		COLLINS, J. T.	7905210230	50-320	
CHILK, S. J.	7905100408	50-320		COLLINS, J. T.	7905230105	50-320	
CHILK, S. J.	7905090192			COLLINS, J. T.	7905230143	50-320	
CHILK, S. J.	7905090215	50-320		COLLINS, J. T.	7905230293	50-320	
CHILK, S. J.	7905090194			COLLINS, J. T.	7905230157	50-320	
CHILK, S. J.	7905140033	50-344		COLLINS, P. F.	7905070070	50-594	
CHILK, S. J.	7905300268	50-320		COLLINS, P. F.	7905240166	50-252	
CHILK, S. J.	7905230678	50-485		COLLINS, P. F.	7905250204	50-267	
CHILK, S. J.	7905230063			COLLINS, P. F.	7905300180		
CHILK, S. J.	7905230646	50-280		COLLINS, P. F.	7905300285		IAEA-SK-178/34
CHILK, S. J.	7905100056			COLMBO, P. W.	7905110039	50-312	
CHILK, S. J.	7905240315			COLMBO, R. W.	7905100282	50-312	
CHILK, S. J.	7905230661	50-344		COLMBO, R. W.	7905110307	50-312	
CHILK, S. J.	7905230373	50-305		COLMBO, R. W.	7905250437	50-312	
CHILK, S. J.	7905240918	50-424		COLMBO, R. W.	7905290004	50-312	
CHILK, S. J.	7905190260	50-599		COLMBO, R. W.	7905300409	50-312	
CHILK, S. J.	7905240435			COLTON, E.	7905150784		
CHILK, S. J.	7905240820			COMBS, R. B.	7905140511		
CHILK, S. J.	7905240510	50-338		COMBY, D. D.	7905230239	50-320	CBE-7865
CHILK, S. J.	7905290165	50-400		CONGEL, F.	7905160129	50-320	
CHILK, S. J.	7905230334			CONGEL, F.	7905190107	50-320	
CHILK, S. J.	7905240358			CONGEL, F.	7905300300	50-320	NUREG-055B
CHILK, S. J.	7905240366			CONLEY, M. E.	7905090032		
CHILK, S. J.	7905250479	50-320		CONLEY, M. E.	7905020080		
CHILK, S. J.	7905250205	50-389		CONLON, T. E.	7905010471	50-302	
CHILK, S. J.	7905250331			CONLON, T. E.	7905240518	50-348	
CHILK, S. J.	7905250539			CONNOR, T. B.	7905290171	50-358	
CHILK, S. J.	7905300481			CONNOR, T. B.	7905290176	50-358	
CHOPKO, M.	7905220434	50-320		CONNOR, T. B.	7905150151	50-358	
CHOPKO, K.	7905220436	50-320		CONNOR, T. B.	7905300067	50-358	
CHOW, E. T.	7905090175	50-409		CONNOR, T. B.	7905100225	27-39	
CHRISTMAN, J. N.	7905230668	50-338		CONNOR, T. B.	7905030214	50-395	
CHRISTMAN, J. N.	7905240814	50-338		CONNOR, T. B.	7905310010	27-39	
CHRISTMAN, J.	7905030207	50-338		CONNOR, T. B.	7905100237	27-39	
CHRISTMAN, J.	7905050209	50-338		CONNOR, T. B.	7905240138	27-39	
CHRISTOFFER, G. M.	7905110047	50-182		CONNOR, T. B.	7905230512	50-277	
CHU, C. K.	7905300561			CONNOR, T. B.	7905140137	50-395	
CHURCHILL, S. W.	7905250339	50-502		CONNELL, J. H.	7905300270	50-206	
CHURCHILL, S. W.	7905300104	50-344		CONNELL, J. H.	7905300277	50-206	
CIANCIO, J. H.	7905290435			CONNELL, C.	7905150304	50-286	
CIESZKIEWICZ, S.	7905160359	50-10		CONNELL, H. R.	7905100021		7905100021
CLACK, S. J.	7905250522			CONNORS, J. E.	7905100023		
CLARK, L.	7905250350	50-596		CONNOLLEY, J. L.	7905140494	50-285	
CLARK, L.	7905040480	50-20		CONNOLLEY, J. L.	7905210259	50-285	
CLARK, C. W.	7905160391	50-329		CONNOLLEY, J. L.	7905210271	50-285	
CLARKE, W. L.	7905090031		7905090031	CONSTABLE, O. L.	7905150604	50-188	
CLARK, J. R.	7905020214	50-201		CONTE, R. J.	7905070158	50-272	
CLARK, R. H.	7905300058	50-445		CONTE, R. J.	7905290145	50-245	
CLARK, R. H.	7905100288	50-445		CONVER, S.	7905190199	50-320	
CLARK, F. R.	7905220387	50-333		CONWAY, J. T.	7905140090	50-320	
CLARK, R. A.	7905310015		7905310015	CONWAY, W. F.	7905080352	50-271	
CLARK, A. T.	7905290282	50-201		CONWAY, W. F.	7905080553	50-271	
CLARK, R. A.	7905240846	50-259		CONWAY, W. F.	7905290037	50-271	
CLAY, E. L.	7905240069	50-335		CONWAY, W. F.	7905290040	50-271	
CLAY, E. L.	7905240336	70-1151		COOK, C. L.	7905150214	71-280	
CLAY, E. L.	7905240312	70-1151		COOK, C. L.	7905150474	71-280	
CLAYTON, F. L.	7905230777	50-348		COOK, T. F.	7905090408		NUREG/CR-0590
CLAYTON, F. L.	7905100279	50-348		COOK, K. W.	7905110116		
CLAYTON, F. L.	7905020242	50-348		COOK, J. R.	7905250245	50-568	
CLAYTON, F. L.	7905240443	50-348		COOK, R. J.	7905250296	50-329	
CLAYTON, F. L.	7905300710	50-348		COOKE, P. S.	7905250042	40-8478	
CLAYTON, F. L.	7905020247	50-348		COOLEY, W. J.	7905150701	70-1287	
CLAYTON, F. L.	7905300554	50-348		COOLEY, R. A.	7905140117	50-320	
CLAYTON, F. L.	7905070631	50-348		COONEY, M. J.	7905070016		
CLAYTON, F. L.	7905090075	50-348		COONEY, M. J.	7905220280	50-277	
CLAYTON, F. L.	7905250036	50-348		COONEY, H. J.	7905220284	50-277	
CLAYTON, F. L.	7905110242	50-348		COONEY, H. J.	7905080464	50-277	
CLAYTON, F. L.	7905140306	50-348		COONEY, H. J.	7905040578	50-277	
CLAYTON, F. L.	7905160403	50-348		COONEY, H. J.	7905040077	50-277	
CLAYTON, F. L.	7905170266	50-348		COONEY, H. J.	7905040092	50-277	
CLAYTON, F. L.	7905230361	50-348		COONEY, K. J.	7905020347	50-277	
CLAYTON, F. L.	7905230414	50-348		COONEY, M. J.	7905020356	50-277	
CLAYTON, F. L.	7905300500	50-348		COONEY, M. J.	7905040581	50-277	
CLAYTON, F. L.	7905310376	50-348		COONEY, M. J.	7905160383	50-277	
CLAYTON, F. L.	7905230239	50-320	CBE-7865 FCBE-79137	COONEY, M. J.	7905170236	50-277	
CLAYTON, F. L.	7905250450			COONEY, M. J.	7905290214	50-277	
CLAYTON, F. L.	7905170251	50-443		COONEY, M. J.	7905290216	50-277	
CLAYTON, A. R.	7905290295	50-471		COOPER, K. F.	7905070551	50-272	
CLAYTON, A. R.	7905290292	50-471		COOPER, J.	7905040050	50-302	
CLAYTON, F. L.	7905090168			COOPER, J.	7905040094	50-302	
CLAYTON, P.	7905110113	50-6134		COOPER, J.	7905070602	50-302	
CLAYTON, R. C.	7905080108			COOPER, J.	7905070626	50-302	
CLAYTON, T. H.	7905150359	50-264		COOPER, J.	7905070540	50-302	
CLAYTON, L. I.	7905100022	50-320		COOPER, J.	7905070648	50-302	
CLAYTON, T. B.	7905140079	70-2623		COOPER, J.	7905040632	50-302	
CLAYTON, B. J.	7905150805	50-590		COOPER, J.	7905070654	50-302	
CLAYTON, R.	7905080540	50-237		COOPER, J.	7905090281	50-302	
CLAYTON, R.	7905170229	50-237		COOPER, J.	7905110244	50-302	
CLAYTON, W. S.	7905300686	50-309		COOPER, J.	7905190628	50-302	
CLAYTON, I.	7905230288	70-33		COOPER, J.	7905230373	50-302	
CLAYTON, M. A.	7905300035	50-250		COOPER, J.	7905300503	50-302	
CLAYTON, M. A.	7905190785	50-250		COOPER, J.	7905250385	50-302	
CLAYTON, M. A.	7905190793	50-250		COOPER, J.	7905300491	50-302	
CLAYTON, M. A.	7905190799	50-250		COOPER, J.	7905310403	50-302	
CLAYTON, M. A.	7905240973	50-250		COOPERSTEIN, R.	7905300691	40-8102	
CLAYTON, M. A.	7905240838	50-389		COOPERSTEIN, R.	7905150634	40-8721	
CLAYTON, M. A.	7905240940	50-568		COOPERSTEIN, R.	7905240855	40-8663	
CLAYTON, M. A.	7905230248	50-320		COOPERSTEIN, R.	7905150806	40-8502	
CLAYTON, H. E.	7905250516			COOPERSTEIN, R.	7905250012	40-8714	
CLAYTON, H. E.	7905250501			COPELAND, J. G.	7905080387	50-466	
CLAYTON, H. E.	7905250517			COPELAND, J. G.	7905080331	50-466	

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
COPELAND, J. G.	7905230230	50-466		CRONEBERGER, D.	7905230011	50-320	
COPELAND, J. G.	7905230177	50-437		CRONEBERGER, D.	7905230009	50-320	
COPELAND, J. G.	7905300066	50-466		CROSBYMAN, W. A.	7905070209	50-445	
COPELAND, J. G.	7905310407	50-466		CROSBYMAN, W. A.	7905150370	50-356	
COPELAND, J. G.	7905290068	50-466		CROUCHER, D. W.	7905020022		NUREG/CR-0283
COPELAND, J. G.	7905240310	50-466		CROW, W. T.	7905080027	70-135	
COPELAND, J. G.	7905240043	50-466		CROW, W. T.	7905090265	70-143	
COPELAND, J. G.	7905250239	50-466		CROW, W. T.	7905240080	70-1319	
COPELAND, R. L.	7905020293	50-537		CROW, W. T.	7905090003	40-8027	
CORRETT, J. B.	7905220434	27-47		CROW, W. T.	7905090008	40-8027	
CORE, M.	7905070345	50-285		CROW, W. T.	7905220029	40-8663	
CORE, M.	7905220306	50-285		CROW, W. T.	7905100064	40-2061	
CORNELL, E. K.	7905090158			CROW, W. T.	7905290479	40-8027	
CORNELL, E. K.	7905020157	27-39		CROW, W. T.	7905250067	40-8035	
CORNELL, E. K.	7905220451	50-320		CROW, W. T.	7905240855	40-8663	
CORREA, C.	7905290089	50-272		CROW, W. T.	7905240180	70-2838	
COSTELLO, J.	7905150273	50-382		CROWLEY, C. J.	7905020154		7905020134
COSTELLO, J.	7905150415	50-382		CROWLEY, C. J.	7905030221		NUREG/CR-0599
COSTELLO, J. R.	7905290113			CROWLEY, C. J.	7905240352		7905240352
COSTELLO, J. R.	7905230393			CROWLEY, B. R.	7905240318	50-348	
COTTE, W. T.	7905020423	50-369		CUBLE, R.	7905080051		NUREG-0484
COTTE, W. T.	7905290717	50-369		CULP, W. Q.	7905220232	50-495	
COUGHLIN, J.	7905140097	50-346		CULP, R. H.	7905080387	50-466	
COUGHLIN, J.	7905230433	50-346		CULP, R. H.	7905080331	50-466	
COUGHLIN, J.	7905080413	50-346		CULP, R. H.	7905250170	50-498	
COUGHLIN, J.	7905160400	50-346		CULP, R. H.	7905080311	50-466	
COUGHLIN, J.	7905310420	50-346		CULP, R. H.	7905080320	50-466	
COUNCIL, W. Q.	7905220446	50-213		CULP, R. H.	7905250225	50-466	
COUNCIL, W. Q.	7905240392	50-213		CULP, R. H.	7905140057	50-466	
COUNCIL, W. Q.	7905240503	50-213		CULP, R. H.	7905250328	50-498	
COUNCIL, W. Q.	7905310473	50-213		CULP, R. H.	7905100391	50-466	
COUNCIL, W. Q.	7905070342	50-213		CULP, P. H.	7905250239	50-466	
COUNCIL, W. Q.	7905300323	50-213		CULP, R. H.	7905290002	50-498	
COUNCIL, W. Q.	7905010485	50-245		CUNNINGHAM, Q. E.	7905150627	71-3926	
COUNCIL, W. Q.	7905010496	50-245		CUNNINGHAM, Q. E.	7905290062	70-754	
COUNCIL, W. Q.	7905250513			CUNNINGHAM, Q. E.	7905240588	70-1007	
COUNCIL, W. Q.	7905250523			CUNNINGHAM, Q. E.	7905250218	70-754	
COUNCIL, W. Q.	7905070658	50-213		CUNNINGHAM, Q. E.	7905240910	71-9009	
COUNCIL, W. Q.	7905040053	50-336		CUNNINGHAM, Q. H.	7905160227	50-320	
COUNCIL, W. Q.	7905040135	50-336		CUNNINGHAM, R. E.	7905220028	70-1318	
COUNCIL, W. Q.	7905070359	50-336		CUNNINGHAM, R. E.	7905310132	70-2623	
COUNCIL, W. Q.	7905070621	50-245		CUNNINGHAM, M.	7905220442	50-320	
COUNCIL, W. Q.	7905080362	50-245		CUNNINGHAM, M.	7905220432	50-320	
COUNCIL, W. Q.	7905080454	50-245		CUNNINGHAM, M.	7905110315	50-320	
COUNCIL, W. Q.	7905080406	50-336		CUNNINGHAM, M.	7905110312	50-320	
COUNCIL, W. Q.	7905100320	50-336		CUNNINGHAM, M.	7905160064	50-320	
COUNCIL, W. Q.	7905160262	50-336		CUNNINGHAM, M.	7905160139	50-320	
COUNCIL, W. Q.	7905160376	50-336		CURRAN, J. K.	7905080425	50-206	
COUNCIL, W. Q.	7905220116	50-336		CURRAN, J. K.	7905110139	50-206	
COUNCIL, W. Q.	7905290073	50-213		CURRAN, J. M.	7905150409	50-206	
COUNCIL, W. Q.	7905300005	50-245		CURRAN, J. M.	7905150512	50-206	
COUNCIL, W. Q.	7905300009	50-336		CURRAN, J. M.	7905310444	50-206	
COUNCIL, W. Q.	7905300261	50-336		CURTIS, N. H.	7905030149	50-387	
COUNCIL, W. Q.	7905310183	50-336		CURTIS, N. H.	7905250186	50-387	
COUNCIL, W. Q.	7905220068	50-250		CURTIS, N. H.	7905020262	50-387	
COWAN, B. Z.	7905250290	50-437		CURTIS, N. H.	7905040504	50-387	
COWGILL, C. J.	7905290145	50-245		CURTIS, N. H.	7905090346	50-387	
COX, C.	7905230175	50-320		CURTIS, N. W.	7905090365	50-387	
COX, E. T.	7905090374	50-448		CURTIS, N. W.	7905110300	50-387	
CRABTREE, R. A.	7905230528	50-309		CURTIS, N. W.	7905190224	50-387	
CRADDOCK, W. G.	7905140572		NUREG/CR-0539	CURTIS, N. W.	7905240574	50-387	
CRAFTON, M.	7905230495	50-346		CURTIS, N. W.	7905250421	50-387	
CRANE, P. A.	7905030244	50-275		CUTCHIN, J. M.	7905240081	50-387	
CRANE, P. A.	7905140303	50-133		CUTCHIN, J. M.	7905240441	50-368	
CRANE, P. A.	7905140554	50-275		DACRO, B. S.	7905140284	50-445	
CRANE, P. A.	7905140556	50-275		DAHLSTROM, C. O.	7905290136		
CRANE, P. A.	7905230490	50-275		DALL, L. C.	7905230699	50-491	
CRANE, P. A.	7905020244	50-275		DALL, L. C.	7905140167	50-413	
CRANE, P. A.	7905150809	50-133		DALL, L. C.	7905240520	50-491	
CRANE, P. A.	7905290011	50-133		DALL, L. C.	7905190100	50-413	
CRANE, P. A.	7905020302	50-275		DALE, L. F.	7905080450	50-414	
CRANE, P. A.	7905090318	50-133		DALLY, J. W.	7905290491		7905290491
CRANE, P. A.	7905090380	50-275		DALTROFF, B. L.	7905230710	50-277	
CRANE, P. A.	7905240701	50-275		DALTROFF, B. L.	7905250182	50-277	
CRANE, P. A.	7905140406	50-133		DALTROFF, B. L.	7905240184	50-277	
CRANE, P. A.	7905190054	50-275		DALY, H.	7905250333	50-596	
CRANE, P. A.	7905210172	50-275		DAMBLI, D. C.	7905240493	50-329	
CRANE, P. A.	7905210169	50-275		DAMBLI, D.	7905310028	50-329	
CRANE, P. A.	7905300168	50-133		DAMERON, H. G.	7905290051	70-27	
CRANE, P. A.	7905300364	50-275		DANCE, H. C.	7905310024	50-302	
CRANE, P. A.	7905300361	50-275		DANCE, H. C.	7905230243	50-324	
CRANE, P. A.	7905300510	50-133		DANCE, H. C.	7905230592	50-261	
CREITZ, W. M.	7905160174	50-320		DANCE, H. C.	7905150107	50-259	
CRESWELL, J. S.	7905110094	50-346		DANCE, H. C.	7905250110	50-321	
CRESWELL, J. S.	7905090175	50-409		DANCE, H. C.	7905150147	50-259	
CREWS, E. H.	7905230605	50-393		DANCE, H. C.	7905020497	50-321	
CREWS, E. H.	7905300692	50-393		DANCE, H. C.	7905100332	50-592	
CREWS, J. L.	7905110044	50-312		DANIELSON, T.	7905240200	40-3453	
CREWS, J. L.	7905110083	50-312		DANIELSON, R. W.	7905210120	50-320	
CREWS, J. L.	7905110086	50-312		DANIEL, J. A.	7905230308	50-341	
CREWS, J. L.	7905230617	50-275		DANIELSON, D. H.	7905080211	50-331	
CREWS, J. L.	7905150533	50-312		DANIELSON, D. H.	7905150165	50-156	
CREWS, J. L.	7905290147	50-275		DANIELSON, F. T.	7905140087	50-293	
CRISTY, M.	7905290498		7905290498	DANIELSON, F. T.	7905240748	50-456	
CRNICH, J.	7905130415	50-382		DANIELSON, D. H.	7905290569	50-155	
CROCKET, L.	7905140570	50-219	NUREG/CR-0634	DANIELSON, D. H.	7905240716	50-373	
CROCKER, H. W.	7905240306	50-244		DANIELSON, D. H.	7905040349	50-461	
CROCKER, H. W.	7905230750	50-277		DANIELSON, D. H.	7905150436	50-331	
CROCKER, H. W.	7905110113	50-6134		DANIELSON, D. H.	7905150535	50-388	
CROCKER, H. W.	7905290196	50-3		DANIELSON, D. H.	7905110207	50-329	
CROCKER, H. W.	7905090140	50-220		DAQUD, L.	7905110207	70-784	
CROCKER, L. P.	7905100325	50-275		DARMITZEL, R. W.	7905150588	50-70	
CROCKER, L. P.	7905300396	50-320		DARMITZEL, R. W.	7905160428	50-546	
CROCKER, L. P.	7905300381	50-320		DATTILO, T. M.	7905110353	50-546	
CRONENBERG, A. W.	7905150213		NUREG/CR-0595	DATTILO, T. M.	7905240872	50-546	
CRONEBERGER, D. K.	7905230014	50-320		DATTILO, T. M.	7905240964	50-546	

327

[illegible]

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
DRAKE, J. H.	7905090325	50-206		ELLIS, J.	7905240929	50-443	
DRAKE, J. H.	7905130400	50-206		ELROD, S. A.	7905020049	50-280	
DRAKE, J. H.	7905170257	50-206		ELBASSER, T. C.	7905090254	50-320	
DREY, K.	7905020533	50-10		ELBASSER, T.	7905090248	50-320	
DREY, K.	7905020234	50-10		ELBASSER, T. C.	7905220439	50-320	
DRUMERICK, A. W.	7905020459	50-338		EMAL, H. A.	7905210070	50-320	
DUCK, J. R.	7905010327	50-327		ENDREB, O. H.	7905030013		NUREG/CR-0426 V1
DUCK, J. R.	7905100304	50-348		ENGEL, R. E.	7905300317		
DUCK, J. R.	7905160396	50-348		ENGEL, D. A.	7905030239	50-549	
DUCK, J. R.	7905300468	50-348		ENGEL, D. A.	7905150266	50-596	
DUDA, E.	7905160394	50-220		ENGELHARDT, T. F.	7905090235	50-320	
DUDA, E.	7905300496	50-220		ENGELHARDT, T. F.	7905150321	50-482	
DUFF, P. A.	7904300258			ENGELHARDT, T. F.	7905150726	50-275	
DUFF, M. E.	7905140332	50-593		ENGELKEN, R. H.	7905010253	50-528	
DUFFLO, M. E.	7905090249	50-320		ENGELKEN, R. H.	7905010287	50-133	
DUFFLO, M. E.	7905220070	50-278		ENGELKEN, R. H.	7905010289	50-344	
DUFFLO, M. E.	7905100067	50-344		ENGELKEN, R. H.	7905010291	50-312	
DUFFLO, M. E.	7905240135	50-338		ENGELKEN, R. H.	7905010292	50-206	
DUFFLO, M. E.	7905240487	50-338		ENGELKEN, R. H.	7905010294	50-397	
DUFFLO, M. E.	7905250318	50-498		ENGELKEN, R. H.	7905030073	50-458	
DUFFLO, M. E.	7905250035	50-389		ENGELKEN, R. H.	7905040076	50-528	
DUFFLO, M. E.	7905150710			ENGELKEN, R. H.	7905040081	50-133	
DUFFLO, M. E.	7905140332	50-320		ENGELKEN, R. H.	7905040086	50-344	
DUFFLO, M. E.	7905150233	50-329		ENGELKEN, R. H.	7905040216	50-133	
DUFFLO, M. E.	7905150342	50-320		ENGELKEN, R. H.	7905040218	50-344	
DUFFLO, M. E.	7905240585	50-277		ENGELKEN, R. H.	7905040220	50-312	
DULEY, J. W.	7905070171			ENGELKEN, R. H.	7905040222	50-984	
DULLINGFORD, M.	7904180171			ENGELKEN, R. H.	7905040225	70-1257	
DUNBAR, J.	7905300447	50-237		ENGELKEN, R. H.	7905040230	70-734	
DUNBAR, J.	7905300499	50-237		ENGELKEN, R. H.	7905040234	70-734	
DUNDAS, W. J.	7905230463	50-266		ENGELKEN, R. H.	7905040239	70-43	
DUNENFELD, M.	7905140056			ENGELKEN, R. H.	7905040423	50-133	
DUNN, C. N.	7905240209	71-5450		ENGELKEN, R. H.	7905040428	50-344	
DUNN, C. N.	7905140332	50-334		ENGELKEN, R. H.	7905040431	50-206	
DUNN, C. N.	7905090066	50-334		ENGELKEN, R. H.	7905040433	50-312	
DUNN, C. N.	7905250461	50-334		ENGELKEN, R. H.	7905150057	50-528	
DUNN, C. N.	7905010491	50-334		ENGELKEN, R. H.	7905150060	50-133	
DUNN, C. N.	7905090373	50-334		ENGELKEN, R. H.	7905150062	50-344	
DUNN, C. N.	7905140300	50-334		ENGELKEN, R. H.	7905150064	50-206	
DUNN, C. N.	7905110011	50-334		ENGELKEN, R. H.	7905150065	50-312	
DUNN, C. N.	7905110070			ENGELKEN, R. H.	7905150069	50-397	
DUNN, C. N.	7905150267	50-412		ENGELKEN, R. H.	7905150165	50-528	
DUNN, C. N.	7905150269	50-412		ENGELKEN, R. H.	7905150167	50-133	
DUNN, C. N.	7905220081	50-334		ENGELKEN, R. H.	7905150168	50-344	
DUNN, C. N.	7905220093	50-334		ENGELKEN, R. H.	7905150170	50-206	
DUNN, J. D.	7905110004	50-312		ENGELKEN, R. H.	7905150171	50-312	
DURHAM, J. W.	7905220187	50-344		ENGELKEN, R. H.	7905150173	50-397	
DYER, N. C.	7905100251	50-285	NUREG/CR-0735	ENGELKEN, R. H.	7905040121	50-528	
DYER, J. A.	7905020423	50-369		ENGELKEN, R. H.	7905040123	50-133	
DYER, J. A.	7905090135	50-338		ENGELKEN, R. H.	7905040125	50-344	
DYER, J. A.	7905240534	50-339		ENGELKEN, R. H.	7905040128	50-206	
EADS, B. O.	7905230160		7905250160	ENGELKEN, R. H.	7905040130	50-312	
EAGLETON, T. F.	7905020212	50-483		ENGELKEN, R. H.	7905040134	50-397	
EARLY, P. J.	7905040505	50-333		ENGELKEN, R. H.	7905150136	50-528	
EARLY, P. J.	7905040513	50-286		ENGELKEN, R. H.	7905150141	50-133	
EARLY, P. J.	7905080565	50-333		ENGELKEN, R. H.	7905150142	50-344	
EARLY, P. J.	7905090315	50-333		ENGELKEN, R. H.	7905150145	50-206	
EARLY, P. J.	7905090343	50-333		ENGELKEN, R. H.	7905150150	50-397	
EARLY, P. J.	7905100156	50-286		ENGELKEN, R. H.	7905010013	50-312	
EARLY, P. J.	7905100175	50-333		ENGELKEN, R. H.	7905010015	50-397	
EARLY, P. J.	7905100179	50-333		ENGELKEN, R. H.	7905010016	50-528	
EARLY, P. J.	7905140307	50-333		ENGELKEN, R. H.	7905010020	50-206	
EARLY, P. J.	7905150452	50-333		ENGELKEN, R. H.	7905010023	50-133	
EARLY, P. J.	7905220380	50-286		ENGELKEN, R. H.	7905010025	50-361	
EARLY, P. J.	7905190073	50-333		ENGELKEN, R. H.	7905010027	50-344	
EARLY, P. J.	7905230430	50-333		ENGELKEN, R. H.	7905030018	50-397	
EARLY, P. J.	7905240697	50-333		ENGELKEN, R. H.	7905030024	50-206	
EARLY, P. J.	7905310443	50-286		ENGELKEN, R. H.	7905030028	50-312	
EASTMAN, P. H.	7905240604	50-284		ENGELKEN, R. H.	7905030030	50-344	
EBERT, D. D.	7905010347	50-77		ENGELKEN, R. H.	7905030043	50-133	
EBERT, R.	7905290389			ENGELKEN, R. H.	7905030050	50-528	
EBNETER, S. D.	7905100433	50-387		ENGELKEN, R. H.	7905040477	50-344	
EBNETER, S. D.	7905290132	50-277		ENGELKEN, R. H.	7905040507	50-528	
EBNETER, S. D.	7905150620	50-528		ENGELKEN, R. H.	7905040508	50-133	
EBNETER, S. D.	7905010471	50-302		ENGELKEN, R. H.	7905040509	50-275	
EBNETER, S. D.	7905240821	50-400		ENGELKEN, R. H.	7905040511	50-206	
EBNETER, S. D.	7905290098	50-400		ENGELKEN, R. H.	7905040512	50-361	
EBNETER, S. D.	7905140330	50-219		ENGELKEN, R. H.	7905040515	50-312	
EBNETER, S. D.	7905220064	50-556		ENGELKEN, R. H.	7905040516	50-397	
EBNETER, S. D.	7905240879	50-556		ENGELKEN, R. H.	7905040516	50-528	
EBNETER, S. D.	7905230567			ENGELKEN, R. H.	7905040614	50-344	
EBNETER, S. D.	7905220089	50-123		ENGELKEN, R. H.	7905040616	50-206	
EBNETER, S. D.	7905240776			ENGELKEN, R. H.	7905040622	50-312	
EBNETER, S. D.	7905020241	50-424		ENGELKEN, R. H.	7905040625	50-397	
EBNETER, S. D.	7905230398	50-424		ENGELKEN, R. H.	7905070098	50-528	
EBNETER, S. D.	7905090226	50-320	SECY-A-78-68	ENGELKEN, R. H.	7905070099	50-133	
EBNETER, S. D.	7905090221	50-320		ENGELKEN, R. H.	7905070102	50-344	
EBNETER, S. D.	7905090225	50-320		ENGELKEN, R. H.	7905070104	50-206	
EBNETER, S. D.	7905090230	50-320		ENGELKEN, R. H.	7905070108	50-312	
EBNETER, S. D.	7905090232	50-320		ENGELKEN, R. H.	7905070110	50-397	
EBNETER, S. D.	7905210062	50-320		ENGELKEN, R. H.	7905030286	50-528	
EBNETER, S. D.	7905190064			ENGELKEN, R. H.	7905030288	50-133	
EBNETER, S. D.	7905110039	50-312		ENGELKEN, R. H.	7905030291	50-275	
EBNETER, S. D.	7905110114	50-312		ENGELKEN, R. H.	7905030293	50-344	
EBNETER, S. D.	7905140287	50-524		ENGELKEN, R. H.	7905030296	50-361	
EBNETER, S. D.	7905150119			ENGELKEN, R. H.	7905030299	50-206	
EBNETER, S. D.	7905230849			ENGELKEN, R. H.	7905030300	50-312	
EBNETER, S. D.	7905240990			ENGELKEN, R. H.	7905030305	50-397	
EBNETER, S. D.	7905140112	50-320		ENGELKEN, R. H.	7905020525	50-528	
EBNETER, S. D.	7905110193	50-320		ENGELKEN, R. H.	7905020527	50-133	
EBNETER, S. D.	7905090219	50-320		ENGELKEN, R. H.	7905020529	50-344	
EBNETER, S. D.	7905040604	50-263		ENGELKEN, R. H.	7905020532	50-206	
EBNETER, S. D.	7905150561	50-443		ENGELKEN, R. H.	7905020535	50-312	
EBNETER, S. D.	7905220090	50-123		ENGELKEN, R. H.	7905020536	50-397	
EBNETER, S. D.	7905140222	50-443		ENGELKEN, R. H.	7905010420	50-528	
EBNETER, S. D.	7905290503						

PERSONAL AUTHOR INDEX

329

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
ENGELKEN, R. H.	7905010422	50-344		FASANO, A. N.	7905300752	50-311	
ENGELKEN, R. H.	7905010425	50-133		FASANO, A. N.	7905270137	50-309	
ENGELKEN, R. H.	7905010434	50-206		FAULKENBERRY, B.	7905150539	50-312	
ENGELKEN, R. H.	7905010437	50-312		FAY, C. W.	7905300493	50-301	
ENGELKEN, R. H.	7905010439	50-397		FAY, E. S.	7905160046	50-320	
ENGELKEN, R. H.	7905080365	50-528		FAZIO, V.	7905100166	50-320	
ENGELKEN, R. H.	7905080366	50-275		FECHYCH, W.	7905090331	50-20	
ENGELKEN, R. H.	7905080368	50-133		FEIT, R.	7905170277		
ENGELKEN, R. H.	7905080369	50-344		FEIT, R.	7905240264		
ENGELKEN, R. H.	7905080371	50-206		FELDMAN, S. M.	7905230124		
ENGELKEN, R. H.	7905080374	50-312		FELTON, J. M.	7905100045	50-320	
ENGELKEN, R. H.	7905080378	50-397		FELTON, J. M.	7905140196	50-320	
ENGELKEN, R. H.	7905010442	50-528		FELTON, J. M.	7905220429	50-320	
ENGELKEN, R. H.	7905010444	50-133		FELTON, J. M.	7905220056		
ENGELKEN, R. H.	7905010445	50-344		FELTON, J. M.	7905020059		
ENGELKEN, R. H.	7905010449	50-206		FELTON, J. M.	7905010660	50-320	
ENGELKEN, R. H.	7905010450	50-312		FELTON, J. M.	7905010024	50-498	
ENGELKEN, R. H.	7905010452	50-397		FELTON, J. M.	7905010657	50-320	
ENGELKEN, R. H.	7904300484	50-320		FELTON, J. M.	7905020052	50-320	
ENGELKEN, R. H.	7905010456	50-528		FELTON, J. M.	7905010652		
ENGELKEN, R. H.	7905010458	50-344		FELTON, J. M.	7905020084		
ENGELKEN, R. H.	7905010460	50-312		FELTON, J. M.	7905020094		
ENGELKEN, R. H.	7905010462	50-206		FELTON, J. M.	7905090034		
ENGELKEN, R. H.	7905010463	50-397		FELTON, J. M.	7905140184		
ENGELKEN, R. H.	7905020227	50-133		FELTON, J. M.	7905090030		
ENGELKEN, R. H.	7905090038	50-528		FELTON, J. M.	7905080031		
ENGELKEN, R. H.	7905090039	50-344		FELTON, J. M.	7905090013		
ENGELKEN, R. H.	7905090041	50-206		FELTON, J. M.	7905140197		
ENGELKEN, R. H.	7905090045	50-312		FELTON, J. M.	7905140102		
ENGELKEN, R. H.	7905090047	50-397		FELTON, J. M.	7905140155	50-115	
ENGELKEN, R. H.	7905020256	50-275		FELTON, J. M.	7905140180		
ENGELKEN, R. H.	7905090053	50-528		FELTON, J. M.	7905140350	50-266	
ENGELKEN, R. H.	7905090054	50-344		FELTON, J. M.	7905140160		
ENGELKEN, R. H.	7905090057	50-206		FELTON, J. M.	7905140525		
ENGELKEN, R. H.	7905090058	50-312		FELTON, J. M.	7905140537	50-320	
ENGELKEN, R. H.	7905090059	50-397		FELTON, J. M.	7905230115	40-2407	
ENGELKEN, R. H.	7905310012	50-361		FELTON, J. M.	7905140509		
ENGELKEN, R. H.	7905040359	50-320		FELTON, J. M.	7905150528		
ENGELKEN, R. H.	7905070025	50-528		FELTON, J. M.	7905230400		
ENGELKEN, R. H.	7905070028	50-344		FELTON, J. M.	7905300389		
ENGELKEN, R. H.	7905070031	50-206		FELTON, J. M.	7905300379	50-320	
ENGELKEN, R. H.	7905070033	50-312		FELTON, J. M.	7905310067	50-320	
ENGELKEN, R. H.	7905070034	50-460		FELTON, J. M.	7905080390	50-259	
ENGELKEN, R. H.	7905040355	50-528		FELTON, J. M.	7905080394	50-259	
ENGELKEN, R. H.	7905070007	50-133		FELTON, J. M.	7905080450	50-321	
ENGELKEN, R. H.	7905070010	50-344		FELTON, J. M.	7905080452	50-321	
ENGELKEN, R. H.	7905070012	50-206		FELTON, J. M.	7905080474	50-302	
ENGELKEN, R. H.	7905070015	50-312		FELTON, J. M.	7905080476	50-302	
ENGELKEN, R. H.	7905070018	50-460		FELTON, J. M.	7905100316	50-250	
ENGELKEN, R. H.	7905170072	50-133		FELTON, J. M.	7905100307	50-250	
ENGELKEN, R. H.	7905310037	50-397		FELTON, J. M.	7905100309	50-335	
ENGELKEN, R. H.	7905310044	50-206		FELTON, J. M.	7905100311	50-335	
ENGELKEN, R. H.	7905310050	50-312		FELTON, J. M.	7905300301	50-250	
ENGELKEN, R. H.	7905310053	50-344		FELTON, J. M.	7905300311	50-250	
ENGELKEN, R. H.	7905310059	50-528		FELTON, J. M.	7905140224	50-445	
ENGELKEN, R. H.	7905240631	50-275		FIKAR, L. F.	7905070466	50-363	
ENGELKEN, R. H.	7905240637	50-460		FINFRACK, I. R.	7905300733	50-219	
ENGELKEN, R. H.	7905090005	50-133		FINFRACK, I. R.	7905070633	50-219	
ENGELKEN, R. H.	7905090115	50-528		FINFRACK, I. R.	7905040478	50-219	
ENGELKEN, R. H.	7905090116	50-344		FINFRACK, I. R.	7905140241	50-219	
ENGELKEN, R. H.	7905090119	50-206		FINFRACK, I. R.	7905150470	50-219	
ENGELKEN, R. H.	7905090120	50-312		FINFRACK, I. R.	7905150275	50-219	
ENGELKEN, R. H.	7905090121	50-397		FINFRACK, I. R.	7905240347	50-219	
ENNIS, E. R.	7905010567	50-290		FINFRACK, I. R.	7905210210	50-219	
EPPERSON, L. M.	7905250512			FINFRACK, I. R.	7905210274	50-219	
ERB, C. M.	7905240748	50-456		FINFRACK, I. R.	7905220381	50-219	
ERLEWINE, J. A.	7905140237	50-280		FINFRACK, I. R.	7905210174	50-219	
ERVIN, A. M.	7905170267	50-260	NEDO-24169A	FINFRACK, I. R.	7905220088	50-219	
ESSIO, T. H.	7905090131	50-282		FINFRACK, I. R.	7905290014	50-219	
ESSIO, T. H.	7905230442	70-1308		FINFRACK, I. R.	7905290023	50-219	
ESSIO, T. H.	7905150820	50-315		FINFRACK, I. R.	7905290164	50-219	
ESSIO, T. H.	7905240454	50-10		FINFRACK, I. R.	7905210265	50-219	
ETHEREDGE, L.	7905300383	50-320		FINFRACK, I. R.	7905210267	50-219	
ETHEREDGE, L.	7905300385	50-320		FINFRACK, I. R.	7905290351	50-219	
ETHERINGTON, H.	7905140031	50-320		FINFRACK, I. R.	7905290394	50-219	
ETHERINGTON, H.	7905140034	50-320		FINFRACK, I. R.	7905290178	50-219	
ETHERINGTON, H.	7905160250			FINFRACK, I. R.	7905290194	50-219	
ETHERINGTON, H.	7905290262			FINFRACK, I. R.	7905290172	50-219	
ETHERINGTON, H.	7905190235	50-320		FINK, J. K.	7905110146		
EVANS, R.	7905300215	50-510		FINKEL, A. E.	7905290132	50-277	
EVANS, D. J.	7905150232	50-389		FINLEY, A. Q.	7905150754	70-1308	
EVANS, D. J.	7905240978	50-348		FINN, J. A.	7905150646	70-1379	
EVANS, D. J.	7905100249	50-348		FIORILLI, G.	7905020521	50-546	
EVANS, D. J.	7905230622	50-250		FIORILLI, G.	7905090386	50-546	
EVANS, D. J.	7905240863			FIORILLI, G.	7905030054	50-373	
EVANS, C. A.	7905230268	50-285		FIORILLI, G.	7905020172	50-329	
EVRAETS, J. C.	7905150730			FIORILLI, G.	7905020461	50-500	
EVRAETS, J. C.	7905230577			FIORILLI, G.	7905040347	50-461	
EWALD, B. C.	7905010207	50-124		FIORILLI, G.	7905230302	50-341	
EWING, J. F.	7905040114	70-27		FIORILLI, G.	7905290048	50-461	
EWING, T. N.	7905250029	50-556		FIORILLI, G.	7905290330	50-329	
EWING, T. N.	7905230424	50-556		FIORILLI, G.	7905080204	50-331	
EWING, T. N.	7905240393	50-556		FIORILLI, G.	7905150410	50-341	
EYBYMONTT, G.	7905110209	50-320		FIORILLI, G.	7905150529	50-358	
EYBYMONTT, G.	7905220445	50-320		FIORILLI, G.	7905250283	50-329	
FAHNER, W. J.	7905090351	50-341		FIORILLI, G.	7905070009	50-358	
FAIN, T. G.	7905290399	50-390	WM28-1-95-101	FIORILLI, G.	7905080024	50-341	
FAINTER, J. W.	7905310111	50-466		FIORILLI, G.	7905240549	50-329	
FAINTER, J. W.	7905140060	50-466		FIORILLI, G.	7905240724	50-329	
FAIRBROTHER, D.	7905030205		BAW-10095 R3	FIORILLI, G.	7905290554	50-153	
FARMER, W. S.	7905080405			FIORILLI, G.	7905290699	50-358	
FARRIS, J. R.	7905290273	50-556		FIORILLI, G.	7905240740	50-456	
FARRIS, J. R.	7905140547	50-556		FIORILLI, G.	7905240711	50-373	
FARRIS, J. R.	7905140550	50-556		FIORILLI, G.	7905140091	50-546	
FARRIS, J. R.	7905240924	50-556		FIORILLI, G.	7905140107	50-358	
FASANO, A. N.	7905040156	50-387		FIORILLI, G.	7905110100	50-346	

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
FIORILLI, O	7905100354	50-346		GAMBLE, D C	7905240632	71-216	
FIORILLI, O	7905110097	50-346		GARCIA, O	7905240256	50-275	
FIORILLI, O	7905110092	50-346		GARN, J	7905250542	40-8698	
FIORILLI, O	7905110089	50-346		GARNETT, H.	7905310397	50-356	
FIORILLI, O	7905250266	50-331		GARNETT, E O	7905300355		
FISCHER, B R	7905190158	50-320		GARNETT, S M	7905250357	50-344	
FISCHER, S	7905230486	50-320		GARNETT, W	7905090134	50-445	
FISHBACK, N	7905230060	50-250		GARY, R. J	7905240196	50-445	
FISHER, W L	7905030046	50-155		GARY, R. J	7905300761	50-445	
FISHER, W L	7905010160	50-266		GARY, R. J	7905290648	50-445	
FISHER, W L	7905230426	50-331		GARY, R. J	7905030365	50-445	
FITZSIMMONS, T R	7905020270	71-6387		GARY, R. J	7905210192	50-445	
FLANNIGAN, R D	7905140336	50-298		GAIVIGAN, F X	7905140521		
FLEISCHAKER, D S	7905030166	50-275		GAIVIGAN, F X	7905230778		
FLEISCHAKER, D S	7905030174	50-275		GAY, O M	7905090154	50-445	
FLEISCHAKER, D S	7905310104	50-275		GAY, O M	7905240115	50-445	
FLEMING, S T	7905040070	50-213		GEHR, A C	7905100002	50-592	
FLINROCK, J R	7905070470	50-363		GEHR, A C.	7905300007	50-275	
FLONWAY, W	7905070462	50-271		GEORGE, H H.	7905130417	50-382	
FLOYD, S D	7905080439	50-261		GEORGE, K. D.	7905010531	50-54	
FLYNN, P.	7905250438	50-329		GEORGE, K. D.	7905010495	50-54	
FLYNN, P.	7905240891	50-329		GERAB, T	7905100163	50-10	
FLYNN, P.	7905240899	50-329		GERETY, H F	7905220362	50-320	
FLYNN, J. D	7905300284	50-358		GETTY, B C	7905140304	50-133	
FOLEY, R. T	7905090417		NUREG/CR-0754	GIBBONS, T D	7905240307	50-327	
FOLEY, T.	7905110394	50-271		GIBBONS, T. D	7905290117	50-395	
FONTANA, L	7905290151	50-382		GIBSON, T	7905160154	50-320	
FORD, D. F.	7905300619			GIBSON, T	7905160184	50-320	
FORD, M R	7905290498		7905290498	GIBSON, T	7905160125	50-320	
FOREMAN, H	7905140565	50-382		GIBSON, T	7905160076	50-320	
FOSTER, H.	7905140321	70-1151		GIBSON, T	7905160110	50-320	
FOSTER, H	7905100419	70-1151		GIBSON, T	7905160003	50-320	
FOSTER, H	7905140315	70-1151		GIBSON, T	7905160049	50-320	
FOSTER, S. C	7905210125	50-255		GIBBS, M E.	7905100147	50-255	
FOSTER, E R	7905150439	50-423		GIBBS, M E	7905250238	50-329	
FOUCHARD, J J	7905230242	50-320		GIBBS, M E	7905250163	50-329	
FOUCHARD, J J	7905020163	50-320		GIBBS, M E	7905290540	50-329	
FOULSHAM, P A	7905290208	50-293		GIBSON, A F	7905290142	50-338	
FOX, H S	7905090314	50-259		GIBSON, C I	7905100243		7905100243
FOX, H S	7905110196	50-296		GIBSON, A	7905190061	50-320	
FOX, H S	7905110313	50-260		GIBSON, A F	7905010207	50-124	
FOX, H S	7905230078	50-260		GIBSON, A F	7905230679	50-339	
FOX, H. S.	7905310362	50-260		GIBSON, A F	7905230623	50-261	
FOX, H S	7905310423	50-296		GIBSON, A F	7905241005	50-25	
FOX, H S	7905310368	50-260		GIBSON, A. F	7905070101	70-1113	
FOX, S	7905160344	50-305		GIEBEKE, J A	7905150140		7905150140
FOX, T D	7905030246		NUREG/CR-0523	GILBERT, R	7905150628	70-820	
FRALEY, R. F	7905140037	50-320		GILBERTSON, L A.	7905250532	70-820	
FRALEY, R F	7905040201	50-10		GILBERT, Y K	7905030205		BAW-10085 R3
FRALEY, R F	7905140014	50-320		GILBERT, L D	7905040098		
FRANKSON, R. S	7905230477	50-466		GILINSKY, V	7905090111	50-382	
FRANKLIN, W. J.	7905230624	50-445		GILINSKY, V	7905110208		
FRANKLIN, W. J.	7905240248	50-498		GILINSKY, V.	7905020024	50-320	
FRANKLIN, W J	7905240824	50-498		GILINSKY, V	7905230220	50-320	
FRANSEN, C. D	7905300523	50-360		GILINSKY, V.	7905110224		
FRANTZ, J. R	7905100104	71-127		GILINSKY, V	7905110253	50-320	
FREEDKIN, S	7905010032			GILINSKY, V	7905110246	50-320	
FREEMAN, M D	7905230056	40-8064		GILINSKY, V	7905110182		
FREEMAN, M D	7905250538	40-8064		GILINSKY, V	7905020046	50-320	
FREIDHEIM, J W	7905300531			GILINSKY, V	7905080070		
FRIEDMAN, L F	7905100374	50-5535		GILINSKY, V.	7905110198	50-320	
FRILINGO, R.	7905230471	50-272		GILINSKY, V.	7905140171	50-320	
FROGGE, J. L	7905150706			GILINSKY, V.	7905140175	50-320	
J. R	7905070647	50-272		GILINSKY, V	7905100020	50-320	
J. K	7905230637	50-267		GILINSKY, V	7905080125	50-320	
J. K	7905030321	50-267		GILINSKY, V.	7905030055	50-320	
IDER, S. P	7905100332	50-592		GILINSKY, V.	7905110179		
	7905150558	50-293		GILINSKY, V.	7905300345	50-320	
	7905150559	50-293		GILINSKY, V.	7905150003		
		50-466		GILINSKY, V.	7905220079		
				GILINSKY, V.	7905290008		
		50-275		GILINSKY, V	7905190233	50-320	
		50-324		GILINSKY, V	7905290003	50-219	
		50-324		GILINSKY, V	7905290031	50-309	
		50-261		GILINSKY, V.	7905190127	50-320	
		50-325		GILLET, W T	7905170252	50-315	
		50-324		GILLET, W T	7905170262	50-316	
		50-324		GILLELAND, J. E.	7905160455	50-327	
		50-325		GILLELAND, J. E.	7905140496	50-327	
		50-325		GILLELAND, J. E.	7905140446	50-327	
		50-325		GILLELAND, J. E.	7905140478	50-518	
		50-325		GILLELAND, J. E.	7905290115		
		50-324		GILLELAND, J E	7905140352	50-327	
		50-261		GILLELAND, J. E.	7905230733	50-566	
		50-261		GILLELAND, J. E.	7905080176	50-259	
		50-261		GILLELAND, J. E.	7905140468	50-327	
		50-261		GILLELAND, J. E.	7905140490	50-390	
		50-324		GILLELAND, J. E.	7905140458	50-327	
		50-325		GILLELAND, J. E.	7905140495	50-327	
		50-27		GILLELAND, J. E.	7905140503	50-390	
				GILLELAND, J E	7905250344	50-259	
		50-267		GILLELAND, J E	7905010481	50-390	
		50-267		GILLELAND, J E	7905010518	50-390	
		50-267		GILLELAND, F. E	7905240972	50-25	
		50-267		GILLELAND, J. E.	7905010564	50-390	
		50-267		GILLELAND, J. E.	7905300745	50-259	
		50-267		GILLELAND, J. E.	7905030343	50-259	
		50-267		GILLELAND, J. E	7905040348	50-390	
		50-463		GILLELAND, J. E.	7905300253	50-327	
				GILLELAND, J. E	7905040345	50-553	
		50-329		GILLELAND, J. E	7905040362	50-327	
		50-556		GILLELAND, J. E	7905010475	50-259	
		50-556		GILLELAND, J. E	7905070420	50-327	
			NUREG/CR-0454	GILLELAND, J. E	7905090333	50-327	
		71-216		GILLELAND, J E	7905090336	50-327	

PERSONAL AUTHOR INDEX

331

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
GILLELAND, J. E.	7905240452	50-259		GOSBICK, L. V.	7905240202		
GILLELAND, J. E.	7905080541	50-318		GOSBICK, L. V.	7905090243	50-320	
GILLELAND, J. E.	7905110177	50-259		GOSBICK, L. V.	7905250089	50-482	
GILLELAND, J. E.	7905110191	50-327		GOSBICK, L. V.	7905290483	50-230	
GILLELAND, J. E.	7905110225	50-390		GOSBICK, L. V.	7905240265	50-275	
GILLELAND, J. E.	7905110228	50-390		GOSBICK, L. V.	7905240334	50-454	
GILLELAND, J. E.	7905090341	50-327		GOSBICK, L. V.	7905240508	50-450	3X
GILLELAND, J. E.	7905110211	50-296		GOSBICK, L. V.	7905160052	50-320	
GILLELAND, J. E.	7905140270	50-553		GOSBICK, L. V.	7905240609	50-219	54
GILLELAND, J. E.	7905140272	50-327		GOUCE, M. J.	7905230753	50-566	50
GILLELAND, J. E.	7905140371	50-259		GOUCE, M. J.	7905230153	50-389	50
GILLELAND, J. E.	7905110008	50-327		GRACE, J. O.	7905150026	71-286	50
GILLELAND, J. E.	7905110024	50-259		GRACE, J. O.	7905150027	71-286	50
GILLELAND, J. E.	7905130322	50-296		GRACE, R. H.	7905010506	50-271	50
GILLELAND, J. E.	7905140317	50-390		GRAHAM, W. E.	7905040599	50-324	50
GILLELAND, J. E.	7905190197	50-327		GRAHAM, W. E.	7905040607	50-324	50
GILLELAND, J. E.	7905130286	50-518		GRAHAM, W. E.	7905140337	50-261	50
GILLELAND, J. E.	7905140303	50-327		GRAHAM, P. D.	7905150523	50-277	50
GILLELAND, J. E.	7905190217	50-390		GRANT, J.	7905230307		50
GILLELAND, J. E.	7905170268	50-260		GRANT, J. S.	7905110099	50-346	50
GILLELAND, J. E.	7905230378	50-260		GRANT, J. S.	7905110091	50-346	50
GILLELAND, J. E.	7905230562	50-327		GRANT, J. S.	7905150121	50-346	50
GILLELAND, J. E.	7905230381	50-390		GRANT, J. S.	7905240097	50-346	50
GILLELAND, J. E.	7905230319	50-327		GRANT, J. S.	7905250198	50-346	50
GILLELAND, J. E.	7905230348	50-438		GRANT, J. S.	7905150402	50-346	50
GILLELAND, J. E.	7905230645	50-327		GRANT, W. B.	7905240454	50-10	50
GILLELAND, J. E.	7905300462	50-318		GRABHAM, T. D.	7905100365	71-305	50
GILLELAND, J. E.	7905290363	50-327		GRABHAM, T. D.	7905100361	71-305	50
GILLELAND, J. E.	7905290390	50-390		GRASSO, E.	7905300647	50-243	
GILLELAND, J. E.	7905310314	50-327		GRAVES, R. H.	7905040061	50-213	
GILLELAND, J. E.	7905300305	50-327		GRAVES, R. H.	7905210211	50-213	50
GILLESPIE, F. P.	7905230641	50-302		GRAVES, R. H.	7905310446	50-213	50
GILLESPIE, F. P.	7905240336	70-1151		GRAY, R.	7905250495	50-546	50
GILLESPIE, F. P.	7905240312	70-1151		GRAY, J. R.	7905100208	50-344	50
GILLESPIE, F. P.	7905230689	70-143		GRAY, J. R.	7905070147	50-344	50
GILLESPIE, F. P.	7905020087	50-269		GRAY, J. R.	7905140013	50-320	50
GILLESPIE, F. P.	7905150116	70-1201		GRAY, J. R.	7905230030	50-344	50
GILLESPIE, F. P.	7905070283	70-1151		GRAY, J. R.	7905160158	50-320	50
GILLESPIE, F. P.	7905300021	70-1201		GRAY, J. R.	7905250148	50-344	50
GILMAN, O.	7905250233	50-338		GRAY, J. R.	7905250153	50-463	50
GILRAY, J.	7905230287	50-320		GRAY, J. R.	7905150114	50-463	50
GILRAY, J.	7905250299			GRAY, J. R.	7905150811	50-344	50
GLAGOLA, A. F.	7905020469			GRAY, J. R.	7905230246	50-463	50
GLAGOLA, A. F.	7905140039			GRAY, J. R.	7905240989	50-548	50
GLAGOLA, A. F.	7905300178			GRAY, J. R.	7905100110	50-548	50
GLAGOLA, A. F.	7905290231			GRAY, J. R.	7905140280	50-324	50
GLAGOLA, A. F.	7905300228			GRAY, J. R.	7905240224	50-344	50
GLAGOLA, A. F.	7905300269			GREENE, T. V.	7905010470	50-366	50
GLAGOLA, A. F.	7905300290			GREENE, T. V.	7905080350	50-321	50
GLICKMAN, D.	7905040299	50-320		GREENE, T. V.	7905150549	50-321	50
GODDARD, R. J.	7905300711	50-295		GREENE, T. V.	7905300638	50-321	50
GODDARD, R. J.	7905230866	50-237		GREENE, T. V.	7905300688	50-321	50
GODDARD, R. J.	7905070154	50-295		GREENE, T. V.	7905300683	50-321	50
GODDARD, R. J.	7905240995	50-295		GREENE, T. V.	7905290120	50-277	50
GODDARD, R. J.	7905250238	50-237		GREENMAN, E. O.	7905150523	50-277	50
GODDARD, R. J.	7905100121	50-295		GREER, R. J.	7905150820	50-315	50
GOSBEL, O. R.	7905090422		NUREQ/CR-0642	GREER, L. R.	7905010160	50-266	50
GOLDBERG, R.	7905100217	50-348		GREER, E.	7905230171	50-320	50
GOLDBERG, S. C.	7905030209	50-338		GRIDLEY, R. L.	7905090275	50-183	50
GOLDBERG, S. C.	7905300722	50-250		GRIDLEY, R. L.	7905160441		50
GOLDBERG, S. C.	7905100137	50-338		GRIER, B. H.	7905300122	50-320	50
GOLDBERG, S. C.	7905240286	50-302		GRIER, B. H.	7905010100	50-293	50
GOLDBERG, S. C.	7905250367	50-295		GRIER, B. H.	7905010101	50-317	50
GOLDBERG, S. C.	7905030207	50-338		GRIER, B. H.	7905010103	50-213	50
GOLDBERG, J. R.	7905020316	50-392		GRIER, B. H.	7905010105	50-334	50
GOLDBERG, J. R.	7905240502	50-592		GRIER, B. H.	7905010106	50-412	50
GOLDBERG, J.	7905100138			GRIER, B. H.	7905010110	50-219	50
GOLDMAN, K.	7905150788	71-9120		GRIER, B. H.	7905010112	50-363	50
GOLDSMITH, R.	7905140136	50-320		GRIER, B. H.	7905010116	50-322	50
GOLDSMITH, R.	7905140132	50-320		GRIER, B. H.	7905010118	50-289	50
GOLDSMITH, R.	7905140129	50-320		GRIER, B. H.	7905010119	50-309	50
GOLDSMITH, R.	7905140134	50-320		GRIER, B. H.	7905010121	50-245	50
GOLDSMITH, R.	7904180377	50-320		GRIER, B. H.	7905010123	50-410	50
GOLDSMITH, R.	7904270088	50-320		GRIER, B. H.	7905010126	50-220	50
GOLDSMITH, R.	7905090231	50-320		GRIER, B. H.	7905010127	50-333	50
GONZALES, B.	7905240078	70-33		GRIER, B. H.	7905010129	50-286	50
GOODHOPE, A. C.	7905240379	27-39		GRIER, B. H.	7905010131	50-277	50
GOODWIN, W. L.	7905020150	70-1151		GRIER, B. H.	7905010134	50-352	50
GOODWIN, C.	7905290078	50-344		GRIER, B. H.	7905010136	50-387	50
GOODWIN, C.	7905150812	50-344		GRIER, B. H.	7905010138	50-272	50
GOODWIN, C.	7905240908	50-344		GRIER, B. H.	7905010140	50-311	50
GOODWIN, C.	7905020478	50-344		GRIER, B. H.	7905010143	50-443	50
GOODWIN, C.	7905030361	50-344		GRIER, B. H.	7905010145	50-485	50
GOODWIN, C.	7905230492	50-344		GRIER, B. H.	7905010148	50-244	50
GOODWIN, C.	7905230407	50-344		GRIER, B. H.	7905010150	50-271	50
GOONEY, M. J.	7905150443	50-277		GRIER, B. H.	7905010152	50-29	50
GOFFEL, M.	7905150047			GRIER, B. H.	7905030266	50-293	50
GOFFEL, M.	7905300727			GRIER, B. H.	7905030270	50-317	50
GOFFEL, M.	7905070042			GRIER, B. H.	7905030272	50-3	50
GORMAN, H. C.	7905150734			GRIER, B. H.	7905030276	50-213	50
GOSBICK, L. V.	7905150679	70-1821		GRIER, B. H.	7905030279	50-286	50
GOSBICK, L. V.	7905300079	50-320		GRIER, B. H.	7905030281	50-29	50
GOSBICK, L. V.	7905300085	50-320		GRIER, B. H.	7905010034	50-293	50
GOSBICK, L. V.	7905300089	50-320		GRIER, B. H.	7905010036	50-317	50
GOSBICK, L. V.	7905190198	50-320		GRIER, B. H.	7905010040	50-213	50
GOSBICK, L. V.	7905300302	50-320		GRIER, B. H.	7905010042	50-334	50
GOSBICK, L. V.	7905140110	50-320		GRIER, B. H.	7905010046	50-219	50
GOSBICK, L. V.	7905020210	50-483		GRIER, B. H.	7905010047	50-289	50
GOSBICK, L. V.	7905140291	50-272		GRIER, B. H.	7905010050	50-309	50
GOSBICK, L. V.	7905010556			GRIER, B. H.	7905010053	50-245	50
GOSBICK, L. V.	7905090260	50-320		GRIER, B. H.	7905010055	50-220	50
GOSBICK, L. V.	7905300100	50-320		GRIER, B. H.	7905010058	50-286	50
GOSBICK, L. V.	7905300103	50-320		GRIER, B. H.	7905010060	50-333	50
GOSBICK, L. V.	7905010041			GRIER, B. H.	7905010063	50-277	50
GOSBICK, L. V.	7905080190			GRIER, B. H.	7905010069	50-272	50
GOSBICK, L. V.	7905230533			GRIER, B. H.	7905010073	50-244	50

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
ORIER, B. H.	7905010073	50-271		ORIER, B. H.	7905040183	50-3	
ORIER, B. H.	7905010077	50-29		ORIER, B. H.	7905040188	50-213	
ORIER, B. H.	7905010080	50-364		ORIER, B. H.	7905040198	50-334	
ORIER, B. H.	7905010082	50-201		ORIER, B. H.	7905040200	50-412	
ORIER, B. H.	7905010086	70-1143		ORIER, B. H.	7905040204	50-219	
ORIER, B. H.	7905010282	50-293		ORIER, B. H.	7905040208	50-322	
ORIER, B. H.	7905010286	50-317		ORIER, B. H.	7905040210	50-289	
ORIER, B. H.	7905010290	50-213		ORIER, B. H.	7905040211	50-309	
ORIER, B. H.	7905010297	50-334		ORIER, B. H.	7905040214	50-336	
ORIER, B. H.	7905010298	50-219		ORIER, B. H.	7905040224	50-245	
ORIER, B. H.	7905010300	50-289		ORIER, B. H.	7905040235	50-410	
ORIER, B. H.	7905010301	50-309		ORIER, B. H.	7905040237	50-220	
ORIER, B. H.	7905010304	50-336		ORIER, B. H.	7905040245	50-286	
ORIER, B. H.	7905010307	50-220		ORIER, B. H.	7905040249	50-333	
ORIER, B. H.	7905010310	50-333		ORIER, B. H.	7905040259	50-277	
ORIER, B. H.	7905010313	50-286		ORIER, B. H.	7905040264	50-352	
ORIER, B. H.	7905010315	50-277		ORIER, B. H.	7905040269	50-387	
ORIER, B. H.	7905010320	50-272		ORIER, B. H.	7905040273	50-272	
ORIER, B. H.	7905010322	50-244		ORIER, B. H.	7905040282	50-311	
ORIER, B. H.	7905010326	50-271		ORIER, B. H.	7905040284	50-443	
ORIER, B. H.	7905010327	50-29		ORIER, B. H.	7905040295	50-485	
ORIER, B. H.	7905190194	50-320		ORIER, B. H.	7905040297	50-271	
ORIER, B. H.	7905190098	50-320		ORIER, B. H.	7905040301	50-29	
ORIER, B. H.	7905210095	50-320		ORIER, B. H.	7905140103	50-272	
ORIER, B. H.	7905210097	50-320		ORIER, B. H.	7905300187	50-320	
ORIER, B. H.	7905210102	50-320		ORIER, B. H.	7905010097	50-3	
ORIER, B. H.	7905020026	50-293		ORIER, B. H.	7905030052	50-293	
ORIER, B. H.	7905020030	50-317		ORIER, B. H.	7905030056	50-317	
ORIER, B. H.	7905020036	50-213		ORIER, B. H.	7905030059	50-213	
ORIER, B. H.	7905020039	50-334		ORIER, B. H.	7905030060	50-334	
ORIER, B. H.	7905020043	50-412		ORIER, B. H.	7905030063	50-412	
ORIER, B. H.	7905020045	50-219		ORIER, B. H.	7905030064	50-219	
ORIER, B. H.	7905020051	50-322		ORIER, B. H.	7905030065	50-363	
ORIER, B. H.	7905020053	50-289		ORIER, B. H.	7905030070	50-322	
ORIER, B. H.	7905020055	50-309		ORIER, B. H.	7905030072	50-289	
ORIER, B. H.	7905020061	50-336		ORIER, B. H.	7905030075	50-309	
ORIER, B. H.	7905020066	50-245		ORIER, B. H.	7905030077	50-245	
ORIER, B. H.	7905020069	50-220		ORIER, B. H.	7905030078	50-220	
ORIER, B. H.	7905020071	50-410		ORIER, B. H.	7905030081	50-410	
ORIER, B. H.	7905020072	50-333		ORIER, B. H.	7905030083	50-333	
ORIER, B. H.	7905020075	50-286		ORIER, B. H.	7905030084	50-286	
ORIER, B. H.	7905020077	50-352		ORIER, B. H.	7905030086	50-352	
ORIER, B. H.	7905020082	50-277		ORIER, B. H.	7905030088	50-277	
ORIER, B. H.	7905020085	50-387		ORIER, B. H.	7905030093	50-387	
ORIER, B. H.	7905020095	50-272		ORIER, B. H.	7905030098	50-272	
ORIER, B. H.	7905020100	50-311		ORIER, B. H.	7905030101	50-311	
ORIER, B. H.	7905020103	50-443		ORIER, B. H.	7905030105	50-443	
ORIER, B. H.	7905020106	50-244		ORIER, B. H.	7905030108	50-244	
ORIER, B. H.	7905020111	50-485		ORIER, B. H.	7905030110	50-485	
ORIER, B. H.	7905020113	50-271		ORIER, B. H.	7905030111	50-271	
ORIER, B. H.	7905020116	50-29		ORIER, B. H.	7905030112	50-29	
ORIER, B. H.	7905210046	50-333		ORIER, B. H.	7905010632	50-293	
ORIER, B. H.	7905020295	50-286		ORIER, B. H.	7905010633	50-317	
ORIER, B. H.	7905020300	50-245		ORIER, B. H.	7905010636	50-3	
ORIER, B. H.	7905020308	50-271		ORIER, B. H.	7905010639	50-247	
ORIER, B. H.	7905020311	50-29		ORIER, B. H.	7905010641	50-213	
ORIER, B. H.	7905020315	50-244		ORIER, B. H.	7905010643	50-334	
ORIER, B. H.	7905020321	50-333		ORIER, B. H.	7905010645	50-412	
ORIER, B. H.	7905020323	50-277		ORIER, B. H.	7905010646	50-219	
ORIER, B. H.	7905020329	50-410		ORIER, B. H.	7905010650	50-363	
ORIER, B. H.	7905020332	50-220		ORIER, B. H.	7905020263	50-322	
ORIER, B. H.	7905020337	50-219		ORIER, B. H.	7905020275	50-289	
ORIER, B. H.	7905020342	50-309		ORIER, B. H.	7905020278	50-309	
ORIER, B. H.	7905020346	50-334		ORIER, B. H.	7905020284	50-245	
ORIER, B. H.	7905020350	50-3		ORIER, B. H.	7905020288	50-220	
ORIER, B. H.	7905020354	50-213		ORIER, B. H.	7905020292	50-410	
ORIER, B. H.	7905020357	50-293		ORIER, B. H.	7905020296	50-333	
ORIER, B. H.	7905020360	50-485		ORIER, B. H.	7905020298	50-286	
ORIER, B. H.	7905020364	50-443		ORIER, B. H.	7905020305	50-352	
ORIER, B. H.	7905020369	50-311		ORIER, B. H.	7905020309	50-277	
ORIER, B. H.	7905020372	50-382		ORIER, B. H.	7905020314	50-387	
ORIER, B. H.	7905020377	50-289		ORIER, B. H.	7905020317	50-272	
ORIER, B. H.	7905020389	50-317		ORIER, B. H.	7905020322	50-311	
ORIER, B. H.	7905020393	50-363		ORIER, B. H.	7905020324	50-443	
ORIER, B. H.	7905020395	50-322		ORIER, B. H.	7905020331	50-485	
ORIER, B. H.	7905020399	50-412		ORIER, B. H.	7905020335	50-244	
ORIER, B. H.	7905020402	50-387		ORIER, B. H.	7905020338	50-271	
ORIER, B. H.	7905030326	50-293		ORIER, B. H.	7905020341	50-29	
ORIER, B. H.	7905030328	50-317		ORIER, B. H.	7905230334	50-320	
ORIER, B. H.	7905030373	50-3		ORIER, B. H.	7905230194	50-320	
ORIER, B. H.	7905040010	50-213		ORIER, B. H.	7905230392	50-3	
ORIER, B. H.	7905040014	50-412		ORIER, B. H.	7905210052	50-320	
ORIER, B. H.	7905040018	50-334		ORIER, B. H.	7905190066	50-219	
ORIER, B. H.	7905040020	50-363		ORIER, B. H.	7905210284	50-320	
ORIER, B. H.	7905040025	50-219		ORIER, B. H.	7905020291	50-302	
ORIER, B. H.	7905040038	50-322		ORIER, B. H.	7905020276	50-302	
ORIER, B. H.	7905040040	50-289		ORIER, B. H.	7905100094	40-2061	
ORIER, B. H.	7905040046	50-309		ORIER, B. H.	7905090171	50-271	
ORIER, B. H.	7905040049	50-336		ORIER, B. H.	7905080239	50-320	
ORIER, B. H.	7905040059	50-245		ORIER, B. H.	7905110231	50-320	
ORIER, B. H.	7905040068	50-410		ORIER, B. H.	7905230523	50-320	
ORIER, B. H.	7905040071	50-220		ORIER, B. H.	7905040150	50-219	
ORIER, B. H.	7905040074	50-333		ORIER, B. H.	7905250456	50-309	
ORIER, B. H.	7905040078	50-286		ORIER, B. H.	7905090330	50-309	
ORIER, B. H.	7905040083	50-352		ORIER, B. H.	7905080435	50-309	
ORIER, B. H.	7905040087	50-277		ORIER, B. H.	7905090061	50-309	
ORIER, B. H.	7905040091	50-387		ORIER, B. H.	7905090372	50-309	
ORIER, B. H.	7905040093	50-311		ORIER, B. H.	7905150434	50-309	
ORIER, B. H.	7905040095	50-272		ORIER, B. H.	7905210137	50-309	
ORIER, B. H.	7905040100	50-443		ORIER, B. H.	7905210130	50-309	
ORIER, B. H.	7905040104	50-485		ORIER, B. H.	7905240656	50-309	
ORIER, B. H.	7905040109	50-244		ORIER, B. H.	7905070455	50-271	
ORIER, B. H.	7905040111	50-271		ORIER, B. H.	7905100319	50-271	
ORIER, B. H.	7905040113	50-29		ORIER, B. H.	7905290088	50-271	
ORIER, B. H.	7905040167	50-293		ORIER, B. H.	7905210177	50-271	
ORIER, B. H.	7905040174	50-317		ORIER, B. H.	7905030333	50-29	

PERSONAL AUTHOR INDEX

333

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
GROCE, R. H.	7905250452	50-29		HANDRAHAN, E.	7905150268	71-33	
GROCE, R. H.	7905040039	50-271		HANDRAHAN, E.	7905150274	71-33	
GROCE, R. H.	7905070948	50-29		HANLEY, H. C.	7905070230	50-502	
GROSS, W. T.	7905020297			HANLEY, H. C.	7905310267	50-502	
GROSSMAN, M. J.	7905080178			HANNON, J. N.	7905240102		
GROTEWIEL, K.	7905150645	50-482		HANNON, J. N.	7905230620	50-325	
GRUSKIN, B. N.	7905030090			HANNON, J. W.	7905150822	50-325	
GUIROIR, D. C.	7905070462	50-271		HANNON, J. W.	7905170260	50-234	
GUMBLE, F. W.	7905010522	50-286		HANSEN, L. J.	7905240497	71-1116	
GUMBLE, F. W.	7905090305	50-286		HANSELL, D.	7905140155	50-1115	
GURN, W. T.	7905110374	50-320		HANSELL, D.	7905150521	27-39	
GURN, W. T.	7905110337	50-320		HANSELL, D.	7905070364	27-39	
GURN, W. T.	7905110370	50-320		HANSEN, R. C.	7905240301	40-8681	
GURN, W. T.	7905110367	50-320		HANSEN, P.	7905020282	50-295	
GURN, W. T.	7905110397	50-320		HANSEN, P. W.	7905100302	50-304	
GURN, W. T.	7905110354	50-320		HANSEN, W. A.	7905250296	50-329	
GURN, W. T.	7905110401	50-320		HANSTOD, A. A.	7905160358	50-282	
GURN, W. T.	7905110397	50-320		HARDIN, A. K.	7905240527	50-346	
GURN, W. T.	7905110395	50-320		HARDWICK, T. J.	7905020352	50-369	
GURN, W. T.	7905110392	50-320		HARRETT, D. J.	7905250120		
GURN, W. T.	7905110393	50-320		HARRETT, D. J.	7905300200		
GURN, W. T.	7905110406	50-320		HARGROVES, D. H.	7905090401		
GURN, W. T.	7905110403	50-320		HARMON, D. W.	7905100264	40-8658	NUREG/CR-0255
GURN, W. T.	7905110405	50-320		HARMON, D. W.	7905180198		
GURN, W. T.	7905110402	50-320		HARMON, D. W.	7905030100		
GURN, W. T.	7905110400	50-320		HARMON, D. W.	7905030092		
GURN, W. T.	7905110396	50-320		HARMON, D. W.	7905290141		
GURN, W. T.	7905110389	50-320		HARMON, D. F.	7905230145	40-2407	
GURN, W. T.	7905110385	50-320		HARMON, D. F.	7905230219	40-2407	
GURN, W. T.	7905110384	50-320		HARMON, D. F.	7905230139	40-2407	
GURN, W. T.	7905110382	50-320		HARMON, D. F.	7905230132	40-2407	
GURN, W. T.	7905110378	50-320		HARPBTER, T. L.	7905110111	50-346	
GURN, W. T.	7905110376	50-320		HARPBTER, T. L.	7905290346	50-263	
GURN, W. T.	7905110373	50-320		HARPBTER, T. L.	7905240729	50-358	
GURN, W. T.	7905110368	50-320		HARRIS, P.	7905240667	50-488	
GURN, W. T.	7905110366	50-320		HARRIS, R.	7905230529	50-346	
GUTTERMAN, A. H.	7905240874	50-318		HARRIS, J. L.	7905300058	50-445	
GUTTMAN, D.	7905240853	50-389		HARRIS, J. L.	7905100288	50-445	
HAAS, P. M.	7905300438	50-320	ORNL/TM-6853	HARRIS, J. L.	7905140070	50-499	
HAAS, W. P.	7905150188			HARRIS, P. B.	7905230473	50-452	
HAAS, W. P.	7905290006	50-29		HARRIS, J. R.	7905240509	50-424	
HAAS, W. P.	7905020482			HARRIS, J. R.	7905070358	50-389	
HAAS, W. P.	7905070660	50-213		HARRIS, J. R.	7905230752	50-491	
HAAS, W. P.	7905070553	50-29		HARTIGAN, J. P.	7905020330	50-346	
HAAS, W. P.	7905240337			HARTIGAN, J. P.	7905020438	50-346	
HAAS, W. P.	7905240411	50-397		HASKIN, F. E.	7905230496	50-320	
HAAS, W. P.	7905240979			HASTINGS, H.	7905270042	50-344	
HAGA, P. B.	7905250313	50-437		HAUGHNEY, C. J.	7905030035	50-201	
HAGA, P. B.	7905040133	50-437		HAUPT, C. A.	7905250091	50-599	
HAGA, P. B.	7905190112	50-437		HAVERKAMP, D.	7905240437	50-289	
HAGA, P. B.	7905220022	50-437		HAWTHORNE, S.	7905090154	50-443	NUREG/CR-0484
HAGA, P. B.	7905310455	50-437		HAWTHORNE, J. R.	7905240925		
HAGAN, T. F.	7905090396			HAYES, D. W.	7905020172	50-329	
HAGAN, T. F.	7905020177			HAYES, D. W.	7905020470	50-500	
HAGEY, H.	7905030180			HAYES, D. W.	7905240734	50-329	
HAGEY, H.	7905030196			HAYES, D. W.	7905150419	50-341	
HAGEY, H.	7905040024			HAYNES, J. O.	7905150374	50-206	
HAGEY, H.	7905040042			HAYNES, J. O.	7905110035	50-206	
HAGEY, H.	7905040064			HAYNES, R. C.	7905150620	50-528	
HAGEY, H.	7905040079			HAYWARD, J.	7905290161	50-1873	
HAGEY, H.	7905240118			HAYWARD, N.	7905250451		
HAGEY, H.	7905240409			HAYLE, A. J.	7905150342		
HAGEY, H.	7905240439			HEAD, J. T.	7905290069	50-206	
HAGEY, H.	7905230697			HEAD, J. T.	7905290500	50-206	
HAGEY, H.	7905240663			HEAD, J. T.	7905240073	50-206	
HAGEY, H.	7905230682			HEAD, J. T.	7905040586	50-206	
HAIGHT, R. F.	7905030231		NUREG/CR-0446	HEAD, J. T.	7905110134	50-206	
HAIRSTON, W. Q.	7905140368	50-348		HEAD, J. T.	7905150503	50-206	
HAIRSTON, W. Q.	7905140357	50-348		HEAD, J. T.	7905310439	50-206	
HAIRSTON, W. Q.	7905150568	50-348		HEDEMAN, W. N.	7905090431		
HAIRSTON, W. Q.	7905020249	50-348		HEIDER, L. H.	7905290058	50-29	
HAIRSTON, W. Q.	7905230362	50-348		HEINEMANN, J. H.	7905100407	40-4602	
HAIRSTON, W. Q.	7905140311	50-348		HEINEMANN, R. E.	7904240392		
HAIRSTON, W. Q.	7905300904	50-348		HEISHMAN, R. F.	7905290536	50-263	
HALE, C. J.	7905030130			HEISHMAN, R. F.	7905020202	50-315	
HALE, C. J.	7905100366			HEISHMAN, R. F.	7905080084	50-255	
HALE, C. J.	7905290113			HEISHMAN, R. F.	7905010333	50-155	
HALE, C. J.	7905100418			HEISHMAN, R. F.	7905070020	50-373	
HALE, C. J.	7905230593			HEISHMAN, R. F.	7905090165	50-331	
HALL, W. C.	7904240395			HEISHMAN, R. F.	7905090173	50-409	
HALL, W. C.	7904240389			HEISHMAN, R. F.	7905150159	50-156	
HALL, W. C.	7905240608	71-5026		HEISHMAN, R. F.	7905150126	50-331	
HALL, T. H.	7905030231		NUREG/CR-0446	HEISHMAN, R. F.	7905240719	50-358	
HALL, E. E.	7905030268	50-395		HEISHMAN, R. F.	7905140084	50-295	
HALL, R. E.	7905240320	50-286	7905240320	HEISHMAN, R. F.	7905090167	50-255	
HALL, R. E.	7905160415	50-254		HEISHMAN, R. F.	7905040161	50-294	
HALL, R. E.	7905300466	50-266		HEISHMAN, R. F.	7905150113	50-346	
HALL, R. E.	7905070495			HEISHMAN, R. F.	7905150152	50-315	
HALL, D. B.	7905140567	50-250		HELBISH, J. F.	7905090320	50-320	
HALL, R. E.	7905190870	50-556		HELLER, L. H.	7905100093	50-553	
HALL, R. E.	7905010312	50-482		HELLER, L. H.	7905240249	50-452	
HALL, R. E.	7905010383	50-498		HELLMS, J.	7905250131	50-269	
HALLER, N. M.	7905140073	50-320		HELYMES, C. J.	7905100117	50-584	
HALLMAN, E. L.	7905300196	50-320		HENDERSON, O. K.	7905250511		
HAMMER, B. J.	7905080438	50-263		HENDRICK, W. G.	7905310069		
HAMMOND, E. L.	7905020291	50-331		HENDRICK, W. G.	7905310074		
HAMMOND, E. L.	7905160363	50-331		HENDRIE, J. M.	7905250169		
HAMMOND, E. L.	7905160386	50-311		HENDRIE, J. M.	7905140165		
HAMMOND, E. L.	7905210220	50-331		HENDRIE, J. M.	7905140169		
HAMMOND, E. L.	7905290182	50-331		HENDRIE, J. M.	7905140174		
HAN, B.	7905140128			HENDRIE, J. M.	7905150010		
HANAUER, S. H.	7905210094			HENDRIE, J. M.	7905250321		
HANAUER, S. H.	7905110316	50-320		HENDRIE, J. M.	7905290465		
HANAUER, S. H.	7905110385	50-320		HENDRIE, J. M.	7905090111		
HANAUER, S. H.	7905140187			HENDRIE, J. M.	7905090259	50-320	
HAND, C. H.	7905100186	50-369		HENDRIE, J. M.	7905170270	50-320	

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
HENDRIE, J. M.	7903020024	50-320		HIGGENBOTHAM, L.	7903210060	50-320	
HENDRIE, J. M.	7903110197	50-320		HIGGINS, J. C.	7903240437	50-289	
HENDRIE, J. M.	7903110230	50-320		HILL, R. H.	7903250463		
HENDRIE, J. M.	7903210044	50-320		HILLYARD, H. W.	7903140294	50-267	
HENDRIE, J. M.	7903090413			HILLYARD, H. W.	7903140323	50-267	
HENDRIE, J. M.	7903230792	50-309		HIMMELSBACH, L.	7903160159	50-320	
HENDRIE, J. M.	7903020046	50-320		HINCKLEY, D. G.	7903250110	50-321	
HENDRIE, J. M.	7903100016	50-320		HIND, J. A.	7903110047	50-182	
HENDRIE, J. M.	7903110190	50-320		HIND, J. A.	7903160488	50-116	
HENDRIE, J. M.	7903140020	50-320		HIND, J. A.	7903150775	50-295	
HENDRIE, J. M.	7903020038			HIND, J. A.	7903150297	70-1308	
HENDRIE, J. M.	7903140258	50-320		HIND, J. A.	7903150744	70-1308	
HENDRIE, J. M.	7903030460			HIND, J. A.	7903150754	70-1308	
HENDRIE, J. M.	7903030055	50-320		HIND, J. A.	7903150768	50-295	
HENDRIE, J. M.	7903100028			HIND, J. A.	7903250206	50-10	
HENDRIE, J. M.	7903110220	50-320		HINDERSTEIN, C.	7903240360	50-466	
HENDRIE, J. M.	7903110005			HINDERSTEIN, C.	7903150087	50-466	
HENDRIE, J. M.	7903250195	50-596		HINDERSTEIN, C.	7903250130	50-466	
HENDRIE, J. M.	7903130003			HINDERSTEIN, C.	7903310042	50-466	
HENDRIE, J. M.	7903250167			HINDERSTEIN, C.	7903310077	50-466	
HENDRIE, J. M.	7903300563			HINDERSTEIN, C.	7903310080	50-466	
HENDRIE, J. M.	7903300594			HINZE, W. J.	7903240326		NUREG-0382
HENDRIE, J. M.	7903300604			HITT, R. E.	7903150098		
HENDRIE, J. M.	7903300525			HITTLE, L. G.	7903300429	50-344	
HENDRIE, J. M.	7903300444			HJELMPFELT, D. C.	7903100217	50-348	
HENDRIE, J. M.	7903300377			KLUCHAN, R. H.	7903240954	50-272	
HENDRIE, J. M.	7903220079			KODALEY, S. D.	7903300332		
HENDRIE, J. M.	7903290008			KODALEY, S.	7903300339		
HENDRIE, J. M.	7903300568	50-309		KODALEY, S.	7903140570	50-219	NUREG/CR-0634
HENDRIE, J. M.	7903300672			KODER, C. J.	7903110223	50-320	
HENDRIE, J. M.	7903300681	50-309		KODDER, H. H.	7903290289	50-389	
HENDRIE, J. M.	7903190233	50-320		KODDOR, A.	7903110202	50-320	
HENDRIE, J. M.	7903290003	50-219		KODDOR, A.	7903110235	50-32	
HENDRIE, J. M.	7903290031	50-309		KODDOR, A.	7903110212	50-320	
HENDRIE, J. M.	7903300515			KODDOR, A.	7903110249	50-320	
HENDRIE, J. M.	7903090236	50-320		KODGES, J. W.	7903230689	70-143	
HENDRIE, J. M.	7903300076	50-320		KODGES, J. W.	7903070283	70-1151	
HENDRIE, J. M.	7903300094	50-320		KODGES, M. W.	7903070086		
HENDRIE, J. M.	7903300101	50-320		KODGES, M.	7903250113		
HENDRIE, J. M.	7903300103	50-320		KOEFLING, R. K.	7903090438	70-2623	
HENDRIE, J. M.	7903300107	50-320		KOEFLING, R. K.	7903090440	70-2623	
HENDRIE, J. M.	7903300115	50-320		KOEFLING, R. K.	7903230766	70-2623	
HENDRIE, J. M.	7903300119	50-320		KOEFLING, R. K.	7903230775	70-2623	
HENDRIE, J. M.	7903300120	50-320		KOEFLING, R. K.	7903310028	50-329	
HENDRIE, J. M.	7903300123	50-320		KOEFLING, R. K.	7903080053	50-322	
HENDRIE, J. M.	7903300124	50-320		KOEFLING, R. K.	7903230053	50-322	
HENDRIE, J. M.	7903300126	50-320		KOFFMAN, H. C.	7903230384	50-189	
HENDRIE, J. M.	7903300128	50-320		KOFFMAN, D. P.	7903090172	50-255	
HENDRIE, J. M.	7903300131	50-320		KOFFMAN, D. P.	7903240309	50-255	
HENDRIE, J. M.	7903300134	50-320		KOFFMAN, D. P.	7903310098	50-155	
HENDRIE, J. M.	7903300135	50-320		KOFFMAN, D. P.	7903040386	50-255	
HENDRIE, J. M.	7903300137	50-320		KOFFMAN, D. P.	7903230364	50-255	
HENDRIE, J. M.	7903300139	50-320		KOFFMAN, D. P.	7903080937	50-255	
HENDRIE, J. M.	7903300144	50-320		KOFFMAN, D. P.	7903100249	50-255	
HENDRIE, J. M.	7903300562			KOFFMAN, D. P.	7903100253	50-255	
HENDRIE, J. M.	7903190127	50-320		KOFFMAN, D. P.	7903110085	50-255	
HENDRIE, J. M.	7903300495			KOFFMAN, D. P.	7903140211	50-155	
HENDRIE, J. M.	7903300645	50-245		KOFFMAN, D. P.	7903150309	50-255	
HENDRIE, J. M.	7903300652			KOFFMAN, D. P.	7903150615	50-255	
HENDRIE, J. M.	7903300325	50-320		KOFFMAN, D. P.	7903210150	50-255	
HENNESSEY, R. J.	7903020033	50-280		KOFFMAN, D. P.	7903220020	50-255	
HENNESSEY, R. J.	7903300026	50-338		KOFFMAN, D. P.	7903220329	50-255	
HENRY, R. E.	7903090406		NUREG/CR-0728	KOFFMAN, D. P.	7903220340	50-255	
HENRY, J.	7903160068	50-320		KOFFMAN, D. P.	7903210163	50-155	
HENSBLEY, K. D.	7903100423	70-143		KOFFMAN, D. P.	7903230052	50-255	
HERBEIN, J. G.	7903230024	50-320		KOFFMAN, D. P.	7903230093	50-255	
HERBEIN, J. G.	7903110149	50-320		KOFFMAN, K. R.	7903140575		NUREG/CR-0645
HERBEIN, J. G.	7903110173	50-289		KOFFMAN, K. R.	7903140576		NUREG/CR-0646
HERBEIN, J. G.	7903160141	50-320		KOHENBOKEN, P.	7903080151	50-237	
HERBEIN, J. G.	7903190209	50-320		HOLLAND, P.	7903140324	50-249	
HERBEIN, J. G.	7903190169	50-320		HOLLY, J. T.	7903100292	50-305	
HERBEIN, J. G.	7903190229	50-320		HOLM, W. H.	7903230540		
HERBEIN, J. G.	7903190231	50-320		HOLMAN, J. J.	7903300289		
HERBEIN, J. G.	7903190236	50-320		HOLDWAY, C. F.	7903240587		7903240587
HERBEIN, J. G.	7903190215	50-320		HOOD, D. S.	7903290415	50-329	
HERBEIN, J. G.	7903020294	50-289		HOOPER, F. F.	7903290583	50-395	
HERBEIN, J. G.	7903020468	50-320		HOOPER, F. F.	7903140016	50-522	
HERBEIN, J. G.	7903160135	50-320		HOSFORD, S.	7903080051		NUREG-0484
HERBEIN, J. G.	7903230005	50-320		HOUZHAN, T. J.	7903030233		
HERBEIN, J. G.	7903080445	50-289		HOUZHAN, T. J.	7903150803		
HERBEIN, J. G.	7903080542	50-289		HOWARD, M.	7903190196	50-320	
HERBEIN, J. G.	7903070587	50-289		HOWE, P. W.	7903080330	50-400	
HERBEIN, J. G.	7903080521	50-320		HOWE, P. W.	7903250015	50-400	
HERBEIN, J. G.	7903090337	50-320		HOWELL, S. H.	7903140219	50-329	
HERBEIN, J. G.	7903290350	50-289		HOWELL, S. H.	7903030308	50-329	
HERBEIN, J. G.	7903140282	50-289		HOWELL, S. H.	7903030358	50-329	
HERBEIN, J. G.	7903220318	50-289		HOWELL, S. H.	7903030362	50-329	
HERBEIN, J. G.	7903190115	50-320		HOWELL, S. H.	7903090082	50-329	
HERBEIN, J. G.	7903220371	50-289		HOWELL, S. H.	7903030327	50-329	
HERBEIN, J. G.	7903230375	50-289		HOWELL, S. H.	7903080532	50-329	
HERBEIN, J. G.	7903240558	50-289		HOWELL, S. H.	7903250526	50-329	
HERDT, A. R.	7903070118	50-281		HOWELL, S.	7903300252	50-329	
HERDT, A. R.	7903230753	50-566		HOWELL, S. H.	7903300478	50-329	
HERDT, A. R.	7903230169	50-339		HOWELL, J. C.	7903130775	50-295	
HERDT, A. R.	7903230153	50-389		HOWLETT, G. H.	7903150505	50-336	
HERDT, A. R.	7903150081	50-518		HOYLE, J. C.	7903090014		
HERDT, A. R.	7903240468	50-395		HOYLE, J. C.	7903090018		
HERDT, A. R.	7903240507	50-518		HOYLE, J. C.	7903140248		
HERDT, A. R.	7903250020	50-400		HOYLE, J. C.	7903150066		
HERDT, A. R.	7903150805	50-390		HOYLE, J. C.	7903090276		
HERSCH, M. H.	7903240577			HOYLE, J. C.	7903090266		
HERSLOFF, L. M.	7903070111			HOYLE, J. C.	7903090267		
HEUBNER, A. T.	7903250494			HOYLE, J. C.	7903110379		
HIATT, J. M.	7903010160	50-266		HOYLE, J. C.	7903110379		FRN-790314
HIATT, J. M.	7903230426	50-331		HOYLE, J. C.	7903140237		
HICKLE, B. J.	7903140240	50-285		HOYLE, J. C.	7903090270		

PERSONAL AUTHOR INDEX

335

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
HOYLE, J. C.	7905090023			JOHNSTON, O. W.	7905150339	50-312	
HOYLE, J. C.	7905090028			JOHNSON, D. H.	7905140054	50-320	
HOYT, W. B.	7905150732	50-201		JOHNSON, L.	7905230204		
HUBACEK, W. G.	7905010383	50-498		JOLAN, D. B.	7904300328		
HUBACEK, W. G.	7905150970	50-556		JOLMERUD, J. H.	7905250453		
HUCKABEE, K. W.	7905290463	71-297		JONES, L. L.	7905290151	50-382	
HUCKABEE, K. W.	7905290469	71-297		JONES, O. L.	7905250515		
HUDSON, O. R.	7905100032			JONES, W. C.	7905140487	50-285	
HUGHAM, J. W.	7905070084	50-327		JONES, D. C.	7905240389		7905240389
HUGHES, J.	7905150419	50-341		JONES, D. C.	7905240415		7905240415
HUGHES, J.	7905290720	50-358		JONES, J. G.	7905300098	50-320	
HUMPHREYS, L. L.	7905230808	50-458		JONES, D. H.	7905040124	70-27	
HUMPHREYS, L. L.	7905150453	50-458		JONES, D. W.	7905150116	70-1201	
HUNNICUTT, D. M.	7905150797			JONES, C. E.	7905020470	50-500	
HUNSTAD, A. A.	7905010311	50-282		JOSTEN, J. K.	7905240355	50-304	
HUNSTAD, A. A.	7905030367	50-282		JORDAN, E. D.	7905010547	50-77	
HUNSTAD, A. A.	7905150499	50-282		JORDAN, E. D.	7905010539	50-77	
HUNSTAD, A. A.	7905080569	50-282		JORDAN, W.	7905140565	50-282	
HUNSTAD, A. A.	7905110131	50-282		JORDAN, E. L.	7905100445	50-346	
HUNSTAD, A. A.	7905150468	50-282		JORDAN, E. L.	7905250231		
HUNSTAD, A. A.	7905220118	50-306		JORDAN, E. L.	7905290162	50-255	
HUNTER, R.	7905020088			JORGENSEN, B. L.	7905080093	50-255	
HUNTER, L. W.	7905170279		TR-39	JOSEPH, P.	7905220061	50-592	
HUNTER, L. W.	7905170282		TR-40	JOYNER, J. H.	7905220052	70-135	
HUNTER, L. W.	7905230448	50-445		JOYNER, J. H.	7905110036	70-820	
HUNTER, V. H.	7905110404			JOYNER, J. H.	7905230288	70-33	
HURLEY, J.	7905150255	50-574		JOYNER, J. H.	7905240784	70-135	
HUTTON, P. H.	7905240113		7905240113	JUDD, J. C.	7905220023		
HYMAN, C. R.	7905140572		NUREG/CR-0539	JUDD, J. C.	7905220039	50-225	
ISER, H. W.	7905230306			JUDD, O.	7905250044	50-309	
IPPOLITO, T. A.	7905090183	50-366		JUDD, H. T.	7905250046	50-309	
IPPOLITO, T. A.	7905090186	50-331		JULIAN, C. A.	7905240480	50-124	
IPPOLITO, T. A.	7905090189	50-366		JUSTICE, R. L.	7905040261		
IPPOLITO, T. A.	7905300398	50-271		JUTRAS, R.	7905070411	50-220	
IPPOLITO, T. A.	7905080246	50-333		KAFIN, R. J.	7905240098	50-596	
IPPOLITO, T. A.	7905300067	50-10		KAFIN, R. J.	7905240106	50-596	
IPPOLITO, T. A.	7905080141	50-237		KAHLE, J. B.	7905290099	70-1113	
IPPOLITO, T. A.	7905150089	50-321		KALIVITANAKIS, N.	7905100296	50-254	
IPPOLITO, T. A.	7905090196	50-331		KALIVITANAKIS, N.	7905090369	50-254	
IPPOLITO, T. A.	7905090199	50-331		KALIVITANAKIS, N.	7905240678	50-265	
IPPOLITO, T. A.	7905090201	50-331		KALIVITANAKIS, N.	7905240702	50-265	
IPPOLITO, T. A.	7905150108	50-324		KALIVITANAKIS, N.	7905240691	50-265	
IPPOLITO, T. A.	7905110001	50-298		KALIVITANAKIS, N.	7905240597	50-254	
IPPOLITO, T. A.	7905110002	50-298		KALIVITANAKIS, N.	7905170230	50-254	
IPPOLITO, T. A.	7905110003	50-298		KALMAN, O.	7905290173	50-244	
IPPOLITO, T. A.	7905250430	50-250		KAMMERER, C.	7905090264	50-522	
IRVING, B. M.	7905290300	50-382		KAMMERER, C.	7905160225	50-320	
ISCOE, D.	7905240178	50-466		KAMMERER, C.	7905160035	50-320	
ISCOE, C.	7905240190	50-466		KAMMERER, C.	7905100012	50-320	
JABLON, R. A.	7905150234	50-250		KAMMERER, C.	7905100159	50-320	
JABLON, R. A.	7905150729	50-250		KAMMERER, C.	7905100212	50-320	
JABLON, R. A.	7905150733	50-250		KAMMERER, C.	7905100218	50-320	
JABLON, R. A.	7905240853	50-389		KAMMERER, C.	7905160025	50-320	
JABLON, R. A.	7905140151	50-445		KAMMERER, C.	7905160027	50-320	
JACK, O. C.	7905150588			KAMMERER, C.	7905300307	50-320	
JACK, O. C.	7905150611			KAMMERER, C.	7905100043	50-320	
JACK, I. H.	7905150134	50-331		KAMMERER, C.	7905100049	50-251	
JACKSON, C.	7905250334	71-161		KAMMERER, C.	7905100051	50-320	
JACKSON, C.	7905250366	71-161		KAMMERER, C.	7905100061	50-320	
JACKSON, F. D.	7905020222	40-4492		KAMMERER, C.	7905100091	50-320	
JACKSON, F. D.	7905070032	40-4492		KAMMERER, C.	7905100136	50-320	
JACKSON, F. D.	7905240444	40-4492		KAMMERER, C.	7905100176	50-320	
JACKSON, L. L.	7905241003	50-25		KAMMERER, C.	7905100198	50-320	
JACKSON, L. L.	7905241003			KAMMERER, C.	7905160040	50-320	
JACOBS, T. J.	7905300487			KAMMERER, C.	7905160041	50-320	
JACOBS, S. B.	7905040615	50-280		KAMMERER, C.	7905160051	50-320	
JAMES, D. K.	7905150249	50-335		KAMMERER, C.	7905100181	50-320	
JAMES, D. K.	7905220128	50-250		KAMMERER, C.	7905160044	50-320	
JAMES, D. K.	7905250392	50-250		KAMMERER, C.	7905100206	50-320	
JAMECEK, R. F.	7905250324	50-10		KAMMERER, C.	7905160023	50-320	
JAMECEK, R. F.	7905010526	50-254		KAMMERER, C.	7905160146	50-320	
JAMECEK, R. F.	7905040603	50-237		KAMMERER, C.	7905140098	50-320	
JAMECEK, R. F.	7905090370	50-10		KAMMERER, C.	7905160021	50-320	
JAMECEK, R. F.	7905140273	50-10		KAMMERER, C.	7905160152	50-320	
JAMECEK, R. F.	7905140276	50-249		KAPLAN, S. N.	7905210178	50-224	
JAMECEK, R. F.	7905190097	50-237		KAPLAN, A. L.	7905290087	70-1113	
JAMECEK, R. F.	7905250533	50-254		KAPLAN, A. L.	7905150791	70-1113	
JAMECEK, R. F.	7905310364	50-237		KAPLAN, A. L.	7905240600	70-1113	
JANIS, J. T.	7905100436	50-312		KAPLAN, A. L.	7905070091	70-1113	
JANSEN, T.	7905300705	50-249		KAPLAN, A. L.	7905240811	70-1113	
JANUSKA, A. O.	7905150646	70-1379		KAPLAN, A. L.	7905220025	70-1113	
JASKE, R. T.	7905250525			KAPLAN, C. H.	7905030080	50-327	
JENNINGS, H. D.	7905090056	50-339		KAPPLE, A. W.	7905140230	50-272	
JENNINGS, G. R.	7905230679	50-338		KAPPLE, A. W.	7905010553	50-272	
JENNINGS, G. R.	7905230623	50-261		KAPPLE, A. W.	7905040541	50-272	
JENNEKENS, J. H.	7905110369	50-320		KAPPLE, A. W.	7905040371	50-272	
JENNINGS, D. W.	7905240462	50-62		KAPPLE, A. W.	7905080525	50-272	
JENS, W. H.	7905070442			KAPPLE, A. W.	7905130446	50-272	
JOHN, D. F.	7905250488	50-445		KAPPLE, A. W.	7905130464	50-272	
JOHN, D. F.	7905230448	50-445		KAPPLE, A. W.	7905220132	50-272	
JOHNSON, B. L.	7905100290	50-305		KAPPLE, A. W.	7905220314	50-272	
JOHNSON, W. J.	7905150282	50-592		KARRASCH, B. A.	7905140028	50-320	
JOHNSON, W. P.	7905040514	50-309		KASPERSKI, D. C.	7905070382		
JOHNSON, W. P.	7905250159	50-309		KASPERSKI, D. C.	7905250485		
JOHNSON, R. G.	7905230394	50-263		KASPERSKI, D. C.	7905250482		
JOHNSON, R. G.	7905290093	50-263		KATO, W. Y.	7905190219	50-320	
JOHNSON, R. W.	7905300188	50-344		KAUFMAN, N.	7905110417	50-3	
JOHNSON, R. W.	7905180722	50-344		KAHULA, L.	7905230367	50-320	
JOHNSON, R. W.	7905240948	50-344		KEATEN, R. W.	7905190089	70-2236	
JOHNSON, H. G.	7905090420	50-395		KEENAN, R. P.	7905290135		
JOHNSON, H. G.	7905010483	50-395		KEENAN, R. P.	7905240119		
JOHNSON, H. G.	7905290108	50-395		KEENAN, R. P.	7905240123		
JOHNSON, D.	7905080110	50-286		KEENAN, R. P.	7905240367	50-77	
JOHNSON, A. H.	7905090139	50-338		KEENE, W. E.	7905010547	40-8681	
JOHNSON, E. H.	7905150604	50-188		KEENE, J. P.	7905240425		
JOHNSON, J. M.	7905150585						

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
KEENEY, H P	7905160058	71-5795		KEPPLER, J O	7905010263	50-546	
KEEPING, W	7905240148	50-596		KEPPLER, J O	7905010267	50-346	
KEHOE, D	7905070210	50-247		KEPPLER, J O	7905010268	50-483	
KEILMAN, T J	7905020235	71-77		KEPPLER, J O	7905010270	50-266	
KEILMAN, T J	7905020299	71-77		KEPPLER, J O	7905010273	50-303	
KEIMIO, R R	7905300192	50-320		KEPPLER, J O	7905090195	50-409	
KEIMIO, R R	7905240437	50-289		KEPPLER, J O	7905030370	50-10	
KEIMIO, R R	7905090146	50-213		KEPPLER, J O	7905030372	50-358	
KEIMIO, R R	7905080110	50-286		KEPPLER, J O	7905040021	50-440	
KEIMIO, R R	7905110371	50-247		KEPPLER, J O	7905040026	50-153	
KEIMIO, R R	7905270173	50-244		KEPPLER, J O	7905040027	50-409	
KEIMIO, R R	7905190175	50-320		KEPPLER, J O	7905040030	50-341	
KEIMIO, R R	7905290157	50-334		KEPPLER, J O	7905040031	50-331	
KELBER, C	7905110387	50-320		KEPPLER, J O	7905040035	50-461	
KELLEY, C R	7905240326		NUREG-0382	KEPPLER, J O	7905040037	50-315	
KELLEY, P J	7905300334	50-338		KEPPLER, J O	7905040041	50-367	
KELLEY, D L	7905150310	50-285		KEPPLER, J O	7905040045	50-484	
KELLEY, J L	7905090235	50-320	SECY-A-78-10	KEPPLER, J O	7905040048	50-263	
KELLEY, J L	7905090246	50-320	SECY-A-78-34	KEPPLER, J O	7905040051	50-546	
KELLEY, J L	7905090222	50-320	SECY-A-78-47	KEPPLER, J O	7905040055	50-346	
KELLEY, J L	7905230470			KEPPLER, J O	7905040058	50-483	
KELLOOG, P J	7905210314	50-320		KEPPLER, J O	7905040060	50-266	
KELLOOG, P J	7905140210	50-317		KEPPLER, J O	7905040065	50-305	
KELLOOG, P J	7905230503	50-249		KEPPLER, J O	7905080529	50-329	
KELLOOG, P J	7905090056	50-339		KEPPLER, J O	7905150424	50-331	
KELLY, R B	7905190200			KEPPLER, J O	7905010155	50-10	
KELLY, W D	7905150585			KEPPLER, J O	7905010162	50-135	
KELLY, J B	7905140200			KEPPLER, J O	7905010165	50-407	
KENDALL, M C	7905140158			KEPPLER, J O	7905010167	50-331	
KENDRICK, J R	7905250290	50-427		KEPPLER, J O	7905010171	50-315	
KENNA, W B	7905240361	70-143		KEPPLER, J O	7905010174	50-263	
KENNA, W B	7905240352	70-143		KEPPLER, J O	7905010176	50-346	
KENNA, W B	7905020078	50-249		KEPPLER, J O	7905010181	50-266	
KENNA, W B	7905040118	70-27		KEPPLER, J O	7905010186	50-305	
KENNA, W B	7905020433	70-143		KEPPLER, J O	7905010191	70-8	
KENNA, W B	7905240054	50-335		KEPPLER, J O	7905010197	70-1193	
KENNA, W B	7905020156	70-1151		KEPPLER, J O	7905010384	50-10	
KENNA, W B	7905230632	50-302		KEPPLER, J O	7905010390	50-153	
KENNA, W B	7905230684	70-143		KEPPLER, J O	7905010394	50-409	
KENNA, W B	7905070252	70-1201		KEPPLER, J O	7905010398	50-331	
KENNA, W B	7905240323	70-1151		KEPPLER, J O	7905010404	50-315	
KENNA, W B	7905240295	70-1151		KEPPLER, J O	7905010410	50-263	
KENNA, W B	7905040105	70-27		KEPPLER, J O	7905010413	50-346	
KENNA, W B	7905020025	50-280		KEPPLER, J O	7905010417	50-266	
KENNA, W B	7905020048	50-269		KEPPLER, J O	7905240933	50-346	
KENNA, W B	7905020146	70-1151		KEPPLER, J O	7905030006	50-315	
KENNA, W B	7905020417	70-143		KEPPLER, J O	7905030007	50-295	
KENNA, W B	7905150112	70-1201		KEPPLER, J O	7905030013	50-10	
KENNA, W B	7905230628	50-302		KEPPLER, J O	7905030017	50-358	
KENNA, W B	7905070240	70-1201		KEPPLER, J O	7905030019	50-440	
KENNA, W B	7905070269	70-1151		KEPPLER, J O	7905030022	50-329	
KENNA, W B	7905030016	70-1201		KEPPLER, J O	7905030023	50-255	
KENNA, W B	7905030023	50-338		KEPPLER, J O	7905030025	50-155	
KENNEDY, W J	7905070446	50-495		KEPPLER, J O	7905030026	50-409	
KENNEDY, W J	7905140245	50-280		KEPPLER, J O	7905030029	50-341	
KENNEDY, W J	7905140382	50-280		KEPPLER, J O	7905030031	50-331	
KENNEDY, W J	7905160335	50-280		KEPPLER, J O	7905030033	50-461	
KENNEDY, W J	7905210111	50-280		KEPPLER, J O	7905030036	50-367	
KENNEDY, W J	7905290335	50-280		KEPPLER, J O	7905030040	50-282	
KENNEDY, R W	7905210154	50-302		KEPPLER, J O	7905030047	50-484	
KENNEDY, R T	7905090111			KEPPLER, J O	7905030049	50-546	
KENNEDY, R T	7905030096	50-320		KEPPLER, J O	7905030053	50-346	
KENNEDY, R T	7905020024	50-320		KEPPLER, J O	7905030058	50-483	
KENNEDY, R T	7905230220	50-320		KEPPLER, J O	7905030062	50-266	
KENNEDY, R T	7905020046	50-320		KEPPLER, J O	7905030069	50-305	
KENNEDY, R T	7905080070			KEPPLER, J O	7905190076	50-320	
KENNEDY, R T	7905100020	50-320		KEPPLER, J O	7905100162	50-16	
KENNEDY, R T	7905160132	50-320		KEPPLER, J O	7905010569	50-10	
KENNEDY, R T	7905160142	50-320		KEPPLER, J O	7905010572	50-295	
KENNEDY, R T	7905080125	50-320		KEPPLER, J O	7905010574	50-358	
KENNEDY, R T	7905160079	50-320		KEPPLER, J O	7905010576	50-440	
KENNEDY, R T	7905030055	50-320		KEPPLER, J O	7905010579	50-135	
KENNEDY, R T	7905160144	50-320		KEPPLER, J O	7905010583	50-329	
KENNEDY, R T	7905160175	50-320		KEPPLER, J O	7905010585	50-409	
KENNEDY, R T	7905190003			KEPPLER, J O	7905010586	50-341	
KENNEDY, R T	7905220079			KEPPLER, J O	7905010588	50-331	
KENNEDY, R T	7905290068			KEPPLER, J O	7905010590	50-461	
KENNEDY, R T	7905190233	50-320		KEPPLER, J O	7905010592	50-315	
KENNEDY, R T	7905290003	50-219		KEPPLER, J O	7905010593	50-367	
KENNEDY, R T	7905290031	50-309		KEPPLER, J O	7905010597	50-484	
KENNEDY, R T	7905190127	50-320		KEPPLER, J O	7905010599	50-263	
KENNEKE, A.	7905090257	50-320		KEPPLER, J O	7905010600	50-282	
KENNEKE, A.	7905090233	50-320		KEPPLER, J O	7905010602	50-546	
KENNEKE, A.	7905090239	50-320		KEPPLER, J O	7905010604	50-346	
KENNEKE, A.	7905090258	50-320		KEPPLER, J O	7905010610	50-483	
KENNEKE, A.	7905090234	50-320		KEPPLER, J O	7905010613	50-266	
KENNEKE, A.	7905090212	50-320		KEPPLER, J O	7905010615	50-305	
KENNINGTON, O. S	7905070037	40-4492		KEPPLER, J O	7905040324	50-255	
KENT, B.	7905160031	50-320		KEPPLER, J O	7905040328	50-155	
KENT, B.	7905160047	50-320		KEPPLER, J O	7905040331	50-329	
KEPFORD, C. P.	7905140519	50-320		KEPPLER, J O	7905040334	50-10	
KEPPLER, J O	7905290183	70-1379		KEPPLER, J O	7905040331	50-358	
KEPPLER, J O	7905020166	50-329		KEPPLER, J O	7905040382	50-440	
KEPPLER, J O	7905010233	50-315		KEPPLER, J O	7905040384	50-409	
KEPPLER, J O	7905010236	50-10		KEPPLER, J O	7905040387	50-341	
KEPPLER, J O	7905010242	50-358		KEPPLER, J O	7905040389	50-331	
KEPPLER, J O	7905010244	50-440		KEPPLER, J O	7905040394	50-461	
KEPPLER, J O	7905010247	50-135		KEPPLER, J O	7905040398	50-367	
KEPPLER, J O	7905010249	50-329		KEPPLER, J O	7905040405	50-263	
KEPPLER, J O	7905010251	50-409		KEPPLER, J O	7905040418	50-484	
KEPPLER, J O	7905010253	50-341		KEPPLER, J O	7905040425	50-346	
KEPPLER, J O	7905010256	50-331		KEPPLER, J O	7905040427	50-483	
KEPPLER, J O	7905010257	50-461		KEPPLER, J O	7905040428	50-266	
KEPPLER, J O	7905010258	50-367		KEPPLER, J O	7905040431	50-305	
KEPPLER, J O	7905010261	50-484		KEPPLER, J O	7905040434	50-331	
KEPPLER, J O	7905010262	50-263		KEPPLER, J O	7905040435		

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
KEPPLER, J. Q.	7905040438	50-266		KIDDS, N. B.	7905010275	50-338	
KEPPLER, J. Q.	7905040440	50-407		KILINGER, Q.	7905140067	50-320	
KEPPLER, J. Q.	7905040443	50-305		KILLOUGH, Q. Q.	7905230788		7905230788
KEPPLER, J. Q.	7905040445	50-484		KINO, R. B.	7905250508		
KEPPLER, J. Q.	7905040451	50-263		KINO, B.	7905150199		
KEPPLER, J. Q.	7905040452	50-358		KINNEY, W.	7905230516	50-320	
KEPPLER, J. Q.	7905040456	50-315		KINTIGH, A. E.	7905220120	50-596	
KEPPLER, J. Q.	7905040459	50-461		KINTIGH, A. E.	7905310342	50-596	
KEPPLER, J. Q.	7905040460	50-341		KINTIGH, A. E.	7905300477	50-596	
KEPPLER, J. Q.	7905040461	50-483		KINTNER, L. L.	7905150630	50-341	
KEPPLER, J. Q.	7905040465	50-327		KIRK, W. F.	7905290059	70-371	
KEPPLER, J. Q.	7905040522	50-313		KIRKSCY, K. A.	7905240540		7905240540
KEPPLER, J. Q.	7905040527	50-295		KISTER, H. B.	7905070182	50-286	
KEPPLER, J. Q.	7905040529	50-10		KISTER, H. B.	7905070158	50-272	
KEPPLER, J. Q.	7905040534	50-358		KISTER, H. B.	7905070210	50-247	
KEPPLER, J. Q.	7905040537	50-440		KISTER, H. B.	7905290166	50-336	
KEPPLER, J. Q.	7905040546	50-329		KISTER, H. B.	7905290126	50-334	
KEPPLER, J. Q.	7905040548	50-255		KISTER, H. B.	7905290145	50-245	
KEPPLER, J. Q.	7905040550	50-155		KLINGER, Q.	7905100375	50-346	
KEPPLER, J. Q.	7905040553	50-409		KLINGER, Q. R.	7905110009	50-312	
KEPPLER, J. Q.	7905040556	50-341		KNIGHTON, Q. H.	7905110123	50-320	
KEPPLER, J. Q.	7905040560	50-331		KNIGHTON, Q.	7905230326	50-320	
KEPPLER, J. Q.	7905040566	50-461		KNOP, R. C.	7905110111	50-346	
KEPPLER, J. Q.	7905040568	50-367		KNOP, R. C.	7905090393	50-846	
KEPPLER, J. Q.	7905040576	50-263		KNOP, R. C.	7905030074	50-373	
KEPPLER, J. Q.	7905040587	50-484		KNOP, R. C.	7905020470	50-500	
KEPPLER, J. Q.	7905040589	50-346		KNOP, R. C.	7905290720	50-358	
KEPPLER, J. Q.	7905040591	50-346		KNOP, R. C.	7905250296	50-329	
KEPPLER, J. Q.	7905040595	50-483		KNOTT, H.	7905020286	50-312	
KEPPLER, J. Q.	7905040598	50-266		KNOTT, J. B.	7905100228	50-445	
KEPPLER, J. Q.	7905040600	50-305		KNOTT, J. B.	7905150821	50-445	
KEPPLER, J. Q.	7905070162	50-155		KNOTT, J. B.	7905090036	50-445	
KEPPLER, J. Q.	7905070164	50-367		KNOTT, J. B.	7905090042	50-445	
KEPPLER, J. Q.	7905070167	50-346		KNOTT, J. B.	7905090050		
KEPPLER, J. Q.	7905070170	50-440		KNOW, R. C.	7905100362	50-346	
KEPPLER, J. Q.	7905070174	50-346		KOCH, L. J.	7905290563	50-461	
KEPPLER, J. Q.	7905170089	50-315		KOCHER, D. C.	7905230788		7905230788
KEPPLER, J. Q.	7905010380	50-373		KOCHER, D. C.	7905030142		NUREQ/CR-0494
KEPPLER, J. Q.	7905010387	50-329		KOESTER, Q. L.	7905300626	50-482	
KEPPLER, J. Q.	7905010396	50-440		KOESTER, Q. L.	7905080514	50-482	
KEPPLER, J. Q.	7905010400	50-358		KOESTER, Q. L.	7905110311	50-482	
KEPPLER, J. Q.	7905010405	50-483		KOESTER, Q. L.	7905290326	50-482	
KEPPLER, J. Q.	7905010411	50-346		KOHLER, R.	7905250477		
KEPPLER, J. Q.	7905010415	50-341		KOLTAY, P. B.	7905100433	50-387	
KEPPLER, J. Q.	7905010419	50-484		KOLTAY, P. B.	7905290132	50-277	
KEPPLER, J. Q.	7905010426	50-461		KOPLAN, A. L.	7905140309	70-1113	
KEPPLER, J. Q.	7905010429	50-367		KORNBLITH, L.	7905230540	50-272	
KEPPLER, J. Q.	7905030204	50-315		KORNBLITH, L.	7905140568	50-272	
KEPPLER, J. Q.	7905030206	50-10		KORNBLITH, L.	7905140561	50-272	
KEPPLER, J. Q.	7905030215	50-358		KORNBLITH, L.	7905140558	50-272	
KEPPLER, J. Q.	7905030217	50-440		KORNBLITH, L.	7905230563	50-310	
KEPPLER, J. Q.	7905030219	50-329		KORNBLITH, L.	7905250070	50-310	
KEPPLER, J. Q.	7905030220	50-155		KOSBI, R. E.	7905190072	50-320	
KEPPLER, J. Q.	7905030222	50-409		KOSIK, L. B.	7905150227	50-358	
KEPPLER, J. Q.	7905030224	50-341		KOSIK, L. B.	7905150212	50-358	
KEPPLER, J. Q.	7905030227	50-331		KOSIK, L. B.	7905150221	50-358	
KEPPLER, J. Q.	7905030228	50-461		KOSIK, L. B.	7905140156	50-358	
KEPPLER, J. Q.	7905030232	50-367		KOSIK, L. B.	7905140157	50-358	
KEPPLER, J. Q.	7905030235	50-484		KOSIK, L. B.	7905140369	50-358	
KEPPLER, J. Q.	7905030237	50-263		KOSIK, L. B.	7905010223	50-358	
KEPPLER, J. Q.	7905030241	50-346		KOSIK, L. B.	7905290464	50-358	
KEPPLER, J. Q.	7905030245	50-346		KOSIK, L. B.	7905240104	50-358	
KEPPLER, J. Q.	7905030249	50-483		KOSB, R. R.	7905250496		
KEPPLER, J. Q.	7905030253	50-266		KORTHAYER, P. H.	7905240626	50-219	
KEPPLER, J. Q.	7905030255	50-305		KOUTS, H. J.	7905150219		NUREQ/CR-0513
KEPPLER, J. Q.	7905010380	50-455		KOUTS, H. J.	7904300253		WCAP-9402 (NP)
KEPPLER, J. Q.	7905040368	50-358		KRAMER, F. W.	7905110098		
KEPPLER, J. Q.	7905140534	50-266		KRAMER, A.	7905140284	50-320	
KEPPLER, J. Q.	7905040142	50-10		KRAMER, J. F.	7905240616	71-110	
KEPPLER, J. Q.	7905080397	50-358		KRAMER, A.	7905100050	50-320	
KEPPLER, J. Q.	7905080400	50-440		KREGER, W. E.	7905150139		7905240556
KEPPLER, J. Q.	7905080404	50-329		KREGER, T. B.	7905240556		
KEPPLER, J. Q.	7905080486	50-155		KRISTOVICH, B.	7905030174	50-275	
KEPPLER, J. Q.	7905080490	50-409		KRISTOVICH, B.	7905310104	50-275	
KEPPLER, J. Q.	7905080492	50-341		KRODT, I.	7905030209	50-338	
KEPPLER, J. Q.	7905080496	50-331		KUHN, W. G.	7905140065	50-320	
KEPPLER, J. Q.	7905080498	50-461		KURTZ, R. J.	7905240113		7905240113
KEPPLER, J. Q.	7905080499	50-315		KUSHNER, W. L.	7905240784	70-135	
KEPPLER, J. Q.	7905080502	50-367		KUSHNER, W. L.	7905220092	70-135	
KEPPLER, J. Q.	7905080503	50-484		KUSSIE, R. R.	7905230417	50-244	
KEPPLER, J. Q.	7905080505	50-263		KUZMYCZ, G.	7905010179	50-267	
KEPPLER, J. Q.	7905080507	50-346		LADUN, R. H.	7905240287	50-225	
KEPPLER, J. Q.	7905080509	50-346		LAFLEUR, J. D.	7905160150	50-320	
KEPPLER, J. Q.	7905080512	50-483		LAFLEUR, J. D.	7905160093	50-320	
KEPPLER, J. Q.	7905080515	50-266		LAFLEUR, J. D.	7905160156	50-320	
KEPPLER, J. Q.	7905080519	50-305		LAFLEUR, J. D.	7905160196	50-320	
KEPPLER, J. Q.	7905150355	50-155		LAFLEUR, J. D.	7905160153	50-320	
KEPPLER, J. Q.	7905140488	50-10		LAFLEUR, J. D.	7905160165	50-320	
KEPPLER, J. Q.	7905240887	50-358		LAFLEUR, J. D.	7905160012	50-320	
KEPPLER, J. Q.	7905240892	50-440		LAFLEUR, J. D.	7905160211	50-320	
KEPPLER, J. Q.	7905240893	50-155		LAFLEUR, J. D.	7905160011	50-320	
KEPPLER, J. Q.	7905240896	50-409		LAFLEUR, J. D.	7905160204	50-320	
KEPPLER, J. Q.	7905240898	50-341		LAFLEUR, J. D.	7905160010	50-320	
KEPPLER, J. Q.	7905240902	50-331		LAFLEUR, J. D.	7905160178	50-320	
KEPPLER, J. Q.	7905240906	50-461		LAFLEUR, J. D.	7905160055	50-320	
KEPPLER, J. Q.	7905240907	50-367		LAFLEUR, J. D.	7905160214	50-320	
KEPPLER, J. Q.	7905310466	50-315		LAFLEUR, J. D.	7905090242	50-320	
KERR, H.	7905230402	50-2		LAFLEUR, J. D.	7905160009	50-320	
KERR, G. W.	7905250038			LAFLEUR, J. D.	7905160181	50-320	
KETCHEN, E. Q.	7905300044	50-275		LAFLEUR, J. D.	7905160066	50-320	
KETCHEN, E. Q.	7905030103	70-2623		LAFLEUR, J. D.	7905160188	50-320	
KETCHEN, E. Q.	7905030116	70-2623		LAFLEUR, J. D.	7905160004	50-320	
KETCHEN, E. Q.	7905030120	70-2623		LAFLEUR, J. D.	7905160195	50-320	
KETCHEN, E. Q.	7905100157	50-275		LAFLEUR, J. D.	7905090245	50-320	
KEY, W. J.	7905080211	50-331		LAFLEUR, J. D.	7905300370	50-320	
KEY, W. J.	7905150436	50-331		LAFLEUR, J. D.	7905300407	50-320	

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
LAFLEUR, J. D.	7905140001	50-320		LEWIS, M. I.	7905250487		
LAFLEUR, J. D.	7905300420	50-320		LEWIS, M.	7905290181		
LAFLEUR, J. D.	7905300369	50-320		LEWIS, M.	7905290187		
LAFLEUR, J. D.	7905300365			LEWIS, R.	7905240251	50-443	
LAFLEUR, J. D.	7905300424	50-320		LEWIS, J. R.	7905290410	70-364	
LAFLEUR, J. D.	7905300359			LEWIS, L.	7905040247		
LAFLEUR, J. D.	7905300410	50-320		LEWIS, S. R.	7905080527	50-287	
LAFLEUR, J. D.	7905300356	50-320		LEWIS, S. R.	7905020340	50-269	
LAFLEUR, J. D.	7905300415	50-320		LEWIS, S. R.	7905230305	50-269	
LAINAS, G. C.	7905230041	50-320		LEWIS, S. R.	7905250408	50-269	
LAINAS, G.	7905300718			LEWIS, S. R.	7905250427	50-269	
LAINAS, G.	7905110130	50-320		LEWIS, S. R.	7905310410	50-287	
LAINAS, G.	7905110133	50-320		LEWIS, S. H.	7905230841	50-349	
LAINAS, G.	7905150798	50-335		LEWIS, S. H.	7905080401	50-482	
LAINAS, G.	7905240302	50-206		LEWIS, S. H.	7905140194	50-261	
LAINAS, G.	7905240253	50-336		LEWIS, S. H.	7905250039	50-286	
LAINAS, G.	7905240471	50-303		LEWIS, S. H.	7905040131	50-482	
LAINAS, G. C.	7905240731	50-255		LEWIS, S. H.	7905070134	50-549	
LAMB, J. C.	7905140568	50-272		LEWIS, S. H.	7905240603	50-261	
LAMB, J. C.	7905140561	50-272		LEWIS, S. H.	7905240771	50-261	
LAMB, J. C.	7905140558	50-272		LEWIS, S. H.	7905110418	50-320	
LAMPKA, J. V.	7905130229			LEWIS, S. H.	7905300367	50-549	
LANTZ, P. H.	7905240587		7905240587	LEWIS, R. C.	7905290167	50-335	
LAGOMARSINO, R.	7905240273	50-273		LEWIS, R. C.	7905230229	50-324	
LARKINS, J. T.	7905110259	50-320		LEWIS, R. C.	7905020040	50-280	
LARSON, J. R.	7905080109		TFBP-TR-209	LEWIS, R. C.	7905230482	50-269	
LARSON, L. K.	7905150074	50-485		LEWIS, R. C.	7905020012	50-280	
LAWRENCE, M.	7905290081	71-322		LEWIS, R. C.	7905010465	50-324	
LAWRENCE, M.	7905290084	71-322		LEWIS, R. C.	7905020412	50-369	
LAWROSKI, S.	7905140164			LEWIS, R. C.	7905010255	50-338	
LAWROSKI, S.	7905230476	50-320		LEWIS, R. C.	7905010466	50-395	
LAWROSKI, S.	7905230480	50-320		LEWIS, R. C.	7905230583	50-261	
LAWROSKI, N.	7905230471	50-320		LEWIS, R. C.	7905090051	50-339	
LAWROSKI, S.	7905030161			LEWIS, R. C.	7905250105	50-321	
LAWROSKI, S.	7905140019			LEWIS, R. C.	7905290707	50-369	
LAWROSKI, H.	7905230443	50-320		LEWIS, R. C.	7905020458	50-339	
LAWYER, S.	7905220438	50-320		LEWIS, R. C.	7905020489	50-321	
LAYFIELD, R. L.	7905230280	40-2407		LEWIS, R. C.	7905090129	50-338	
LAYFIELD, R. L.	7905230270	40-2407		LEWIS, R. C.	7905130138	50-259	
LAYFIELD, R. L.	7905230255	40-2407		LEWIS, R. C.	7905130251	50-250	
LAYFIELD, R. L.	7905230250	40-2407		LEWIS, R. C.	7905230396	50-302	
LAZARUS, W. J.	7905090146	50-213		LEWIS, R. C.	7905210047	50-320	
LAZO, R. M.	7905090178	50-592		LEWIS, R. C.	7905240474	50-124	
LAZO, R. M.	7905290576	50-369		LEWIS, R. C.	7905240483	50-327	
LAZO, R. M.	7905100186	50-369		LEWIS, R. C.	7905240523	50-348	
LAZSON, L. K.	7905230497	50-485		LEWIS, R. C.	7905240530	50-339	
LEASE, R. S.	7905150438	50-315		LEWIS, R. C.	7905230209	50-324	
LEBERSTEIN, J. H.	7905040472	50-280	VEP-FRD-32	LEWIS, R. C.	7905250173	50-369	
LEBO, C. D.	7905240107			LEWIS, R. C.	7905250381	50-302	
LEBO, C. D.	7905300182			LI, R. H.	7905070213		
LEBO, C. D.	7905300247			LIBARKIN, M. H.	7905140022	50-320	
LEBO, C. D.	7905240787			LIBARKIN, M. H.	7905140013	50-320	
LEE, B.	7905250069			LIBRIZZI, F. P.	7905030360	50-272	
LEE, B.	7905030366	50-10		LIBRIZZI, F. P.	7905010529	50-272	
LEE, E. W.	7905040349	50-461		LIBRIZZI, F. P.	7905040538	50-272	
LEE, T. T.	7905300561			LIBRIZZI, F. P.	7905040370	50-272	
LEE, T. D.	7905020439	70-143		LIBRIZZI, F. P.	7905080485	50-272	
LEE, W. S.	7905010530	50-269		LIBRIZZI, R. P.	7905140227	50-272	
LEE, W. S.	7905020283	50-269		LIBRIZZI, R. P.	7905170263	50-272	
LEECH, P. H.	7905090211	50-522		LIBRIZZI, F. P.	7905150280	50-272	
LEEDS	7905140564	50-329		LIBRIZZI, F. P.	7905150444	50-272	
LEDEL, R. A.	7905160380	50-320		LIBRIZZI, F. P.	7905150462	50-272	
LEHMAN, W.	7905220100	50-250		LIBRIZZI, F. P.	7905220127	50-272	
LEHMAN, W.	7905290486	50-250		LIBRIZZI, R. P.	7905220308	50-272	
LEHMAN, W.	7905240864	50-250		LICHTENBERGER, H.	7905240269	70-1100	
LEHPOEB, T. E.	7905300486	50-220		LICHTENBERGER, H.	7905250013	71-90	
LEHMAN, J. J.	7905090426	50-395		LICITRA, E. A.	7905090180	50-592	
LEONARD, J. D.	7905010584	50-333		LICITRA, E. A.	7905230731	50-482	
LEONARD, J. D.	7905290162	50-333		LICITRA, E. A.	7905230858	50-482	
LEONARD, J. D.	7905240290	50-333		LICITRA, E. A.	7905240869	50-498	
LEONARD, J. D.	7905010499	50-333		LIKE, I.	7905240234	50-322	
LEONARD, J. D.	7905010503	50-333		LINBLAD, W. J.	7905090433		
LEONARD, J. D.	7905290194	50-333		LINDER, C.	7905080556	50-249	
LEONARD, J. D.	7905110254	50-333		LINDER, F.	7905020238	50-409	
LEONARD, J. D.	7905130475	50-333		LINDER, F.	7905290336	50-409	
LEONARD, J. D.	7905300411	50-333		LINDER, F.	7905010504	50-409	
LEONARD, J. D.	7905300506	50-333		LINDER, F.	7905020243	50-409	
LEONARD, J. D.	7905300522	50-333		LINDER, F.	7905240516	50-409	
LEONARD, J. D.	7905140335	50-298		LINDER, F.	7905040373	50-409	
LEONARD, J. D.	7905180522	50-298		LINDER, F.	7905090043	50-409	
LEONARD, J. D.	7905100586	50-445		LINDER, F.	7905090382	50-409	
LEONARD, J. D.	7905240967	50-445		LINDER, F.	7905240698	50-409	
LEONARD, J. D.	7905250129	50-445		LINDER, F.	7905140231	50-409	
LEONARD, J. D.	7905100106	50-445		LINDER, F.	7905130517	50-409	
LEONARD, J. D.	7905250191	50-498		LINDER, F.	7905160425	50-409	
LEONARD, J. D.	7905090430			LINDER, F.	7905250404	50-409	
LEONARD, J. D.	7905010860			LINDER, F.	7905220401	50-409	
LEONARD, J. D.	7905100021		7905100021	LINDER, F.	7905290086	50-409	
LEONARD, J. D.	7905230413			LINDER, F.	7905290417	50-409	
LEONARD, J. D.	7905230425			LINDER, F.	7905300012	50-409	
LEONARD, J. D.	7905230453			LINDER, F.	7905300314	50-409	
LEONARD, J. D.	7905230441			LINDER, F.	7905110303	50-409	
LEONARD, J. D.	7905240316		7905240316	LINDER, F.	7905170293	50-409	
LEONARD, J. D.	7905220043		7905220043	LINDNER, T. P.	7905170283		
LEONARD, J. D.	7905230741		7905230741	LINDNER, T. P.	7905170288		
LEONARD, J. D.	7905160083	50-320		LINDNER, T. P.	7905170280		
LEONARD, J. D.	7905110285	50-320		LINDNER, T. P.	7905170289		
LEONARD, J. D.	7905110248	50-320		LINDNER, T. P.	7905150105		
LEONARD, J. D.	7904170091			LINDNER, T. P.	7905240325		
LEONARD, J. D.	7905100336	50-471		LINEHAN, J. J.	7905150616	40-6659	
LEONARD, J. D.	7905240233	50-471		LINEHAN, J. J.	7905150613	40-299	
LEONARD, J. D.	7905250455			LINEHAN, J. J.	7905150624	40-8584	
LEONARD, J. D.	7905250457			LINENBERGER, O. A.	7905290583	50-395	
LEONARD, J. D.	7905240446			LINENBERGER, O. A.	7905230182	50-466	
LEONARD, J. D.	7905250498			LINENBERGER, O. A.	7905140016	50-522	
LEONARD, J. D.	7905230736	50-466		LING, J.	7905080219		

PERSONAL AUTHOR INDEX

339

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
LINGENFELTER, J	7905150456	50-346	45-79/HI24AF	HACDONALD, C E	7905110210	71-116	7905150777
LINKER, H	7905250224	50-3		HACDONALD, C E	7905240565	71-70	
LIOU, C P	7905250530	50-329		HACDONALD, C E	7905240974	71-241	
LIPINSKI, R J	7905110267	50-320		HACDONALD, C E	7905241000	71-109	
LITTLE, L M	7905240579	27-39		HACDONALD, C E	7905290255	71-261	
LITTLE, L W	7905230563	50-510		HACDONALD, C E	7905070075	71-6144	
LITTLE, L W	7905250070	50-510		HACDONALD, C E	7905070081	71-6144	
LITTLE, W B	7905090169	50-331		HACDONALD, C E	7905070302	71-6272	
LITTLE, W S	7905140087	50-295		HACDONALD, C E	7905070307	71-6272	
LITTLE, W S	7905110094	50-346		HACDONALD, C E	7905070290	71-6771	
LITTLE, W S	7905180163	50-156		HACDONALD, C E	7905070295	71-6771	
LIU, L	7905100400	71-296		HACDONALD, C E	7905090089	71-6744	
LIU, L	7905110163	50-331		HACDONALD, C E	7905240017	71-4986	
LIU, L	7905130090	50-331		HACDONALD, C E	7905240020	71-4986	
LIU, L	7905300272	50-331		HACDONALD, C E	7905240036	71-6400	
LIU, L	7905040491	50-331		HACDONALD, C E	7905240039	71-6400	
LIU, L	7905080469	50-331		HACDONALD, C E	7905240128	71-6273	
LIU, L	7905090368	50-331		HACDONALD, C E	7905250305	71-6679	
LIU, LEE	7905080465	50-331		HACDONALD, C E	7905250316	71-6679	
LIU, L	7905230522	50-331		HACDONALD, C E	7905290096	71-231	
LIU, L	7905310447	50-331		HACDONALD, C E	7905100167	71-238	
LIVINGSTON, R L	7905130035	50-320	7905020151	HACDONALD, C E	7905100342	71-235	
LIVINGSTON, B	7905240330	50-255		HACDONALD, C E	7905100347	71-235	
LLOYD, D E	7905110298	50-134		HACDONALD, C E	7905100352	71-237	
LLOYD, R D	7905140361	50-346		HACDONALD, C E	7905110063	71-136	
LOCHBETTER, M A	7905300130	40-8698		HACDONALD, C E	7905110065	71-209	
LOCHBETTER, M A	7905100403	50-320		HACDONALD, C E	7905110067	71-214	
LONDON, E J	7905020151			HACDONALD, C E	7905110069	71-72	
LONG, R L	7905190121	50-320		HACDONALD, C E	7905110071	71-74	
LONG, R L	7905230082	50-320		HACDONALD, C E	7905110075	71-111	
LONG, J	7904270399	50-320		HACDONALD, C E	7905110078	71-120	
LOOMIS, T	7905010648			HACDONALD, C E	7905110081	71-128	
LOSS, F J	7905110033			HACDONALD, C E	7905110084	71-141	
LOTTES, P A	7905130099			HACDONALD, C E	7905110095	71-181	
LOTZ, J B	7905230733	50-466		HACDONALD, C E	7905140119	71-131	
LOWE, V P	7905180479	50-77		HACDONALD, C E	7905150149	71-31	
LOMERRE, R W	7905310111	50-466		HACDONALD, C E	7905150157	71-108	
LOMERRE, R W	7905140060	50-466		HACDONALD, C E	7905150160	71-66	
LU, T	7905230010	50-320		HACDONALD, C E	7905150169	71-189	
LUCIA, O	7905110409	50-272		HACDONALD, C E	7905150176	71-48	
LUCIA, O	7905230233	50-272		HACDONALD, C E	7905240041	71-2	
LUEBKE, E A	7905100186	50-369	7905110033 7905150099	HACDONALD, C E	7905240046	71-24	7905150777
LUEBKE	7905140564	50-329		HACDONALD, C E	7905240099	71-9506	
LUNDVALL, A E	7905110118	50-317		HACDONALD, C E	7905240140	71-39	
LUNDVALL, A E	7905290712	50-317		HACDONALD, C E	7905240136	71-121	
LUNDVALL, A E	7905300742	50-317		HACDONALD, C E	7905240161	71-143	
LUNDVALL, A E	7905090049	50-317		HACDONALD, C E	7905240165	71-77	
LUTON, E	7905300032	50-456		HACDONALD, C E	7905240382	71-65	
LUTON, E	7905090187	50-454		HACDONALD, C E	7905230066	71-234	
LUTON, E	7905100327	50-471		HACDONALD, C E	7905230219	71-6058	
LUTON, E	7905150243	50-295		HACDONALD, C E	7905230226	71-6058	
LUTON, E	7905290268			HACDONALD, C E	7905240833	71-266	
LYON, J H	7905290633	50-471		HACDONALD, C E	7905240845	71-266	
LYON, H D	7905130607	50-397		HACDONALD, C E	7905240847	71-8	
MACARTHUR, T G	7905070084	50-327		HACDONALD, C E	7905240854	71-8	
HACDONALD, C E	7905100340	71-215		HACDONALD, C E	7905250331	71-6386	
HACDONALD, C E	7905180318	71-50		HACDONALD, C E	7905250346	71-6386	
HACDONALD, C E	7905130323	71-50		HACDONALD, C E	7905180576	71-9010	
HACDONALD, C E	7905180329	71-38		HACDONALD, C E	7905240244	71-9070	
HACDONALD, C E	7905180333	71-38		HACDONALD, C E	7905240331	71-68	
HACDONALD, C E	7905170278	71-1		HACDONALD, C E	7905240318	71-68	
HACDONALD, C E	7905230691	71-5790		HACDONALD, C E	7905240834	71-169	
HACDONALD, C E	7905070047	71-6058		HACDONALD, C E	7905240839	71-169	
HACDONALD, C E	7904200311	71-110		HACDONALD, C E	7905290041	71-9009	
HACDONALD, C E	7905020170	71-9852		HACDONALD, C E	7905290046	71-9009	
HACDONALD, C E	7905250227	71-217		HACDONALD, C E	7905240327	71-6697	
HACDONALD, C E	7905130723	71-296		HACDONALD, C E	7905240331	71-6697	
HACDONALD, C E	7905020185	71-6		HACDONALD, C E	7905230847	71-5805	
HACDONALD, C E	7905020407	71-88		HACQUINEA, D B	7905100196	50-348	
HACDONALD, C E	7905070228	71-277	7905150777	MACKIN, J	7905240542		7905150777
HACDONALD, C E	7905240109	71-5364		MACKLIN, L	7905230066	71-9120	
HACDONALD, C E	7905240112	71-6244		MACHILLAN, J H	7905100391		
HACDONALD, C E	7905100169	71-167		MACHILLAN, J H	7905300391	50-320	
HACDONALD, C E	7905100185	71-162		MAGRAE, C F	7905090398	50-285	
HACDONALD, C E	7905020191	71-239		MAGRAE, C F	7905310243	50-285	
HACDONALD, C E	7905020193	71-226		MADERA, T J	7905110047	50-182	
HACDONALD, C E	7905020196	71-225		MADIA, H J	7905150777		
HACDONALD, C E	7905020198	71-34		MADISON, B R	7905250080	50-549	
HACDONALD, C E	7905020376	71-220		MADISON, H R	7905190193	50-338	
HACDONALD, C E	7905020384	71-216		MADSEN, O L	7905010529	50-313	
HACDONALD, C E	7905020386	71-213		MADSEN, O L	7905010530	50-298	
HACDONALD, C E	7905020392	71-180		MADSEN, O L	7905010533	50-285	
HACDONALD, C E	7905020394	71-175		MADSEN, O L	7905010538	50-267	
HACDONALD, C E	7905020399	71-178		MADSEN, O L	7905010539	50-313	
HACDONALD, C E	7905070257	71-119		MADSEN, O L	7905010544	50-298	
HACDONALD, C E	7905070267	71-89		MADSEN, O L	7905010546	50-285	
HACDONALD, C E	7905070272	71-99		MADSEN, O L	7905010548	50-267	
HACDONALD, C E	7905070279	71-103		MADSEN, O L	7905010549	50-313	
HACDONALD, C E	7905070282	71-127		MADSEN, O L	7905010558	50-298	
HACDONALD, C E	7905070287	71-130		MADSEN, O L	7905010559	50-285	
HACDONALD, C E	7905070292	71-104		MADSEN, O L	7905010677	50-313	
HACDONALD, C E	7905100079	71-9079		MADSEN, O L	7905010675	50-298	
HACDONALD, C E	7905180178	71-166		MADSEN, O L	7905010601	50-285	
HACDONALD, C E	7905180205	71-168		MADSEN, O L	7905010606	50-267	
HACDONALD, C E	7905180682	71-63		MADSEN, O L	7905010695	50-313	
HACDONALD, C E	7905180739	71-47		MADSEN, O L	7905240451	50-313	
HACDONALD, C E	7905180742	71-126		MADSEN, O L	7905010685	50-313	
HACDONALD, C E	7905160033	71-5795		MADSEN, O L	7905180306	50-285	
HACDONALD, C E	7905240291	71-223		MADSEN, O L	7905180310	50-285	
HACDONALD, C E	7905240639	71-214		MADSEN, O L	7905180604	50-188	
HACDONALD, C E	7905290318	71-287		MADSEN, O L	7905180596	50-188	
HACDONALD, C E	7905080180	71-5957		MADSEN, O L	7905010654	50-267	
HACDONALD, C E	7905100339	71-268		MADSEN, O L	7905010655	50-72	
HACDONALD, C E	7905100448	71-273		MADSEN, O L	7905020122	50-298	
HACDONALD, C E	7905110199	71-260		MADSEN, O L	7905100261	50-267	
HACDONALD, C E	7905110204	71-87		MADSEN, O L	7905150578	50-112	

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
MADSEN, O. L.	7903020325	50-348		MATERS, B. R.	7903160443	50-341	
MADSEN, O. L.	7903150110	50-267		MATHEWS, E. R.	7903240319	50-305	
MADSEN, O. L.	7903150117	50-313		MATHEWS, E. R.	7903290501	50-305	
MADSEN, O. L.	7903150120	50-298		MATHEWS, E. R.	7903240289	50-305	
MADSEN, O. L.	7903150122	50-285		MATHEWS, E. R.	7903150330	50-305	
MADSEN, O. L.	7903040106	50-313		MATHEWS, E. R.	7903100289	50-305	
MADSEN, O. L.	7903040110	50-298		MATHEWS, E. R.	7903150563	50-305	
MADSEN, O. L.	7903040112	50-285		MATHEWS, E. R.	7903240384	50-305	
MADSEN, O. L.	7903040115	50-267		MATHEWS, E. R.	7903300028	50-305	
MADSEN, O. L.	7903150223	50-267		MATHEWS, E. R.	7903310365	50-305	
MADSEN, O. L.	7903150253	50-313		MATHEWS, E. R.	7903300395	50-305	
MADSEN, O. L.	7903150258	50-298		MATHEWS, P. R.	7903210068	50-320	
MADSEN, O. L.	7903150261	50-285		MATHIAS, C. H.	7903300244	50-320	
MADSEN, O. L.	7903230268	50-285		MATHIS, C. J.	7903010540	50-293	
MADSEN, O. L.	7903230257	50-285		MATHIS, C. J.	7903020267	50-293	
MADSEN, O. L.	7903030008	50-313		MATHIS, C. J.	7903140247	50-293	
MADSEN, O. L.	7903150795	50-267		MATHIS, C. J.	7903160423		
MADSEN, O. L.	7903150584	50-112		MATHIS, C. J.	7903290100	50-293	
MADSEN, O. L.	7903150096	50-313		MATHIS, C. J.	7903300543	50-293	
MADSEN, O. L.	7903150097	50-298		MATHIS, H.	7903030161		
MADSEN, O. L.	7903150100	50-285		MATHIS, H.	7903140019		
MADSEN, O. L.	7903150102	50-267		MATIN, L. E.	7903150550	50-382	
MADSEN, O. L.	7903240428	50-267		MATSON, V.	7903100358	70-2084	
MADSEN, O. L.	7903240440	50-285		MATSON, V.	7903020290		
MADSEN, O. L.	7903240445	50-298		MATSON, V.	7903240121	70-2198	
MADSON, B.	7903310292	27-39		MATSON, V.	7903100417		
MAGERS, J. E.	7903150312	50-331		MATSON, V.	7903150195		
MAIMONI, A.	7903020464			MATSON, V.	7903290118		
MAKEPEACE, J. M.	7903040006	50-247		MATSON, V.	7903290121		
MAKEPEACE, J. M.	7903040279	50-247		MATSUBI, R. T.	7903020011	50-320	
MALINAUSKAS, A. P.	7903300078		NUREG/CR-0682	MATT, P. K.	7903030199		
MALLORY, R.	7903160103	50-320		MATT, P. K.	7903140089		
MALONEY, G. P.	7903110183	50-315		MATT, P. K.	7903100007		
MANCUBO, F.	7903230504			MATTIMOE, J. J.	7903110032	50-312	
MANCZER, W. B.	7903230658			MATTIMOE, J. J.	7903110153	50-312	
MANN, J. R.	7903090011			MATTIMOE, J. J.	7903020306	50-312	
MANN, J. R.	7903140316	50-321		MATTIMOE, J. J.	7903100293	50-312	
MANN, M.	7903010469	50-366		MATTIMOE, J. J.	7903190156	50-312	
MANN, M.	7903010502	50-321		MATTIMOE, J. J.	7903240710	50-312	
MANN, M.	7903080846	50-321		MATTIMOE, J. J.	7903190134	50-312	
MANN, M.	7903080473	50-321		MATTIMOE, J. J.	7903250434	50-312	
MANN, M.	7903080820	50-321		MATTIMOE, J. J.	7903290369	50-312	
MANN, M.	7903070639	50-366		MATTIMOE, J. J.	7903300405	50-312	
MANN, M.	7903150465	50-366		MATTIA, M. J.	7903090399		
MANN, M.	7903150519	50-321		MATTIA, M. J.	7903140179		
MANN, M.	7903150543	50-321		MATTON, R. J.	7903080048		
MANN, M.	7903150344	50-366		MATTON, R. J.	7903140299	50-524	
MANN, M.	7903300627	50-321		MATTON, R. J.	7903080044		
MANN, M.	7903300644	50-321		MATTON, R. J.	7903140292	50-524	
MANN, M.	7903300683	50-321		MATTON, R. J.	7903080041		
MANN, M.	7903300591	50-321		MATTON, R. J.	7903230123	50-320	
MANN, M.	7903300664	50-321		MATTON, R. J.	7903190194	50-320	
MANSER, W. C.	7903020425	70-143		MATTON, R. J.	7903110292	50-320	
MANSER, W. C.	7903250335	70-143		MATTON, R. J.	7903190250	50-320	
MANSER, W. C.	7903150024	70-143		MATTON, R. J.	7903110219	50-320	
MANSER, W. C.	7903240344	70-143		MATTON, R. J.	7903110282	50-320	
MANSER, N.	7903240279	50-275		MATTON, R. J.	7903230070	50-320	
MARCHI, M. L.	7903300399	50-305		MATTON, R. J.	7903300075	50-320	
MARCHEBE, A.	7904270399	50-320		MATTON, R. J.	7903210082	50-320	
MARGOLIS, K. R.	7903230789	50-275		MATTON, R. J.	7903190172	50-320	
MARINOS, E. C.	7903090210	50-320		MATTON, R. J.	7903080364		
MARINO, O. P.	7903110351	50-320		MATTON, R. J.	7903160091	50-320	
MARINO, O. P.	7903110343	50-320		MATTON, R. J.	7903220455	50-320	
MARK, J. C.	7903290262		NUREG/CR-0724	MATTU, R.	7903080051		NUREG-0484
MARKIND, J.	7903100229			MAUNEY, B. R.	7903250300		
MARKOWSKI, R.	7903290126	50-334		MAURA, F. A.	7903070027	50-373	
MARKS, O. H.	7903230104	50-255		MAXWELL, O. F.	7903090393	50-346	
MARTDTA, C. R.	7903300433	50-320		MAY, E. L.	7903190428	50-29	
MARTDTA, C. R.	7903300434	50-320		MAY, E. L.	7903150437	50-29	
MARGUARDT, P. A.	7903150285	50-452		MAY, E. L.	7903190128	50-29	
MARGUARDT, P. A.	7903310431	50-16		MAY, H.	7903300394		
MARRANZING, A. P.	7903150481	50-274		MAY, K. N.	7903230814	50-270	
MARRIOTT, P. H.	7903210328	50-320		MAYER, B. M.	7903240120	50-466	
MARRIOTT, P. H.	7903210324	50-320		MAYER, L. O.	7903020236	50-282	
MARRIOTT, D.	7903150061	40-8698		MAYER, L. O.	7903040415	50-263	
MARRONE, J.	7903020274	50-320		MAYER, L. O.	7903090369	50-263	
MARSCH, R.	7903210057	50-320		MAYER, L. O.	7903010509	50-282	
MARSHALL, E. H.	7903020232	50-445		MAYER, L. O.	7903010474	50-282	
MARTIN, A.	7903230751	50-466		MAYER, L. O.	7903030364	50-282	
MARTINEZ, F. P.	7903140326			MAYER, L. O.	7903080413	50-263	
MARTIN, J. E.	7904180179			MAYER, L. O.	7903040011	50-263	
MARTIN, W. O.	7903220087	70-135		MAYER, L. O.	7903070366	50-263	
MARTIN, W. O.	7903110029	70-820		MAYER, L. O.	7903070459	50-282	
MARTIN, W. O.	7903230277	70-33		MAYER, L. O.	7903080543	50-282	
MARTIN, W. O.	7903240775	70-135		MAYER, L. O.	7903080424	50-263	
MARTIN, W. O.	7903240277	50-225		MAYER, L. O.	7903090388	50-263	
MARTIN, W. O.	7903220072	70-135		MAYER, L. O.	7903110127	50-282	
MARTIN, W. O.	7903240756	70-135		MAYER, L. O.	7903190496	50-282	
MARTIN, R. D.	7903090133	50-338		MAYER, L. O.	7903160352	50-282	
MARTIN, R. D.	7903010467	50-395		MAYER, L. O.	7903160379	50-263	
MARTIN, R. D.	7903240480	50-124		MAYER, L. O.	7903190466	50-282	
MARTIN, R. D.	7903240491	50-327		MAYER, L. O.	7903190033	50-263	
MARTIN, R. D.	7903240934	50-339		MAYER, L. O.	7903210279	50-306	
MARTIN, L. E.	7903010383	50-498		MAYER, L. O.	7903220114	50-306	
MARTIN, J. B.	7903080087			MAYER, L. O.	7903240560	50-263	
MARTIN, J. B.	7903080101			MAYER, L. O.	7903300406	50-282	
MARTIN, R.	7903210295	50-320		MAYOR, L. O.	7903240681	50-263	
MARTIN, R.	7903230088	50-320		MAZZONE, J.	7903020383	50-293	
MARX, D. J.	7903070588	50-271		MCBREARTY, R. A.	7903040156	50-387	
MASCIULLI, S.	7903190018	50-3		MCBREARTY, R. A.	7903240673	50-322	
MASCIULLI, S.	7903190023	50-3		MCBRIDE, M. F.	7903240195	50-485	
MASRI, S. F.	7903030051			MCBRIDE, M. F.	7903180074	50-485	
MASSE, R. E.	7903130163	50-156		MCCABE, E. C.	7903110217	50-219	
MASTERSON, D. J.	7903250016	71-205		MCCABE, E. C.	7903110394	50-271	
MASTERSON, D. J.	7903250019	71-205		MCCABE, E. C.	7903240704	50-245	
MASTER, V. P.	7903090083	50-592		MCCABE, E. C.	7903290120	50-277	

PERSONAL AUTHOR INDEX

341

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
McCabe, E. C.	7905150523	50-277		Menning, J. E.	7905290546	50-263	
McCann, H. J.	7905080461	50-336		Menning, J. E.	7905240729	50-358	
McCarthy, L. T.	7905240644	50-312		Menzel, H. C.	7905150598	50-275	
McClain, C. M.	7905280084	50-219		Merigold, G.	7905020036		
McClintock, R. O.	7905150727	70-2428		Merrill, D. N.	7905170233	50-443	
McClintock, R. O.	7905290165	30-1873		Merson, S. D.	7905230356	50-317	
McClintock, R. O.	7905100422	30-6949		Merson, S. D.	7905230358	30-317	
McClintock, R. O.	7905290156	30-1873		Messitt, B. R.	7905230243	50-324	
McClintock, R. O.	7905210246	50-320		Metcalfe, L. J.	7905090401		NUREQ/CR-0255
McCloskey, D. J.	7905140149		NUREQ/CR-0649	Metzenbaum, H. M.	7905100040	50-320	
McCorkle, B.	7905310116	50-466		Mewhinney, J. A.	7905100213		NUREQ/CR-0673
McCorkle, B.	7905310123	50-466		Mevers, J. E.	7905230031	50-331	
McCorkle, B. A.	7905250135	50-466		Meyer, W. A.	7905290305	71-304	
McCormack, J. B.	7905290043			Meyer, W. A.	7905290309	71-304	
McCormale, O. M.	7905220032	70-820		Meyer, M. B.	7905100326	50-471	
McCormale, O. M.	7905240938	70-2623		Meyer, B. A.	7905240541	50-293	
McCormale, O. M.	7905300583	70-135		Mevers, S. C.	7905100165		NUREQ/CR-0643
McCormale, O. M.	7905230844	70-143		Meyer, J. F.	7905100277		
McCormale, O. M.	7905300051	70-1173		Michaelson, N.	7905230735	50-466	
McCormale, O. M.	7905140026	50-320		Michaelson, C.	7905210232		
McCormale, O. M.	7905140015	50-320		Miguel, C. J.	7905130664	70-143	
McCormale, O. M.	7905140023	50-320		Michaelson, C.	7905020159	50-320	
McCormale, O. M.	7905160155	50-320		Middleton, G.	7905150594	40-8698	
McCreless, T. G.	7905100378	50-346		Midura, H. J.	7905080462	50-272	
McCreless, T.	7905100101			Midura, H. J.	7905290070	50-272	
McCreless, T.	7905140126	50-445		Midura, H. J.	7905290495	50-272	
McCreless, T.	7905140151	50-445		Midura, H. J.	7905080466	50-272	
McCreless, T.	7905150757	50-358		Midura, H. J.	7905080489	50-272	
McDonough, J. A.	7905170302	50-272		Midura, H. J.	7905080421	50-272	
McDonough, J. A.	7905170300	50-272		Midura, H. J.	7905230441	50-272	
McDonough, J. A.	7905090056	50-339		Midura, H. J.	7905300421	50-272	
McDuffie, M. A.	7905070475	50-400		Midura, H. J.	7905300417	50-272	
McDuffie, M. A.	7905090348	50-400		Midura, H. J.	7905150293	50-272	
McDuffie, M. A.	7905290380	50-400		Midura, H. J.	7905300431	50-272	
McFarlane, E. D.	7905140341	50-288		Midura, H. J.	7905290408	50-272	
McFarlane, E. D.	7905230169	50-339		Midura, H. J.	7905300363	50-272	
McFarlane, E. D.	7905240317	70-2623		Midura, H. J.	7905190083	50-317	
McGarry, J. H.	7905240414	71-6698		Midura, H. J.	7905290430	50-317	
McGarry, J. H.	7905110040	70-2623		Midura, H. J.	7905300270	50-206	
McGarry, J. H.	7905300099	50-488		Midura, H. J.	7905300277	50-206	
McGarry, J. H.	7905110037	70-2623		Midura, H. J.	7905150415	50-382	
McGarry, J. H.	7905150440	70-2623		Midura, H. J.	7905230649	50-272	
McGarry, J. H.	7905250061	50-491		Midura, H. J.	7905290102	50-272	
McGarry, J. H.	7905290475	50-488		Midura, H. J.	7905150681	50-27	
McGarry, J. H.	7905240470	70-2623		Midura, H. J.	7905150672	50-272	
McGarry, J. H.	7905140339	50-416		Midura, H. J.	7905230540	50-272	
McGarry, J. H.	7905020435	50-416		Midura, H. J.	7905140568	50-272	
McGarry, J. H.	7905140334	50-416		Midura, H. J.	7905140561	50-272	
McGarry, J. H.	7905290061	50-416		Midura, H. J.	7905140558	50-272	
McGarry, J. H.	7905040510	50-416		Midura, H. J.	7905300437	50-320	
McGarry, J. H.	7905040631	50-416		Midura, H. J.	7905020405	50-320	
McGarry, J. H.	7905040636	50-416		Midura, H. J.	7905100147	50-255	
McGarry, J. H.	7905240673	50-322		Midura, H. J.	7905100271	50-445	
McGarry, J. H.	7905240684	50-363		Midura, H. J.	7905070650	50-482	
McGarry, J. H.	7905240433			Midura, H. J.	7905250098	50-321	
McGarry, J. H.	7905240164			Midura, H. J.	7905010361	50-267	
McGarry, J. H.	7905240991			Midura, H. J.	7905150800	50-267	
McGarry, J. H.	7905010336	50-293		Midura, H. J.	7905150299	50-272	
McGarry, J. H.	7905020261	50-293		Midura, H. J.	7905020480	50-445	
McGarry, J. H.	7905140244	50-293		Midura, H. J.	7905290131		
McGarry, J. H.	7905160420	50-293		Midura, H. J.	7905240212	50-510	
McGarry, J. H.	7905150535	50-293		Midura, H. J.	7905100412	50-445	
McGarry, J. H.	7905150534	50-293		Midura, H. J.	7905290108	50-329	
McGarry, J. H.	7905290095	50-293		Midura, H. J.	7905150716		
McGarry, J. H.	7905300472	50-293		Midura, H. J.	7905220048	70-2623	
McGarry, J. H.	7905300935	50-293		Midura, H. J.	7905230664	70-2623	
McGarry, J. H.	7905230398	50-466		Midura, H. J.	7905150663	50-445	
McGarry, J. H.	7905250386	50-498		Midura, H. J.	7905250379		
McGarry, J. H.	7905300081	50-498		Midura, H. J.	7905150780	50-445	
McGarry, J. H.	7905300064	50-498		Midura, H. J.	7905230677	50-445	
McGarry, J. H.	7905290049	50-382		Midura, H. J.	7905240885	50-329	
McGarry, J. H.	7905230992	50-261		Midura, H. J.	7905140564	50-329	
McGarry, J. H.	7905310356	50-170		Midura, H. J.	7905230563	50-310	
McGarry, J. H.	7905310399	50-302		Midura, H. J.	7905230070	50-310	
McGarry, J. H.	7905110036	70-820		Midura, H. J.	7905290268		
McGarry, J. H.	7905160071	50-320		Midura, H. J.	7905080033	50-259	
McGarry, J. H.	7905020155	50-320		Midura, H. J.	7905070669	50-321	
McGarry, J. H.	7905010577	40-8698		Midura, H. J.	7905040267	50-348	
McGarry, J. H.	7905210040	50-320		Midura, H. J.	7905220035	50-312	
McGarry, J. H.	7905210252	50-320		Midura, H. J.	7905150290	50-261	
McGarry, J. H.	7905210319	50-320		Midura, H. J.	7905110019	40-8584	
McGarry, J. H.	7905230138	50-320		Midura, H. J.	7905150482	50-311	
McGarry, J. H.	7905230154	50-320		Midura, H. J.	7905150486	50-289	
McGarry, J. H.	7905230163	50-320		Midura, H. J.	7905240100	50-315	
McGarry, J. H.	7905220414	50-320		Midura, H. J.	7905150104	50-269	
McGarry, J. H.	7905220084	50-358		Midura, H. J.	7905230850	70-371	
McGarry, J. H.	7905150130	50-335		Midura, H. J.	7905290398	50-281	
McGarry, J. H.	7905140159	50-522		Midura, H. J.	7905230426	50-331	
McGarry, J. H.	7905140161	50-522		Midura, H. J.	7905110331	50-320	
McGarry, J. H.	7905160347	50-522		Midura, H. J.	7905240124	50-466	
McGarry, J. H.	7905230459	50-522		Midura, H. J.	7905040500	50-327	
McGarry, J. H.	7905310372	50-522		Midura, H. J.	7905040375	50-409	
McGarry, J. H.	7905310383	50-522		Midura, H. J.	7905100224	50-387	
McGarry, J. H.	7905300070	50-206		Midura, H. J.	7905240806	50-387	
McGarry, J. H.	7905300077	50-206		Midura, H. J.	7905230460		BECY-78-624
McGarry, J. H.	7905300374			Midura, H. J.	7905080035		BECY-78-130
McGarry, J. H.	7905140170			Midura, H. J.	7905080082		BECY-79-187
McGarry, J. H.	7905300154	40-8698		Midura, H. J.	7905100036		
McGarry, J. H.	7905040473	50-471		Midura, H. J.	7904270178	50-320	
McGarry, J. H.	7905150803			Midura, H. J.	7904270576	50-320	
McGarry, J. H.	7905010553	50-361		Midura, H. J.	7905230608		
McGarry, J. H.	7905300303			Midura, H. J.	7905250322		
McGarry, J. H.	7905300414			Midura, H. J.	7905210015	50-320	
McGarry, J. H.	7905230717			Midura, H. J.	7904300260		
McGarry, J. H.	7905290431			Midura, H. J.	7905110138	50-320	
McGarry, J. H.	7905250481	50-280		Midura, H. J.	7905110322	50-320	

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
MIRAGLIA, F. J.	7904270152	50-320		MOWRY, W. R.	7905300326		
MIRAGLIA, F. J.	7905110151	50-320		MUELLER, E. E.	7905240132	50-466	
MIRAGLIA, F. J.	7905110126	50-320		MUELLER, R.	7905300557	50-285	
MIRAGLIA, F. J.	7905070005	50-320		MULKEY, M. E.	7905300048	50-133	
MIRAGLIA, F. J.	7905110140	50-320		MULLER, R. E.	7905250115		
MIRAGLIA, F. J.	7905110121	50-320		MULLEARY, T.	7905230189	50-320	
MIRAGLIA, F. J.	7905110119	50-320		MULLINS, C. B.	7905140572		NUREG/CR-0539
MIRAGLIA, F.	7905100333	50-320		MULLON, T. P.	7905140201	50-131	
MISHIMA, J.	7905150777		7905150777	MUMPER, H. J.	7905250509		
MITCHELL, D. O.	7905230376	50-289		MUNDTH, L. K.	7905110150		
MITCHELL, D. O.	7905220323	50-289		MURDOCK, L. T.	7905030136	40-299	
MITCHELL, D. O.	7905290384	50-289		MURDOCK, L. T.	7905030132	40-299	
MITTL, R. L.	7905070552	50-334		MURLEY, T. E.	7905140017	50-320	
MITTL, R. L.	7905040519	50-311		MURLEY, T. E.	7905110283		
MITTL, R. L.	7905080481	50-311		MURPHY, P. M.	7905160504	50-556	
MITTL, R. L.	7905090308	50-311		MURPHY, P. M.	7905090185	50-556	
MITTL, R. L.	7905220349	50-272		MURPHY, P. M.	7905230284	50-454	
MITTL, R. L.	7905250100	50-311		MURPHY, J. D.	7905290148	71-1	
MITTL, R. L.	7905250415	50-311		MURPHY, J. D.	7905290146	71-1	
MOELLER, D. W.	7905140164			MURPHY, C. E.	7905070590	50-316	
MOELLER, D. W.	7905030161			MURPHY, C. E.	7905010418	50-302	
MOELLER, D. W.	7905140019			MURPHY, C. E.	7905290112	50-395	
MOELLER, D. W.	7905160250			MURPHY, C. E.	7905240498	50-518	
MOLYNEUX, E. L.	7905150766	71-309		MURPHY, C. E.	7905240661	50-324	
MOLYNEUX, E. L.	7905150763	71-309		MURPHY, C. E.	7905010403	50-302	
MONDICS, D.	7905220428	50-320		MURPHY, C. E.	7905020326	50-369	
MONTGOMERY, D. M.	7905210303	50-320		MURPHY, C. E.	7905020435	50-327	
MONTI, W. A.	7905220376	50-3		MURPHY, C. E.	7905020097	50-391	
MOODY, D. E.	7905030185	50-309		MURPHY, C. E.	7905070352	50-309	
MOODY, D. E.	7905150516	50-309		MURPHY, C. E.	7905230740	50-566	
MOODY, D. E.	7905300019	50-309		MURPHY, C. E.	7905010235	50-389	
MOODY, D. E.	7905070693	50-271		MURPHY, C. E.	7905070115	50-281	
MOODY, D. E.	7905080423	50-271		MURPHY, C. E.	7905230129	50-339	
MOODY, T. E.	7905070462	50-271		MURPHY, C. E.	7905240292	50-327	
MOODY, D. E.	7905160253	50-271		MURPHY, C. E.	7905290383	50-281	
MOODY, D. E.	7905150341	50-271		MURPHY, C. E.	7905230137	50-389	
MOODY, D. E.	7905080075	50-29		MURPHY, C. E.	7905090424	50-395	
MOODY, D. E.	7905250359	50-29		MURPHY, C. E.	7905150802	50-390	
MOODY, D. E.	7905150334	50-29		MURPHY, C. E.	7905150072	50-518	
MOORE, D.	7905020281	50-320	ESG-79-7	MURPHY, C. E.	7905230726	50-491	
MOORE, J. D.	7905080517	50-375		MURPHY, C. E.	7905240464	50-395	
MOORE, J. B.	7905110077	50-6134		MURPHY, C. E.	7905250422	50-518	
MOORE, T. C.	7905230510			MURPHY, C. E.	7905240514	50-348	
MOORE, O. H.	7905010532	50-334		MURPHY, C. E.	7905240525	50-491	
MOORE, O. H.	7905010537	50-334		MURPHY, C. E.	7905240500	50-424	
MOORE, O. C.	7905150206	50-302		MURPHY, C. E.	7905020285	50-369	
MOORE, J. B.	7905090277	50-361		MURPHY, C. E.	7905020074	50-391	
MOORE, J. B.	7905080418	50-206		MURPHY, C. E.	7905080325	50-400	
MOORE, H. O.	7905310423	50-361		MURPHY, C. E.	7905230698	50-566	
MOORE, R. N.	7905070334	50-327		MURPHY, C. E.	7905230017	50-400	
MOORE, R. N.	7905240021			MURPHY, C. E.	7905140162	50-413	
MOORE, R. N.	7905230634			MURPHY, C. E.	7905290361	50-281	
MOORE, R. N.	7905230716			MURPHY, J. A.	7905210027	50-320	
MOORE, R. W.	7905250323			MURRAY, T. D.	7905100380	50-346	
MOORE, J. E.	7905150180	50-272		MURRAY, T. D.	7905100341	50-346	
MOORE, J. E.	7905150187	50-272		MURRAY, T. D.	7905020266	50-346	
MOORE, T. F.	7905150192	50-272		MURRAY, T. D.	7905100286	50-346	
MOORE, J. E.	7905220038	50-272		MURRAY, T. D.	7905020303	50-346	
MOORE, J. E.	7905100150	50-549		MURRAY, T. D.	7905020418	50-346	
MOORE, R.	7905080198	50-286		MURRAY, T. D.	7905020488	50-346	
MOORE, R.	7905090220	50-320		MURRAY, T. D.	7905020427	50-346	
MOORE, R.	7905090224	50-320		MURRAY, T. D.	7905020443	50-346	
MOORE, R. H.	7905100913	50-376		MURRAY, T. D.	7905040129	50-346	
MOORE, V. A.	7905100099	50-423		MURRAY, T. D.	7905090269	50-346	
MORIARTY, J. M.	7905100103	50-412		MURRAY, T. D.	7905140233	50-346	
MORIARTY, J. M.	7905100107	50-395		MURRAY, T. D.	7905150455	50-346	
MORIN, H. F.	7905020466	50-338		MURRAY, T. D.	7905160404	50-346	
MORIN, J. P.	7905290210	50-322		MURRAY, T. D.	7905220124	50-346	
MORRIS, K. J.	7905090317	50-285		MURRAY, T. D.	7905220096	50-346	
MORRIS, K. J.	7905080446	50-285		MURRAY, T. D.	7905220117	50-346	
MORRIS, K. J.	7905100312	50-285		MURRAY, T. D.	7905230134	50-346	
MORRIS, K. J.	7905240562	50-285		MURRAY, J. P.	7905100406	50-320	
MORRISSEY, J. C.	7905030244	50-275		MURRAY, B.	7905160208	50-320	
MORRISSEY, J. C.	7905300007	50-275		MURTAGH, W. J.	7905100266	50-267	
MORRILL, P. O.	7905230640	50-275		MUSCARA, J.	7905240258	40-8681	
MORTON, K. V.	7905140105			MYERS, J. A.	7905110319	50-320	
MORTON, K. V.	7905040024			MYNATT, A.	7905040285	50-320	
MORTON, K. V.	7905030184			MYNATT, A.	7905150101		
MORTON, K. V.	7905150109			MYNATT, A.	7905140099		
MORTON, K. V.	7905030234			MYNATT, A.	7905030226		
MORTON, K. V.	7905040069			MYNATT, A.	7905150535	50-358	
MORTON, K. V.	7905040090			MYNATT, A.	7905230333		
MORTON, K. V.	7905030203			MYNATT, A.	7905070210	50-247	
MORTON, K. V.	7905040032			MYNATT, A.	7905150620	50-328	
MORTON, K. V.	7905240125			MYNATT, A.	7905250307	70-1086	
MORTON, K. V.	7905230690			MYNATT, A.	7905250314	70-1086	
MORTON, K. V.	7905240420			MYNATT, A.	7905030332	50-409	
MORTON, K. V.	7905240447			MYNATT, A.	7905070396	50-295	
MORTON, K. V.	7905230702			MYNATT, A.	7905090360	50-599	
MORTON, K. V.	7905240669			MYNATT, A.	7905170246	50-599	
MOCHNER, R. A.	7905230730	70-754		MYNATT, A.	7905240664	50-599	
MOSELEY, N. C.	7905110187	50-320		MYNATT, A.	7905150351	50-434	
MOSELEY, N. C.	7905110184	50-320		MYNATT, A.	7905170264	50-599	
MOSELEY, N. C.	7905110421	50-329		MYNATT, A.	7905290079	50-295	
MOSELEY, N. C.	7905160216	50-320		MYNATT, A.	7905310393	50-599	
MOSELEY, N. C.	7905110420	50-329		MYNATT, A.	7905220101	50-346	
MOSELEY, N. C.	7905160209	50-320		MYNATT, A.	7905020149	50-488	
MOSELEY, N. C.	7905110413	50-320		MYNATT, A.	7905230750	50-277	
MOSELEY, N. C.	7905140047	50-320		MYNATT, A.	7905290196	50-3	
MOSELEY, N. C.	7905160216	50-500		MYNATT, A.	7905300010	50-280	
MOSELEY, N. C.	7905290174	50-335		MYNATT, A.	7905150789	50-280	
MOSELEY, N. C.	7905300049	71-5908		MYNATT, A.	7905310472	50-280	
MOTT, M. E.	7905020387	71-6346		MYNATT, A.	7905290405	50-280	
MOWRY, W. R.	7905150208			MYNATT, A.	7905030330	50-338	
MOWRY, W. R.	7905300321			MYNATT, A.	7905030074	50-373	
				MYNATT, A.	7905070035	50-320	

PERSONAL AUTHOR INDEX

343

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
NELSON, D. D.	7905240602	50-313		O'NEILL, J. H.	7905140255	50-400	
NELSON, J. M.	7905020500	50-346		O'NEILL, J. H.	7905140261	50-400	
NELSON, J. M.	7905160409	50-346		O'REILLY, J. P.	7905070460	50-280	
NELSON, J. M.	7905250142	50-346		O'REILLY, J. P.	7905150103	50-259	
NELSON, C. C.	7905070373	50-309		O'REILLY, J. P.	7905010158	50-437	
NELSON, C. C.	7905240367	50-309		O'REILLY, J. P.	7905010161	50-348	
NELSON, C. C.	7905020101			O'REILLY, J. P.	7905010169	50-261	
NEHEATHY, E.	7905240625	50-387		O'REILLY, J. P.	7905010177	50-269	
NEUMAN, J. R.	7905250328	50-498		O'REILLY, J. P.	7905010183	50-413	
NEWACHECK, R. L.	7905240357	50-32		O'REILLY, J. P.	7905010192	50-302	
NEWMAN, J. R.	7905240043	50-466		O'REILLY, J. P.	7905010200	50-321	
NEWMAN, J. R.	7905080387	50-466		O'REILLY, J. P.	7905010204	50-416	
NEWMAN, J. R.	7905080331	50-466		O'REILLY, J. P.	7905010205	50-395	
NEWMAN, J. R.	7905250170	50-498		O'REILLY, J. P.	7905010224	50-259	
NEWMAN, J. R.	7905080311	50-466		O'REILLY, J. P.	7905020404	50-302	
NEWMAN, J. R.	7905080320	50-466		O'REILLY, J. P.	7905030290	50-348	
NEWMAN, J. R.	7905250225	50-466		O'REILLY, J. P.	7905030294	50-261	
NEWMAN, J. R.	7905300066	50-466		O'REILLY, J. P.	7905030301	50-413	
NEWMAN, J. R.	7905310407	50-466		O'REILLY, J. P.	7905030307	50-269	
NEWMAN, J. R.	7905290068	50-466		O'REILLY, J. P.	7905030310	50-250	
NEWMAN, J. R.	7905070239	50-466		O'REILLY, J. P.	7905030312	50-321	
NEWMAN, J. R.	7905140037	50-466		O'REILLY, J. P.	7905030314	50-416	
NEWMAN, J. R.	7905240310	50-466		O'REILLY, J. P.	7905030317	50-395	
NEWMAN, J. R.	7905100391	50-466		O'REILLY, J. P.	7905030319	50-280	
NEWMAN, J. R.	7905250239	50-466		O'REILLY, J. P.	7905030323	50-437	
NEWMAN, J. R.	7905270002	50-498		O'REILLY, J. P.	7905010093	50-348	
NEWMAN, R. I.	7905150674	70-1821		O'REILLY, J. P.	7905010095	50-261	
NEWMAN, R. I.	7905220109	40-3392		O'REILLY, J. P.	7905010102	50-302	
NIESCHMIDT, E. B.	7905240867	71-277		O'REILLY, J. P.	7905010104	50-250	
NIMITZ, R. L.	7905100291	50-283	NUREG/CR-0755	O'REILLY, J. P.	7905010107	50-321	
NIMITZ, R. L.	7905230750	50-277		O'REILLY, J. P.	7905010113	50-259	
NIX, R. T.	7905110113	30-6134		O'REILLY, J. P.	7905010123	50-280	
NIX, R. T.	7905150467	50-366		O'REILLY, J. P.	7905010132	50-322	
NIX, R. T.	7905150525	50-321		O'REILLY, J. P.	7905010137	70-143	
NOLAN, F.	7905300676	50-321		O'REILLY, J. P.	7905010339	50-348	
NOLAN, F. J.	7905100375	50-346		O'REILLY, J. P.	7905010346	50-325	
NOLAN, F.	7905110006	50-312		O'REILLY, J. P.	7905010350	50-269	
NOLAN, F.	7905110200	50-286		O'REILLY, J. P.	7905010353	50-302	
NORDEHAUO, L. R.	7905140067	50-320		O'REILLY, J. P.	7905010358	50-250	
NORDEHAUO, L. R.	7905150249	70-734		O'REILLY, J. P.	7905010360	50-321	
NORELIUS, C. E.	7905020172	70-1257		O'REILLY, J. P.	7905010363	50-259	
NORTH, H. S.	7905230664	50-323		O'REILLY, J. P.	7905010369	50-280	
NORTH, H. S.	7905040366	50-344		O'REILLY, J. P.	7905010371	50-302	
NORTH, H. S.	7905240768	50-273		O'REILLY, J. P.	7905020124	50-348	
NORTON, B.	7905300007	50-273		O'REILLY, J. P.	7905020125	50-261	
NOSENZO, L. V.	7905240875			O'REILLY, J. P.	7905020127	50-280	
NOSENZO, L. V.	7905240883			O'REILLY, J. P.	7905020133	50-339	
NOSENZO, L. V.	7905240889			O'REILLY, J. P.	7905080334	50-280	
NOSENZO, L. V.	7905240897			O'REILLY, J. P.	7905070137	50-140	
NOSENZO, L. V.	7905250054			O'REILLY, J. P.	7905070138	50-124	
NOSENZO, L. V.	7905150184			O'REILLY, J. P.	7905070142	50-83	
NOSENZO, L. V.	7905150123			O'REILLY, J. P.	7905070146	50-111	
NOSENZO, L. V.	7905150183			O'REILLY, J. P.	7905070152	50-406	
NOSENZO, L. V.	7905150191			O'REILLY, J. P.	7905070153	50-538	
NOSENZO, L. V.	7905230301			O'REILLY, J. P.	7905070156	50-129	
NOSENZO, L. V.	7905160234			O'REILLY, J. P.	7905070159	50-13	
NOSENZO, L. V.	7905150807			O'REILLY, J. P.	7905030180	50-437	
NOSENZO, L. V.	7905160228			O'REILLY, J. P.	7905030198	50-395	
NOSENZO, L. V.	7905230599			O'REILLY, J. P.	7905030368	50-259	
NOSENZO, L. V.	7905230575			O'REILLY, J. P.	7905040141	50-335	
NOSENZO, L. V.	7905230597			O'REILLY, J. P.	7905040145	50-437	
NOSENZO, L. V.	7905230669			O'REILLY, J. P.	7905040148	50-348	
NOSENZO, L. V.	7905240431			O'REILLY, J. P.	7905040163	50-261	
NOSENZO, L. V.	7905230442			O'REILLY, J. P.	7905040176	50-269	
NOSENZO, L. V.	7905230708			O'REILLY, J. P.	7905040185	50-413	
NOTLEY, D. P.	7905300428	50-320		O'REILLY, J. P.	7905040209	50-302	
NOVAKARD, D.	7905290168			O'REILLY, J. P.	7905040212	50-250	
NOVAKOVICH, D.	7905290573			O'REILLY, J. P.	7905040216	50-321	
NOVAK, T. M.	7905230281	50-320		O'REILLY, J. P.	7905040223	50-416	
NOVAK, T. M.	7905230298	50-320		O'REILLY, J. P.	7905040225	50-395	
NOVAK, T. M.	7905230109	50-320		O'REILLY, J. P.	7905040233	50-259	
NOVAK, T.	7905110055			O'REILLY, J. P.	7905040234	50-280	
NOVAK, T.	7905110060			O'REILLY, J. P.	7905040263	50-269	
NOVARRD, J. P.	7905240996	50-322		O'REILLY, J. P.	7905040266	50-413	
NOVARRD, J. P.	7905040439	50-322		O'REILLY, J. P.	7905040271	50-280	
NOVARRD, J. P.	7905040318	50-322		O'REILLY, J. P.	7905040281	50-261	
NOVARRD, J. P.	7905240639	50-322		O'REILLY, J. P.	7905040298	50-348	
NOVARRD, J. P.	7905080500	50-322		O'REILLY, J. P.	7905040304	50-321	
NOWICKI, B. J.	7905150154			O'REILLY, J. P.	7905040306	50-302	
NOWICKI, B. J.	7905100239	50-155		O'REILLY, J. P.	7905040308	50-250	
NUGENT, E. L.	7905100025	40-2259		O'REILLY, J. P.	7905040312	50-416	
NUNN, C. N.	7905030342	50-334		O'REILLY, J. P.	7905040322	50-348	
NUSSBAUMER, D. A.	7905230312	40-2407		O'REILLY, J. P.	7905040329	50-261	
NUSSBAUMER, D. A.	7905230193	40-2407		O'REILLY, J. P.	7905040346	50-413	
NUSSBAUMER, D. A.	7905230177	40-2407		O'REILLY, J. P.	7905040381	50-269	
NUSSBAUMER, D. A.	7905230348	40-2407		O'REILLY, J. P.	7905040395	50-302	
NUSSBAUMER, D. A.	7905230342	40-2407		O'REILLY, J. P.	7905040404	50-250	
NUSSBAUMER, D. A.	7905230183	40-2407		O'REILLY, J. P.	7905040413	50-424	
NUSSBAUMER, D. A.	7905230164	40-2407		O'REILLY, J. P.	7905040420	50-416	
NUSSBAUMER, D. A.	7905230291	40-2407		O'REILLY, J. P.	7905040424	50-395	
NUSSBAUMER, D. A.	7905230150	40-2407		O'REILLY, J. P.	7905040448	50-280	
NUSSBAUMER, D. A.	7905230670	40-2407		O'REILLY, J. P.	7905040457	50-437	
NUSSBAUMER, D. A.	7905230313	50-437		O'REILLY, J. P.	7905110363	50-327	
NYMANT, J. A.	7905310232	50-327		O'REILLY, J. P.	7905150696	50-324	
NYMANT, J. A.	7905230528	50-327		O'REILLY, J. P.	7905150700	50-259	
NYGIST, R. Q.	7905150675	50-10	45-79/M124AF	O'REILLY, J. P.	7905010317	50-339	
O'BRIEN, G. M.	7905150653	50-454		O'REILLY, J. P.	7905010324	50-400	
O'BRIEN, G. M.	7905110280	50-320		O'REILLY, J. P.	7905010325	50-369	
O'CONNOR, L. A.	7905190075	50-245		O'REILLY, J. P.	7905010341	50-327	
O'CONNOR, P. H.	7905110128	50-320		O'REILLY, J. P.	7905010356	50-413	
O'CONNOR, P. H.	7905230097	50-10		O'REILLY, J. P.	7905010366	50-424	
O'DELL, C. B.	7905090417		NUREG/CR-0754	O'REILLY, J. P.	7905010371	50-416	
O'KEEFE, A. J.	7905160431	50-47					

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
O'REILLY, J. P.	7905010374	50-395		OPLINGER, O. O.	7905080165		
O'REILLY, J. P.	7905030133	50-437		OPLINGER, O. O.	7905150705		
O'REILLY, J. P.	7905030137	50-348		OPLINGER, O. O.	7905220448		
O'REILLY, J. P.	7905030141	50-261		OPLINGER, O. O.	7905220449		
O'REILLY, J. P.	7905030153	50-413		OPLINGER, O. O.	7905290127		
O'REILLY, J. P.	7905030160	50-267		OPLINGER, O. O.	7905290128		
O'REILLY, J. P.	7905030162	50-302		OPLINGER, O. O.	7905290133		
O'REILLY, J. P.	7905030164	50-250		OPLINGER, O. O.	7905080174		
O'REILLY, J. P.	7905030165	50-321		OPLINGER, O. O.	7905150030		
O'REILLY, J. P.	7905030167	50-414		OPLINGER, O. O.	7905150040		
O'REILLY, J. P.	7905030169	50-395		OPLINGER, O. O.	7905230524		
O'REILLY, J. P.	7905030172	50-259		OPLINGER, O. O.	7905240023		
O'REILLY, J. P.	7905030191	50-338		OPLINGER, O. O.	7905240050		
O'REILLY, J. P.	7905010324	50-403		OPLINGER, O. O.	7905290101		
O'REILLY, J. P.	7905010331	50-364		OPLINGER, O. O.	7905290186		
O'REILLY, J. P.	7905010337	50-389		OPLINGER, O. O.	7905100447		
O'REILLY, J. P.	7905010341	50-391		OPLINGER, O. O.	7905150029		
O'REILLY, J. P.	7905010356	50-489		OPLINGER, O. O.	7905150031		
O'REILLY, J. P.	7905020365	50-364		OPLINGER, O. O.	7905150032		
O'REILLY, J. P.	7905020370	50-348		OPLINGER, O. O.	7905150033		
O'REILLY, J. P.	7905020373	50-324		OPLINGER, O. O.	7905150035		
O'REILLY, J. P.	7905020426	50-261		OPLINGER, O. O.	7905150037		
O'REILLY, J. P.	7905020429	50-269		OPLINGER, O. O.	7905150038		
O'REILLY, J. P.	7905020433	50-413		OPLINGER, O. O.	7905150804		
O'REILLY, J. P.	7905020460	50-369		OPLINGER, O. O.	7905150810		
O'REILLY, J. P.	7905020463	50-302		OPLINGER, O. O.	7905150813		
O'REILLY, J. P.	7905020465	50-335		OPLINGER, O. O.	7905150815		
O'REILLY, J. P.	7905020467	50-321		OPLINGER, O. O.	7905150787		
O'REILLY, J. P.	7905020472	50-416		OPLINGER, O. O.	7905250252		
O'REILLY, J. P.	7905020473	50-395		OPLINGER, O. O.	7905250253		
O'REILLY, J. P.	7905020475	50-395		OPLINGER, O. O.	7905250257		
O'REILLY, J. P.	7905020479	50-259		OPLINGER, O. O.	7905250272		
O'REILLY, J. P.	7905020495	50-327		OPLINGER, O. O.	7905250276		
O'REILLY, J. P.	7905020496	50-280		OPLINGER, O. O.	7905250282		
O'REILLY, J. P.	7905020502	50-339		OPLINGER, O. O.	7905250287		
O'REILLY, J. P.	7905140095	50-437		OPLINGER, O. O.	7905250295		
O'REILLY, J. P.	7905290150	50-335		OPLINGER, O. O.	7905250300		
OBRO, C. R.	7905010312	50-482		OPLINGER, O. O.	7905250345		
OBLOADO, A.	7905040375	50-409		ORERA, E. O.	7905030205		
ODHSTEIN, D. S.	7905160410	50-483		ORLOVSKY, P. M.	7905190019	50-57	BAW-10085 R3
ODTHMANN, M. J.	7905090131	50-282		ORNSTEIN, H. L.	7905140035	50-320	
OH, I.	7905090422		NUREQ/CR-0642	ORNSTEIN, H.	7905140252		
OKRENT, D.	7905030210	50-320		ORTLOFF, O. D.	7905150070	40-8102	
OKRENT, D.	7905100052	50-320		OSTER, J.	7905210262	50-254	
OKRENT, D.	7905190235	50-320		OTTOBON, H. L.	7905040592	50-206	
OLDHAM, W. A.	7905240619	50-201		OTTOBON, H. L.	7905240689	50-206	
OLMSTEAD, W. J.	7905310028	50-329		OVERMAN, R. F.	7905140267	50-320	
OLMSTEAD, W. J.	7905160033	50-320		OWEN, B.	7905250156	50-322	
OLMSTEAD, W. J.	7905150240	50-329		OWEN, W. H.	7905030371	50-269	
OLSEN, A. F.	7905140411	50-99		OWBLEY, O. F.	7905080393		
OLSEN, A. F.	7905140414	50-99		PAOLARD, J. A.	7905150646	70-1379	
OLSEN, A. F.	7905140408	50-99		PALLADINO, N. J.	7905230058	50-320	
OLSEN, A. F.	7905140383	50-99		PANETTA, L. E.	7905300501	50-320	
OLSEN, A. F.	7905110309	50-99		PAPADAKIS, C. N.	7905250530	50-329	45-79/H124AF
OLSEN, A. F.	7905290427	50-13		PAPERIELLO, C. J.	7905230144	50-320	
OLSHAN, L.	7905310402	50-261		PAPERIELLO, C. J.	7905230038	50-320	
OLSHAN, L.	7905240229	50-247		PAPPAS, H.	7905240997		
OLSHANSKI, J.	7905230172	50-320		PAPPAS, H.	7905140213		
OLSHANSKI, B. M.	7905240223	50-367		PAPWORTH, L. O.	7905010510	50-409	
ONGAVAGE, M. P.	7905150182	50-250		PAPWORTH, L. O.	7905010520	50-409	
ONGAVAGE, M. P.	7905150175	50-250		PAPWORTH, L. O.	7905140234	50-409	
ONGAVAGE, M. P.	7905290026	50-250		PAPWORTH, L. O.	7905150530	50-409	
ONG, C.	7905220416	50-320		PARCELL, M.	7905160385	50-237	
ONSDORFF, K. A.	7905240789	50-272		PARCELL, M.	7905300480	50-237	
OPEKA, J. F.	7905290076	71-9044		PARIS, D. H.	7905140567	50-250	
OPEKA, J. F.	7905080456	50-336		PARKER, D. L.	7905240178	50-466	
OPEKA, J. F.	7905130502	50-336		PARKER, D. L.	7905240190	50-466	
OPEKA, J. F.	7905220395	50-245		PARKER, W. O.	7905100299	50-269	
OPEKA, J. F.	7905300452	50-336		PARKER, W. O.	7905100303	50-269	
OPEKA, J. F.	7905300533	50-245		PARKER, W. O.	7905230770	50-369	
OPEKA, J. F.	7905290221	50-336		PARKER, W. O.	7905020064	50-269	
OPLINGER, O. O.	7905230839			PARKER, W. O.	7905140506	50-287	
OPLINGER, O. O.	7905230846			PARKER, W. O.	7905230272	50-269	
OPLINGER, O. O.	7905230828			PARKER, W. O.	7905250466		
OPLINGER, O. O.	7905220060			PARKER, W. O.	7905230279	50-269	
OPLINGER, O. O.	7905250099			PARKER, W. O.	7905140483	50-287	
OPLINGER, O. O.	7905240960			PARKER, W. O.	7905020408	50-369	
OPLINGER, O. O.	7905020136			PARKER, W. O.	7905100298	50-269	
OPLINGER, O. O.	7905020349			PARKER, W. O.	7905020301	50-369	
OPLINGER, O. O.	7905020355			PARKER, W. O.	7905240214	71-266	
OPLINGER, O. O.	7905020361			PARKER, W. O.	7905100046	50-269	
OPLINGER, O. O.	7905020366			PARKER, W. O.	7905140373	50-269	
OPLINGER, O. O.	7905020381			PARKER, W. O.	7905150234	50-369	
OPLINGER, O. O.	7905030127			PARKER, W. O.	7905220463	70-2623	
OPLINGER, O. O.	7905150158			PARKER, W. O.	7905290700	50-369	
OPLINGER, O. O.	7905180162			PARKER, W. O.	7905240432	50-269	
OPLINGER, O. O.	7905230629	70-2198		PARKER, W. O.	7905240426	50-369	
OPLINGER, O. O.	7905230781			PARKER, W. O.	7905240505	50-269	
OPLINGER, O. O.	7905030068			PARKER, W. O.	7905010521	50-269	
OPLINGER, O. O.	7905020385			PARKER, W. O.	7905040047	50-269	
OPLINGER, O. O.	7905020409			PARKER, W. O.	7905020327	50-269	
OPLINGER, O. O.	7905020518			PARKER, W. O.	7905040352	50-269	
OPLINGER, O. O.	7905020499			PARKER, W. O.	7905070481	50-369	
OPLINGER, O. O.	7905020306			PARKER, W. O.	7905080433	50-269	
OPLINGER, O. O.	7905020510			PARKER, W. O.	7905080566	50-269	
OPLINGER, O. O.	7905020522			PARKER, W. O.	7905080388	50-269	
OPLINGER, O. O.	7905040171			PARKER, W. O.	7905240466	50-269	
OPLINGER, O. O.	7905040186			PARKER, W. O.	7905080523	50-287	
OPLINGER, O. O.	7905040189			PARKER, W. O.	7905110264	50-269	
OPLINGER, O. O.	7905020454			PARKER, W. O.	7905110268	50-269	
OPLINGER, O. O.	7905020483			PARKER, W. O.	7905140189	50-269	
OPLINGER, O. O.	7905020486			PARKER, W. O.	7905240231	50-269	
OPLINGER, O. O.	7905030082			PARKER, W. O.	7905150317	50-269	
OPLINGER, O. O.	7905030087			PARKER, W. O.	7905160361	50-269	
OPLINGER, O. O.	7905040137			PARKER, W. O.	7905140283	50-269	
				PARKER, W. O.	7905140365	50-269	

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
PARKER, W. O	7905140268	50-269		PILANT, J. M.	7905020129	50-298	
PARKER, W. O	7905160389	50-269		PILANT, J. M.	7905020269	50-298	
PARKER, J. P.	7905150534	50-270		PILANT, J. M.	7905080478	50-298	
PARKER, W. O	7905220270	50-269		PILANT, J. M.	7905080487	50-298	
PARKER, W. O	7905220235	50-269		PILANT, J. M.	7905140228	50-298	
PARKER, W. O	7905220398	50-269		PILANT, J. M.	7905150369	50-298	
PARKER, W. O	7905300541	50-269		PILANT, J. M.	7905150384	50-298	
PARKER, W. O	7905220351	50-269		PILANT, J. M.	7905160127	50-298	
PARKER, W. O	7905230487	50-287		PILANT, J. M.	7905230355	50-298	
PARKER, W. O	7905230543	50-269		PIGHKO, D. C.	7905110347	50-488	
PARKER, W. O	7905240593	50-287		PLATO, P.	7905290673		
PARKER, W. O	7905230303	50-269		PLESSET, M. S.	7905240203		
PARKER, W. O	7905240475	50-269		PODOLAK, E. M.	7905100018	50-320	
PARKER, W. O	7905240478	50-269		PODOLAK, E. M.	7905100034	50-320	
PARKER, W. O	7905250401	50-269		PODOLAK, E. M.	7905100017	50-320	
PARKER, W. O	7905250423	50-269		PODOLAK, E. M.	7905100029	50-330	
PARKER, W. O	7905310348	50-269		POIRER, M. R.	7905030175	50-445	
PARKER, W. O.	7905310404	50-287		POIRIER, M. R.	7905140115	50-445	
PARKER, W. O	7905310211	50-269		POIRIER, M. R.	7905140151	50-445	
PARR, O. D.	7905250240	50-368		PORTER, F. L.	7905300208	50-133	
PARR, O. D.	7905100069	50-498		PORTER, H. L.	7905230541		
PARR, O. D.	7905150794	50-387		PORTER, H. L.	7905240921	70-2623	
PARR, O. D.	7905040260	50-373		PORTER, I.	7905300155	50-320	
PARR, O. D.	7905080114			PORTER, I.	7905230018	50-320	
PARR, O. D.	7905300594	50-311		POTAPOV, U.	7905150581		
PARR, O. D.	7905300616	50-392		POTAPOV, U.	7905030144		
PARR, O. D.	7905290066	50-396		POTAPOV, U.	7905290097		
PARR, O. D.	7905300372	50-498		POTAPOV, U.	7905100356		
PARR, O. D.	7905300376	50-438		POTAPOV, U.	7905110398		
PARR, O. D.	7905240226	50-311		POTAPOV, U.	7905100410		
PARR, O. D.	7905310461	50-438		POTAPOV, U.	7905150792		
PARR, O. D.	7905310464	50-396		POTAPOV, U.	7905230581		
PARR, O. D.	7905090304	50-338		POTAPOV, U.	7905100343		
PARRQT, M. H.	7905250519			POTAPOV, U.	7905290085		
PARSONT, M. A.	7904180377	50-320		POTTER, J. P.	7905290099	70-1113	
PARTLOW, J. G.	7905230798	70-371		POTTHOFF, F. H.	7905230247	50-466	
PARTLOW, J. G.	7905300680	70-734		POUCHAL, W. F.	7905290879		
PARTLOW, J. G.	7905020530	70-364		POWELL, R. E.	7905100271	50-445	
PARTLOW, J. G.	7905140141	70-143		POWELL, D. C.	7905030246		NUREG/CR-0523
PARTLOW, J. C.	7905150135	50-143		POWERS, D. A.	7905140149		NUREG/CR-0649
PARTLOW, J. G.	7905240222	70-1113		PRALL, T. F.	7905290671	30-471	
PARTLOW, J. G.	7905230852	70-1151		PRELL, J. A.	7904210768		
PARTLOW, J. G.	7905250184	70-1201		PRESSESKY, A. J.	7905150639	50-482	
PATON, W. D.	7905170162	50-3		PRICE, M. H.	7905250518		
PATON, W. D.	7905100402	50-389		PRICE, W. J.	7905150683	70-1821	
PATON, W. D.	7905100226	50-556		PRICE, M.	7905100082	50-320	
PATON, W. D.	7905240154	50-389		PRICE, D. S.	7905150147	50-259	
PATTERSON, K. P.	7905150458	50-394		PRICHARD, C.	7904210061		
PATTERSON, J. P.	7905150754	70-1308		PRieto, R.	7905090272	50-584	
PAUL, R.	7905290107			PRieto, R.	7905230432	50-584	
PAULUS, R. C.	7905020260	50-320		PRINCE, R. J.	7905110145		
PAULUS, R. C.	7905040296	50-320		QUATTROCHI, J.	7905070497	50-3	
PAULUS, R. C.	7905140253	50-320		QUICK, D.	7905250410	50-302	
PECK, C.	7905040147	50-244		QUINTENZ, T. E.	7905090332	50-219	
PECK, C. H.	7905040187	50-244		QUIRK, J. F.	7905100194		
PECK, C. H.	7905040191	50-244		QUIRK, J. F.	7905100185		
PEGORA, D.	7905090422		NUREG/CR-0642	RADACK, E. D.	7905250503		
PEDERSON, D. E.	7905160381	50-263		RADER, R.	7905100225	27-39	
PEDERSEN, K. S.	7905230470			RADER, R. H.	7905030214	50-395	
PEEPLES, W. P.	7905290110			RADER, R. H.	7905290077	50-498	
PEEPLES, W. P.	7905150238			RADER, R. H.	7905140137	50-395	
PELTIER, I. A.	7905010659	50-358		RAFFETY, S. J.	7905160427	50-409	
PELTIER, I. A.	7905100258	50-322		RAQAN, K. H.	7905140177		
PELTIER, I. A.	7905230558	50-322		RACONE, S.	7905290296	50-280	
PENNER, K. L.	7905020265	50-320		RANDALL, J. D.	7905220097	50-128	
PENNER, P.	7905040330	50-461		RANDOLPH, M. L.	7905240540		7905240540
PERDUE, W. D.	7905140539	50-320		RANGL, C.	7905100013	50-320	
PERKINS, L.	7905240667	50-488		RAY, J. J.	7905160250		
PERKINS, T. J.	7905020367	50-220		RAY, M. J.	7905010494	50-596	
PERKINS, T. J.	7905150511	50-220		REAVES, R.	7905300163	40-8681	
PERLMAN, J.	7905300194			REAVES, T. E.	7905090268		
PERLMAN, J.	7905250114			REAVIS, J. A.	7905220365	50-269	
PERROTTI, D.	7905230527	50-320		REBELOWSKI, T.	7905080110	50-286	
PERRY, R. H.	7905240125			REBELOWSKI, T.	7905110371	50-247	
PERRY, J. C.	7905040458	50-344		REDEMEYER, P. C.	7905100113	40-299	
PERRY, J. C.	7905100270	50-344		REED, C.	7905020421	50-10	
PERRY, J. C.	7905170247	50-344		REED, C.	7905250460		
PERRY, J. C.	7905220293	50-344		REED, C.	7905250280	50-10	
PERRY, J. C.	7905220316	50-344		REED, C.	7905150076	71-8	
PERRY, W. H.	7905010468	50-324		REED, C.	7905250215	50-10	
PERSON, L. B.	7905110258	50-320		REED, C.	7905010523	50-373	
PERSON, L. B.	7905160029	50-320		REED, C.	7904270366	50-10	
PERY, W. H.	7905070084	50-327		REED, C.	7905020312	50-373	
PEGONEN, D. E.	7905070227	50-133		REED, C.	7905240633	50-10	
PETERSON, G.	7905140494	50-285		REED, C.	7905150148	50-10	
PETERSON, G.	7905070545	50-285		REED, C.	7905040502	50-295	
PETERSON, G. R.	7905210259	50-285		REED, C.	7905300242	50-10	
PETERSON, H. E.	7905160382	50-285		REED, C.	7905070567	50-454	
PETERSON, H. E.	7905160406	50-285		REED, C.	7905170237	50-295	
PETERSON, G.	7905220306	50-285		REED, C.	7905190016	50-237	
PETERSON, H. E.	7905300349	50-285		REED, C.	7905220337	50-456	
PETERSON, M.	7905100287			REED, C.	7905220102	50-599	
PETERSON, H. T.	7905160096	50-320		REED, C.	7905250391	50-10	
PETERSON, T.	7905190153	50-320		REED, C.	7905310361	50-373	
PETRICK, N. A.	7905310411	50-482		REGAN, W. H.	7905070087	50-338	
PETRICK, N. A.	7905070649	50-482		REGAN, W. H.	7905150783	50-580	
PETTIT, A. P.	7905100294	50-313		REGAN, W. H.	7905240151	50-471	
PFAFF, S. J.	7905100284	40-6659		REGAN, W. H.	7905220058	50-592	
PFEFFERKORN, W. O.	7905110347	50-488		REGAN, W. H.	7905070316	50-596	
PHILLAN, M. K.	7905150265	71-151		REGAN, W. H.	7905150115	50-596	
PHILLIPS, J. R.	7905030174	50-275		REHM, T. A.	7905150332		
PHILLIPS, J. R.	7905310104	50-275		REHM, T. A.	7905240155		
PICKETT, J. F.	7905300088			REHM, T. A.	7905240153		
PICKERING, T. R.	7905300677			REHM, T. A.	7905300648		
PICKINGTON, C.	7905230744	50-466		REHM, T. A.	7905100278		
PICKLESIMER, M. L.	7905220468			REID, R. H.	7905110023		

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
REID, R. W.	7905250014	50-269		RIGBERG, S.	7905150757	50-358	
REID, R. W.	7905250018	50-269		RIGOR, R. R.	7905250302		
REID, R. W.	7905070011	50-309		RILEY, B. W.	7905230243	50-324	
REID, R. W.	7905070332	50-336		RINACA, J. M.	7905030258	50-338	
REID, R. W.	7905070337	50-336		RINDAL, A.	7905100323		
REID, R. W.	7905070351	50-336		RISCHLING, J. L.	7905070596	50-316	
REID, R. W.	7905150772	50-128		RITSHER, J. A.	7905010447	50-443	
REID, R. W.	7905070231	50-335		RITSHER, J. A.	7905170245	50-443	
REID, R. W.	7905070236	50-335		RITSHER, J. A.	7905210129	50-443	
REID, R. W.	7905070299	50-335		RIVARD, J. B.	7905110267	50-320	
REID, R. W.	7905090300	50-313		ROBERT, A. W.	7905300352	50-320	
REID, R. W.	7905090200	50-302		ROBERTS, D. M.	7905070582	50-3	
REID, R. W.	7905090279	50-77		ROBERTS, D.	7905110205	70-364	
REID, R. W.	7905030155	50-309		ROBERTS, V. M.	7905290516	71-154	
REID, R. W.	7905250076	50-313		ROBERGE, J. C.	7905250528	50-329	45-79/HI24AF
REID, R. W.	7905250079	50-313		ROBERTSON, L.	7905160063	50-320	
REID, R. W.	7905250090	50-313		ROBERTSON, J. S.	7905020161	70-1151	
REID, R. W.	7905080123	50-317		ROBERTSON, J. S. C.	7905070259	70-1201	
REID, R. W.	7905150372	50-317		ROBERTS, H. W.	7905150797		
REID, R. W.	7905290356	50-289		ROBERTS, J. P.	7905250338		
REID, R. W.	7905080130	50-269		ROBERTS, I. C.	7904180171		
REID, R. W.	7905240819	50-309		ROBERTS, I. C.	7905140052	50-320	
REID, R. W.	7905150278	50-335		ROBINSON, J. D.	7905230001	50-320	
REID, R. W.	7905250002	50-317		ROCKENBAUGH, T.	7905310349	50-592	
REID, R. W.	7905250003	50-317		RODGERS, W.	7905230026	50-320	
REID, R. W.	7905250007	50-317		RODI, P. J.	7905230520		
REID, R. W.	7905230836	50-128		RODRIGUEZ, J. P.	7905150411	50-206	
REID, R. W.	7905240982	50-269		RODRIGUEZ, R. J.	7905100281	50-312	
REID, R. W.	7905230263	50-335		ROE, L. E.	7905240671	50-346	
REID, R. W.	7905250049	50-313		ROE, L. E.	7905080416	50-346	
REID, R. W.	7905250055	50-313		ROE, L. E.	7905090353	50-346	
REID, R. W.	7905250065	50-313		ROE, L. E.	7905190031	50-346	
REIFF, D.	7905110229	50-320		ROE, L. E.	7905240586	50-346	
REIFF, D. D.	7905110323	50-320		ROE, L. E.	7905220095	50-346	
REILLY, M. K.	7905250373	50-416		ROE, L. E.	7905230371	50-346	
REINERT, S.	7905290473	50-485		ROE, L. E.	7905240403	50-346	
REINERT, S.	7905310203	50-485		ROE, L. E.	7905290419	50-346	
REIS, H. F.	7905250170	50-498		ROE, L. E.	7905310430	50-346	
REIS, H. F.	7905080311	50-466		ROE, L. E.	7905300483	50-346	
REIS, H. F.	7905080320	50-466		ROE, L. E.	7905310375	50-346	
REIS, H. F.	7905250223	50-466		ROE, L. E.	7905300418	50-346	
REIS, H. F.	7905250476			ROGERS, H. W.	7905240904	71-55	
REIS, H. F.	7905140037	50-466		ROGERS, C. S.	7905240273	50-556	
REIS, H. F.	7905100009	50-38		ROGERS, C. S.	7905150063	50-556	
REIS, H. F.	7905100011	50-389		ROGERS, C.	7905230759	50-556	
REIS, H. F.	7905100019	50-389		ROGERS, C. L.	7905240346	50-295	
REIS, H. F.	7905250228	50-498		ROGERS, W. H.	7905080477	50-321	
REIS, H. F.	7905100391	50-466		ROGERS, R. F.	7905020497	50-321	
REIS, E. J.	7905100248	27-39		ROGERS, L. R.	7905140203		
REIS, E. J.	7905030168	27-39		ROHRER, E.	7905220125	50-346	
REIS, E. J.	7905160039	50-320		ROISHAN, A. Z.	7905080286		
REIS, E. J.	7905240299	27-39		ROISHAN, A. Z.	7905080296		
REIS, E. J.	7905100372	27-39		ROISHAN, A. Z.	7905250458		
REIS, E. J.	7905150362	50-400		ROISHAN, A. Z.	7905240178	50-466	
REITER, E. K.	7905250477	70-1151		ROISHAN, A. Z.	7905240190	50-466	
REITER, E. K.	7905250474	70-1151		ROISHAN, A. Z.	7905030034		
REIZEN, H. S.	7905230304	50-315		ROISHAN, A. Z.	7905240482	70-2623	
REKEMEYER, P. C.	7905010501	50-299		ROISHAN, A. Z.	7905080184	50-437	
REKEMEYER, P. C.	7905290033	40-299		ROISHAN, A. Z.	7905080202	50-437	
REMITCH, F. J.	7905240379	27-39		ROISHAN, A. Z.	7905220458	50-437	
RENBARGER, D. L.	7905070453	50-397		ROISHAN, A. Z.	7905250292	50-437	
RENBARGER, D. L.	7905250467			ROISHAN, A. Z.	7905140079	70-2623	
RENBARGER, D. L.	7905040294			ROISHAN, A. Z.	7905140094	50-320	
RENBARGER, D. L.	7905010478	50-397		ROISHAN, A. Z.	7905290679	70-2623	
RENBARGER, D. L.	7905040379	50-508		ROLLINS, J. D.	7905020252	71-6698	
RENBARGER, D. L.	7905010486	50-397		ROMANO, F. R.	7905210058	50-334	
RENBARGER, D. L.	7905090069	50-397		ROMANO, A. J.	7905150219		NUREQ/CR-0513
RENBARGER, D. L.	7905070499	50-397		ROME, A. H.	7905070651	50-219	
RENBARGER, D. L.	7905090284	50-508		ROOD, H.	7905230589	50-361	
RENBARGER, D. L.	7905040601	50-397		ROOD, H. E.	7905290411	50-361	
RENBARGER, D. L.	7905110232	50-397		ROOK, H. E.	7905240747	50-275	
RENBARGER, D. L.	7905160337	50-508		ROOK, H. F.	7905240768	50-275	
RENBARGER, D. L.	7905190067	50-460		ROPSON, D. J.	7905100292	50-308	
RENBARGER, D. L.	7905190076	50-397		ROSENFIELD, A. R.	7905230214		7905250214
RENBARGER, D. L.	7905190117	50-397		ROSENTHAL, A. S.	7905080163		
RENBARGER, D. L.	7905230534	50-460		ROSENBERG, A. S.	7905150561	50-445	
RENBARGER, D. L.	7905230537	50-397		ROSLIE, E.	7905250279	50-344	
RENY, R. H.	7905010549	50-309		ROSLIE, E.	7905250273	50-344	
RESNIKOFF, M. R.	7905230768	50-295		ROSLIE, E.	7905230550	50-344	
REST, J.	7905110348	50-320		ROSLIE, E.	7905230546	50-344	
REVELEY, W. T.	7905100152	50-316		ROSS, D. H.	7905290071	71-9010	
REYNOLDS, N. S.	7905100228	50-445		ROSS, D. A.	7905230349	50-219	
REYNOLDS, N. S.	7905150821	50-445		ROSS, D. A.	7905040481	50-219	
REYNOLDS, N. S.	7905100193	50-445		ROSS, D. A.	7905140243	50-219	
REYNOLDS, N. S.	7905230639	50-445		ROSS, D. A.	7905150472	50-219	
REYNOLDS, L. E.	7905240187	71-6244		ROSS, D. A.	7905160369	50-219	
REYNOLDS, L. E.	7905241004	27-39		ROSS, D. A.	7905160374	50-219	
REYNOLDS, L. E.	7905300636	71-6244		ROSS, D. A.	7905250077	50-219	
REYNOLDS, N. S.	7905240901	50-513		ROSS, D. A.	7905210217	50-219	
RHODES, L.	7905100332	50-592		ROSS, D. A.	7905210281	50-219	
RHODE, G. K.	7905150597			ROSS, D. A.	7905220388	50-219	
RHODE, G. K.	7905080414	50-220		ROSS, D. A.	7905290017	50-219	
RHOW, S. K.	7905010561			ROSS, D. A.	7905290175	50-219	
RIB, L. N.	7905110235	50-320		ROSS, D. F.	7905040472	50-280	VEP-FRD-32
RIB, L. N.	7905110237	50-320		ROSS, T. K.	7905190252	50-320	
RIB, L. N.	7905110263	50-320		ROSS, D. F.	7905210238	50-320	
RICE, J. K.	7905140226	50-445		ROSS, D. F.	7905100384	50-320	
RICHARDS, C.	7905240515	50-358		ROSS, D. F.	7905240130		
RICHARDSON, J. E.	7905110281	50-320		ROSS, D. F.	7905241001	50-548	
RICKARD, C. L.	7905150008			ROSS, D. F.	7905080361	50-491	
RIDGWAY, K. R.	7905010336	50-155		ROSS, D. F.	7905230037	50-320	
RIDGWAY, K. R.	7905290569	50-155		ROSS, D. F.	7905230048	50-320	
RIEDEL, W. R.	7905250168	40-8681		ROSS, D. F.	7905230212	50-320	
RIGBERG, S.	7905290464	50-358		ROSS, D. F.	7905250011	40-2289	
RIGBERG, S.	7905290468	50-358		ROSBACH, L. W.	7905250011		
RIGBERG, S.	7905290520	50-358		ROSTOCZY, Z. R.	7905110061		

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
ROBITOICY, Z. R.	7905110226			BALTZMAN, J.	7905160167	50-83	
ROBITOICY, Z. R.	7905110068	50-269		BALTZMAN, J.	7905160170	50-263	
ROBITOICY, Z. R.	7905110074	50-269		BALTZMAN, J.	7905160172	50-235	
ROTHE, P. H.	7905020154		7905020154	BALTZMAN, J.	7905160176	50-267	
ROTHE, P. H.	7905030221		NUREQ/CR-0599	BALTZMAN, J.	7905160180	50-293	
ROTHE, P. H.	7905240552		7905240552	BALTZMAN, J.	7905160183	50-261	
ROTHFLEISCH, J.	7905240658	40-8698		BALTZMAN, J.	7905160186	50-244	
ROTHFLEISCH, J. E.	7905250022	40-8698		BALTZMAN, J.	7905160187	50-344	
ROUSE, L. C.	7905090164	70-2623		BALTZMAN, J.	7905160189	50-241	
ROUSE, L. C.	7905290090	50-269		BALTZMAN, J.	7905160192	50-139	
ROUSE, L. C.	7905240370	70-1308		BALTZMAN, J.	7905160193	50-393	
ROUSE, L. C.	7905240383	70-1308		BALTZMAN, J.	7905160198	50-333	
ROUSE, L. C.	7905090138	70-2623		BALTZMAN, J.	7905160199	50-334	
ROUSE, L. C.	7905150669	70-1821		BALTZMAN, J.	7905160203	50-113	
ROUSSELOT, M. C.	7905250335	50-275		BALTZMAN, J.	7905160205	50-134	
ROY, D. H.	7905190223	50-320		BALTZMAN, J.	7905160207	50-129	
ROY, D. H.	7905230507	50-320		BALTZMAN, J.	7905160215	50-271	
ROY, D. H.	7905190068	50-320		BALTZMAN, J.	7905160217	50-433	
ROY, D. H.	7905190079	50-320		BALTZMAN, J.	7905160221	50-326	
ROY, D. H.	7905080372			BALTZMAN, J.	7905160222	50-394	
RUDDLEPH, J. J.	7905220121	50-346		BALTZMAN, J.	7905160224	50-348	
RUETER, D. A.	7905020343	50-368		BALTZMAN, J.	7905160230	50-327	
RUETER, D. A.	7905100318	50-313		BALTZMAN, J.	7905160231	50-346	
RUETER, D. A.	7905310387	50-368		BALTZMAN, J.	7905160232	50-538	
RUETHER, J. C.	7905210283	50-306		BALTZMAN, J.	7905160233	50-360	
RUITER, O. H.	7905150567	50-305		BALTZMAN, J.	7905160235	50-142	
RUITER, O. H.	7905300399	50-305		BALTZMAN, J.	7905160236	50-112	
RUITER, O. H.	7905310366	50-305		BALTZMAN, J.	7905160238	50-208	
RUSCHE, B.	7905230005	50-320		BALTZMAN, J.	7905160240	50-294	
RUSCHE, B.	7905230024	50-320		BALTZMAN, J.	7905160243	50-312	
RUSH, B.	7905150293	50-363		BALTZMAN, J.	7905160244	50-274	
RUSHMORE	7905150291	50-220		BALTZMAN, J.	7905160249	50-87	
RUBB, O. D.	7905160223	50-320		BALTZMAN, J.	7905160252	50-302	
RUBSELL, L. B.	7905100348	50-317		BALTZMAN, J.	7905160254	50-406	
RUBSELL, L. B.	7905110122	50-317		BALTZMAN, J.	7905160258	50-182	
RUBSELL, L. B.	7905010524	50-317		BALTZMAN, J.	7905160260	50-193	
RUBSELL, L. B.	7905080494	50-318		BALTZMAN, J.	7905160265	50-288	
RUBSELL, L. B.	7905080555	50-317		BALTZMAN, J.	7905160266	50-225	
RUBSELL, L. B.	7905190080	50-317		BALTZMAN, J.	7905160268	50-223	
RUBSELL, L. B.	7905290426	50-317		BALTZMAN, J.	7905160272	50-358	
RYAN, C. R.	7905090007	50-498		BALTZMAN, J.	7905160273	50-305	
RYAN, T. O.	7905240127	50-445		BALTZMAN, J.	7905160275	50-331	
RYAN, T. O.	7905070040	50-445		BALTZMAN, J.	7905160276	50-146	
RYAN, T. O.	7905070045	50-445		BALTZMAN, J.	7905160278	50-47	
RYAN, R. O.	7905250447			BALTZMAN, J.	7905160280	50-30	
RYAN, R. O.	7905090217	50-320		BALTZMAN, J.	7905160281	50-184	
RYAN, R. O.	7905090252	50-320		BALTZMAN, J.	7905160282	50-188	
RYAN, R. O.	7905140313			BALTZMAN, J.	7905160285	50-29	
RYAN, R. O.	7905140320			BALTZMAN, J.	7905160286	50-220	
RYAN, R. O.	7905140325			BALTZMAN, J.	7905160289	50-213	
RYAN, R. O.	7905140329			BALTZMAN, J.	7905160291	50-155	
RYAN, R. O.	7905140331			BALTZMAN, J.	7905160292	50-219	
RYAN, R. O.	7905090244	50-320		BALTZMAN, J.	7905160298	50-133	
RYAN, R. O.	7905090241	50-320		BALTZMAN, J.	7905160300	50-27	
RYAN, R. O.	7905090240	50-320		BALTZMAN, J.	7905160306	50-156	
RYAN, R. J.	7905090237	50-320		BALTZMAN, J.	7905160308	50-124	
BAAR, R. P.	7905090400	50-320		BALTZMAN, J.	7905160311	50-201	
BABOL, A. R.	7905040146	50-387		BALTZMAN, J.	7905160314	50-206	
BACHSE, J.	7905240175	71-299		BALTZMAN, J.	7905160320	50-94	
BACHSE, J.	7905240183	71-299		BALTZMAN, J.	7905160322	50-20	
BALCHON, B.	7905090048		NUREQ-0553	BALTZMAN, J.	7905160326	50-106	
BALTZMAN, J.	7905030154	50-445		BALTZMAN, J.	7905160328	50-5	
BALTZMAN, J.	7905140404	50-10		BALTZMAN, J.	7905160329	50-252	
BALTZMAN, J.	7905140407	50-3		BALTZMAN, J.	7905160332	50-57	
BALTZMAN, J.	7905140415	50-171		BALTZMAN, J.	7905160334	50-284	
BALTZMAN, J.	7905140422	50-243		BALTZMAN, J.	7905160336	50-123	
BALTZMAN, J.	7905140431	50-266		BALTZMAN, J.	7905160339	50-186	
BALTZMAN, J.	7905140438	50-269		BALTZMAN, J.	7905160341	50-2	
BALTZMAN, J.	7905140444	50-280		BALTZMAN, J.	7905160343	50-59	
BALTZMAN, J.	7905140449	50-250		BALTZMAN, J.	7905160345	50-187	
BALTZMAN, J.	7905140456	50-254		BALTZMAN, J.	7905160348	50-34	
BALTZMAN, J.	7905140462	50-259		BALTZMAN, J.	7905160351	50-22	
BALTZMAN, J.	7905140470	50-295		BALTZMAN, J.	7905160353	50-16	
BALTZMAN, J.	7905140477	50-282		BALTZMAN, J.	7905160355	50-192	
BALTZMAN, J.	7905140481	50-315		BALTZMAN, J.	7905160357	50-264	
BALTZMAN, J.	7905140486	50-289		BALTZMAN, J.	7905230456	50-62	
BALTZMAN, J.	7905140489	50-313		BALTZMAN, J.	7905300034	50-72	
BALTZMAN, J.	7905140493	50-321		BALTZMAN, J.	7905300038	50-97	
BALTZMAN, J.	7905140499	50-317		BALTZMAN, J.	7905300045	50-160	
BALTZMAN, J.	7905140508	50-324		BALTZMAN, J.	7905300052	50-84	
BALTZMAN, J.	7905140512	50-273		BALTZMAN, J.	7905300059	50-32	
BALTZMAN, J.	7905140523	50-338		BALTZMAN, J.	7905300063	50-5	
BALTZMAN, J.	7905140538	50-369		BALTZMAN, J.	7905300069	50-8	
BALTZMAN, J.	7905140546	50-373		BALTZMAN, J.	7905300190	50-18	
BALTZMAN, J.	7905150360	50-309		BALTZMAN, J.	7905300202	50-37	
BALTZMAN, J.	7905150365	50-298		BALTZMAN, J.	7905300714	50-13	
BALTZMAN, J.	7905150367	50-272		BALTZMAN, J.	7905140281	50-72	
BALTZMAN, J.	7905150370	50-151		BALTZMAN, J.	7905190171	50-30	
BALTZMAN, J.	7905150373	50-170		BALTZMAN, J.	7905150308	50-18	
BALTZMAN, J.	7905150375	50-262		BALTZMAN, J.	7905150382	70-734	
BALTZMAN, J.	7905150376	50-166		BALTZMAN, J.	7905160297	50-131	
BALTZMAN, J.	7905150377	50-199		BALTZMAN, J.	7905150363	50-124	
BALTZMAN, J.	7905150386	50-141		BALTZMAN, J.	7905190049	50-193	
BALTZMAN, J.	7905160100	50-131		BALTZMAN, J.	7905220354	50-267	
BALTZMAN, J.	7905160106	50-116		BALTZMAN, J.	7905240675	50-406	
BALTZMAN, J.	7905160108	70-1143		BALTZMAN, J.	7905310232	50-27	
BALTZMAN, J.	7905160116	70-364		BANDER, R. D.	7904300319		
BALTZMAN, J.	7905160117	50-180		BANDER, H. E.	7905150273	50-382	
BALTZMAN, J.	7905160122	50-77		BANDIFORTH, D.			
BALTZMAN, J.	7905160123	70-1237		BANDOL, B. A.	7905010561		
BALTZMAN, J.	7905160148	70-824		SANDVIK, R. H.	7905250180	50-322	
BALTZMAN, J.	7905160151	70-754		SANGER, H. B.	7905240874	50-518	
BALTZMAN, J.	7905160157	50-409		SARATHY, P. K.	7905150273	50-382	
BALTZMAN, J.	7905160160	50-148		SATTERFIELD, R. M.	7904300123	50-330	
BALTZMAN, J.	7905160162	50-333		BAUERLENDER, O. H.	7905090428		NUREQ/CR-0454
BALTZMAN, J.	7905160164	50-285		BAUER, R. C.	7905240491	50-327	
				SCARANO, R. A.	7905290488	40-2259	

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
SCARANO, R A	7903250176	40-2259		SCHWENGER, A	7905080080	50-250	
SCARANO, R A	7905240592	40-8681		SCINTO, J F	7905090150	50-491	
SCARANO, R A	7905220039	40-2259		SCINTO, J F	7905080249		
SCARANO, R A	7905250011	40-2259		SCINTO, J	7905110203	50-320	
SCARANO, R A	7905240849	40-2259		SCINTO, J F	7905160163	50-320	
SCARANO, R A	7905150806	40-8502		SCINTO, J	7905160050	50-320	
SCARANO, R A	7905100059			SCINTO, J F	7905010115	50-320	
SCARANO, R A	7905240496			SCINTO, J F	7905160191	50-320	
SCARANO, R A	7905240398			SCINTO, J F	7905110418	50-320	
SCHAFER, K H	7905070406			SCOTT, J M	7905240232	50-424	
SCHAUKE, R	7905020037	50-320		SCOTT, J M	7905300177	50-466	
SCHAUER, F	7905080263			SCOTT, J M	7905230242	50-466	
SCHENDEL, K R	7905150592			SCOTT, J M	7905110339	50-466	
SCHENDEL, K R	7905240267	40-8502		SCOTT, S M	7905110341	50-466	
SCHERER, A E	7905220080			SCOTT, R	7904210774		
SCHERER, A E	7905070564			SCOTT, H J	7905230372	27-39	
SCHERER, A E	7905110288			SCOUTEN, J W	7905010654	50-320	
SCHERER, A E	7905300368			SEELINGER, J L	7905110079	50-320	
SCHERER, A E	7905300526			SEIDE, P	7905030051		
SCHIFFER, R O	7904170521			SEIDLE, W C	7905070191	50-445	
SCHMIDT, A D	7905150241	50-335		SEIDLE, W C	7905010302	50-482	
SCHMIDT, A D	7905080467	50-250		SEIDLE, W C	7905010365	50-445	
SCHMIDT, A D	7905080354	50-251		SEIDLE, W C	7905010376	50-498	
SCHMIDT, A D	7905080367	50-251		SEIDLE, W C	7905150855	50-445	
SCHMIDT, A D	7905090067	50-250		SEIDLE, W C	7905150864	50-556	
SCHMIDT, A D	7905090074	50-250		SEIDLE, W C	7905150841	50-382	
SCHMIDT, A D	7905090062	50-335		SEIDLE, W C	7905030085	50-445	
SCHMIDT, A D	7905220091	50-335		SEIDLE, W C	7905030087	50-458	
SCHMIDT, A D	7905220103	50-250		SEIDLE, W C	7905030094	50-498	
SCHMIDT, A D	7905220122	50-250		SEIDLE, W C	7905030097	50-482	
SCHMIDT, A D	7905230388	50-250		SEIDLE, W C	7905030113	50-382	
SCHMITT, R C	7905240886		NUREQ/CR-07B5	SEIDLE, W C	7905030091	50-458	
SCHNEIDER, R R	7905100421	50-220		SEIDLE, W C	7905030095	50-498	
SCHNEIDER, R R	7905070401	50-220		SEIDLE, W C	7905030099	50-482	
SCHNEIDER, R R	7905150808	50-220		SEIDLE, W C	7905030102	50-382	
SCHNEIDER, R R	7905160392	50-220		SEIDLE, W C	7905030107	50-445	
SCHNEIDER, R R	7905230295	50-220		SEIDLE, W C	7905030139	50-458	
SCHNEIDER, R R	7905230478	50-220		SEIDLE, W C	7905030143	50-498	
SCHNEIDER, F W	7905070140	50-272		SEIDLE, W C	7905030146	50-482	
SCHNEIDER, F W	7905290065	50-272		SEIDLE, W C	7905030147	50-382	
SCHNEIDER, F W	7905290072	50-272		SEIDLE, W C	7905030151	50-445	
SCHNIEDER, J R	7905310394	50-286		SEIDLE, W C	7905030177	50-458	
SCHOPPMAN, M A	7905080471	50-250		SEIDLE, W C	7905030118	50-498	
SCHOPPMAN, M A	7905080359	50-251		SEIDLE, W C	7905030119	50-482	
SCHOPPMAN, M A	7905080371	50-251		SEIDLE, W C	7905030122	50-382	
SCHOPPMAN, M A	7905090072	50-250		SEIDLE, W C	7905030124	50-445	
SCHOPPMAN, M A	7905090081	50-250		SEIDLE, W C	7905030186	50-458	
SCHOPPMAN, M A	7905090064	50-335		SEIDLE, W C	7905030189	50-498	
SCHOPPMAN, M A	7905220098	50-335		SEIDLE, W C	7905030193	50-482	
SCHOPPMAN, M A	7905220113	50-250		SEIDLE, W C	7905030197	50-382	
SCHROEDER, F	7905220392	50-528		SEIDLE, W C	7905030201	50-445	
SCHULER, U	7905070136	50-320		SEIDLE, W C	7905030057	50-482	
SCHULTZ, W B	7905080036			SEIDLE, W C	7905030066	50-382	
SCHULTZ, W B	7905080047			SEIDLE, W C	7905030071	50-498	
SCHUMACHER, M C	7905030046	50-155		SEIDLE, W C	7905030076	50-445	
SCHUTT, R	7905230365	50-596		SEIDLE, W C	7905030238	50-458	
SCHUTT, R	7905230370	50-596		SEIDLE, W C	7905030240	50-498	
SCHUTT, D M	7905220067	70-820		SEIDLE, W C	7905030248	50-498	
SCHUTT, R	7905240160	50-596		SEIDLE, W C	7905030250	50-382	
SCHWARTZ, M D	7905290002	50-498		SEIDLE, W C	7905030254	50-445	
SCHWARTZ, H	7905230270	40-8695		SEIDLE, W C	7905020516	50-498	
SCHWARTZ, H	7905290258	40-8695		SEIDLE, W C	7905020524	50-382	
SCHWARTZ, S A	7905300053	50-320		SEIDLE, W C	7905020528	50-458	
SCHWENDIMAN, L C	7905150777		7905150777	SEIDLE, W C	7905020534	50-482	
SCHWENK, E B	7905240113		7905240113	SEIDLE, W C	7905020538	50-458	
SCHWEIBINZ, E R	7905090093	50-546		SEIDLE, W C	7905020544	50-482	
SCHWENGER, A	7905070311	50-286		SEIDLE, W C	7905020548	50-458	
SCHWENGER, A	7905070315	50-286		SEIDLE, W C	7905020550	50-498	
SCHWENGER, A	7905040307	50-261		SEIDLE, W C	7905020558	50-482	
SCHWENGER, A	7905070109	50-250		SEIDLE, W C	7905020562	50-445	
SCHWENGER, A	7905070114	50-250		SEIDLE, W C	7905020566	50-482	
SCHWENGER, A	7905070124	50-250		SEIDLE, W C	7905020570	50-445	
SCHWENGER, A	7905020490	50-272		SEIDLE, W C	7905040575	50-482	
SCHWENGER, A	7905140313	50-266		SEIDLE, W C	7905040580	50-382	
SCHWENGER, A	7905140333	50-266		SEIDLE, W C	7905040584	50-445	
SCHWENGER, A	7905240893	50-303		SEIDLE, W C	7905240686	50-498	
SCHWENGER, A	7905240903	50-303		SEIDLE, W C	7905290631	50-445	
SCHWENGER, A	7905240911	50-303		SEIDLE, W C	7905070046	50-482	
SCHWENGER, A	7905090065	50-266		SEIDLE, W C	7905070180	50-458	
SCHWENGER, A	7905090068	50-266		SEIDLE, W C	7905070185	50-498	
SCHWENGER, A	7905090076	50-266		SEIDLE, W C	7905070188	50-382	
SCHWENGER, A	7905250183	50-293		SEIDLE, W C	7905070193	50-445	
SCHWENGER, A	7905250190	50-293		SEIDLE, W C	7905310206	50-482	
SCHWENGER, A	7905240373	50-303		SEIDLE, W C	7905310216	50-498	
SCHWENGER, A	7905240378	50-303		SEIDLE, W C	7905310222	50-382	
SCHWENGER, A	7905240382	50-303		SEIDLE, W C	7905310226	50-458	
SCHWENGER, A	7905070121	50-261		SEIDLE, W C	7905310230	50-445	
SCHWENGER, A	7905070125	50-261		SEIDLE, W C	7905240374	50-382	
SCHWENGER, A	7905070130	50-261		SEIDLE, W C	7905240385	50-498	
SCHWENGER, A	7905090079	50-348		SEIDLE, W C	7905240394	50-458	
SCHWENGER, A	7905090084	50-348		SEIDLE, W C	7905240399	50-445	
SCHWENGER, A	7905100439	50-266		SEIDLE, W C	7905240418	50-482	
SCHWENGER, A	7905100442	50-266		SEIDLE, W C	7905250372	27-39	
SCHWENGER, A	7905100446	50-266		SEIDLE, W C	7905150256	50-295	
SCHWENGER, A	7905240308	50-282		SEKULER, S N	7905310273		
SCHWENGER, A	7905240322	50-282		SEKULER, S N	7905190248	50-295	
SCHWENGER, A	7905240333	50-282		SEKULER, S N	7905290107	50-596	
SCHWENGER, A	7905290050	50-303		SELLS, D E	7905150731		
SCHWENGER, A	7905290054	50-303		SELLS, D E	7905290196	50-3	
SCHWENGER, A	7905290064	50-303		SEWELL, R B	7905100660	40-8698	
SCHWENGER, A	7905290425	50-295		SEYFRIT, K V	7905150079	50-313	
SCHWENGER, A	7905290440	50-295		SEYFRIT, K V	7905150083	50-299	
SCHWENGER, A	7905230356	50-286		SEYFRIT, K V	7905150085	50-285	
SCHWENGER, A	7905080063	50-250		SEYFRIT, K V	7905150086	50-267	
SCHWENGER, A	7905080069	50-250		SEYFRIT, K V	7905010448	50-313	

PERSONAL AUTHOR INDEX

349

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
BEYFRIT, K. V.	7905010451	50-298		SHALLER, D. V.	7905040611	50-315	
BEYFRIT, K. V.	7905010453	50-285		SHALLER, D. V.	7905070583	50-316	
BEYFRIT, K. V.	7905010454	50-267		SHALLER, D. V.	7905070598	50-315	
BEYFRIT, K. V.	7905020440	50-285		SHALLER, D. V.	7905110120	50-315	
BEYFRIT, K. V.	7905020441	50-313		SHALLER, D. V.	7905130423	50-315	
BEYFRIT, K. V.	7905020444	50-298		SHALLER, D. V.	7905150488	50-316	
BEYFRIT, K. V.	7905020446	50-267		SHALLER, D. V.	7905240602	50-315	
BEYFRIT, K. V.	7905010276	50-382		SHALLER, D. V.	7905170248	50-315	
BEYFRIT, K. V.	7905010277	50-458		SHALLER, D. V.	7905170261	50-316	
BEYFRIT, K. V.	7905010279	50-498		SHALLER, D. V.	7905210135	50-315	
BEYFRIT, K. V.	7905010280	50-482		SHALLER, D. V.	7905220320	50-315	
BEYFRIT, K. V.	7905010281	50-445		SHALLER, D. V.	7905230325	50-316	
BEYFRIT, K. V.	7905020268	50-285		SHALLER, D. V.	7905310367	50-316	
BEYFRIT, K. V.	7905020273	50-298		SHANAHAN, W. R.	7905280521		
BEYFRIT, K. V.	7905020277	50-313		SHANNON, P. C.	7905300756	50-280	
BEYFRIT, K. V.	7905020279	50-267		SHAPAR, H. K.	7905160109		
BEYFRIT, K. V.	7905020411	50-267		SHAPAR, H. K.	7905130327		
BEYFRIT, K. V.	7905020413	50-285		SHAPAR, H. K.	7905010215	50-358	
BEYFRIT, K. V.	7905020415	50-298		SHAPAR, H. K.	7905240412	50-358	
BEYFRIT, K. V.	7905020419	50-313		SHAPAR, H. K.	7905160105		
BEYFRIT, K. V.	7905020428	50-298		SHAPAR, H. K.	7905300403	50-320	SECY-79-235
BEYFRIT, K. V.	7905020431	50-267		SHAPAR, H. K.	7905160017	50-320	
BEYFRIT, K. V.	7905020434	50-285		SHAPAR, H. K.	7905090213	50-320	
BEYFRIT, K. V.	7905020436	50-313		SHAPER, H. K.	7905230713		
BEYFRIT, K. V.	7905140143	50-267		SHAPIRO, R.	7905240941	50-322	
BEYFRIT, K. V.	7905140146	50-285		SHAPIRO, R.	7905240915	50-322	
BEYFRIT, K. V.	7905140148	50-298		SHEA, R.	7905240001		SECY-79-102A
BEYFRIT, K. V.	7905140152	50-313		SHEA, J. R.	7905240039		SECY-79-120A
BEYFRIT, K. V.	7905150045	50-313		SHEA, J. R.	7905250033		SECY-79-183A
BEYFRIT, K. V.	7905150046	50-298		SHEA, J. R.	7905240147		SECY-79-248
BEYFRIT, K. V.	7905150049	50-285		SHEA, J. R.	7905240173		SECY-79-249
BEYFRIT, K. V.	7905150051	50-267		SHEA, J. R.	7905220051		SECY-79-256
BEYFRIT, K. V.	7905010455	50-458		SHEA, J. R.	7905230820		SECY-79-142A
BEYFRIT, K. V.	7905010457	50-498		SHEA, J. R.	7905230822		SECY-79-255
BEYFRIT, K. V.	7905010459	50-482		SHEA, J. R.	7905240281		SECY-79-258
BEYFRIT, K. V.	7905010461	50-382		SHEA, J. R.	7905230835		
BEYFRIT, K. V.	7905010464	50-445		SHEA, J. R.	7905300111	50-320	
BEYFRIT, K. V.	7905030104	50-482		SHEA, J. R.	7905100033		SECY-79-270
BEYFRIT, K. V.	7905030131	50-458		SHEA, J. R.	7905100415		SECY-79-269
BEYFRIT, K. V.	7905030134	50-382		SHEA, J. R.	7905230533		SECY-79-271
BEYFRIT, K. V.	7905030138	50-498		SHEA, J. R.	7905250264	40-8695	SECY-79-268
BEYFRIT, K. V.	7905030140	50-445		SHEA, J. R.	7905240371		SECY-79-28814
BEYFRIT, K. V.	7905210030	50-320		SHEA, J. R.	7905100230		
BEYFRIT, K. V.	7905210035	50-320		SHEA, J. R.	7905250207		
BEYFRIT, K. V.	7905140088	50-368		SHEA, J. R.	7905150311		
BEYFRIT, K. V.	7905040486	50-285		SHEA, J. R.	7905230537		SECY-79-272
BEYFRIT, K. V.	7905040488	50-313		SHEA, J. R.	7905250291		
BEYFRIT, K. V.	7905040489	50-458		SHEDECOR, E.	7905300426	50-344	
BEYFRIT, K. V.	7905040492	50-498		SHEDELOSKY, J. T.	7905240704	50-245	
BEYFRIT, K. V.	7905040494	50-482		SHEKETOFF, C.	7905300615	50-271	
BEYFRIT, K. V.	7905040496	50-382		SHEKETOFF, C.	7905300607	50-271	
BEYFRIT, K. V.	7905040498	50-267		SHELLEY, W. J.	7905090425	40-8027	
BEYFRIT, K. V.	7905040501	50-445		SHEPARD, A. M.	7905290083	50-443	
BEYFRIT, K. V.	7905040557	50-298		SHERMAN, F. L.	7905240078	70-33	
BEYFRIT, K. V.	7905040606	50-313		SHERWOOD, G. O.	7905080440		
BEYFRIT, K. V.	7905040610	50-458		SHERWOOD, G. O.	7905140274		
BEYFRIT, K. V.	7905040613	50-498		SHERWOOD, G. O.	7905300532		
BEYFRIT, K. V.	7905040617	50-482		SHERWOOD, G. O.	7905310339		
BEYFRIT, K. V.	7905040618	50-382		SHEWMON, P. O.	7905140012	50-320	
BEYFRIT, K. V.	7905040621	50-298		SHEWMON, P. O.	7905290262		
BEYFRIT, K. V.	7905040623	50-285		SHIDLER, J. J.	7905080516	50-482	
BEYFRIT, K. V.	7905040627	50-267		SHIER, W. O.	7905100021		7905100021
BEYFRIT, K. V.	7905040629	50-445		SHIER, W. O.	7905100235	50-309	BNL-NUREG-25781
BEYFRIT, K. V.	7905070043	50-313		SHIMBARK, R. E.	7905250407	50-409	
BEYFRIT, K. V.	7905070050	50-458		SHIPLEY, D. B.	7905030015		NUREG/CR-0426 V1
BEYFRIT, K. V.	7905070055	50-498		SHIVELY, C. N.	7905130601	50-368	
BEYFRIT, K. V.	7905070062	50-482		SHIVELY, C. N.	7905140176	50-368	
BEYFRIT, K. V.	7905070066	50-382		SHIVELY, C. N.	7905140182	50-368	
BEYFRIT, K. V.	7905070072	50-298		SHIVELY, C. N.	7905140185	50-368	
BEYFRIT, K. V.	7905070073	50-285		SHIVELY, C. N.	7905170239	50-368	
BEYFRIT, K. V.	7905070077	50-267		SHIVELY, C. N.	7905140263	50-313	
BEYFRIT, K. V.	7905070080	50-445		SHIVELY, C. N.	7905130580	50-368	
BEYFRIT, K. V.	7905010435	50-382		SHIVELY, C. N.	7905130587	50-368	
BEYFRIT, K. V.	7905010440	50-445		SHIVELY, C. N.	7905170232	50-368	
BEYFRIT, K. V.	7905010441	50-498		SHIVELY, C. N.	7905170259		
BEYFRIT, K. V.	7905010443	50-458		SHIVELY, C. N.	7905220400	50-368	
BEYFRIT, K. V.	7905090096	50-313		SHIVELY, C. N.	7905220405	50-368	
BEYFRIT, K. V.	7905090098	50-458		SHIVELY, C. N.	7905290109	50-313	
BEYFRIT, K. V.	7905090099	50-498		SHIVELY, C. N.	7905300517	50-368	
BEYFRIT, K. V.	7905090100	50-482		SHIVELY, C. N.	7905160325	50-317	
BEYFRIT, K. V.	7905090101	50-382		SHOEMAKER, C. L.	7905110026		
BEYFRIT, K. V.	7905090103	50-298		SHORR, P. R.	7905210277	50-367	
BEYFRIT, K. V.	7905090104	50-285		SHORB, E. M.	7905290222	50-285	
BEYFRIT, K. V.	7905090106	50-267		SHORT, T. E.	7905150211	50-285	
BEYFRIT, K. V.	7905090108	50-445		SHORT, T. E.	7905230618	50-285	
BEYFRIT, K. V.	7905030265	50-313		SHORT, T. E.	7905100128	50-285	
BEYFRIT, K. V.	7905030267	50-458		SHORT, T. E.	7905240672	50-285	
BEYFRIT, K. V.	7905030271	50-498		SHORT, T. E.	7905290499	50-285	
BEYFRIT, K. V.	7905030273	50-482		SHORT, T. E.	7905090046	50-285	
BEYFRIT, K. V.	7905030274	50-382		SHORT, T. E.	7905090363	50-285	
BEYFRIT, K. V.	7905030277	50-298		SHORT, T. E.	7905140238	50-285	
BEYFRIT, K. V.	7905030280	50-285		SHORT, T. E.	7905150319	50-285	
BEYFRIT, K. V.	7905030282	50-267		SHORT, T. E.	7905230458	50-285	
BEYFRIT, K. V.	7905030283	50-445		SHORT, T. E.	7905310248	50-320	
BEYFRIT, K. V.	7905010446	50-482		SHORT, T. E.	7905030210	50-320	
BEYFRIT, K. V.	7905080346	50-313		SIESS, C.	7905100052	50-409	
BEYFRIT, K. V.	7905080348	50-368		SIOH, H.	7905030332	70-1201	
BEYFRIT, K. V.	7905080352	50-298		SILK, E. J.	7905070245	71-9132	
BEYFRIT, K. V.	7905080354	50-285		SIMCHUK, J. D.	7905150786	50-320	
BEYFRIT, K. V.	7905080355	50-267		SIMON, H. R.	7905020447		
BEYFRIT, K. V.	7905240886			SIMONS, D. B.	7905070213	50-255	
SHACKELFORD, B.	7905300364	50-275		SINCLAIR, M.	7905290691	50-309	
SHACKELFORD, B.	7905150053	50-312		SJOGREN, R. M.	7905150520	50-271	
SHAFER, H. D.	7905250410	50-302		SJOGREN, R. M.	7905180343	50-29	
SHALLER, D. V.	7905250352	50-315		SJOGREN, R. M.	7905150337		
SHALLER, D. V.	7905040001	50-316		SKARUPA, J. D.	7905250265		

NUREG/CR-0785

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
SKOGEN, F. B	7903100290	50-305	KN-NF-79-27	SPENCER, W. C.	7903070473	50-280	
SKOLDS, J. L.	7903020471	50-339		SPENCER, W. C.	7903070610	50-280	
SLAGOLE, E. L.	7903220426	50-320		SPENCER, W. C.	7903250092	50-280	
SLICKEY, F. K.	7903150545	50-445		SPENCER, W. C.	7903250132	50-280	
SLOBODIEN, M. J.	7903210108	50-320		SPESBARD, R. L.	7903150134	50-331	
SLOBODIEN, M. J.	7903210144	50-320		SPRAUL, J.	7903250122		
SLOBODIEN, M. J.	7903210247	50-320		STACHOM, E. O.	7903230818	50-522	
SLOBODIEN, M. J.	7903210246	50-320		STAENBERG, M. R.	7903100157	50-275	
SLOBODIEN, M. J.	7903210293	50-320		STAFFA, R. W.	7903100244	50-321	
SLOCUM, J. J.	7903140527	50-266		STAFFA, R. W.	7903300309	50-321	
SMITH, W. R.	7903250481	50-250		STAFFA, R. W.	7903240489	50-424	
SMITH, H. P.	7903070181			STAHL, D. M.	7903250361	50-445	
SMITH, M. E.	7903300467			STAHL, D.	7903140138	50-445	
SMITH, C. V.	7903070584	50-243		STAHL, D. M.	7903030260	50-445	
SMITH, R. E.	7903300422	50-182		STAHL, D. M.	7903240241	50-445	
SMITH, J. R.	7903290641	50-471		STAHL, D.	7903100118	50-445	
SMITH, J. R.	7903290637	50-471		STAHL, D.	7903100123	50-445	
SMITH, I. W.	7903240105	50-389		STAHL, D. M.	7903100271	50-445	
SMITH, I. W.	7903290583	50-393		STAHL, C. R.	7903100220	50-390	
SMITH, I. W.	7903130796	50-389		STALLINGS, C. M.	7903040305		
SMITH, I. W.	7903250362	50-400		STALLINGS, C. M.	7903290125	50-338	
SMITH, B. H.	7903250137	50-272		STALLINGS, C. M.	7903230658	50-338	
SMITH, B. H.	7903150180	50-272		STALLINGS, C. M.	7903140401	50-338	
SMITH, B. H.	7903150187	50-272		STALLINGS, C. M.	7903290372	50-281	
SMITH, B. H.	7903150192	50-272		STALLINGS, C. M.	7903080164	50-280	
SMITH, B. H.	7903030020	50-272		STALLINGS, C. M.	7903230631	50-338	
SMITH, B. H.	7903070131	50-471		STALLINGS, C. M.	7903020245	50-338	
SMITH, B. H.	7903290055	50-471		STALLINGS, C. M.	7903020474	50-338	
SMITH, B. H.	7903070129	50-471		STALLINGS, C. M.	7903020512	50-280	
SMITH, B. H.	7903150068	50-272		STALLINGS, C. M.	7903240181	50-280	
SMITH, O. H.	7903210110	50-320		STALLINGS, C. M.	7903010484	50-281	
SMITH, O. H.	7903210112	50-320		STALLINGS, C. M.	7903010492	50-280	
SMITH, O. H.	7903190173	50-320		STALLINGS, C. M.	7903020358	50-338	
SMITH, O. H.	7903210072	50-320		STALLINGS, C. M.	7903020391	50-338	
SMITH, O. H.	7903210261	50-320		STALLINGS, C. M.	7903040036	50-280	
SMITH, O. H.	7903210308	50-320		STALLINGS, C. M.	7903040626	50-338	
SMITH, O. H.	7903210299	50-320		STALLINGS, C. M.	7903300734	50-338	
SMITH, O. C.	7903110036	70-820		STALLINGS, C. M.	7903040380	50-280	
SMITH, O. H.	7903300108	50-320		STALLINGS, C. M.	7903040396	50-280	
SMITH, O. H.	7903210273	50-320		STALLINGS, C. M.	7903070637	50-280	
SMITH, O. H.	7903110102	50-6134		STALLINGS, C. M.	7903080441	50-339	
SMITH, O. H.	7903110105	50-6134		STALLINGS, C. M.	7903070530	50-338	
SMITH, O. H.	7903230724	50-277		STALLINGS, C. M.	7903070655	50-280	
SMITH, O. H.	7903290188	50-3		STALLINGS, C. M.	7903070656	50-338	
SMITH, O. H.	7903090134	50-220		STALLINGS, C. M.	7903240481	50-338	
SMITH, O. H.	7903240294	50-244		STALLINGS, C. N.	7903300706	50-280	
SMITH, O. H.	7903110072	50-6134		STALLINGS, C. M.	7903080428	50-338	
SMITH, O. H.	7903230694	50-277		STALLINGS, C. M.	7903080444	50-338	
SMITH, O. H.	7903290177	50-3		STALLINGS, C. M.	7903080506	50-338	
SMITH, R.	7903110340	50-320		STALLINGS, C. M.	7903080538	50-280	
SHOLINSKY, J. H.	7903030247	50-549		STALLINGS, C. M.	7903110142	50-338	
SHOLINSKY, J.	7903030350	50-549		STALLINGS, C. M.	7903190062	50-338	
SHOLINSKY, J.	7903070467	50-596		STALLINGS, C. M.	7903110087	50-280	
SHNAIDER, R. P.	7903290523			STALLINGS, C. M.	7903110157	50-280	
SNIEZEK, J. H.	7903100375	50-346		STALLINGS, C. M.	7903150310	50-280	
SNIEZEK, J. H.	7903110006	50-312		STALLINGS, C. M.	7903150270	50-338	
SNIEZEK, J. H.	7903210253	50-320		STALLINGS, C. M.	7903160432	50-338	
SNIEZEK, J. H.	7903220412	50-320		STALLINGS, C. M.	7903190191	50-338	
SNOW, B. A.	7903220223	50-244		STALLINGS, C. M.	7903190119	50-280	
SNYDER, A. W.	7903300061	50-320		STALLINGS, C. M.	7903210176	50-338	
SNYDER, O. L.	7903300090	50-320		STALLINGS, C. M.	7903210258	50-338	
SNYDER, B. J.	7903160102	50-320		STALLINGS, C. M.	7903210275	50-280	
SOBON, L. J.	7903040028			STALLINGS, C. M.	7903220142	50-280	
SOBON, L. J.	7903210173	50-219		STALLINGS, C. M.	7903230536	50-338	
SOBON, L. J.	7903290259			STALLINGS, C. M.	7903220287	50-338	
SOBON, L. J.	7903030340			STALLINGS, C. M.	7903230060	50-338	
SOBON, L. J.	7903140392	50-219		STALLINGS, C. M.	7903230341	50-281	
SOBON, L. J.	7903210152			STALLINGS, C. M.	7903240342	50-338	
SOBON, L. J.	7903030588			STALLINGS, C. M.	7903240485	50-280	
SOBON, L. J.	7903310321			STALLINGS, C. M.	7903250108	50-280	
SOHINKI, B. H.	7903310013	50-466		STALLINGS, C. M.	7903250141	50-280	
SOHINKI, B. H.	7903210381	50-466		STALLINGS, C. M.	7903290005	50-280	
SOHINKI, B. H.	7903150127	50-592		STALLINGS, C. M.	7903290032	50-280	
SOHINKI, B. H.	7903100276	50-466		STALLINGS, C. M.	7903290001	50-280	
SOHINKI, B. H.	7903300072	50-466		STALLINGS, C. M.	7903300018	50-280	
SOHINKI, B. H.	7903150125	50-333		STALLINGS, C. M.	7903300312	50-280	
SOHINKI, B. H.	7903150737	50-452		STALLINGS, C. M.	7903300401	50-338	
SOHINKI, B. H.	7903150740	50-466		STALL, D. H.	7903240391	50-6	
SOHINKI, B. H.	7903150745	50-465		STAMPLEY, N. L.	7903090271		
SOHINKI, B. H.	7903150748	50-592		STAMPLEY, N. L.	7903300439	50-416	
SOHINKI, B. H.	7903300537	50-592		STANGL, R.	7903150348	50-366	
SOHINKI, B. H.	7903100125	50-466		STANLEY, W. B.	7903080451	50-289	
SOHINKI, B. H.	7903100146	50-466		STANLEY, K. B.	7903080547	50-289	
SOHINKI, B. H.	7903100122	50-437		STANLEY, W. B.	7903140296	50-289	
SOHINKI, B. H.	7903240133	50-592		STARKEY, R. B.	7903040535	50-261	
SOHINKI, B. H.	7903240294	50-466		STARKEY, R. B.	7903150451	50-261	
SOHINKI, B. H.	7903240149	50-466		STARKEY, R. B.	7903150463	50-261	
SOHINKI, B. H.	7903240528	50-466		STARKEY, R. B.	7903190030	50-261	
SOLBERG, D. E.	7903110273	50-320		STARKEY, R. B.	7903190088	50-261	
SOLBRIG, C. W.	7903040482	50-10		STARKEY, R. B.	7903220110	50-261	
SORENSEN, S. M.	7903230376			STARKEY, R. B.	7903290230	50-261	
SOUCY, A. R.	7903160309	50-29		STEINER, R.	7903070143	50-320	
SOUCY, A. R.	7903310390	50-29		STEINHARDT, B.	7903240469	50-271	
SPAAK, F.	7903130573			STEIN, H. H.	7903300114		
SPARKS, E.	7903150692	71-47		STELLO, V.	7903020128	50-320	
SPARKS, D. W.	7903170302	50-272		STELLO, V.	7903110050	50-312	
SPECTOR, S.	7903110104	50-244		STELLO, V.	7903110180	50-312	
SPECTOR, S.	7903310435	50-244		STELLO, V.	7903090286	50-313	
SPETS, T. P.	7903310160	50-267		STELLO, V.	7903080347	50-280	
SPETS, T. P.	7903310171	50-267		STELLO, V.	7903070017	50-309	
SPETS, T. P.	7903310186	50-267		STELLO, V.	7903230123	50-320	
SPETS, T. P.	7903300210	50-267		STELLO, V.	7903190194	50-320	
SPELMAN, H. J.	7903240114	40-2061		STELLO, V.	7903230801		
SPENCER, W. C.	7903300520	50-280		STELLO, V.	7903230081	50-320	
SPENCER, W. C.	7903240162	50-338		STELLO, V.	7903230085	50-320	
SPENCER, W. C.	7903240783	50-339		STELLO, V.	7903150174	50-313	

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
STELLQ, V.	7905100158	50-280		STODOLY, D. O.	7905100334	50-471	
STELLQ, V.	7905230125	50-320		STODOLY, D. O.	7905240233	50-471	
STELLQ, V.	7905230128	50-320		STODOLY, D. O.	7905290626	50-471	
STELLQ, V.	7905230135	50-320		STOUT, J. W.	7905220282	50-317	
STELLQ, V.	7905070014	50-295		STRAIN, P.	7905140191		
STELLQ, V.	7905290392	50-296		STRATHAN, R. A.	7905300457	50-336	
STELLQ, V.	7905210055	50-320		STRAUSS, K. J.	7905150652		
STELLQ, V.	7905230175	50-320		STREBEL, B. J.	7905100004		
STELLQ, V.	7905050212	50-320		STREBEL, B. J.	7905100007		
STELLQ, V.	7905100054	50-320		STREETER, J. F.	7905070027	50-373	
STENSVAAO, J.	7905080411	50-263		STREETER, J. F.	7905090175	50-409	
STENSVAAO, T.	7905080482	50-263		STRELOW, R.	7905150498		
STEPHENS, P. W.	7905300263	50-133		STRELOW, R.	7905150494		
STEPHENSON, B. B.	7905040432	50-237		STREIGHT, R. L.	7905240218	50-392	
STEPHENSON, B. B.	7905080535	50-237		STROTZ, R. H.	7905170245	50-398	
STEPHENSON, B. B.	7905080548	50-249		STROUPE, E. P.	7905140428		
STEPHENSON, B. B.	7905220257	50-237		STROUPE, E. P.	7905140426		
STEPHENSON, B. B.	7905140318	50-249		STROUPE, E. P.	7905220348		
STEPHENSON, B. B.	7905160384	50-237		STROUPE, E. P.	7905140297		
STEPHENSON, B. B.	7905160394	50-10		STROUPE, E. P.	7905300328		
STEPHENSON, B. B.	7905170226	50-237		STUCKENBERGER, M. J.	7905300090		
STEPHENSON, B. B.	7905300567	50-237		STUCKENBERGER, O.	7905110021	70-1318	
STEPHENSON, B. B.	7905300443	50-237		SU, T. H.	7905200235	50-219	
STEPHENSON, B. B.	7905300465	50-237		SUDBECK, R. R.	7905150294	50-116	
STEPHENSON, B. B.	7905300579	50-249		SULLIVAN, T. J.	7905230761		
STEPHENSON, B. B.	7905300697	50-249		SULLIVAN, T. J.	7905250478		
STEPHENSON, B. B.	7905300475	50-237		SULLIVAN, T. J.	7905090416		
STEPHENS, P.	7905250158	50-295		SULLIVAN, R. F.	7905150107	50-259	
STERNBERG, D. M.	7905230640	50-275		SUNDARAM, R. K.	7905020151		7905020151
STERNBERG, D. M.	7905290152	50-275		SUTHERLAND, J. T.	7905070078	50-327	
STETKA, T. F.	7905110394	50-271		SUTHERLAND, J. T.	7905010193	50-124	
STEVENSON, W. M.	7905220037	50-382		SUTHERLAND, J. T.	7905290130	50-338	
STEVENS, J. R.	7905110137			SUTHERLAND, J. T.	7905230672	50-338	
STEWART, W. P.	7905070538	50-302		SUTHERLAND, J. T.	7905230610	50-261	
STEWART, W. P.	7905010408	50-302		SUTHERLAND, J. T.	7905290092	70-1113	
STEWART, W. P.	7905080095	50-302		SUTHERLAND, J. T.	7905240992	50-25	
STEWART, W. P.	7905100238	50-302		SUTHERLAND, J. T.	7905070095	70-1113	
STEWART, W. P.	7905250390	50-302		SUTHERLAND, J. T.	7905230648	50-338	
STEWART, W. P.	7905240802	50-302		SUTHERLAND, J. T.	7905230398	50-261	
STEWART, W. P.	7905040043	50-302		SUTHERLAND, J. T.	7905240947	50-25	
STEWART, W. P.	7905030351	50-302		SUTHERLAND, J. T.	7905290082	70-1113	
STEWART, W. P.	7905040088	50-302		SUTHERLAND, J. T.	7905290119	50-338	
STEWART, W. P.	7905040630	50-302		SWAIN, W. E.	7905170296	71-300	
STEWART, W. P.	7905070537	50-302		SWAIN, W. E.	7905170299	71-300	
STEWART, W. P.	7905070597	50-302		SWALES, J.	7905240699	50-265	
STEWART, W. P.	7905070611	50-302		SWAN, W. B.	7905250431	50-508	
STEWART, W. P.	7905070624	50-302		SWAN, W. B.	7905240537	50-491	
STEWART, W. P.	7905070645	50-302		SWANBERG, F.	7905110275	50-320	
STEWART, W. P.	7905070652	50-302		SWANSON, D. O.	7905030339	50-437	
STEWART, W. P.	7905080429	50-302		SWANSON, V. A.	7905080513	50-375	
STEWART, W. P.	7905290493	50-302		SWANSON, D. T.	7905290033	50-396	
STEWART, W. P.	7905090278			SWANSON, D. T.	7905100178	50-396	
STEWART, W. P.	7905290013	50-302		SWANSON, D. T.	7905241006	50-338	
STEWART, W. P.	7905110241	50-302		SWANSON, D. T.	7905240258	50-338	
STEWART, W. P.	7905190023	50-302		SWART, F. E.	7905140288	50-267	
STEWART, W. P.	7905210153	50-302		SWART, F. E.	7905140319	50-267	
STEWART, W. P.	7905210272	50-302		SWART, F. E.	7905300222	50-267	
STEWART, W. P.	7905230369	50-302		SWED, J. P.	79053300871		
STEWART, W. P.	7905250375	50-302		SWENY, H.	7905220423	50-320	
STEWART, W. P.	7905250383	50-302		SWINDLE, D. L.	7905150389	50-313	
STEWART, W. P.	7905300497	50-302		SWITZER, D. C.	7905160262	50-336	
STEWART, W. P.	7905310298	50-302		SWITZER, D. C.	7905160376	50-336	
STEWART, W. P.	7905300153	50-302		SZALINSKI, P. A.	7905110141		
STEWART, W. P.	7905300183	50-302		TALWANI, P.	7905300700	50-395	
STEWART, W. P.	7905300484	50-302		TAMBLING, T. N.	7905110111	50-346	
STEWART, W. P.	7905300344	50-302		TAMBLING, T. N.	7905100362	50-346	
STEWART, W. P.	7905310391	50-302		TAMPLIN, A. R.	7905140079	70-2623	
STEWART, W. L.	7905020519	50-280		TANAKA, N.	7905140096		
STEWART, W. L.	7905010487	50-281		TANNER, H. A.	7905310360	50-329	
STEWART, W. L.	7905010498	50-280		TAPIA, J. I.	7905010312	50-482	
STEWART, W. L.	7905040414	50-280		TAVERNIER, B. W.	7905140043	50-312	
STEWART, D.	7905150515	50-280		TAYLOR, J. H.	7905030194		
STEWART, W. L.	7905110164	50-280		TAYLOR, J. H.	7905070555		
STEWART, W. L.	7905190123	50-280		TAYLOR, J. H.	7905100153		
STEWART, W. L.	7905230344	50-281		TAYLOR, J. H.	7905020348		
STEWART, W. L.	7905250130	50-280		TAYLOR, J. H.	7905030356		
STEWART, W. L.	7905250154	50-280		TAYLOR, J. H.	7905210136		
STEWART, W. L.	7905250157	50-280		TAYLOR, J. H.	7905140314		
STEWART, W. L.	7905290010	50-280		TAYLOR, J. H.	7905080242		
STEWART, R. C.	7905150550	50-382		TAYLOR, J. H.	7905190161		
STEYER, K. O.	7905160104	50-320		TAYLOR, J. H.	7905160370		
STODDART, P.	7905230141	50-320		TAYLOR, J. H.	7905160388	70-135	
STODDART, P.	7905230152	50-320		TAYLOR, J. H.	7905220408		
STOHR, J. P.	7905190168	50-320		TAYLOR, J. H.	7905160373		
STOHR, J. P.	7905190170	50-320		TAYLOR, J. H.	7905220324		
STOHR, J. P.	7905190177	50-320		TAYLOR, J. H.	7905240494		
STOHR, J. P.	7905210133	50-320		TAYLOR, J. H.	7905310406		
STOHR, J. P.	7905210140	50-320		TAYLOR, J. H.	7905310343		
STOHR, J. P.	7905210124	50-320		TAYLOR, J. H.	7905310370	50-313	
STOHR, J. P.	7905210245	50-320		TAYLOR, J. H.	7905310377		
STOIBER, C.	7905250324			TAYLOR, R. L.	7905140225	50-250	
STOIBER, C.	7905090218	50-320		TAYLOR, P. A.	7905230503	50-269	
STOIBER, C.	7905090223	50-320		TAYLOR, R. O.	7905070209	50-445	
STOLZ, J. F.	7905070674	50-275		TAYLOR, R. O.	7905010370	50-445	
STOLZ, J. F.	7905090290			TAYLOR, H.	7905300259	50-320	
STOLZ, J. F.	7905230578	50-275		TEDESCO, R. L.	7905110239	50-320	
STOLZ, J. F.	7905290528	50-341		TEDESCO, R. L.	7905110290	50-320	
STOLZ, J. F.	7905230826	50-322		TEDESCO, R. L.	7905110334	50-320	
STOLZ, J. F.	7905240572	50-358		TEDESCO, R. L.	7905190155	50-320	
STOLZ, J. F.	7905100431	50-416		TEDESCO, R. L.	7905220457	50-320	
STOLZ, J. F.	7905240857	50-522		TEDESCO, R. L.	7905110349		
STOLZ, J. F.	7905280049	50-313		TEDESCO, R. L.	7905010198	50-320	
STOLZ, J. F.	7905310083	50-341		TELFORD, J. T.	7905230278	50-320	
STONE, L. R.	7905220397	50-528		TELFORD, J. T.	7905230265	50-320	
STONE, R.	7905240718	50-250		TELFORD, J. T.	7905210073	50-320	
STONE, R.	7905300742	50-250		TEMPEST, L.	7905240424		

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
TEMPLE, J	7905230493			TRIMBLE, D C	7905110007	50-368	
TEPEL, R C	7905240346		7905240346	TRIMBLE, D C	7905150215	50-313	
TERNEY, W B	7905230104	50-255		TRIMBLE, D C	7905040008	50-313	
TERRY, S H	7905040168	50-294		TRIMBLE, D C	7905070490	50-313	
TERRY, S H	7905040165	50-294		TRIMBLE, D C	7905110066	50-313	
THADANI, A C	7905230102			TRIMBLE, D C	7905140172	50-368	
THADANI, A C	7905290597			TRIMBLE, D C	7905150460	50-313	
THADANI, A C	7905240476			TRIMBLE, D C	7905140230	50-313	
THADANI, A C	7905230210	50-255		TRIMBLE, D C	7905150572	50-368	
THADANI, A C	7905230087	50-255		TRIMBLE, D C	7905170227	50-368	
THAM, R W	7905240285	71-158		TRIMBLE, D C	7905170254	50-313	
THIELSCH, H	7905080128	71-36		TRIMBLE, D C	7905190167	50-313	
THIESING, J W	7905230496	50-320		TRIMBLE, D C	7905230020	50-313	
THIESING, J W	7905230468	50-320		TRIMBLE, D C	7905220248	50-313	
THIESING, J W	7905230065	50-320		TRIMBLE, D C	7905210266	50-313	
THIESING, J W	7905230069	50-320		TRIMBLE, D C	7905220398	50-368	
THIES, A C	7905110125	50-267		TRIMBLE, D C	7905240365	50-313	
THIES, A C	7905110129	50-267		TRIMBLE, D C	7905240712	50-313	
THOMAS, E B	7905030346	50-220		TRIMBLE, D C	7905290155	50-313	
THOMAS, E B	7905030337	50-244		TRIMBLE, D C	7905300488	50-313	
THOMAS, E B	7905040085	50-485		TRIMBLE, D C	7905290103	50-313	
THOMAS, E B	7905310218	50-220		TRIMBLE, D C	7905300001	50-313	
THOMAS, E B	7905040007	50-341		TRIMBLE, D C	7905300509	50-368	
THOMAS, J H	7905290665	40-3392		TRIPP, L	7905210240	50-320	
THOMAS, E L	7905040313			TRIPP, L	7905020140	50-289	
THOMAS, Q	7905240275	50-556		TRIPP, L	7905290137	50-309	
THOMAS, Q	7905150063	50-556		TRIPP, L	7905040156	50-387	
THOMAS, W N	7905040468	50-280		TROCHESSET, K P	7905230744	50-466	
THOMAS, R D	7905020320	50-142		TROFFER, O J	7905030338	50-289	
THOMAS, C O	7905150641	50-556		TROFFER, O J	7905090320	50-320	
THOMPSON, M W	7905020234	50-269		TROUP, O L	7905070101	70-1113	
THOMPSON, D	7905110416	50-500		TROWBRIDGE, C D	7905240293	71-222	
THOMPSON, D	7905020260	50-320		TROWBRIDGE, O F	7905090247	50-320	
THOMPSON, D	7905040296	50-320		TROWBRIDGE, O F	7905300698	50-400	
THOMPSON, D	7905140293	50-320		TROWBRIDGE, O F	7905080232	50-400	
THOMPSON, D	7905160201	50-320		TROWBRIDGE, O F	7905230340	50-382	
THOMPSON, H L	7905160113	50-320		TROWBRIDGE, O F	7905140221	50-400	
THOMUS, L H	7905090140	50-220		TROWBRIDGE, O F	7905140261	50-400	
THORNBUROGH, D	7905190251	50-320		TROWBRIDGE, O F	7905150738		
THORNBUROGH, D	7905140092	50-320		TROWBRIDGE, O F	7905220459	50-320	
THORNBUROGH, H D	7905230837	50-482		TSUJI, K	7905240005		
THORPE, J R	7905090203			TSUJI, K	7905240010		
THRASH, C O	7905230230	50-466		TSUJI, K	7905230037		
THRASH, C O	7905300066	50-466		TSUJI, K	7905290190		
THRASH, C O	7905310407	50-466		TURLEY, R E	7905010661	50-72	
THRASH, C O	7905290068	50-466		TURNER, J E	7905150647	71-217	
THRASH, C O	7905240310	50-466		TURNER, W G	7905140231	50-341	
THRASH, C O	7905240043	50-466		TURNER, E A	7905240693	50-498	
THURLOW, E W	7905230803	50-309		TURNER, E A	7905030336	50-498	
TIBBITTS, D L	7905230686	50-395		TURNER, E A	7905080408	50-498	
TIBBITTS, D L	7905240340	50-395		TURNER, E A	7905150236	50-498	
TIERNEY, F P	7905040521	50-282		UDALL, M K	7905300637		
TIETZ, G	7905240707	50-265		UORIO, R E	7905040985	50-335	
TILBE, H E	7905160124	50-320		UORIO, R E	7905150605		
TILBE, H R	7905300175	50-320		UORIO, R E	7905300040	50-250	
TIMKO, D R	7905140302	50-334		UORIO, R E	7905290159	50-335	
TIPTON, T E	7905240513	50-219		UORIO, R E	7905240045	50-335	
TOALSTON, A L	7905230832	50-329		UORIO, R E	7905150247	50-250	
TOALSTON, A L	7905310373	50-361		UORIO, R E	7905240434	50-250	
TOBIN, W J	7905020087	50-269		UORIO, R E	7905240169	50-335	
TOBIN, W J	7905020033	50-280		UORIO, R E	7905070410	50-335	
TOBIN, W J	7905300026	50-338		UORIO, R E	7905140217	50-250	
TODD, G A	7905240069	50-335		UORIO, R E	7905140220	50-250	
	7905300021	70-1201		UORIO, R E	7905140310	50-335	
	7905090229	50-320		UORIO, R E	7905210121	50-335	
	7905030347	50-324		UORIO, R E	7905300015	50-250	
	7905080518	50-325		UORIO, R E	7905220027	50-335	
	7905090289	50-324		UORIO, R E	7905240486	50-251	
	7905090311	50-324		UORIO, R E	7905240547	50-250	
				UORIO, R E	7905230397	50-335	
				UORIO, R E	7905230411	50-250	
				UORIO, R E	7905290143	50-250	
				UORIO, R E	7905310214	50-335	
				UORIO, R E	7905300014	50-335	
				UORIO, R E	7905310305	50-335	
				UORIO, R E	7905310309	50-335	
				ULLMAN, A	7905300507		
				ULRICH, W T	7905140346	50-277	
				ULRICH, W T	7905230861	50-277	
				URBAN, H	7905240598	50-592	
				URHIO, R E	7905080412	50-250	
				URHIO, R E	7905230426	50-250	
				UTLEY, E E	7905190013	50-261	
				UTLEY, E E	7905100241	50-324	
				UTLEY, E E	7905230613	50-261	
				UTLEY, E E	7905010817	50-261	
				UTLEY, E E	7905030331	50-261	
				UTLEY, E E	7905030353	50-324	
				UTLEY, E E	7905010857	50-261	
				UTLEY, E E	7905240192	50-324	
				UTLEY, E E	7905040084	50-261	
				UTLEY, E E	7905010952	50-261	
				UTLEY, E E	7905020333	50-261	
				UTLEY, E E	7905040032	50-261	
				UTLEY, E E	7905040624	50-324	
				UTLEY, E E	7905300283	50-324	
				UTLEY, E E	7905080402	50-324	
				UTLEY, E E	7905080417	50-324	
				UTLEY, E E	7905080436	50-324	
				UTLEY, E E	7905080437	50-261	
				UTLEY, E E	7905300296	50-261	
				UTLEY, E E	7905310379	50-324	
				UTLEY, E E	7905190328	50-261	
				UTLEY, E E	7905210165	50-324	
				UTLEY, E E	7905230121	50-261	
				UTLEY, E E	7905220346	50-261	

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
UTLEY, E E	7905290374	50-261		WALBRIDGE, W C	7905010477	50-443	
UTLEY, E E	7905300449			WALKER, R B	7905020123	50-320	
UTLEY, E E	7905290370	50-324		WALKER, R D	7905150134	50-331	
UTLEY, E E	7905290388	50-261		WALL, I B	7905230417		
VAHRENWALD, J	79051100297	50-254		WALL, I B	7905230434		
VAHRENWALD, J	7905240687	50-265		WALLACE, A	7905190070	50-320	
VALORE, C	7905230525	50-272		WALLACE, A T	7905250448		
VALORE, C	7905230532	50-272		WALLACE, A	7905240417		
VALORE, C	7905150801	50-272		WALLACE, E G	7905230015	50-320	
VALORE, C	7905230653	50-272		WALLACE, J A	7905250213	50-331	
VALORE, C	7905250024	50-272		WALLACE, L E	7905240874	50-518	
VALORE, C	7905250028	50-272		WALLACE, J J	7905150335	50-305	
VAN BRUNT, E E	7905220386	50-328		WALLACE, J R	7905300162	50-320	
VAN BRUNT, E E	7905310378	50-392		WALPOLE, J R	7905150752		
VAN BRUNT, E E	7905300287	50-392		WALSH, C	7905140084	50-320	
VAN BRUNT, E E	7905150609	50-528		WALTERS, D K	7905020442	50-327	
VAN BICKEL, J	7905020253	50-331		WALTON, Q A	7905020140	50-289	
VAN BICKEL, J	7905160368	50-331		WANDKE, N E	7905020272	50-295	
VAN BICKEL, J	7905160387	50-331		WANDKE, N E	7905090322	50-295	
VAN BICKEL, J	7905210224	50-331		WANDKE, N E	7905100300	50-304	
VAN BICKEL, J	7905290191	50-331		WANDKE, N E	7905100306	50-304	
VAN TRAN, T	7905100229		NUREQ/CR-0724	WANDKE, N E	7905240543	50-293	
VANBRUNT, E E	7905290056	50-528		WANDKE, N E	7905240530	50-304	
VANBRUNT, E E	7905290072	50-528		WANDKE, N E	7905240538	50-293	
VANDENBURGH, D E	7905250355	50-309		WANDKE, N E	7905070584	50-243	
VANDENBURGH, D	7905210161	50-309		WANDKE, N E	7905250469		
VANDENBURGH, D	7905010480	50-271		WARD, J E	7905020462	50-282	
VANDENBURGH, D	7905010500	50-271		WARD, E C	7905140214	50-282	
VANDENBURGH, D E	7905240613	50-271		WARD, E C	7905230308	50-341	
VANDENBURGH, D E	7905250473			WARD, K D	7905290569	50-155	
VANDEL, T E	7905290720	50-358		WARD, K D	7905240716	50-373	
VANNESS, S C	7905240789	50-272		WAREHNSBURG, D	7905010507	50-267	
VARGA, S A	7905070665	50-536		WAREHNSBURG, D	7905040374	50-267	
VARGA, S A	7905230795	50-397		WAREHNSBURG, D	7905080544	50-267	
VARGA, S A	7905090299	50-466		WAREHNSBURG, D	7905080435	50-267	
VARGA, S A	7905100171	50-546		WAREHNSBURG, D	7905160367	50-267	
VARGA, S A	7905100435	50-413		WAREHNSBURG, D	7905160372	50-267	
VARGA, S A	7905130649	50-327		WAREHNSBURG, D	7905160315	50-267	
VARGA, S A	7905080497	50-321		WAREHNSBURG, D	7905230025	50-267	
VASQUEZ, R O	7905080278			WAREHNSBURG, D	7905230393	50-267	
VASSALLO, D B	7905080171			WAREHNSBURG, D	7905020208	50-315	
VASSALLO, D B	7905080217			WAREHNSBURG, D	7905080093	50-255	
VASSALLO, D B	7809050087	50-457	NUREQ-0219	WAREHNSBURG, D	7905290546	50-263	
VASSALLO, D B	7905080230			WAREHNSBURG, D	7905240729	50-358	
VASSALLO, D B	7905080239			WARREN, M C	7905100369	71-307	
VASSALLO, D B	7905110143			WARREN, M C	7905100368	71-307	
VASSALLO, D B	7905160185	50-320		WARRENSBURG, D	7905250464	50-267	
VASSALLO, D B	7905020406	50-367		WATANABE, N	7905230041		
VASSALLO, D B	7905020406	50-382		WATANABE, N	7905250043		
VASSALLO, D B	7905020414	50-393		WATERHOUSE, E	7905300720	50-275	
VASSALLO, D B	7905020420	50-437		WATERHOUSE, H	7905300719	50-275	
VASSALLO, D B	7905020424	50-440		WATFORD, M L	7905130426	50-261	
VASSALLO, D B	7905020432	50-482		WATSON, B	7905240725	50-546	
VASSALLO, D B	7905020437	50-458		WATSON, C	7905020182		
VASSALLO, D B	7905020445	50-546		WATTERHAHN, M J	7905170303	50-358	
VASSALLO, D B	7905020452	50-556		WATTS, M J	7905020169		
VASSALLO, D B	7905010156	50-320		WATTS, M J	7905150368		
VASSALLO, D B	7905110158	50-320		WATTS, M J	7905100142		
VASSALLO, D B	7905110414			WEBB, R E	7905130691	50-295	
VASSALLO, D B	7905100395	50-320		WEBER, B	7905250353	50-596	
VASSALLO, D B	7905160112	50-320		WEBER, M D	7905090261		
VASSALLO, D B	7905100392	50-320		WEBSTER, L	7905020246	50-320	
VASSALLO, D B	7905100390	50-320		WEBSTER, E H	7905290174	50-335	
VASSALLO, D B	7905100389	50-320		WEEKS, E D	7905190130	50-133	
VASSALLO, D B	7905250126	50-522		WEEKS, J R	7905150196	50-27	BNL-NUREQ-23021
VASSALLO, D B	7905100388	50-320		WEEKS, J R	7905150201	50-272	BNL-NUREQ-25582
VASSALLO, D B	7905230840	50-368		WEOLEY, H L	7905030246		NUREQ/CR-0523
VERDERY, E H	7905150259	50-250		WEHRLI, R R	7905290511	71-104	
VIOLETTE, J B	7905250531			WEIGAND, J G	7905310429	50-458	
VOIGHT, H H	7905300025	50-341		WEILAND, R W	7905300658	71-57	
VOIGHT, H H	7905240195	50-485		WEINGARTEN, V I	7905030051		
VOIGHT, H H	7905150074	50-485		WEINHOLD, E H	7905300336	50-443	
VOIGHT, H H	7905240801	50-548		WEISER, J L	7905210018	50-320	
VOLGER, B H	7905100138			WEISER, J L	7905210021	50-320	
VOLLMER, R H	7905140287	50-524		WEISER, E R	7905030262	50-338	
VOLLMER, R H	7905150119			WEISER, E R	7905230749		
VOLLMER, R H	7905230023	50-320		WEISER, E R	7905230760		
VOLLMER, R H	7905230029	50-320		WEISS, N M	7904300173		
VOLLMER, R H	7905230126	50-320		WEISS, N M	7904300341		
VOLLMER, R H	7905230032	50-320		WEISS, N M	7905100013	50-320	
VOLLMER, R H	7905230040	50-320		WEISS, T	7905240984	70-371	
VOLLMER, R H	7905190226	50-320		WEISS, D	7905110052	70-364	
VOLLMER, R H	7905190247	50-320		WEISS, D	7905150790	70-8	
VOLLMER, R H	7905230178	50-320		WEISS, D	7905240230	70-754	
VOLLMER, R H	7905230116	50-320		WEISS, D	7905240946	70-824	
VOLLMER, R H	7905230118	50-320		WEISSBERG, S	7905160111	50-320	
VOLLMER, R H	7905020128	50-320		WEISSBERG, S	7905160126	50-320	
VOLLMER, R H	7905230165	50-320		WEISS, S H	7905030297		
VOLLMER, R H	7905100034	50-320		HENNER, S	7905250347	50-596	
VOLLMER, R H	7905210012	50-320		HENNER, S	7905290268		
VOLLMER, R H	7905230130	50-320		MERLING, J A	7905310384	50-334	
VOLLMER, R	7905150179			MERLING, J A	7905080460	50-334	
VOLLMER, R H	7905100073	50-280		MERLING, J A	7905080468	50-334	
VOLLMER, R	7905150808			MERLING, J A	7905080545	50-334	
VOTH, M H	7905070058	71-6058		MERLING, T A	7905080551	50-334	
VOTH, M H	7905150281	71-6058		MERLING, J A	7905150531	50-334	
WACHTER, L J	7905070344	50-282		MERLING, J A	7905150536	50-334	
WACHTER, L J	7905140104	50-282		MERLING, J A	7905240568	50-334	
WACHTER, L J	7905150573	50-263		MERLING, J A	7905010395	50-313	
WACHTER, L J	7905290321	50-263		WESTERN, F	7905140203		
WACHTER, L J	7905040517	50-263		WESTERN, F	7905100324	50-409	
WACHTER, L J	7905040022	50-263		WETMORE, J B	7905150131	50-358	
WACHTER, L J	7905290290	50-282		WETTERHAHN, M J	7905150133	50-358	
WACHTER, L J	7905230515	50-263		WETTERHAHN, M J	7905290171	50-358	
WACHTER, L J	7905250429	50-263		WETTERHAHN, M J	7905290176	50-358	
WALBRIDGE, W C	7905220465	50-312					

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
WETTERHAHN, H. J.	7905290180	50-358		WOLFE, S. J.	7905230182	50-466	
WETTERHAHN, H. J.	7905150151	50-358		WOLFE, S. J.	7905150677	50-437	
WETTERHAHN, H. J.	7905300062	50-358		WOLFE, S. J.	7905150491	50-556	
WETTERHAHN, H. J.	7905300067	50-358		WOLFE, S. J.	7905220071		
WETTERHAHN, H. J.	7905170301	50-358		WOLFE, S. J.	7905230560	50-556	
WETTERHAHN, H. J.	7905100169	50-358		WOLFE, S. J.	7905230570	50-556	
WETTERHAHN, H. J.	7905250117	50-358		WOLFE, S. J.	7905250541	50-382	
WETTERHAHN, H. J.	7905230123	50-358		WOLFF, C. E.	7905140541	40-8602	
WETTERHAHN, H. J.	7905310093	50-358		WOLFF, C. E.	7905030363	40-8602	
WETTERHAHN, H. J.	7905240094	50-272		WOLFF, C. E.	7905290063	40-8602	
WHITE, M. C.	7905150588			WOLFF, T.	7905090176		
WHITE, M. C.	7905150611			WOLIVER, J. D.	7905150144	50-358	
WHITE, M.	7905310111	50-466		WOLIVER, J. D.	7905150218	50-358	
WHITE, M.	7905140060	50-466		WONG, S.	7905300265	50-206	
WHITE, L. D.	7905250181	50-244		WOOD, H. C.	7905250492		
WHITE, L. D.	7905040101	50-244		WOOD, H. C.	7905250505		
WHITE, L. D.	7905040180	50-244		WOOD, J. C.	7905070251	50-498	
WHITE, L. D.	7905070486	50-244		WOOD, E. C.	7905090382	50-309	
WHITE, L. D.	7905070580	50-244		WOOD, E. C.	7905230467	50-309	
WHITE, L. D.	7905100149	50-244		WOOD, E. C.	7905190151	50-309	
WHITE, L. D.	7905110101	50-244		WOOD, E. C.	7905220243	50-309	
WHITE, L. D.	7905220377	50-244		WOOD, E. C.	7905220251	50-309	
WHITE, L. D.	7905220031	50-244		WOOD, E. F.	7905040506	50-387	
WHITE, L. D.	7905300474	50-244		WOODARD, J. R.	7905140550	50-556	
WHITE, L. D.	7905310393	50-244		WOODHEAD, C. P.	7905080392	50-466	
WHITE, L. D.	7905310431	50-244		WOODHEAD, C. P.	7905080039	50-219	
WHITESELL, D. E.	7905110404			WOODHEAD, C. P.	7905090419	50-219	
WHITESELL, D. E.	7905150585			WOODHEAD, C. P.	7905150143	50-510	
WHITLOCK, W. N.	7905090292	50-546		WOODHEAD, C. P.	7905100226	50-556	
WHITLER, J. D.	7905240585	50-348		WOODRUFF, R. W.	7905110028	50-312	
WHITMAN, J. H.	7905240548	40-6659		WOODLEVER, E. J.	7905010541	50-412	
WHITMER, C. F.	7905240227	50-424		WOODLEVER, E. J.	7905080370	50-334	
WHITMER, C. F.	7905250462			WOODSTENHULME, J.	7905310453	50-466	
WHITMER, C. F.	7905080427	50-321		WOZNIAK, B. F.	7905100292	50-305	
WHITMER, C. F.	7905100213	50-321		WRIGHT, R. L.	7905190077	50-320	
WHITMER, C. F.	7905170234	50-321		WRIGHT, K. H.	7905020222	40-4492	
WHITMER, C. F.	7905190039	50-321		WRIGHT, F. B.	7905090411	50-471	
WHITMER, C. F.	7905230047	50-321		WRIGHT, H.	7905220264	50-237	
WHITMER, C. F.	7905230538	50-321		WRIGHT, R. W.	7905230153	50-389	
WHITMER, C. F.	7905290184	50-366		WRIGHT, G. C.	7905090169	50-331	
WHITMER, C. F.	7905300006	50-321		WRIGHT, E. O.	7905110144	50-320	
WHITMAN, O. D.	7905020004			WRIGHT, E. O.	7905110174	50-320	
WHITTEMORE, F. C.	7905100132	50-516		WRIGHT, E. O.	7905110171	50-320	
WHITTEMORE, F. C.	7905230311	50-322		WRIGHT, R. H.	7905110265	50-320	
WHITTEMORE, F. C.	7905150207	50-322		WRIGHT, R. H.	7905110266	50-320	
WHITT, K. W.	7905110006	50-312		WU, T. Y.	7905240103		
WHITT, K. W.	7905250410	50-302		WYLER, B.	7905230789	50-275	
WIDNER, W. A.	7905290029	50-321		WYMAN, E. H.	7905220341	50-309	
WIDNER, W. A.	7905290035	50-321		WYRICK, R.	7905250430	50-250	
WIDGINTON, D.	7905290723	50-334		YACKLE, T. R.	7905150213		
WILBER, M.	7905220450	50-320		YAGER, D. H.	7905150603	50-275	
WILBORN, L.	7905230673			YALE, A. H.	7905040375	50-409	
WILCOX, H. H.	7905110227	50-320		YAMAZAKI, H.	7905290139		
WILCOX, J. D.	7905070118	50-281		YARRONDO, L. J.	7905110287	50-320	
WILKENS, P. C.	7905150393	50-244		YARRONDO, L. J.	7905080055		
WILKINS, T. D.	7905150116	70-1201		YEAGER, L. L.	7905090163		
WILLEMSEN, B.	7905240605	50-254		YELDERMAN, J. C.	7905090262		
WILLIAM, W. A.	7905140183			YELLIN, J.	7905160138	50-320	
WILLIAMS, R. E.	7905240170			VIN, L. T.	7905150535	50-358	
WILLIS, C. A.	7905150741			YORE, J. R.	7905080154		
WILLIAMS, C. E.	7905230211	71-9023		YORE, J. R.	7905250330	50-275	
WILLIAMS, D. H.	7905070491	50-368		YORE, T. R.	7905020105	50-488	
WILLIAMSON, E. A.	7905230104	50-255		YORE, J. R.	7905240762	50-514	
WILLIS, E.	7905150638	50-324		YOUNG, R. E.	7905150084	71-63	
WILLIAMS, J. L.	7905110014	50-314		YOUNGBLOOD, J.	7905250470		
WILLIAMS, F. P.	7905190150	50-206		YOUNGBLOOD, J.	7905240410		
WILLIAMS, O. H.	7905020161	70-1151		YOUNGBLOOD, J.	7905240401		
WILLIAMS, O. H.	7905020439	70-143		YOUNGBLOOD, J.	7905240438		
WILLIAMS, O. H.	7905240069	50-335		YOUNG, R.	7905220404	50-245	
WILLIAMS, O. H.	7905040124	70-27		YOUNG, F. M.	7905300082		
WILLIAMS, O. H.	7905070259	70-1201		YOUNG, T.	7905290152	50-275	
WILLIAMS, C. C.	7905080211	50-331		YOUNGBLOOD, B. J.	7905100338	50-320	
WILLIAMS, C. C.	7905130436	50-331		YUHAB, O. P.	7905240306	50-244	
WILLIAMS, P. M.	7905100277			YUN, J. H.	7905230327		
WILLIAMS, E.	7905310232	50-27		YUSEF, A. R.	7905280340	50-382	
WILLIAMS, D.	7905230696			ZAHN, L. L.	7905150301	70-1308	
WILLIAMS, D.	7905030106			ZALOUDEK, F. R.	7905280133		
WILLIAMS, D.	7905030123			ZAKIS, L.	7905230010	50-320	
WILLIAMS, D.	7905070105			ZAVADOBK, R. W.	7905290142	50-338	
WILLIAMS, D.	7905240176			ZEBRAK, I. L.	7905250365	50-596	
WILLIAMS, D.	7905150203			ZEBRAK, I. L.	7905250370	50-596	
WILLIAMS, R.	7905150348	50-270		ZEBRAK, I. L.	7905150164	50-596	
WILLIAMS, C.	7905250430	50-250		ZEBRAK, I. L.	7905240160	50-596	
WILLIAMS, R.	7905190116	50-320		ZIBULSKY, H.	7905230288	70-33	
WILLIAMS, F.	7905020388	50-344		ZIELINSKI, C. A.	7905250209	50-596	
WILLIAMS, F.	7905220078	50-344		ZIEMANN, D. L.	7905140520	50-266	
WILLIAMS, E.	7905150435	50-156		ZIEMANN, D. L.	7905100321	50-219	
WILLIAMS, E.	7905070209	50-445		ZIEMANN, D. L.	7905090160	50-245	
WILLIAMS, B. D.	7905020128	50-320		ZIEMANN, D. L.	7905030126	50-244	
WILLIAMS, B. D.	7905040449	50-344		ZIEMANN, D. L.	7905080381	50-245	
WILLIAMS, B. D.	7905100267	50-344		ZIEMANN, D. L.	7905080382	50-245	
WILLIAMS, B. D.	7905080431	50-344		ZIEMANN, D. L.	7905020449	50-206	
WILLIAMS, B. D.	7905110167	50-344		ZIEMANN, D. L.	7905020450	50-206	
WILLIAMS, B. D.	7905170238	50-344		ZIEMANN, D. L.	7905020457	50-206	
WILLIAMS, B. D.	7905220289	50-344		ZIEMANN, D. L.	7905150648	50-155	
WILLIAMS, B. D.	7905220311	50-344		ZIEMANN, D. L.	7905150707	50-155	
WILLIAMS, B. D.	7905310350	50-344		ZIEMANN, D. L.	7905150715	50-155	
WILLIAMS, B. D.	7905110261	50-320		ZIEMANN, D. L.	7905080570	50-237	
WILLIAMS, B. D.	7905150493	50-316		ZIEMANN, D. L.	7905080337	50-10	
WILLIAMS, B. D.	7905150501	50-316		ZIEMANN, D. L.	7905080339	50-237	
WILLIAMS, B. D.	7905210142	50-315		ZIEMANN, D. L.	7905080343	50-245	
WILLIAMS, B. D.	7905110086	50-312		ZIEMANN, D. L.	7905090016	50-213	
WILLIAMS, B. D.	7905240369	50-322		ZIEMANN, D. L.	7905090020	50-206	
WILLIAMS, B. D.	7905140565	50-382		ZIEMANN, D. L.	7905090022	50-29	
WILLIAMS, B. D.	7905160045	50-320		ZIEMANN, D. L.	7905090024	50-219	
WILLIAMS, J.	7905310409	50-466		ZIEMANN, D. L.	7905090026	50-244	

NUREG/CR-0595

7905080055
7905090163

PERSONAL AUTHOR INDEX

355

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
ZIEMANN, D. L.	7903090029	50-255		ZIEMANN, D. L.	7903230343	50-255	
ZIEMANN, D. L.	7903240271	50-155		ZIEMANN, D. L.	7903300729	50-245	
ZIEMANN, D. L.	7903230602	50-255		ZIEMANN, D. L.	7903290007	50-245	
ZIEMANN, D. L.	7903020218	50-206		ZIEMANN, D. L.	7903290012	50-245	
ZIEMANN, D. L.	7903020351	50-244		ZIEMANN, D. L.	7903290019	50-245	
ZIEMANN, D. L.	7903020363	50-29		ZIEMANN, D. L.	7903150489	50-155	
ZIEMANN, D. L.	7903090205	50-244		ZIMMERMAN, R. P.	7903290166	50-336	
ZIEMANN, D. L.	7903090207	50-244		ZITT, K. L.	7903300749	30-358	
ZIEMANN, D. L.	7903090263	50-244		ZITTEL, H. E.	7903240576		7903240576
ZIEMANN, D. L.	7903100174	50-409		ZUDANS, Z.	7903250106		
ZIEMANN, D. L.	7903230599	50-409		ZUFELT, E.	7903110256	50-333	
ZIEMANN, D. L.	7903080158	50-255		ZURAKAWSKI, P. R.	7903150701	70-1257	
ZIEMANN, D. L.	7903100132	50-409		ZWETZIO, Q. B.	7903100330	50-312	
ZIEMANN, D. L.	7903290074	50-409					

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
CITIZEN GROUP/INDIVIDUAL/MEDIA			Abco Perforators, Inc		
Another Mother for Peace	7905240168	50-574	7905150474	71-280	
Appalachian Research & Defense Fund, Inc	7905150098		7905150214	71-280	
Citizens Association for Sound Energy	7905240929	50-445	7905100229		
Citizens for a Better Environment	7905230239	50-320	7905030339	50-437	
	7905250450		7905100365	71-305	
CBS News, CBS, Inc	7905020037	50-320	7905100361	71-305	
Citizens Concerned About Nuclear Power, Inc	7905090007	50-498	7904210774		
Council of Energy Resource Tribes	7905150718		7905220026		
Citizens Energy Forum	7905030209	50-338	7905080536	50-329	
Citizens for Safe Environment	7905140319	50-320	7905250309		
Citizens Action For Safe Energy	7905290273	50-556	7905220023		
Intervenor's Cleanon	7905290295	50-471	7905230331		
	7905290292	50-471	7905150699	71-47	
Center for Law in the Public Interest	7905030174	50-275	7905150692	71-47	
	7905310104	50-275	7905030221		
Coalition for Safe Power	7905250279	50-344	7905240552		
	7905230818	50-522	7905020154		
	7905250273	50-344	7905090163		
	7905250357	50-344	7905030136	40-299	
	7905230550	50-344	7905030332	50-409	
	7905230546	50-344	7905030132	40-299	
Citizens United for Responsible Energy	7905150312	50-331	7905030028	50-133	
	7905250031	50-331	7905090401		
The Denver Post	7905140191		7905090408		
Ecology Action of Oswego	7905250353	50-596	7905150213		
	7905290473	50-485	7905100251	50-285	
	7905310203	50-485	7905110287	50-320	
Environmental Coalition on Nuclear Power	7905100403	50-320	7905230486	50-320	
	7905290181		7905080109		
	7905290187		7905190158	50-320	
Fulton Orange #66	7905230593	50-463	7905290469	71-297	
Great Lakes Energy Alliance	7905290691	50-255	7905290463	71-297	
Kudzu Alliance	7905290098	50-400	7905080568	50-397	
Louisiana Consumer's League, Inc	7905290300	50-382	7905250482		
Miami Valley Power Project	7905290464	50-358	7905250485		
	7905290468	50-358	7905090274	50-584	
	7905290520	50-358	7905230435	50-584	
	7905150757	50-358	7905090272	50-584	
	7905150227	50-358	7905230432	50-584	
	7905150212	50-358	7905240904	71-55	
	7905150221	50-358	7905170299	71-300	
Mid-Hudson Nuclear Opponents, Inc	7905230409	50-596	7905170296	71-300	
Milwaukee Sentinel	7905140527	50-266	7905150274	71-33	
Nautilus Alliance	7905150255	50-574			
News-Journal Co. W.Delaware	7905150524		7905150268	71-33	
Natural Resources Defense Council	7905250224	50-3	7905030042		
	7905240178	50-466	7905030051		
	7905240190	50-466	7905030176		
	7905240482	70-2623	7905150188		
	7905080184	50-437	7905150693		
	7905080202	50-437	7905150689	71-311	
	7905250292	50-437	7905160124	50-320	
	7905140079	70-2623	7905300175	50-320	
	7905290679	50-320	7905150888	71-137	
	7905080286	70-2623	7905150078	71-137	
	7905080296		7905300467		
	7905030034		7905070531	50-272	
	7905080286		7905020239	71-77	
	7905250458	50-437	7905020255	71-77	
	7905150279	50-556	7905020232	71-6698	
	7905040330	50-461	7905040375	50-409	
	7905140072	50-320	7905160427	50-409	
	7905080036		7905010648		
	7905010032		7905150094	71-63	
	7905080040	50-22	7905150084	71-63	
	7905080047		7905100060	40-8698	
	7905030207	50-338	7905250019	71-205	
	7905100328	50-280	7905250016	71-205	
	7905250233	50-338	7905240183	71-299	
	7905100262	50-280	7905240175	71-299	
	7905300487		7905310074		
	7905100332	50-592	7905310069		
	7905250350	50-596	7905140234	50-320	
	7905310267	50-502	7905100223	40-8452	
	7905070230	50-502	7905100233	40-8452	
	7905300215	50-510	7905240283	40-8452	
	7905240251	50-443	7905070111		
	7905150293	50-363	7905020056		
	7905250052	50-275	7905230527	50-320	
	7905240872	50-546	7905240293	71-222	
	7905240964	50-546	7905040615	50-280	
	7905240232	50-424	7905140245	50-280	
	7905300172	50-466	7905140239	50-280	
	7905300177	50-466	7905210111	50-280	
	7905250242	50-466	7905290335	50-280	
	7905110339	50-466	7905140382	50-280	
	7905110341	50-466	7905160335	50-280	
	7905100050	50-320	7905070446	50-495	
	7905290024		7905190200		
	7905300619		7905220232	50-495	
	7905240469	50-271	7905290309	71-304	
	7905300618	50-271	7905290305	71-304	
ENGINEERING/CONSTRUCTION/CONSULTANTS/SERVICES			7905250281	71-290	
American Airlines, Inc.	7905240348	71-9033	7905010618	40-8698	
	7905150785		7905290251	71-282	
			7905240103		
			7905240285	71-158	
EDUCATIONAL INSTITUTIONS					
			American Univ.	7905090417	
			Bentley College	7905020080	

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
Bunker Hill Community College	7905150229		Baker & Botts	7905080387	50-466
Catholic Univ	7905010547	50-77		7905080331	50-466
	7905150479	50-77		7905250230	50-466
	7905010539	50-77		7905310520	50-443
	7905070213			7905300066	50-466
Colorado State Univ	7905150458	50-394		7905310407	50-466
California Polytech State Univ	7905250506			7905290068	50-466
California State Univ, Sacramento	7905140539	50-320		7905150190	50-443
Eastern Washington Univ	7905240178	50-466		7905230651	50-443
Georgetown Univ Law School	7905240190	50-466		7905230624	50-443
	7905140164			7905240310	50-466
Harvard Univ	7905160138	50-320		7905240043	50-466
	7905160489	50-116		7905250239	50-466
Iowa State Univ	7905160276	50-116		7905290002	50-498
	7905240604	50-284		7905250177	50-437
Idaho State Univ	7905300232	50-320	Butzel & Kass	7905240983	50-547
Illinois Institute of Technology	7905170279		Cherry, M. M. / Cherry, Flynn & Kanter	7905250438	50-327
Johns Hopkins Univ	7905170282			7905240891	50-327
	7905240123			7905240899	50-327
Kansas State Univ	7905230384	50-188	Conner, Moore & Corber	7905150133	50-358
	7905140570	50-219		7905290171	50-358
Lehigh Univ	7905020151			7905290176	50-358
	7905040168	50-294		7905290180	50-358
Michigan State	7905040165	50-294		7905150131	50-358
	7905040480	50-20		7905300067	50-358
Massachusetts Institute of Technology	7905090331	50-20		7905100225	27-39
	7905300383	50-320		79053030214	50-395
	7905300385	50-320		7905310010	27-39
	7905310452	50-8		7905170303	50-358
North Carolina State Univ	7905170243	50-598		7905100237	27-39
Northwestern Univ	7905070584	50-243		7905240138	27-39
Oregon State Univ	7905090428			7905230812	50-277
Pennsylvania State Univ	7905230058	50-320		7905100169	50-358
	7905240326			7905250117	50-358
Purdue Univ	7905300422	50-182		7905280123	50-358
	7905140341	50-288		7905290077	50-498
Reed College	7905220391	50-225		7905140137	50-395
Rensselaer Polytechnic Inst	7905240387	50-141		7905310093	50-358
Stanford Univ	7905190019	50-97		7905150131	50-358
New York State Univ of Buffalo	7905240675	50-406		7905300062	50-358
Tuskegee Inst	7905220097	50-128		7905170301	50-358
Texas A & M Univ	7905240607	50-113		7905240094	50-272
Arizona, Univ of	7905210181	50-224	Gammon & Shapiro	7905240914	50-322
California, Univ of Berkeley	7905210178	50-224		7905240915	50-322
	7905250139		Dattilo, T.M.	7905150220	50-546
California, Univ of Los Angeles	7905250111		Douglass & Barham	7905170233	50-261
	7905250118		Debevoise & Lieberman	7905100228	50-443
	7905290047			7905150821	50-443
California, Univ of Santa Barbara	7905240170			7905090036	50-443
Idaho, Univ of	7905290491			7905090042	50-443
Maryland, Univ of	7905230406	50-2		7905090050	
Michigan, Univ of	7905090298	50-2		7905100193	50-443
	7905230402	50-2		7905230639	50-443
	7905090367	50-2		7905240317	70-2623
	7905290673			7905240414	71-6698
Missouri, Univ of	7905220090	50-123	Evergreen Legal Services	7905140159	50-522
	7905310401	50-123		7905140161	50-522
	7905220089	50-123	Feldman & Feldman	7905230124	
South Carolina, Univ. of	7905300700	50-395	Fried, Frank, Harris, Shriver & Kempelman	7904170521	
Texas, Univ of	7905240326		Fleischaker, D. S.	7905030166	50-275
Virginia, Univ of	7905250492			7905030174	50-275
	7905250505			7905310104	50-275
	7905240462	50-62	Fontana, L.	7905290151	50-382
	7905250169		Garry, Drayfus, McTermen, Brotsky,	7905070227	50-133
	7905010661	50-72	Harnden & Pesonen, Inc		
Wisconsin, Univ of Madison	7905150435	50-156	Green, Feldman, Hall & Woodward	7905140547	50-556
Wyoming, Univ. of	7905070037	40-4492		7905140550	50-556
Worcester Polytechnic Inst.	7905110298	50-134		7905240924	50-556
Washington State Univ	7905310236	50-27	Goldberg, Fieldman & Latham, P.C	7905100217	50-348
	7905310239	50-27	Gillespie & Jones	7905290151	50-382
	7905310242	50-27	Hunton & Williams	7905030258	50-338
	7905310245	50-27		7905100152	50-316
	7905310232	50-27		7905230668	50-338
	7905240472	50-27		7905250311	50-322
				7905230668	50-338
				7905240814	50-338
8			Huber, Magill, Lawrence & Farrell	7905230365	50-596
-				7905250370	50-596
Canada	7905250166	50-320		7905150164	50-596
	7905110369		Hodder, M.H.	7905290289	50-389
	7905150588		Isham, Lincoln & Beale	7905100147	50-255
	7905180611			7905160504	50-556
on of	7905150573			7905090185	50-556
	7905150047			7905230361	50-443
	7905300727			7905140138	50-443
	7905100323			7905300022	50-295
	7905150741			7905250284	50-454
	7905140328			7905100118	50-443
	7905140326			7905100123	50-443
	7905250115			7905100271	50-443
NIES				7905250179	50-556
----				7905250238	50-329
	7905230448	50-445		7905250163	50-329
	7905250488	50-445		7905290540	50-329
	7905020383	50-293		7905220062	50-556
	7905020274	50-320		7905290174	50-556
	7905070497	50-3		7905250158	50-295
	7905080530	50-320		7905240127	50-443
	7905220352	50-320		7905250238	50-329
	7905290285	50-320		7905070040	50-443
	7905150185			7905070043	50-443
	7905240068			7905250163	50-329
				7905290540	50-329

CORPORATE SOURCE INDEX

359

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905220062	50-556	Northcutt Ely	7905240332	50-445
	7905250174	50-556	Nuclear Energy Liability Insurance	7905100163	50-10
	7905070424		Association		
	7905030260	50-445		7905110107	50-280
Johnson & Higgins Insurance	7905240241	50-445		7905110107	50-339
	7905300334	50-338		7905110090	50-280
Kafin, R. J.	7905160399	50-293	Bruce Norton	7905300007	50-275
	7905240098	50-596	D'Neil, Backus, Spielman	7905010329	50-443
Kosik, L. B.	7905240106	50-596		7905020422	50-443
	7905140157	50-358		7905010323	50-443
	7905140369	50-358		7905020416	50-443
	7905290464	50-358		7905080398	50-443
	7905140136	50-358	Pfefferkorn & Cooley, P. A.	7905110347	50-488
	7905240104	50-358	Ropes & Gray	7905100336	50-471
LeBoeuf, Lamb, Leiby & MacRae	7905010223	50-358		7905240233	50-471
	7905300025	50-341		7905170245	50-443
	7905230497	50-485		7905010447	50-443
	7905240195	50-485		7905210129	50-443
	7905150074	50-485	Stuel, Hector & Davis	7905150793	50-250
	7905240801	50-548		7905150799	50-250
	7905030346	50-220		7905240838	50-389
	7905030357	50-244		7905150755	50-250
	7905040085	50-485		7905240973	50-250
	7905090358	50-285	Sheldon, Harmon & Roisman	7905030262	50-338
	7905150316	50-285		7905230760	
	7905310218	50-220		7905230749	
	7905310243	50-285	Spiegel & McDermid	7905030199	
	7905040007	50-341		7905150234	50-250
Lowenstein, Newman, Reis, Axelrad & Toll	7905080387	50-466		7905150733	50-250
	7905300035	50-250		7905140115	50-445
	7905080331	50-466		7905140089	
	7905250170	50-498		7905100007	
	7905080311	50-466		7905140126	50-445
	7905080320	50-466		7905240853	50-389
	7905030158	50-344		7905140131	50-445
	7905150722	50-344		7905030175	50-445
	7905250230	50-466		7905070222	
	7905250225	50-466		7905100101	
	7905150793	50-250		7905030175	50-445
	7905150799	50-250		7905100004	
	7905300066	50-466		7905150729	50-250
	7905310407	50-466	Snell & Hilmer	7905100002	50-592
	7905240207	50-389		7905300007	50-275
	7905290068	50-466		7905090247	50-320
	7905150190	50-445	Shaw, Pittman, Potts, & Trowbridge	7905300698	50-400
	7905230651	50-445		7905080232	50-400
	7905140057	50-466		7905100133	50-484
	7905100011	50-389		7905240999	50-484
	7905100019	50-389		7905250339	50-502
	7905230328	50-498		7905250340	50-382
	7905230624	50-445		7905140255	50-400
	7905240310	50-466		7905140261	50-400
	7905100391	50-466		7905300104	50-344
	7905240853	50-389		7905140221	50-400
	7905250239	50-466		7905220459	50-320
	7905290002	50-498		7905150738	
	7905240970	50-376	Valore, C.	7905230532	50-272
	7905070239	50-466		7905230523	50-272
	7905100009	50-38		7905150801	50-272
	7905070239	50-466	Volpe, Boskey & Lyons	7905100196	50-348
	7905240248	50-498		7905150665	70-1821
	7905240939	50-376	West Texas Legal Services	7905090194	50-445
	7905240824	50-498		7905240115	50-445
	7905250476		Worsham, Forsythe & Sampaio	7905150545	50-445
Metford & Dattilo	7905160212	50-320	Holliver, J.D.	7905150144	50-358
Mutual Atomic Energy Liability Underwrit- ers	7905070582	50-3		7905150218	50-358
	7905110205	70-364			
Marsh & McLennan, M & M Nuclear Consultan- ts, Inc. Div.	7905010527	50-327	LOCAL GOVERNMENT AND AGENCIES		
	7905080390	50-239	Alken County, SC		
	7905080394	50-239	Anderson County, SC		
	7905080430	50-321	Austin, TX		
	7905080432	50-321	Citrus County, FL		
	7905080474	50-302			
	7905080476	50-302	Contra Costa Co		
	7905100316	50-250	Cumberland Cour		
	7905100304	50-348	Florence County	7905240148	50-596
	7905100307	50-280	Gardiner, NY	7905150594	40-8698
	7905100309	50-333	Garfield County, UT	7905250493	
	7905100311	50-333	Grundy County, IL	7905250521	
	7905140361	50-346	Humboldt County, CA	7905250496	
	7905160396	50-348	Kewaunee County, WI	7905230683	50-272
	7905290089	50-272	Lower Alloways Creek, NJ	7905230235	50-272
	7905300301	50-250		7905230024	50-272
	7905300311	50-250		7905230028	50-272
	7905300468	50-348		7905250514	
McGrath, E. J.	7905240991		Oconee County, SC	7905170302	50-272
	7905240164		Pennsville, NJ	7905170300	50-272
McCutchen, Doyle, Brown & Emerson	7905020169			7905250499	
	7905030233		Richland County, SC	7905250495	50-546
	7905150368		Saluda Township, IN	7905180603	50-275
	7905100142		Santa Barbara County, CA	7905180898	50-275
	7905150803			7905250520	
Means, Donald B.	7905140159	50-522	St. Lucie County, FL	7905240234	50-322
	7905140161	50-522	Suffolk County, NY	7905100078	40-2061
Menroe & Lemann	7905220037	50-382	West Chicago, IL	7905240114	40-2061
Morgan, Lewis & Bockius	7905220064	50-556			
	7905240879	50-556			
	7905220064	50-556			
	7905240879	50-556			
McGinnis, Lochridge & Kilgore	7905230448	50-445	MEDICAL INSTITUTIONS/LABORATORIES		
Matthews, Nowlin, MacFarlane & Barrett	7905070231	50-498	Holyoke Hosp. HO, Massachusetts	7905290161	30-1873
			Lakeview Medical Center SA, Illinois	7905150734	

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
Michael Reese Hosp & Medical Center	7905150652			7905240269	70-1100
Vet Admin Hosp NE/OM	7905140204	50-131		7905250013	71-90
	7905140192	50-131		7905220080	
	7905140198	50-131	C-E Power Systems	7905110294	
	7905140201	50-131		7905300526	
				7905070544	
				7905110288	
MANUFACTURERS/EQUIPMENT AND SUPPLIES				7905300368	
Allied Chemical Corp , Nuclear Services	7905290665	40-3392	Carac. Inc	7905150784	
Div			Chemtree Corp	7904240395	
Aerojet Ordnance Co	7905250270	40-8695		7904240389	
	7905270258	40-8695	Chicago Bridge & Iron Co	7905290514	71-104
Aerostat Operations	7905240357	50-32		7905290511	71-104
Allied General Nuclear Services	7905150654	70-1821	Chem-Nuclear Systems, Inc	7905240187	71-6244
	7905230762	50-32		7905300636	71-6244
	7905150683	70-1821		7905220454	27-47
Allied Chemical Corp	7905210070	50-320		7905241004	27-39
	7905220109	40-3392	Colt Industries, Inc.	7905100099	50-423
	7905240867	71-277		7905100103	50-412
Anafco, Inc	7905290148	71-1		7905100107	50-395
	7905290146	71-1	Curtiss-Wright Corp.	7905230366	71-161
Air Products & Chemicals, Inc	7905290589			7905230354	71-161
	7905290168		Dow Chemical Co	7905150359	50-864
	7905290573		E I du Pont de Nemours & Co , Inc	7905140267	50-320
ATCOR	7905010473		Ederer, Inc (subs of Formac Internatio	7905160391	50-329
Bear Creek Mining Co (subs of Kennecott	7905250304	40-8452	nal, Inc)		
Corp)			Edlow International Co	7905150198	
Borg-Warner Corp	7905150314			7905030100	
	7905140128			7905290141	
BPB Instruments, Inc	7905150027	71-286		7905230567	
	7905150026	71-286		7905100264	40-8658
Buckeye International, Inc , Steel	7905240715	71-110	Energy Fuels Nuclear, Inc	7905030092	
Castings Div				79050300132	40-8681
				7905240344	40-8681
Babcock & Wilcox Co	7905240616	71-110	Euratom Supply Agency (Belgium)	7905070042	
	7905210232		Exxon Nuclear Co , Inc. (subs. of Exxon	7905100290	50-305
	7905140384	50-99	Corp.)		
	7905030205			7905080393	
	7905140028	50-320	Exxon Minerals Co., USA	7905150070	40-8102
	7905290084	71-322		7905220538	40-8064
	7905300391	50-320		7905220056	40-8064
	7905210138			7905220538	40-8064
	7905190164		Exxon Corp.	7905030658	71-57
	7905220410		Fansteel, Inc	7905020297	
	7905220330		Federal American Partners	7905240752	40-4492
	7905240495			7905240444	40-4492
	7905310386			7905020222	40-4492
	7905190072	50-320		7905070052	40-4492
	7905190070	50-320	Fellows Medical Mfg Co , Inc ,	7905230390	
	7905190077	50-320	Fellows-Testagar Div,		
	7905190074	50-320		7905230276	40-2407
	7905230507	50-320		7905230253	40-2407
	7905210076	50-320		7905230368	
	7905190079	50-320		7905230360	40-2407
	7905100436	50-312		7905230370	40-2407
	7905090383	50-404		7905230357	40-2407
	7905230019	50-320		7905230352	40-2407
	7905240763	70-138		7905230351	40-2407
	7905140411	50-99		7905230345	40-2407
	7905140414	50-99		7905230338	40-2407
	7905140408	50-99		7905230332	40-2407
	7905140383	50-99		7905230328	40-2407
	7905040114	70-27		7905230320	40-2407
	7905070245	70-1201		7905230315	40-2407
	7905100351			7905230312	40-2407
	7905150137	70-364		7905230304	40-2407
	7905290081	71-322		7905230299	40-2407
	7905240594	70-135		7905230284	40-2407
	7905230048	70-135		7905230261	40-2407
	7905290051	70-27		7905230247	40-2407
	7905190068	50-320		7905230788	40-2407
	7905030356			7905230224	
	7905290427	50-13		7905230584	
	7905310343			7905230214	
	7905090306		General Atomic Co. (subs. of Gulf Oil	7905150208	
	7905110309	50-99	Corp.)		
	7905210136			7905300326	
	7905140214			7904300260	
	7905030194			7905300321	
	7905070555			7905020387	71-6346
	7905310406			7905150008	
	7905310370	50-313	General Electric Co.	7905300361	
	7905190223	50-320		7905080442	
	7905100153			7905030106	
	7905020348			7905030123	
	7905080372			7905070105	
	7905080242			7905150382	70-784
	7905190161			7905210324	50-320
	7905160370			7905230696	
	7905220408			7905290087	70-1113
	7905160373			7905150791	70-1113
	7905220324			7905150627	71-5926
	7905240494			7905210328	50-320
	7905310377			7905080440	
Babcock & Wilcox Co , Nuclear Material	7905160388	70-135		7905190154	50-73
Div,	7905220077	70-135		7905210173	50-219
				7905040028	
	7905090060	70-135		7905140428	
Babcock & Wilcox Co., Nuclear Material	7905240089	70-364		7905140426	
Div	7905290410	70-364		7905110116	
Combustion Engineering, Inc.	7905240276	70-1100		7905080440	
	7905090055	50-317		7905220348	
	7905220083			7905090031	

CORPORATE SOURCE INDEX

361

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
General Dynamics Corp., Quincy Shipbuilding Div	7905290516	71-154	Ogle Petroleum, Inc.	7905100172	40-8693
General Electric Co., Nuclear Energy Products Div	7905300561		Offshore Power Systems (subs of Westinghouse Electric Corp.)	7905250313	50-437
	7905240176			7905250290	50-437
	7905210561			7905310458	50-437
	7905150203			7905040133	50-437
	7905170269	50-260		7905220022	50-437
	7905300535			7905190112	50-437
	7905300263	50-133		7905310455	50-437
	7905070091	70-1113	Pathfinder Mines Corp.	7905100025	40-2259
	7905240811	70-1113	Petrochemicals, Inc.	7905100284	40-6659
	7905150301	70-1308		7905240348	40-6659
	7905290091		Pullman, Inc.	7905150647	71-217
	7905240588	70-1007	Radium Chemical Co., Inc.	7905250540	
	7905100425	70-1308	Radiation Services, Inc.	7905250376	
	7905140305	70-1308	Reuter-Stokes, Inc.	7905250265	
	7905140309	70-1113	Rockwell International Corp.	7905080513	50-375
	7905220025	70-1113		7905080517	50-375
	7905240910	71-9009		7905090422	
	7905230730	70-784		7905080510	50-375
	7905240600	70-1113		7905220397	50-528
	7905230730	70-784	RSA Corp.	7905300114	
	7905290062	70-784	Sigma Chemical Co. (subs. of Sigma Aldrich Corp.)	7905150161	
	7905250218	70-784		7905030109	
	7905290259			7905140093	
	7905140392	50-219	Snupps-Standardized Nuclear Unit Power Plant System	7905070650	50-482
	7905210152				
	7905160428	50-70		7905310411	50-482
	7905300532				
	7905090275	50-183		7905070649	50-482
	7905010560			7905240608	71-5026
	7905160441		Teledyne, Inc.	7904300354	
	7905310339		Texas Instruments, Inc.	7904300328	
	7905300317			7905240078	70-33
	7905300558			7905230529	50-546
	7905100185			7905150193	
			Transnuclear, Inc.	7905290121	
	7905100194			7905100358	70-2084
	7905140274			7905020290	
	7905300532			7905240121	70-2198
	7905310321			7905100417	
	7905140297			7905290118	
	7905020328			7905150788	71-9120
	7905030340			7905230066	71-9120
	7905240353			7905150417	80-382
	7905100023		Chematron Corp., Tube Turns Div	7905100369	71-307
	7905070094		Texas Pipe Bending Co. (subs of Bendix Corp.)		
Golden Gate Switchboard Co.				7905100368	71-307
Gulf Oil Corp., Gulf Mineral Resources Co.			Union Carbide Corp.	7905070058	71-6058
Hess Oil Virgin Islands Corp.	7905130265	71-151		7905010501	50-299
Hoke, Inc.	7905170293			7905290033	40-299
	7905170283			7905100113	40-299
	7905170280			7905150281	71-6058
	7905170289			7905010531	50-54
	7905160103			7905010495	50-54
	7905240323			7905030231	
	7905150106		United Nuclear Corp.	7905220067	70-820
Hudson Products Corp.	7905240210	71-317		7905230236	70-820
Isotope Products Laboratories	7905240206	71-317		7905140544	40-8460
International Telephone & Telegraph Corp.	7905240116			79050303	
	7905230306			790524	
	7905080134	71-36		790515	
	7905080128	71-36		7905	
Kawacki Beryllco Industries, Inc.	7905040098			7905	
US Nuclear, Inc.	7905090425	40-8027		7905	
Liberty Equipment & Supply Co.	7905250373	50-416		7905	
Metals & Controls Corp.	7904300319		Unipax International	7905	
	7904300258		US Steel Corp.	7905	
	7904300173		Westinghouse Electric Corp.	7905	
	7904300341			7905	
Malco U.S.A., Inc.	7905250333			7905	
Metallforms, Inc.	7905150632	71-312		7905	
	7905150626	71-312		7905	
Mitsubishi Travel Service of America, Inc.	7905290139			7905	
Monsanto Co.	7905300339			7905	
	7905300332			7905	
	7905220105	71-9306		7905	
Mitsubishi International Corp. (subs of Mitsubishi Corp.)	7905240010			7905	
	7905250037			7905	
	7905140096			7905	
	7905240008			7905	
	7905250041			7905	
	7905250045			7905	
National Annealing Box Co.	7905100104	71-127		7905	
Nuclear Fuel Services, Inc. (subs of Getty Oil Co.)	7905240619	50-201		7905	
	7908020423	70-143		7905	
	7905240344	70-143		7905	
	7905020214	50-201		7905	
	7905150664	70-143		7905	
	7905250335	70-143		7905	
	7905150024	70-143		7905	
	7905100423	70-143		7905	
Nissho-Iwai American Corp.	7905290190			7905	
NL Industries, Inc.	7905110021	70-1318		7905	
NL Industries, NL Nuclear Div	7905250211	71-9023		7905	
Nuclear Packaging, Inc.	7905150786	71-9132		7905	
	7905240497	71-9116		7905	
... obsolete code...	7905240643	71-216		7905	
	7905240632	71-216		7905	

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7903110096		Minnesota, State of	7903080411	50-263
	7903210146			7903080482	50-263
	7903190063			7903080411	50-263
	7903090366		Missouri, State of	7903080482	50-263
Western Nuclear, Inc (subs of Phelps Dodge Corp)	7903150592	40-1162	North Dakota, State of	7903160410	50-483
	7903170292			7903100398	71-288
	7903240437	40-1162	New Hampshire, State of	7903100393	71-288
	7903240442	40-1162		7903250046	50-309
	7903300147	40-1162	New Jersey, State of	7903250044	50-309
Worthington Pump, Inc (subs of Studebaker-Worthington, Inc)	7903150766	71-309		7903240954	50-272
			New Mexico, State of	7903240787	50-272
	7903150763	71-309		7903240542	
Wyoming Mineral Corp	7903240267	40-8502		7903070201	
Yuba Heat Transfer Corp	7903250454			7903240377	
				7903150199	
				7903090176	
PROFESSIONAL/INDUSTRIAL INSTITUTIONS, SOCIETIES			Nevada, State of	7903250443	
			New York, State of	7903030247	50-549
Atomic Industrial Forum	7903140086	50-320		7903150271	50-592
	7903250467			7903250080	50-549
	7903160223	50-320		7903230813	50-201
Air Transport Association	7903040313			7903150266	50-596
American Mining Congress	7903150752			7903030239	50-549
American Nuclear Energy Council	7903140050	50-320		7903190099	50-320
American Newspaper Publishers Association	7903300531			7903070447	50-596
American Nuclear Society	7903090261			7903010497	50-244
American Society of Mechanical Engineers	7903080219			7903030350	50-549
Edison Electric Institute	7903040247			7903290435	
European Nuclear Conference	7903140260	50-320		7903150732	50-201
Health Physics Society	7903230577			7903250209	50-596
	7903220034			7903290106	50-516
Industry Advisory Group	7903190176	50-320	Ohio, State of	7903240433	
	7903230496	50-320	Oklahoma, State of	7903240275	50-536
	7903230468	50-320		7903190043	50-536
	7903230026	50-320		7903230759	50-536
	7903230063	50-320	Oregon, State of	7903230180	50-522
	7903230069	50-320		7903250819	
International Brotherhood of Electrical Workers	7903110026		Pennsylvania, State of	7903190231	50-320
Maine Merchants Association, Inc.	7903010349	50-309		7903140092	50-320
Non-Destructive Testing Management Association	7903150238			7903230453	
Portland Cement Association	7903080516	50-482	South Carolina, State of	7903230510	
Special Instrument Group	7903220453	50-320	Texas, State of	7903310111	50-466
				7903140060	50-466
			Utah, State of	7903240260	40-3453
				7903230042	40-8698
				7903150303	40-8698
				7903300505	40-8722
				7903240425	40-8681
				7903230201	40-8681
				7903240301	40-8681
				7903240424	
			Virginia, State of	7903030330	50-338
				7903230515	
			West Virginia, State of	7903300756	50-280
				7903040265	
			Wyoming, State of	7903290038	
				7903020280	40-299
STATE GOVERNMENTS/AGENCIES			U S FEDERAL GOVERNMENT AND AGENCIES		
Arkansas, State of	7903250512		Coast Guard, Transportation, Dept. of	7903250168	40-8681
Arizona, State of	7903240410		Congress (Joint & Rotating Committees, etc.)	7903150055	50-320
	7903240401		Defense, Dept. of, Defense Nuclear Agency	7903310356	50-170
	7903240438		Agriculture, Dept. of	7903090441	40-8698
California, State of	7903250470			7903010377	40-8698
	7903030090			7903090090	50-522
	7903300270	50-206		7903090345	50-592
	7903300277	50-206		7903100349	50-592
	7903010353	50-361		7903100349	50-592
	7903080028			7903100349	50-592
	7903300631	50-312		7903100349	50-592
	7903240598	50-592		7903100349	50-592
	7903300265	50-206		7903100349	50-592
	7903300631	50-312		7903100349	50-592
	7903100364	50-320		7903100349	50-592
	7903240644	50-312		7903100349	50-592
	7903240713	50-275		7903100349	50-592
Colorado, State of	7903150342			7903100349	50-592
Connecticut, State of	7903250504			7903100349	50-592
	7903250494			7903100349	50-592
	7903300647	50-245		7903100349	50-592
Delaware, State of	7903230451			7903100349	50-592
Florida, State of	7903230497			7903100349	50-592
Georgia, State of	7903230522			7903100349	50-592
Iowa, State of	7903230448			7903100349	50-592
	7903240417			7903100349	50-592
Illinois, State of	7903230768	50-295		7903100349	50-592
	7903250372	27-39		7903100349	50-592
	7903030171	27-39		7903100349	50-592
	7903150521	27-39		7903100349	50-592
	7903150256	50-295		7903100349	50-592
	7903310392	27-39		7903100349	50-592
	790310273			7903100349	50-592
	7903100190			7903100349	50-592
	7903150248	50-295		7903100349	50-592
	7903140153	50-115		7903100349	50-592
	7903100089	40-2061		7903100349	50-592
	7903110181	27-39		7903100349	50-592
	7903100032			7903100349	50-592
	7903070364	27-39		7903100349	50-592
Indiana, State of	7903140158			7903100349	50-592
Kansas, State of	7903230468			7903100349	50-592
Kentucky, State of	7903240725	50-546		7903100349	50-592
Massachusetts, State of	7903070026	50-443		7903100349	50-592
	7903240943	50-471		7903100349	50-592
	7903100326	50-471		7903100349	50-592
	7903090411	50-471		7903100349	50-592
	7903240794	50-471		7903100349	50-592
	7903230396			7903100349	50-592
Maine, State of	7903300372	50-309		7903100349	50-592
Michigan, State of	7903230504	50-315		7903100349	50-592
	7903140251	50-341		7903100349	50-592
	7903310360	50-329		7903100349	50-592
	7903080139			7903100349	50-592

363

[illegible]

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905040407	50-225		7905250413	50-325
	7905090082	50-329		7905250419	50-325
	7905030327	50-329		7905250219	50-261
	7905080480	50-155		7905250230	50-261
	7905080484	50-155		7905250388	50-261
	7905080488	50-155		7905300384	50-324
	7905250364	50-225		7905300390	50-329
	7905080532	50-329		7905300425	50-325
	7905080537	50-225		7905300432	50-325
	7905250278	50-155		7905300371	50-324
	7905100249	50-225		7905300375	50-324
	7905100252	50-225		7905300377	50-324
	7905100255	50-225		7905300380	50-324
	7905100259	50-225		7905300387	50-324
	7905150457	50-155		7905300397	50-324
	7905150459	50-155		7905300512	50-325
	7905150615	50-225		7905300518	50-325
	7905150625	50-225		7905010517	50-261
	7905220329	50-225		7905070475	50-400
	7905220335	50-225		7905090348	50-400
	7905220340	50-225		7905290380	50-400
	7905220343	50-225		7905040599	50-324
	7905300252	50-329		7905040607	50-324
	7905150484	50-155		7905140337	50-261
	7905210125	50-225		7905300449	
	7905250303	50-155		7905030353	50-324
	7905250326	50-329		7905040624	50-324
	7905150309	50-225		7905080402	50-324
	7905210150	50-225		7905080417	50-324
	7905310449	50-155		7905080436	50-324
	7905010498			7905310379	50-324
	7905040099	50-155		7905210165	50-324
	7905110085	50-225		7905230544	50-324
	7905140211	50-155		7905290370	50-324
	7905220020	50-225		7905190013	50-261
	7905210163	50-155		7905030331	50-261
	7905230052	50-225		7905040084	50-261
	7905230095	50-225		7905010552	50-261
	7905250095	50-155		7905040032	50-261
	7905030308	50-329		7905080437	50-261
	7905030358	50-329		7905150328	50-261
	7905030362	50-329		7905250121	50-261
	7905090307	50-329		7905220346	50-261
	7905110207	50-329		7905290374	50-261
	7905230761			7905080453	50-261
	7905090416		CEBS - Central & Southwest Services, Inc	7905090357	50-556
CPL - Carolina Power & Light Co.	7905070480	50-400	CYAP - Connecticut Yankee Atomic Power	7905300327	50-213
	7905150638	50-324	Co.		
	7905150426	50-261		7905070544	50-213
	7905190012	50-261		7905210214	50-213
	7905250124	50-261		7905210211	50-213
	7905020333	50-261		7905040070	50-213
	7905150631	50-324		7905240392	50-213
	7905150418	50-261		7905040061	50-213
	7905090302	50-324		7905310473	50-213
	7905140419	50-400		7905300323	50-213
	7905230223	50-324		7905310446	50-213
	7905080330	50-400		7905240503	50-213
	7905100241	50-324		7905070542	50-213
	7905230613	50-261	DAYP - Dairyland Power Cooperative	7905090356	50-409
	7905230604	50-261		7905160427	50-409
	7905010557	50-261		7905140234	50-409
	7905240192	50-324		7905140231	50-409
	7905250015	50-400		7905020238	50-409
	7905030345	50-324		7905290336	50-409
	7905030347	50-324		7905010504	50-409
	7905300283	50-324		7905010510	50-409
	7905040531	50-261		7905010520	50-409
	7905040535	50-261		7905290407	50-409
	7905300296	50-261		7905020243	50-409
	7905080504	50-325		7905240516	50-409
	7905080518	50-325		7905240698	50-409
	7905090282	50-324		7905150517	50-409
	7905090289	50-324		7905150530	50-409
	7905090311	50-324		7905250404	50-409
	7905090321	50-325		7905250417	50-409
	7905090324	50-325		7905090543	50-409
	7905090340	50-325		7905310337	50-409
	7905090344	50-325		7905040373	50-409
	7905150427	50-325		7905090352	50-409
	7905150432	50-325		7905160425	50-409
	7905150506	50-325		7905220401	50-409
	7905150518	50-325		7905290086	50-409
	7905150450	50-261		7905300012	50-409
	7905150451	50-261		7905300314	50-409
	7905150461	50-261	DE - Detroit Edison Co.	7905090355	50-341
	7905150463	50-261		7905150285	50-342
	7905190010	50-261		7905090351	50-341
	7905190027	50-261		7905160443	50-341
	7905190030	50-261		7905310451	50-16
	7905190086	50-261		7905230473	50-452
	7905190088	50-261		7905070442	
	7905220106	50-261	DL - Duquesne Light Co.	7905030344	50-334
	7905220110	50-261		7905010493	50-334
	7905230615	50-324		7905010531	50-412
	7905220342	50-325		7905010537	50-334
	7905220345	50-325		7905220099	50-334
	7905220361	50-325		7905220104	50-334
	7905220367	50-325		7905140302	50-334
	7905220369	50-325		7905180249	50-412
	7905220373	50-325		7905140300	50-334
	7905220406	50-324		7905310364	50-334
	7905220411	50-324		7905140322	50-334
	7905240630	50-325		7905250461	50-334
	7905240637	50-325		7905010541	50-412

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7903080460	50-334		7903110303	50-409
	7903080468	50-334		7903160361	50-269
	7903080543	50-334		7903310348	50-269
	7903080551	50-334		7903040352	50-269
	7903180531	50-334		7903080433	50-269
	7903180536	50-334		7903080566	50-269
	7903240568	50-334		7903080388	50-269
	7903240209	71-5450		7903110264	50-269
	7903030342	50-334		7903240231	50-269
	7903010532	50-334		7903150317	50-269
	7903090373	50-334		7903140283	50-269
	7903090666	50-334		7903140365	50-269
	7903010491	50-334		7903160389	50-269
	7903080370	50-334		7903220270	50-269
	7903110011	50-334		7903230487	50-287
	7903110070			7903230543	50-269
	7903220081	50-334		7903240593	50-287
	7903220093	50-334		7903240475	50-269
	7903240583	50-334		7903240478	50-269
	7903130247	50-412		7903310211	50-269
DPC - Duke Power Co	7903100301	50-269		7903070481	50-369
	7903190106	50-413		7903190100	50-413
	7903190101	50-413		7903030371	50-269
	7903190103	50-413		7903100299	50-269
	7903190104	50-413		7903100303	50-269
	7903110040	70-2623		7903230541	
	7903030099	50-488		7903110125	50-269
	7903110037	70-2623		7903110129	50-269
	7903150440	70-2623	EPEC - El Paso Electric Co	7903150282	50-592
	7903250061	50-491	FPC - Florida Power Corp.	7903210154	50-302
	7903160390	50-269		7903300189	50-302
	7903150262	50-369		7903300164	50-302
	7903290475	50-488		7903030351	50-302
	7903240470	70-2623		7903210153	50-302
	7903220239	50-269		7903070538	50-302
	7903220365	50-269		7903010408	50-302
	7903300550	50-269		7903080095	50-302
	7903240921	70-2623		7903100238	50-302
	7903250466			7903250390	50-302
	7903110264	50-269		7903040050	50-302
	7903220358	50-269		7903040094	50-302
	7903110017	50-269		7903070602	50-302
	7903110020	50-287		7903070626	50-302
	7903230770	50-369		7903240802	50-302
	7903020064	50-269		7903070340	50-302
	7903140506	50-287		7903040043	50-302
	7903230272	50-269		7903070648	50-302
	7903230279	50-269		7903040088	50-302
	7903080527	50-287		7903040632	50-302
	7903140483	50-287		7903040630	50-302
	7903230699	50-491		7903070337	50-302
	7903020408	50-369		7903070397	50-302
	7903100298	50-269		7903070611	50-302
	7903100046	50-269		7903070624	50-302
	7903140373	50-269		7903070645	50-302
	7903150254	50-369		7903070652	50-302
	7903290700	50-369		7903070654	50-302
	7903140167	50-413		7903080429	50-302
	7903240452	50-269		7903090281	50-302
	7903240426	50-369		7903290493	50-302
	7903240505	50-269		7903110244	50-302
	7903040047	50-269		7903090278	
	7903240520	50-491		7903290013	50-302
	7903020327	50-269		7903110241	50-302
	7903020340	50-269		7903190028	50-302
	7903080523	50-287		7903230373	50-302
	7903110268	50-269		7903190023	50-302
	7903150534	50-270		7903300303	50-302
	7903150548	50-270		7903250380	50-302
	7903230303	50-269		7903230369	50-302
	7903230305	50-269		7903250375	50-302
	7903250401	50-269		7903250385	50-302
	7903250408	50-269		7903250383	50-302
	7903250423	50-269		7903300497	50-302
	7903250427	50-269		7903300491	50-302
	7903310404	50-287		7903300484	50-302
	7903310410	50-287		7903310291	50-302
	7903020301	50-369		7903310403	50-302
	7903220463	70-2623		7903300668	71-6698
	7903240214	71-266		7903020291	50-302
	7903010521	50-269		7903020276	50-302
	7903010550	50-269		7903310298	50-302
	7903020283	50-269		7903300546	50-302
	7903040352	50-269		7903310399	50-302
	7903070481	50-369		7903150206	50-302
	7903080388	50-269		7903210272	50-302
	7903240466	50-269		7903300158	50-302
	7903140189	50-269		7903300185	50-302
	7903240231	50-269		7903250430	50-250
	7903150317	50-269		7903240492	50-251
	7903140283	50-269		7903140225	50-250
	7903140365	50-269		7903290159	50-335
	7903140268	50-269		7903150249	50-335
	7903160389	50-269		7903240048	50-335
	7903220270	50-269		7903150247	50-250
	7903220235	50-269		7903080467	50-250
	7903300541	50-269		7903080471	50-250
	7903220351	50-269		7903080554	50-251
	7903230487	50-287		7903080599	50-251
	7903240593	50-287		7903080567	50-251
	7903190100	50-413		7903080571	50-251
	7903240473	50-269		7903240434	50-250
	7903310211	50-269		7903240169	50-335
			FPL - Florida Power & Light Co.		

CORPORATE SOURCE INDEX

367

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905090067	50-250		7905110389	50-320
	7905090072	50-250		7905110397	50-320
	7905090074	50-250		7905110354	50-320
	7905090081	50-250		7905110401	50-320
	7905090082	50-335		7905110397	50-320
	7905090084	50-335		7905110395	50-320
	7905220091	50-335		7905110392	50-320
	7905220103	50-250		7905110393	50-320
	7905220113	50-250		7905110406	50-320
	7905300015	50-250		7905110403	50-320
	7905220122	50-250		7905110405	50-320
	7905220128	50-250		7905110402	50-320
	7905250388	50-250		7905110400	50-320
	7905250392	50-250		7905110396	50-320
	7905150241	50-335		7905110385	50-320
	7905220098	50-335		7905110384	50-320
	7905250397	50-335		7905110382	50-320
	7905250411	50-250		7905110378	50-320
	7905300040	50-250		7905110376	50-320
	7905080412	50-250		7905110373	50-320
	7905140217	50-250		7905110368	50-320
	7905140310	50-335		7905110366	50-320
	7905240486	50-251		7905110337	50-320
	7905240347	50-250		7905230117	50-320
	7905250426	50-250		7905230099	50-320
	7905040583	50-335		7905230107	50-320
	7905070410	50-335		7905230110	50-320
	7905210121	50-335		7905190116	50-320
	7905220027	50-335		7905190113	50-320
	7905310214	50-335		7905190111	50-320
	7905300014	50-335		79052210228	50-320
	7905310303	50-335		7905190093	50-320
	7905310309	50-335		7905190120	50-320
	7905140220	50-250		7905190187	50-320
	7905290143	50-250		7905230009	50-320
	7905150603			7905230005	50-320
GAP - Georgia Power Co.	7905150348	50-366		7905230006	50-320
	7905250462			7905230103	50-320
	7905150344	50-366		7905230362	50-320
	7905080524	50-321		7905210120	50-320
	7905140316	50-321		7905230082	50-320
	7905100244	50-321		7905230011	50-320
	7905010470	50-366		7905230013	50-320
	7905010469	50-366		7905230024	50-320
	7905010502	50-321		7905230368	50-219
	7905080546	50-321		7905210270	50-219
	7905080550	50-321		7905230080	50-320
	7905290029	50-321		7905070203	50-320
	7905080473	50-321	GSU - Gulf States Utilities Co	7905110374	50-458
	7905080479	50-321		7905230808	50-458
	7905080520	50-321		7905150453	50-458
	7905070639	50-366	HLP - Houston Lighting & Power Co	7905310429	50-498
	7905070646	50-366		7905080409	50-498
	7905300309	50-321		7905240693	50-498
	7905240489	50-424		7905030336	50-498
	7905150465	50-366		7905080408	50-498
	7905150467	50-366		7905150236	50-498
	7905150319	50-321		7905250398	50-446
	7905150325	50-321	IELP - Iowa Electric Light & Power Co	7905210224	50-331
	7905150343	50-321		7905210220	50-331
	7905150349	50-321		7905110163	50-331
	7905290035	50-321		7905150050	50-331
	7905300627	50-321		7905300272	50-331
	7905300638	50-321		7905020251	50-331
	7905300644	50-321		7905020253	50-331
	7905300660	50-321		7905250213	50-331
	7905300683	50-321		7905160363	50-331
	7905300688	50-321		7905160368	50-331
	7905300591	50-321		7905160386	50-311
	7905300603	50-321		7905160387	50-331
	7905300664	50-321		7905290182	50-331
	7905300676	50-321		7905290191	50-331
	7905250098	50-321		7905100400	71-296
	7905190213	50-321		7905040491	50-331
	7905170234	50-321		7905080469	50-331
	7905230047	50-321		7905090368	50-331
	7905230338	50-321		7905080465	50-331
	7905290184	50-366		7905310447	50-331
	7905300006	50-321		7905230522	50-331
	7905080427	50-321	IIGE - Iowa-Illinois Gas & Electric	7905070406	
	7905240227	50-424	ILPR - Illinois Power Co.	7905290563	50-461
	7905020241	50-424	IMPR - Indiana & Michigan Power Co.	7905070437	50-315
	7905230398	50-424		7905170252	50-315
	7905190059	50-321		7905170262	50-316
GENP - General Public Utilities	7905110234	50-320		7905170248	50-315
GMPC - Green Mountain Power Corp.	7905140065	50-320		7905170261	50-316
	7905170251	50-443		7905150156	50-315
	7905310261	50-271		7905250392	50-313
GPU - GPU Service Corp	7905170253	50-443		7905040001	50-316
	7905230012	50-320		7905040002	50-316
	7905230010	50-320		7905150345	50-313
	7905230007	50-320		7905070583	50-316
	7905230008	50-320		7905070590	50-316
	7905220438	50-320		7905070598	50-315
	7905190140	50-320		7905070604	50-315
	7905230014	50-320		7905070613	50-315
	7905230015	50-320		7905280371	50-315
	7905230001	50-320		7905310469	50-315
	7905190089	50-320		7905110120	50-315
	7905140025	50-320		7905110124	50-315
	7905210018	50-320		7905150423	50-315
	7905210021	50-320		7905150430	50-315
	7905110370	50-320		7905150438	50-315
	7905110367	50-320		7905150441	50-315

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
JCPL - Jersey Central Power & Light Co	7905150488	50-316		7905110170	
	7905150493	50-316		7905110176	50-320
	7905150501	50-316		7905140140	50-320
	7905210135	50-315		7905110079	50-320
	7905210142	50-315		7905080528	50-320
	7905220320	50-315		7905080531	50-320
	7905220326	50-315		7905190248	50-320
	7905220333	50-315		7905190246	50-320
	7905220339	50-315		7905190243	50-320
	7905230325	50-316		7905160380	50-320
	7905230330	50-316		7905080526	50-320
	7905310367	50-316		7905230376	50-289
	7905070396	50-316		7905030338	50-289
	7905070428	50-315		7905090320	50-320
	7905110183	50-315		7905230189	50-320
	7905290149	50-315		7905220371	50-289
	7905290366	50-315		7905160174	50-320
	7905310440	50-315		7905110333	50-320
	7905040056	50-315		7905160141	50-320
	7905040611	50-315		7905160135	50-320
	7905240602	50-315		7905230375	50-289
	7905020401	50-315		7905230018	50-320
	7905070470	50-363		7905090251	50-320
	7905250084	50-219		7905190209	50-320
	7905150277	50-219		7905190231	50-320
	7905210179	50-219		7905190215	50-320
	7905210269	50-219		7905210240	50-320
	7905290198	50-219		7905080445	50-289
	7905250077	50-219		7905080451	50-289
	7905250349	50-219		7905080542	50-289
	7905300733	50-219		7905080547	50-289
	7905070557	50-219		7905080521	50-320
	7905070651	50-219		7905290350	50-289
	7905040478	50-219		7905220318	50-289
	7905040481	50-219		7905220325	50-289
	7905090332	50-219		7905290384	50-289
	7905140330	50-219		7905140282	50-289
	7905090329	50-219		7905140296	50-289
	7905140327	50-219		7905110165	50-320
	7905140341	50-219		7905110178	50-289
	7905140243	50-219		7905110149	50-320
	7905150470	50-219		7905110173	50-289
	7905150472	50-219		7905190121	50-320
	7905160369	50-219		7905020274	50-289
	7905160374	50-219		7905020468	50-320
	7905210210	50-219		7905230003	50-320
	7905210217	50-219		7905230082	50-320
	7905210274	50-219		7905070587	50-289
	7905210281	50-219		7905190115	50-320
	7905220381	50-219		7905240558	50-289
	7905220388	50-219		7905190169	50-320
	7905290014	50-219		7905190229	50-320
	7905290017	50-219		7905090337	50-320
	7905290023	50-219		7905190236	50-320
	7905290025	50-219		7905300135	50-320
	7905290164	50-219		7905100420	50-289
	7905290175	50-219	MPL - Mississippi Power & Light Co	7905140340	50-416
	7905070633	50-219		7905090271	
	7905150275	50-219		7905300441	50-416
	7905240347	50-219		7905140339	50-416
	7905210174	50-219		7905020435	50-416
	7905220088	50-219		7905140334	50-416
	7905210265	50-219		7905290361	50-416
	7905210267	50-219		7905040510	50-416
	7905240513	50-219		7905040631	50-416
	7905290178	50-219		7905040636	50-416
	7905290194	50-219		7905300439	50-416
	7905290172	50-219		7905080430	50-416
	7905290351	50-219		7905090268	
	7905290394	50-219		7905090375	50-309
	7905230302	50-219		7905150520	50-309
KSCE - Kansas Gas & Electric Co	7905070466	50-363		7905240657	50-309
	7905110314	50-482		7905150516	50-309
	7905300626	50-482		7905030185	50-309
	7905290326	50-482		7905250456	50-309
	7905080514	50-482		7905250355	50-309
LAPL - Louisiana Power & Light Co	7905110311	50-482		7905090330	50-309
	7905110262	50-382		7905080433	50-309
	7905150273	50-382		7905150434	50-309
	7905150415	50-382		7905210127	50-309
	7905170231	50-382		7905210130	50-309
	7905240590	50-382		7905210161	50-309
	7905150264	50-382		7905250139	50-309
	7905150408	50-382		7905220341	50-309
	7905170228	50-382		7905230528	50-309
	7905110260	50-382		7905090061	50-309
	7905240634	50-322		7905090372	50-309
	7905240645	50-322		7905090382	50-309
	7905240648	50-322		7905240686	50-309
	7905240650	50-322		7905300019	50-309
	7905150207	50-322		7905230467	50-309
	7905240376	50-322		7905190151	50-309
	7905290210	50-322		7905220243	50-309
	7905240996	50-322		7905220251	50-309
	7905040439	50-322		7905230803	50-309
	7905040318	50-322		7905040514	50-309
	7905080500	50-322	NENE - Northeast Nuclear Energy Co. (Northeast Utilities)	7905010485	50-245
	7905240369	50-322			
	7905240639	50-322			
	7905080508	50-321	NENP - New England Power Co	7905010496	50-245
Authority of	7905080497	50-321	NEUT - Northeast Utilities	7905110137	50-213
	7905100425	50-289		7905070666	50-336
				7905150505	50-336
				7905310189	50-336

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905220404	50-245		7905150468	50-282
	7905250523			7905210279	50-304
	7905150502	50-334		7905210283	50-304
	7905220395	50-245		7905220114	50-304
	7905250444	50-213		7905220118	50-263
	7905080454	50-334		7905230519	50-263
	7905080461	50-334		7905230429	50-263
	7905300452	50-334		7905140104	50-282
	7905300457	50-334		7905020236	50-263
	7905300533	50-245		7905090369	50-263
	7905300544	50-245		7905010474	50-282
	7905290221	50-334		7905080413	50-263
	7905290076	71-9044		7905010479	50-282
	7905190075	50-245		7905040330	50-263
	7905040053	50-334		7905070344	50-263
	7905040135	50-334		7905070459	50-282
	7905070359	50-334		7905130225	50-263
	7905080406	50-334		7905240560	50-263
	7905100320	50-334		7905240681	50-263
	7905160262	50-334		7905300406	50-282
	7905160376	50-334		7905230394	50-263
	7905220116	50-334		7905290093	50-263
	7905290073	50-213		7905040517	50-263
	7905300009	50-334		7905040011	50-263
	7905300261	50-334		7905190033	50-263
	7905310183	50-334		7905300477	50-394
	7905070621	50-245	NYEO - New York State Electric & Gas Corp.	7905310342	50-594
	7905080562	50-245		7905010494	50-594
	7905080454	50-245		7905220120	50-594
	7905290073	50-213		7905240160	50-594
	7905150439	50-423	NYSEO - New York State Electric & Gas	7905300353	50-283
	7905070658	50-213	OPPD - Omaha Public Power District	7905090363	50-283
	7905250513			7905140240	50-283
NIPS - Northern Indiana Public Service Co.	7905210280	50-367		7905150319	50-283
	7905010934	50-367		7905310248	50-283
	7905140308	50-367		7905140238	50-283
	7905110306	50-367		7905140494	50-283
	7905220207	50-367		7905140487	50-283
	7905210277	50-367		7905290222	50-283
NMP - Niagara Mohawk Power Corp	7905300329	50-367		7905150211	50-283
	7905020367	50-220		7905230618	50-283
	7905150511	50-220		7905070543	50-283
	7905310221	50-220		7905100128	50-283
	7905150508	50-220		7905240672	50-283
	7905100421	50-220		7905290499	50-283
	7905070401	50-220		7905210259	50-283
	7905070411	50-220		7905070541	50-238
	7905160392	50-220		7905210256	50-283
	7905160394	50-220		7905210268	50-283
	7905300486	50-220		7905210271	50-283
	7905300496	50-220		7905220300	50-283
	7905150291	50-220		7905220306	50-283
	7905220295	50-220		7905300557	50-283
	7905080414	50-220		7905300548	50-283
	7905220478	50-220		7905160382	50-283
	7905150597			7905160406	50-283
NPPD - Nebraska Public Power District	7905080495	50-298		7905300349	50-283
	7905150526	50-298		7905230458	50-283
	7905150522	50-298		7905090317	50-283
	7905020129	50-298		7905080446	50-283
	7905140335	50-298		7905090046	50-283
	7905140336	50-298		7905100312	50-283
	7905080487	50-298	PACP - Pacific Power Co	7905240562	50-283
	7905150384	50-298		7905090293	50-308
	7905160127	50-298		7905220304	50-344
	7905140228	50-298		7905230472	50-322
	7905020269	50-298	PASN - Power Authority State of New York	7905040518	50-286
	7905080478	50-298		7905100161	50-286
	7905150369	50-298		7905100183	50-333
	7905230355	50-298		7905150304	50-286
NSP - Northern States Power Co.	7905010511	50-282		7905100179	50-333
	7905150231	50-263		7905110256	50-333
	7905070380	50-263		7905220380	50-286
	7905040022	50-263		7905110294	50-333
	7905070372	50-263		7905150302	50-286
	7905150499	50-282		7905030181	50-286
	7905090392	50-263		7905010584	50-333
	7905010509	50-282		7905250172	50-286
	7905090388	50-263		7905220319	50-286
	7905150496	50-282		7905220322	50-286
	7905070344	50-282		7905220327	50-286
	7905150575	50-263		7905220331	50-286
	7905290321	50-263		7905220334	50-286
	7905030364	50-282		7905220338	50-286
	7905030367	50-282		7905250162	50-333
	7905020462	50-282		7905250241	50-286
	7905040521	50-282		7905240290	50-333
	7905040604	50-263		7905010499	50-333
	7905080543	50-282		7905010503	50-333
	7905080569	50-282		7905010505	50-333
	7905080424	50-263		7905010508	50-333
	7905080438	50-263		7905250194	50-333
	7905290290	50-282		7905010516	50-286
	7905110127	50-282		7905010522	50-286
	7905110131	50-282		7905090301	50-286
	7905140214	50-282		7905090305	50-286
	7905160332	50-282		7905150479	50-333
	7905160358	50-282		7905150477	50-333
	7905160379	50-263		7905300411	50-333
	7905160381	50-263		7905300416	50-333
	7905150466	50-282		7905300506	50-333

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905300314	50-333		7905220311	50-344
	7905300522	50-333		7905220316	50-344
	7905300527	50-333		7905310350	50-344
	7905070168	50-286		7905020388	50-344
	7905100175	50-333		7905220078	50-344
	7905110175	50-333		7905300426	50-344
	7905220387	50-333		7905020478	50-344
	7905040505	50-333		7905040520	50-344
	7905080565	50-333		7905090291	50-344
	7905090315	50-333		7905150387	50-344
	7905090343	50-333		7905230492	50-344
	7905140307	50-333		7905220187	50-344
	7905150452	50-333		7905230407	50-344
	7905190073	50-333		7905110014	50-314
	7905230430	50-333		7905080431	50-344
	7905240697	50-333		7905290042	50-344
	7905040513	50-286		7905090433	50-387
	7905100156	50-286	PPL - Pennsylvania Power & Light Co.	7905040506	50-387
	7905230531	50-286		7905030149	50-387
	7905310394	50-286		7905250186	50-387
	7905310443	50-286		7905110300	50-387
PECO - Philadelphia Electric Co	7905070417			7905160424	50-387
	7905140346	50-277		7905250421	50-387
	7905030352	50-277		7905040146	50-387
	7905110076	50-277		7905040304	50-387
	7905170241	50-277		7905240574	50-387
	7905170236	50-277		7905020262	50-387
	7905220280	50-277		7905090365	50-387
	7905220284	50-277		7905150224	50-387
	7905080464	50-277	PSC - Public Service Co of Colorado	7905090346	50-387
	7905250152	50-277		7905010314	50-267
	7905040578	50-277		7905080437	50-267
	7905040077	50-277		7905010507	50-267
	7905040092	50-277		7905080485	50-267
	7905140344	50-277		7905140288	50-267
	7905040581	50-277		7905140294	50-267
	7905150443	50-277		7905140319	50-267
	7905230861	50-277		7905140323	50-267
	7905160383	50-277		7905250464	50-267
	7905290214	50-277		7905230637	50-267
	7905290216	50-277		7905300222	50-267
	7905230710	50-277		7905040374	50-267
	7905240184	50-277		7905040376	50-267
	7905030348	50-277		7905080544	50-267
	7905110073	50-277		7905080549	50-267
	7905220347	50-277		7905160367	50-267
	7905020347	50-277		7905160371	50-267
	7905020356	50-277		7905160372	50-267
	7905290345	50-277		7905160377	50-267
PEP - Petomac Electric Power Co	7905020538			7905230393	50-267
	7905090376	50-448		7905230403	50-267
	7905090374	50-448		7905010361	50-267
POE - Pacific Gas & Electric Co	7905300174	50-133		7905150800	50-267
	7905300529	50-133		7905160315	50-267
	7905150368			7905230023	50-267
	7905030244	50-275	PBEO - Public Service Electric & Gas Co.	7905030321	50-267
	7905140554	50-275	of New Jersey	7905080483	50-311
	7905140556	50-275			
	7905150803				
	7905090319	50-133		7905300421	50-272
	7905190132	50-133		7905150299	50-272
	7905300007	50-275		7905250471	50-272
	7905300364	50-275		7905080462	50-272
	7905250490	50-275		7905080466	50-272
	7905020302	50-275		7905300417	50-272
	7905190130	50-133		7905300421	50-272
	7905140303	50-133		7905080489	50-272
	7905140304	50-133		7905150295	50-272
	7905150809	50-133		7905070140	50-272
	7905090380	50-275		7905290065	50-272
	7905240701	50-275		7905290070	50-272
	7905290011	50-133		7905290495	50-272
	7905190054	50-275		7905030360	50-272
	7905300168	50-133		7905010325	50-272
	7905140406	50-133		7905010335	50-272
	7905300310	50-133		7905250441	50-272
	7905090318	50-133		7905040538	50-272
	7905020244	50-275		7905040541	50-272
	7905210172	50-275		7905040370	50-272
	7905210169	50-275		7905040371	50-272
PG&E - Portland General Electric Co	7905300361	50-275		7905080485	50-272
	7905250475	50-344		7905080525	50-272
	7905030158	50-344		7905140227	50-272
	7905150722	50-344		7905230072	50-272
	7905090288	50-344		7905150444	50-272
	7905220298	50-344		7905150446	50-272
	7905040523	50-344		7905150462	50-272
	7905110169	50-344		7905180464	50-272
	7905240948	50-344		7905220127	50-272
	7905030361	50-344			
	7905240948	50-344		7905220132	50-272
	7905110167	50-344		7905220308	50-272
	7905290078	50-344		7905220314	50-272
	7905040458	50-344		7905290406	50-272
	7905040449	50-344		7905080421	50-272
	7905150812	50-344		7905300363	50-272
	7905240908	50-344		7905070552	50-354
	7905100267	50-344		7905070647	50-272
	7905100270	50-344		7905170263	50-272
	7905170238	50-344		7905150280	50-272
	7905170247	50-344		7905040517	50-311
	7905220289	50-344		7905080481	50-311
	7905220293	50-344		7905090308	50-311

CORPORATE SOURCE INDEX

371

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
PSIN - Public Service Co of Indiana, Inc.	7905220349	50-272	TOED - Toledo Edison Co	7905190134	50-312
	7905250100	50-311		7905110153	50-312
	7905250415	50-311		7905010477	50-443
	7905140097	50-546		7905110307	50-312
PSNH - Public Service Co of New Hampshire	7905250433	50-546	TVA - Tennessee Valley Authority	7905020306	50-312
	7905160400	50-546		7905100424	50-312
	7905310420	50-546		7905150053	50-312
	7905080415	50-546		7905290067	50-312
PSOK - Public Service Co of Oklahoma	7905290063	50-443		7905140235	50-346
	7905090359	50-556		7905150405	50-346
	7905250029	50-556		7905290422	50-346
	7905230424	50-556		7905240671	50-346
PSPL - Puget Sound Power & Light Co.	7905240393	50-556		7905240586	50-346
	7905090285	50-509		7905140233	50-346
	7905250463	50-522		7905100380	50-346
	7905160356	50-522		7905100341	50-346
ROE - Rochester Gas & Electric Corp	7905160347	50-522		7905100345	50-346
	7905250459	50-522		7905220125	50-346
	7905310372	50-522		7905020266	50-346
	7905310383	50-522		7905240097	50-346
SCE - Southern California Edison Co.	7905030359	50-244		7905250198	50-346
	7905240227	50-244		7905100286	50-346
	7905220223	50-244		7905020303	50-346
	7905250181	50-244		7905020330	50-346
SCEG - South Carolina Electric & Gas Co.	7905040101	50-244		7905020418	50-346
	7905040147	50-244		7905020438	50-346
	7905040180	50-244		7905020488	50-346
	7905040187	50-244		7905020300	50-346
SDGE - San Diego Gas & Electric Co	7905040191	50-244		7905020427	50-346
	7905110101	50-244		7905020443	50-346
	7905110104	50-244		7905040129	50-346
	7905310431	50-244		7905040132	50-346
SMUD - Sacramento Municipal Utility District	7905310435	50-244		7905090269	50-346
	7905230417	50-244		7905090273	50-346
	7905070486	50-244		7905150402	50-346
	7905070380	50-244		7905150455	50-346
SCEQ - South Carolina Electric & Gas Co.	7905100149	50-244		7905150456	50-346
	7905150393	50-244		7905160404	50-346
	7905220377	50-244		7905160409	50-346
	7905220031	50-244		7905220124	50-346
SCEG - South Carolina Electric & Gas Co.	7905300474	50-244		7905220096	50-346
	7905310395	50-244		7905220101	50-346
	79053150619	50-244		7905220117	50-346
	7905150404	50-206		7905220121	50-346
SCEG - South Carolina Electric & Gas Co.	7905090326	50-206		7905250134	50-346
	7905090361	50-206		7905250142	50-346
	7905150411	50-206		7905110099	50-346
	7905310426	50-361		7905110091	50-346
SCEG - South Carolina Electric & Gas Co.	7905150409	50-206		7905150121	50-346
	7905290069	50-206		7905080416	50-346
	7905290300	50-206		7905300418	50-346
	7905240073	50-206		7905090353	50-346
SCEG - South Carolina Electric & Gas Co.	7905040386	50-206		7905170031	50-346
	7905040592	50-206		7905220095	50-346
	7905090277	50-361		7905230371	50-346
	7905080418	50-206		7905240403	50-346
SCEG - South Carolina Electric & Gas Co.	7905080425	50-206		7905290419	50-346
	7905110134	50-206		7905310450	50-346
	7905110139	50-206		7905300483	50-346
	7905150503	50-206		7905310375	50-346
SCEG - South Carolina Electric & Gas Co.	7905150512	50-206		7905140284	50-443
	7905240689	50-206		7905140226	50-443
	7905310423	50-361		7905140224	50-443
	7905310439	50-206		7905240196	50-443
SCEG - South Carolina Electric & Gas Co.	7905310444	50-206		7905300761	50-443
	7905240395	50-206		7905290648	50-443
	7905090325	50-206		7905210192	50-443
	7905150400	50-206		7905030365	50-443
SCEG - South Carolina Electric & Gas Co.	7905170257	50-206		7905090313	50-443
	7905210160	50-361		7905020159	50-320
	7905090347	50-206		7905010567	50-290
	7905160319	50-206		7905160460	50-290
SCEG - South Carolina Electric & Gas Co.	7905150374	50-206		7905140497	50-290
	7905110035	50-206		7905140451	50-290
	7905230514	50-206		7905290399	50-290
	7905300696	50-393		7905140482	50-290
SCEG - South Carolina Electric & Gas Co.	7905090420	50-393		7905240874	50-290
	7905230605	50-393		7905140363	50-290
	7905010483	50-393		7905140473	50-290
	7905290105	50-393		7905140491	50-290
SCEG - South Carolina Electric & Gas Co.	7905300692	50-393		7905140491	50-290
	7905150406	50-206		7905140491	50-290
	7905190150	50-206		7905140491	50-290
	7905090085	50-592		7905140491	50-290
SCEG - South Carolina Electric & Gas Co.	7905100282	50-312		7905140491	50-290
	7905110004	50-312		7905140491	50-290
	7905100293	50-312		7905140491	50-290
	7905100281	50-312		7905140491	50-290
SCEG - South Carolina Electric & Gas Co.	7905100430	50-312		7905140491	50-290
	7905110032	50-312		7905140491	50-290
	7905110039	50-312		7905140491	50-290
	7905220465	50-312		7905140491	50-290
SCEG - South Carolina Electric & Gas Co.	7905250434	50-312		7905140491	50-290
	7905250437	50-312		7905140491	50-290
	7905290004	50-312		7905140491	50-290
	7905300405	50-312		7905140491	50-290
SCEG - South Carolina Electric & Gas Co.	7905300409	50-312		7905140491	50-290
	7905190156	50-312		7905140491	50-290
	7905240710	50-312		7905140491	50-290
	7905290369	50-312		7905140491	50-290

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905140352	50-327		7905020519	50-280
	7905230733	50-366		7905240181	50-280
	7905080176	50-259		7905010484	50-281
	7905140468	50-327		7905010487	50-281
	7905140490	50-390		7905010492	50-280
	7905140458	50-327		7905010498	50-280
	7905140495	50-327		7905020391	50-338
	7905140503	50-390		7905040626	50-338
	7905250344	50-259		7905300734	50-338
	7905010481	50-390		7905040396	50-280
	7905010518	50-390		7905040414	50-280
	7905300745	50-259		7905070404	50-339
	7905030343	50-259		7905070533	50-338
	7905300253	50-327		7905070659	50-338
	7905040562	50-327		7905070662	50-338
	7905090333	50-327		7905070530	50-338
	7905090336	50-327		7905070656	50-338
	7905240652	50-259		7905080511	50-339
	7905090314	50-259		7905240481	50-338
	7905090316	50-259		7905300706	50-280
	7905110191	50-327		7905080434	50-339
	7905110228	50-390		7905080444	50-338
	7905110196	50-296		7905080447	50-338
	7905110201	50-296		7905080449	50-338
	7905110313	50-260		7905080452	50-339
	7905110318	50-260		7905090297	50-339
	7905110317	50-390		7905110147	50-338
	7905190197	50-327		7905110152	50-338
	7905110303	50-327		7905110142	50-338
	7905190217	50-390		7905110157	50-280
	7905230562	50-327		7905110164	50-280
	7905230569	50-327		7905110214	50-339
	7905230078	50-260		7905110418	50-339
	7905230336	50-260		7905190123	50-280
	7905230381	50-390		7905190119	50-280
	7905230548	50-438		7905210258	50-338
	7905230557	50-438		7905210260	50-338
	7905230645	50-327		7905210275	50-280
	7905310362	50-260		7905220344	50-339
	7905310363	50-260		7905220287	50-338
	7905310425	50-296		7905220296	50-338
	7905310427	50-296		7905230060	50-338
	7905310368	50-260		7905230071	50-338
	7905310369	50-260		7905230341	50-281
	7905240972	50-25		7905230344	50-281
	7905040345	50-353		7905230141	50-280
	7905040500	50-327		7905230180	50-280
	7905080541	50-318		7905230184	50-280
	7905140270	50-353		7905230197	50-280
	7905140272	50-327		7905290005	50-280
	7905140371	50-259		7905290010	50-280
	7905110024	50-259		7905290032	50-280
	7905170268	50-260		7905290404	50-339
	7905300462	50-318		7905300017	50-339
	7905310314	50-327		7905300018	50-280
	7905300305	50-327		7905300401	50-338
	7905010475	50-259		7905300404	50-338
	7905110177	50-259		7905300406	50-338
	7905150322	50-296		7905300412	50-338
	7905230378	50-260		7905110432	50-338
	7905110211	50-296		7905110437	50-338
	7905150286	50-318		7905110444	50-338
	7905010364	50-390		7905110454	50-338
	7905040348	50-390		7905110458	50-338
	7905070420	50-327		7905020338	50-338
	7905110225	50-390		7905040468	50-280
	7905090341	50-327		7905070473	50-280
	7905110008	50-327		7905040036	50-280
	7905230519	50-327		7905040126	50-338
	7905290363	50-327		7905240407	50-338
	7905290390	50-390		7905040380	50-280
	7905290503			7905070637	50-280
	7905290115			7905080441	50-339
VEPC - Virginia Electric & Power Co	7905030207	50-338		7905070460	50-280
	7905030209	50-338		7905070655	50-280
	7905110088	50-280		7905100317	50-338
	7905040472	50-280		7905080443	50-338
		50-280		7905110062	50-338
		50-338		7905110087	50-280
		280		7905150270	50-338
		338		7905210176	50-338
		339		7905220111	50-404
		339		7905220142	50-280
		339		7905230536	50-338
		338		7905230022	50-338
		338		7905230108	50-280
		338		7905290375	50-338
		338		7905230132	50-280
		281		7905290001	50-280
		280		7905300312	50-280
		339		7905240342	50-338
		338		7905240485	50-280
		280		7905070473	50-280
		338		7905070610	50-280
		338		7905080538	50-280
		338		7905250092	50-280
		338		7905040468	50-280
		339		7905040380	50-280
		338		7905110087	50-280
		338		7905230108	50-280
		338		7905290001	50-280
		280		7905300312	50-280
				7905220142	50-280

CORPORATE SOURCE INDEX

373

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905020358	50-338		7905300030	50-305
	7905040126	50-338		7905150330	50-305
	7905240407	50-338		7905290501	50-305
	7905080428	50-338		7905240289	50-305
	7905080443	50-338		7905150563	50-305
	7905080506	50-338		7905150567	50-305
	7905190062	50-338		7905300399	50-305
	7905110297	50-404		7905310365	50-305
	7905150270	50-338		7905310366	50-305
	7905220111	50-404		7905300395	50-305
	7905230536	50-338		7905160364	50-305
	7905230022	50-338		7905240384	50-305
	7905290296	50-280		7905100289	50-305
	7905090435			7905300028	50-305
VYNP - Vermont Yankee Nuclear Power Corp.	7905040305		WMPC - Washington Water Power Co	7905090303	50-508
	7905070592	50-271	YAE - Yankee Atomic Electric Co.	7905150337	50-29
	7905010482	50-271		7905240776	
	7905070462	50-271		7905250473	
	7905150343	50-271		7905150334	50-29
	7905010506	50-271		7905080075	50-29
	7905150341	50-271		7905250452	50-29
	7905070693	50-271		7905250359	50-29
	7905080552	50-271		7905150422	50-29
	7905080553	50-271		7905150428	50-29
	7905290088	50-271		7905150433	50-29
	7905290037	50-271		7905150437	50-29
	7905290040	50-271		7905190126	50-29
	7905010500	50-271		7905190128	50-29
	7905100319	50-271		7905290058	50-29
	7905160253	50-271		7905030333	50-29
	7905210197	50-271		7905160309	50-29
	7905150361	50-271		7905310390	50-29
	7905070588	50-271		7905040039	50-271
	7905080423	50-271		7905110317	50-29
	7905010480	50-271		7905070548	50-29
	7905070455	50-271			
	7905070588	50-271			
WIEP - Wisconsin Electric Power Co	7905240613	50-271	RESEARCH INSTITUTIONS AND LABORATORIES		
	7905010490	50-502	Argonne National Laboratory	7905140164	
	7905010515	50-502		7905240886	
	7905160365	50-266		7905090406	
	7905160362	50-266		7905040462	50-329
	7905020289	50-301		7905160058	71-5795
	7905020304	50-301		7905130099	
	7905020310	50-266		7905110348	50-320
	7905020318	50-266		7905250214	
	7905290075	50-266	Battelle Memorial Institute, Columbus Laboratories	7905100126	71-6058
	7905240519	50-266		7905150814	70-8
	7905100256	50-301		7905240391	50-6
	7905100263	50-301		7905150140	
	7905240303	50-266		7905030015	
	7905100314	50-301			
	7905100315	50-301	Battelle Memorial Institute, Pacific Northwest Laboratory	7905030246	
	7905300316	50-266		7905250133	
	7905240831	50-266		7905300523	50-360
	7905240611	50-266		7905130777	
	7905240627	50-266		7905310015	
	7905290284	50-266		7905240113	
	7905150378	50-301		7905100243	
	7905010489	50-502	Brookhaven National Laboratory	7905130196	50-27
	7905010513	50-502		7905130219	
	7905020271	50-266		7905130201	50-272
	7905080470	50-502		7905100235	50-309
	7905300453	50-301		7905240320	50-286
	7905230463	50-266		7905160415	50-254
	7905150349			7905300466	50-266
	7905150202	50-266		7905070495	
	7905150448	50-266		7905240529	
	7905240397	50-301		7905100021	
	7905310359	50-266		7905240427	
	7905300453	50-301		7905240415	
	7905300337	50-502		7905240389	
	7905150381	50-502		7905240199	50-280
	7905070319	50-397		7905090430	
				7905250106	
	7905090295	50-508	Environmental Policy Institute	7905100165	
	7905070456	50-397	Electric Power Research Institute		
	7905040388	50-508	Franklin Institute Research Laboratory		
	7905240901	50-513	Hanford Engineering Development Laboratory		
	7905090073	50-397			
	7905110237	50-397			
	7905190069	50-460			
	7905250467				
	7905240319	50-305	Idaho National Engineering Laboratory	7905210187	
	7905010478	50-397		7905210166	
	7905090069	50-397		7905210184	
	7905190067	50-460		7905020022	
	7905190076	50-397		7905140578	
	7905190117	50-397		7905140574	
	7905040379	50-508	Kinetic Research, Inc.	7905080053	
	7905010486	50-397	Lawrence Livermore Laboratory	7905140177	
	7905090284	50-508	Lovelace Biomed & Environmental Research Institute	7905020464	
	7905160337	50-508	Navy, Dept. of, Naval Research Laboratory	7905100213	
	7905230534	50-460			
	7905070453	50-397		7905240925	
	7905070499	50-397		7905110033	
	7905040601	50-397		7905300438	50-320
	7905110232	50-397		7905240556	
	7905250537	50-397		7905250160	
	7905040294			7905020004	
WPSC - Wisconsin Public Service Corp.	7905100292	50-305		7905030142	
	7905150335	50-305		7905140572	
	7905100291	50-305		7905300078	
				7905240540	
				7905240576	
				7905240587	
				7905290498	

CORPORATE SOURCE INDEX

374

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
Sandia Laboratories	7905240346			7905140032	50-320
	7905230788			7905240553	
	7905140149			7905240404	
	7905110269	50-320		7905110267	50-320
	7905300061	50-320			

FEDERAL REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
Commission	7905300282			7905220443	50-320
	7905090131	50-320		7905110209	50-320
	7905140123	50-320		7905160056	50-320
	7905150009			7905230220	50-320
	7905150010			7905110224	
	7905090111			7905110190	50-320
	7905110213	50-320		7905160114	50-320
	7905020024	50-320		7905160119	50-320
	7905110197	50-320		7905160132	50-320
	7905210044	50-320		7905160088	50-320
	7905110233	50-320		7905160147	50-320
	7905020046	50-320		7905220443	50-320
	7905080070			7905300054	50-320
	7905100020	50-320		7905100016	50-320
	7905060123	50-320		7905160038	50-320
	7905030053	50-320		7905160097	50-320
	7905090004			7905160194	50-320
	7905150003			7905160107	50-320
	7905160008	50-320		7905160113	50-320
	7905220079			7905300211	50-320
	7905290008			7905160072	50-320
	7905190233	50-320		7905160154	50-320
	7905290003	50-219		7905160177	50-320
	7905290031	50-309		7905110208	
	7905160042	50-320		7905110238	50-320
	7905160059	50-320		7905160031	50-320
	7905190127	50-320		7905160056	50-320
	7905300300	50-320		7905160077	50-320
	7905300377			7905160081	50-320
	7905140020	50-320		7905190139	50-320
	7905300363			7905160149	50-320
	7905300313			7905160184	50-320
	7905150139			7905160073	50-320
	7905300464			7905160259	50-320
	7905250167			7905110245	50-320
	7905150005			7905110417	50-320
	7905300325			7905160076	50-320
	7905140238	50-320		7905160110	50-320
	7905090239	50-320		7905160121	50-320
	7905110220	50-320		7905160134	50-320
	7905300119	50-320		7905160140	50-320
	7905300643	50-245		7905090253	50-320
	7905300101	50-320		7905110246	50-320
	7905100028			7905210189	50-320
	7905300103	50-320		7905110249	50-320
	7905300128	50-320		7905160101	50-320
	7905300076	50-320		7905110179	
	7905300123	50-320		7905110215	50-320
	7905300348	50-309		7905300345	50-320
	7905300139	50-320		7905300604	
	7905300094	50-320		7905090236	50-320
	7905300120	50-320		7905160003	50-320
	7905300126	50-320		7905160007	50-320
	7905300113	50-320		7905160049	50-320
	7905250193	50-594		7905160087	50-320
	7905300134	50-320		7905110235	50-32
	7905300137	50-320		7905110253	50-320
	7905140175	50-320		7905230494	
	7905300144	50-320		7905300096	50-320
	7905300124	50-320		7905110182	
	7905300107	50-320		7905110198	50-320
	7905300135	50-320		7905230494	
	7905100322	50-502		7905110212	50-320
	7905300131	50-320		7905160137	50-320
	7905300596			7905160223	50-320
	7905300672			7905160035	50-320
	7905090413			7905100012	50-320
	7905300652			7905100159	50-320
	7905020038			7905100212	50-320
	7905250321			7905100218	50-320
	7905090413			7905100043	50-320
	7905020038			7905100049	50-251
	7905090413			7905100051	50-320
	7905020038			7905100061	50-320
	7905290465			7905100091	50-320
	7905020038			7905100136	50-320
	7905300495			7905100176	50-320
	7905090413			7905100198	50-320
	7905300460			7905100181	50-320
	7905160084	50-320		7905100206	50-320
	7905170270	50-320		7905240609	50-219
	7905110243	50-320		7905160021	50-320
	7905110230	50-320			
	7905140171	50-320			
	7905300681	50-309			
	7905020038				
	7905090413				
	7905020038				
	7905020038				
	7905020038				
	7905230792	50-309			
	7905110198	50-320			
	7905160142	50-320			
	7905160079	50-320			
	7905160144	50-320			
	7905160175	50-320			
	7905160123	50-320			
	7905110198	50-320			
	7905110202	50-320			
	7905110209	50-320			
	7905160056	50-320			
	7905160119	50-320			
	7905160147	50-320			

0111

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905250326			7905150066	
	7905090225	50-320		7905090276	
	7905090230	50-320		7905090266	
	7905090221	50-320		7905090267	
	7905230470			7905110379	
	7905090236	50-320		7905110379	
	7905140163	50-320		7905140237	
	7905140166	50-320		7905090270	
	7905140188	50-320		7905090023	
	7905090218	50-320		7905090028	
	7905090223	50-320		7905040170	50-10
	7905090250	50-320		7905110274	50-320
	79053000319	50-320		7905030161	
	7905220434	50-320		7905140019	
	7905220436	50-320		7905160250	
	7905160103	50-320		7905030210	50-320
	7905160086	50-320		7905100052	50-320
Office of Inspector & Auditor	7905150130	50-335		7905290262	
	7905220084	50-358		7905190235	50-320
Office of Public Affairs	7905020163	50-320		7905240205	
	7905230242	50-320		7905140014	50-320
Office of Policy Evaluations	7905230470			7905230476	50-320
	7905090257	50-320		7905230480	50-320
	7905090233	50-320			
	7905090239	50-320		7905230471	50-320
	7905090258	50-320		7905230445	50-320
	7905090234	50-320		7905300632	
	7905090212	50-320		7905020162	
	7905160092	50-320		7905230765	
	7905300342			7905090161	
	7905300350			7905230787	
	7905220416	50-320		7905100090	
	7905160102	50-320		7905250086	
Office of the Secretary of the Commission	7905100047	50-320		7905230572	
	7905090192			7905240090	
	7905090194			7905140022	50-320
	7905140033	50-344		7905160071	50-320
	7905230678	50-485		7905140031	50-320
	7905230646	50-280		7905140034	50-320
	7905230661	50-344		7905140048	50-320
	7905230573	50-305		7905140021	50-320
	7905240918	50-424		7905140037	50-320
	7905150260	50-399		7905140011	50-320
	7905240310	50-338		7905230188	
	7905250479	50-320		7905140026	50-320
	7905250205	50-389		7905140012	50-320
	7905300481			7905140013	50-320
	7905100408	50-320		7905140015	50-320
	7905300613			7905140154	50-320
	7905230701			7905140023	50-320
	7905230484			7905300725	
	7905230499			7905300378	50-320
	7905100026	50-320		7904160268	
	7905090283	50-313		7905280189	
	7905300268	50-320		79050400201	50-10
	7905250063			7905040057	50-320
	7905100056			7905040021	50-10
	7905240315			7905140053	50-320
	7905240820			7905140165	
	7905240358			7905140169	
	7905240366			7905140174	
	7905250331				
	7905090215	50-320			
	7905250165	50-400			
	7905140054	50-320			
	7905240435				
	7905250334				
	7905250539				
Atomic Energy Commission (Pre 1975)	7904300342		ATOMIC SAFETY BOARD(S) & PANEL(S)	7905090249	50-320
	7905140203		Atomic Safety and Licensing Appeal Panel	7905220070	50-278
	7905150669	70-1821		7905100067	50-344
	7905230204			7905240135	50-338
	7905230386	40-2407		7905240487	50-338
	7905230374	40-2407		7905250318	50-498
	7905230201	40-2407		7905150710	
	7905230348	40-2407		7905140332	50-320
	7905230342	40-2407		7905150233	50-329
	7905230183	40-2407		7905150542	50-320
	7905230164	40-2407		7905240585	50-277
	7905230291	40-2407		7905250035	50-389
	7905230280	40-2407	Atomic Safety and Licensing Board Panel	7905080163	
	7905230270	40-2407		7905020232	50-445
	7905230253	40-2407		7905090178	50-592
	7905230250	40-2407		7905300032	50-456
	7905230150	40-2407		7905020480	50-445
	7905230177	40-2407		7905090187	50-434
	7905230670	40-2407		7905240105	50-389
	7905230219	40-2407		7905230649	50-272
	7905230139	40-2407		7905310409	50-466
	7905230132	40-2407		7905100381	50-255
	7905020101			7905240479	50-250
	7905140200			7905290114	50-275
	7905140187			7905290131	
Directorate of	7905300325	50-320		7905100327	50-471
	7905300283			7905240212	50-510
				7905300690	50-358
	7905220292	50-528		7905100412	50-445
				7905230853	50-445
n Reactor	7905090014			7905250208	50-383
				7905290108	50-329
	7905090018			7905290583	50-395
	7905140248			7905140030	50-522
				7905290576	50-369
				7905230182	50-466
				7905150716	

377

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905220048	70-2623		7905300161	
	7905230666	70-2623		7905300194	
	7905150663	50-445		7905300200	
	7905150681	50-27		7905300237	
	7905220053	50-445		7905300280	
	7905250379			7905300297	
	7905100186	50-369		7905300308	
	7905150780	50-445		7905300423	
	7905220071			7905300260	
	7905230677	50-445		7905230720	
	7905250347	50-596		7905240111	
	7905230655	50-338		7905240808	
	7905150796	50-389		7905290438	
	7905140016	50-522		7905300156	50-320
	7905150672	50-272	Administrative Contracts Branch	7905090399	
	7905140565	50-382		7905020182	
	7905240885	50-329		7905090396	
	7905230540	50-272		7905020177	
	7905140564	50-329		7905140170	
	7905150243	50-295	Contract Policy Branch	7905140179	
	7905230560	50-556	Purchasing Section	7905290114	
	7905230570	50-556	Research Contracts Branch	7905040034	
	7905290036	50-358		7905030184	
	7905140567	50-250		7905150101	
	7905140568	50-272		7905150109	
	7905150284	50-358		7905030234	
	7905140561	50-272		7905040069	
	7905240579	27-39		7905040090	
	7905140558	50-272		7905140099	
	7905240571	50-338		7905030203	
	7905230563	50-510		7905040052	
	7905240330	50-255		7905240125	
	7905250070	50-510		7905030226	
	7905250541	50-382		7905230690	
	7905290489	50-250		7905030180	
	7905250362	50-400		7905030196	
	7905240762	50-514		7905040024	
	7905290268			7905040042	
	7905160045	50-320		7905040064	
	7905150491	50-556		7905040079	
	7905250330	50-275		7905240118	
	7905020105	50-488		7905240409	
	7905290102	50-272		7905240420	
	7905160043	50-320		7905240439	
	7905150677	50-437		7905240447	
	7905080184			7905230697	
				7905230702	
				7905240663	
				7905240669	
				7905230682	
OFFICE OF EXECUTIVE DIRECTOR FOR OPERATIONS (EDO)				7905280299	
Office of the Executive Director for Operations	7905150332		Technical Assistance Contracts Branch	7905020469	
	7905240155			7905020477	
	7905240153			7905140059	
	7905100278			7905300186	
	7905010041	70-1821		7905110412	
	7905150679			7905110415	
	7905010556			7905300178	
	7905080190			7905230638	
	7905230533			7905240107	
	7905240202			7905240787	
	7905020157	27-39		7905290231	
	7905250089	50-482		7905300152	
	7905290483	50-250		7905300228	
				7905300249	
	7905240265	50-275		7905300290	
	7905240334	50-454		7905300303	
	7905090158			7905300414	
	7905020210	50-483		7905300247	
	7905140291	50-272		7905230717	
	7905240508	50-450		7905290431	
	7905190198	50-320		7905250309	
	7905110260	50-320	Technical Information & Document Control		
	7905090260	50-320	Division of Facilities & Operations		
	7905300105	50-320	Telecommunications Branch		
	7905300079	50-320	License Fee Management Branch		
	7905300105	50-320			
	7905140252				
	7905140055	50-320			
	7905220451	50-320			
	7905210094				
	7905300105	50-320			
	7905300085	50-320			
	7905300089	50-320			
	7905300302	50-320			
	7905140110	50-320			
	7905300100	50-320			
	7905300648				
	7905090243	50-320			
	7905160052	50-320			
EDO - OFFICE OF ADMINISTRATION					
Office of Administration	7905140573				
	7905150014				
	7905150660	70-1821			
	7905300118	50-320			
Division of Contracts	7905140105				
	7905250120				
	7905140069				
	7905230647				
	7905290242				

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
Division of Security	7905150528			7905300359	
	7905140102			7905300356	50-320
	7905310067	50-320		7905160093	50-320
	7905100045	50-320		7905300370	50-320
	7905010652			7905300369	50-320
	7905020039			7905300365	
	7905020084			7905300359	
	7905140537	50-320		7905300356	50-320
	7905300379	50-320		7905250207	
	7905010637	50-320		7905230835	
	7905090013			7905100230	
	7905230115	40-2407		7905100287	
	7905010660	50-320		7905300359	
	7905140525			7905300370	50-320
	7905080031			7905300369	50-320
	7905140155	50-115		7905300365	
	7905140160			7905300356	50-320
	7905230400			7905160093	50-320
	7905140180			7905300111	50-320
	7905140196	50-320		7905240021	
	7905220429	50-320		7905230634	
	7905160024	50-320		7905230716	
	7905160026	50-320		7905250323	
	7905160006	50-320		7905160001	50-320
	7905160005	50-320		7905090242	50-320
	7905220423	50-320		7905090245	50-320
	7905220419	50-320	Assistant Director for Export/Import & International Safeguards	7905230839	
	7905300347	50-320			
	7905160063	50-320		7905230846	
	7905160006	50-320		7905230828	
	7905160005	50-320		7905220060	
	7905160006	50-320		7905250039	
	7905160005	50-320		7905020136	
Personnel Security Branch	7905160099	50-320		7905020349	
	7905160166	50-320		7905020355	
	7905160190	50-320		7905020361	
	7905160173	50-320		7905020366	
	7905160159	50-320		7905020381	
	7905160161	50-320		7905030127	
	7905160179	50-320		7905150158	
	7905160171	50-320		7905150162	
				7905230629	70-2198
EDO - OFFICE OF INTERNATIONAL PROGRAMS				7905030068	
Office of International Programs				7905020385	
	7905240001			7905020409	
	7905240059			7905020318	
	7905250033			7905230337	
	7905240147			7905020499	
	7905240173			7905020806	
	7905220031			7905020310	
	7905230820			7905020522	
	7905230822			7905020454	
	7905240281			7905020483	
	7905100053			7905020486	
	7905100415			7905030082	
	7905230553			7905030087	
	7905250264	40-8695		7905040137	
	7905240371			7905290127	
	7905160055	50-320		7905290128	
	7905160066	50-320		7905290133	
	7905160153	50-320		7905150030	
	7905160012	50-320		7905150040	
	7905160011	50-320		7905100447	
	7905160010	50-320		7905150029	
	7905160009	50-320		7905150031	
	7905160004	50-320		7905150032	
	7905160093	50-320		7905150033	
	7905160153	50-320		7905150035	
	7905160012	50-320		7905150037	
	7905160011	50-320		7905150038	
	7905160010	50-320		7905150804	
	7905160055	50-320		7905150810	
	7905160009	50-320		7905150813	
	7905160066	50-320		7905150815	
	7905160004	50-320		7905150787	
	7905160150	50-320		7905250252	
	7905160156	50-320		7905250255	
	7905160196	50-320		7905250257	
	7905160165	50-320		7905250272	
	7905160211	50-320		7905250276	
	7905160204	50-320		7905250282	
	7905160178	50-320		7905250287	
	7905160214	50-320		7905250291	
	7905160181	50-320		7905250293	
	7905160188	50-320		7905250300	
	7905160195	50-320		7905150311	
	7905300407	50-320		7905230781	
	7905300420	50-320		7905040189	
	7905300424	50-320		7905240023	
	7905300410	50-320			
	7905300418	50-320		7905240860	
	7905160153	50-320		7905080165	
	7905160012	50-320		7905150705	
	7905160011	50-320		7905220448	
	7905160010	50-320		7905220449	
	7905160053	50-320		7905080174	
	7905160009	50-320		7905240050	
	7905160066	50-320		7905290101	
	7905160004	50-320		7905290186	
	7905300370	50-320		7905040171	
	7905300369	50-320		7905040177	
	7905300365			7905040186	

ORGANIZATIONAL SOURCE INDEX

379

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905230524			7905240995	50-295
	7905230345			7905100150	50-549
				7905080198	50-285
EEO - OFFICE OF EXECUTIVE LEGAL DIRECTOR				7905100137	50-338
Office of the Executive Legal Director	7905300403	50-320		7905070134	50-295
	7905010215	50-358		7905080401	50-482
	7905240412	50-358		7905140194	50-261
	7905130327			7905040131	50-482
	7905090213	50-320		7905230866	50-237
	7905160109			7905030048	50-133
	7905160017	50-320		7905070131	50-471
	7905160022	50-320		7905070134	50-549
	7905090255	50-320		7905240603	50-261
	7905160105			7905220038	50-272
	7905090150	50-491		7905240771	50-261
	7905230713			7905070129	50-471
Deputy Executive Legal Director	7905150321	50-482	Branch 3	7905100137	50-338
	7905150726	50-275		7905100150	50-549
Administrative Branch	7905220428	50-320		7905160227	50-320
Hearings Division	7905110418	50-320		7905230348	50-466
	7905110203	50-320		7905080392	50-466
	7905160163	50-320		7905240144	50-255
	7905010115	50-320		7905150127	50-592
	7905160050	50-320		7905080379	50-358
	7905160191	50-320		7905300056	50-488
	7905080170			7905300091	50-358
Branch 1	7905080249			7905230829	50-400
	7905250386	50-498		7905100248	27-39
	7905250271	50-445		7905100276	50-466
	7905100208	50-344		7905300072	50-466
	7905300081	50-498		7905300044	50-275
	7905100170	50-596		7905030100	70-2623
	7905300064	50-498		7905030116	70-2623
	7905250128	50-522		7905030120	70-2623
	7905300362	50-445		7905290028	50-485
	7905240255	50-338		7905100224	50-256
	7905290049	50-382		7905240296	50-466
	7905240224	50-344		7905240328	50-466
	7905290053	50-596		7905290353	50-443
	7905070147	50-344		7905220443	50-400
	7905250148	50-344		7905250099	50-488
	7905150114	50-463		7905230093	50-400
	7905150811	50-344		7905070216	50-400
	7905230246	50-463		7905070225	50-380
	7905250140	50-344		7905080377	50-880
	7905150811	50-344		7905240635	50-488
	7905150114	50-463		7905240703	50-400
	7905230246	50-463		7905030152	50-400
	7905070147	50-344		7905240299	27-39
	7905240909	50-548		7905150737	50-452
	7905100110	50-548		7905150740	50-466
	7905140280	50-524		7905100125	50-466
	7905250153	50-463		7905100146	50-466
	7905250143	50-445		7905150562	50-400
	7905241006	50-338		7905110046	50-255
	7905070147	50-344		7905240149	50-466
	7905150114	50-463		7905300140	50-255
	7905150811	50-344		7905080039	50-219
	7905230246	50-463		7905090419	50-219
	7905240909	50-548		7905100122	50-437
	7905100110	50-548		7905020334	50-358
	7905160280	50-524		7905220075	50-358
	7905160130	50-320		7905080341	50-358
	7905160226	50-320		7905240635	50-488
	7905250030	50-344		7905250099	50-488
Branch 2	7905310013	50-466		7905150748	50-592
	7905300711	50-295		7905300537	50-592
	79053030209	50-338		7905110046	50-255
	7905230841	50-549		7905240133	50-592
	7905150180	50-272		7905240136	50-358
	7905150187	50-272		7905080039	50-219
	7905150192	50-272		7905090419	50-219
	7905030020	50-272		7905240299	27-39
	7905070131	50-471		7905020448	50-546
	7905070184	50-295		7905020456	50-846
	7905290055	50-471		7905080359	50-491
	7905070129	50-471		7905090147	50-491
	7905300722	50-250		7905240243	50-443
	7905100121	50-295		7905240738	50-491
	7905110418	50-320		7905290195	50-491
	7905240284	50-502		7905150745	50-485
	7905150048	50-272		7905030168	27-39
	7905250347	50-295		7905020334	50-358
	7905250137	50-272		7905080039	50-219
	7905250039	50-286		7905220075	50-358
	7905070184	50-295		7905250093	50-400
	7905240038	50-272		7905020147	50-448
	7905280039	50-286		7905070216	50-400
	7905070134	50-549		7905070225	50-880
	7905030048	50-133		7905080341	50-358
	7905280288	50-237		7905090419	50-219
	7905100137	50-338		7905150143	50-310
	7905240771	50-261		7905150685	50-580
	7905240288	50-237		7905220443	50-400
	7905300367	50-549		7905240635	50-488
	7905070131	50-471		7905240703	50-400
	7905240603	50-261		7905030079	50-448
	7905240771	50-261		7905030152	50-400
	7905070129	50-471		7905240081	50-387
	7905250258	50-237		7905250099	50-488
				7905150125	50-335

ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905310028	50-329	Assistant Director for Emergency Preparedness	7905090214	50-320
	7905100157	50-275		7905250501	
	7905110418	50-320		7905250517	
	7905240278	50-516		7905250444	
	7905100226	50-556	Assistant Director for Program Development	7905300082	
	7905100215	50-556			
	7905100219	50-556			
	7905150240	50-329			
	7905240564	50-275			
	7905240154	50-389			
	7905150059	50-556	OFFICE OF INSPECTION & ENFORCEMENT		
	7905250053	50-322	Division of Reactor Construction Inspection	7905230857	50-482
	7905080053	50-322	Office of Inspection & Enforcement	7905240061	
	7905100370	50-275		7905240058	
	7905170162	50-3		7905240065	
	7905100402	50-389		7905240053	
	7905230259	50-556		7905240051	
	7905100130	50-389		7905100375	50-346
	7905170162	50-3		7905240047	
	7905150059	50-556		7905110006	50-312
	7905100370	50-275		7905240035	
Operations & Administrative Division	7905160032	50-320		7905240025	
	7905240493	50-329		7905240031	
Rulemaking & Enforcement Division	7905310028	50-329		7905190055	
	7905100406	50-320		7905240028	
Regulations Division	7905160208	50-320		7904170040	50-320
	7905030207	50-338		7905110200	50-286
	7905100269	50-348		7905150245	50-267
Anti-Trust Division	7905100157	50-275		7905010083	50-3
	7905240978	50-348		7905110186	50-320
	7905100269	50-348		7905110009	50-312
	7905100273	50-445		7905140067	50-320
	7905100386	50-445		7905040406	50-320
	7905230622	50-230		7905020230	50-320
	7905100138			7905020260	50-320
	7905100106	50-445		7905040296	50-320
	7905150216	50-395		7905040360	50-320
	7905230466	50-445		7905040262	50-320
	7905250129	50-445		7905040365	50-133
	7905150232	50-389		7905040358	50-528
	7905240967	50-445		7905140253	50-320
	7905250191	50-498		7905230198	50-320
	7905020316	50-592		7905300250	50-320
	7905240502	50-592		7905300151	50-320
	7905240967	50-445		7905150656	50-482
	7905250129	50-445		7905240998	50-482
	7905240863			7905210276	50-320
	7905230743	50-395		7905190057	50-320
	7905150737	50-452		7905190138	50-320
	7905150740	50-466		7905230016	50-320
	7905150748	50-592		7905210253	50-320
	7905300537	50-592		7905210117	50-320
	7905100125	50-466		7905190173	50-320
	7905240641	50-568		7905230171	50-320
	7905110046	50-255		7905220412	50-320
	7905100122	50-437		7905220450	50-320
	7905240133	50-592		7905230516	50-320
	7905160039	50-320		7905210299	50-320
	7905150748	50-592		7905190168	50-320
	7905300537	50-592		7905190170	50-320
	7905240133	50-592		7905110361	50-320
Branch 4	7905100372	27-39		7905110187	50-320
	7905070021	50-556		7905210110	50-320
	7905090182	50-556		7905210112	50-320
	7905090438	70-2623		7905210056	50-320
	7905090440	70-2623		7905300192	50-320
	7905230766	70-2623		7905110184	50-320
	7905230775	70-2623		7905300112	50-320
EDO - OFFICE OF MANAGEMENT & PROGRAM ANALYSIS				7905210314	50-320
Office of Management and Program Analysis	7905090220	50-320		7905110187	50-320
	7905090224	50-320		7905210056	50-320
	7905100253			7905110184	50-320
	7905090216	50-320		7905110187	50-320
	7905190199	50-320		7905210056	50-320
	7905140073	50-320		7905110184	50-320
EDO - OFFICE OF STATE PROGRAMS				7905110187	
				7905110184	
				7905110187	
				7905110184	
				7905190196	50-320
				7905230041	50-320
				7905210072	50-320
				7905210261	50-320
				7905190060	50-320
				7905210308	50-320
				7905110028	50-312
				7905110416	50-800
				7905210091	50-320
				7905110218	50-320
				7905110361	50-320
				7905210060	50-320
			Division of Fuel Facility & Materials Safety		
			Division of Reactor Operations Inspections	7905110421	50-329
	7905140325				
	7905250525				
	7905090248	50-320		7905110420	50-329
	7905090254	50-320		7905250231	
	7905300053	50-320		7905290162	50-255
	7905140325			7905110413	50-320
	7905090241	50-320		7905140047	50-320
	7905250516			7905110413	50-320
				7905140047	50-320

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

381

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
NRG Regional Offices Region 1, Philadelphia, Office of the Director	7905110413	50-320		7905030059	50-213
	7905140047	50-320		7905010641	50-213
	7905110413			7905010103	50-334
	7905140047				
	7905110413			7905010106	50-412
	7905140047			7905010042	50-334
	7905160216	50-320		7905010297	50-334
	7905160209	50-320		7905020039	50-334
	7905100445	50-346		7905020043	50-412
	7905150820	50-315		7905020346	50-334
	7905140210	50-317		7905020398	50-412
				7905040014	50-412
	7905230385	50-320		7905040018	50-334
	7905230732	50-277		7905040198	50-334
	7905230750	50-277		7905040200	50-412
	7905040156	50-387		7905010079	50-3
	7905040153	50-387		7905030060	50-334
	7905110113	50-6134		7905030063	50-412
	7905290196	50-3		7905010643	50-334
	7905070182	50-286		7905010645	50-412
	7905290193	50-3		7905220461	50-320
	7905070177	50-286		7905210052	50-320
	7905070158	50-272		7905010110	50-219
	7905110036	50-820		7905010112	50-363
	7905070149	50-272		7905010046	50-219
	7905100374	50-6533		7905010298	50-219
	7905090146	50-213		7905020045	50-219
	7905070210	50-247		7905020337	50-219
	7905090140	50-220		7905020393	50-363
	7905230288	50-33		7905040020	50-363
	7905080110	50-286		7905040025	50-219
	7905020140	50-289		7905040204	50-219
	7905100433	50-387		7905030064	50-219
	7905110217	50-219		7905030065	50-363
	7905110371	50-247		7905010646	50-219
	7905110394	50-271		7905010650	50-363
	7905240784	50-135		7905190066	50-219
	7905240437	50-289		7905010114	50-322
	7905240704	50-245		7905020051	50-322
	7905300752	50-311		7905020395	50-322
	7905240306	50-244		7905040038	50-322
	7905240673	50-322		7905040208	50-322
	7905240684	50-363		7905030070	50-322
	7905290166	50-336		7905020263	50-322
	7905290126	50-334		7905010118	50-289
	7905290132	50-277		7905010047	50-289
	7905290145	50-245		7905010300	50-289
	7905290173	50-244		7905210036	50-320
	7905290120	50-277		7905210039	50-320
	7905290137	50-309		7905020053	50-289
	7905290157	50-334		7905210040	50-320
	7905150514	50-277			
	7905150523	50-277		7905020377	50-289
	7905300090	50-320		7905040040	50-289
	7905150298	50-363		7905040210	50-289
	7904210770			7905030072	50-289
	7905100422	50-6949		7905020275	50-289
	7905290165	50-1873		7905210252	50-320
				7905210319	50-320
	7905290156	50-1873		7905230138	50-320
	7905150727	50-2428		7905230154	50-320
	7905010080	50-364		7905230163	50-320
	7905010082	50-201		7905210284	50-320
	7905010086	50-1143		7905010119	50-309
	7905210245	50-320		7905010050	50-309
	7905210046	50-333		7905010301	50-309
	7905220414	50-320		7905020055	50-309
	7905010100	50-293		7905020342	50-309
	7905030266	50-293		7905040046	50-309
	7905010034	50-293		7905040211	50-309
	7905010282	50-293		7905030075	50-309
	7905020026	50-293		7905020278	50-309
	7905020357	50-293		7905010121	50-245
	7905030326	50-293		7905010053	50-245
	7905040167	50-293		7905010304	50-336
	7905030032	50-293		7905020061	50-336
	7905010632	50-293		7905020066	50-245
	7905140208	50-317		7905020300	50-245
	7905010101	50-317		7905040049	50-336
	7905030270	50-317		7905040059	50-245
	7905010036	50-317		7905040214	50-336
	7905010286	50-317		7905040224	50-245
	7905020030	50-317		7905030077	50-245
	7905020389	50-317		7905020284	50-245
	7905030328	50-317		7905010125	50-410
	7905040174	50-317		7905010126	50-220
	7905030056	50-317		7905010055	50-220
	7905010633	50-317		7905010307	50-220
	7905030372	50-3		7905020069	50-220
	7905020350	50-3		7905020071	50-410
	7905030373	50-3		7905020329	50-410
	7905040183	50-3		7905020332	50-220
	7905010635	50-3		7905040068	50-410
	7905010639	50-247		7905040071	50-220
	7905030392	50-3		7905040235	50-410
	7905010103	50-213		7905040237	50-220
	7905030276	50-213		7905030078	50-220
	7905010040	50-213		7905030081	50-410
	7905010290	50-213		7905020288	50-220
	7905020336	50-213			
	7905020354	50-213		7905020292	50-410
	7905040010	50-213		7905010127	50-333
	7905040188	50-213		7905010129	50-286

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905030279	50-286		7905210097	50-320
	7905010058	50-286		7905210102	50-320
	7905010060	50-333		7905210108	50-320
	7905010310	50-333		7905190177	50-320
	7905010313	50-286		7905210144	50-320
	7905020072	50-333		7905210124	50-320
	7905020073	50-286		7905300063	50-320
	7905020295	50-286		7905300038	50-320
	7905020321	50-333		7905190061	50-320
	7905040074	50-333		7905300108	50-320
	7905040078	50-286		7905210305	50-320
	7905040245	50-286		7905300122	50-320
	7905040249	50-333		7905210042	50-320
	7905030083	50-333		7905210034	50-320
	7905030084	50-286		7905210140	50-320
	7905020296	50-333		7905220439	50-320
	7905020298	50-286		7905300187	50-320
	7905010131	50-277		7905230144	50-320
	7905010134	50-352		7905230194	50-320
	7905010065	50-277		7905210247	50-320
	7905010315	50-277		7905210246	50-320
	7905020077	50-352		7905210095	50-320
	7905020082	50-277		7905190194	50-320
	7905290116	50-277		7905210279	50-320
	7905020323	50-277		7905210293	50-320
	7905020372	50-352		7905210133	50-320
	7905040083	50-352		7905150287	50-363
	7905040087	50-277		7905040156	50-387
	7905040259	50-277	Region 1, Philadelphia, Reactor Construction & Engineering Support Branch		
	7905040264	50-352		7905100433	50-387
	7905030086	50-352		7905240673	50-322
	7905030088	50-277		7905240684	50-363
	7905020305	50-352		7905290132	50-277
	7905020309	50-277		7905240679	50-363
	7905010136	50-387		7905240668	50-322
	7905020085	50-387		7905020135	50-289
	7905020402	50-387		7905290134	50-309
	7905040091	50-387			
	7905040269	50-387		7905290129	50-277
	7905030093	50-387		7905040149	50-387
	7905020314	50-387		7905100428	50-387
	7905010138	50-272		7905040140	50-387
	7905010140	50-311		7905030129	50-387
	7905010069	50-272	Region 1, Philadelphia, Fuel Facility & Materials Safety Branch	7905230750	50-277
	7905010320	50-272		7905110113	50-6134
	7905020095	50-272		7905110105	50-6134
	7905020100	50-311		7905290196	50-3
	7905020369	50-311		7905090140	50-220
	7905040093	50-311		7905110102	50-6134
	7905040095	50-272		7905110072	50-6134
	7905040273	50-272		7905290188	50-3
	7905040282	50-311		7905290177	50-3
	7905140103	50-272		7905090134	50-220
	7905030098	50-272		7905230724	50-277
	7905030101	50-311		7905230694	50-277
	7905020317	50-272		7905240294	50-244
	7905020322	50-311	Region 1, Philadelphia, Reactor Operations Nuclear Support Branch	7905070182	50-286
	7905010143	50-443			
	7905020103	50-443		7905070158	50-272
	7905020364	50-443		7905090146	50-213
	7905040100	50-443		7905070210	50-247
	7905040284	50-443		7905080110	50-286
	7905030105	50-443		7905110217	50-219
	7905020324	50-443		7905110371	50-247
	7905010145	50-485		7905110394	50-271
	7905010148	50-244		7905240704	50-245
	7905010073	50-244		7905300752	50-311
	7905010322	50-244		7905290166	50-336
	7905290169	50-244		7905290126	50-334
	7905020106	50-244		7905290145	50-245
	7905020111	50-485		7905290173	50-244
	7905020315	50-244		7905290120	50-277
	7905020360	50-485		7905290157	50-334
	7905040104	50-485		7905150823	50-277
	7905040109	50-244		7905070189	50-247
	7905040295	50-485		7905110362	50-247
	7905030108	50-244		7905090142	50-213
	7905030110	50-485		7905290123	50-334
	7905020331	50-485		7905290154	50-334
	7905020335	50-244		7905110216	50-219
	7905010150	50-271		7905240430	50-289
				7905240492	50-245
				7905290140	50-245
				7905290160	50-336
				7905070172	50-286
				7905080099	50-286
				7905070161	50-286
				7905150907	50-277
				7905070145	50-272
				7905300743	50-311
				7905070133	50-272
				7905110388	50-271
				7905190175	50-320
				7905220092	70-133
			Region 1, Philadelphia, Safeguards Branch		
				7905110036	70-820
				7905230288	70-33
				7905240784	70-133
				7905240287	50-225
				7905240277	50-225
				7905240775	70-133

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

383

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
Region 2, Atlanta, Office of the Director	7905240756	70-135		7905030290	50-348
	7905220087	70-135		7905010093	50-348
	7905220072	70-135		7905010337	50-348
	7905230277	70-33		7905020124	50-348
	7905110029	70-820		7905040148	50-348
	7905250410	50-302		7905040296	50-348
				7905040322	50-348
	7905230503			7905030137	50-348
	7905020087	50-269		7905010331	50-348
	7905020439	70-143		7905020365	50-348
	7905020442	50-327		7905020370	50-348
	7905290170	50-335		7905010168	50-261
	7905290174	50-335		7905030294	50-261
	7905010421	50-302		7905010095	50-261
	7905010471	50-302		7905010346	50-325
	7905020102	50-391		7905240661	50-324
	7905020117	50-391		7905020125	50-261
	7905240069	50-335		7905040163	50-261
	7905020049	50-280		7905040281	50-261
	7905040124	70-27		7905040329	50-261
	7905230237	50-324		7905150696	50-324
	7905230243	50-324		7905010324	50-400
	7905020019	50-280		7905030141	50-261
	7905020471	50-339			
	7905020161	70-1151		7905010324	50-403
	7905020423	50-369		7905020373	50-324
	7905070084	50-327		7905020426	50-261
	7905090132	50-338		7905010177	50-269
	7905090135	50-338		7905010183	50-413
	7905230747	50-366		7905030301	50-413
				7905030307	50-269
	7905230753	50-546		7905010098	50-269
	7905240207	50-327		7905010350	50-269
	7905230592	50-261		7905040174	50-269
	7905230641	50-302		7905040183	50-413
	7905290138	50-335		7905040263	50-269
	7905090056	50-339		7905040266	50-413
	7905130107	50-239		7905040346	50-413
	7905230169	50-339		7905040381	50-269
	7905230679	50-338		7905010333	50-369
	7905230689	70-143		7905010356	50-413
	7905290392	50-281		7905030153	50-413
	7905290398	50-281		7905030160	50-269
	7905230153	50-389		7905010356	50-489
	7905230674	50-338		7905020429	50-269
	7905290717	50-369		7905020453	50-413
	7905230110	50-321		7905020460	50-369
	7905090426	50-395		7905010418	50-302
	7905130081	50-318		7905010192	50-302
	7905130147	50-239		7905020404	50-302
	7905020497	50-321		7905010102	50-302
	7905230614	50-261		7905010353	50-302
	7905230623	50-261		7905310017	50-302
	7905230402	50-302		7905010403	50-302
	7905240336	70-1151		7905040209	50-302
	7905241003	50-25		7905040306	50-302
	7905241003			7905040395	50-302
	7905290094	70-1113		7905030162	50-302
	7905290099	70-1113		7905020463	50-302
	7905240312	70-1151		7905010193	50-250
	7905240468	50-395		7905030310	50-250
	7905241003	50-25		7905010104	50-250
	7905240480	50-124		7905010358	50-250
	7905250431	50-508		7905020127	50-250
	7905240491	50-327		7905040141	50-335
	7905240527	50-348		7905040212	50-250
	7905240518	50-348		7905040308	50-250
	7905240534	50-339		7905040404	50-250
	7905290117	50-395		7905030164	50-250
	7905240665	50-324		7905010337	50-389
	7905070101	70-1113		7905020465	50-335
	7905240507	50-518			
	7905240537	50-491		7905290150	50-335
	7905130116	70-1201		7905010200	50-321
	7905310024	50-302		7905030312	50-321
	7905240509	50-424		7905010107	50-321
	7905020033	50-280		7905010360	50-321
	7905070283	70-1151		7905040216	50-321
				7905040304	50-321
	7905240361	70-143		7905040413	50-424
	7905230020	50-400		7905010366	50-424
	7905300021	70-1201		7905030165	50-321
	7905300026	50-338		7905020467	50-321
	7905010138	50-437		7905010204	50-416
	7905030323	50-437		7905030314	50-416
	7905030188	50-437		7905040223	50-416
	7905040143	50-437		7905040312	50-416
	7905040457	50-437		7905040420	50-416
	7905030133	50-437		7905010371	50-416
	7905070137	50-160		7905030167	50-416
	7905070153	50-538		7905020472	50-416
	7905070146	50-111		7905010205	50-395
	7905070152	50-406		7905030317	50-395
	7905070142	50-83		7905290112	50-395
	7905070148	50-62		7905030199	50-395
	7905070138	50-124		7905040225	50-395
	7905070156	50-129		7905040424	50-395
	7905010132	50-332		7905010374	50-395
	7905070159	50-13		7905030169	50-395
	7905010137	70-143		7905020473	50-395
	7905240352	70-143		7905020475	50-395
	7905140095	50-437		7905150103	50-259
	7905010141	50-348		7905010211	50-259

ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905010113	50-259		7905020049	50-280
	7905010363	50-259		7905230243	50-324
	7905240498	50-518		7905020019	50-280
	7905030368	50-259		7905020471	50-339
	7905040223	50-259		7905020423	50-369
	7905110365	50-327		7905070135	50-338
	7905150700	50-259		7905010264	50-338
	7905010341	50-327		7905010275	50-338
	7905030172	50-259			
	7905010341	50-391		7905230592	50-261
	7905020479	50-259		7905010467	50-395
	7905020495	50-327		7905090056	50-339
	7905010224	50-280		7905150107	50-259
	7905030319	50-280		7905250110	50-321
	7905010123	50-280		7905150147	50-259
	7905010369	50-280		7905150259	50-250
				7905020497	50-321
	7905020133	50-339		7905240480	50-124
	7905080534	50-280		7905240491	50-327
	7905040254	50-280		7905240527	50-348
	7905040271	50-280		7905240534	50-339
	7905040448	50-280		7905240474	50-124
	7905010317	50-339		7905240523	50-348
	7905030191	50-338		7905230229	50-324
	7905020496	50-280		7905010465	50-324
	7905020502	50-339		7905230583	50-261
	7905230202	50-320		7905230209	50-324
	7905020339	50-369		7905230482	50-269
Region 2, Atlanta, Reactor Constructi on & Engineering Support Branch				7905020412	50-369
	7905020352	50-369		7905290707	50-369
	7905020442	50-327		7905250173	50-369
	7905020117	50-391		7905250396	50-302
	7905070358	50-389		7905250381	50-302
	7905070118	50-281		7905290167	50-335
	7905230753	50-566		7905150251	50-250
	7905240307	50-327		7905250105	50-321
	7905010243	50-389		7905020489	50-321
	7905230169	50-339		7905010466	50-395
	7905230689	70-143		7905150138	50-259
	7905290398	50-281		7905240483	50-327
	7905230153	50-389		7905020040	50-280
	7905090426	50-395		7905020012	50-280
	7905150081	50-518		7905010255	50-338
	7905230752	50-491		7905090051	50-339
	7905240468	50-395		7905020458	50-339
	7905250431	50-508		7905090129	50-338
	7905240518	50-348		7905240530	50-339
	7905240507	50-518		7905210047	50-320
	7905240537	50-491	Region 2, Atlanta, Safeguards Branch	7905020087	50-269
	7905240509	50-424		7905020439	70-143
	7905250020	50-400		7905240069	50-335
	7905240514	50-348		7905040124	70-27
	7905080323	50-400		7905070259	70-1201
	7905250017	50-400		7905150116	70-1201
	7905020356	50-349		7905020033	50-280
	7905230726	50-491		7905070283	70-1151
	7905240523	50-491		7905300021	70-1201
	7905020285	50-369		7905300026	50-338
	7905140162	50-413		7905040118	70-27
	7905070352	50-389		7905070252	70-1201
	7905010235	50-389		7905040105	70-27
	7905230137	50-389		7905150112	70-1201
	7905240500	50-424		7905070240	70-1201
	7905090424	50-395		7905300016	70-1201
				7905020433	70-143
	7905240464	50-395		7905230684	70-143
	7905020435	50-327		7905020417	70-143
		50-391		7905020156	70-1151
		50-566		7905240323	70-1151
		50-327		7905240295	70-1151
		50-390		7905020146	70-1151
		50-518		7905070269	70-1151
				7905020078	50-269
				7905020048	50-269
				7905230632	50-302
				7905230628	50-302
				7905240084	50-335
				7905020025	50-280
				7905300023	50-338
				7905110108	50-346
				7905110111	50-346
				7905100362	50-346
				7905110093	50-346
				7905110094	50-346
				7905020205	50-315
				7905020208	50-315
				7905080093	50-255
				7905030046	50-155
				7905090390	50-546
				7905090393	50-546
				7905030061	50-373
				7905030074	50-373
				7905010336	50-155
				7905070023	50-373
				7905070027	50-373
				7905090169	50-331
				7905090175	50-409
				7905010151	50-266
				7905010160	50-266
				7905020172	50-329
				7905020470	50-500
				7905040349	50-461

Region 3, Chicago, Office of the
Director

U.S. NUCLEAR SAFETY COMMISSION ORGANIZATIONAL SOURCE INDEX

385

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905150646	70-1379		7905010387	50-329
	7905090131	50-282		7905030219	50-329
	7905230308	50-341		7905030520	50-155
	7905110047	50-182		7905080404	50-329
	7905150805	50-590		7905080486	50-155
	7905230426	50-331		7905150355	50-155
	7905230442	70-1308		7905240893	50-155
	7905150419	50-341		7905010251	50-409
	7905080211	50-331		7905090155	50-409
	7905150129	50-331		7905040027	50-409
	7905150134	50-331		7905010165	50-409
	7905150143	50-156		7905010394	50-409
	7905150436	50-331		7905030026	50-409
	7905150413			7905010585	50-409
	7905150429	50-337		7905040384	50-409
	7905150819	50-315		7905040440	50-409
	7905150820	50-315		7905040553	50-409
	7905250296	50-329		7905030222	50-409
	7905140087	50-295		7905080490	50-409
	7905150535	50-338		7905240896	50-409
	7905240734	50-329		7905010253	50-341
	7905240748	50-456		7905040030	50-341
	7905240494	50-10		7905030029	50-341
	7905290569	50-155		7905010986	50-341
	7905290720	50-358		7905040387	50-341
	7905290546	50-263		7905040460	50-341
	7905240716	50-373		7905040556	50-341
	7905150775	50-295		7905010415	50-341
	7905040158	50-10		7905030224	50-341
	7905150754	70-1308		7905080492	50-341
	7905140492	50-10		7905240898	50-341
	7905100162	50-16		7905010256	50-331
	7905040368	50-358		7905040031	50-331
	7905010197	70-1193		7905150424	50-331
	7905020521	50-346		7905010167	50-331
	7905240977			7905010398	50-331
	7905140213			7905030031	50-331
	7905030006	50-315		7905010588	50-331
	7905040456	50-315		7905040389	50-331
	7905040522	50-315		7905040435	50-331
	7905030204	50-315		7905040560	50-331
	7905310466	50-315		7905030227	50-331
	7905010236	50-10			
	7905030370	50-10		7905080496	50-331
	7905010155	50-10		7905240902	50-331
	7905010384	50-10		7905010287	50-461
	7905030007	50-295		7905040035	50-461
	7905030013	50-10		7905030033	50-461
				7905010590	50-461
	7905010569	50-10		7905040394	50-461
	7905010572	50-295		7905040459	50-461
	7905040534	50-10		7905040566	50-461
	7905040527	50-295		7905010425	50-461
	7905040529	50-10		7905030228	50-461
	7905010380	50-373		7905080498	50-461
	7905030206	50-10		7905240906	50-461
	7905010380	50-455		7905010223	50-315
	7905040142	50-10		7905040037	50-315
	7905140488	50-10		7905010171	50-315
	7905010242	50-358		7905010404	50-315
	7905030372	50-358		7905010592	50-315
	7905030017	50-358		7905170089	50-315
	7905010574	50-358		7905030204	50-315
	7905040351	50-358		7905080499	50-315
	7905040452	50-358		7905010429	50-367
	7905040534	50-358		7905010258	50-367
	7905010400	50-358		7905040041	50-367
	7905030215	50-358		7905030036	50-367
	7905080397	50-358		7905010593	50-367
	7905240887	50-358		7905040398	50-367
	7905010246	50-440		7905040568	50-367
	7905040021	50-440		7905070164	50-367
	7905030019	50-440		7905030232	50-367
	7905010576	50-440		7905080502	50-367
	7905040382	50-440		7905240907	50-367
	7905040537	50-440		7905010261	50-484
	7905070170	50-440		7905010262	50-263
	7905010396	50-440		7905040045	50-484
	7905030217	50-440		7905040049	50-263
	7905080400	50-440		7905010174	50-263
	7905240892	50-440		7905010410	50-263
	7905020166	50-329		7905290536	50-263
	7905010247	50-155		7905030040	50-282
	7905010249	50-329		7905030047	50-484
	7905040026	50-155		7905010597	50-484
	7905080529	50-329		7905010599	50-263
	7905010162	50-155		7905010600	50-282
	7905010390	50-155		7905040403	50-263
	7905030022	50-329		7905040418	50-484
	7905030023	50-255		7905040445	50-484
	7905030025	50-155			
	7905010579	50-155		7905040451	50-263
	7905010583	50-329		7905040576	50-263
	7905040324	50-255		7905040587	50-484
	7905040328	50-155		7905010419	50-484
	7905040331	50-329		7905030235	50-484
				7905030237	50-263
	7905040465	50-329		7905080503	50-484
	7905040546	50-329		7905080505	50-263
	7905040548	50-255		7905010625	50-546
	7905040550	50-155		7905040051	50-546
	7905070162	50-155		7905030049	50-546
				7905010602	50-546

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905040425	50-346	Region 3, Chicago, Reactor Operations Nuclear Support Branch	7905100357	50-346
	7905040589	50-346		7905110094	50-346
	7905070167	50-346		7905080086	50-233
	7905010411	50-346		7905070027	50-373
	7905030241	50-346		7905240729	50-338
	7905080507	50-346		7905090169	50-331
	7905010267	50-346		7905090175	50-409
	7905040035	50-346		7905150134	50-331
	7905010176	50-346		7905150163	50-156
	7905010413	50-346		7905040161	50-294
	7905240733	50-346		7905150159	50-156
	7905030053	50-346		7905020202	50-315
	7905010604	50-346		7905150152	50-315
	7905040427	50-346		7905070030	50-373
	7905040591	50-346		7905140084	50-295
	7905070174	50-346		7905240719	50-358
	7905030245	50-346		7905080084	50-253
	7905080509	50-346		7905010333	50-155
	7905010268	50-483		7905090167	50-233
	7905040038	50-483		7905090173	50-409
	7905030058	50-483		7905090165	50-331
	7905010610	50-483		7905150126	50-331
	7905040428	50-483		7905250266	50-331
	7905040461	50-483		7905110100	50-346
	7905040395	50-483		7905100354	50-346
	7905010405	50-483		7905110097	50-346
	7905030247	50-483		7905110092	50-346
	7905080512	50-483			
	7905010270	50-266		7905110089	50-346
	7905040060	50-266		7905150113	50-346
	7905010181	50-266	Region 3, Chicago, Safeguards Branch	7905110047	50-182
	7905010417	50-266		7905150775	50-295
	7905030062	50-266		7905150734	70-1308
	7905010613	50-266		7905160488	50-116
	7905040431	50-266		7905110041	50-182
				7905150744	70-1308
	7905040438	50-266		7905150297	70-1308
	7905040598	50-266		7905150768	50-295
	7905030233	50-266		7905250206	50-10
	7905080515	50-266	Region 4, Dallas, Office of the Director	7905010391	50-313
	7905010273	50-305		7905010395	50-313
	7905040065	50-305		7905310001	40-7086
	7905010186	50-305		7905070207	50-445
	7905030069	50-305		7905010306	50-482
	7905010615	50-305		7905010308	50-482
	7905040434	50-305		7905010312	50-482
	7905040443	50-305		7905010370	50-445
	7905040600	50-305		7905010379	50-498
	7905030235	50-305		7905010383	50-498
	7905080519	50-305		7905150561	50-445
	7905010191	70-8		7905150570	50-556
	7905290183	70-1379		7905150544	50-382
	7905140534	50-266		7905150530	50-382
	7905210057	50-320		7905150604	50-188
	7905190096	50-320		7905230268	50-285
Region 3, Chicago, Reactor Constructi on & Engineering Support Branch	7905020172	50-329		7905020128	50-320
	7905040349	50-461		7905150584	50-112
	7905150805	50-390		7905230681	
	7905150419	50-341		7905150581	
	7905150436	50-331		7905150079	50-313
	7905230296	50-329		7905010448	50-313
	7905150535	50-358		7905020441	50-313
	7905030054	50-373		7905020277	50-313
	7905240740	50-456		7905020419	50-313
	7905240711	50-373		7905020436	50-313
	7905150929	50-358		7905140132	50-313
	7905070009	50-358		7905150045	50-313
	7905290699	50-358		7905140088	50-368
	7905140107	50-358		7905040488	50-313
	7905290330	50-329		7905040606	50-313
	7905250283	50-329		7905070043	50-313
	7905240549	50-329		7905010529	50-313
	7905240724	50-329		7905090096	50-313
	7905290554	50-155		7905030265	50-313
	7905230302	50-341			
	7905150410	50-341		7905010538	50-313
	7905080024	50-341		7905010554	50-313
	7905080204	50-331		7905080346	50-313
	7905040347	50-461		7905080348	50-368
	7905290048	50-461		7905010367	50-313
	7905090386	50-346		7905010283	50-328
	7905140091	50-346		7905010277	50-458
				7905010435	50-458
Region 3, Chicago, Fuel Facility & Materials Safety Branch	7905020461	50-500		7905030131	50-458
	7905030046	50-155		7905040489	50-458
	7905010160	50-266		7905040610	50-458
	7905150640	70-1379		7905070050	50-458
	7905230420	50-331		7905010443	50-458
	7905230426	50-331		7905090098	50-458
	7905290635	40-3392		7905030267	50-458
	7905230437	70-1308		7905010279	50-498
	7905150817	50-315		7905010457	50-498
	7905240448	50-10		7905030138	50-498
	7905030041	50-155		7905040492	50-498
	7905230412	50-331		7905040613	50-498
	7905110159	50-331		7905070055	50-498
	7905090126	50-282		7905010441	50-498
	7905140100	50-282		7905090099	50-498
	7905010142	50-266		7905030271	50-498
	7905150635	70-1379		7905010280	50-482
	7905100071	40-2061		7905010459	50-482

**U.S. NUCLEAR REGULATORY COMMISSION
ORGANIZATIONAL SOURCE INDEX**

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905030104	50-482		7905310226	50-438
	7905040494	50-482		7905240394	50-438
	7905040617	50-482		7905010376	50-478
	7905070062	50-482		7905030094	50-498
	7905090100	50-482		7905030095	50-498
	7905030273	50-482		7905030143	50-498
	7905010446	50-482		7905030118	50-498
	7905010276	50-382		7905030189	50-498
	7905010461	50-382		7905030071	50-498
	7905030134	50-382		7905030240	50-498
	7905040496	50-382		7905020514	50-498
	7905040618	50-382		7905020505	50-498
	7905070066	50-382		7905040391	50-328
	7905010435	50-382		7905240686	50-498
	7905090101	50-382			
	7905030274	50-382		7905070185	50-498
	7905210030	50-320		7905310216	50-498
	7905210035	50-320		7905240385	50-498
	7905150083	50-298		7905010302	50-482
	7905010451	50-298		7905030097	50-482
	7905020444	50-298		7905030099	50-482
				7905030146	50-482
	7905020273	50-298		7905030119	50-482
	7905020415	50-298		7905030193	50-482
	7905020428	50-298		7905030057	50-482
	7905140148	50-298		7905030248	50-482
	7905150046	50-298		7905020534	50-482
	7905040537	50-298		7905020503	50-482
	7905040621	50-298		7905030621	50-482
	7905070072	50-298		7905040575	50-482
	7905010330	50-298		7905070046	50-482
	7905090103	50-298		7905310206	50-482
	7905030277	50-298		7905240418	50-482
	7905010544	50-298		7905150541	50-382
	7905010558	50-298		7905030113	50-382
	7905080352	50-298		7905030102	50-382
	7905010375	50-298		7905030147	50-382
	7905150085	50-285		7905030122	50-382
	7905010433	50-285		7905030197	50-382
	7905020440	50-285		7905030066	50-382
	7905020268	50-285		7905030250	50-382
	7905020413	50-285		7905020524	50-382
	7905020434	50-285		7905020511	50-382
	7905140146	50-285		7905040579	50-382
	7905150049	50-285		7905070188	50-382
	7905040486	50-285		7905310222	50-382
	7905040623	50-285		7905240374	50-382
	7905070073	50-285		7905150364	50-356
	7905010533	50-285		7905070191	50-443
	7905090104	50-285		7905010365	50-443
	7905030280	50-285		7905150536	50-443
	7905010546	50-285		7905030085	50-443
	7905010559	50-285		7905030107	50-443
	7905080354	50-285		7905030131	50-443
	7905010401	50-285		7905030124	50-443
	7905010287	50-133		7905030201	50-443
	7905010289	50-344		7905030074	50-443
	7905150086	50-267		7905030234	50-443
	7905010454	50-267		7905020514	50-443
	7905020446	50-267		7905020508	50-443
	7905020279	50-267		7905040580	50-443
	7905020411	50-267		7905270631	50-443
	7905020431	50-267			
	7905140143	50-267		7905070193	50-443
	7905150051	50-267		7905310230	50-443
	7905040498	50-267		7905240397	50-443
	7905040627	50-267		7905230693	50-443
	7905070077	50-267			
	7905010535	50-267		7905100266	50-267
				7905240451	50-313
	7905090106	50-267		7905010395	50-313
	7905030282	50-267			
	7905080335	50-267		7905150310	50-285
	7905010406	50-267		7905150604	50-188
	7905010292	50-206		7905230268	50-285
	7905010548	50-267		7905150584	50-112
	7905010291	50-312		7905150596	50-188
	7905010281	50-443		7905150578	50-112
	7905010444	50-443		7905010655	50-72
	7905030140	50-443		7905010385	50-313
	7905040501	50-443		7905020325	50-368
	7905040629	50-443		7905130117	50-313
	7905070080	50-443		7905040106	50-313
	7905010440	50-443		7905130253	50-313
	7905090108	50-443		7905030008	50-313
	7905030283	50-443		7905130096	50-313
	7905010294	50-397		7905020122	50-298
	7905010393	50-313		7905150120	50-298
				7905040110	50-298
	7905010312	50-482		7905150258	50-298
	7905010383	50-498		7905150097	50-298
	7905150561	50-443		7905240445	50-298
	7905030089	50-438		7905150306	50-285
	7905030091	50-438		7905150122	50-285
	7905030139	50-438		7905040112	50-285
	7905030117	50-438		7905150261	50-285
	7905030196	50-438		7905230257	50-285
	7905030073	50-438		7905150100	50-285
	7905030238	50-438		7905240440	50-285
	7905020528	50-438		7905010354	50-267
	7905020498	50-438		7905100261	50-267
	7905040584	50-438		7905150110	50-267
	7905070180	50-438		7905040113	50-267
Region 4, Dallas, Reactor Construction & Engineering Support Branch			Region 4, Dallas, Fuel Facility & Materials Safety Branch		
			Region 4, Dallas, Reactor Operations Nuclear Support Branch		

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7903150223	50-267		7903030293	50-344
	7903150795	50-267		7903020529	50-344
	7903150102	50-267		7903010422	50-344
	7903240428	50-267		7903080369	50-344
Region 4, Dallas, Vendor Inspection Branch	7903030150			7903010443	50-344
	7905100360			7903010458	50-344
	7905100366			7903090039	50-344
	7905290104			7903090054	50-344
	7905290113			7903090116	50-344
	7905110404			7903070028	50-344
	7905150585			7903070010	50-344
	7905100413			7903310093	50-344
	7905100418			7903010220	50-206
	7905150797			7903010431	50-206
	7905230587			7903150064	50-206
	7905230593			7903150170	50-206
	7905030144			7903040128	50-206
	7905100410			7903130143	50-206
	7905100356			7903010020	50-206
	7903100343			7903010025	50-361
	7905290097			7903030024	50-206
	7905290083			7903040511	50-206
	7905150792			7903040512	50-361
	7905230581			7903040619	50-206
	7905110398			7903070104	50-206
Region 5, San Francisco, Office of the Director	7905110086	50-312		7903030296	50-361
	7905020520	50-142		7903030297	50-206
	7905150620	50-528		7903040532	50-206
	7905150701	70-1257		7903010434	50-206
	7905230664	50-323		7903080371	50-206
	7905230640	50-275		7903010447	50-206
	7905040366	50-344		7903010462	50-206
	7905290152	50-275		7903070041	50-206
	7905010228	70-1257		7903070057	50-206
	7905010234	70-734		7903310012	50-361
	7903010230	70-754		7903070119	50-206
	7905010239	70-25		7903070031	50-206
	7905040076	50-528		7903070012	50-206
	7905150057	50-528		7903310044	50-206
	7905150165	50-528		7903010222	50-312
	7905040121	50-528		7903010433	50-312
	7905150136	50-528		7903150069	50-312
	7903010016	50-528		7903040171	50-312
	7905030050	50-528		7903040130	50-312
	7905040507	50-528		7903010013	50-312
	7903040614	50-528		7903030028	50-312
	7905070098	50-528		7903040515	50-312
	7903030286	50-528		7903040622	50-312
	7903020525	50-528		7903070108	50-312
	7905010420	50-528		7903030300	50-312
	7905080365	50-528		7903020535	50-312
	7903010442	50-528		7903010437	50-312
	7903010436	50-528		7903080374	50-312
	7903090038	50-528		7903010450	50-312
	7903090053	50-528		7903010460	50-312
	7903090115	50-528		7903090045	50-312
	7903070023	50-528		7903090058	50-312
	7903040355	50-528		7903090120	50-312
	7903310059	50-528		7903070033	50-312
	7903040081	50-133		7903070015	50-312
	7903010216	50-133		7903310050	50-312
	7903010423	50-133		7903150069	50-397
	7903150060	50-133		7903150173	50-397
	7903010167	50-133		7903040134	50-397
	7903040123	50-133		7903150150	50-397
	7903150141	50-133		7903010015	50-397
	7903010023	50-133		7903030018	50-397
	7903030045	50-133		7903040514	50-397
	7903040508	50-133		7903040623	50-397
	7903040509	50-275		7903070110	50-397
	7903070099	50-133		7903030305	50-397
	7903020288	50-133		7903020936	50-397
	7903030291	50-275		7903010439	50-397
	7903020327	50-133		7903080378	50-397
	7903010425	50-133		7903010452	50-397
	7903080366	50-275		7903010463	50-397
	7903080368	50-133		7903090047	50-397
	7903010444	50-133		7903090059	50-397
	7904300484	50-320		7903090121	50-397
	7903020227	50-133		7903070034	50-460
	7903020254	50-275		7903070018	50-460
	7903090005	50-133		7903310037	50-397
	7903040399	50-320		7903240657	50-460
	7903070007	50-133		7903010225	70-984
	7903170072	50-133		7903300352	50-320
	7903240651	50-275	Region 5, San Francisco, Reactor Construction & Engineering Support Branch	7903180620	50-528
	7903040066	50-344		7903150609	50-528
	7903010218	50-344	Region 5, San Francisco, Fuel Facility & Materials Safety Branch	7903020520	50-142
	7903010428	50-344		7903150701	70-1257
	7903150062	50-344		7903230664	50-323
	7903180168	50-344		7903240768	50-275
	7903040125	50-344		7903040366	50-344
	7903180142	50-344		7903020513	50-142
	7903010027	50-344		7903150686	70-1257
	7903030030	50-344		7903230656	50-323
	7903040497	50-344		7903240747	50-275
	7903040616	50-344		7903040362	50-344
	7903070102	50-344		7903110086	50-312

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

389

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
Region 3, San Francisco, Reactor Operations Nuclear Support Branch	7905230440	50-275		7905240382	71-65
	7905150339	50-312		7905020384	71-213
	7905290152	50-275		7905150149	71-71
	7905230617	50-275		7905110079	71-111
	7905290147	50-275		7905020384	71-216
	7905110083	50-312		7905150178	71-166
	7905150333	50-312		7905150682	71-65
	7905110044	50-312		7905020394	71-175
	7905150289	70-1257		7905150205	71-168
Region 3, San Francisco, Safeguards Branch				7905240161	71-143
	7905100048	70-734		7905150576	71-9010
	7905100022	50-320		7905100340	71-215
Office of I&E, Executive Officer for Management & Analysis				7905150742	71-126
Office of I & E Executive Officer for Operations Support	7905160201	50-320		7905150169	71-189
				7905070279	71-103
				7905140119	71-131
				7905250366	71-234
				7905020193	71-226
				7905240327	71-6697
				7905070228	71-277
				7905110081	71-128
				7905170278	71-1
				7905110199	71-260
				7905240041	71-2
				7904200311	71-110
				7905070047	71-6058
				7905020407	71-88
				7905020198	71-34
				7905070075	71-6144
				7905070302	71-6272
				7905240036	71-6400
				7905230305	71-6679
				7905110069	71-72
				7905290041	71-9009
				7905070287	71-130
				7905070292	71-104
				7905240112	71-6244
				7905230847	71-5803
				7905110095	71-181
				7905150329	71-38
				7905150333	71-38
				7905240017	71-4986
				7905070272	71-99
				7905240565	71-70
				7905110067	71-214
				7905240017	71-4986
				7905290041	71-9009
				7905240327	71-6697
				7905020376	71-220
				7905020399	71-178
				7905020392	71-180
				7905100079	71-9079
				7905240046	71-24
				7905110063	71-156
				7905100352	71-257
				7905070257	71-119
				7905150176	71-48
				7905110065	71-209
				7905240244	71-9070
				7905150157	71-188
				7905150318	71-30
				7905150323	71-30
				7905070282	71-127
				7905240109	71-3364
				7905240156	71-121
				7905240036	71-6400
				7905240638	71-216
				7905110071	71-74
				7905290227	71-217
				7905110084	71-141
				7905240291	71-223
				7905290219	71-6058
				7905241000	71-109
				7905290219	71-6058
				7905020183	71-4
				7905240974	71-241
				7905100347	71-253
				7905240140	71-39
				7905240036	71-4400
				7905290096	71-251
				7905150167	71-238
				7905150342	71-235
				7905020191	71-239
				7905020196	71-223
				7905070267	71-89
				7905100339	71-268
				7905100448	71-273
				7905110204	71-87
				7905110210	71-116
				7905290255	71-261
				7905230691	71-5790
				7905020170	71-9852
				7905080180	71-5737
				7905240128	71-6273
				7905240099	71-9506
				7905250341	71-6386
				7905150576	71-9010
				7905290361	71-9009
				7905240327	71-6697
				7905070073	71-6144
				7905070047	71-6058
				7905070073	71-6144
				7905070302	71-6272
				7905070290	71-6771
Office of Nuclear Material Safety & Safeguards	7905100240				
Office of Nuclear Material Safety & Safeguards	7905080082				
	7905020180	71-6698			
	7905240406				
	7905240413				
	7905310132	70-2623			
	7905110172	27-39			
	7905080081				
	7905310152	70-2623			
	7905160028	50-320			
	7905020176	71-6698			
Division of Fuel Cycle & Material Safety	7905240658	40-8698			
	7905080027	70-135			
	7905220028	70-1318			
	7905290488	40-2239			
	7905310132	70-2623			
	7905080087				
Assistant Director for Fuel Cycle Safety & Licensing	7905080101				
Fuel Process & Fab. Branch	7905300691	40-8102			
	7905100044	40-2061			
	7905090003	40-8027			
	7905290479	40-8027			
	7905090265	70-143			
	7905220029	40-8663			
	7905250176	40-2239			
	7905240592	40-8681			
	7905240080	70-1319			
	7905250067	40-8035			
	7905090008	40-8027			
	7905150634	40-8721			
Fuel Reprocess & Recycle Branch	7905240383	70-1308			
	7905290282	50-201			
	7905240370	70-1308			
	7905090164	70-2623			
	7905290090	50-269			
	7905090138	70-2623			
	7905030035	50-201			
	7905230706	50-364			
	7905250338				
	7905110258	50-320			
	7905160029	50-320			
	7905230193	40-2407			
Radioisotopes Licensing Branch (Pre 790301)	7905230177	40-2407			
	7905230160	40-2407			
	7905230145	40-2407			
	7905110162				
	7905110144	50-320			
	7905110171	50-320			
	7905220039	40-2239			
	7905240849	40-2239			
	7905110160	50-320			
	7905110156	50-320			
	7905110174	50-320			
	7905250011	40-2239			
	7905240855	40-8663			
	7905150806	40-8502			
	7905250012	40-8714			
	7905310088	40-8681			
	7905240369	71-70			
	7905070081	71-6144			
	7905070307	71-6272			
	7905070295	71-6771			
	7905240020	71-4986			
	7905240039	71-6400			
	7905250316	71-6679			
	7905290226	71-6058			
	7905240843	71-664			
	7905240834	71-6			
	7905250346	71-6386			
	7905240318	71-68			
	7905240839	71-169			
	7905290046	71-9009			
	7905240331	71-6697			
	7905240434	50-320			
	7905150739	71-47			
	7905290318	71-287			
	7905150160	71-66			
	7905110078	71-120			
	7905010185	71-162			
	7905010169	71-167			

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7903090089	71-6744		7905150093	
	7905250303	71-6679		7905250025	50-331
	7905090089	71-6744		7905240201	50-424
	7905240847	71-8		7905240455	50-280
	7905070290	71-6771		7905080137	
	7905240833	71-266		7905030027	
	7905240834	71-169		7905030157	
	7905130723	71-296		7905240791	50-346
	7905240017	71-4986		7905070450	50-272
	7905240311	71-68		7905220045	50-447
	7905070047	71-6058		7905220024	50-263
	7905160053	71-5795		7905090144	50-363
	7905070302	71-6272		7905300751	50-280
	7905250305	71-6679		7905020523	50-10
	7905250219	71-6058		7905250275	50-335
	7905070290	71-6771		7905150075	50-424
	7905090089	71-6744		7905150307	50-331
	7905240163	71-77		7905240850	50-456
	7905300433	50-320		7905020410	50-443
Assistant Director for Waste Management (Pre 790501)	7905100039			7905240189	50-280
	7905150616	40-6659		7905310033	50-280
	7905150613	40-299		7905300667	50-322
	7905150624	40-8584		7905300216	50-320
Low Level Waste Branch (Pre 790501)	7905140035	50-320		7905300430	50-320
	7905250232	27-47		7905110271	50-320
	7905160036	50-320		7905210086	50-320
	7905230771	70-1193		7905230053	50-320
	7905240146	70-1193		7905230097	50-320
	7905240139	70-1193		7905140038	50-320
	7905230756	70-1193		7905110138	50-320
	7905240180	70-2838		7905110322	50-320
	7905070141			7905210263	50-320
	7905020041	50-320		7905230002	50-320
Material Control Licensing Branch	7905240188	70-2838		7905210069	50-320
	7905020530	70-364		7905190114	50-320
	7905250184	70-1201		7905140051	50-320
	7905300680	70-754		7905190118	50-320
	7905240222	70-1113		7905110251	50-320
	7905140141	70-143		7905190081	50-320
	7905130135	50-143		7905210049	50-320
	7905230798	70-371		7905210323	50-320
Physical Security Licensing Branch	7905230852	70-1151		7905080144	
	7905300583	70-135		7905230278	50-320
	7905300031	70-1173		7905190082	50-320
	7905230844	70-143		7905300259	50-320
	7905220032	70-820		7905230053	50-320
Uranium Recovery Licensing Branch	7905240938	70-2623		7905110296	50-320
	7905240496			7905230086	50-320
	7905250022	40-8698		7905230278	50-320
	7905240398			7905110295	50-320
				7904270152	50-320
				7905230265	50-320
				7905110126	50-320
OFFICE OF NUCLEAR REACTOR REGULATION				7905070005	50-320
Office of Nuclear Reactor Regulation	7905080051			7905230298	50-320
	7905090083	50-348		7905140051	50-320
	7905020430	50-443		7905230278	50-320
	7905100035			7905080144	
	7905070347	50-336		7905190082	50-320
	7905090117			7905080144	
	7905300288	50-320		7905190082	50-320
	7905140046	50-320		7905230053	50-320
	7905100140	50-338		7905230094	50-320
	7905300403	50-320		7905110151	50-320
	7905140526	50-266		7905230281	50-320
	7905140529	50-266		7905140051	50-320
	7905240204	50-280		7905110064	
	7905070277	50-335		7905250322	
	7905090071	50-266		7905070005	50-320
	7905250187	50-293		7905300400	
	7905150111	50-267		7905300656	50-322
	7905070127	50-261		7905230035	50-320
	7905250085	50-313		7905090280	50-313
	7905240813	50-546		7905230273	50-320
	7905250027	50-331	Antitrust & Indemnity Group	7905110194	50-320
	7905250439	50-331		7905140281	50-72
	7905150080	50-424		7905190171	50-30
	7905240211	50-424		7905150308	50-18
	7905290559	50-289		7905150382	70-754
	7905020163	50-320		7905160297	50-131
	7905090208	50-244		7905150363	50-124
	7905240329	50-282		7905190049	50-193
	7905310180	50-267		7905220354	50-267
	7905020128	50-320		7905240675	50-406
	7905220030	50-263		7905030154	50-445
	7905220033	50-263		7905160276	50-146
	7905250005	50-317		7905150375	50-262
	7905290016	50-245		7905160122	50-77
	7905110003	50-298		7905160238	50-208
	7905290040	50-305		7905300038	50-97
	7905110016	50-376		7905160222	50-394
	7905110279	50-320		7905300045	50-160
	7905240461	50-280		7905160106	50-116
	7905230206	50-320		7905160334	50-284
	7905300278			7905160282	50-188
	7905300295			7905150386	50-141
	7905190254	50-320		7905160268	50-223
	7905300716	50-275		7905150377	50-199
	7905040003			7905160232	50-538
	7905040343	50-363		7905160240	50-294
	7905150071	50-266		7905160189	50-241
	7905140027	50-320		7905160322	50-20
				7905160326	50-106

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

391

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905160117	50-150		7905160298	50-133
	7905160328	50-5		7905160187	50-344
	7905160238	50-182		7905160199	50-334
	7905160265	50-288		7905160176	50-267
	7905160266	50-225		7905150367	50-272
	7905160332	50-57		7905160185	50-244
	7905160234	50-406		7905160314	50-206
	7905160343	50-59		7905310373	50-361
	7905160203	50-113		7905160193	50-395
	7905300052	50-84		7905160243	50-312
	7905160221	50-326		7905160231	50-346
	7905160235	50-142		7905140462	50-259
	7905160219	50-433		7905160230	50-327
	7905160167	50-83		7905140444	50-280
	7905150370	50-151		7905140523	50-338
	7905160160	50-148		7905160215	50-271
	7905150376	50-166		7905140431	50-266
	7905160341	50-2		7905160273	50-305
	7905160336	50-123		7905160285	50-29
	7905160339	50-186		7905300055	50-6
	7905300069	50-8	Program Support Branch	7905160233	50-360
	7905160329	50-252		7905110121	50-320
	7905160236	50-112		7905110140	50-320
	7905160260	50-193		7905110119	50-320
	7905160355	50-192	Technical Section	7905100325	50-320
	7905230456	50-62	Division of Site Safety & Environmental	7905240219	50-424
	7905300034	50-72	Analysis		
	7905160192	50-139		7905160129	50-320
	7905160306	50-156		7905240955	50-313
	7905160308	50-124		7905230591	50-463
	7905160205	50-134		7905020390	50-596
	7905160300	50-27		7904170363	
	7905160207	50-129		7904130020	
	7905150373	50-170		7905230141	50-320
	7905160100	50-131		7905230152	50-320
	7905300059	50-32		7904130020	
	7905160116	70-364		7905190107	50-320
	7905160148	70-824	Assistant Director for Site Analysis	7905020128	50-320
	7905300714	50-13		7905100034	50-320
	7905160357	50-264		7905230118	50-320
	7905160123	70-1257		7905230165	50-320
	7905300202	50-37		7905190226	50-320
	7905160151	70-734		7905210012	50-320
	7905300190	50-18		7905230130	50-320
	7905160311	50-201		7905140287	50-524
	7905160345	50-187		7905150119	
	7905160320	50-94		7905230178	50-320
	7905160348	50-54		7905190247	50-320
	7905160108	70-1143		7905230029	50-320
	7905160249	50-87		7905230116	50-320
	7905160351	50-22		7905230023	50-320
	7905160311	50-201		7905230029	50-320
	7905160278	50-47		7905230032	50-320
	7905160244	50-274		7905230040	50-320
	7905160280	50-30		7905230116	50-320
	7905160281	50-184		7905230023	50-320
	7905160224	50-348		7905230029	50-320
	7905140489	50-313		7905230126	50-320
	7905160180	50-293		7905230032	50-320
	7905140499	50-317		7905230040	50-320
	7905160275	50-331		7905230178	50-320
	7905140404	50-10		7905230032	50-320
	7905140456	50-254		7905230040	50-320
	7905140470	50-295		7905230023	50-320
	7905140546	50-373		7905230178	50-320
	7905140407	50-3	Effluent Treatment Systems Branch	7905230105	50-320
	7905160272	50-358		7905230293	50-320
	7905160275	50-331		7905230074	50-320
	7905230832	50-329		7905230143	50-320
	7905160172	50-255		7905230056	50-320
	7905160291	50-155		7905230074	50-320
	7905140508	50-324		7905210230	
	7905160183	50-261		7905230143	
	7905160272	50-358		7905230157	
	7905160289	50-213		7905230056	
	7905160157	50-409		7905230074	
	7905160353	50-16		790	
	7905160199	50-334	Assistant Director for Environmental		
	7905140415	50-171	Projects		
	7905140438	50-269	Environmental Projects Branch 1		
	7905140538	50-349			
	7905160272	50-358			
	7905160252	50-302			
	7905140449	50-250			
	7905160198	50-335			
	7905140493	50-321			
	7905160275	50-331			
	7905140456	50-254			
	7905140481	50-315			
	7905140486	50-289			
	7905160292	50-219	Environmental Projects Branch 2		
	7905140486	50-289			
	7905160273	50-305			
	7905150360	50-309			
	7905140422	50-245			
	7905160286	50-220			
	7905150365	50-298			
	7905140477	50-282			
	7905160170	50-263			
	7905160199	50-334			
	7905160164	50-285			
	7905160162	50-333			
	7905140415	50-171			
	7905140512	50-275	Geosciences Branch		

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
Cost Benefit Analysis Branch Division of Operating Reactors	7905100093	50-353	Reactor Safeguards Licensing Branch Assistant Director for Systems & Projects	7905240846	50-259
	7905100338	50-320		7905140320	50-266
	7905230175	50-320			
	7905030212	50-320		7905110193	50-320
	7905100054	50-320		7905100073	50-280
	7905070014	50-293		7905150179	
	7905230849			7905150808	
	7905240990			7905140112	50-320
	7905230128	50-320		7905110130	50-320
	7905230125	50-320		7905110133	50-320
	7905230135	50-320		7905150798	50-333
	7905100158	50-280		7905240253	50-336
	7905070017	50-309		7905040150	50-219
	7905140287	50-524		7905240471	50-305
	7905150119			7905090168	
7905230123	50-320	7905240302	50-206		
7905190194	50-320	7905240421	50-10		
7905230081	50-320	7905240731	50-255		
7905230085	50-320	7905300718			
7905110144	50-312	7905070315	50-286		
7905230801		7905040309	50-261		
7905210073	50-320	7905070114	50-230		
7905110050	50-312	7905070119	50-250		
7905110180	50-312	7905070124	50-230		
7905230081	50-320	7905250435	50-293		
7905230085	50-320	7905140533	50-266		
7905080347	50-280	7905240903	50-303		
7905110050	50-312	7905240911	50-305		
7905110180	50-312	7905090068	50-266		
7905080347	50-280	7905090076	50-266		
7905090286	50-313	7905250183	50-293		
7905230081	50-320	7905250190	50-293		
7905230085	50-320	7905240378	50-303		
7905150174	50-313	7905240382	50-305		
7905210053	50-320	7905070125	50-261		
7905290552	50-296	7905070130	50-261		
7905090171		7905090080	50-348		
		7905090084	50-348		
		7905100442	50-266		
		7905100446	50-266		
		7905240322	50-282		
		7905240333	50-282		
		7905290084	50-303		
		7905290064	50-303		
		7905250432	50-293		
		7905250440	50-293		
		7905250556	50-286		
		7905090079	50-348		
		7905250423	50-293		
		7905040307	50-261		
		7905070121	50-261		
		7905070109	50-250		
		7905240308	50-282		
		7905070311	50-286		
		7905140313	50-266		
		7905090065	50-266		
		7905100439	50-266		
		7905240895	50-303		
		7905240373	50-303		
		7905290080	50-303		
		7905020490	50-272		
		7905300010	50-280		
		7905290723	50-334		
		7905110038	50-230		
		7905310402	50-261		
		7905240229	50-247		
		7905150789	50-280		
		7905310472	50-280		
		7905290405	50-280		
		7905080049	50-250		
		7905080073	50-250		
		7905080080	50-250		
		7905080382	50-245		
		7905020450	50-206		
		7905020457	50-206		
		7905150707	50-155		
		7905150715	50-155		
		7905090207	50-244		
		7905090263	50-244		
		7905300731	50-245		
		7905290012	50-245		
		7905290019	50-245		
		7905090160	50-245		
		7905080970	50-237		
		7905080337	50-10		
		7905080339	50-237		
		7905180648	50-155		
		7905090029	50-255		
		7905240271	50-155		
		7905230602	50-255		
		7905080158	50-255		
		7905250343	50-255		
		7905180489	50-155		
		7905090016	50-213		
		7905230599	50-409		
		7905100132	50-409		
		7905290074	50-409		
		7905080063	50-250		
		7905100321	50-219		
		7905090024	50-219		
		7905080381	50-245		
		7905080343	50-245		
		7905300729	50-245		

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

38

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905290007	50-243	Light Water Reactors Branch 3	7905080114	
	7905030126	50-244		7905200616	50-392
	7905090026	50-244		7905040260	50-373
	7905020381	50-244		7905100069	50-498
	7905020363	50-244		7905300372	50-498
	7905090203	50-244		7905250240	50-548
	7905020449	50-206		7905290044	50-074
	7905090020	50-206		7905310444	50-576
	7905020218	50-206		7905150794	50-387
	7905090022	50-29		7905300594	50-311
	7905110128	50-320		7905240226	50-311
	7905190134			7905300376	50-438
	7905100174	50-409		7905310461	50-488
	7905100324	50-409		7905240218	50-572
	7905100239	50-153		7905020439	50-338
	7905250040	50-29		7905240218	50-572
	7905250097	50-10		7905090180	50-872
Reactor Safety Branch	7905030257			7905100224	50-387
Systematic Evaluation Programs Branch	7905290523			7905230858	50-482
	7905110154			7905240804	50-387
	7905110126	50-320		7905290021	50-073
Division of Project Management	7905110135	50-320		7905240869	50-498
	7905230582	50-275		7905230731	50-488
	7905300392	50-424	OFFICE OF NUCLEAR REACTOR REGULATION		
	7905180118	50-275	Light Water Reactors Branch 4	7905100435	50-413
	7905240676	50-532		7905090299	50-446
	7905070432	50-495		7905100112	50-582
	7905140516	50-382		7905070665	50-534
	7905230837	50-594		7905150649	50-327
	7905240662	50-346		7905090304	50-338
	7905290006	50-29		7905230795	50-877
	7905100325	50-275		7905290415	50-387
	7905210238	50-320		7905150607	50-397
	7905110358	50-320		7905100171	50-546
	7905100384	50-320		7905100220	50-390
	7905010664	50-596		7905020493	
	7905240130		Assistant Director for Quality Assurance & Operations	7905020482	
	7905190252	50-320	Operator Licensing Branch	7905300289	
	7905210238	50-320		7905140117	50-382
	7905190252	50-320		7905300180	
	7905210238	50-320		7905240166	50-282
	7905300396	50-320		7905290204	50-267
	7905300381	50-320		7905070070	50-888
Assistant Director for Light Water Reactors	7905190252	50-320	Quality Assurance Branch	7905070663	50-213
	7905290015			7905240979	
	7905020420	50-437		7905240337	
	7905230840	50-368		7905070440	50-213
	7809050087	50-437		7905240415	50-897
	7905020424	50-440		7905070553	50-27
	7905020437	50-458		7905100378	50-344
	7905020432	50-482		7905250122	
	7905020406	50-382		7905230287	50-320
	7905020400	50-367		7905310171	50-267
	7905020445	50-844	Advanced Reactors Branch	7905310186	50-267
	7905020452	50-856		7905310160	50-267
	7905230126	50-322		7905300210	50-267
	7905020414	50-395		7904270399	50-320
	7905160112	50-320		7905010179	50-267
	7905110143			7905100277	
	7905110158	50-320		7905240392	50-384
	7905100393	50-320	Standardization Branch	7905300070	50-380
	7905100392	50-320	Division of Systems Safety	7905190172	50-320
	7905100390	50-320		7905220455	50-320
	7905100389	50-320		7905210295	50-320
	7905100388	50-320		7905230088	50-320
	7905080278			7905290122	50-572
	7905080171				
	7905080217				
	7905080230				
	7905080239				
	7905160185	50-320			
	7905010156	50-320			
	7905080230				
	7905110414				
	7905080217				
Light Water Reactors Branch 1	7905090294				
	7905230826	50-522			
	7905090290				
	7905250049	50-313			
	7905240372	50-358			
	7905290528	50-341			
	7905310083	50-341			
	7905100431	50-416			
	7905070674	50-273			
	7905230578	50-273			
	7905240857	50-522			
	7905180630	50-341			
	7905010659	50-358			
	7905100258	50-322			
	7905230558	50-322			
	7905240359	50-390			
	7905150641	50-556			
Light Water Reactors Branch 2	7905240977				
	7905250050				
	7905240936	50-580			
	7905140040	50-443	Structural Engineering Branch		
	7905230686	50-395	Assistant Director for Plant 24		
	7905230589	50-361			
	7905240108	50-437			
	7905150759	50-399			
	7905240340	50-395			
	7905290411	50-361			

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905110335	50-320		7905110293	50-320
	7905220457	50-320		7905110299	50-320
	7905110349			7905110301	50-320
	7905110316	50-320		7905110302	50-320
Auxiliary Systems Branch	7905190203	50-320		7905230453	
Containment Systems Branch	7905040316	50-322		7905160452	50-320
	7905020235	50-219		7905110291	50-320
Electric Instrumentation & Control Systems Branch	7905110331	50-320		7905090237	50-320
	7904300123	50-320		7905110248	50-320
Assistant Director for Reactor Safety	7905230048	50-320		7905110304	50-320
	7905010198	50-320		7905230425	
	7905230048	50-320		7905230441	
	7905230212	50-320		7905230413	
	7905241001	50-548		7905240316	
	7905080361	50-491		7905230036	50-320
	7905230037	50-320		7905240316	
Analysis Branch	7905110061			7905220043	
	7905110226			7905230741	
	7905110061			7905160131	50-320
	7905110068	50-269		7904300253	
	7905110074	50-269		7905110229	50-320
	7905070086			7905160083	50-320
	7905250113			7905110286	50-320
	7905110061			7905220442	50-320
	7905110226			7905110381	
Core Performance Branch	7905140056			7905220432	50-320
Reactor Systems Branch	7905290597			7905210027	50-320
	7905250210	50-255		7905160018	50-320
	7905110060			7905110319	50-320
	7905230098			7905110285	50-320
	7905240476			7905110308	50-320
	7905230087	50-255		7905110285	50-320
	7905290102			7905110289	50-320
	7905110055			7905110285	50-320
				7905110308	50-320
OFFICE OF STANDARDS DEVELOPMENT			Probabilistic Analysis Branch	7905160002	50-320
Office of Standards Development	7905230460			7905230419	
	7905090350			7904180171	
	7905090354			7905230443	
	7905080035			7905160064	50-320
	7905230508			7905230449	
	7905230511			7904180171	
	7905080082			7905110315	50-320
	7905020142			7905110312	50-320
	7905290018			7905160139	50-320
	7905230483			7905160143	50-320
	7905230608			7905160149	50-320
	7905210015	50-320	Environmental Effects Research Branch	7905230434	
	7905100036			7904210061	
	7904270576	50-320		7905110275	50-320
	7905140136	50-320	Systems Performance Branch	7905110273	50-320
	7905140132	50-320	Division of Reactor Safety Research	7904170091	
	7905140129	50-320		7905110323	50-320
	7905160096	50-320		7905140017	50-320
	7905140134	50-320		7905110363	50-320
	7904270178	50-320		7905110328	50-320
	7905250322			7905170277	
	7905230460			7905110283	
	7905160104	50-320	Assistant Director for Advanced Reactor Safety Research	7905240264	50-320
Division of Engineering Standards	7905090228	50-320		7905110387	50-320
Engineering Methodology Standards Branch	7905090219	50-320		7905110255	50-320
Reactor Systems Standards Branch	7905300428	50-320		7905110257	50-320
	7905300437	50-320		7905110263	50-320
	7905300374			7905110255	50-320
	7905090210	50-320	Experimental Fast Reactor Safety Research Branch	7905110265	50-320
Assistant Director for Materials Safety Branch	7905230611			7905110266	50-320
	7905160220	50-320	Experimental Gas-Cooled Reactor Safety Research Branch	7905110259	50-320
Fuel Process Systems Standards Branch	7905160015	50-320		7905110281	50-320
Transportation & Product Standards Branch	7905110261	50-320	Mechanical Engineering Branch	7905110340	50-320
	7905150582		RBR Field Office, Idaho	7905220468	
	7905160068	50-320	Fuel Behavior Branch	7905110351	50-320
	7905070035	50-320		7905110343	50-320
Assistant Director for Siting Standards	7904180175		Research Support Branch	7905080405	
	7904180171			7905110330	50-320
	7905140052	50-320		7904190311	
	7904180171				
Environ Protect Standards Branch	7905160202	50-320			
	7905190107	50-320			
Occupational Health Standards Branch	7905130702				
Radiological Health Standards Branch	7904270088	50-320			
	7905100018	50-320			
	7904180377	50-320			
	7905100034	50-320			
	7905100029	50-530			
	7905090231	50-320			
	7905100017	50-320			
Safeguards Standards Branch	7904210768				
	7905190153	50-320			
OFFICE OF NUCLEAR REGULATORY RESEARCH					
Office of Nuclear Regulatory Research	7905110272	50-320			
	7905110270	50-320			
	7905110280	50-320			
	7905130315	50-331			
	7905110277	50-320			

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	DOCKET NUMBER	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	DOCKET NUMBER	OTHER REPORT NUMBER
45-79/M12AAF	7905250528	50-329		MUREQ-0539	7905020063		
45-79/M12AAF	7905250530	50-329		MUREQ-0540 V1 N3	7905150014		
7270-RP-16A51	7905310458	50-437		MUREQ-0541	7905110016	50-376	
7905020151	7905020151			MUREQ-0544	7905140573		
7905020154	7905020154			MUREQ-0553	7905090048		
7905080055	7905080055			MUREQ-0558	7905300300	50-320	
7905090031	7905090031			MUREQ-0560	7905300295		
7905090163	7905090163			MUREQ/CP-0003	7905100240		
7905100021	7905100021		BNL-MUREQ 25855	MUREQ/CR-0040 V1 N4	7905240025		
7905100243	7905100243		PNL-2931	MUREQ/CR-0253	7905090401		
7905110033	7905110033			MUREQ/CR-0283	7905020022		TRNE-1267
7905150099	7905150099			MUREQ/CR-0426 V1	7905030015		PNL-2773 VOL
7905150140	7905150140			MUREQ/CR-0446	7905030231		UNIT-TR-3
7905150777	7905150777		PNL-2260-9	MUREQ/CR-0454	7905090428		
7905220043	7905220043		LF-59	MUREQ/CR-0486	7905240925		NRL REPT 8287
7905230741	7905230741			MUREQ/CR-0494	7905030142		ORNL/MUREQ/TH-
7905230788	7905230788		ORNL/HASRD-21	MUREQ/CR-0513	7905150219		BNL-MUREQ-509C
7905240113	7905240113			MUREQ/CR-0523	7905030246		PNL-2419
7905240316	7905240316	50-286		MUREQ/CR-0539	7905140572		ORNL/MUREQ-53
7905240320	7905240320			MUREQ/CR-0590	7905090408		
7905240346	7905240346			MUREQ/CR-0595	7905150213		TRNE-1330
7905240353	7905240353			MUREQ/CR-0599	7905030221	50-219	CREARE TN-287
7905240389	7905240389			MUREQ/CR-0634	7905140570		
7905240404	7905240404			MUREQ/CR-0642	7905090422		RFP-2888
7905240415	7905240415			MUREQ/CR-0643	7905100165		MEDL-THE-78-75
7905240427	7905240427			MUREQ/CR-0645	7905140579		TRNE-1323
7905240529	7905240529			MUREQ/CR-0646	7905140576		TRNE-1324
7905240540	7905240540		ORNL/HASRD-34	MUREQ/CR-0647	7905140149		BAND77-1371
7905240552	7905240552		CREARE TN-292	MUREQ/CR-0673	7905100213		LF-63
7905240553	7905240553			MUREQ/CR-0682	7905090078		ORNL/MUREQ/TH-
7905240556	7905240556		ORNL/FIR-566	MUREQ/CR-0724	7905100229		
7905240576	7905240576		ORNL/ED/EIS-88	MUREQ/CR-0728	7905090406		
7905240587	7905240587		ORNL/HASRD-33	MUREQ/CR-0754	7905090417	50-285	
7905250160	7905250160		ORNL/FTR-581	MUREQ/CR-0755	7905100251		
7905250214	7905250214			MUREQ/CR-0756	7905100190		FIN A-2045
7905290491	7905290491			MUREQ/CR-0785	7905240886	50-320	
7905290498	7905290498		ORNL/HASRD-22	ORNL/TH-6853	7905300438		
7905310015	7905310015			PCBE-79137	7905250450	50-320	
APCI-78-B	7905070319	50-397		SECY-79-235	7905230822		
BAW-10085 R3	7905030203			SECY-78-136	7905080035		
BAW-1533	7905210138			SECY-78-624	7905230460		
BN-TOP-4	7905220026			SECY-79-0340	7905090117		
BNL-MUREQ-23021	7905150196	50-27		SECY-79-102A	7905240001		
BNL-MUREQ-25582	7905150201	50-272		SECY-79-120A	7905240059		
BNL-MUREQ-25781	7905100235	50-309		SECY-79-142A	7905230820		
CBE-7865	7905230239	50-320		SECY-79-183A	7905250033		
CEN 107-(B)-NP	7905090055	50-317		SECY-79-187	7905080082		
CEN-108(N)-NP	7905310189	50-336		SECY-79-207	7905100030	50-320	
CENPD-133 3-NP	7905220083			SECY-79-233	7905300403	50-320	
ESB-79-7	7905080517	50-375		SECY-79-245	7905240147		
FRN-790314	7905110379			SECY-79-249	7905240173		
IAEA-BM-178/34	7905300285			SECY-79-256	7905220051		
LD-79-029	7905110294			SECY-79-258	7905240281		
MHH-79-3-8F2	7905030349	50-259		SECY-79-268	7905230264	40-8695	
MEDE-23887	7905080442			SECY-79-269	7905100415		
NEDO-24169A	7905170269	50-260	79NED268	SECY-79-270	7905100053		
NU-QA-1	7905070666	50-213		SECY-79-271	7905230353		
MUREQ-0040 V1 N2	7905240047			SECY-79-272	7905230357		
MUREQ-0040 V1 N3	7905240035			SECY-79-28814	7905240371		
MUREQ-0040 V2 N6	7905240031			SECY-A-78-10	7905090235	50-320	
MUREQ-0040 V3 N1	7905240028			SECY-A-78-34	7905090246	50-320	
MUREQ-0040-01	7905240061			SECY-A-78-47	7905090222	50-320	
MUREQ-0040-02	7905240038			SECY-A-78-68	7905090226	50-320	
MUREQ-0040-03	7905240063			TFRP-TR-209	7905080109		
MUREQ-0040-08	7905240081			TR-39	7905170277		
MUREQ-0040-77/2	7905240087			TR-40	7905170282		
MUREQ-0219	7809030087	50-457		VCP-FRD-32	7905040472	50-280	
MUREQ-0380 V3 N4	7905100253			WAP-9402 (NF)	7905110058		
MUREQ-0382	7905240326			WM28-1-65-101	7905290359	50-390	
MUREQ-0484	7905080051		FB-287432	WF-TM-003	7905090339	50-320	
MUREQ-0511 V1	7905240406			XN-WF-79-27	7905100290	50-305	
MUREQ-0511 V2	7905240413			XN-WF-79-47	7905210179	50-219	

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. Application/Construction Stage Documents and Correspondence

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

1. Correspondence and documents relating to unresolved design and construction issues.
2. Meeting announcements and summaries of meeting discussions on issues of item 1.
3. Correspondence regarding Preliminary and Final Safety Analysis Reports.
4. NRC questions, requests for additional information, and applicant responses.
5. Applicant's Quality Assurance Manual.
6. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
7. Federal Register notices that do not apply to other categories.
8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
9. Scheduling of license application submission or review.
10. Reports of site visits.
11. Backup technical documents (i.e., topical reports) submitted in support of the application.
12. Early site review information.
13. Construction Permit, amendments and correspondence relating to construction permit.
14. Environmental review information.
15. Construction permit.

B. Utility Preliminary Safety Analysis Report (PSAR) and Amendments

This category is strictly limited to the items listed below. All related to Category A.

1. Preliminary Safety Analysis Report (PSAR) submitted by
2. Amendments and changes to the PSAR.
3. Transmittal letters.
4. Letters acknowledging receipt.
5. Hazards Summary Report submitted by utility (now desl

6. Safety Analysis Report submitted by utility (now designated PSAR).
7. Certificates of Service of PSAR.

C. Utility Environmental Report (ER), Amendments and Correspondence

1. Environmental Report (ER) submitted by the utility.
2. Amendments and supplements to the ER.
3. Transmittal letters.
4. Information on scheduling of submittal or review of ER.
5. NRC questions, requests for additional information, and applicant responses.
6. Federal Register notice citing availability of items 1 and 2.
7. Correspondence relating to the review of ER.
8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), Supplements and Correspondence

1. Draft and Final Environmental (Impact) Statements (DES and FES).
2. Supplements to DES and FES.
3. Correspondence relating to the DES or FES.
4. Comments from other federal, state, and local government agencies.
5. Transmittal letters.
6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
7. Backup technical documents submitted in connection with above.
8. Notices of availability of above.
9. Draft of detailed statement.

NRC Safety Evaluation Report (SER), Supplements and Correspondence

1. Safety Evaluation Report (SER).

o SER.

4. Notices advising of the availability of 1 and 2.
5. Information on scheduling of SER submittals and review.
6. Requests for additional information for use in preparing SER; responses to such requests.
7. Meeting announcements or reports of meetings where the primary subject of discussion is the safety review or safety evaluation.
8. Transmittal letters.
9. Comments from other agencies relative to safety review.
10. NRC-AEC Hazard Analysis Reports (now designated SER).

F. Security, Medical, Emergency, and Fire-Protection Plans

All plans in this category are submitted separately. Information submitted for the PSAR or FSAR is excluded.

1. Correspondence relating to plans.
2. Supplements, changes, and revisions to plans.
3. Fire Hazard Protection Plan and Surveys.

G. Adjudicatory Correspondence

This category contains all documents on hearings, Atomic Safety and Licensing Board (ASLB) review, and opposition except word-for-word transcripts of ASLB hearings (Category T) and anti-trust hearings (Category N).

1. ASLB hearing and review documents.
2. Correspondence to and from intervenors.
3. Correspondence to and from persons writing in opposition to the facility. Those writing for information or in support of the facility are in category H.
4. Board orders and decisions.
5. Requests to make appearances at hearings.
6. Transmittal of supporting documents (i.e., SER, FES) to the board.
7. Federal Register notices regarding hearings.
8. Requests for a hearing.
9. Petitions from participants (including petition for request for extension
10. Corrections to transcripts.
11. Professional qualifications, if presented at a hearing.

12. Memorandums and orders authorizing issuance of license, changes, and other issuances by the Atomic Safety and Licensing Board.
13. Hearing index.

H. General correspondence

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

1. Qualification statements of new employees.
2. Change of address notifications.
3. Changes in organization.
4. Changes in service lists, "Certificate of Service" documents (without a document attached).
5. NRC requests to applicant for additional copies of documents.
6. Correspondence from the public in support of or requesting information about the facility.
7. Letters of "concern" (NOT "opposition") and response thereto.
8. Correspondence on strictly administrative matters.
9. Correspondence regarding the local Public Document Room.
10. Memoranda to Public Document Room regarding withholding a document (unaccompanied by that document).
11. Press releases from applicant.
12. Any other material that fits the criteria given above.
13. Professional qualifications (resumes).
14. Congressional correspondence and constituent letters.

Information

1. Company annual reports.
2. Separately submitted financial information and related correspondence.

J. Insurance and Indemnity Information

1. All correspondence and documentation regarding indemnity and insurance.
2. Endorsements to insurance policies.
3. NELPIA – Nuclear Energy Liability Property Insurance information.

K. Utility Final Safety Analysis Report (FSAR) and Amendments

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

1. Final Safety Analysis Report (FSAR).
2. Amendments and changes to the FSAR.
3. Transmittal letters.
4. Letters acknowledging receipt of items.
5. Hazards Final Summary Report (now designated FSAR).
6. Certificates of Service of FSAR.

L. Limited Work Authorization and Related Correspondence

This category is limited to items issued before the construction permit is granted.

1. Limited Work Authorizations.
2. Environmental exemptions.
3. Correspondence relating to 1 and 2.
4. All information concerning site preparation prior to the issuance of a construction permit.

M. Antitrust Correspondence

1. All material concerning antitrust except hearing transcripts (category N)
2. All material marked with an A immediately following the docket number. The A signifies antitrust proceedings.

N. Antitrust Hearing Transcripts

This category contains only word-for-word transcripts of hearings in antitrust cases they will be marked with an A following the docket number. Related in category M.

O. Advisory Committee on Reactor Safeguards (ACRS) Reports and Correspondence

1. Correspondence and letter reports relating to ACRS reviews
2. Correspondence from ACRS
3. Announcements of ACRS meetings

4. Transmittal letters to ACRS
5. ACRS reports.

P. Operating License Stage Documents and Correspondence

This file assumes the position of the application file for general technical items dated on or after the issuance of the operating license. It includes:

1. Operating license, amendments, proposed amendments, and changes.
2. Technical specifications and changes.
3. Announcements of issuance of 1 and 2.
4. Transmittal letters.
5. All general technical correspondence relating to technical specifications or operating license.
6. License conditions.
7. Operator licenses or administrative information bearing on the licensing of operators.
8. Meeting announcements or summaries of discussions where the main subject is technical specifications, operating license, or any technical issue arising after the issuance of the operating license.
9. Correspondence regarding codes (ASME), regulations, laws, or changes in policy that may affect plant operation or bear on the operating license.
10. Information on the Standard Review Plan (SRP).
11. Results of surveys or tests conducted in accordance with the technical specifications (NOT periodic reports, which fall in category R).
12. Requests for issuance of operating license.
13. Requests for copies of items 1 and 2 and responses.
14. Correspondence on generic technical issues.
15. Owner's group meeting announcements and reports.
16. Orders for modification of license.
17. Requests for extension date of license or license modification.
18. Quality assurance information.

Environmental matters (technical).

ore cooling system.

waste information.

Q. Inspection Reports, IE Bulletins and Correspondence

1. Inspection reports.
2. Bulletins and Circulars of NRC Office of Inspection and Enforcement (IE).
3. Responses by applicant to IE correspondence.
4. Applicant's determination of proprietary nature of inspection reports.
5. Letters concerning areas of noncompliance.
6. Any correspondence relating to inspection and enforcement that does not specifically relate to incidents as defined in category S.
7. In-service inspections.
8. Regulatory Operations (RO) Bulletins.

R. Periodic Operating Reports and Related Correspondence

This category includes periodic reports of a routine nature.

1. Monthly, semiannual, or annual reports (other than financial).
2. Periodic environmental monitoring, effluent testing, or similar reports.
3. Gray Book Information.
4. Correspondence or other documents relating to the above listed items.

S. Reportable Occurrences, LERs and Related Correspondence

This category contains all materials relating to abnormal, unusual, reportable, nonroutine, or 10 CFR 50.55e occurrences. This includes:

1. All 24-hour, 10-day, 30-day, interim, final, and followup reports on these events.
2. Other related documents.

NOTE: Also called licensee event reports, incident reports, etc.

T. Hearing Transcripts on Non-Antitrust Matters

This category contains only word-for-word transcripts in non-antitrust matters. Related correspondence is in category G.

NRC FORM 335 (7-77)		U.S. NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET		1. REPORT NUMBER (Assigned by DDC) NUREG-0540 Vol. 1 No. 5	
4. TITLE AND SUBTITLE (Add Volume No., if appropriate) Title List of Documents Made Publicly Available				2. (Leave blank)	
7. AUTHOR(S)				3. RECIPIENT'S ACCESSION NO.	
9. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) Division of Technical Information and Document Control U.S. Nuclear Regulatory Commission Washington, D. C. 20555				5. DATE REPORT COMPLETED MONTH June YEAR 1979	
12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) Division of Technical Information and Document Control U.S. Nuclear Regulatory Commission Washington, D. C. 20555				DATE REPORT ISSUED MONTH June YEAR 1979	
13. TYPE OF REPORT Monthly				PERIOD COVERED (Inclusive dates) May 1 to May 31, 1979	
15. SUPPLEMENTARY NOTES				6. (Leave blank)	
16. ABSTRACT (200 words or less) <p> This document is a monthly publication containing descriptions of information received and generated by the U.S. NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The docketed information includes information formerly issued through U.S. DOE's Technical Information Center under the title <u>Power Reactor Docket Information (PRDI)</u>. This document replaces PRDI, which will no longer be prepared. It is indexed by a Personal Author Index, Corporate Source Index and Report Number Index. </p>				8. (Leave blank)	
17 KEY WORDS AND DOCUMENT ANALYSIS				10. PROJECT/TASK/WORK UNIT NO.	
17a. DESCRIPTORS				11. CONTRACT NO.	
17b. IDENTIFIERS/OPEN-ENDED TERMS				14. (Leave blank)	
18. AVAILABILITY STATEMENT Unlimited		19. SECURITY CLASS (This report)		21. NO. OF PAGES	
20. SECURITY CLASS (This page)		22. PRICE		\$	